X3.N111.21-2/2 10

NUREG-0540 Vol. 2, No. 1

Title List of Documents Made Publicly Available

October 1-31, 1980

Office of Administration U.S. Nuclear Regulatory Commission



600

RETURN TO HOV. DOCS, CLERK

Available from

NRC/GPO Sales Program
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

A year's subscription consists of 12 issues of this publication

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



3,		

CONTENTS

Preface	٧
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material – Docket 40	4
Domestic Licensing of Production and Utilization Facilities – Docket 50	12
Domestic Licensing of Special Nuclear Material - Docket 70	285
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71,	300
Nondocketed Items	305
10CFR - Commission Meeting Records	305
ACRS - Advisory Committee on Reactor Safeguards	305
COMMISSION – NRC Commissioners	307
CONTRACT — NRC Contracts and Modifications	308
DISCLOSURE - Financial Disclosure Information	318
FOIA - Freedom of Information Act Requests and Releases	318
GEN TECH IS - Generic Technical Issues	321
I&E - Inspection and Enforcement.	322
MISC - Public Document Room Miscellaneous	324
NUREG NUREG Reports and Related Correspondence	325
ORG - Correspondence with Other Organizations	330
PR - Proposed Rule	331
PRM — Petition for Rulemaking	338
PROJ - Projects - Predocket Licensing	338
PT21 - Noncompliance Reports and Related Correspondence	338
QA999 — Quality Assurance Inspections	339
REGGD - Regulatory Guides	341
RES - Research and Technical Assistance Reports	343
REVIEW GRP - NRC Research Review Groups	344
RM — Rulemakings	344
SECY - Position Papers Before the Commission	345
STATE PROG - State Programs	345
TOPREP — Vendor Reports and Related Correspondence	348
WASTE MGT - Nuclear Waste Management	351
XPORTLIC - Export and Import Licenses	351
Personal Author Index	359
Corporate Source Index	393
Report Number Index	423
Cross Reference of Enclosures to Principal Documents	425
Appendix A - Definitions of Docket 50 Categories	441
Appendix B — Definitions of Nondocketed Categories	449

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- II. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are.




P. Operating license stage documents & correspondence



7904170015 Forwards info on TMI: JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- 1 NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO"

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects-Predocket Licensing

PT9 — Public Records

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:


1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

(4) Typnamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.



- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document

10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: "8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mall orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8380	Rocky Mountain Energy Co.	8
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8385	Dept, of the Air Force, Headquarters	8
27-047	Barnwell, SC, Chem-Nuclear Systems	3	40.0424	Aerospace Medical Division	0
27-048	Richland, WA, Nuclear Engineering Co.	3	40-8434	Home State Mining Co.	8
40-0299	Union Carbide Corp.	4	40-8452	Bear Creek Uranium Co.	8
40-0341	General Services Administration	4	40-8502	Irigaray Mine, Wyoming Mining Corp.	8
40-0672	Nuclear Metals, Inc.	4	40-8511	Cotter Corp,	10
40-1162	Western Nuclear, Inc.	4	40-8584	Union 76 Minerals Exploration Co.	10
40-1193	Babcock & Wilcox Co.	5	40-8585	Wyoming Mineral Corp.	10
40-1341	Edgemont Uranium Mine, TVA, and	5	40-8602	United Nuclear Corp.	10
	Mines Development, Inc.		40-8611	Dept. of the Air Force, Hill AFB, UT	10
40-2061	West Chicago Facility, Kerr-McGee Corp.	5	40-8663	Nuclear Dynamics, Inc.	10
40-2259	Pathfinder Mines Corp.	6	40-8672	Dept. of the Air Force, Hill AFB, UT	10
40-2384	RMI Co,	6	40-8681	Energy Fuels Nuclear, Inc.	10
40-2791	Kulite Tungsten Corp.	6	40-8692	Cotter Corp.	10
40-β392	Allied Chemical Corp,	6	40-8697	Rocky Mountain Energy Co,	10
40-3453	Atlas Minerals	6	40-8698	Plateau Resources, Ltd.	11
40-4492	Federal American Partners (Mining)	6	40-8710	Radiology Specialists, Southfield, MI	11
40-6622	Pathfinder Mines Corp.	7	40-8714	Cleveland Cliffs Iron Co.	11
40-6659	Petrotomics Co., Getty Oil Co.	7	40-8727	Kerr-McGee Nuclear Corp.	11
40-6920	Automation Industries, Inc.	7	40-8728	Teton Exploration Drilling Co., Inc.	11
40-7783	Boeing Co.	7	40-8742	Chemetron Corp.	11
40-7869	Plateau Resources, Ltd.	7	40-8743	Conoco	11
40-8027	Kerr-McGee Corp.	7	40-8745	Ogle Petroleum	11
40-8064	Exxon Minerals Co. USA, Exxon Corp.	7	40-8768	Kerr-McGee Nuclear Corp.	12
40-8084	Lisbon Mine, Rio Algom Corp.	8	40-8771	Nuclear Assurance Corp.	12
40-8102	Exxon Minerals Co. USA, Exxon Corp.	8	40-8778	Teton Exploration Drilling Co., Inc.	12
40-8200	Cleveland Cliffs Iron Co.	8	50-2	Univ. of Michigan Research Reactor	12
40-8348	In Situ Uranium Leaching Project	8	50-3	Indian Point Station, Unit 1	12

Docket	Name	Page	Docket	Name	Page
50-5	Pennsylvania State Univ. Research Reactor	13	50-141	Stanford Univ. Research Reactor	19
50-6	Battelle Memorial Institute Research Reactor	13	50-142	UCLA Training Reactor	20
50-8	North Carolina State Univ.	13	50-146	Saxton Nuclear Experimental Facility	20
	Research Reactor		50-147	Rockwell International Corp. Critical Facility	20
50-10	Dresden Nuclear Power Station, Unit 1	13	50-148	Univ. of Kansas Research Reactor	20
50-13	Babcock & Wilcox Co. Critical Facility	15	50-150	Ohio State Univ. Research Reactor	20
50-14	Battelle Memorial Institute Critical Facility	15	50-151	Univ. of Illinois Research Reactor	20
50-20	Massachusetts Institute of Technology Research Reactor	15	50-153	Bettis Critical Facility	21
50-22	Westinghouse Test Reactor	15	50-155	Big Rock Point Nuclear Plant	21
50-27	Washington State Univ. Research Reactor	15	50-156	Univ. of Wisconsin Research Reactor	23
50-29	Yankee-Rowe Nuclear Power Station	15	50-157	Cornell Univ. Research Reactor	24
50-34	Yankee Atomic Power Reactor	17	50-160	Georgia Institute of Technology Research Reactor	24
50-37	TRIGA-Mark I Prototype Reactor	17	50-163	General Atomic Co.	24
50-54	Union Carbide Research Reactor	17	50-166	Univ. of Maryland Research Reactor	24
50-57	State Univ. of New York Research Reactor	17	50-170	National Naval Medical Center	24
50-70	General Electric Test Reactor	17	50-171	Peach Bottom Atomic Power Station, Unit 1	24
50-72	Univ. of Utah Research Reactor	17	50-182	Purdue Univ. Research Reactor	24
50-83	Univ. of Florida Training Reactor	17	50-184	National Bureau of Standards Reactor	24
50-87	Westinghouse Critical Experiment	17	50-186	Univ. of Missouri Research Reactor	24
50-89	General Atomic Co.	18	50-187	Space Radiation Research Reactor	25
50-94			50-188	Kansas State Univ. Research Reactor	25
30-34	Rockwell International Corp, Research Reactor	18	50-191	Babcock & Wilcox Co. Critical Facility	25
50-97	Cornell Univ. Zero Power Reactor	18	50-192	Univ. of Texas Research Reactor	25
50-99	Babcock & Wilcox Co. Test Reactor	18	50-193	Rhode Island & Providence Plantations	25
50-106	Oregon State Univ.	18	50.000	AEC	
50-111	North Carolina State Univ. Research Reactor	18	50-200	Babcock & Wilcox Co, Test Reactor	25
50-112	Univ. of Okiahoma Research Reactor	18	50-201	West Valley Reprocessing Plant	25
50-116	Iowa State Univ. Research Reactor	18	50-206	San Onofre Nuclear Station, Unit 1	27
50-123	Univ. of Missouri Research Reactor	18	50-208	Columbia Univ. Research Reactor	30
50-128	Texas A&M Univ. Research Reactor	19	50-213	Haddam Neck Plant	30
50-133	Humboldt Bay Power Plant, Unit 3	19	50-219	Oyster Creek Nuclear Power Plant	32
50-139	Univ. of Washington Research Reactor	19	50-220	Nine Mile Point Nuclear Station, Unit 1	35

Docket	Name	Page	Docket	Name	Page
50-223	Univ. of Lowell Research Reactor	36	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	78
50-233	Mexico Research Reactor	36	50-277	Peach Bottom Atomic Power Station, Unit 2	81
50-234	Tungsten Nuclear Rocket Critical Facility	36	50-278	Peach Bottom Atomic Power Station, Unit 3	84
50-235	Accelerator Pulsed Fast Assembly	36	50-280	Surry Power Station, Unit 1	86
50-237	Dresden Nuclear Power Statinn, Unit 2	36	50-281	Surry Power Station, Unit 2	88
50-240	High Temperature Gas Cooled Critical Experiment	39	50-282	Prairie Island Nuclear Station, Unit 1	90
50-243	Oregon State Univ. Research Reactor	39	50-284	Idaho State Univ. Research Reactor	91
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	40	50-285	Fort Calhoun Station, Unit 1	91
50-245	Millstone Nuclear Power Station, Unit 1	41	50-286	Indian Point Station, Unit 3	93
50-247	Indian Point Station, Unit 2	44	50-287	Oconee Nuclear Station, Unit 3	94
50-249	Dresden Nuclear Power Station, Unit 3	45	50-289	Three Mile Island Nuclear Station, Unit 1	96
50-250	Turkey Point Plant, Unit 3	48	50-293	Pilgrim Nuclear Power Station, Unit 1	103
50-251	Turkey Point Plant, Unit 4	50	50-294	Michigan State Univ. Research Reactor	106
50-254	Quad-Cities Station, Unit 1	52	50-295	Zion Nuclear Power Station, Unit 1	106
50-255	Palisades Nuclear Plant	54	50-296	Browns Ferry Nuclear Power Station, Unit 3	108
50-256	Univ. of Montevideo Research Reactor	57	50-298	Cooper Nuclear Station	110
50-259		57	50-301	Point Beach Nuclear Plant, Unit 2	112
30-239	Browns Ferry Nuclear Power Station, Unit 1	3/	50-302	Crystal River Nuclear Plant, Unit 3	113
50-260	Browns Ferry Nuclear Power Station, Unit 2	59	50-304	Zion Nuclear Power Station, Unit 2	115
50-261	H. B. Robinson Plant, Unit 2	61	50-305	Kewaunee Nuclear Power Plant	117
50-262	Brigham Young Univ. Research Reactor	62	50-306	Prairie Island Nuclear Station, Unit 2	119
50-263	Monticello Nuclear Generating Plant	63	50-309	Maine Yankee Atomic Power Plant	120
50-264	Dow Chemical Co.	64	50-311	Salem Nuclear Generating Station, Unit 2	121
50-265	Quad-Cities Station, Unit 2	64	50-312	Rancho Seco Nuclear Generating Station	123
50-266	Point Beach Nuclear Plant, Unit 1	66	50-313	Arkansas Nuclear One, Unit 1	125
50-267	Fort St. Vrain Nuclear Generating Station	68	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	128
50-269	Oconee Nuclear Station, Unit 1	69	50-316	Donald C. Cook Nuclear Power Plant,	140
50-270	Oconee Nuclear Station, Unit 2	71	00010	Unit 2	129
50-271			50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	130
	Vermont Yankee Nuclear Power Station	73	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	132
50-272	Salem Nuclear Generating Station, Unit 1	75	50-320	Three Mile Island Nuclear Station, Unit 2	134
50-273	Beznau Nuclear Station, Unit 1, Switzerland	78	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	140
50-274	U.S. Geological Survey Research Reactor	78	50-322	Shoreham Nuclear Power Station	142

I	Docket	Name	Page	Docket	Name	Page
	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	143	50-369	William B. McGuire Nuclear Station, Unit 1	201
	50-324	Brunswick Steam Electric Plant, Unit 2	146	50-370	William B. McGuire Nuclear Station, Unit 2	203
	50-325	Brunswick Steam Electric Plant, Unit 1	149	50-373	LaSalle County Station, Unit 1	206
	50-327	Sequoyah Nuclear Plant, Unit 1	151	50-374	LaSalle County Station, Unit 2	207
	50-328	Sequoyah Nuclear Plant, Unit 2	154	50-375	Nuclear Examination Reactor	208
	50-329	Midland Plant, Unit 1	155	50-376	North Coast Nuclear Plant, Puerto Rico	209
	50-330	Midland Plant, Unit 2	157	50-378	Caorso Nuclear Station, Italy	209
	50-331	Duane Arnold Energy Center	160	50-382	Waterford Generating Station, Unit 3	209
	50-332	Barnwell Reprocessing Plant	161	50-387	Susquehanna Steam Electric Station, Unit 1	210
	50-333	James A. Fitzpatrick Nuclear Power Plant	162	50-388	Susquehanna Steam Electric Station, Unit 2	212
	50-334	Beaver Valley Power Station, Unit 1	164	50-389	St. Lucie Plant, Unit 2	213
	50-335	St. Lucie Plant, Unit 1	167	50-390	Watts Bar Nuclear Plant, Unit 1	214
	50-336	Millstone Nuclear Power Station, Unit 2	169	50-391	Watts Bar Nuclear Plant, Unit 2	215
	50-338	North Anna Power Station, Unit 1	171	50-395	Virgil C. Summer Nuclear Station, Unit 1	216
	50-339	North Anna Power Station, Unit 2	173	50-397	WPPSS Nuclear Project, Unit 2	218
	50-340	Seabrook Nuclear Station, Unit 1	176	50-400	Shearon Harris Nuclear Power Plant, Unit 1	219
	50-341	Enrico Fermi Atomic Power Plant, Unit 2	176	50-401	Shearon Harris Nuclear Power Plant, Unit 2	220
	50-344	Trojan Nuclear Plant	176	50-402	Shearon Harris Nuclear Power Plant, Unit 3	221
	50-346	Davis-Besse Nuclear Power Station, Unit 1	179	50-403	Shearon Harris Nuclear Power Plant, Unit 4	222
	50-348	Joseph M. Farley Nuclear Plant, Unit 1	181	50-404	North Anna Power Station, Unit 3	223
	50-352	Limerick Generating Station, Unit 1	182	50-405	North Anna Power Station, Unit 4	223
	50-353	Limerick Generating Station, Unit 2	184	50-409	La Crosse Boiling Water Reactor	223
	50-354	Hope Creek Nuclear Station, Unit 1	185	50-410	Nine Mile Point Nuclear Station, Unit 2	225
	50-355	Hope Creek Nuclear Station, Unit 2	186	50-412	Beaver Valley Power Station, Unit 2	226
	50-356	Univ. of Illinois LOPRA Research Reactor	187	50-413	Catawba Nuclear Station, Unit 1	227
	50-358	William H. Zimmer Nuclear Station, Unit 1	187	50-414	Catawba Nuclear Station, Unit 2	228
	50-361	San Onofre Nuclear Station, Unit 2	188	50-416	Grand Gulf Nuclear Station, Unit 1	230
	50-362	San Onofre Nuclear Station, Unit 3	190	50-417	Grand Gulf Nuclear Station, Unit 2	231
	50-363	Forked River Nuclear Station, Unit 1	191	50-423	Millstone Nuclear Power Station, Unit 3	233
	50-364	Joseph M. Parley Nuclear Plant, Unit 2	192	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	233
	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	194	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	234
	50-367	Bailly Generating Station	197	STN-50-437	Floating Nuclear Plant	234
	50-368	Arkansas Nuclear One, Unit 2	198	50-438	Bellefonte Nuclear Plant, Unit 1	234

Docket	Name	Page	Docket	Name	Page
50-439	Bellefonte Nuclear Plant, Unit 2	236	STN-50-488	Perkins Nuclear Station, Unit 1	260
50-440	Perry Nuclear Power Plant, Unit 1	237	STN-50-489	Perkins Nuclear Station, Unit 2	261
50-441	Perry Nuclear Power Plant, Unit 2	237	STN-50-490	Perkins Nuclear Station, Unit 3	261
50-443	Seabrook Nuclear Station, Unit 1	238	STN-50-491	Cherokee Nuclear Station, Unit 1	261
50-444	Seabrook Nuclear Station, Unit 2	239	STN-50-492	Cherokee Nuclear Station, Unit 2	261
50-445	Comanche Peak Steam Electric Station,	240	STN-50-493	Cherokee Nuclear Station, Unit 3	262
50.446	Unit I	242	STN-50-498	South Texas Project, Unit 1	262
50-446	Comanche Peak Steam Electric Station, Unit 2	243	STN-50-499	South Texas Project, Unit 2	264
STN-50-447	GESSAR-238	246	50-500	Davis-Besse Nuclear Power Station, Unit 2	267
50-452	Greenwood Energy Center, Unit 2	246	50-501	Davis-Besse Nuclear Power Station, Unit 3	267
50-453	Greenwood Energy Center, Unit 3	246	STN-50-508	WPPSS Nuclear Project, Unit 3	267
50-454	Byron Station, Unit 1	246	STN-50-509	WPPSS Nuclear Project, Unit 5	267
50-455	Byron Station, Unit 2	247	50-510	Blue Hills Station, Unit 1	268
50-456	Braidwood Station, Unit 1	247	50-511	Blue Hills Station, Unit 2	268
50-457	Braidwood Station, Unit 2	248	50-513	WPPSS Nuclear Project, Unit 4	268
50-458	River Bend Station, Unit 1	249	50-514	Pebble Springs Nuclear Plant, Unit 1	269
50-459	River Bend Station, Unit 2	249	50-515	Pebble Springs Nuclear Plant, Unit 2	269
50-460	WPPSS Nuclear Project, Unit 1	250	STN-50-516	Jamesport Nuclear Station, Unit 1	269
50-461	Clinton Power Station, Unit 1	250	STN-50-517	Jamesport Nuclear Station, Unit 2	270
50-462	Clinton Power Station, Unit 2	251	STN-50-518	Hartsville Nuclear Plant, Unit 1	270
50-463	Fulton Generating Station, Unit 1	252	STN-50-519	Hartsville Nuclear Plant, Unit 2	271
50-464	Fulton Generating Station, Unit 2	252	STN-50-520	Hartsville Nuclear Plant, Unit 3	271
50-466	Allens Creek Nuclear Station, Unit 1	252	STN-50-521	Hartsyille Nuclear Plant, Unit 4	272
50-467	Allens Creek Nuclear Station, Unit 2	254	STN-50-522	Skagit Nuclear Power Project, Unit 1	273
50-471	Pilgrim Nuclear Power Station, Unit 2	255	STN-50-523	Skagit Nuclear Power Project, Unit 2	273
50-472	Pilgrim Nuclear Power Station, Unit 3	255	STN-50-528	Palo Verde Nuclear Station, Unit 1	273
STN-50-477	Atlantic Generating Station, Unit 1	255	STN-50-529	Palo Verde Nuclear Station, Unit 2	274
STN-50-478	Atlantic Generating Station, Unit 2	255	STN-50-530	Palo Verde Nuclear Station, Unit 3	275
STN-50-482	Wolf Creek Generating Station	256	50-537	Clinch River Breeder Reactor	275
STN-50-483	Calloway Plant, Unit 1	256	50-538	Memphis State Univ. Research Reactor	275
STN-50-484	Tyrone Energy Park, Unit 1	259	STN-50-546	Marble Hill Nuclear Station, Unit 1	275
STN-50-485	Sterling Power Project Nuclear, Unit 1	259	STN-50-547	Marble Hill Nuclear Station, Unit 2	277
STN-50-486	Calloway Plant, Unit 2	259	50-549	Greene County Nuclear Power Plant	279

Docket	Name	Page	Docket	Name	Page
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	279	70-0754	Vallecitos Nuclear Center, General Electric Co.	290
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	279	70-0820	United Nuclear Corp.	290
STN-50-556	Black Fox Station, Unit 1	280		•	
STN-50-557	Black Fox Station, Unit 2	280	70-0824	Babcock & Wilcox Co.	291
50-564	Nuclear Fuels Recovery and Recycle Center	280	70-0882	Columbia Univ.	292
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	282	70-0925	Cimarron Pacility, Kerr-McGee Corp.	292
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	282	70-1068	Univ. of Florida	292
STN-50-568	NEP Nuclear, Unit 1	283	70-1100	Combustion Engineering, Inc.	292
STN-50-569	NEP Nuclear, Unit 2	283	70-1113	General Electric Co.	292
50-582	Sundesert, Unit 1	283	70-1143	Westinghouse Electric Corp.	292
50-583	Sundesert, Unit 2	284	70-1151	Westinghouse Electric Corp.	292
STN-50-596	New Haven, Unit 1	284	70-1192	Kerr-McGee Nuclear Corp.	293
STN-50-597	New Haven, Unit 2	284	70-1193	Cimarron Facility, Kerr-McGee Corp.	293
50-599	Carroll Facility I	284	70-1201	UF-6 Conversion Facility, Babcock & Wilcox Co.	293
50-600	Carroll Facility II	284	70-1257	Mixed Oxide Fabrication Plant,	294
70-0008	Battelle Columbus Laboratories	285		Exxon Nuclear Co., Inc.	
70-0025	Rockwell International Corp.	285	70-1308	Morris Operations, General Electric Co.	294
70-0027	Babcock & Wilcox Co.	285	70-1327	UF-6 Conversion Facility, Allied-General Nuclear Services Corp.	295
70-0033	Texas Instruments, Inc.	286	70-1363	Dept. of the Air Force	296
70-0036	Combustion Engineering, Inc.	286	70-1374	Idaho State Univ.	296
70-0048	Westinghouse Electric Corp.	286	70-1406	Veterans Administration Hospital,	296
70-0082	Nuclear Metals, Inc.	286	70-1432	New Orleans, LA	206
70-0134	Univ. of Wisconsin, Madison, WI	286	70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	296
70-0135	Babcock & Wilcox Co.	286	70-1447	Lancaster General Hospital, Lancaster, PA	297
70-0143	Nuclear Fuel Services, Inc.	287	70-1503	Westinghouse R&D Center, Westinghouse	297
70-0157	Univ. of Texas	288		Electric Corp.	
70-0162	Lucius Pitkin, Inc.	288	70-1703	Eastman Kodak Co.	297
70-0364	Parks Township Site, Babcock & Wilcox Co.	288	70-1821	Plutonium Production Facility, Allied- General Nuclear Services Corp.	297
	r Corp,	289	70-2185	Hillcrest Medical Center, Tulsa, OK	298
		290	70-2313	Nuclear Fuel Services, Inc.	298
	-chance Electric Corp.	290	70-2317	Teledyne Cast Products	298
		290	70-2478	Transnuclear, Inc.	299

Docket	Name	Page I	ocket	Name	Page
70-2479	Transnuclear, Inc.	299	71-5957	Model: BMI-1, Dept. of Energy	301
70-2560	Oklahoma Osteopathic Hospital, Tulsa, OK	299	71-5971	Model: GE-200, General Electric Co.	301
70-2609	Commonwealth Edison Co.	299	71-5998	Model: GE-400, General Electric Co.	301
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	299	71-6058	Model: B3-1, Nuclear Engineering Co.	301
70-2885	Commonwealth Edison	299	71-6089	Model: 33-FE-100, General Atomic Co.	301
70-2896	McKay-Dee Hospital Center, Ogden, UT	299	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	301
70-2909	Westinghouse Electric Corp. Power Systems	299	71-6273	Model: 48X, F, A, Y, Allied-General	301
70-2910	Tennessee Valley Authority	299	71 6004	Nuclear Services Corp.	
70-2913	Tennessee Valley Authority	299	71-6294	Model: UNC-2901, Combustion Engineering, Inc.	301
70-2926	Detroit Edison Co.	299	71-6346	Model: FSV-1, General Atomic Co.	302
70-2932	Texas Utilities Generating Co.	299	71-6347	Model: FSV-3, General Atomic Co.	302
70-2033	Eastman Kodak Co.	300	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	302
71-0018	Nuclear Assurance Corp.	300	71-6400	Model: Super Tiger, Westinghouse	302
71-0046	Teledyne Energy Systems	300	71 6400	Electric Corp.	200
71-0102	Source Products & Equipment Co., Inc.	300	71-6489 71-6581	Model: GB-0999B, General Atomic Co.	302
71-0371	Model: NNFD-10, Unified Nuclear Corp.	300	/1-0301	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	302
71-0385	Dept. of the Navy, Naval Nuclear Power Unit, Port Hueneme, CA	300	71-6601	Model: LL-50-100, Chem-Nuclear Systems, Inc.	302
71-0395	Dept. of the Navy, Naval Facilities Engineering Command	300	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	302
71-0396	Atcor Washington, Inc.	300	71-6717	Model: 6717 B	302
71-5026	Model: BC-48-220, Atcor, Inc.	300	71-6722	Model: BS-33-180, Tennessee Valley Authority	302
71-5059	Model: URANY NIT-TNK, Nuclear Fuel Services, Inc.	300	71-6744	Model: Poly Tiger, Nuclear Engineering Co.	302
71-5088	Model: D34710-1, U.S. Nuclear, Inc.	300	71-9001	Model: IF-300, General Electric Co.	302
71-5274	Model: UNC-1634, United Nuclear Corp.	300	71-9009	Model: FL-10-1, General Electric Co.	303
71-5442	Model: LA-36, Babcock & Wilcox Co.	300	71-9010	Model: NLI-1/2, NL Industries, Inc.	303
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	300	71-9011	Model: E-MEH-00-00004, Dept. of Transportation	303
71-5641	Model: UNC-2500	301	71-9016	Model: TN-9, Transnuclear, Inc.	303
71-5796	Model: 181361, Picker Corporation	301	71-9018	Model: BU-6, General Electric Co.	303
71-5805	Model: ATCOR VNDB Cask, Atcor, Inc.	301	71-9019	Model: BU-7, General Electric Co.	303
71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	301	71-9022	Model: CE-250-2, Combustion Engineering, Inc.	303
71-5926	Model: 100, General Electric Co.	301	71-9033	Model: 660 & 660E, Technical Operations, Inc.	303
71-5939	Model: GE-1500, General Electric Co.	301	71-9034	Model: TRIGA-1, General Atomic Co.	303

Docket	Name	Page	Docket	Name	Page
71-9036	Model: C-1, Source Production Equipme Co.	nt 303	71-9090	Model: 480M, Allied Chemical Corp.	304
71-9037	Model: TRIGA-2, General Atomic Co.	303	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	304
71-9039	Model: 715, Technical Operations, Inc.	303			
71-9044	Model: GE-1600, General Electric Co.	303	71-9132	Model: T-3, Nuclear Packaging, Inc.	304
71-9049	Model: GE-500, General Electric Co.	303	71-9136	Model: GE-9136, General Electric Co.	304
71-9057	Model: FPD-100, General Atomic Co.	303	71-9853	Model: ORNL - BNL - NBS,	304
71-9074	Model: AP-100, Anefco, Inc.	304		Unirradiated Fuel Container, Dept. of Energy	

1.11

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Accelerator Pulsed Fast Assembly	50-235	36	Braidwood Station, Unit 2	50-457	248
Allens Creek Nuclear Station, Unit 1	50-466	252	Brigham Young Univ. Research Reactor	50-262	62
Aliens Creek Nuclear Station, Unit 2	50-467	254	Browns Ferry Nuclear Power Station,	50-259	57
Arkansas Nuclear One, Unit 1	50-313	125	Unit 1		
Arkansas Nuclear One, Unit 2	50-368	198	Browns Ferry Nuclear Power Station, Unit 2	50-260	59
Duane Arnold Energy Center	50-331	160	Browns Ferry Nuclear Power Station,	50-296	108
Atlantic Generating Station, Unit 1	STN-50-477	255	Unit 3		
Atlantic Generating Station, Unit 2	STN-50-478	255	Brunswick Steam Electric Plant, Unit 1	50-325	149
Babcock & Wilcox Co. Critical Facility	50-13	15	Brunswick Steam Electric Plant, Unit 2	50-324	146
Babcock & Wilcox Co. Critical Facility	50-191	25	Byron Station, Unit 1	50-454	246
Babcock & Wilcox Co. Test Reactor	50-99	18	Byron Station, Unit 2	50-455	247
Babcock & Wilcox Co. Test Reactor	50-200	25	Calloway Plant, Unit 1	STN-50-483	256
Bailly Generating Station	50-367	197	Calloway Plant, Unit 2	STN-50-486	259
Barnwell Reprocessing Plant	50-332	161	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	130
Battelle Memorial Institute Critical Facility	50-14	15	Calvert Cliffs Nuclear Power Plant,	50-318	132
Battelle Memorial Institute Research Reactor	50-6	13	Unit 2		
Beaver Valley Power Station, Unit 1	50-334	164	Caorso Nuclear Station, Italy	50-378	209
Beaver Valley Power Station, Unit 2	50-412	226	Carroll Facility I	50-599	284
Bellefonte Nuclear Plant, Unit 1	50-438	234	Carroll Facility II	50-600	284
Bellefonte Nuclear Plant, Unit 2	50-439	236	Catawba Nuclear Station, Unit 1	50-413	227
Bettis Critical Facility	50-153	21	Catawba Nuclear Station, Unit 2	50-414	228
Beznau Nuclear Station, Unit 1, Switzerland	50-273	78	Cherokee Nuclear Station, Unit 1	STN-50-491	261
Big Rock Point Nuclear Power Plant	50-155	21	Cherokee Nuclear Station, Unit 2	STN-50-492	261
Black Fox Station, Unit 1	STN-50-556	280	Cherokee Nuclear Station, Unit 3	STN-50-493	262
Block Fox Station, Unit 2	STN-50-557	280	Clinch River Breeder Reactor	50-537	275
Blue Hills Station, Unit 1	50-510	268	Clinton Power Station, Unit 1	50-461	250
Blue Hills Station, Unit 2	50-511	268	Clinton Power Station, Unit 2	50-462	251
Braidwood Station, Unit 1	50-456	247	Columbia Univ. Research Reactor	50-208	30
· · · · · · · · · · · · · · · · · · ·	,	7.			

Name	Docket	Page	Name	Docket	Page
Comanche Peak Steam Electric Station, Unit 1	50-445	240	General Atomic Co.	50-89	18
	50.446	242	General Atomic Co.	50-163	24
Comanche Peak Steam Electric Station, Unit 2	50-446	243	General Electric Test Reactor	50-70	17
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	128	Georgia Institute of Technology Research Reactor	50-160	24
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	129	GESSAR-238	50-447	246
Cooper Nuclear Station	50-298	110	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	40
Cornell Univ. Research Reactor	50-157	24	Grand Gulf Nuclear Station, Unit 1	50-416	230
Cornell Univ. Zero Power Reactor	50-97	18	Grand Gulf Nuclear Station, Unit 2	50-417	231
Crystal River Nuclear Plant, Unit 3	50-302	113	Greene County Nuclear Power Plant	50-549	279
Davis-Besse Nuclear Power Station, Unit 1	50-346	179	Greenwood Energy Center, Unit 2	50-452	246
		267	Greenwood Energy Center, Unit 3	50-453	246
Davis-Besse Nuclear Power Station, Unit 2	50-500		Haddam Neck Plant	50-213	30
Davis-Besse Nuclear Power Station, Unit 3	50-501	267	Shearon Harris Nuclear Power Plant, Unit 1	50-400	219
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	78	Shearon Harris Nuclear Power Plant, Unit 2	50-401	220
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	143	Shearon Harris Nuclear Power Plant, Unit 3	50-402	221
Dow Chemical Co.	50-264	64	Shearon Harris Nuclear Power Plant,	50-403	222
Dresden Nuclear Power Station, Unit 1	50-10	13	Unit 4	5500 50 540	
Dresden Nuclear Power Station, Unit 2	50-237	36	Hartsville Nuclear Plant, Unit 1	STN-50-518	270
Dresden Nuclear Power Station, Unit 3	50-249	45	Hartsville Nuclear Plant, Unit 2	STN-50-519	271
Joseph M. Farley Nuclear Plant, Unit 1	50-348	181	Hartsville Nuclear Plant, Unit 3	STN-50-520	271
Joseph M. Farley Nuclear Plant, Unit 2	50-364	192	Hartsville Nuclear Plant, Unit 4	STN-50-521	272
Enrico Fermi Atomic Power Plant, Unit 2	50-341	176	Edwin I. Hatch Nuclear Plant, Unit 1 Edwin I. Hatch Nuclear Plant, Unit 2	50-321 50-366	140 194
James A. Fitzpatrick Nuclear Power Plant	50-333	162	High Temperature Gas Cooled Critical Experiment	50-240	39
Floating Nuclear Plant	STN-50-437	234	Hope Creek Nuclear Station, Unit 1	50-354	185
Forked River Nuclear Station, Unit 1	50-363	191	Hope Creek Nuclear Station, Unit 2	50-355	186
Fort Calhoun Station, Unit 1	50-285	91	Humboldt Bay Power Plant, Unit 3	50-133	19
Fort St. Vrain Nuclear Generating Station	50-267	68	Idaho State Univ. Research Reactor	50-284	91
Fulton Generating Station, Unit 1	50-463	252	Indian Point Station, Unit 1	50-3	12
Fulton Generating Station, Unit 2	50-464	252	Indian Point Station, Unit 2	50-247	44

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	93	New Haven, Unit 1	STN-50-596	284
Iowa State Univ. Research Reactor	50-116	18	New Haven, Unit 2	STN-50-597	284
Jamesport Nuclear Station, Unit 1	STN-50-516	269	Nine Mile Point Nuclear Station, Unit 1	50-220	35
Jamesport Nuclear Station, Unit 2	STN-50-517	270		60.410	225
Kansas State Univ. Research Reactor	50-188	25	Nine Mile Point Nuclear Station, Unit 2	50-410	225
Kewaunee Nuclear Power Plant	50-305	117	North Anna Power Station, Unit 1	50-338	171
La Crosse Bolling Water Reactor	50-409	223	North Anna Power Station, Unit 2	50-339	173
LaSalle County Station, Unit 1	50-373	206	North Anna Power Station, Unit 3	50-404	223
LaSalle County Station, Unit 2	50-374	207	North Anna Power Station, Unit 4	50-405	223
Limerick Generating Station, Unit 1	50-352	182	North Carolina State Univ. Research	50-8	13
Limerick Generating Station, Unit 2	50-353	184	Reactor		
Maine Yankee Atomic Power Plant	50-309	120	North Carolina State Univ. Research Reactor	50-111	18
Marble Hill Nuclear Station, Unit 1	STN-50-546	275	North Coast Nuclear Plant, Puerto Rico	50-376	209
Marble Hill Nuclear Station, Unit 2	STN-50-547	277	Nuclear Examination Reactor	50-375	208
Massachusetts Institute of Technology Research Reactor	50-20	15	Nuclear Fuels Recovery and Recycle Center	50-564	280
William B. McGuire Nuclear Station,	50-369	201	Oconee Nuclear Station, Unit 1	50-269	69
Unit 1			Oconee Nuclear Station, Unit 2	50-270	71
William B. McGuire Nuclear Station, Unit 2	50-370	203	Oconce Nuclear Station, Unit 3	50-287	94
Memphis State Univ, Research Reactor	50-538	275	Ohio State Univ. Research Reactor	50-150	20
Mexico Research Reactor	50-233	36	Oregon State Univ.	50-106	18
Michigan State Univ. Research Reactor	50-294	106	Oregon State Univ. Research Reactor	50-243	39
Midland Plant, Unit 1	50-329	155	Oyster Creek Nuclear Power Plant	50-219	32
Midland Plant, Unit 2	50-330	157	Palisades Nuclear Plant	50-255	54
Milistone Nuclear Power Station,	50-245	41	Palo Verde Nuclear Station, Unit 1	STN-50-528	273
Unit 1			Palo Verde Nuclear Station, Unit 2	STN-50-529	274
Milistone Nuclear Power Station, Unit 2	50-336	169	Palo Verde Nuclear Station, Unit 3	STN-50-530	275
Millstone Nuclear Power Station, Unit 3	50-423	233	Peach Bottom Atomic Power Station, Unit 1	50-171	24
Monticello Nuclear Generating Plant	50-263	63	Peach Bottom Atomic Power Station, Unit 2	50-277	81
National Bureau of Standards Reactor	50-184	24	Peach Bottom Atomic Power Station,	50-278	84
National Naval Medical Center	50-170	24	Unit 3	- J 21 T	0.1
NEP Nuclear, Unit 1	STN-50-568	283	Pebble Springs Nuclear Plant, Unit 1	50-514	269
NEP Nuclear, Unit 2	STN-50-569	283	Pebble Springs Nuclear Plant, Unit 2	50-515	269

Name	Docket	Page	Name	Docket	Page
Pennsylvania State Univ. Research	50-5	13	San Onofre Nuclear Station, Unit 3	50-362	190
Reactor	00°N 60 400	260	Saxton Nuclear Experimental Facility	50-146	20
Perkins Nuclear Station, Unit 1	STN-50-488	260	Seabrook Nuclear Station, Unit 1	50-340	176
Perkins Nuclear Station, Unit 2	STN-50-489	261	Seabrook Nuclear Station, Unit 1	50-443	238
Perkins Nuclear Station, Unit 3	STN-50-490	261	Scabrook Nuclear Station, Unit 2	50-444	239
Perry Nuclear Power Plant, Unit 1	50-440	237	Sequoyah Nuclear Plant, Unit 1	50-327	151
Perry Nuclear Power Plant, Unit 2	50-441	237	Sequoyalı Nuclear Plant, Unit 2	50-328	154
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	279	Shoreham Nuclear Power Station	50-322	142
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	279	Skagit Nuclear Power Project, Unit 1	STN-50-522	273
Pilgrim Nuclear Power Station, Unit 1	50-293	103	Skagit Nuclear Power Project, Unit 2	STN-50-523	273
Pilgrim Nuclear Power Station, Unit 2	50-471	255	South Texas Project, Unit 1	STN-50-498	262
Pilgrim Nuclear Power Station, Unit 3	50-472	255	South Texas Project, Unit 2	STN-50-499	264
Point Beach Nuclear Plant, Unit 1	50- 266	66	Space Radiation Research Reactor	50-187	25
Point Beach Nuclear Plant, Unit 2	50-301	112	Stanford Univ. Research Reactor	50-141	
Prairie Island Nuclear Station, Unit 1	50-282	90			19
Prairie Island Nuclear Station, Unit 2	50-306	119	State Univ. of New York Research Reactor	50-57	17
Purdue Univ. Research Reactor	50-182	24	Sterling Power Project, Nuclear, Unit 1	STN-50-485	259
Quad-Cities Station, Unit 1	50-254	52	St. Lucie Plant, Unit 1	50-335	167
Quad-Cities Station, Unit 2	50-265	64			
Rancho Seco Nuclear Generating Station	50-312	123	St. Lucie Plant, Unit 2 Virgil C. Summer Nuclear Station,	50-389 50-395	213 216
Rhode Island & Providence Plantations AEC	50-193	25	Unit 1 Sundesert, Unit 1	50-582	283
River Bend Station, Unit 1	50-458	249	Sundesert, Unit 2	50-583	284
River Bend Station, Unit 2	50-459	249	Surry Power Station, Unit 1	50-280	86
H.B. Robinson Plant, Unit 2	50-261	61			
tockwell International Corp. Critical	50-201		Surry Power Station, Unit 2	50-281	88
Facility	30-147	20	Susquehama Steam Electric Station, Unit 1	50-387	210
lockwell International Corp. Research Reactor	50-94	18	Susquehanna Steam Electric Station, Unit 2	50-388	212
alem Nuclear Generating Station, Unit 1	50-272	75	Texas A&M Univ. Research Reactor	50-128	19
Salem Nuclear Generating Station,	50-311	121	Three Mile Island Nuclear Station, Unit 1	50-289	96
Unit 2	20-211	161	Three Mile Island Nuclear Station, Unit 2	50-320	134
lan Onofre Nuclear Station, Unit 1	50-206	27	TRIGA-Mark I Prototype Reactor	50-37	17
lan Onofre Nuclear Station, Unit 2	50-361	188	Trojan Nuclear Plant	50-344	176

Name	Docket	Page	Name	Docket	Page
Tungsten Nuclear Rocket Critical Facility	50-234	36	Alvın W. Vogtle Nuclear Plant, Unit 1	50-424	233
Turkey Point Plant, Unit 3	50-250	48	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	234
Turkey Point Plant, Unit 4	50-251	50	Washington State Univ. Research Reactor	50-27	15
Tyrone Energy Park, Unit 1	STN-50-484	259	Waterford Generating Station, Unit 3	50-382	209
UCLA Training Reactor	50-142	20	Watts Bar Nuclear Plant, Unit 1	50-390	214
Union Carbide Research Reactor	50-54	17	Watts Bar Nuclear Plant, Unit 2	50-391	215
Univ. of Florida Training Reactor	50-83	17	Westinghouse Critical Experiment	50-87	17
Univ. of Illinois LOPRA Research Reactor	50-356	187	Westinghouse Test Reactor	50-22	15
Univ. of Illinois Research Reactor	50-151	20	West Valley Reprocessing Plant	50-201	25
Univ. of Kansas Research Reactor	50-148	20	Wolf Creek Generating Station	STN-50-482	256
Univ. of Lowell Research Reactor	50-223	36	WPPSS Nuclear Project, Unit 1	50-460	250
Univ. of Maryland Research Reactor	50-166	24	WPPSS Nuclear Project, Unit 2	50-397	218
Univ. of Michigan Research Reactor	50-2	12	WPPSS Nuclear Project, Unit 3	STN-50-508	267
Univ. of Missouri Research Reactor	50-123	18	WPPSS Nuclear Project, Unit 4	50-513	268
Univ. of Missouri Research Reactor	50-186	24	WPPSS Nuclear Project, Unit 5	STN-50-509	267
Univ. of Montevideo Research Reactor	50-256	57	Yankee Atomic Power Reactor	50-34	17
Univ. of Oklahoma Research Reactor	50-112	18	Yankee-Rowe Nuclear Power Station	50-29	15
Univ. of Texas Research Reactor	50-192	25	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	282
Univ. of Utah Research Reactor	50-72	17			
Univ. of Washington Research Reactor	50-139	19	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	282
Univ. of Wisconsin Research Reactor	50-156	23	William H. Zimmer Nuclear Station, Unit 1	50-358	187
U.S. Geological Survey Research Reactor	50-274	78	Zion Nuclear Power Station, Unit 1	50-295	106
Vermont Yankee Nuclear Power Station	50-271	73	Zion Nuclear Power Station, Unit 2	50-304	115

1		

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

- 801022018B PNO-V-80-071. on 800923. Region 5 notified by State of NV that entire US Army had been banned from use of low level waste burial site at Beatty, NV Based on several itams of noncompliance all Army burial permits cancelled. THOMAS.R D Region 5. San Francisco, Office of the Director 80/09/24.
- 8010200613 Notification of contract execution "Low Level Waste Radwaste Records for NECO Sites," awarded to Nuclear Engineering Co. Inc.
 HAIRSTON, C. Technical Assistance Contracts Branch FIN 8-6974-0
 80/09/30 in
- --8010200423 Contract "Low Level Waste Radwaste Records for NECO Sites," awarded to Nuclear Engineering Co. Inc., (subs. of Teledyne, Inc.)

 **Nuclear Engineering Co. Inc., (subs. of Teledyne, Inc.)

 **DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN B-6974-0 80/09/30, 11p
- 8010220206 PNO-I-80-1398 on E01003, re shipment of low level waste w/ leaking drum Leaking drum & box repackaged for shipment to licensee State of RI has requested NRC to increase insp of licensee activities KINNEY, W H, CROCKER, H W, SMITH, O H Region 1, Philadelphia, Office of the Director. 80/10/03 2pp
- 8010270140 Add1 response to FDIA request for documents re sites used for dumping radwasts off Pacific Coast Forwards documents listed in App A NRC action is completed FELTON, J. M. Division of Rules and Records 80/10/21 2pp
- --8010270149 Forwards addl info in support of 580215 application for matl/byproduct license re disposal of radwaste.application for interim license & description of method for packaging radwaste LAN, J. E. Nuclear Engineering Co . Inc . (subs. of Teledyne, Inc.) 58/03/28, 1p
- --8010270156 Application for matl/byproduct license authorizing JE Law to use &/or supervise use & disposal of 400 Ci byproduct & source matl & 2 g SNM in any byproduct source & SNM Addl info re license applications and LAN, J. E. Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) 58/03/28 52pp

DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO.

- 8010090545 Forwards listed data to assist in contract to characterize existing surface conditions at facility Aerial photograph will be provided after sits visitation, if needed, H/o encls TURI.G.P. Low Level Waste Licensing Branch FIN B-6970-0. 80/07/08. 1p
- 8010280267 Forwards Waste Packaging Insp Rept 15000037/80-15 on 800727-0801 No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/09/19. 2pp
- --8010280274 Waste Packaging Insp Rept i5000039/80-15 on 800727-0801
 No noncompliance noted Major areas inspected shipping paper
 requirements, DOT placarding requirements, radiation levels
 MACARTHUR, TC Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch. 80/09/16. Spp.
- 8010300168 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted 8TOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/09/19 2pp.

- ---8010300179 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801
 No noncompliance noted Major areas inspected shipping paper.
 DUT placarding radiation levels, removable contamination &
 DUT marking & labeling requirements for packages
 MACARTHUR.T C . POTTER.J P Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch 80/09/16 8pp
- 8010300360 Forwards Waste Packaging Insp Rept 19000039/80-15 on 800727-0801 No noncompliance noted STOHR, J. P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/07/19 2pp
- --8010300369 Wasts Packaging Insp Rept 15000039/80-15 on 800727-0801.

 No noncompliance noted Major areas inspected, shipping paper,
 DOT placarding, radiation levels, removable contamination &
 DOT marking & labeling requirements for packages
 MACARTHUR.T C Region i, Philadelphis, Fuel Facility & Materials
 Safety Branch POTTER.J.P Region 2, Atlanta, Fuel Facility &
 Materials Safety Branch 80/09/16 Gpp
- 8010200646 Notification of contract execution: "Evaluation of Location & Rates of Oroundwater Discharge from Sheffield Low Lavel Waste Disposal Facility:" awarded to DDI HAIRSTON. C Technical Assistance Contracts Branch FIN 8-6967-0, 80/09/25 1p
- --8010200653 Contract "Evaluation of Location & Rates of Groundwater Discharge from Sheffield Low Level Wester Disposal Facility," awarded to DDI BAJEMA, D. Interior, Dept of DDUOHERTY, D. J. Technical Assistance Contracts Branch FIN 8-6967-0 80/09/25 Spp
- 8010200613 Notification of contract execution: "Low Level Haste Radwaste Records for NECO Sites," awarded to Nuclear Engineering Co. Inc.
 MARSTON.C Technical Assistance Contracts Branch FIN 8-6974-0
 80/09/30 1p
- --B010200623 Contract "Low Leve) Waste Radwaste Records for NECO Sites,"
 awarded to Nuclear Engineering Co. Inc
 * Nuclear Engineering Co. inc. (subs of Teledyne, Inc.)
 DUOMERTY,D J Technical Assistance Contracts Branch FIN
 B-6974-0 80/09/30 iip
- 8010300465 Notification of FL Doyle 801007 familiarization visit to Sheffield low level waste disposal facility. Conveys Belfken & Shaffner request to visit site on 801014-15 to observe site conditions & gather environ assessment info.

 SMITHIR D High Level Waste Technical Development Branch. 80/10/02 ip
- 8010100127 Order granting extension until 801020 for Commission to review ALAB-606 CHILKIS J Office of the Secretary of the Commission 80/10/03 ip
- 8010300111 Forwards "Characterization of Existing Burface Conditions at Sheffield Low Level Waste Disposal Facility," final rept for Jul 1980 MARTIN.J.B Division of Waste Management. 80/10/06 2pp
- --8010300119 "Characterization of Existing Burface Conditions at Sheffield Low Level Maste Disposal Facility," final rept for Jul 1980 HEIM.6 E : MACHALINSKI.M Harding-Lawson Associates. NRC-02-80-057 NUREO/CR-1683. B0/07/31. 108pp.
- 8010140347 Response to NRC 800923 motion for clarification of 800909 prehearing conference order Relief would eliminate threshold consideration of NRC jurisdiction over Nuclear Engineering Co Certificate of Suc encl.
 CONNER.T.B. RADER.R.M. Nuclear Engineering Co , Inc , (subs. of Teledyne, Inc) CONNER.T.B. Conner, Houre & Corber 80/10/08, 6pp

- 8010140522 Notice of withdrawal from proceeding SIMPER, L N Hearing Branch 2 80/10/10. ip
- B010190005 Advases of filing first set of interrogatories to Nuclear Engineering Co NRC awaits ASLB ruling on followup discovery & depositions LEBBY,R.P Hearing Branch 4 80/10/10. 2pp.
- 801018004B First set of interrogatories & request for production of documents Requests into re 1988 acquisition of CA Nuclear, Inc. correspondence w/Teledyne. Inc & actions tatem re license termination Certificate of Buc encl.
 LESSY, R P. Antitrust Division 80/10/10, 14ap.
- 8010150537 Notice of TG Baer & JN Neel depositions & request for production of documents SEKULER'S N : FAMPER'T C Illinois, State of, 80/10/10 2pp.
- --B010150542 Notice of H Althouse & A Crase depositions & request for production of documents.
 SEMULERIS, N. FAMMER, T. C. Illinois, State of B0/10/10 2pp
- --8010150547 Notice of CF Eason & RA Shoenig depositions & request for production of documents SEKULER,8 N. FAHNER, T.C. 111inois, State of. 80/10/10. Rpp.
- --8010150551 Notice of BT Reider & HH Botton depositions & request for production of documents.

 SKULLER, B. N. FAHNER, T. C. Illinois, State of. 80/10/10. 2pp.
- --8010150536 Notice of HM Hipsher & HO Heulton depositions & request for production of documents.
 SEKULERIS N. FANNER, T.C. Illinois, State of 80/10/10, 2pp
- --BD101B0562 Notice of V Abble & D Bickford depositions & request for production of documents.

 BEKULER, 8 N . FAHMER, T C Illinois, State of. BO/10/10 2pp.
- --8010180367 Notice of D Buckner & SV Wright depositions & request for production of documents SEKULERIS N. FARMERIT.C. Illinois, State of 80/10/10 2ps.
- --8010150569 Notice of RE Phalen & A Arabrust depositions & request for production of documents SEKULER'S N. FANNER', T.C. Illinois: State of. 80/10/10 28p.
- --8010130377 Notice of V DePoir deposition & request for production of documents Certificate of Evc encl.

 BEKULER: 8 N , FAHNER: T.C. Illinois, State of 80/10/10. 4pp.
- B010:3039A Interrogatories directed to other intervenors requesting identity of persons & documents used in formulating position on MRC conditions proposed for Nuclear Engineering Co DL termination. W/Cestificate of Buc Related correspondence.

 WANAT, B W , CANNON, J M American Nuclear Society B0/10/10 Spp
- O10150603 Interrogatories soliciting info re identity of those involved in NRC position on conditions for termination of Nuclear Engineering Co OL witheases & documents relied upon. Certificate of Box encl Related correspondence.

 HANAF.S. H., CAMNON, J. K. American Nuclear Society, 80/10/10 ópp.
- CO10150536 Application for subpoens for B01104 deposition of UN Neel. Certificate of Bvc entl.Related correspondence ANSPACH.K. G. FAHNER, T. C. Illinois: State of. B0/10/10. App.
- Oi0150639 First request for production of documents of applicant, Nuclear Engineering Co Requests insp repts & documents describing radionuclide migrations brench failure & leaching tests Certificate of Byc encl. Related correspondence.

 BEKULER: S. N., FAHNER: T. C. Illinois, State of. BO/10/10. 7pp.
- 010160774 Request for designation of Intervenor witnesses, SEKULER, S. N. . FARNER, T. C. Illinois, State of. 80/10/10. 2pp.
- -8010160777 First set of interrogatories to applicant. Nuclear Engineering Co soliciting info re organization, shareowners, decision to abandon facility, radwaste containers & removal of radioactive meti. Certificate of 8vc encl.

 SEMULER: 8 N FARMER: T C. Illinois. State of. 80/10/10. 22pp.
- DIG200517 Forwards Nuclear Engineering Co requests for admissions, interrogatories & requests for production of documents, addressed to NRC. Btate of IL & intervenors, Discovery request response deadline is 803101. Related correspondence CONNER. T. B. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.), CONNER. T.B. Conner, Moore & Corber, 80/10/10 ip.

- --B010200931 Requests that ABLAB direct NRC to respond to interrogatories contained in encl requests for admissions, interrogatories & requests for production of documents CONNER, T B. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.) CONNER, T B. Conner, Moore & Gorber B0/10/10 1p
- --8010200537 Nuclear Engineering Co requests for admissions, interrogatories & requests for production of documents re NRC past actions & positions concerning conditions at Sheffield site.
 CONNER: T B Nuclear Engineering Co., Inc., (subs. of Teledyne. Inc.). CONNER: T B Conner, Moore & Corber 80/10/10 18pp
- --8010200545 Nuclear Engineering Co requests for admissions, interrogatories & requests for production of documents, addressed to Btate of IL.
 CONNERT.T.B. Nuclear Engineering Co., Inc., (subs. of Teledyne. Inc.). CONNER.T.B. Conner, Hoore & Corber. 80/10/10, 9pp
- ~~8010200550 Nuclear Engineering Co interrogatories & requests for graduction of documents, addressed to intervenors CONNER, T. B. Nuclear Engineering Co., Inc.; (subs of Teledyne, Inc.) CONNER, T. B. Conner, Moore & Corber. 80/10/10. Spp
- ~-8010200560 Nuclear Engineering Co requests for interrogatories & requests for production of documents, addressed to intervenor County of Bureau, Certificate of Byc encl CONNER, T. B. Nuclear Engineering Co. Inc., (subs. of Teledyne, Inc.) CONNER, T. B. Conner, Moore & Corber 80/10/10 7pp.
- 8010170091 Request for 2-wk extension in all phases of ABLB 800909 prehearing conference order re discovery schedule due to recent availability of rept on site surface conditions Certificate of Bvc encl CONNER.T.B Nuclear Engineering Co , Inc , (subs. of Teledyne, Inc.). CONNER.T.B. Conner, Moore & Corber 80/10/14, Spp.
- 8010160782 Request for 2-wk extension in discovery schedule re "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Disposal Facility" due to recent evaliability Certificate of Svc encl.
 CONNER.T B. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). CONNER.T B. Conner, Moore & Corber 80/10/15. Spp.
- S010220319 Response in apposition to Chicago Section of ANB Interrogatory 4, based upon incorrect assumption, 7 & 9 for ambiguity & 10 & 15 for lack of specificity. Certificate of Byc encl
 LESSY, R P Hearing Branch 3, 80/10/20 6pp
- 8010220508 Response in opposition to State of IL first set of interropatories. Files aiready inspected & are still open for further insp. Certain info privileged re work-product & client-atty communications
 CONNER, T. B., RADER, R. M. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). GONNER, T B. Conner, Moore & Corber. 80/10/20, 100a
- 8010220515 Response in opposition to NRC first set of interrogatories & request for production of documents. Files already inspected & are still open for further insp. Certain info privileged re work product & client-atty communications. CONNER, T. B., RADER, R. M. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). CONNER, T. B. Conner, Moore & Corber. 80/10/20. 780.
- 8010220520 Motion to vacate State of IL 801010 notices of deposition & requests for production of documents. Request contrary to ASLB 800909 order & fails to comply w/rules of practice CONNER: T B., RADER; R. M. Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). CONNER, T. B. Conner, Moore & Corber. 80/10/20 7pp.
- 8010220537 Order granting extension until 801027 for Commission to elect whether to review ALAB~606 CHILK, S. J. Office of the Secretary of the Commission. 80/10/20
- 8010240063 Response in opposition to all interrogatories & requests for production of documents & admissions served on State of IL., Specific objections & answers will be filed in proper time. Cartificate of Svc encl. Related correspondence.

 ANSPACH.K.Q., FAHNER.T.C Illinois, State of. 80/10/20, 2pp.
- 8010280015 Notice of appearance in proceeding Notice of BN Sekuler withdrawal & Certificate of Svc encl.
 ANSPACH.K.O. Illinois, State of 80/10/20 4pp.
- 8010230424 Forwards corrected Page & to objections by Nuclear Engineering Co. Inc to NRC first set of interregatories & request for production of documents Related correspondence, RADER,R. M. Conner, More & Gorber, 80/10/21, 2pp.

- 8010240074 Order clarifying NASLP 800907 prehearing conference order, upon NRC motions Evidence on three issues of order will be heard at hearings, after which initial decision will be issued Time will be granted to parties re depositions.
 ODODHOPE, A C Atomic Safety and Licensing Board Panel 80/10/21
- 8010280010 Response in opposition to Nuclear Engineering 601010 requests for admissions, interrogatories & documents premised on requests Beeks protective order due to factual & legal irrelevance Certificate of Bvc encl
 REIS.E J. Hearing Branch 3 80/10/23 27pp
- 8010280621 Forwards NRC 801023 objections to Nuclear Engineering interrogatories & requests for admissions & production of documents, Pleading constitutes reply to TB Conner 801010 ltr to HJ Dircks, H/o encl.

 REIG. E. J. Hearing Branch 3 80/10/23 ip.
- 8010270380 Requests for admissions, interrogatories & request for production of documents re NUREO/CR-1663 on characterization of existing surface conditions Certificate of Buc Related correspondence CONNER.T.B Nuclear Engineering Co., Inc., (subs of TeledyneInc.), CONNER.T.B Conner, Moore & Corber B0/10/24, 13pp.
- 8010270348 Informs that, on 801027, ALAB-606 became final agency action for purposes of judicial review CHILK.B. J. Office of the Secretary of the Commission, 80/10/27.

DOCKET 27-047 BARNWELL, BC . CHEM-NUCLEAR BYSTEMS

- 8003240244 Forwards Hasts Package Insp Rept 79-06A on 791126-28 No noncompliance noted. SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/12/31 2pp.
- --B003240287 Waste Packaging Insp Rept 79-06A on 791126-28, No nuncompliance noted. Major areas inspected shipping paper requirements. DOT placarding requirements radiation levels. removable contamination & DOT marking.
 POTTER, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/12/12. 7pp
- 8004080145 Forwards Waste Packaging Insp Rept 80-02A on 800206-08. No noncompliance noted. 8TOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/26. Spp
- --B0040B0147 Waste Packaging Insp Rept 80-02A on 800206-08, No noncompliance noted. Major areas inspected. DOT & NRC requirements including shipping paper. DOT placard, radiation levels, marking & labeling.
 POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 80/02/20. App.
- 8005120223 Forwards Waste Packaging Insp 80-03 on 800227-29 No noncompliance noted. STOHR,J.P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/03/20 2pp.
- --B005120230 Waste Packaging Insp Rept B0-03 on B00227-29. No noncompliance noted Major areas inspected; placarding requirements radiation levels, marking & labeling requirements for packages.
 POTTER.J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch, 80/03/17 7pp
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted. STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/04/07. 2pp.
- --8005230341 Waste packaging insp rept on 800313-14. No noncompliance noted, Major areas inspected; licensed-shipper vahicles inspected for compliance w/DOT & NRC regulations including shipping paper & DOT placerding requirement, POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/03/28, 4pp.
- 8006040077 Forwards Haste Packaging Insp Rept 80-05 on 800319.No noncompliance noted. 8TOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/04/14. 2pp.

- --8006040082 Waste Packaging Insp Rept 80-05 on 800319. No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & prohibited articles of contents, POTTER. J. P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/04/04. App
- 8008060175 Forwards Haste Packaging Insp Rept i5000039/80-07 on 800515 & 16 No noncompliance noted. 8TOHR, J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 8D/06/R3 2pp
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance noted Major areas inspected, compliance w/NRC & DOT regulations TROUP.O L. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/06/23 App.
- 8010100428 Ack receipt of 800905 itr informing NRC of steps taken to correct violation noted in IE Insp Rapt 50-277/80-27 & Waste Packaging Insp Rept 15000039/80-09 SMITH, 0 H Region i, Philadelphia, Fuel Facility & Materiale Safety Branch 80/09/15. ip.
- ~~80i0i00431 Responds to NRC 800814 ltr re violations noted in IE Insp. Rept 50~277/80~27 & Waste Packaging Insp. Rept 15000039/80~09 Corrective actions installing permanent flip signs on front of all trailers used at facility GALLAOHER.J W Philadelphia Electric Co. 80/09/05. 2pp.
- ---8010100434 Forwards IE Insp Rept 50-277/80-27 on 800605 & notice of violation. Waste Packaging Insp Rept 15000039/80-09 also enc!
 BMITH.O.H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 80/08/14 2pp.
- --8010100434 Notice of violation from insp on 800605 * Region 1, Philadalphia, Office of the Director 80/07/28. ip.
- --8010100438 IE Insp Rept 50-277/80-27 on 800605 Noncompliance noted. failure to placard front of vehicle u/radioactive sign MACARTHUR.T G. Region i, Philadelphia, Office of the Director. POTTER.J P. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 80/07/28 jp.
- --8010100441 Waste Packaging Insp Rept 15000037/80-07 on 800605.
 Noncompliance noted, failure to placard front of vehicle w/radioactive sign.
 MACARTHUR, T. G., POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/07/28. Spp.
- B010210296 Ack receipt of documents supporting relicensing action for SNM receipt storage & disposal Questions forwarded re site license application, std operating procedures, environ assessment & pre-liminary site stabilization & closure plan. PANOBURN, O. G. Low Level Haste Licensing Branch. 80/10/03. Spp.

DOCKET 27-048 RICHLAND, WA. , NUCLEAR ENGINEERING CO.

- 8010180500 Forwards IE Insp Repts 50-320/80-10 & 50-320/80-14 on 800317-0411 Waste Packaging Insp Rept 15000046/80-72 also encl. ORIER, 8. H. Region 1, Philadelphia, Office of the Director. 80/08/12. 2pp.
- --B010150511 IE Insp Repts 50-320/B0-10 & 50-320/B0-14 on B00317-0411.
 Noncompliance noted: failure to use leak resistant containers
 for radioactive liquid shipments & failure to comply w/
 authorized packaging for Type A shipment
 FABANO,A.N., THONUB,L.H., BHANBAKY.M.M. Region 1: Philadelphia:
 Office of the Director. B0/07/30. Opp.
- ---B01015051B Waste Packaging Insp Rept 15000046/80-72 on 800610, Noncompliance noted loose locking ring & broken weld observed on shipping containers.

 ZURAKCHRKI.P. Region 5, San Francisco, Office of the Director. THOMAB.R.D., BDOK.H.E. Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch. 80/06/30. App.
- 8010140037 Forwards Waste Packaging Insp Rept 15000046/80~74 & notice of violation.

 8RGNN, O.D. Region 4, Dellas, Fuel Facility & Materials Bafety
 Branch. 80/09/02 2pp
- --B010140040 Notice of violation from inep on 600518.

 * Region 4. Dellas, Office of the Director. 80/07/21. 2pp.

- ---B010140044 Ferwards Waste Packaging Insp Rept 15000046/80-74 on 800618 One item of noncompliance w/DDT/NRC regulations identified B00K,H E Region 3, San Francisco, Fusi Facility & Materials B4fety Branch 80/07/22 ip
- --B010140049 Waste Packaging Insp Rept 15000046/80-74 on 800618 Noncompliance noted improper radioactive labels attached to two containers Shipper to receive warning itr re item of noncompliance FONO.F T Region 5. Ban Francisco, Office of the Director. THOMAS.R D . B00K: M E Region 5. San Francisco, Fuel Facility & Materials Safety Branch 800/07/21 dpp
- 8010200613 Notification of contract execution "Low Level Waste Radwaste Records for NECO Sites." awarded to Nuclear Engineering Co. Inc.
 HAIRBION.C Technical Assistance Contracts Branch. FIN 8-6974-0. 80/09/30. ip
- --8010200623 Contract: "Low Level Waste Radwaste Records for NECO Bites," awarded to Nuclear Engineering Co.Inc * Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.). FIN 8-6774-0 80/09/30 11p
- 8010220546 PNO-V-80-072° on 80100B, Ragion 5 notified that State of WA has cancelled burial permit & banned Hount Sinai Hosp. New York, NY from use of Richland, WA burial site Action based upon noncompliance re leaking drum
 THOMAS: 8 D Region 5. San Francisco, Office of the Director 80/10/08 ip

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP.

- 8010140593 FOIA request for environ repts & other documents re Union Carbide & operation of Oas Hills U mill OIROUARD,P Black Hills Alliance 80/08/01 2pp
- 8010230614 Comments on Oas Hills U Project FEB for NRC licensing action. Possibility of draining residual fluid in tailings gond should be investigated. Composites of weekly filter samples should be screened monthly HILLIAMS, R.L. Environmental Protection Agency. BO/09/17 ip
- 8010270435 Submits addl info re evaluation of Union Carbide stability analysis of evaporation ponds at East Cas Kills site.

 Technical portions of static & dynamic stability analysis meet NRC requirements.

 HANSON, W.W. Barr Engineering Co. 80/09/17. Opp
- 8010220139 Recommends approval of Amend 16 to Source Matl License 8UA-64B Amend authorizes const & operation of two evaporation ponds KUTSCH, J. L, GLLEN, D. H. LINEHAN, J. J. Uranium Recovery Licensing Branch 80/09/22, 6pp
- 8010220301 Amend 16 to Source Matl License SUA-648, authorizing use of two symporation pends for storage & symporation of tailings liquor pumped from below-grade tailings disposal impoundment BCARANO, R A Uranium Recovery Licensing Branch. 80/07/22. 3pp
- 8010270308 Ack receipt of final EIS.NURED-0702 in which proposed revisions are not incorporated Requests that document reasin open until six items of contern are reviewed & resolved REKEHEYER.P.C. Union Carbide Corp. 80/10/01. 2pp
- 8010140591 Responds to FOIA request for environ repts & other documents re Union Carbide & operation of Gas Hills V mill. Forwards documents listed in App A NRC was unable to locate environ rept for Pab 1976. H/O encis.

 FELTON, J M. Division of Rules and Records 80/10/08 2pp.
- 010280391 Forwards addl Info re Amend 16.Condition 1 of License 8UA-0448.consisting of Miller Testing Co final rept. "QC Testing for Evaporation Ponds "
 HONG: T Union Carbide Corp. 80/10/23, 79pp.

CKET 40-0341 GENERAL SERVICES ADMINISTRATION

10200386 Approves 800822 request for release of Bidg 921 at Gurtis Bay, MD, for unrestricted use. Contamination levels are within current NRC guidelines. Permission must be granted by Matis Licensing Branch prior to actual release.

KINNEMARJD. Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/09/15 ip.

- --8010200370 Requests release of Bidg 921 at Curtis Bay, MD for unrestricted use All radwaste disposed of at Barnwell.SC site Radiological checks determined readings below 0.5 mr/hr CAMPBELL, W.R. General Services Administration 80/08/22 1p
- DOCKET 40-0672 NUCLEAR METALS, INC.
- 8010220143 Ack receipt of 800731 & 0825 ltrs forwarding final rept re smoke release from reduction furnace Matter will be reviewed during next insp KINNEMAN.J D Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/09/15 10
- --B010220149 Notifies of incident involving reduction furnace for conversion of green salt to derby in which escape & subsequent ignition of magnesium vapor occurred Furnace may be interrupted for more than 1 day GILMAN.A R Nuclear Metals. Inc 80/07/31 ip
- --8010220155 Forwards rept of facility 800730 smoke release incident Cause of smoke was release of magnesium oxide fume from furnace reduction chamber due to incomplete sealing of chamber OILMAN A R Muclear Metals, Inc. 80/08/25 7pp
- 8010020500 EN-80-046 on 800926, notice of violation & notice of proposed imposition of civil penalty will be issued for license. Action based on items of noncompliance re delivery of packages of low specific activity radioactive matl ENDOKEYT.T U., THOMPSDN.D Office of Inspection & Enforcement, Office of the Director 80/09/24 ip
- 8010100242 Discusses IE insp on 800618 & 0730-0801 & forwards notice of violation & notice of proposed imposition of civil penalty. STELLO, V Office of Inspection & Enforcement. Office of the Director 80/07/26. 2pp
- --8010100243 Notice of violation from insp on 800618 & 0730-0801 Noncompliance noted upon arrival of low specific activity mat1 at burial site, dose rate to occupied position in truck was in excess of limits # Office of Inspection & Enforcement, Office of the Director. 80/09/26 ip
- -8010100248 Notice of proposed imposition of civil penalty in amount of 42,000 for item of noncompliance noted in IE insp on B00618 & 0730-0801.

 * Office of Inspection & Enforcement, Office of the Director B0/09/26 | 1p
- 8010160646 Responds to NRC B00926 Itr re special insp of activities involving transportation of radioactive waste Corrective actions adding supervisory staff to functions of packaging, audit & insp
 TUFFIN.W B Nuclear Metals, Inc 80/10/03 3pp

DOCKET 40-1162 WESTERN NUCLEAR: INC

- 8009090219 Forwards "Rept on Extension of Ground Magnetometer Survey. Hestern Nuclear Split Rock Tailings Impoundment, Jeffrey City.WY " BB00BN.0 Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/08/04 Ip
- --8009070223 "Rept on Extension of Ground Magnetometer Survey, Western Nuclear Split Rock Tailings Impoundment Jeffrey City, WY "
 SPECTOR, A Allan Spector & Associates, Ltd J234. 80/07/31 9pp.
- BO10140625 FOIA request for 13 documents re facilities
 JUNEB, L. Black Hills Alliance. 80/08/21 2pp
- 8010020132 Forwards Bplit Rock Mill tailings dam inep rept for 800818-24 800DEN.0 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/08/25 4pp
- 8010140171 Forwards inservice insp rept from 800901-07. BOODEN, C. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.), 80/09/09 19.
- -8010140191 Inservice insp rept on 800901-07. Daily insp for cracking, sloughing, movement, settlement, seepage & distance of water from crest revealed no abnormalities. Tabulations of water elevations in plezometers & weekly monument survey encl CRONK, R J Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/09/08 3pp.

- 8010140627 Clarifies ref to "dump area" in D'Appolonia rept discussed w/NRC on 800922 Rept does not intend to imply that NRC was intimately familiar w/dump area & subsequent removal BUGDEN, O Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/09/10
- 8010240044 Forwards response to proposed language for license conditions re groundwater monitoring & protection EAST.D J Wyoming Outdoor Council 80/09/11 3pp
- 8010190658 Forwards Split Rock mill tailings dam insp rept for 800908-14 BOQDEN.O Western Nucleur, Inc (subs of Phelps Dodge Corp) 80/09/14 App
- 8010240004 Forwards tailings dam insp rept for 800915-21 8000EN.O Western Nuclear, Inc (subs of Phelps Dodge Corp). 80/09/24. 4pp
- 8010230248 Submits info requested in 800725 telcon re-spacing for resistivity survey Soundings should be spaced at five times min channel size 8000EN.G Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/09/30 3pp
- 8010270352 Forwards Split Rock mill tailings dam insp rept for 800922-28 BAODEN, O Western Nuclear, Inc. 80/09/30 4pp
- 8010270302 Advises of preparation & distribution of proposed Split Rock mill license conditions, as result of 800813 meeting Objects to Condition il which raises question of applicability of federal or state stds Urges delation of condition BOGDEN, O Western Nuclear, Inc. (subs of Phelps Dodge Corp.), 80/10/03 2pp
- 8010240013 Authorizes payment for travel costs & prof svcs for R Williams re 801027-31 visit to NRC in Silver Spring.MD. 8CARAND, R. A. Uranium Recovery Licensing Branch. 80/10/06. 1p
- 80i0140621 Responds to FOIA request for 13 documents re facilities. Forwards documents re Dockets 40-1341,40-4492 & 40-8502 & 40-1162. Documents re Docket 40-1341 have been included in response to A Reid FOIA Request 80-220 W/o encls FELTON, J M Division of Rules and Records 80/10/08 1p.
- 8010140048 Request for 7-day extension within which petitioner, WY Outdoor Council, will file contentions. Certificate of Svc encl MCGVUREN, H J Hearing Branch 1. 80/10/10 3pp.
- B010160772 Order granting NRC B01010 request for 7-day extension of time within which petitioner shall file contentions. Hestern Nuclear, Inc & NRC may respond to petitioner contentions by 801107 HOLFE, B. J. Atomic Safety and Licensing Board Panel B0/10/14, 1p.
- B010300082 Response in support of MY Outdoor Council B01015 motion to withdraw petition to intervene Motion consistent w/encl stipulation signed by parties MCOURREN.H J Hearing Branch 3, 80/10/27 ip.
- ---8010300090 Executed stipulation to renew License BUA-56 based upon six new conditions agreeable to all parties & made part of renewed license Certificate of Syc enci BOOKE, B L. Hyoming Outdoor Council. WALPOLE, J. R. Hestern Nuclear, Inc. (subs of Phelps Dodge Corp). MCGURREN, H. J. Hearing Branch 3. 80/10/15 5pp
- 8010300069 Response in support of WY Outdoor Council motion to withdraw petition to intervene due to executed stipulation entered into by parties. Certificate of Syc encl MALPOLE, J. R Western Nuclear, Inc. (subs. of Phelps Dodge Corp.), MALPOLE, J. R Holland & Hart 80/10/28 2pp.

DOCKET 40-1173 BABCOCK & WILCOX

- 8010080152 Provides Bubcommittee on Energy & Environ w/DOE comments re NRC safeguards case study rept on NUMEC U processing plant at Apollo:PA during mid-1740 AHEARNE, J F Commissioners 80/09/11 ip.
- ---B0100B015B Confirms that NRC rept. "Eafeguards Case Btudy of NUMEC U Processing Plant, Apollo, PA." has no significant errors or calssions BATEMAN. M. Energy, Dept. of. 80/08/15. 1p.

- DOCKET 40-1341 EDGEMONT URANIUM MINE. TVA & MINES DEVELOPMENT, INC.
- B010270003 F01A request for correspondence re facility Info needed for assessment of NRC & TVA considerations re decommissioning of old U mill & tailings piles
 REID.A B Black Hills Alliance B0/05/12 3pp
- 8010140625 FOIA request for 13 documents re facilities JONES,L. Black Hills Alliance 80/08/21 2pp
- 8010140601 FOIA request for 11 documents re facilities JONES.L. Black Hills Alliance 80/09/02 2pp
- 8010220453 Forwards "Environ Radioactivity Levels Sequoyah Nuclear Plant Annual Rept. 1979 " MAXMELL.R 8 Tennessee Valley Authority 80/09/05. 4pp
- --8010220455 "Environ Radioactivity Levels Sequoyah Nuclear Plant Annual Rept. 1979 " # Tennessee Valley Authority RH-80-7-802, 80/08/31 51ep
- 8010160276 Summary of 800826 meeting w/ORNL & Cectechnical Engineers. Inc. in Silver Spring, MD re TVA Edgement decommissioning E18 tailings mgt evaluation section responsibility confirmation TRACER.E.A Uranium Recovery Licensing Branch 80/09/08 Opp
- 9010150159 Requests that BMML be sent written instructions detailing procedures for receipt & storage of radioactive metls. Info is needed for radiological survey to determine areas of elevated residual radioactivity

 SCARAND, R. A. Uranium Recovery Licensing Branch. 80/09/18. 1p.
- 8010200212 Forwards Revision 5 to "Edgement U Mill Decommissioning Plan Environ Rept " MILLS, LM Tennessee Valley Authority. 80/09/19. Spp
- ---8010200220 Revision 5 to "Edgement U Mill Decommissioning Plan Environ Rept " * Tennessee Valley Authority 80/09/19 120pp
- 8010230258 Forwards table of facilities that U Recovery Licensing Branch is responsible for & status of 40CFR190 compliance check.
 FREEMAN, J Uranium Recovery Licensing Branch. 80/10/06. 5pp.
- 8010240157 Bubmits comments on 800710 preliminary comments & syaluation of TVA Edgemont decommissioning plan environ statement Draft rept should contain sections on tailings mgt evaluation, recommended license conditions & unresolved questions, TRAGER.E A. Uranium Recovery Licensing Branch 80/10/06. 1p.
- 801014059B Responds to FOIA request for 11 documents re facilities Forwards documents re Dockets 40-8064 & 40-8502 Remaining eight documents re Docket 40-1341 have been included in response to A Reid FOIA Request B0-270. W/o encis.

 FELTON, J M Division of Rules and Records 80/10/08, 1p.
- 8010140621 Responds to FOIA request for 13 documents re facilities. Forwards documents re Dockets 40-1341.40-4492 & 40-8502 & 40-1162 Documents re Docket 40-1341 have been included in response to A Reid FOIA Request 80-220 W/o encis.

 FELTON, J. M. Division of Rules and Records. 80/10/08. 1p.
- 8010270001 Responds to FDIA request for correspondence re facility. Forwards documents. M/o encis FELTON.J M Division of Rules and Records 80/10/17. ip.
- DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP
- B010200270 Forwards "Rept to City of West Chicago: Summary of Geological Considerations Re Kerr-McGee Btabilization Plan of 1979 "Ltr forwarding rept to City of West Chicago encl. PORT.E. A Rediation Bervices. Inc. B0/08/26. 4pp.
- ~-8010200276 "Rept to City of West Chicago Summary of Geological Considerations Re Kerr-McGee Stabilization Plan of 1979." OUGGENHEIM.8., YOUNKER.L. Illinois, Univ. of, at Chicago Circle. 80/05/07. ling

- DOCKET 40-2259 PATHFINDER MINES CORP
- 8010010669 Forwards comments in response to 800825 meeting in which questions were raised to compliance w/25 mannems/yr std based on review of ambient air sampling data One oversize drawing encl
 NUCENTIE L Pathfinder Mines Corp 80/09/25, 6pp.
- --8010010672 "Exhibit 1/Lucky Mc U Mill Wind Rose Distribution Index. Data From Aug 1978 Aug 1980."

 * Fathfinder Mines Corp #80/09/21. 1p
- 801027055B Forwards matls describing seepage situation for which NRC advice is requested. Situation will be monitored & NRC provided W/findings FRANCIB.E Humming. State of 60/10/01. Spp.
- 8010230258 Forwards table of facilities that U Recovery Licensing Stanch is responsible for & status of 400FR190 compliance check
 FREEMAN, J Uranium Recovery Licensing Branch 80/10/06. Spp

DOCKET 40-2384 RMI CO.

- 8010220114 Forwards IE Insp Rept 40-2384/80-02 on 800925 & 0806 of activities under License SHB-602.No noncompliance noted. DAYIS.A B. Region S. Chicago, Fuel Facility & Materials Safety Branch 80/09716. 2pp.
- --80i0220125 JE Insp Rept 40-2384/80-02 on 800325 % 0806 No noncompliance noted. Major areas inspected:environ sample & radiation survey in vicinity of sites & planning meeting to determine scope of alleged problem PAOLIARO, J. A. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. PAPERIELLO. C. J. WIEDEMAN, D. Region 3, Chicago, Office of the Director. 80/09/14, 34pp.

DOCKET 40-2791 KULITE TUNGSTEN CORP

8010200383 Confirms vendor response to NRC 800829 inquiry re use of depleted U Vendor does not use or possess licensed matl & is not planning to inttiate program in near future. KINNEMAN J D Region 1, Philadelphia, Fuel Facility & Haterials Bafety Branch. 80/09/15 fp.

DOCKET 40-3392 ALLIED CHEMICAL CORP

- 8009150163 Forwards IE Insp Rept 40-3392/80-01 on 800617-19 No noncompliance noted BAVIS, A.B. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 80/07/28 2pp.
- --8009190165 IE Insp Rept 40-3392/80-01 on 800617-19 No noncompliance noted. Major areas inspected, facility changes & mode, audits, asfety committees: training, internal exposure control & transportation activities
 FIBHER, M. L. Region G. Chicago, Fuel Facility & Materials Safety Branch PECK, C. C. Region G. Chicago, Office of the Director. 80/07/24. Spp.

DOCKET 40-3433 ATLAS HINERALB

- 8010200263 Discusses onsite insp of Atlas Minerals tailings structure w/J Tapie (NRC) & 9 Swanby & L Jacobs (Atlas Minerals).
 Embankment const per design specs & monitoring program adequate.
 HDWARD.T.R. Affiliation Unknown 80/04/25. 2pp.
- 8010220393 Forwards "Effluent Monitoring Rept Jan-June 1980," per 10GFR40.65. Mosb mill no longer releases liquid effluent to unrestricted areas. Map w/correct location of continuous air samples anci EDWARDS, D. L. Atias Minerals 80/08/27 Rpp.
- --8010220398 "Efficent Monitoring Rept Jen-June 1980." * Atles Minerals 80/08/27. 23pp.
- B010210687 Confirms B00707 telcon & issues Amend & to License BUA-917 to reflect concerns to protection of tailings pile from effects of mex flooding & acquirement of surety arrangements to cover reclamation & decommissioning costs.

 SCARANO, R. A. Uranium Recovery Licensing Branch. B0/09/09. 4pp.

- 801001006B Forwards revised page to fourth quarter rept for 1979 on continuous air samples, correcting error on Rn-222 EDWARDS, D.L. Atlas Minerals 80/09/10 2pp
- 8010140149 Responds to 800829 ltr forwarding manuscript on mineral development in southern UT NRC is investigating source of smog enveloping Hoab Valley Article should not indicate that smog is radioactive until investigation is complete SCARANG.R.A Uranium Recovery Licensing Branch B0/09/10 1p
- 80i0150077 Responds to 800717 telcon & followup ltr re location of background air particulate & radon sampling site for facility U mill Arches Park monitoring site is not acceptable Rept on sampling site location due by 800726 LINEHAN, J. J. Uranium Recovery Licensing Branch 80/07/10 2pp
- 8010280175 Responds to 800717 itr re interpretation of Condition ii of license restricting average mill throughout facility to 850 metric tons of U oxide per yr boes not agree w/ interpretation re "average" meaning over 5-yr period LINEHAN: J. J Uranium Recovery Licensing Branch 80/09/10 ip
- 8010090542 Discusses facility failure to implement certain monitoring requirements in timely fashion Soil vegetation, background groundwater & yellowcake dryer sampling data were not submitted. Air particulate sampling was partially done.

 OARCIA.P.J Uranium Recovery Licensing Branch 80/09/17, ip.
- 8010150696 Requests comment on proper communication channels between NRC & Atlas BUANEY.0.T Atlas Hinerals 80/09/17. ip
- 8010200085 Forwards 8008R0 photograph of existing beaches, averaging 150 ft per license requirement 80/07/19 2pp
- 8010200171 Confirms 800919 telcon re background monitoring Impossible to meet all criteria per NRC 800910 ltr Discusses background monitoring site selection
 SMANBY, C. T. Atlas Minerals 80/09/19 ip

DOGKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

- 8010140628 FOIA request for 13 documents re facilities JONES, L. Black Hills Alliance 80/08/21 2pp
- 8009240156 Forwards four maps w/appropriately labeled waterways in response to Question ii of NRC 800703 ltr KEMP, E Emmarson Kemp & Associates, Inc 80/09/03 ip
- --B009240161 "UB Geological Survey, Cas Hills Quadrangle, WY, " 7.5 minute series (topographic map) # Interior, Dapt. of, Geological Survey 58/12/31, ip
- --8009240164 "McIntosh Meadows Quadrangle,WY," 7.5 minute series (topographic map)

 4 Interior,Dept.of, Quological Survey 52/12/31, ip.
- --8009240167 "Puddle Bprings Guadrangle, WY Fremont County, " 7 5 minut; series (topographic map)

 * Interior, Dept of, Geological Survey, 57/12/31 1p.
- --8009240170 "Coyota Spring Guadrangle, WY Framont County," 7.5 minute series (topographic map) # Interior. Dept of, Gaological Survey, 52/12/31, 1p,
- 8010030100 Forwards add1 info consisting of environ rept mods & principal parameters for radiological assessment.

 KEMP.E. Emmerson Kemp & Associates, Inc. 80/09/03 11pp.
- B010090539 Forwards Questions 34 & 35 of 800703 series, for insertion into Section 2 of 800829 submission, PIERSON, C. W. Federal American Partners, 80/09/05, 7pp.
- 8010220634 Forwards IE Insp Rept 40~4492/80-01 on 800818-20 & notice of Violation. 9ROHN O.D. Region 4: Dailes: Fuel Facility & Materials Bafety Branch. 80/09/10. 2pp.
- --8010220637 Notice of violation from insp on 800818-20.

 * Region 4. Dalias. Office of the Director. 80/09/09. 2pg.

- --8010220644 IE Insp Rept 40-4492/80-01 on 800818-20, Noncompliance noted failure to conduct radiation safety surveys of maint activity & failure to collect annual soil & vegetation samples BROWN.O D Region 4, Dallas, Fuel Facility & Materials Safety
 - BROWN.O D Region 4, Dalias, Fuel Facility & Materials Safety Branch. WILBORN.L., SPITZBERG.D B Region 4, Dallas, Office of the Director 80/09/09 7pp
- 8010150647 Advises of termination of employment w/Federal-American Partners Future NRC contact will be w/E Kemp or N Andrus PIERSON, G W Federal American Partners 80/09/15 1p
- 8010140194 Forwards map of environ monitoring stations, in response to 800917 teleon WATTS, K. Federal American Partners 80/09/17 ip
- --8010140241 "Environ Monitoring Stations " * Federal American Partners 80/08/27 ip
- 8010150650 Forwards net weights & emission spectrographic analysis of calcined sledge & carbon samples for burial of matl in Number 2 tailings pond
 ANDRUS.N.J Federal American Partners 80/09/19 3pp
- 8010230259 Forwards table of facilities that U Recovery Licensing Branch is responsible for & status of 40CFR170 compliance check. FREEMAN.J Uranium Recovery Licensing Branch 80/10/04 5pp
- 8010240149 Bubmits comments & questions re NRC review of hydrogeologic data presented in vendor 800829 info submittal Dutstanding items include status of Number 1 pond verification of casing vols of water & contamination of wells

 LINEHAN, J J Uranium Recovery Licensing Branch. 80/10/06 3pp
- 8010140621 Responds to FOIA request for 13 documents re facilities. Forwards documents re Dockets 40-1341.40-4492 & 40-8502 & 40-1162. Documents re Docket 40-1341 have been included in response to A Reid FOIA Request 80-220 W/o encls FELTON, J M Division of Rules and Records 80/10/08 ip.
- 8010210394 Ack receipt of 800929 ltr informing NRC of steps taken to correct violations noted in IE insp rept.

 BROWN, O D. Region 4, Dallas, Fuel Facility & Materials Bafety Branch. 80/10/09 lp.
- --8010210399 Responds to NRC 800910 ltr re violations noted in IE insp rept. Corrective actions environ monitoring TLD results have been provided in semiannual rept ANDRUB:N J Faderal American Partners. 80/09/29. 10pp.

DOCKET 40-6622 PATHFINDER MINES CORP

- 8010230258 Forwards table of facilities that U Recovery Licensing Branch is responsible for & status of 400FR190 compliance check.
 FREEMAN, J. Uranium Recovery Licensing Branch, 80/10/06 5pp.
- DOCKET 40-4459 PETROTOMICS CO . DETTY DIL
- B010140624 Informs that no radionuclide liquid effluents were released to unrestricted areas during six months prior to B00701 PFAFF, B. J. Getty Oil Co., Petrotomics Co. Div B0/09/09. 1p
- 8010220119 Bubmits radioactive effluent release rept for Jan-June 1980. PFAFF.8 J. Getty Oil Co., Petrotomics Go Div. 80/09/09. 1p.
- 8010160641 Forwards NRC 800813 request for license amend fee for dust sampling program changes.
 MEI8B.D License Fee Management Branch 80/07/24, 1p
- --8010160653 Forwards amend to License SUA-551, revising dust sampling program re 751215 supplemental radiation safety info. Revision reflects minor changes in mill circuits. PFAFF, 8 J License Fee Management Branch, 80/07/22. 24pp.
- 8010230258 Forwards table of facilities that U Recovery Licensing Branch is responsible for & status of 40CFR190 compliance check, FREEMAN.J. Uranium Recovery Licensing Branch 80/10/06 5pp.

DOCKET 40-6920 AUTOMATION INDUSTRIES, INC.

- 8010100257 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-05978/80-01 & 40-6920/80-01 Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 80/08/27 ip
- --B010100265 Responds to NRC 800714 ltr re violations noted in IE Insp. Repts 30-05998/80-01 & 40-6920/80-01 Corrective actions: alternate source for whole body counting will be located Heelty wipe tests will be performed BANYORO: M P Automation Industries; Inc. 80/08/05, 2pp.
- --8010100268 Forwards IE Insp Repts 30-05978/80-01 & 40-6920/80-01 on 800521 & notice of violation.
 KINNEMAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/07/14 2pp
- --B010100269 Notice of violation from insp on B00521

 * Region I: Philadelphia, Fuel Facility & Materials Safety Branch, B0/07/11 ip.
- --8010100270 IE insp Repts 30-05998/80-01 & 40-6920/80-01 on 800521, Noncompliance noted:possession in excess of license limit & failure to perform monthly contamination survey in hot cell & annual bioassay in 1979 KINNEMAN.J D Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/07/11, 5pp.

DOCKET 40-7783 BUEING CO.

8010160080 Requests NRC approval re Boeing Co application to add Air New Zealand Limited, British West Indies Alrways, Limited, & Luxevia as ultimate consignees to License XU-8302 MOROAN, H. E Boeing Co. 80/09/22 ip.

DOCKET 40-7869 PLATEAU RESOURCES. LTD

- B010230215 Forwards two maps of Shootering Canyon area red accomissioning of License SUA-1013 in response to B00922 telcon. M/o encl HEAD. M.J. Plateau Resources, Ltd B0/09/23, ip.
- DOCKET 40-8027 KERR-MCGEE CORP
- 8010010485 Ack receipt of 800912 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-8027/80-01.

 BROWN, 0 D Region 4, Dallae, Fuel Facility & Materials Safety Branch. 80/09/18, ip
- --8010010498 Forwards IE Insp Rept 40-8027/80-01 on 800723-25 & notice of violation.
 BROHN, G.D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/08/21. 2pp.
- --8010010489 Notice of violation from insp on 800723-25,
 # Region 4: Dalles, Office of the Director 80/08/15 ip.
- --B010010495 IE Insp Rept 40-B027/80-01 on 800723-25 Noncompliance noted: failure to use respiratory protective equipment as required. BROWN.9 D Region 4. Dallas, Fuel Facility & Materials Bafety Branch. B0/08/15. Bp
- 801021060B Forwards Table I, "Radioactivity in Qaseous Effluent," re release of nuclides in effluents to unrestricted areas during first half of 1980 per 10CFR40, 65 & requirements of License BUB-1010 BHELLEY,W J, Kerr-McGee Nuclear Corp. 80/09/26. 2pp
- DOCKET 40-8044 EXXDN HINERALS CO USA, EXXON CORP
- B010140601 FOIA request for 11 documents re facilities JUNES, L. Black Hills Alliance B0/09/02. 2pp.
- B010140398 Responds to FDIA request for 11 documents re facilities. Forwards documents re Dockets 40-8064 & 40-8502 Remaining eight documents re Docket 40-1341 have been included in response to A Raid FDIA Request B0-270 M/O encls.

 FELTON J M. Division of Rules and Records 80/10/08. 1p.

DOCKET 40-8084 LIBBON MINE, RIO ALCOH CORP

- 8010310052 Ack receipt of 800804 ltr forwarding average weekly exposure calculations in response to NRC 800708 ltr Requests that add info re units of measurament applicable to exposure calculations be subsitted within 19 days of ltr receipt.

 BEYFRIT.K V Region 4. Dallas, Office of the Director. 80/08/15.

 1p.
- --B010310039 Forwards average weekly exposure calculations in response to NRC 800708 ltr. No instances of exposure in excess of IOCFR20 103(a)(2) limits New time sheet has been designed & put into use at each work station in mill.
 BURNETT, J T Rig Algom, Ltd., 80/08/04 13pp.
- 8010150135 Forwards request for add1 info re groundwater contemination for evaluation of tailings mgt study Extent of taepage may require plant cleanup project.

 BCARANO.R A. Uranium Recovery Licensing Branch 80/09/05. Spp.
- 8010240564 Corrects two arrors in consultant rept entitled "Rept of Quotechnical Evaluation to Support Requests for 5-ft Dam Rise. Upper Tailings Fond Embankment Bys, Liebon Valley Operations, for Rio Aigon Corp."

 BODDY, J. R. Dames & Hoore 80/09/11. ip
- BOI0150963 Forwards enalysed air sample summary from B00625-27 collection at facility. No evaluation criteria available at present re variations between vendor & NRC results. BROWN, O.D. Region 4, Ballaw, Fuel Facility & Haterials Bafety Branch. B0/09/30 2pp.
- 801031000B Forwards comparisons of samples taken at facility on 800625-27, analyzed by ID Health Svcs Lab. w/samples analyzed by licensee. Data supplied for info only.

 8000N, 0.D. Region 4, Dailar, Fuel Facility & Materials Safety Branch. 80/09/30 2pp
- 8010300478 Responds to 800725 ltr requesting hydrologic info by 800922 re 5-ft dam raise. Extension until 801029 requested.

 LAHTON: M D Ric Algom. Ltd. 80/10/03. 19.
- 8010230258 Forwards table of facilities that U Recovery Licensing Branch is responsible for & status of 40CFR190 compliance check FREEMAN.J Uranium Recovery Licensing Branch 80/10/06, Spp
- B010290177 EN-B0-048 on B01008, notice of violation & notice of proposed imposition of civil panelties of \$7,100 will be issued. Action based on alleged items of noncompliance re-control of personnel contamination & exposure. BROCKETT, T. W., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/10/04. 1p.

DOCKET 40-8102 EXXON MINERALS CO. USA: EXXON CORP.

- BO10020713 Forwards addl info & three oversize drawings re hydrogeologic sys at Highland U Operations site, in response to BO0618 request for add info. ORTLOFF. O. D. Exxon Minerels Co. USA. 80/09/08. 41pp
- 8010220343 Forwards NRC comparison data re vandor 800605-06 air samples from packaging room & water samples from saepage collection pand east of tailings embankment.Criteria to evaluate variations is not available at present.

 BROWN.O.D. Region 4: Dailas: Fuel Facility & Materials Safety Branch. 80/10/01 2pp.
- 8010310516 Forwards questions & comments re 800903 response to NRC 800610 request for addi info re monitor wells Requests preliminary reply by 80110.

 LINEHANGU J. Uranium Recovery Licensing Branch, 80/10/16, 2pp.

DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO.

10060076 Bubmits costs incurred & manhours expanded in review of 300329 application.
[ADIE: 6 0., HILLER, H. J. Uranium Recovery Licensing Branch. 30/09/08. ip.

KKET 40-8348 IN SITU URANIUM LEACHING PROJECT

)10200207 Requests partial refund of renewal fee. LARSON.T.L. Union 76 Minerals Exploration Co. 80/09/11. ip.

- 8010140132 Notifies of partial refund of renewal fee for License 8UA-1223. MILLER, M.D. License Fee Management Branch 80/09/15, 1p
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO
- 8010230530 Ack receipt of State of WY Water Quality Div enc1 800818 ltr approving sampling procedures & discharge limits for Reservoir B Procedures will be modified, Company 800612 ltr to Btate of MY enc1 NEUMANN, M R Rocky Mountain Energy Co 80/07/08 5pp
- 8010230560 Forwards 800821 t 0905 sampling results of Pattern III monitoring wells. Production rate increase in second sampling rendered insignificant change in water quality but confirmed that cone of depression is being effectively maintained NEUMANN-M R Rocky Mountain Energy Co. 80/09/16 App
- DOCKET 40-8385 AIR FORCE, DEPT OF, HOOTRE AEROSPACE MED DIV.
- 8010010287 Ack receipt of 800812 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 40-8385/80-01.
 KINNEMAN, J. D. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 80/09/09. 1p.
- --80i0010292 Forwards response to items of noncompliance noted in IE Ins Rept 40-8385/80-01. Corrective actions: base operating instructions updated. MOYER, W B Air Force, Dept of, 80/08/12, 1p
- --8010010274 Responds to NRC 800420 ltr re violations noted in IE Insp Rept 40-8385/80-01 Corrective actions provides listing of personnel to serve in supervisory position. BARTO, J. F. Air Force, Dept. of. 80/07/07 2pp.
- --8010010308 Discusses IE Insp Rept 40-8985/80-01 on 800516 & forwards notice of violation. CROCKER,H M. Region 1, Philadelphia, Fuel Facility & Materiels Safety Branch 80/06/20 2pp.
- --8010010312 Notice of violation from insp on 800316. Noncompliance noted use of licensed meth by unauthorized individuals.

 * Region 1. Philadelphia. Office of the Director. 80/06/20. ip.

DOCKET 40-8434 HOME STATE HINING CO. LA

- 8010220295 Forwards renewed Source Matl License SUA-1249, authorizing research program for recovery of U from mine water. License contains revisions to previous license conditions.

 SCARANO, R. A. Uramium Recovery Licensing Branch. 80/09/25 ip
- --8010220278 Renewal of Bource Matl License BUA-1249, authorizing researc program for recovery of U from mine water.

 8CARAND, R A. Urenium Recovery Licensing Branch. 80/09/25. 4pp.

DOCKET 40-8452 BEAR CREEK URANIUM CO.

- 8010150128 Confirms 900828 telcon re disposal of radioactive matl in tailings basin. LINENAN, J. J. Uranium Recovery Licensing Branch 80/09/05, ip.
- 8010030536 Forwards comments re rept "Response to NRC Request for Info. 800701.Bear Creek U Co Tailings Mgt Plan." Requests justification re calculations LINEMAN, J. Uranium Fuel Licensing Branch. 80/09/10. 15pp.
- DOCKET 40-8502 IRIOARAY MINE, WYOMING MINING CORP.
- 8007070132 Forwards "Response to NRC 800523 Order Modifying License & Terminating Show Gause Order." Data clarifies & demonstrates fluid migrations experienced at facility are well contained within wellfield vicinity. Thirty oversize drawings encl. TIEPEL, E. W. Myoming Mineral Corp. 80/08/21. 200pp.
- --8007070156 "Project Map."

 * D'Appolonia Consulting Engineers, Inc. 60/08/19, ip.
- --8009090159 "Chloride Concentrations in Coal Unit -- Aug 1979 & May 1980,"
 * D'Appolonia Consulting Engineers, Inc. 80/08/19, 1p.

--8007090169 "Chloride Concentrations in Unit 1 Sand.May 1980 "
* D'Appolonia Consulting Engineers, Inc. 80/08/19 ip ---8007070178 "NRC - 1C. Boring & Gasphysical Logs "
* D'Appolonia Consulting Engineers, Inc. 80/08/19 --8009090185 "NRC - RC, Baring & Geophysical Lags "
. # D'Appolonia Consulting Engineers, Inc 80/08/19 ip --8009090193 "NRC - 3C, Boring & Geophysical Logs "
+ D'Appolonia Consulting Engineers, Int 80/08/19. 1p --8009090201 "Cross Section Location Hep "

* D'Appolonia Consulting Engineers, Inc. 80/08/19 1 p --8009090210 "Crows Section.NRC-2C to NRC-1C "

* D'Appolonia Consulting Engineers, Inc 80/08/19 1p. --8009090225 "Cross Section, NRC-2C to NRC-3C " D'Appolonia Consulting Engineers, Inc. 80/08/19, 1s --8007070251 "Cross Sections, A-A & B-B,"
* D'Appolonia Consulting Engineers, Inc 80/08/19 10 --8007070255 "Cross Section C-C "

* D'Appolonia Consulting Engineers, Inc. 80/08/19 10 ---8009090263 "Cross Section D-D "
* D'Appolonia Consulting Engineers: Inc 40/08/19 to. --8009090270 "Gross Section E-E."

* D'Appolonia Consulting Engineers, Inc. 80/08/19 80/0B/19 in. --8009090284 "Cross Sections 0-0 & H-H "
* D'Appolonia Consulting Engineers, Inc. 80/08/19. 16 ---8007070272 "Cross Sections.T-J & K-K "
* D'Appolonia Consulting Engineers. Inc 80/08/19 1p --8009090318 "Isopech of Claystone Unit."

* D'Appolonia Consulting Engineers: Inc. 80/08/19. ip --8007070324 "Isopach of Unit 1 Band."

* D'Appolonia Consulting Engineers: Inc. 80/08/19. ip. --8009090327 "Structure Map on Base of Coal Unit. * D'Appolonia Consulting Engineers, Inc. 80 80/08/19 1s. ---8009090334 "Isopach of Total Overburden Above UISS "
* D'Appolonia Consulting Engineers, Inc. 80/08/19. 1p. --8009090340 "Water Table Map " * D'Appolonia Consulting Engineers, Inc 80/08/19 ip --8007070345 "Pump Test Locations "
* D'Appolonia Consulting Engineers, Inc. 80/08/19. 1p. ---8007070360 "Plan Location of Damaged Casings."

* D'Appolonia Consulting Engineers, Inc. 80/08/19. ip. --8009090364 "Schematic Representation of Exploration Borehole Density "
* D'Appolonia Consulting Engineers, Inc. 80/08/19. ip. --- 8009090372 "Comparison of Chloride Concentrations & Overburden Thickness."
D'Appolonia Consulting Engineers, Inc. 80/08/19. ip. --8009090379 "Comparison of Chloride Concentrations in Coal Unit & Damaged Casings."

D'Appolonia Consulting Engineers, Inc. 80/08/19. 1p. ~~8009090390 "Comparison of Chloride Concentrations in Unit 1 Sand & Damaged Casings."
D'Appolonia Consulting Engineers, Inc. 80/08/19. 1p.

--B009090396 "Comparison of Chloride Concentration in Coal Unit & Exploration Borehole Density."

+ D'Appolonia Consulting Engineers, Inc. 60/07/19. 1p.

- --8009090407 "Location of Shallow Zone, Unit 1 Sand & Water Table, Monitor # Wyoming Mineral Corp. 80/08/19 ip 8009090211 "Cross Section.NRC-3C to NRC-16"
 * D'Appolonia Consulting Engineers, Inc 80/08/19 is 8010140625 FOIA request for 13 documents re facilities. JDNES,L Black Hills Alliance 80/09/21. 2pp 8010030203 Responds to 800808 ltr re Shallow Zone Control Program All control/cleanup measures presently being implemented in shallow coal monitor zone will be shut down on 800823 Shutdown includes pumping activities & fresh water sweep WICHERS,D L. Wyoming Mineral Corp. 80/08/22 2pp BO100B03BD Forwards corrected Table 1 of estimated releases of radioactive matls in effluents to unrestricted areas from facility Table 1 replaces table in previously submitted semiannual effluent monitoring rept for Jan-June 1980. CORCORAN. J M Hyoming Mineral Corp 80/08/22 2pp --8010080588 Corrected Table 1 to seminannual effluent monitoring rept re estimated releases of radicactive matts in effluents to unrestricted areas. # Wyoming Mineral Corp 80/08/22, ip. 8010220385 Disagress w/statements in MY Mineral Corp 800730 ltr to NRC. Irigaray Mine Units 6 & 7 800116 revised baseline water quality & hydrology rapt did not satisfy Dept of Environ Quality requirements.

 ACKERMAN, W C Wyoming, State of 80/08/22 2pp 8010020566 Forwards application for permit to construct or modify Wastewater Treatment Facility 78-12R at Irigaray mine site in Johnson Gounty, Wy Mod to Evaporation Pond "E" will consist of discharge pipeline to Willow Creek WICHERS, D.L. Wyoming Mineral Corp., 80/08/26 Spp 8010020415 Forwards geophysical logs, in response to 800828 telcon request, M/o encl WIGHERS, D. L. Wyoming Mineral Corp 80/08/28 ip. 8010090148 Forwards IE Investigation Rept 40-8502/80-02 on 800814 of activities under License 8UA-1341 No noncompliance noted BROWN, O D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/09/02 ip --8010090154 IE Investigation Rept 40-8502/80-02 on 800814 No noncompliance noted Major areas investigated allegations of unauthorized releases to the environ & failure to meet license conditions

 EVERETT.R J Region 4, Dallas, Office of the Director, BR Region 4, Dallas, Fuel Facility & Materials Safety Branch, 80/08/28. Spp. BROWN, O. D.
- 8010140401 FOIA request for 11 documents re facilities.
 JONES, L. Black Hills Alliance. 80/09/02 2pp
- B0102401B2 Comments on vendor 800822 ltr Well RS-25 should be monitored for U.Uninterrupted biweekly sampling of SSM & HT wells should be continued.
 MOUNEY.O. Wyoming, State of. 80/09/08, 1p
- B010230335 Recommends amend of License SUA-1341 authorizing licensee to conduct bloassay program in accordance w/conditions in licensee 790817 ltr
 HEYER, R.S., LINEHAN, J. Uranium Recovery Licensing Branch.
 B0/09/R3. 2pp
- 8010270344 Notifies of amend to License SUA-1341, adding Condition 47 that allows licenses to conduct bloassay program in accordance w/program submitted by 800817 ltr. SCARARO, R. A. Uranium Recovery Licensing Branch 80/09/23. 2pp.
- 8010230238 Forwards response to NRC 800918 comments on "Rept on Irigaray Mine Shallow Zone Evaluation."
 TIEPEL.E.W. Wyoming Mineral Corp 80/09/26, 26pp
- 8010270862 Confirms 800919 telcon w/D Little re return of shallow monitor well 98M-4 to official excursion status after slight increase in chloride levels caused by relaxation of monitor zone. WICHERS,D L. Wyoming Mineral Corp 80/09/26. ip.

- BOIO220354 Forwards branch comments k questions on addl geophysical ings & licenses BOO821 response to NRC order modifying license & terminating show cause order, Data is not consistent throughout rept, LINEMAN, J. J. Uranium Recovery Licensing Branch. BO/10/06, dap.
- 8010140598 Responds to FDIA request for 11 focuments re facilities, Forwards documents re Dockets 40-8064 & 40-8502. Remaining eight documents re Doctet 40-1341 have been included in response to A Reid FDIA Request 80-270, M/o encis. FELTON, J M Division of Rules and Records. 80/10/08. ip.
- 8010140521 Responds to FOIA request for 13 documents re facilities. Forwards documents re Dockets 40-1341,40-4492 & 40-8502 & 40-1152 Documents re Docket 40-1341 have been included in response to A Reid FOIA Request 80-220, M/o encis. FELTON, J. M. Division of Rules and Records. 80/10/08. is

DOCKET 40-8511 COTTER CORP.

8010090523 PNA-80-035: on B00917. State of CO informed NRC of pensing release of CO Sureau of Investigation rest critical of Cotter Corp & CO health dept. Findings indicate manipulated data & deficiant rediation confrol program. Rept requested.

KERR. G. H., DODA, R. Office of State Programs, Director. 80/09/22. Per.

DOCKET 40-8584 UNION 76 HINERALB EXPLORATION CO.

- 6010030137 Forwards revised QC program for uring specimens at facility. Revision brings program into agreement w/Tables 1 k 2 of NRC Reg Guide 8 22.Also forwards revised Page 5-15 to application for license.
 ACOSTA.A.P. Minerals Exploration Co. (subs. of Union Dil Co. of California). 60/08/27. 7pp.
- --B010030150 Revised Page 5-15 to 800115 application for Source Natl Hinerals Exploration Co. (subs. of Union Oil Co. of California). 80/08/31.
- 8010060075 Amend 4 to License BUA-1350 changing environ Rn-222 empling from active monitoring to continuous passive monitoring sys. SCARANO, R. A. Uranium Recovery Licensing Branch. 80/09/10. lp.
- B010070104 Submite proposed Amend 4 to License SUA-1350, changing Rn-222 templing to continuous passive menitoring sys. OILLEN. D. M., LINEHAN. J. J. Uranium Recovery Licensing Branch. B0/09/10. 2pp.
- 8010210378 Forwards IE Insp Rept 40-8584/80-02 on 900821. No noncompliance noted. BROHN. 9 D. Region 4: Dallas: Fuel Facility & Materials Safety Branch. B0/09/13. 2pp.
- --B0102103B4 IE Insp Rept 40-8384/80-02 on B00821. No nencompliance notes. Mayor areas inspected: U mili presperational activities, including internal review & audit training, waste mpt & environ protection.

 WILBORNI. L.: SPITZBERO, D. B Region 4, Dallas, Cefice of the Director. BROWN, O. D. Region 4, Dallas, Fuel Facility & Haterials Befork Branch. 90/09/12 App.
- 8010210503 Responds to IE Bulletin 79-ip, "Packaging of Low Level Radwaste for Transport & Burlel." No low level radwaste is generated for shipment.

 ACORTA, A. P. Union 75 Minerals Exploration Co. 80/10/17. ip.

DOCKET 40-8585 HYDMING MINERAL CORP.

- S010020037 Forwards into re-stack emissions for Jan-Jul 1980, Links physical changes in calciner product feed due to adjustments in chemical processes w/higher concentrations of radioactive matis in effluents.

 BERO, R. E. Wyoming Mineral Corp. 90/09/08. 2pp.
- 9010060055 Submits cost & manhours re 800527 application for amend to License SUA-1318. HEYER, R., LINEHAN, J. Uranium Recovery Licensing Branch. B0/09/18.

DOCKET 40-8402 UNITED NUCLEAR CORP.

- 8010020746 Forwards comments on FES, NUREG-0532 for United Nuclear Corp Morton Ranch U mill. NRC responses are positive & have cleared up ambiguities. WILLIAMS,R.L. Environmental Protection Agency. 80/08/29, 4pp
- DOCKET 40-8611 AIR FORCE, DEPT OF, HILL AFB, UT
- 8010240362 IE Insp Findings & Licensee Act dtd 801009 of License 8M8-1327, Insp findings:no items of noncompliance noted, CAIR, C.L. Region 4, Dallas, Office of the Director 80/10/09. 80/10/09. 1p.

DOCKET 40-8663 NUCLEAR DYNAMICS, INC.

- 8010230383 Forwards *1980 Activity & Restoration Rept. * BTDICK.A.F. Nuclear Dynamics. 80/09/26 2pp STOICK. A. F. Nuclear Dynamics.
- --8010230389 "1980 Activity & Restoration Rept," STOICK, A. F. Nuclear Dynamics, 80/09/26, 58pp.

DOCKET 40-8672 AIR FORCE, DEPT. OF, HILL AFB, UT

9010240367 IE Insp Findings & Licensee Ack dtd 801009 of License SM8-1328 Insp findings:no items of nancompliance noted, GAIN.G.L. Region 4, Dallas, Office of the Director. 80/10/09, B0/10/09, 1p.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC.

8010220279 Confirms 800829 telcon re 800727 meeting in Silver Spring, MO to discuss proposed facility expansion. Requests that date be changed to 800730.

BAKER.C.E. Emerson Consultante, Inc. 80/08/29. ip.

DOCKET 40-8492 COTTER CORP.

- B010090523 PNA-80-035; on 800917; State of CD informed NRC of pending release of CD Bureau of Investigation rept critical of Cotter Corp & CD health dept. Findings indicate manipulated data & deficient rediction control program, Rept requested, KERR, G. H.; DODA: R. Office of State Programs: Director, 80/09/R2. 80/09/22.
- 8010230339 Submits costs & manhours used in reviewing 800715 application for Amend 1 to License 8UA-1370, ROTHFLRISCH.J. Urenium Recovery Licensing Branch. 80/10/06, 1p.

POCKET 40-8497 ROCKY HOUNTAIN ENERGY CO.

- 8010090165 Porwards into to accompany 800731 quarterly rept for License 8UA-1338. Into pertains to questions re method used to determine upper control limits for Pattern 1 at facility & Table III re max dirborns particulates NEUMANN, M. R. Rocky Mountain Energy Co. 80/08/28. 28pp.
- 9007070386 Forwards "Bestannual Effluent Monitoring Rept, Jan-June SPIELES, P. R. Rocky Mountain Energy Co. 80/08/29. 1p.
- BOIO230844 Forwards Table V-B.Revision Q: "Pattern I Munitor Hells: Excursion Control Parameters:" showing calculated lower control limits for pH values.Calculations were taken from baseline sample data following outliner removal. NEUHANN.H.R. Rocky Mountain Energy Co. BO/09/19, Spp.
- 8010270342 Requests approval of upper control limits in encl Table B & authorization to proceed w/leaching of Pattern II monitor & production wells. Tables A & C also encl.
 NEUMANN/M.R. Rocky Mountain Energy Co. 80/09/26, 23pp.

8010240572 Forwards raw data sheets for groundwater sample analyses of Pattern II, in response to 800926 raquest Establishment of baseline water quality for sand monitor well is ongoing. Requests conditional approval for startup NEUMANN. If R Rocky Mountain Energy Co. 80/09/29 13pp.

DOCKET 40-8698 PLATEAU RESOURCES, LTD

- 8010200160 Responds to NRC 800509 ltr Notifies that embankment fill will be 10% complete within six wks
 BENNETT, M 8 Mountain States Mineral Enterprises, Inc 80/09/10
- 8010230523 Forwards Mountain States Mineral Enterprises 800910 ltr to NRC re completion of ambankment fill.

 JACKBON, K E Plateau Resources, Ltd. 80/09/15, [p

DOCKET 40-8710 RADIOLOGY SPECIALISTS SOUTHFIELD, MI

- B010ZB0107 Application to amend License BUC-1342 to reflect change in name of licensee & address. Category 7B amend fee encl.
 BURNS, D J Radiation Therapy Associates Detroit, HI 80/07/25. 1p.
- --8010280111 Forwards fee re 800725 application to amend license COOPER, J Region 3, Chicago, Office of the Director. 80/08/04, ip
- --8010280114 Forwards fee refund re 800725 application to amend License 800-1342 Request is fee exempt JACK80N:0. License Fee Management Branch 80/08/18. 1p

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

- 8010240323 Submits observations made during 800701 insp of Collins Draw Site Plant seemed well maintained except for yellow dust found on floor of yellowcake storage room Meeting ensued to discuss upper control limits. W/related documentation. MULLER, K Wyoming, State of 80/07/11 Spp.
- B009100B19 Forwards "NRC Quarterly Rapt, Apr~June 1980," per Condition 29 of License BUA-1332, LAMAN, J. T. Glaveland-Cliffs Iron Co. B0/08/26, 1p.
- --8009100820 "NRC Quarterly Rept. Apr-June 1980." * Cleveland-Cliffs Iron Co. 80/08/26. 12pp.
- --8009100823 "Sits Plan.Figure Map-1."
 * Cleveland-Ciiffs Iron Co. 80/02/27. is.
- 8010240015 Amend 2 to 8UA-1352 authorizing use of oxygen as oxident in U solution extraction studies.

 SGARAND, R. A. Uranium Recovery Licensing Branch. 80/09/22. ip.
- 8010240138 Safety evaluation re vendor 800714 proposed Amend 2 to License 6UA-1352, requesting uss of oxygen as exidant in U extraction process Recommends approval of request, ROTHFLE18CH. J., MILLER, H. J. Uranium Recovery Licensing Branch. 80/09/22. 20p.

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP

- 8010220241 Responds to NRC 800710 1tr noting items of noncompliance on Matl/Byproduct License SUA-1378. Pond redesign will be completed by 801015. Contingency plan will be submitted upon completed on Requests license amend for revised date.

 SHELLEY, N. J. Kerr-McGee Nuclear Gorp. 80/08/27. 1p.
- 8010220146 Recommands issuance of Amend 1 modifying Source Matl License SUA-1378. Amend revises submitted date for contingency plan. HEYER, R. B. LINEHAN, J. J. Uranium Recovery Licensing Branch. 80/09/25. 1a.
- 8010220303 Amend i to Source Matl License SVA-1378 revising Condition 14 to authorize 801015 submittel of contingency plan describing corrective actions in case of major lesk from pond or determination that cell is inadequate.

 BCARAND, R. A. Uranium Recovery Licensing Branch. 80/09/25. 2pp.

- DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC
- 8010150107 Submits cost & manhours for review of 800201 application for amend to License SUA-1373.
 KAUPMANN, R. MILLER, H. J. Uranium Recovery Licensing Branch 80/09/08. 1p
- 8010230233 Submits final rapt re reported excursion for Monitor Wall PNS-1.570. Wall is not excursion status. New upper control limits were overlooked & old values were used. Upper control limits soci APPEL, R R Taton Exploration Drilling Co : Inc 80/09/30. 2pp

DOCKET 40-8742 CHEMETRON CORP

8010030544 PNO-III-80-117 on 800618, Region 3 radiation specialists found surface contamination of 1 milliradian/hr at dump atte in Cleyeland, OH 8011 & water samples taken for analysis Region 3 continuing to investigate BRENIAHSKI, D J., DAVIG.A B Region 3. Chicago, Office of the Diractor 80/06/24 2pp

DOCKET 40-8743 CONOCO

- BO10170133 Forwards radiological assessment list. GUIOLEY, T W. CONDOO, Inc. (Continental Dil Co.). 80/09/08 16pp.
- 8010210014 Forwards original June 1979 mine permit application to Btate of HY. Also forwards Hazan Research rept on processing criteria Application withdrawn. New application will present mine/mil complex w/add environ baseline work, H/O encl QUIQLEY.T W. Conoco Coal Development Co. 80/09/12 2pp
- B010240327 Informs that environ rept was distributed to addresses listed in NRC 800829 ltr.Rept will be sent to individuals, organizations & agencies on attached list GUIGLEY,T W. GONGGO,Inc (Continental Dil Co.). 80/09/16 2pp.
- 8010210002 Notification of contract execution: "Evaluation of Potential Burface & Groundwater Impacts from Programed Conoco Band Rock U Mill Project," awarded to Ott Water Engineers. HAIRBION.C. Technical Assistance Contracts Branch. FIN 8-7308-0.80/09/23 16.
- --B010210004 Contract: "Evaluation of Potential Burface & Groundwater Impacts from Proposed Conoco Band Rock U Mill Project."
 awarded to Ott Hater Engineers.
 4 Ott Hater Engineers. Inc. DOUOHERTY.D.J. Technical Assistance Contracts Branch. FIN 8-7308 80/09/23. 13pp.
- 8010240180 Ack receipt of environ rept for project & natifies of error in NRC public inep process Fremont County library should not be repository for NRC documents pertaining to activities in HY Campbell County Public Library appropriate alternative. EAST.D. Hypming Outdoor Council. 80/09/23. ip.
- 8010270121 Requests Conoco. Inc application for license to const & operate project.

 HV88.J. Affiliation Unknown. 80/09/26. 19.
- 8010240037 Advises that telephone verification of parties receiving Sand Rock Mill environ rept has been completed Conoco. Inc 800924 1tr to Campbell County Library. Gillet. WY encl. QUICLEY, T W. CONGOLING. (Continental Gil Co.). 80/09/30. 3pp.
- 8010270489 Advises that environ rept for facility contains insufficient info re historic & cultural resources. Evidence of eligibility for inclusion in Natl Register of Historic Places must be provided.

 MALLIL S. Advisory Council on Historic Preservation. 80/10/02.
 2pp.

DOCKET 40-8745 DOLE PETROLEUH

- 8010020087 Discusses approved mining permit application requirements to be addressed in util annual rept. Implementation of procedure for testing well integrity may be required before annual rept completion date, N/o encl permit.
 FRANCIB.E. Hyoming, Btate of. 80/08/15. 2pp.
- 8010220279 Corrects 800807 comments on draft EIS. Section 4.4.2.2 re sulphur dioxide std & Section 4.8 i re air quality impacts. EAST.D. Wyoming Quidoor Council. 80/08/25. ip.

- 8010150632 Summarizes discussions during Jul 1980 & on 800807 re DES changes State application covering evaporation pond conterring program encl CATCHPOLE, O J Ogle Petroleum, Inc. 80/09/15 7pp
- B010200177 Submits responses to final EPA comments re commercial source matl license application
 CATCHPOLE.G J Ogle Petroleum, Inc. 80/09/16 3pp
- 8010060089 Summarires 800815 telcon u/HY Dept of Enviran Quality replanned approval of mining permit for vendor NRC does not object to proposed itr of approval or contents of permit ROTHFLEISCH J Uranium Recovery Licansing Branch 80/09/17 ip
- 8010230260 Responds to NRC 80090B ltr re exploration holes that were drilled & plugged & wells that were plugged whentonits or w/hentonits & cement. Map showing locations encl CATCHFOLE.0 J Ogle Petroleum, Inc. 80/09/22 Gpp
- 8010160929 Requests authorization to begin drilling injection & recovery wells in mining Unit 1 CATCHPOLE: 9 J. Ogle Petrolsum, Inc. 80/10/08 2pp
- 8010210357 Forwards monitor wall location map & advises that identification number for second lower aquifer monitor well has been changed from M-20 to K-63(L) for mining Unit 1 CATCHPOLE.0 J Ogla Petroleum, Inc. 80/10/13
- 8010210392 Submits add1 info re Industrial water well.per 800908 request Industrial water well 303-1 i provides water for domestic uses & plant housekeeping.yislding 1 to 3 gallons per minute CATCHPOLE.8 J Ogie Petroleum. Inc 80/10/13 3pp
- 8010280399 Bummarizes 801007 meeting w/NRC re details of pump tests mentioned in NRC 800908 ltr. Drawing of monitor well locations enci CATCHPOLE. 0. J Ggle Petroleum. Inc 80/10/22. 3pp.

DOCKET 40-8768 KERR-HCKEE NUCLEAR CORP.

B010310040 Forwards application submitted to MY Dept of Environ Quality & corrected pages to update NRC application in response to NRC B00701 request M/o MY Dept of Environ Quality application.

SHELLEY, W J Kerr-McGee Nuclear Corp 80/09/11 8pp

DOCKET 40-8771 NUCLEAR ASSURANCE CORP

8010170114 Confirms 800902 telcon re status of NRC licensing action. NRC review of project application delayed until mid-Oct 1980. due to current heavy caseload HOTHFLEISCH. J. Uranium Recovery Licensing Branch 80/09/08 1p.

DOCKET 40-8778 TETON EXPLORATION DRILLING CO. . INC.

- 8010150443 Forwards "Levenberger Project Bource Hatl License 8UA-1373;" quarterly rept for Jul-9apt 1980 HERLIHY, D. H. United Nuclear Corp. 80/10/09 App
- --8010150453 "Levenberger Project Source Hatl License 8VA-1373," quarterly rept for Jul-Sept 1980 * United Nuclear Corp 80/09/30, 76pp

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR J. Insurance & indemnity information

GO10280713 Requests endorsements & copy of Amend 10 to Policy E-24.

DINITI, Utility Finance Branch (formerly Antitrust & Indomnity)
60/09/24 ip

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
 Q. Adjudicatory correspondence
- B010210510 Order denying NY State Energy Ofc & Citizens Committee for Protection of Environ petitions to review ALAB-406 & ALAB-561 re seismic issues Motion to strike portions of NRC answer to petitions denied CHILK.S J. Office of the Secretary of the Commission 80/10/17, 22p
- J Insurance & indomnity information
- 80:0150382 Forwards Endorsements 104 & 107 to ANI Policy NF-100 & Endorsements 73 & 94 to MAELU Policy MF-29 IARAKAB:P Commonwealth Edison Co 80/10/08 5pp
- P Operating license stage documents & correspondence
- BOOT230052 informs that examption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified. Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp.
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also ancl. EISENHUT.D O Division of Licensing 80/07/17 28pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010010692 Responds to IE Bulletin 80-19. Unit 2 has no mercury-watted relays in reactor protection sys Unit 1 is defusled & bulletin is not applicable.

 ZARAKAS.P Consolidated Edison Co of New York. 80/08/30. ip.
- 8010220049 Forwards response to 1E Bulletin 80-20, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches "Bulletin did not apply to Unit 1 Required testing completed at Unit 2 ZARAKAB.P Consolidated Edison Co. of New York 80/09/15, 5pp.
- B010300654 Responds to IE Builetin B0-18. "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture." Unit 2 charging pumps are positive displacement, not centrifugal pumps ZARAKAS,P Consolidated Edison Co of New York 80/09/22 2pp.
- 8010270434 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested. ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/24 ip.
- 8010240137 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required.
 ORIER, B.H. Region i, Philadelphia, Office of the Director 80/10/02 ip
- B010280237 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/10. ip
- R Periodic operating reports & related correspondence
- 8010130447 Forwards species code list & info re circulating water temps river water discharge & gross electrical output per Section 401 Cartification for Espt 1980 MONTL-W A Consolidated Edison Co. of New York 80/10/10 18pp
- BOIG240425 Forwards tabulation of daily records of fish collections for Sept 1980 Daily species code list, count & total weight encl, ZARAKAB,P. Commonwealth Edison Co BO/10/15 App.
- 8010200519 Forwards decommissioning plan for Indian Point Unit 1, in response to NRC 800619 order revoking authority to operate facility ZARAKAS,P. Consolidated Edison Co. of New York. 80/10/17. ip.
- --8010200823 Decommissioning plan for Indian Point Unit 1.
 ** Consolidated Edison Co. of New York. * Nuclear Energy Service;
 Inc. 80/10/31 44sp.

- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8010230016 Forwards Amend 20 to License R-2 & sefety evaluation MILLER, J R Standardization & Special Projects Branch 80/09/10 20p
- --8010230018 Amend 20 to License R-2, increasing possession & use limits from 7 kg to 9 kg U-235, contained in TRIOA fuel elements MILLER, J R Stendardization & Special Projects Branch 80/09/10 200
- --8010230020 Bafety evaluation supporting Amend 20 to License R-2 * Standardization & Special Projects Branch 80/09/10 2pp
- DOCKET 50-6 BATTELLE MEMORIAL INST RESEARCH REACTOR
 J Insurance & insemmity information
- B0102803P4 Requests Endorsements 79.80 & 82 to Policy NF-17 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity), B0/09/24 ip
- 8010080537 Forwards Endorsements 79,80,82,85 & 87 to ANI Policy NF-17 STALL,D H Battella Memorial Institute, Columbus Laboratories, 80/10/03, 8pp
- DOGKET 50-8 NORTH CAROLINA STATE UNIV RESEARCH REACTOR
- J Insurance & indemnity information
- 8010280703 Requests endorsements & copy of Amend 13 to Policy E-7 DINITY.1 Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24 ip
- 8010230364 Forwards executed Amend 13 to Indemnity Agreement E-7. changing description of location BRAY.T C North Cerolina State Univ 80/10/10 3pp.
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8010020162 Requests resubmission of Revision 8 to util security plan Wyspecific changes properly identified Original submittal unacceptable for review CRUTCHFIELD.D Operating Reactors Branch 5 80/09/10 2pp.
- O Adjudicatory correspondence
- 8010020267 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment Submittal of info required by 801101 CRUTCHFIELD, D Operating Reactors Branch 5 80/08/27, 2pp.
- --8010020277 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENNUT, D G. Division of Licensing. 80/08/29. Spp.
- --8010020281 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment, EISENNUT.D.O. Division of Licensing. 80/08/29. 6pp.
- 8010070611 Forwards listed discovery documents. W/o encl FITZGIBBONB, R. Commissioners. 80/07/30 ip
- B010140034 Petition for Commission approval to delay environ qualification of electrical equipment until restart Requests stay of NRC 800919 order requiring quelification by 80101. STEPTOE.P. Commonwealth Edison Co STEPTOE.P. Isham, Lincoln & Beale. 80/10/14. 4pp.
- ---8010160040 Affidevit re qualification of electric equipment Deferral of environ qualification will hold down electricity cost & allow util to concentrate on qualifying electrical equipment at operating reactors.

 BMITH-N P Commonwealth Edison Co. 80/09/30, 4pp.

- --8010160045 Request for hearing to consider amending director 800919 order to allow for submission of required info prior to startup scheduled in June 1986 BTEPTOE, P Commonwealth Edison Co STEPTOE, P Isham, Lincoln & Beals 80/10/14 2pp
- --8010200673 Forwards revised 800829 order re response to IE Bullstin 79-018.correcting refs Dete for which hearing may be requested also revised EISENHUT.D O Division of Licensing 80/09/19 2pp
- --8010200475 Order directing licenses to respond fully & completely to IE Bullstin 79-018.re environ qualification of Class IE equipment, by 801101 EISENHUT, D. O Division of Licensing 80/09/19 App
- 8010230464 Forwards eddl documents pursuant to informal discovery agreement per 801016 request Documents are specific portions of Comm Ed QA manual re 10CFR21 reporting procedures, Related correspondence
 STEPTOE, P Isham, Lincoln & Beele 80/10/17. 2pp
- H. General correspondence
- 8010200633 Advises that Region 3 ltr re environ & well monitoring samples in plant area sent to listed concerned citizens on 800725 PAPPAS, H Region 3, Chicago, Office of the Director 80/09/30
- B010210342 Requests full investigation of pipe corrosion & possible cracking at facility prior to final EIS issuance & decontamination
 BHINEFLUO.M Illinois Safe Energy Alliance 80/10/16. 2pp.
- J Insurance & indemnity information
- 8010280613 Requests Endorsement 108 to Policy NP-43 & Endorsement 87 to Policy MF-22 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 Ip
- 8010070326 Forwards Endorsement 109 to NELIA Policy NF-43 in response to 800924 ltr Endorsement 108 never issued Util 760726 ltr of transmittel re Endorsement 87 to MAELU Policy MF-22 encl DBTER.J Commonweelth Edison Co
- --8010070329 Forwards Endorsement 87 to MAELU Policy MF-22 H/o encl OBTER: J Commonwealth Edison Co. 76/07/26 1p
- P. Operating license stage documents & correspondence
- 7812080199 Discusses possible dangers of LOCA in containment purging during normal plant operation Requests commitment to either case purging or limit purging to absolute min. not to exceed 90 hours per yr. Forwards SRP & model Tech Specs.

 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. App.
- --7812080207 Model Tech Specs 3 6.1 8 & 4.6.1.8 re containment ventilation sys, including limiting conditions & surveillance requirements * Operating Reactors Branch 2 (Pre 790625). 78/11/27. 2pp.
- 8010290355 Forwards eddl info to assist in preparation of final EIB for primary sys chemical cleaning. Encls discuss radioisotope analyses transurant concentration in cleaning waste, chemical cleaning & need for programmatic EIB JANECEK, R F Commonwealth Edison Co 80/09/04 12pp.
- 8007270143 Notification of 800724 meeting w/utils & Kerr-McGee Chemical Corp in Bathesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment, ALLISON, D P Bystematic Evaluation Program Branch. 80/09/08 Spp.
- B010140126 Submits add1 SEP topics to be added to NRC 771116 list for deletion from plant review. Items removed are not applicable to facility or are being reviewed as generic issue, Revised listing of DBE accident & transient groups encl CRUTCHFIELD.D. Operating Reactors Brench 5. 80/09/11. 5pp.
- B010220357 Concludes that response to ECCS clad swelling & rupture.Task B-47, is adequate No further action necessary. CRUTCHFIELD,D Operating Reactors Branch 5. 80/09/11. 2pp.

DOCKETED ITEMS

- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of THI action plan requirements Corrected table of implementation schedule also encl EISENBUT, D. O. Division of Licensing 80/09/19, 28pp.
- BOIO100361 Bubmits list of current qualification programs for EPRI util equipment qualification owners group resulting from BO0917 meeting Requests info re which program best fits NRC schedule.

 LAMKEN.D.C. Commonwealth Edison Co. 80/09/24 2pp
- 8010070394 Conturs w/factual info contained in SEP Topic V-11. A. "Requirements for Isolation of High & Low Pressure Sgs " Disagrees w/rept conclusion Conclusion should state that facility complies w/current licensing criteria in SRP 6.3. JANECEK.R.F. Commonwealth Edison Co. 80/09/26 2pp.
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of THI Action Plan Requirements" Urgss NRC to consider weighing each proposed revision against benefit of having plant changes inplemented promptly REED, C Commonwealth Edison Co 80/10/01. 5pp
- 8010150343 Forwards "ECCB Design Rept," Revision 2,8everal mods will be made prior to plant startup.

 JANECEK.R.F. Commonwealth Edison Co. 80/10/09. 1p.
- --B010150348 Revision 2, "ECCB Design Rept."
 * Commonwealth Edison Co. 80/09/30, 175pp.
- 8010150434 Forwards responses to NRC 780512 request for addl info concerning MPGI design Info is presented as update to ECCB design rept JANECEK, R. F. Commonwealth Edison Co. 80/10/09 12pp.
- 8010180444 Forwards XN-NF-79-95 (NP). Revision 1 "ECCS Evaluation of Dresden 1. Using Exxon Nuclear Co WREM-Based Monget Pump Evaluation Model." Break spectrum results identify location, size & configuration of worst break in reactor sys.

 JANECEK. R. F. Commonwealth Edison Co 80/10/09. 1p.
- --Boioi50452 Revision 1 of "ECCS Evaluation of Dreeden i.Using Exxon Nuclear Co WREM -- Based Nonjet Puap Evaluation Hodel." COLLINGHAM.R. E. : HORGAN.J N. BOFFER.O.A. Exxon Nuclear Co., Inc (aubs. of Exxon Corp.). XN-NF-79-93(NP) R1. 80/04/24. 85pp
- B010210401 Forwards leach rate data on Dow NS-1 solidified radioactive chelated decontamination solvent.Leach rates are less than published data obtained w/other hiquid wastes solidified w/ Dow process

 JANECEK, R. F. Commonwealth Edison Co. 80/10/16. 4pp.
- 8010280675 Forwards FES re primary cooling sys chemical decontamination for facility & notice of availability GRUTCHFIELD.D. Operating Reactors Branch 5. 80/10/17. 1p.
- --8010280679 Notice of availability of FES. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/10/17. 2pp.
- ---8010280685 Forwards notice of availability of FES.M/o encl. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/10/17. 6pp.
- --8010280688 FR8 re primary cooling sys chamical decontamination for facility. # Office of Nuclear Reactor Regulation, Director, NURES-0686, 80/10/31 225pp. Available at NTIS.
- 8010280700 Forwards FEB re primary cooling sys chemical decontamination NUREO-0686 & notice of availability.
 CRUTCHFIELD, D Deprating Reactors French B. 80/10/17. ip.
- B010270366 Responds to NRC 800619 ltr re loss of offsits power survey status Concludes that events reported in 791219 ltr have been misinterpreted as no instances of partial or complete power loss have been observed.

 JANECEK, R. F. Commonwealth Edison Co. 80/10/23. Spp.
- Q. Inspection reports: IE Bulletine & correspondence
- 8006040077 Forwards Waste Packaging Insp Rept 80-05 on 800017, No noncompliance noted.
 STORR: J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/04/14. 2pp.

- --8006040082 Waste Packaging Insp Rept 80-05 on 800317. No noncompliance noted Major areas inspected shipping paper requirements, DDT placarding requirements, radiation levels, removable contamination to prohibited articles of contents POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/04 App
- 8010210008 Provides updated info re admittance of Region 3 personnal to facilities. Forwards lists of personnal for whom permanent nonemployee badges are requested & personnal requiring badge for unescorted access in protected areas KEPPLER. J G Region 2. Atlanta. Office of the Director 80/09/03 4pg
- 8010140133 Forwards Inst of Nuclear Power Operations, "Evaluation of Dresden Nuclear Power Station" BYELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/09/30 ip.
- --8010140137 Forwards Inst of Nuclear Power Operations. "Evaluation of Dresden Nuclear Power Station " KEPPLER. J D Region 3, Chicago, Office of the Director. 80/09/16
- --8010280674 "Evaluation of Dresden Nuclear Station"
 # Institute of Nuclear Power Operations, 80/09/12, 40pp
- 8010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required KEPPLER, J. Q Region 3, Chicago, Office of the Director. 80/09/30, 10.
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee dualifications," No written response required KEPPLER, J. O. Region 3. Chicago, Defice of the Director. 80/10/02
- SD10270039 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting," No specific action or response requested, KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/10,
- 80:016:0036 Petition for Commission approval to delay environ qualification of electrical equipment until restart.Requests stay of NRC 800919 order requiring qualification by 80:101.
 STEPTOE.P. Commonwealth Edison Co. STEPTOE.P Isham. Lincoln & Beals. 80:10/14. App.
- --8010200673 Forwards revised 800829 order re response to IE Bulletin 79-01B.correcting refs. Date for which hearing may be requested also revised corrections. 80/09/19, 2pp
- --8010200575 Order directing licensee to respond fully & completely to IE Bulletin 79-018, re environ qualification of Class IE equipment, by 801101. EIGENRUID D Division of Licensing 80/09/19, App.
- 8010270120 Forwards IE Insp Repts 50-010/80-16,50-237/80-19 & 50-249/80-23 on 800922-26 & notice of violation Notice of violation withheld (ref 100FR2 790).
 HIND, J.A. Region G. Chicago, Bafeguards Branch 80/10/22 2pp.
- --8010270125 IE Insp Repts 50-010/80-16, 50-237/80-19 & 50-249/80-23 on 800922-26. Noncompliance noted: failure to maintain records of proper screening documentation on contractor personnel Details withheld (ref 10GFR2, 790), BELANDER.J. L. CHRIBTOFFER.D. Region 3, Chicago, Office of the Director, HIND.J.A Region 3, Chicago, Safeguards Branch. 80/10/21. 2pp.
- R. Periodic operating reports & related correspondence
- 8010210440 Forwards monthly operating repts for Sept 1780. 8001T.D. J. Commonweelth Edison Co. 80/10/18. 1p.
- --8010210441 Monthly operating repte for Sept 1780. CEISZKIEWICZ, B. Commonwealth Edison Co. 80/10/01, 15pp.
- 8. Reportable accurrences, LERs & related correspondence
- 8010090136 FNO-III-80-169:on 800904; reporter from Chicago Sun Times contacted NRC resident inspectors re allegations that 400,000 gallons of radioactive water leaked from station since Jul 1980.

 EARKER, J., DAVIS, A.B., REIMANN, F.W., Region G. Chicago, Office of the Director. 80/09/05, 2pp.

- B010090262 PNO-III-80-169A since 800905, extensive investigations by Region 3 & util personnel into allegations of radioactive release has not datermined whether actual release of low level radioactive weter occurred DAVIS,A.B., HEIBHMAN, F., REIMANN, F.W. Region 3, Chicago, Office of the Director 80/09/10, 2pp.
- 8010080638 PNO-III-80-176. potentially high press interest exists in results of Institute of Nuclear Power Operations insp of station. Bummany of insp rept encl BPE88ARD,R L. REPPLER, J. Region 3. Chicago. Office of the Director B0/09/15 App.
- T. Hearing transcripts on non-antitrust matters
- 8010160399 Transcript of Subcommittee on Dresden Nuclear Power Station, Unit 1 801008 hearing in Washington, DC. Pp 1-167 * ACR8 - Advisory Committee on Reactor Refeguards. 80/10/08, 167n.
- U Congressionel/Executive Correspondence
- 8010030425 Ack receipt of 800626 ltr trensmitting NUREQ-0686. DEB, reproposed chemical decontamination of plant in response to 800512 ltr. Requests comments on ancl Comm Ed 800910 ltr readdl costs resulting from NRC decision.

 CDRCDRAN, T. House of Rep., Interstate & Foreign Commerce. 80/09/29, 5pp.
- 8010270332 Responds to 800929 ltr re regulatory action of proposed chemical decontamination. NRC has been evaluating safety & environ issues of decontamination since 1975. Draft EI8 issued 800830 Final EI8 expected to be issued in Oct DIRCKS. M. J. Office of the Erecutive Director for Operations. 80/10/15 Gpp.
- ---8010270534 Forwards util 800915 ltr re chemical decontamination schedule delays caused by EIS Util financial ability to bring facility on line seriously impaired by late NRC decision to prapare EIS.

 CORCORAN.T House of Rep. 80/09/29 5pp.
- DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY
- J. Insurance & indemnity information
- B0102B024B Requests endorsements & copy of Amend 20 to Policy B-B DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity), B0/09/24. 1p.
- 8010060282 Forwards executed Amend 20 to Indomnity Agreement B-B, modifying prefatory language of Paragraph 5, Article I retransportation OLBEN, A.F. Babcock & Wilcox Co. 80/10/01. 2pp.
- DOCKET 50-14 BATTELLE HEMORIAL INST. CRITICAL FACILITY
- J. Insurance & indemnity information
- 8010280326 Requests Endorsements 79.80 & 82 to Policy NF-17. DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24. 1p.
- 8010080539 Forwards Endorsements 79,80,82,85 & 87 to ANI Policy NF-17. STALL,D.H. Battelle Memorial Institute, Columbus Laboratories. 80/10/03. Spp.
- DOCKET 50-20 MASSACHUSETTS INST. OF TECH, RES. REACTOR
- J. Insurance & indemnity information
- BOIO2B0141 Requests endorsement & copy of Amend 11 to Polcy E-39, DINITZ, I. Utility Finance Branch (formerly Antitrust & Indemnity). BO/09/24, 1p.
- 8010070391 Responds to NRC 900924 ltr. Amend 11 to Indemnity Agreement E-39 was forwarded on 791030.
 VALENTINE, K. Massachusetts Institute of Technology. 80/10/03. ip.

- P Operating license stage documents & correspondence
- 8010160473 Forwards info thet describes storage locations at reactor for radioective matls. Consideration given to handling, transfer & storage of metls. Storage capabilities adequate for safe handling & storage of matls. Requests approval. FECYCH. W. Hessechusetts Institute of Technology. 80/10/10, 2pp.

DUCKET 50-22 WESTINGHOUSE TEST REACTOR

- J Insurence & indemnity information
- 8010280179 Requests endorsement & copy of Amends 19 & 20 to Policy B-18, Endorsements 78, 79, 80 & 81 to Policy MF-4 & Endorsements 76 through 82 to Policy NF-52. DINTER: Utility Finance Branch (formerly Antitrust & Indemnity), 80/09/24. ip.
- DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- 8010220490 Forwards revised security plan. Plan withheld (ref 10CFR2.790). MILBON.H.E. Washington Univ. 80/10/15. 1p.
- G. Inspection reports, IE Builetine & correspondence
- 8010310074 Forwards IE Insp Rapt 50-027/80-02 on 800902-05,No noncompilence noted. CREMS.J.L. Region 5: San Francisco: Reactor Operations Nuclear Support Branch. 80/09/22. 2pp.
- ---8010310082 IE Insp Rept 50-027/80-02 on 800902-05. No noncompliance noted Major areas inspected organization logs & records, review & audit requalification training, procedures, surveillance & experiments.

 JOHNSON: A D. Region 5, San Francisco, Office of the Director, FAULKEMBERRY, P. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/18. 4pp.
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8010280148 Notification of 801021 meeting w/util in Bethasde, MD reresults of staff review of facility emergency plen, CARUBO, R. Operating Reactors Branch 5, 80/10/15, 2pp.
- O. Adjudicatory correspondence
- 8010300542 Forwards revised order correcting 800829 order for mod of DL which contained inaccurate refs. Date of hearing accordingly revised.

 EISENHUT, D 9. Division of Licensing, 80/09/19. 3pp.
- ---8010300548 Order for mod of OL DPR-3, correcting 800829 order which contained inaccurate refs. Response to NRC 800306 & 28 ltrs shall be filed by 801101. Request for hearing will not stey effectiveness, UCS patition discharged.

 EISENHUT, D. O. Division of Licensing. 80/09/19. App.
- 8010240417 Requests on behalf of Rowe Nuclear Conversion Campaign, public hearing in Frenklin County, MA prior to plent reopening & NRC help in obtaining util cooperation. Campaign 800902 ltr to util & response encl.
 MEYER, J. L. MILLER, E. M. , MILLER, B. H Affiliation Unknown. 80/10/06. 5pp.
- P. Operating license stage documents & correspondence
- 8010230398 Advises of review of response to NRC 791109 lbr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Util response is acceptable. No further action is necessary.

 CRUTCHFIELD, D. Operating Reactors Branch 5. 80/09/11. 2pp.
- 8010080492 Bubmits Proposed Change 170 to amend App A to Tech Specs for License DPR-3, Mods & additions to Tech Specs include TMI-2 Lessons Learned Category A items. Fee encl. VANDENBURGH.D. Yankse Atomic Electric Co. 80/09/16. Gpp.

- ---B0100B0496 Proposed Tech Spec changes for License DPR-3 Pages in App A Sections 3/4 3,3/4 4 & 6 are revised replaced & added Sections 2 C(6) & 2 C(7) are added as condition of license + Yankes Atomic Electric Co 80/09/16 16pp.
- 8010160126 Forwards request for add1 info on SEP Topics VI-7 B,VI-7 C, VI-10.VII-3,VIII-2 & VIII-3 CRUTCHFIELD.D. Operating Reactors Branch 5, 80/09/16 3pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D G Division of Licensing 80/09/19. 28pp
- 801004030B Informs of completing review in response to NRC 800815 ltr request re review of Tach Spacs & procedures to assure min level of water over fuel assemblies it approx 33 ft. Review shows compliance w/requirements No further action needed. HOODY, D E Yankee Atomic Electric Co 80/09/25 ip
- GO10150S30 Summary of S00904 meeting w/utils.B&H & NUS Corp re proposed upgrade mods to auxiliary faedwater sys Agenda & S00808 memo encl VISBING.0 S Operating Reactors Branch 4 G0/09/30 48pg.
- --8010150544 Submits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys. Beismically induced core melt due to loss of decay heat removal could be as much as six times more likely than NASH-1400 estimates,
 MATTSON:R J. Division of Safety Technology. 80/08/08 22pp
- 8010230598 Notification of 801009 meeting w/util in Bathesda,MD re SEP seismic evaluation.
 CARUSO,R Operating Reactors Branch 5. 80/10/07. 2pp.
- 8010310363 Accepts util commitments to 771023, "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability "
 CRUICHFILED, D Operating Reactors Branch 5. 80/01/08. 2pp
- B010160071 Forwards "Evaluation of Saismic Capacity of Yankee Huclear Power Station." No mods are required for steel yapor container or fuel pool bidg Mods are underway to increase seismic resistance of structure. Supporting documents encl. HGIDER, L. H Yankee Atomic Electric Co 80/10/15. 10pp
- --B010160574 "Evaluation of Seismic Capacity of Yankee Nuclear Power Station."

 * Yankee Atomic Electric Co 80/10/14. 6pp
- ---8010160577 "Preliminary Belimic Evaluation Summary Rept "
 * Earthquake Engineering Systems Inc 80/10/14, 16pp.
- B010240506 Forwards summary of NRC orders & 10CFR50,54f ltrs received during 1980.
 EDMARDB, D. H. Yankee Atomic Electric Co. 80/10/17 2pp
- 8010300356 Application for amend to License DPR-3, incorporating App A Tech Specs re facility mode to fire protection sys. VANDENBURGH, D. Yantee Atomic Electric Co. 80/10/20, 2pp.
- --8010300363 Proposed ravised Tech Specs Pages 3/4 3-28,3/4 7-30 through 3/4 7-40,3/4 7-7 & 6-21, reflecting fire protection mode.

 * Yenkee Atomic Electric Co. 89/10/20 13pg.
- G. Inspection reports, IE Bulletins & correspondence
- 8010060077 Forwards Hgt Meeting Rept 30-027/80-09 & performance evaluation rept resulting from 800626 meeting at facility ORIER, B. H Region 1, Philadelphia, Office of the Director. 80/08/04 ip
 - 010060081 Mgt Meeting Rept 30-029/80-09 on 800626, Subj discussed: licensee performance evaluation Performance evaluation rept encl.
 - enci.

 BORES.R.J. Region i, Philadelphia, Fuel Facility & Materials

 Bafety Branch. CARUBO.R. Region i, Philadelphia, Diffice of the

 Director. BRUNNER,E J. Region i, Philadelphia, Reactor Operations

 Nuclear Busport Branch. 80/07/23. 7pp.
 - >220135 Forwards IE Insp Rept 50-029/80-08 on 800505-16 & notice of folation.

 **ROMER,E.J. Region i. Philadelphia: Reactor Operations Nuclear Import Branch. 80/08/14 2pp.
 -)10220141 Notice of violation from insp on 800305-16. Details withheld (ref 100582.790). * Replan 1, Philadelphia, Office of the Director. 80/07/25. 1p.

- --B01022014B IE Insp Rept 50-029/80-0B on B00505-16 Noncompliance notedfailure to control entry to access controlled area Details withheld (ref 10CFR2.790) MARTIN.T T Region i, Philadelphia, Reactor Operations Nuclear Support Branch. FOLEY, T Region i, Philadelphia, Office of the Director 80/07/25 9pp
- 8010010716 Responds to IE Bulletin 79-17. Revision 1 Various piping syswere inspected & examined & no evidence of cracking due to stress corrosion was found MCCDV, D. E. Yankse Atomic Electric Co. 80/08/26 App
- 8010010381 Ack receipt of 800811 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/80-11 Details withheld (ref 10CFR2 790).
 MARTIN.W 0 Region 1. Philadelphia. Safeguards Branch 80/08/27
- --8010010386 Responds to NRC 800724 ltr re violations noted in IE Insp Rept 50-029/80-11. Corrective actions withheld (ref 10CFR 2 770). HGBDY, D E Yankee Atomic Electric Co 80/08/11 1p
- --8010010392 Forwards IE Insp Rept 50-029/80-11 on 800608-13 & notice of violation. Notice of violation withheld (ref 10CFR2 790). MARTIN.W G Region 1. Philadelphia. Bafeguards Branch 80/07/24.
- --8010010401 IE Insp Rept 50-027/80-11 on 800608-13 Noncompliance notedfailure to change lock on vital area door Details withheld (ref 10CFR2 790). LADUN,R H Region 1, Philadelphia, Office of the Director DEVLIN,J H. Region 1, Philadelphia, Safeguards Branch 80/07/07.
- 8010010198 Responds to IE Bulletin 80-19. Mercury-wetted relays are not used in reactor protection sys.

 MODDY, D. E. Vankse Atomic Electric Co. 80/08/29 2pp
- 8010010434 Responds to IE Builetin 80-20 Hestinghouse Type H-2 control suitches are not in use in safety-related applications MDODY.D E Yankee Atomic Electric Co 80/08/29 ip.
- 8010010727 Responds to IE Bulletin 80-15 re loss of emergency notification sys w/loss of offsite power. Emergency notification sys is supplied onsite power w/emergency backup power.

 HEIDER, L. H Yankee Atomic Electric Co. 80/08/27 2pp
- 8010240289 Forwards IE Insp Rept 50-029/80-10 on 800527-0703. No noncompliance noted BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Busport Branch 80/09/12 2pp
- --8010240296 IE Insp Rept 30-029/80-10 on 800527-0703 No noncompliance noted Major areas inspected shift logs, operating records, physical security, radiation protection controls & previous insp findings
 MARTIN.T T. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. FOLEY, T. Region i, Philadelphia, Office of the Director, 80/09/10. 11pp
- BO10200371 Responds to IE Bulletin 80-(B. "Maint of Adequate Min Flow Thru Centrifugal Cherging Pumps Following Becondary Bide High Energy Line Rupture " Min cooling is provided for centrifugal pumps used for high pressure injection MODDY.D E Yankee Atomic Electric Co 80/09/18, 1p.
- 8010270456 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coulant During Steam Generator Decontamination " No specific action or response requested, ORIER B H. Region i, Philadelphia, Office of the Director, BO
- 8010300108 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
 ORIER, B. H. Region 1, Philadelphia, Office of the Director. 80/09/30. 1p.
- 8010080354 Confirms items raised in BNL 790911 ltr to NRC re facility inservice insp program. Revision I Items addressed include flow path for HP18. full stroke test for 81-V-2 & verification for safety injection sys check valves. MOODY. D E. Yankes Atomic Electric Co 80/10/01. Gpp
- 8010240150 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/02, ip.

8010280171 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting," No specific action or response requested ORIER.B H Region 1, Philadelphia, Office of the Director 80/10/10 ip

R Periodic operating reports & related correspondence

8010150322 Forwards monthly operating rept for Sept 1980 MOODY, D.E. Yankee Atomic Electric Co. 80/10/10 ip

--8010150325 Monthly operating rept for Sept 1980 BEERS, F.C. Yankee Atomic Electric Co. 80/10/10 5pp.

B Reportable occurrences, LERs & related correspondence

8010160460 Forwards cancelled LER 80-12 AUTIO, H A Yankee Atomic Electric Co 80/07/02 in

--8010160461 LER 80-12 has been cancelled COLLINS, M Yankes Atomic Electric Co 80/07/02 1p.

V Operator Examinations

B010310369 Informs that staffing practices & capabilities of interim criteria for shift staffing comply w/requirements per B00731 ltr. Revised license program schedule to ensure that requirements per B00731 ltr will be met by 820701.

MOGDY.D. E Yankee Atomic Electric Go. B0/10/27, ip.

DOCKET 50-34 YANKEE ATOMIC POWER REACTOR

J. Insurance & indemnity information

8010280179 Requests endorsement & copy of Amends 19 & 20 to Policy B-18, Endorsements 78,79,80 & 81 to Policy MF-4 & Endorsements 76 through 82 to Policy NF-52 DINITZ. I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24.

DOCKET 50-37 TRIGA-MARK I PROTOTYPE REACTOR

J. Insurance & indemnity information

8010280720 Requests Endorsement 109 to Policy NF-34 Endorsement 47 to Policy MF-99 & Amends 29,30,31 & 32 to Policy B-9 DINITZ, I. Utility Finance Branch (Pormerly Antitrust & Indemnity) 80/09/24, 1p.

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

J Insurance & indemnity information

801028023B Requests endorsement 54 to Policy NF-105. DINITZ, I Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24. ip.

P Operating license stage documents & correspondence

8010200638 Forwards encl to 800817 ltr. "Union Carbide Medical Products Div Request for Exemption Per 100FR73,800718." Encl withheld (ref 100FR2.790). VOTH.H.M. Union Carbide Corp 80/08/15 ip.

B0102B040B Forwards corrected Tach Specs, originally submitted w/ application for renewal of License R-Bi GEORGE, K. D. Union Carbide Corp 80/10/20, 1p.

--8010280412 Corrected Yech Bpecs 4.0-4.10 & 6.13-6.1.5 1 re surveillance requirements & staffing # Union Carbide Corp. 80/10/20, 6pp

Q Inspection reports, IE Bulletins & correspondence

6010230716 Ack receipt of 791205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-054/79-04 & 70-0687/79-04 MARTIN: W O Region 1, Philadeiphia, Safeguards Branch. 80/02/20 is.

1

--8010230718 Forwards IE Insp Repts 50-054/79-04 & 70-0687/79-04 on 790821-24 & notice of violation Notice of violation withheld (ref 10CFR2 790)

MARTIN, N O Region 1, Philadelphia, Bafeguards Branch, 79/11/02 200

--8010230719 IE Insp Repts 50-054/79-04 & 70-0687/79-04 on 790821-24 Noncompliance noted alerm sys, hot cell manipulators & unlocked doors Details withheld (ref lOCFR2 790) BAILEY.R J Region i, Philadelphia, Office of the Director, DEVLIN.J W Region i, Philadelphia, Safeguards Branch 79/10/23 ip

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

J Insurance & indemnity information

8010280599 Requests endorsements & copy of Amends 12 & 13 to Policy E-34 DINITZ:I Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24, 1p

B01010030B Forwards Amend 12 to Indemnity Agreement E-34 Amend 13 will be submitted pending receipt of proper signature HENRY,L New York, State Univ of, Buffalo 80/10/02 2pp.

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

O Advisory Committee on Reactor Safeguards reports & correspondence

8010170068 Revision of tentative schedule for ACR8 subcommittee 800616-17 meeting in Sunol CA to discuss GETR * ACR8 - Advisory Committee on Reactor Safeguards. 80/06/10 2pp.

8010170080 Revision to tentative schedule for ACRS subcommittee 800616-17 meeting in Sunol.CA to discuss GETR * ACRS - Advisory Committee on Reactor Safeguards. 80/06/10. 2pp

, P. Operating license stage documents & correspondence

8010130428 Forwards add1 info re ability of QETR swismic scram sys to operate following postulated O 25 gravity pulse of short duration during first milliseconds of warthquake. Add1 records re Parkfield & Imperial Velley earthquakes whol DARMITZEL, R. H. Oeneral Electric Co. 80/10/13 5pp.

8010270347 Submits responses to info request re fuel flooding sys flow rates Fuel flooding sys utilizes single reservoir supply lines to containment bldg Lines split leading to reactor core & canal fuel storage tanks
DARMITZELR W. General Electric Co 80/10/27 3pp

DOCKET 50-72 UNIV. OF UTAH RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8009300449 Forwards amended annual operating rept for Jul 1979-June 1980 TURLEY, R. E. Utah, Univ of, 80/09/23 1p

~-8010010265 "Amended Annual Operating Rept, Jul 1979-June 1980 "
JENSON, C. M. , TURLEY, R. E. Utah, Univ. of 80/09/23, 3pp.

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

B. Reportable occurrences, LERs & related correspondence

8007080194 PND-II-80-127.on 800724.reactor was being brought to power when area monitor elarmed Caused by failure to remove startup source Reactor manually tripped & startup source removed.

ORAHAM.M J. QUICK, D. R. Region 2. Atlanta. Office of the Director. 80/07/24. 1p

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

J Insurance & indemnity information

8010280225 Requests endorsements & copy of Amends 7.8 & 9 to Policy B-56 & Endorsements 20.21 & 22 to Policy NF-202 DINITY. Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24. ip.

DOCKET 50-89 GENERAL ATOMIC CO

- J. Insurance & indemnity information
- 8010280720 Requests Endorsement 109 to Policy NF-34, Endorsement 47 to Policy NF-39 & Amends 29, 30, 31 & 32 to Policy B-9.
 BINITZ: L. Utility Finance Branch (formerly Antitrust & Indemnity).
 80/09/24. ip.
- 8010280382 Forwards Endorsement 109 to ANI Policy NF-34 & Endorsement 47 to MAELU Policy MF-59.
 CORREA, C Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/10/22 3pt

DOCKET 50-94 ROCKHELL INTERNATIONAL REBEARCH REACTOR

- J Insurance & indemnity information
- 8010280285 Requests Endorsements 91.92 & 93 to Policy NF-12 & Endorsements 81 & 82 to Policy NF-93.
 DINITZ, I. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24. 1p.
- 8010230002 Unexecuted Amend 17 to Indomnity Agraement B-13, changing Item 3 of attachment re license numbers. SALTZMAN.J. Utility Finance Branch (formerly Antitrust & Indomnity), 80/09/27. 1p.
- B010280434 Forwards executed Amend 17 to Indemnity Agreement B-13, deleting Item 3 re license number or numbers from agreement. BRINDLEY, J.H. Rockwell International Corp., Energy Systems Div. 80/10/23. 2pp.

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

- J. Insurance & indemnity information
- 8010210403 Requests tht Amends 10 & 11 to Indemnity Agreement E-4 be forwarded for consideration to provide info in response to NRC 800924 request. VERBAOE, D. A. Cornell Univ. 80/10/14. 1p.
- --8010210407 Requests info re Amends 10 & 11 to Indomn'ty Agreement E-4.
 DINITY, 1. Utility Finance Branch (formerly Antitruct & Indomn'ty).
 80/09/24 ip.

DOCKET 90-99 BABCOCK & WILCOX TEST REACTOR

- J Insurance & indemnity information
- 801028026B Requests enforsements 4 copy of Amend 20 to Policy B-B. DINITZ.I. Utility Finance Branch (Pormerly Antitrust & Indomnity). 80/09/24 ip
- 8010280662 Requests Endorsement 41 to Policy NF-198 & Endorsements 34 & 38 to Policy NF-56
 DINITZ. I. Utility Finance Branch (formerly Antitrust & Indemnity), 80/09/24. 19.
- 010060282 Forwards executed Amend 20 to Indemnity Agreement B-8, modifying prefatory language of Paragraph 5, Article I retransportation, OLBEN, A.F. Babcock & Milcox Co. 80/10/01, 2pp.

DOKET 50-106 GREGON STATE UNIV.

- A Insurance & indemnity information
- 8010280696 Requests endersement & copy of Amend 12 to Policy E-11. DINITZ.I. Utility Finance Branch (formerly Antibrust & Indeanity). 80/09/24. ip.
- G. Inspection reports, IE Bulletins & correspondence
- 8010280695 Forwards apscial close but IE Insp Rept 50-106/80-03, Facility meets contamination criteria of Rey Ouife 1.86 k may be released for unrestricted use. BOOK: HE. Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch. 80/09/24. ip,

- ---8010280701 Forwards special close out IE Insp Rept 50-106/80-03 on 800909 of activities under License R-51 BOOK,H.E. Region 5, San Francisco. Fuel Facility & Materials Safety Branch. 80/09/24, 2pp.

DOCKET 50-111 NORTH CARDLINA STATE UNIV RESEARCH REACTOR J. Insurance & Indemnity Information

- 8010280703 Requests endorsements & copy of Amend 13 to Policy E-7. DINITZ, I. Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24 ip.
- 8010230344 Forwards executed Amend 13 to Indemnity Agreement E-7, changing description of location.
 BRAY, T. C. North Carolina State Univ. 80/10/10 3pp.

DOCKET 30-112 UNIV. OF OKLAHOMA RESEARCH REACTOR P. Operating license stage documents & correspondence

- 8010170069 Forwards Amend 7 to License R-53 & safety evaluation. W/o notice of issuance.
 MILLER, J.R. Standardization & Special Projects Branch. 80/10/02,
- --8010170079 Amené 7 to License R-53 increasing possession limits of SAM to 1,700 g contained U-235 enriched equal to or less than 20%.
 MILLER, J. R Standardization & Special Projects Branch. 80/10/02
- ---8010170110 Bafety evaluation supporting Amend 7 to License R-53. MILLER, J. R. Standardization & Special Projects Branch 80/10/02 22p.
- 8010210083 Notice of issuance & availability of Amend 7 to License R-53.
 MILLER, J.R. Standardization & Special Projects Branch. B0/10/02

DOCKET 50-116 IONA STATE UNIV RESEARCH REACTOR G. Inspection reports, IE Sulletins & correspondence

- 8010310380 Forwards 1E Insp Rept 50-116/80-02 on 800922-24, No noncompliance noted HEISHMAN,R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch, 80/10/20, 2pp
- ---B010310585 IE Insp Rept 50-i16/B0-02 on B00722-24. No noncompliance noted, Major areas inspected: records, logs & organization, review & audit functions & requalification training RIJGHAY, K. R.; BDONE, J. M.; BOVD, D. C. Region 3, Chicago, Office of the Director. B0/10/16. Spp.

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR G. Inspection reports, IE Bulletins & correspondence

- BOI0270131 Forwards IE lnsp Rept BO-123/BO-02 on 800707-10 No noncompliance noted. DAVIS.A.B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/07/26. 2pp.
- --8010290104 IE Insp Rept 80-123/80-02 on 800909-10. No noncompliance noted, Hajor areas inspected; emergency plans & procedures, savrgency equipment & training & dvills.

 GREER, J. J. PAPERIELLO.C. J. Region 3, Chicago, Office of the Director, 80/09/20. 3pp.
- 8010310843 Forwards IE Insp Rept 50-123/80-03 on 800709-10, No nencompliance noted, DAVIG.A.S. Region G. Chicago, Fuel Facility & Materials Safety Branch, 80/10/03, 2pp.

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

- 8 Reportable occurrences, LERs & related correspondence
- 8010100410 PNO-IV-80-026 on 800821, irradiated sample container exploded & three experimenters suffered small cuts which were successfully decontaminated Property damage was minimal & decontamination is in progress

 EVERETT, J. Region 4, Dallas, Office of the Director. 80/08/21 ip

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

- 9. Adjudicatory correspondence
- B010240544 Motion to hold proceedings in abeyance until B01231 to allow for analysis of costs needed prior to determining return to operation. Certificate of Svc encl. LOCKE, R.F., FURBUSH, M. H., NORTON, B. Pacific Gas & Electric Co. B0/10/06 3pp.
- 8010230685 Response in opposition to licensee 801006 fourth motion to hold proceedings in absyance. Util offered no supportive explanation re failure to perform cost analysis by June 1980. Certificate of Svc encl.

 BHERHOOD, M. R., BROWN, L. J., Friends of the Earth, BHERHOOD, M. R. 81erra Club. 80/10/17. 8pp.
- 8010220674 Response stating no objection to applicant 801006 motion to hold proceeding in abeyance until 801231 for applicant to assess future commercial potential of facility. Certificate of 8vc encl.

 90LDBER0,8 C Hearing Branch 2. 80/10/21. App.
- P. Operating license stage documents & correspondence
- B010010765 Forwards trip rept describing B00714-17 field trip & visit to plant site & surrounding area by NRC geologist. No change in NRC position contemplated until util & consultants present documented written rept IPPOLITO, T A Operating Reactors Branch 2. B0/09/17 2ipp
- 8010220099 Forwards errats sheets amending 800905 ltr which provided praliminary clarification of THI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D O. Division of Licensing. 80/09/19. 28pp
- 8010240274 Forwards summary rept & apps to "Evaluation of Potential for Resolving Geologic & Beismic Issues at Humboldt Bay Power Plant Unit G." Investigations indicate high potential for resolving issues of surface faults & ground motion CLUFF, L. B. PATHARDHAN, A. B., SHAN, F. H. Hoodward-Clyde Consultants, Inc. 80/10/01. ip.
- --8010240279 Summary rept, "Evaluation of Potential for Resolving Geologic & Seismic Issues at Humboldt Bay Power Plant Unit 3." # Woodward-Clyde Consultants, Inc. 80/10/01. Sipp.
- --80i0240283 Apps to "Evaluation of Potential for Resolving Geologic & Seismic Issues at Humboldt Bay Power Plant Unit 3."

 Oversize drawings encl.

 * Hoodward-Clyde Consultants, Inc. 80/i0/01. 400pp
- Q. Inspection reports, IE Bulletins & correspondence
- 8010300386 Responds to IE Bulletin 80-17,8uppl 3 re failure of control rods to insert during scram at BHR.Review testing & resolution of any problems will be performed following completion of ongoing geologic investigation GRANE, P. A Pacific Ges & Electric Co. 80/09/04. 2pp.
- BO10300376 Responds to IE Builetins 80-17 & 80-19. Revision i, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E." No subj. relays used in protection sys. CRANE.P.A. Pacific Gas & Electric Co. 80/09/04. ip.
- 8010300391 Responds to IE Bullstin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Butches." No Type W-2 switches used in safety-related applications. CRANE.P.A. Pacific Gas & Electric Co. 80/09/08. ip.

- 8010290408 Forwards IE Circular 80-21, "Regulation of Refueling Craws." No written response required ENGELKEN.R H. Region 5, Ban Francisco, Office of the Director. 80/09/10 1p
- 8010080385 Responds to IE Bulletin 80-17, Suppls 1 & 2, "Failure of 76 of 185 Control Rods to Fully Insert During Screm at SHR." Appropriate surveillance tests on screm dump tank will be performed prior to returning unit to operation CRANE.P A. Pacific Oss & Electric Co. 80/09/17. App
- 8010280025 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required. ENGELKEN,R H. Region 5, San Francisco, Office of the Director. 80/10/02. 1p
- R Periodic operating reports & related correspondence
- 8010160469 Forwards monthly operating rapt for Sept 1980, WEEKS, E.D. Pacific Gas & Electric Co. 80/10/07. 1p.
- --8010140470 Monthly operating rept for Bept 1980. BAUM, P. M. Pacific Gas & Electric Co. 80/10/03. 4pp.
- 8. Reportable occurrences: LERs & related correspondence
- 8010280460 Forwards LERs 80-006/03L-0 & 80-005/03L-0, CRANE, P. A. Pacific Gas & Electric Co. 80/10/24. 1p.
- --8010280467 LER B0-006/03L-0. on 800926; w/plant shut down, leak observed in gate valve housing at screen wash pump discharge 6. Caused by corrosion & erosion, due to natural end-of-life. Valve will be replaced w/Pratt monoflange MK II butterfly valve.

 BAUM, P. M. Pacific Gas & Electric Co. 80/10/26. Ip.
- --8010280471 LER 80-005/03L-0; on 800926; w/plant shutdown; water seepage observed through cracks in pavement 4 ft above 10-inch line connecting screen wash pumps in fossil & nuclear units. Caused by faulty installation. Broken section to be replaced. BAUM, P H. Pacific Oas & Electric Co. 80/10/26. 1p
- V Operator Examinations
- B010280439 Responds to B00731, "Interim Criteria for Bhift Staffing." Present staffing levels at facility comply w/requirements. Echaeule for compliance for other modes of operation will be submitted following completion of geologic investigation CRANE, P. A. Pacific Gas & Electric Co. B0/10/21. 1p.

DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR

- J. Insurance & indemnity information
- 8010280684 Requests endorsements & copy of Amand 9 to Policy E-27.
 DINITY, I. Utility Finance Branch (formerly Antitrust & Indomnity).
 80/09/24. ip.
- 8010160547 Forwards executed Amend 9 to Indomnity Agraement E-29, changing amount of financial protection. PETTIT.8 Hashington, Univ. of. 80/10/04. 2pp.
- G Inspection reports, IE Bulletins & correspondence
- 8010100049 Forwards IE Insp Rept 50-109/80-04 on 800718-22. No noncompliance noted, 800K.H.E Region 5, Ban Francisco, Fuel Facility & Materials Bafety Branch, 80/09/04, 2pp.
- --B010100052 IE Insp Rept 80-139/80-04 on 80718-22. No noncompliance noted. Major areas inspected tradiation controls environ protection & emergency planning programs.

 CURTIS.J.R. HKMSLAMSKI.F.A. Region 5. Ban Francisco. Office of the Director. BOOK.H.E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch. 80/09/03. App.

DOCKET 50-141 STANFORD UNIV. RESEARCH REACTOR

- J. Insurance & indemnity information
- 8010280670 Requests endorsements & copy of Amend 10 to Policy E-19. DINITZIE, Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24. 1p.

8010080418 Forwards executed Amend 10 to Indemnity Agreement E-17, defining "in course of transportation within US" BETH,R II Stanford Univ 80/10/02, 2pp

DOCKET 50-142 UCLA TRAINING REACTOR

9. Adjudicatory correspondence

8010010233 Notice of appearance in proposed renewal of UCLA research reactor license proceeding Certification of Svc encl H0005;0 R., HELWICK,C California, Univ of, Los Angeles 80/09/26

B010070004 Order re B00B25 prehearing conference, Committee to Bridge The Cap interest established Contentions II, III. IV & VII accepted as rephrased by NRC, Contentions VI & XX deferred Differences re remaining contentions will be negotiated.
BDMERB.E S Atomic Bafety and Licensing Board Panel B0/10/02 3pg

8010150010 Notice of appearance in proceeding Certificate of Svc ancl GRAY, J R Hearing Branch 1 80/10/09 Jpp.

B010130001 Forwards draft stipulation reflecting 800925 meeting & 801002 teleon Hods can be discussed during 801022 conference call 80v list agreed to at 800925 meeting also encl LAVERTY, J H. Hearing Branch 1 80/10/10. 17pp.

8010150003 Forwards draft stipulation reflecting 800725 meeting & 801002 teleon Mods can be discussed during 801022 conference call Svc list agreed to at 800925 meeting also enci.

LAVERTY. J. H. Hearing Branch 1 80/10/10 17pp

8010200593 Order granting extension until 801028 for Commission to determine whether to review Director's denial under 10CFR2 206. CHILK-S. J. Office of the Secretary of the Commission 80/10/14.

8010300053 Discusses 800925 prehearing conference & subsequent events re wording & admissibility of contentions. Final agreement will be reached at 801110 conference Stipulation will be filed by 801128 & final statements of position on 801128 LAVERTY, J H. Hearing Branch 1. 80/10/27, 2pp

B010300037 Order granting estension until 801107 for Commission to elect whether to review Director's decision under 100F2, 206. CMLLA, B J Office of the Secretary of the Commission 80/10/27

J Insurance & indemnity information

B010300364 Requests endorsements & copy of Amends 7 & 9 to Policy E-16.
DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity).
80/09/24. 1p

. Hearing transcripts on non-antitrust matters

10100041 Transcript of B00925 prehearing conference we proposed ranewal of facility license in Los Angeles CA Pp 1-75 * Atomic Sefety and Licensing Board Panel B0/09/25 77pp

CRET 30-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY
Inspection reports: IE Bulletine & correspondence

010230465 Forwards IE Insp Rept 50-146/79-01 on 790720-22,1019 & 800225 & notice of violation SHITH, G.H. Region i, Philadelphia. Fuel Facility & Materials Safety Branch 80/09/05 2pp

-8010230668 Notice of violation from insp on 790920-22, 1019 & 8000325.

Region i, Philadelphia, Gaston of the Director, 80/09/05. Ip.

i on 790720-22,1019 & 800325 iduct adequate surveys. him Office of the Director, as Fuel Facility & Materials

spondence

reribes status of

---B010070488 "Annual Rept for 1979 " Describes status of decommissioning facility & Barton Nuclear Experimental Goro 80/09/25 11pp

DOCKET 50-147 ROCKHELL INTL CORP CRITICAL FACILITY

J Insurance & indemnity information

8010280285 Requests Endorsements 91:92 & 93 to Policy NF-12 & Endorsements 81 & 82 to Policy NF-93 DINTIZ. I Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24 ip

8010230002 Unexecuted Amené 17 to Indemnity Agreement B-13, changing item 3 of attachment re license numbers BALTMAN, J Utility Finance Branch (formerly Antitrust & Indemnity), 80/09/27 ip

8010280499 Forwards Amend 17 to Indemnity Agreement B. inadvertently omitted from 801001 itr Requests signature & return to NRC, REID,R H Operating Reactors Branch 4 80/10/10 3pp

8010280434 Forwards executed Amend 17 to Indemnity Agreement B-13, deleting Item 3 re license number or numbers from agreement BRINDLEY.J H. Rockwell International Corp., Energy Systems Div. 80/10/23. 2pp.

8010200024 Forwards order terminating License CX-17 & related safety evaluation W/o encl Amend 17 to Indemnity Agreement 8-13 REID.R H Operating Reactors Branch 4 80/10/01 2pp

--8010200029 Bafaty evaluation supporting order terminating License CX-17.

* Operating Reactors Branch 4 80/10/01 1p

--8010200036 Order terminating License GX-17 NOVAK.T M Assistant Director for Operating Reactors 80/10/01.

DOCKET 90-148 UNIV OF KANSAS RESEARCH REACTOR

J. Insurance & indomnity information

8010280152 Requests endorsement & copy of Amend 10 to Policy E-21. DINITZ, I. Utility Finance Branch (formerly Antitrust & Indomnity). BO/09/24 ip

R. Periodic operating reports & related correspondence

B010020464 Provides annual operating rept for Jul 1979-June 1980. MEGLER, R B Kansas State Univ 80/09/22 3pp.

DOCKET 50-150 DHID STATE UNIV. RESEARCH REACTOR

J Insurance & indomnity information

8010280689 Requests endorsements & copy of Amends 9 & 10 to Policy E-8 DINITZ. I Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24. ip.

G Inspection reports: IE Bulletins & correspondence

B010270392 Forwards IE Insp Rept 50-180/80-04 on 800930. No noncompliance noted Details withheld (ref 10GFR2 790), HIND: J. A. Region 3: Chicago: Safeguards Branch 80/10/15 2pp.

--8010270374 IE Insp Rept 50-150/80-04 on 800930 No noncompliance nated. Major areas inspected approved security plan & implementation re-protection of SNM & security organization Details withheld (ref 10CFR2 790). XNICELEY, J. Region 3, Chicago, Office of the Director, HIND, J. A. Region 3, Chicago, Safeguards Branch, 80/10/10, 1p

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

F. Becurity, medical, emergency & fire protection plans

B010080524 Submits items re physical security plan requirements. Info withheld (ref 10CFR2, 790). BECK, Q P Illinois, Univ. of, Urbana-Champaign. 80/09/29. 1p.

P Operating license stage documents & correspondence

- 8010210530 Requests NRC permission to use BF3 start-up channel in place of channel described in Aug 1967 SAR New channel fed to sealer where either continuous count may be obtained or to obtain counts for preset time Procedures encl BECK.0 P. MILAVICKAS,L R Illinois, Univ of, Urbana-Champaign 80/10/16 2pp
- --8010210533 "Use of BF3 Bys for Start-Up Channel "
 MILAVICKAS,L R Illinois, Univ of, Urbena-Champaign 80/10/16
- 8010210537 Requests permission to utilize alternate startup channel under License R-115 BECK.0 P Illinois, Univ of, Urbana-Champaign 80/10/17 ip.
- 8010310142 Forwards Amend 03 to License R-115 & safety evaluation MILLER, J R Btandardization & Special Projects Branch 80/10/23, 2pp
- --8010310147 Amend 03 to License R-115 authorizing substitution of BF3 neutron counting sys for currently authorized sys & use of either administrative rod-prohibit procedures or automatic interlock.

 MILLER.J R Standardization & Special Projects Branch. 80/10/23 App
- --8010310151 Safety evaluation supporting Amend 03 to License R-115 * Office of Nuclear Reactor Regulation, Director 80/10/23 3pp

Q Inspection reports, IE Bulletins & correspondence

- 8010200097 Ack receipt of 800909 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-151/80-02 & 50-356/80-02
 DAVIS:A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/09/29 ip
- --8010200102 Informs of error noted in Item 15, independent measurements, Reactor actually operating at 500 kW during survey BECK, O.P. Illinois, Univ. of, Urbana-Champaign, 80/07/09 ip.
- --8010200108 Responds to NRC 800902 ltr re violations noted in IE Insp Repts 50-151/80-02 & 50-336/80-02 Corrective actions written confirmation will be obtained previous to shipping of Class A matis MILEY.O H Illinois, Univ of, Urbana-Champaign 80/09/09 2pp
- --8010200113 Forwards IE Insp Repts 50-151/80-02 & 50-355/80-02 on 800819-20 & notice of violation. DAVIE.A.B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/09/02 2pp
- --8010200117 Notice of violation from insp on 800817-20 * Region S. Chicago, Office of the Director. 80/08/28. ig
- --8010200124 IE Insp Repts 50-151/80-02 & 50-356/80-02 on 800819-20 Noncompliance noted failure to maintain certification & safety analysis, required of all shippers of spec 7A packaging, demonstrating that container meets spec 7A, PAUL, R A , FISHERIM L Region 3, Chicago, Office of the Director 80/08/28. 7pp.

DOCKET 50-153 BETTIS CRITICAL FACILITY

J Insurance & indemnity information

8010280179 Requests endorsement & copy of Amends 19 & 20 to Policy B-18. Endorsements 78.79.80 & 81 to Policy MF-4 & Endorsements 76 through 82 to Policy NF-52 DINITY. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24 ip

DOCKET 50-155 BIG ROCK FOINT NUCLEAR PLANT

- F. Security, medical, emergency & fire protection plans
- 8010020167 Requests add1 info & commitments re util emergency plan submittals for final review ve NUREO-0654 criteria. Outstanding items include assignment of responsibility, onsite amergency organization & emergency response support CRUICHFIELD, D. Operating Reactors Branch 5 80/09/05 8pp.

9 Adjudicatory correspondence

- 8010020235 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment Submittal of info required by 801101 CRUTCHFIELD.D Operating Reactors Branch 5 80/08/29, 2pp
- --8010020240 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENKUT, D O Division of Licensing 80/08/29 &pp.
- --8010020246 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing 80/08/29 App.
- 8009160205 Memorandum & order accepting ABLB 800912 referral of rulings re environ impacts of spent fuel pool expension. Opposing briefs shall be filed by 801020 supporting briefs by 801124 & reply briefs by 801210 CEG coursel may file same BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/12 2pp
- 8010300527 Forwards revised orders correcting 800829 orders for mod of OL & provisional OL which contained inaccurate refs Date of hearings accordingly revised.

 EISENHUT, D 0 Division of Licensing 30/09/19 4pp
- --8010300932 Order for mod of OL DPR-6, correcting 800B29 order which contained inaccurate refs Response to NRC 800306 & 2B itrs shall be submitted by 801101 Request for hearing will not stay effectiveness UCB petition discharged EIGENHUT, D. G. Division of Licensing 80/09/19 App
- --8010300538 Order for mod of provisional CL:correcting 800829 order which contained inaccurate refs.Response to NRC 800306 & 28 ltrs shall be filed by 80i101 Request for hearing will not stay order UCS petition discharged.

 EISENHUT, D 0 Division of Licensing. 80/09/19 App
- 8010020031 Order urging parties to address applicability of Section 102 (2)(E) of NEPA on expansion of spent fuel gool within add1 term of operation that mod would permit ASLB 800912 referral may require ASLAB to decide issue w/o remand, TOKPRINS.B A. Atomic Safety and Licensing Appeal Panel, 80/09/30, 2pp
- 8010230446 Forwards first set of interrogatories re spent fuel pool expansion history
 O'NETLL, J Affiliation Unknown 80/10/13 ip
- --8010230449 First set of interrogatories to NRC seeking pertinent background info to spent fuel pool expansion issue O'NEILL.J Affiliation Unknown. 80/10/13 4pp
- 8010200190 Forwards ASLB 800912 order re NEPA review ASLAB 800912 order & ASLB 800930 order re spent fuel mod hearing H/o ancl, MODRE, J. E. Hearing Branch 2 80/10/17 1p
- 8010220313 Reply brief in opposition to ABLB 800912 memorandum & order on NEPA review, requiring EIS in spent fuel pool expansion proceeding ABLB is not vested w/such authority prior to fair evidentiary hearings W/Certificate of Svc.
 MODRE, J. E. Heering Branch 2 80/10/20 34pp
- B010220333 Forwards listed documents re spent fuel pool mod proceeding, in response to J O'Neill request M/o encl.
 MODRE, J. E. Hearing Branch 2. 80/10/20. 1p
- 8010240364 Brief in opposition to ASLE 800912 order requesting EIB on proposed spent fuel pool mod EIB has no basis absent EIA. 8cope of action misconstrued. Urges applicability of NEPA requirement re cost/benefit analysis. M/Certificate of Byc. OALLO, J. THORNTON, P. Consumers Power Co. QALLO, J. Isham, Lincoln & Beale. 80/10/20 32pp.
- 8010240590 Forwards J O'Neill & CPC briefs before ASLB in response to 801013 request. Remaining documents available in PDR & LPDR. H/o encls
 H/O encls
 HOORR: J E Hearing Branch 2 80/10/23 1p
- 8010270359 Advises of code requirements re svc of papers Docteting & Svc Branch does not provide free copying & svc of interrogatories. Since encl regulation is new branch will comply w/request for svc of 801013 interrogatories QROSEMAN, H Atomic Safety and Licensing Board Panel. 80/10/23, 280.

- BO10290039 Formards NRC B01020 brief opposing Memorandum & order on NEPA review per 801027 telcon W/o encl. MOORE, J. E. Hearing Branch 2 80/10/28, 1p.
- 8010300098 Forwards NRC 801020 brief opposing memorandum & order on MEPA review.per J O'Neill 801027 telcon. W/o encl. MOORE, J E. Hearing Branch 2 80/10/28 1p.

H. General correspondence

- 8010290146 Responds to 800816 ltr transmitting C Will questions re existing safeguards to prevent spent nuclear fuel accidents & factility exemption from minimal safety stds. BIRCREM J Office of the Elecutive Director for Operations. 80/10/21, lipp.
- P. Operating license stage documents & correspondence
- B010010798 Forwards SEP Technical Evalution Topic VIII-2, "Diesel Congrators," as input to integrated safety assessment. Evaluation compares as-built facility design against NRC criteria. CRUTCHFIELD.D. Operating Reactors Branch S. 80/08/20. 2pp.
- --8010100148 "Onsite Emergency Power Bys Dissel Generator," BEP technical evaluation Topic VIII-2.for Big Rock Point. * Operating Reactors Branch 5. 80/08/20, 13pp.
- 8010010501 Forwards SEP Topic VI-7.C.1. "Independence of Redundant Onsite Power Bys." Assessment compares facility w/criteria used for licensing new facilities. CRUICHFIELD.D. Operating Reactors Branch 5. 80/08/20. 2pp.
- --B010010508 SEP Topic VI-7.C i. "Independence of Redundant Onsite Power Bys." * Operating Reactors Branch 5, 80/09/29 App
- 8010230392 Advises of review of response to NRC 791109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of repture Util response is acceptable. No further action is necessary.

 CRUTCHFIELD.D Operating Reactors Branch 5. 80/09/11. 3pp.
- 8010220099 Forwards errate sheats amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENRUT, D Q Division of Licensing. 80/09/19. 28pp.
- 8010220475 Informs that RE Schaffstall 800828 itr to DM Crutchfield on Ashaif of SEP pamers group constitutes util response to NRC request for action plan re cable tray selamic design. HOPFHAN, D. P. Gensumers Power Co. 80/09/19. ip.
- 8010220468 Advises that util response to NRC evaluations of SEP topics will be submitted prior to 801231. Manpower limitations due to work on electrical squipment qualifications prevent development of datailed comments by requested date. HOFFMAN, D. P. Consumers Power Co. 80/09/24. 2pp.
- 8010070303 Forwards application for amend of License DPR-6, changing Tech Space to auxiliary neutron sources, Class III fee encl, HOFFMAN, D. P. Consumers Power Gq. 80/09/25, 1p.
- --8010070306 Application for emend of License DPR-6, changing Tech Spec 5.1.6 re auxiliary neutron sources.

 Consumers Power Co. 80/09/25. 3pp.
- 8010220480 Forwards proposed Tech Spec changes to License DPR-6, in response to MIC 800702 ltr requesting amond application to incorporate specs addressing actions taken in response to Category A items from THI-2 Lessons Learned HOFFMAN, D. P. Consumers Power Co. 80/09/25, 2pp.
- --8010220481 Proposed Tech Spec changes to License DPR-6 incorporating space addressing actions taken in response to Category A items from TMI-2 Lessons Learned.

 ** Consumers Power Co. 80/09/23, lipp.
- S010090410 Forwards application for amend of License DPR-6, changing Tach Specs 11.4.1.4 re firs protection age automatic isolation valve. Hos will be performed during 1980 refueling outage beginning S01031.61 was III fee such. HOFFMAN. D. P. Consumers Power Co. 80/10/01. 1p.

- --8010090411 Application for amend of License DPR-6, changing Tech Spac 11.4.1.4 re fire protection mys automotic isolation valve 4 Consumers Power Co. 80/10/01 2pp
- ~-8010090413 Proposed Tech Spec 11.4 1 4 rd fire protection systematic isolation valve. 4 Consumers Power Co 80/10/01 ip
- 8010310203 Forwards Amends 35 & 61 to Licenses DPR-6 & DPR-20, respectively & notice of issuance & availability CRUTCHFIELD.D. Operating Reactors Branch 5. 80/10/01, 4pp.
- --8010310206 Amends 35 & 61 to Licenses DPR-6 & DPR-20, respectively, adding license conditions to include approved safeguards contingency plan as part of licenses.

 CRUTCHFIELD.D. Operating Reactors Branch B 80/10/01 4pp.
- --8010310210 Notice of issuence & availability of Amends 35 & 61 to Licenses DPR-6 & DPR-20, respectively. CRUTCHFIELD, D Operating Reactors Branch 5. 80/10/01. 3pp.
- 8010100237 Porwards Tech Spec change to Section 5 R.2 adding new Paragraph h.in response to NRC 800707 request re continued operability of control rod drive sys during power operation HOFFRAN, D. P. Consumers Power Co. 80/10/03 1p.
- ---8010100243 Tech Spec change for Section 5.2.2 Adds new Paragraph h to operation of scham dump tank valves & high level alarm. DEHITT,R,B. Consumers Power Co. 80/10/03. 2pp.
- BOI0150291 Submits proposed seismic evaluation program & basis for continued interim operation in response to NRC 800804 request. Site specific spectra in preliminary stayes of completion Continued operation planned.

 HOFFMAN, D. F. Consumers Power Co. BO/10/10 7pp
- B010150403 Forwards response to NRC B00804 request for add1 info reprimary reactor containment leakage testing. Current testing program gives adequate assurance of containment integrity. HOFFMAN.D.P Consumers Power Co. B0/10/10 7pp
- ---8010150405 "PLID:Fire & Post Incident Cooling Sys."

 * Bechtel Corp. 71/11/19 1p
- 8010210574 Forwards "Analysis of Containment Atmosphere Over-Temp Condition Resulting from Steam Line Breaks, Big Rock Point " Proposed implementation schedule re mode will be provided by 80115. WITHROW, G. C. Consumers Power Co 80/10/15 2pp
- --B010210579 "Analysis of Containment Atmosphere Over-Temp Condition Resulting from Steam Line Breaks: Big Rock Point." * Consumers Power Co. B0/10/31 18pp.
- 8010220533 Discusses 780727 Tech Specs change request to update ABME Code usage for final period of 10-yr interval.Code addition will be 1977 edition of ABME Soiler & Pressure Vassel Code, Section XI w/addenda through Summer 1978 WITHROW, O C. Consumers Power Co. 80/10/15. ip.
- 8010270285 Responds to NRC 770927 request for commitment to implement valve qualification program Forwards documentation resulting from Allis-Chaimers analyses of butterfly valves & HPR Associates analyses of swing-check valves.

 HOFFMAN.D. 8. Consumers Power Co. 80/10/24, 10pp.
- ---B010270287 "Reactor Bldg. Ventilating, Heating & Cooling Piping & Instrumentation Diagrams."

 OLSEN: D. Hechtel Corp. 79/10/30 1p.
- ~~8010290290 "Test Rept on Allis-Chalmers A-Inch BTREAMBEAL Butterfly Valve in Air Concerning Nuclear Containment Isolation Valves."

 8GHAARI, P. R., ZEIDERB, R. H., OOLDMAN, H. L., Allis-Chaimers Corp., VER-0209. 79/12/17. 14App.
- --8010290292 Revision 1 to "Pisc Impact Velocity for Containment Ventilation Bye Check Valve Closure."

 * MPR Associates: Inc. MPR-664 Ri. 80/06/30, 148pp.
- BO10310452 Responds to NRC B01001 request for plans to evaluate acrea discharge sys beyond scope of IE Bulletin B0-17. Forwards BMR owners sub-group criteria for re-evaluation of scram discharge sys Clarifications re criteria applicability anci. HOFFMAN.D.P. Consumers Power Co. B0/10/27. Spp.

- Q Inspection reports, IE Bulletins & correspondence
- B010150118 Forwards IE Insp Rept 50-155/80-09 on 800703-0804.No noncompliance noted HEIBHMAN.R.F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/08/20, 2pp
- --B010150124 IE Insp Rept 50-155/B0-09 on B00703-0B04, No noncompliance noted, Major areas inspected operational safety verification & review & activities pertaining to IE Bulletin 80-17 recontrol rod insertion failure B000, D.C., WRIOHT, Q.C. Region 3, Chicago, Office of the Director, B0/08/20 4pp
- 8010090514 Forwards response to IE Bulletin, Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR."
 Current scram discharge sys meets requirements w/o addl mods or surveillance
 HOFFMAN.D P Consumers Power Co. 80/09/02. 3pp.
- 8010210071 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas.

 KEPPLER, J G Region 3, Chicago, Office of the Director. 80/09/30, San.
- B010020307 Forwards into for review to resolve items of noncompliance re security issue noted in IE insp Rept 50-155/80-05; Item 1. Info withheld (ref 10CFR2.770) HOFFMAN.D P. Consumers Power Co. 80/09/24. 1p.
- 8010160235 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/09/30.
- 8010220131 Responds to IE Bulletin 80-13 re cracking in core apray spargers. Util does not intend to inspect sparger during all refueling outages but will inspect every 40 months per ABME code.
 HOFFMAN.D P. Consumers Power Co HO/10/01. 2pp.
- 8010280664 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications." No written response required. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/02. 1p.
- 8010270022 Forwards IE Info Notice 80-34, "Failure of Steam Generator Bupport Bolting." No specific action or response requested.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/10,
- 8010270386 Forwards IE Insp Rept 50-155/80-11 on 800917-19. No noncompliance noted Details withheld (ref 10CFR2.790). HIND, J. A. Region 3, Chicago, Bafeguarde Branch. 80/10/15. 2pp.
- --8010270389 IE Insp Rept 50-155/80-11 on 800917-19. No noncompliance noted Major areas inspected metl control & accountability including facility organization & operation & storage & internal controls. Rept withheld (ref 100FR2.790). FINLEY, A.O., PATTERBON, J. P. Region 3, Chicago. Office of the Director. HIND, J. A. Region 3, Chicago. Bafeguards Branch. 80/10/15. 1p.
- 8010290153 Forwards IE Insp Rept 50-195/80-12 on 800922-26 k notice of violation, Notice of violation withheld (ref 10CFR2, 790), HIND, J. A. Region 3, Chicago, Bafeguards Branch, 80/10/21. 2pp.
- --8010290155 IE Insp Rept 50-155/80-12 on 800922-26. Noncompliance noted: failure to conduct proper background acreening of contractor personnel. Datails withheld (ref 100FR2. 790).
 MADEDA,T.J., PIRTLE,G.L. Region 3, Chicago, Office of the Director. HIND,J.A. Region 3, Chicago, Bafeguards Branch. 80/10/20. 2pp.
- R. Periodic operating reports & related correspondence
- BO10140448 Forwards monthly operating rept for Sept 1980, HARTMAN, C. J. Consumers Power Co. 80/10/06. 4pp.
- --B010140455 Monthly operating rept for Sept 1980. HIMESAUCH, N. Consumers Power Co. 80/10/07. 2pp.

- 8. Reportable occurrences, LERs & related correspondence
- BO1010041B PNO-III-BO-151 on BOOB13, licensee reported that analysis of small break accidents inside containment indicates that containment design tenp would be exceeded. New operating instruction assures temp not exceeded.
 BDYD, D. C. . HEISHMAN, R. F. Region 3, Chicago, Office of the Diractor. BO70BJ13. 2pp.
- 8010090280 PNO-III-80-162 on 800831, labor contract expires Negotiations for new contract are continuing Possibility exists that strike might be called 800901 or later Strike would involve operations, maint & const personnel.

 JORGENBERG B. BOYD, D. C. HEIBHMAN, R. F. Region 3, Chicago, Office of the Director 80/08/29, 2pp.
- 8010140411 Forwards LERs 80-028/03L-0 & 80-029/03L-0. HOFFMAN, D. P Consumers Power Co 80/10/10. ip.
- --B010140416 LER B0-028/03L-0 on 800909; following automatic test circuit alarms; sensor Channel D removed from svc to vent reactor water level transmitter LT3183, Tech Bpec change request submitted 80828 to provide greater margin in trip setpoint a Consumers Power Co. 80/10/07 ip.
- --8010140422 LER 80-029/03L-0; on 800911, during manthly gravity checks, cell 12 of reactor depressurizing battery for Channel D had low reading of i 171, Cause unknown, Cell replaced 800917, Consumers Power Co. 80/10/07, ip.
- 8010200554 Forwards LERs 80-032/03L-0 & 80-033/01T-0. WITHROW, 0. C Consumers Power Co. 80/10/15. 1p.
- ---B010200564 LER 80-032/03L-0 on B00917.following intermittent automatic test circuit alarms: sensor channel D of reactor depressuriting sys was removed to vent reactor water level transmitter LT0180 Gaused by conservative callbr shift.

 * Consumers Power Co. B0/10/15. ip.
- --8010200571 LER 80-033/01T-0:on 801003, investigation of 800927 minor leak in reactor cleanup demineralizar sys established event reportability. Caused by bearing failure of canned rotor pump * Consumers Power Co. 80/10/15. 2pp.
- 8010210574 Forwards "Analysis of Containment Atmosphere Over-Temp Condition Resulting from Steam Line Breaks, Big Rock Point." Proposed implementation schedule re mode will be provided by 801115 WITHROW, O. C. Consumers Power Co 80/10/15, 2pp,
- --8010210579 "Analysis of Containment Atmosphere Over-Temp Condition Resulting from Steam Line Breaks.Big Rock Point." # Consumers Power Co. 80/10/31. 18pp.
- 8010220456 Forwards LER 80-030/03L-0. WITHROW, G. C. Consumers Power Co. 80/10/17. 1p.
- --B010220660 LER 80-030/03L-0 on 800919 minor seat leakage discovered in containment isolation valve CV4027. Caused not determined. Valve seat scheduled for replacement due to previous indication of wear.

 ### Consumers Power Co. 80/10/17 1p.
- 8010230393 Forwards LER 80-031/03L-0, HOFFMAN, D. P. Consumers Power Co. 80/10/20 1p.
- --8010230399 LER 80-031/03L-0 on 800923 reactor level transmitter LT3183 on reactor depressurization sys was returned to svc w/trip satpoint lower than required Causad by equipment defect. Revised setpoints implemented, , * Consumers Power Co. 80/10/20, 4pp.
- DOCKET 50-154 UNIV. OF HIBCONBIN RESEARCH REACTOR

 G. Inspection reports, IE Bullstins & correspondence
- 8010030495 Forwards IE Insp Rept 50-156/80-03 on 800811-12.No noncompliance noted, DAVIG,A, E. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/08/28. 2pp.
- --B010030502 IE Insp Rept 50-156/80-03 on GO0811-12. No noncompliance noted Major areas inspected emergency plan & procedures, decontamination equipment & supplies & evacuation drills. DAVIS, A.B. Region 3. Chicago. Fuel Facility & Materials Bafety Branch. 90/08/24. 3pp.

- B010030515 Forwards IE Imsp Repts 50-156/80-04 & 70-0134/80-02 on B00B11-12 No moncompliance noted. DAVIS,A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. B0/08/28 2pp
- --8010030517 IE Insp Repts 50-154/80-04 & 70-0134/80-02 on 800811-12 No noncompilance noted Major areas inspected radiation protection training, radwaste mgt program, effluent controls & transportation activities
 FIBHER,W L. Region 3, Chicago, Fuel Facility & Materials Safety
 Branch BOVENDALE,P C. Region 3, Chicago, Office of the Director-80/08/24

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

J. Insurance & indemnity information

80/08/26

- 8010210403 Requests tht Amends 10 & 11 to Indemnity Agreement E-4 be forwarded for consideration to provide info in response to NRC 300924 request VERBAGE D A Cornell Univ 80/10/14 ip
- --B010210407 Requests info re Amends 10 & 11 to Indemnity Agreement E-4.
 DIMITZ. 1 Utility Finance Branch (formerly Antitrust & Indemnity).
 B0/09/24, ip.
- DOCKET 50-160 GEORGIA INST. OF TECH. RESEARCH REACTOR
- @ Inspection reports: IE Bullstins & correspondence
- 8003240244 Forwards Waste Pactage Insp Rept 79-06A on 791126-28.No noncompliance noted BUTHERLAND, J T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/12/31 2pp.
- ---8003240287 Waste Packaging Insp Rept 79-06A on 791126-28. No noncompliance noted Major areas inspected: shipping paper requirements. BOT placarding requirements, radiation levels, removable contamination & DOT marking POTTER. J. P. Region 2, Atlanta, Fuel Facility & Haterials Bafety Branch 79/12/12 7pp.

DOCKET 50-163 GENERAL ATOMIC COMPANY

- J. Insurance & indemnity information
- 8010280720 Requests Endorsement 109 to Policy NF-34.Endorsement 47 to Policy HF-39 & Amends 29.30.31 & 32 to Policy 8-9. DINITZ:1 Utility Finance Branch (formerly Antitrust & Indemnity) 80/09724 ip.
- 47 to MAELU Policy NG-59 CORREAC. Hersh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/10/22 3pp 8010280382 Forwards Endorsement 109 to ANI Policy NF-34 & Endorsement

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

- J. Insurance & indemnity information
- B010280680 Requests endorsements & copy of Amend 10 to Policy E-22 DINITZ. I. Utility Finance Branch (formerly Antitrust & Indomnity) B0/07/24. 19
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER
- F. Security, medical, emergency & fire protection plans
- B010060220 Application to renew License R-84 for 20 yrs TYLER,P.E Defense,Dept.of, Defense Nuclear Agency 80/10/03. 2pp.
- --8010050248 Emergency plan for AFRRI-TRIOA Reactor Dames & Moore 80/10/03 27pp.
- . Operating license stage documents & correspondence
- 010060220 Application to renew License R-84 for 20 yrs. TYLER.P.E. Defense Dept of, Defense Nuclear Agency. 80/10/03. 2pp.
- -8010060226 Forwards safety analysis of FBAR for AFRRI TRIDA facility. TYLER, P. E. Defense, Dept. of, Defense Nuclear Agency. 80/10/03 1p.

- --8010060228 "Bafety Analysis of Hazard Summary Rept. Chapter 6 to FSAR." * Dames & Moore 80/09/18 29pp
- --8010060233 "Reactor Operator Requalification Program "
 a Defense, Dept of, Defense Nuclear Agency 80/10/03 26pp
- --801006023B Amend 17 to facility Tech Specs * Defense, Dept of, Defense Nuclear Agency 80/01/03 61pp
- --8010060243 "EIA Data for AFRRI-TRIOA Reactor."

 * Defense: Dept of. Defense Nuclear Agency 80/10/03 10pp
- --8010060248 Emergency plan for AFRRI-TRIGA Reactor * Dames & Moore 80/10/03 27pp
- V Operator Examinations
- 8010060220 Application to renew License R-84 for 20 yrs
 TYLER,P E Defense,Dept of, Defense Nuclear Agency 80/10/03 2pp
- ---B010060233 "Reactor Operator Requalification Program
 * Defense, Dept of, Defense Nuclear Agency B0/10 BQ/10/03 24pp
- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1
- J Insurance & indemnity information
- 8010280292 Requests endorsements & copy of Amend 21 to Policy B-28 DINITZ. I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- B010240522 Responds to NRC B00924 ltr indicating that signed copy of Amend 21 to Indemnity Agreement B-2B was never received Amend 21 was signed by co-owners & forwarded to J Baltzman BRADLEY, E. J. Philadelphia Electric Co 80/10/09
- G. Inspection reports. IE Bulletins & correspondence
- 8010020203 Responds to IE Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys
 DALTROFF, S.L. Philadelphia Electric Co. 80/08/27 ip
- DUCKET 50-182 PURDUE UNIV. RESEARCH REACTOR F. Security, medical, emergency & fire protection plans
- 8010310269 Forwards changes to security plan Plan withheld (ref 100FR2, 790). STANSBERRY:E R Purdue Univ. 80/10/27 ip
- DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR R Pariodic operating reports & related correspondence
- 6010140217 Forwards "Bemiannual Operating Rept. Jan-June 1980 "CARTER.R 8 Commerce, Dept of, National Bureau of Standards 80/09/26. 1p
- --8010140220 "Bemiannual Operating Rept, Jan-June 1980 "
 GARTER, R 8 Commerce, Dept, of, National Bureau of Standards 80/09/26 5pp
- DOCKET 50-184 UNIV. OF MISSOURI RESEARCH REACTOR Q Inspection reports: IE Bulletins & correspondence
- 8010010390 Forwards IE Insp Repts 50-186/80-04 & 30-02278/80-02 on 800715-17 & notice of violation. DAVIS.A.B. Region 3. Chicago: Fuel Facility & Materials Bafety Branch 80/08/22 2pp
- --8010010594 Notice of violation from insg on 800715-17
 * Region 3, Chicago, Office of the Director 80/0 80/08/15. 2pp

- --B010010601 IE Insp Rept 50-186/80-04 & 30-02278/80-02 on 800715-17
 Noncompliance noted failure to inform technician of reactor
 startup & changed radiological conditions Failure to control
 access to high radiation in beam port E area
 FISHER.W L. Region 3. Chicago, Fuel Facility & Materials Safety
 Branch PAUL, R A. LOVENDALE.P C Region 3. Chicago, Office of
 the Director 80/08/15 12pp
- B Reportable occurrences: LERs & related correspondence
- 8010280378 Submits rept re 800922 semiannual compliance check on reactor coolant inlet high temp scram Unit 980A Meter relay control unit scram did not actuate in response to high temp signal Unit was replaced MCKIBBEN.J C . BRUGOER.R M Missouri, Univ of, Columbia 80/10/20 20a
- DOGKET 50-187 SPACE RADIATION RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8010310463 Informs NRC that License R-90 should not be on US list of IAEA eligible facilities Company does work which has direct natl security significance AVANT.D. Northrop Corp 80/10/23 Ip
- DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8010070333 Bubmits changes in procedures & facility for Oct 1979-Sept 1980 Includes tests & experiments conducted w/o prior NRC approval FAW.R E Kansas State Univ 80/10/02 2pp
- DOCKET 50-191 BABCOCK & WILCOX COMPANY CRITICAL FACILITY
 J. Insurance & Indemnity Information
- 801028026B Requests endorsements & copy of Amend 20 to Policy B-B. DINITZ. I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- 8010040282 Forwards executed Amend 20 to Indemnity Agreement B-8, modifying prefatory language of Paragraph 5.Article I retransportation.

 OLSEN.A F Babcock & Wilcox Co. 80/10/01 2pp,
- DOCKET 50-172 UNIV, OF TEXAS RESEARCH REACTUR
 P. Operating license stage documents & correspondence
- 8010210496 Forwards revised Tech Bpecs for TRIOA Mark I.Current & expected staff funding revisions encl.
 BAUER:T L. Texas: Univ of 80/10/15 3pp.
- --8010210499 Revised Tech Specs for TRIGA Mark I at Univ of Texas. * Texas, Univ of 80/07/31 40pp.
- DOCKET 50-193 RHODE 18LAND & PROVIDENCE PLANTATIONS AEC
 J. Insurance & indemnity information
- 8010280694 Requests endorsement & copy of Amend 10 to Policy E-43 DINITY, I Utility Finance Branch (formerly Antitrust & Indemnity), 80/09/24. 1p.
- 8010240528 Notifies that Amend 10 to Indemnity Agreement E-43 was mailed to NRC on 771024.in response to NRC 800724 ltr.
 DIMEGLIO.A.F Rhode Island, State of, 80/10/06 ip
- --8010240532 Executed Amend 10 to Indemnity Agreement E-43, modifying prefatory language of Paragraph 4, Article 1
 BALTZMAN, J. Antitrust & Indemnity Group * Rhode Island, State of. 79710/24. ip.

- DOCKET 50-200 B&W TEST REACTOR

 J Insurance & indemnity information
- 8010280268 Requests endorsements & copy of Amend 20 to Policy 8-8 DINITZ,I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 1p
- 8010060282 Forwards executed Amend 20 to Indemnity Agreement 8-8, modifying prefatory language of Paragraph 5,Article I retransportation OLSEN,A F Babtoock & Wilcox Co 80/10/01 2pp
- DOCKET 50-201 WEBT VALLEY REPROCESSING PLANT

 F Security, medical, emergency & fire protection plans
- 8010130601 Responds to NRC 800715 itr re vulnerability assessment rept, Mar 1780 Recommendations per 800528 meeting can be implemented by 800930 Forwards outline of initiated & contemplated measures Encl withheld (ref 10CFR2, 790) DUCKWORTH, J.P. Nuclear Fuel Services, Inc., West Valley Reprocessing Plant 80/08/18 ip
- Q Adjudicatory correspondence
- 8010010930 Comments on proposed rule RM 50-8 re NRC termination of efforts on GEBMO fuels NRC should resume GEBMO proceeding. Certificate of 8vc & svc list encl DECHERIO Affiliation Unknoun. 80/09/03 7pp
- B0102302B1 Comments by TN Technological Univ on rulemaking 50-5 GESMO proceedings should be restarted immediately DEMAS.N G Affiliation Unknown 80/09/11 lp.
- 8010230349 Comments on rulemaking 50-8 supports radpening of GESMO proceedings.
 LDRFING.D. Addition Unknown 80/07/11 ip
- 8010220540 Comments on rulemaking 50-5 NRC should not reopen QEGMD or other nuclear recycle-related licensing proceedings. Opposes action which would be contrary to US nonproliferation policy MCLAUGHLIN, W T Affiliation Unknown 80/09/12 ip
- B010230265 Comments on rulemaking 50-8 GEBMO proceedings should be resumed. HACHNEY, C. A. Affiliation Unknown B0/09/12 1p
- 8010230341 Comments on rulemeting 50-5 OESMO proceedings should be reopened LOPEZ.C.R Affiliation Unknown 80/09/12 1p
- 8010020699 Recommends GESMO proceedings be completed Tachnically competent people available to complete OESMO project. Further delay in proceedings will increase energy costs GESMO will provide basis for future decisons re spent nuclear fuel MURRAY. H Affiliation Unknown 80/09/13, 1p
- 8010230328 Comments on rulemaking 50-5 GEBM9 hearings should not be reopened duy to problems w/reprocessing. Health hazards associated w/transport & reprocessing shown to be more serious than previous expectations
 CLEMENTS.T Affiliation Unknown 80/09/13 ip.
- 801022051B Comments on rulemaking 80-5 CEBMO hearings should resume immediately.

 BARRY, D. Affiliation Unknown 80/09/14. ip.
- BO10230317 Comments on rulemaking 50-5; GEBMO proceedings should not be reopened.

 TUCKER, C. A. Affiliation Unknown 80/09/14 ip
- 8010230323 Comments on rulemaking 50-5 re resuming GEBMD proceedings. CHUBB.W. Affiliation Unknown 80/09/14. 3pp
- 8010230231 Comments on rulemaking 50-5:9E8MO proceedings should be resumed Delays will not serve nath security & will increase cost of energy COURTNEY, J C Affiliation Unknown 80/09/15, ip.
- 8010230247 Comments on rulemaking 50-5. Commission should reopen QEBMO grocesdings.

 BARRY.J E Affiliation Unknown 80/09/15. 1p.

- BO10230291 Comments on rolemaking 50-5. GESMO hearings should be reopened.
 JONES, W. Affiliation Unknown 80/09/15 ip
- 8010220529 Comments on rulemaking 50-5 supports resumption of QESMO proceedings. CREINZEUSKI, P. Affiliation Unknown. 80/09/16. 1p.
- 8010220663 Comments on rulemaking 50-5.0EBMO proceedings should be respensed Draft article encl which should have some input in forming policy on recycling Pu., DEYA.R. Gitizans United for Responsible Energy. 80/09/17. 9pp.
- 8010230304 Comments on rulemaking 50-5 OEBHO proceedings should be resumed. US should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent fuel. PANZANI,F A Affiliation Unknown. 80/09/17. 1p
- 8010020019 Comments on reopening of OESMO proceedings re Rulemaking 30-5, reopening & successful completion of hearing is logical precedent to commercial reprocessing of spent nuclear fuel. Q1886.D.C. Affiliation Unknown 80/09/23. 2pp.
- 8010020690 Recommends resumption of GESMO proceedings. Persian Oulf area warfare necessitates technical devalopment of spent reactor fuels to lessem dependence on laparted oil MARMICK.E.F. Affiliation Unknown. 80/09/23. 1p
- 8010020012 Comments by two citizens in support of reopening of OEBHO proceedings re Rulawaking 50-5 further consideration meeded for energy development RECITHAYER.F., KIRTLEY.J Affiliation Unknown. 80/09/24. 2pp.
- 8010020682 Forwards constituent comments on QEBMO proceedings, Requests status of NRC intentions on proceedings. HOORE, N. H. House of Rep., Hays and Means. 80/09/24. 3pp.
- B010020005 Comments on reopening of OREMO proceedings to Rulemaking 50-5:continuation of review process needed to determine whether reprocessing & recycling is viable option. DRAPER, E. L. Ouif States Utilities Co. B0/09/28. 2pp.
- 8010020081 Comments on reopening of CERMO processings re Rulemaking UC-5:hearing must be reopened promptly due to need for establishing legal to logical basis for evaluation of spent fuel reprocessing.

 BEHNKE, W. B. Commonwealth Editon Co. 80/09/25. 2pp.
- 8010020007 Comments on responing of QESMO proceedings to Rulemaking 50-5: no further action needed due to completion of evidence. THOMAS.R. Environmentalists: Inc. 80/09/26 ip.
- 8010030484 Recommends requesting of GESMO proceedings CHAMPAGNE, A. J. Affiliation Unknown, 80/09/26, 1
- 8010010687 Order denying Ailied General Nuclear Sycs 900926 request for 60-day extension to respond to Commission 800807 order. Untimely comments will be considered only to extent positive CHILK, B. J. Office of the Becretary of the Commission. BO/09/29.
- 8010020001 Forwards comments on reopening of 088HD proceedings re Rulemaking 30-5: reinstitution of hearing reflects UB interest in energy need & will establish framework for timely decisions on reprocessing & recycling. NALBKE.C. Atomic Industrial Forum 80/09/29. 3pp.
- 8010020451 Comments on rulemaking 80-5 on behalf of 9ESMO Util Group: 9ESMO proceeding should be reactivated. IRWIN.D.F. Hunton & Milliams. 80/09/27. App.
- 9010020463 Comments on rulemaking 50-5:958MO proceeding should be rescheduled.

 SURT: D. M. Capital Legal Foundation. FIELD, H.P. Affiliation
 Unitnown. TODOROVICH. M. M. Scientists & Engineers for Secure Energy.

 80/09/29. 2pp.
- 8010020470 Forwards comments on behalf of NRDG on rulemaking 50-5: QEBHO proceedings should not be reopened.
 WEISSER, Natural Resources Defense Council. HEISSER, R. Sheldon, Harmon & Heiss 80/09/29. Spp.
- 8010030477 Views of Westinghouse on NRC 800807 order re resumption of OEMO & other recycle-related licensing proceedings. Resumption recommended, Certificate of Svc encl. COMAN, S.I. KENRICK, J. R., CAMPBELL, V. H. Westinghouse Electric Corp. 80/09/29. 1388.

- 8010020673 Recommends that NRC reopen GEBMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced.

 OLBOY, R. & Affiliation Unknown 80/09/30 ip
- B010030471 Responds to Commission B00807 order requesting comments on reopening of QEBMO & other recycle-related licensing proceedings Proceedings should be reactivated & consistent position on use of energy initiated KEARNEY.J.J Edison Electric Institute 80/09/30 3pp
- 8010160695 Supports resumption of OEGMO proceeding as prelude to closure of nuclear fuel cycle
 MDDDY, J. H. Yankee Atomic Electric Co. 80/10/08 2pp
- B010270506 Responds to 800924 ltr transmitting J Courtney request for NRC resumption of OESMO proceedings. J Courtney comments will be incorporated into public record to be considered by NRC KAMMERER. C. Office of Congressional Affairs 80/10/08 ip.
- 8010130364 Submits comments on resumption of GEBMO rulemaking on behalf of AZ Public Byc Co. CP&L. Con Ed & HI Electric Power Co.
 Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues GALLO. J Isham, Lincoln & Reale 80/10/10 Spp.
- 8010200395 Advises of address change from Culumbia, 8C to Washington, DC & requests records be changed.

 RELSER.T.M. Belser, Belser, & Baker 80/10/13 ip.
- 8010220494 Forwards JC Courtney 800916 ltr requesting that GEBMO hearings be resumed LONG, R. Senate, 80/10/13, 2pp
- H General correspondence
- E010090469 Requests listed documents re fuel storage at facility CLAUSON: M. K. Affiliation Unknown 80/07/31, 1p.
- B010100120 Responds to B00731 request for documents re NRC sponsored analyses of effects of severe sarthquake on fuel receipt & storage pool. Interim safety evaluation of Aug 1977 is still most recent version. Previous ltr 4td 790720 encl. HAUGHKEY, C J Advanced Fuel & Spent Fuel Licensing Branch B0/09/08 2pp
- --80(0100123 Responds to 790709 ltr requesting info re facility, Proposed rule 100FR72, 30, NRC interim safety evaluation of Aug 1977 & consultant repts re earthquake effects on facility encl. M/o encls HA00HNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 79/07/20. 1p.
- BOIO150088 Responds to BO0731 & 0715 requests for info re facility. Forwards interim safety evaluation for facility & repts on effects of earthquake on fuel receipt & storage pool at facility U/o encis.

 HAUGHKEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch BO/07/22, ip
- 8010310521 Forwards repts re NRC ongoing safety assessments of shutdown nuclear fuel reprocessing facility in West Valley, NY, H/o encl.
 HAUSHNEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch.
 B0/09/23 3pp.
- J. Insurance & indemnity information
- 6010070674 Notification of 600828 meeting w/NF8 & NY State Energy R&D Authority to discuss indemnification & liability issues Authority to discuse indemnification & liability issues associated w/facility.

 HAUGHNEY.C. J. Advanced Fuel & Spant Fuel Licensing Branch.

 BO/08/19. 2pp.
- P. Operating license stage documents & correspondence
- BO10090474 Provides info me current status of facility, in response to NRC B00605 ltm.Lease w/NY Btate Energy RkD Authority will expire B01231, Possible replacement operator has not yet been named. Complete resolution depends on pending legislation. DEUSTER.R.W. Nuclear Fuel Bervices, Inc. (subs. of Getty Dil Co.), 80/07/03. ip.
- 8010090483 Discusses MJ Direks 800626 ltr re insp & evaluation of NFS high level liquid waste storage sys by NRC contractor Rockwell Hanford. NFS is gasperdixing solidification program by requiring signing of indemnification agreements. HAMILTON, M. P. REENIKOFF, M. Sierra Club. 80/07/23. ip.

- 8010070644 Requeste indefinite suspension of additions of water to 8D2 pan pending insp of high level waste storage sys by Rockwell Hanford Operations
 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/08/19
- 8010080649 Bummary of 800813 meeting w/NF8, NY State Energy R&D Authority & util in Silver Spring, MD re progress of NF8 efforts to process technical decontamination & decommissioning data Next meeting scheduled for 801015 HAUGHNEY, C J Advanced Fuel & Spent Fuel Licensing Branch 80/0817 19pe
- 8010070076 Notification of B01015 meeting w/NY State Energy R&D Authority & NFS in Silver Spring.MD to discuss NFS efforts to process available technical into forming basis for future decontamination & decommissioning of facility. HAUGHNEY, C J. Advanced Fuel & Spent Fuel Licensing Branch. 80/08/19 2pp
- 8010080659 Summary of 800724 meeting w/NY State Energy R&D Authority, NFS, DGE & Rockwell Hanford Operation in Silver Spring, MD reindemnification & Liability issues associated w/contractor work implementation Next meeting scheduled for 800828 TINO.W W Advanced Fuel & Spent Fuel Licensing Branch. 80/08/22, 350
- 8010220093 Ack receipt of June & Jul monthly repts.Commends progress in fabricating & testing photographic inspectionent Supports recommendations addressed in 800825 ltr refield work scheduling.

 HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80709717.
- 8010070264 Comments on rulemaking 50-5 re reopening of OESMO & recycle related proceedings Reopening record will resolve economic, environ & resource questions re fuel reprocessing.

 DISE, D.P. Niagara Mohawk Power Corp. 80/09/26 1p.
- @ Inspection reports, IE Bulletins & correspondence
- B010020274 Responds to IE Bulletin B0-15 re emergency notification sys power Emergency notification sys powered by offsite power from Iroquois Talaphone Co. BUCKMORTH.J.P. Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.), B0/08/26 2pp.
- R Periodic operating reports & related correspondence
- 8010160369 Forwards "Environ Rept Number 28, Jan-June 1980."

 DUCKNORTH.J.P Nuclear Fuel Bervices, Inc. (subs of Oetty Dil Co.).

 80/08/29, 1p.
- --8010160378 "Environ Rept Number 28.Jan-June 1980."
 WILCOX,D P., 8MOKOWSKI.R.T. Nuclear Fuel Services, Inc. (subs. of / Oetty 011 Co.). 80/08/29. 24pp.
- 8010160362 Forwards Aug 1980 discharge monitoring rept for Permit NY0000973 DUCKMORTH, J. P. Nuclear Fuel Services, Inc. (subs. of Ostty Gil Co.). 80/09/03. App
- 8. Reportable occurrences, LERs & related correspondence
- 8010160357 PNO-I-80-144.on 801003.lightning damaged measuring & recording equipment in onsite meteorological tower.Lightning also disrupted equipment associated w/plant security & telephone sus RDTH.J., GROCKER.H.H., SMITH.Q H Region i, Philadelphia, Office of the Director. 80/10/06. ip.
- DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8008150360 Forwards "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Plume Exposure Pathway Emergency Planning Zone."

 BASKIN.K.P Southern California Edison Co. 80/08/01. ip.
- --8008150368 "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Plume Exposure Pathway Emergency Planning Zone."

 # Hilbur Smith & Associates. 80/08/31. 94pp.

- B010010522 Forwards response to comments & recommendations re BNL review of fire protection program Response includes new design change commitments Oversize drawings, hydraulic design info & calculation sheets available in Central Files, BABKIN-K.P. Southern California Edison Co B0/09/24 19pp.
- O Adjudicatory correspondence
- 8010310278 Forwards revised order correcting 800827 order for mod of DL which contained inaccurate refs Date of hearing accordingly revised EISENHUT.D 9. Division of Licensing 80/09/19 3pp.
- --8010310304 Order for mod of License DPR-13, correcting 800827 order which contained inaccurate refs Response to NRC 800304 & 28 ltrs shall be filed by 801101 Request for hearing will not stay affectiveness UCS petition discharged EISENHUT, D 0. Division of Licensing. 80/09/17 4pp.
- H General correspondence
- 8010140407 Forwards B Feldman 800905 ltr re insurance & limbility from possible facility damage.

 BADMAM:R.E House of Rep. 80/09/29 2pp.
- B01027003B Responds to B00214 ltr to President Carter re ability of facilities to withstand earthquakes & effect of low level radiation ASLB plans to reopen Ben Onotre hearing record re seismic adequacy in first quarter of 1981
 MIRAGLIA,F.J. Licensing Branch 3 80/10/16 3pp
- J. Insurance & indemnity information
- 8010280277 Requests Endorsements 71.72.73 & 74 to Policy NF-146 & Endorsements 62.63 & 65 to Policy NF-38. DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24. ip
- P Operating license stage documents & correspondence
- 8010160003 Requests revision to shipping routs from facility to GE storage facility at Morrie. IL.

 8EAMAN.W.H. Southern California Edison Co. 80/08/07. 2pp.
- 8010080310 Notification of contract execution: "Followon Bimulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station," awarded to K Aki
 LITTLE.M. Administrative Contracts Branch. FIN B-6898-0 80/08/22.
- ---8010080315 Contract: "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station," awarded to K Aki.
 AKI.K. Hassachusetts Institute of Technology PERLMAN, J. Administrative Contracts Branch. FIN 8-4898-0. 80/08/22. 3pp
- 8010270390 Bummary of 800815 meeting w/util & BNL in Betheeda. MD restatus & results of steam generator insp & repair program Viewgraphs encl.
 NONICKI.S.J. Operating Reactors Branch 5. 80/09/11. 6pp.
- 8010240049 Approves util 800807 proposed route change. Forwards food & fuel stops & strip map W/o encl.

 MCCORKLE, Q. H. Physical Security Licensing Branch. 80/09/12. ip.
- BOIO100117 Forwards request for add1 info on BEP Topics VI-7.8, engineered safety feature switchover from injection to recirculation mode.VI-7/C ECCB single failure criteria, VI-10.4, VI-10.8, VII-9.0, VII-9.8, CRUTCHFIELD.D Operating Reactors Branch 5. 80/09/16. 3pp.
- 8010220099 Forwards errata sheets amending 800905 1tr which provided prailminery clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D O Division of Licensing. 80/09/19, 28pp.
- B010280043 Summary of 800903 meeting w/util & BNL in Bethesda, MD restatus of steem generator repairs. NDMICKI, B. J. Operating Reactors Branch 5, 80/09/22. 4pp.
- B010300154 Summary of B00731 meeting w/util in Bethesda, MD re elseving design concept for steam generator tube repair & plans to deconteminate generator bowl prior to sleeving.

 NOWICKI, B. J. Operating Reactors Branch 5. B0/09/22. 42pp.

- 8010150330 Summary of 800904 meeting w/utils,8&W & NUS Corp re proposed upgrade mods to auxiliary feedwater sys Agenda & 800808 memo
 - VISBING: 0 B Operating Reactors Branch 4 80/09/30 48pp
- --80:0:50544 Submits analysis & recommendations re plants w/o smismically qualified auxiliary feedwater sys Seismically induced core melt due to loss of decay heat removal could be as much as six bimes more likely than WASH-1400 estimates. 80/08/08 22pp. Division of Safety Technology
- 8010070277 Forwards Drawing 235234-0. "Control Logic Diagram Containment Isolation Valves FOV-9 & 10 " Diagram indicates that recently installed containment isolation valve override switches do not override containment high radiation signal. BASKIN,K P Southern California Edison Co 80/10/02 2pp
- --8010070278 "Control Logic Diagram Containment Isolation Valves FOV-9 & POV-10," * Bauthern California Edison Co 80/04/29 ip
- 8010070462 Notifies that evaluation of postulated water hammers will be completed by 801030 due to delay in receipt of info from Hestinghouse Southern California Edison Co 80/10/02 1p.
- 8010210293 Immediate action itr confirming 801001 telcon re Model NFS-4, Cask is presently closed in manner to prevent release of radioactive matl Removal from restricted area must have prior NRC approval. ENGELKEN, R. H. Regi
- 8010140135 Notification of 801010 meeting w/util & Westinghouse in Pittsburgh, PA re proprietary steam generator repair program Por facility.
 NOWICKI.B J Operating Reactors Branch 5 80/10/06 29p.
- 8010140326 Notifies that date for submittal of info re analyses of main steam line or feedwater line break assuming early initiation of auxiliary feedwater flow has been rescheduled for 801201 Ltr vs TMI Lessons Esarned requirement mode encl BASKIN.K P. Southern California Edison Co. 80/10/05 4pp
- 8010150284 Responds to NRC 800611 ltr requesting Tech Spec changes re redundency in decay hest removal Facility does not have STS Operating modes will be redefined to conform more closely to STS Response will be delayed until 801114.

 BASKIN.K P Southern California Edison Go 80/10/06 2pp
- 8010310558 Accepts util commitments to 791023, "Interim Position on Containment Furging & Venting Pending Resolution of Isolation Valve Operability " CRUTCHFIELD,D. Operating Reactore Branch 5 80/10/08 2pp.
- 80:01:30:372 Notifies that date for submittal of info re design details for reactor coolent vents & addl info for main steam line piping integrity evaluation will be submitted 80:10: & 120:respectively BASKIN-K P Southern California Edison Co 80/10/09 ip
- 8010210331 Forwards application for Amend 93 of License DPR-13, consisting of Proposed Change 94 to revise App B ETB by deleting limiting conditions for operation & related environ programs & adding ref to NPDES permit.Class III fee encl. DIETCH.R. Southern California Edison Go. 80/10/15 2pp.
- --8010210337 Application for Amend 93 of License DPR-13, consisting of Proposed Change 94 to revise App B.EY8 by deleting limiting conditions for operation k related environ programs & adding ref to NPDEB permit & revising administrative controls.

 DIETCH,R. Southern California Edison Co. 80/10/06 6pp
- --8010210343 Proposed changes to App B ETS deleting limiting conditions for operation & related environ programs & adding NPDES parmit & revising administrative controls State permit & Certificate of Svc ancl.
 * Southern California Edison Co. 80/10/15. 56pp.
- BOIO240491 Responds to MRC BOIOOB request for addl info re evaluation of flooding from failure of nonsefety-related piping & equipment. Info & drawing encl.

 BABKIN K P Bouthern California Edison Co. BO/10/15 Opp.
- 8010200354 Forwards design details for automated auxiliary feedwater sys k RCS to be installed per TMI Lessons Learned requirements. Info provided supersedes info in 800610 ltr. Drawings in Contral Files Aperture cards in PDR.
 8ASKIN:K.P., Southern Callfornia Edison Co. 80/10/16 8pp.

- 8010280047 Notification of 801023 & 24 meeting w/util in Forest Hills, PA to discuss Hestinghouse proprietary steam generator repair program NDHICKI/S J Operating Reactors Branch 5 80/10/20 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8010080283 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power " Power for emergency notification sys changed to existing battery/inverter circuit for station internal telephone sys OTTOSON, H L Southern California Edison Co 80/08/28 3pp
- 8010170438 Forwards IE 1msp Rept 50-206/80-24 on 800804-08 No onercompliance noted, CREWS, J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/02 2pp.
- --8010170466 IE Insp Rept 80-206/80-24 on 800804-08 No noncompliance noted Major areas inspected; fire protection mods, IE builetin/circular followup & independent insp effort HORN, A J Region 5, San Francisco, Office of the Director. FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/02 Spp
- 8010080274 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Switches " Total of 11 Mestinghouse Type M-2 control switches w/spring return to neutral used in safety-related applications HAYNES, J Q Southern California Edison Co 80/09/05 3pp
- 8010300692 Submits results of concrete expansion anchor testing & insp program re IE Bulletin 79-02 Five of six failed anchors located on one piping support involving feedwater line inside containment. Bouthern Catifornia Edison Co 80/09/05 4pp.
- 8010290402 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required ENGELKEN,R H Region 3, San Francisco, Office of the Director. 80/09/10 1p
- 8010270390 Summary of BOOBIS meeting w/util & BNL in Bethesda, HD restatus & results of steem generator insp & repair program.
 Visugraphs encl
 NONICKI.B J Operating Reactors Branch 5 80/09/11 App.
- 8010270370 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Calculations & equipment mods do not apply to facility HAYNES.J O Southern California Edison Co 80/09/18 2pp.
- 8010080183 Ack receipt of 800923 itr informing NRC of steps taken to correct violations noted in IE Insp Rapt 50-206/80-17. ENGELKEN, R H Region 5. San Francisco. Office of the Director. 80/09/23. 1p.
- --8010080189 Responds to NRC 800815 ltr re violations noted in IE Imap Rept 50-206/80-17 Corrective actions:appropriate labeling was applied to each drum or container of radwasts. PAPAY.L.T Bouthern California Edison Co 80/09/08 2pp
- B0100B0076 Ack receipt of B00904 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-206/80-21. CREMB.J L. Region 3: San Francisco, Reactor Operations Nuclear Support Branch. B0/09/25. lp.
- ---BD10080107 Responds to NRC 800820 ltr re violations noted in IE Thea Rept 50-206/80-21 Corrective actions:control point manned by security officer established & entry-exit log maintained. PAPAY, J. L. Bouthern California Edison Co. 80/09/04. 4pp
- --8010080113 Forwards IE Insp Rept 50-206/80-21 on 800630-0724 & notice of violation.

 CREWS.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 80/08/20 2pp
- ---8010080120 Notice of violation from insp on 800630-0724. * Region 5, San Francisco, Office of the Director, E 2pp 80/08/15.
- ---8010080126 IE Insp Rept 50-206/80-21 on 800630-0724. Noncompliance noted failure to follow radiation exposure control procedure & failure to implement physical security plan requirement. HILLER, L. Region 5, San Francisco, Office of the Director, FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/08/15, 6pp.

43

ţ

- 8010270504 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/09/26 ip
- 8010280016 Forwards IE Insp Rept 50-206/80-29 on 800811-29 No noncompliance noted CREMS.J L. Region 5. Ban Francisco. Reactor Operations Nuclear Support Branch 80/09/24. 2pp
- --8010280019 IE Insp Rept 50-206/80-25 on 800011-29 No noncompliance noted Major areas inspected plant operations during long-term outage, monthly maint & surveillance observations & raview of LERs
 MILLER, L. Region B. San Francisco, Office of the Director FAULKENBERRY, B. Region B. San Francisco, Reactor Operations Nuclear Support Branch. 80/09/26 4pp
- 8010160051 Forwards Buppl 2 to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment." No written response required ENGELKEN.R.H Region 5, San Francisco, Office of the Director BO/09/29 1p
- 8010310385 Forwards IE Insp Rept 50-206/80-23 on 800818-22 No noncompliance noted ENGELKEN,R.H Region 5. San Francisco. Office of the Director. 80/09/20 2pp.
- --8010310389 IE Insp Rept 50-206/80-23 on 800818-22 No noncompliance noted Major areas inspected radiation protection planning & preparations associated w/impending steam generator repair activity
 CILLIB.M . CURTIS.R . YUMAS.O P. Region 5. San Francisco. Office of the Director. 80/09/29 9pp
- 8010210438 Ack receipt of 800924 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-206/80-22 on 800708-10 ENGELKEN,R H Region 5, San Francisco, Office of the Director. 80/10/02 ip
- --8010210442 Responds to NRC 800703 itr re violations noted in IE Insa Rept 50-204/80-22 on 800708-10. Corrective actions addit personnel assigned to dosimetry & recordkeeping to assure that badge data is promptly evaluated PAPAY, L.T. Southern California Edison Co 80/07/24 4pp
- --8010210444 Forwards IE Insp Rept 50-206/80-22 on 800708-10 & notice of violation ENGELKEN,R H Region 5, San Francisco, Office of the Director. 80/09/03, Spp.
- --8010210446 Notice of violation from insp on 800708-10.

 * Region 5, San Francisco, Office of the Director 80/08/20 20s.
- ---8010210449 IE Insp Rept 30-206/80-22 on 800708-10 Noncompliance noted, failure to perform adequate surveys as defined in 10CFR20 201(b) & personal exposure exceeded i, 800 millirem per quarter 8DDK,H E Region 5. 8an Francisco, Fuel Facility & Materials 8afety Branch CURTIS.J R , WENSLAMSKI,F A Region 5. 8an Francisco, Office of the Director 80/08/20. 9pp
- 8010280667 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required. ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/10/02 ip
- R Periodic operating reports & related correspondence
- 8010180277 Submits update of 800703 rept re personnel exposures for quarters ending 800630 & 0930.per 1007820 101 Eleven individuals exceeding exposure limits during second quarter & four during third quarter PAPAY.L T. Southern California Edison Co 80/10/01 2pp
- 8010150440 Forwards monthly operating rept for Sept 1980. CURRAN, J. M. Southern California Edison Co. 80/10/07. 1p
- --8010150454 Monthly operating rept for Bept 1980.
 JOY, J M Southern California Edison Co. 80/10/07. 5pp

- 8 Reportable occurrences, LERs & related correspondence
- 8010010637 Requests add1 into re 800310 failure of salt water cooling sys Basis for 200 F limit indicated for component cooling water sys needed Equipment design limitations should be explicitly referenced LAIMAS.G C Assistant Director for Bafety Assessment 80/08/27 3pp
- 8010100391 PNO-V-80-048 on 800903, licensee reported that certain combinations of safety injection signals & loss of offsite power signals will cause failure of circuits to sequentially load diesel generator ZMETZIO.0 B Region 5. San Francisco. Office of the Director 80/09703 ip
- B0100602B9 Forwards LER 80-034/03L-0
 HAYNES J 0 Boutharn California Edison Co 80/09/17 2pp
- --8010060297 LER 80-034/03L-0 on 800901 during steam generator tube removal unexpected water in secondary side intruded into RCS Caused by inadequate drainage between water source & generators Drain has been installed CURRAN J M Southern California Edison Co 80/09/17 ip
- 8010040348 RO Micro Switch Series 2 mfg by Honeywell caused grounding of circuits when replacing burned out indicating lights Personnel instructed re procedural steps which should be performed prior to lamp replacement C
- 8010060266 RD on 800922, while decontaminating steam generator channel heads; decontamination sys was shut down due to excess makeup in sys Examination of seal revealed 10-inch tear in rubber ballon resulting in seal failure. Cause under review CURRAN, J. H Bouthern California Edison Co 80/09/22 Zpp.
- B010100287 PNO-V-80-068A on B00923, testing of diesel generator load sequencer circuits has determined that previously reported problem does not exist. Testing found when safety injection signal is blocked.loads will not sequence for loss of power FAULKENBERRY.B . HORN.A. Region 5. San Francisco, Office of the Director 80/09/23 ip
- 8010090211 PNU-V-B0-069A on B00916, representative of Governor Brown ofc contacted Region 5 to discuss transient worker radiation exposure in steam generator repair. Governor ofc considers transient worker exposure as misuse of resources.
 WENSLAMEXI,F., B00K.H E Region 5, San Francisco, Office of the Director, B0/10/01, 2pp
- 8010210673 Forwards LER 80-036/03L-0 HAYNES, J Q Southern California Edison Co. 80/10/03 2pp
- --8010210685 LER 80-036/03L-0.on 800922, dilution of RCS occurred when containment integrity had not been established Caused by RCS loop seal feilure during steam generator channel head contamination, Loop seal replaced & requalified CURRAN, J.M. Bouthern California Edison Co. 80/10/03 ip
- 8010160788 PND-V-80-074 on 801008, samples collected in yard drain sump, normally nonradioactive sys, were found to contain I-131 activity. No other radionuclides were present. Licensee is investigating source of activity YUMAS, 9 Region 5, San Francisco, Office of the Director 10.
- 8010270378 Forwards LER 80-035/01T-0 HAYNES:J 0 Southern California Edison Co. 80/10/10 Spp
- --8010270379 LER 80-035/017-0. on 800918, after installation of containment isolation panels 13A & 13B, problem arose which could cause 'short circuit or inadvertent actuation of control circuit. Caused by poor switch design & improper application. HAYNEB, J Q. Southern California Edison Co. 80/10/10. 1p
- B01027053B PNO-V-B0-74A update of unmunitored potentially radioactive liquid waste release on B0100B, revealed most likely source of 1-121 activity was biological excrement from worker undergoing medical treatment.

 CILLIB, M. Region 5. San Francisco. Office of the Director B0/10/21, 1p
- V. Operator Examinations
- 8010210328 Provides plans, schedules & commitments to meet interim criteria for shift staffing & administrative controls, in response to NRC 800731 request. Full compliance u/criteria will be achieved no later than 820701.

 BASKIN, K. P. Bouthern California Edison Co. 80/10/15 Spp.

- DOCKET 50-208 COLUMBIA UNIV. RESEARCH REACTOR
- J Insurance & indemnity information
- 601028025; Requests endorsement & copy of Amend 1 & 2 to Policy E-60 DINITZ, I Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24 1p
- TRANSPORT SON TO THE PROPERTY OF THE PROPERTY
- 8010020251 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment Submittal of info required by 801101 GRUTCHFIELD. D Operating Reactors Branch 5 80/08/29.
- -- 9010020257 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment ELSENHUTLD 0 Division of Licensing 80/08/29 App
- --8010020263 Order for mod of license requiring timely submission of info proviously requested re environ qualification of safety-related electrical equipment. EIBCNNUT.D.O. Division of Licensing, 80/09/29. App
- P Operating license stage documents & correspondence
- 8010010961 Forwards SEP Topic VIII-2. "Oneite Energency Power Sys --Diesel Generator." Assessment companes facility w/NRC critaria for licensing new facilities CRUTCHFIELD.D. Operating Reactors Branch 5. 80/08/20. 2pp
- --801001011 SEP Topic VIII-2, "Onsite Energancy Power Sign Dissel Generator for Haddam Neck,"

 * Operating Reactors Branch 5 80/08/20, 10pp
- 8010090488 Forwards responses to 800623 lir concerning proposed design of post-accident sampling & analysis sys for facilities Requirement for obtaining pressurized samples can be deleted.
 CRUICHFIELD.D Operating Reactors Branch 5 80/09/17 6pp
- 8010220099 Forwards errata sheets amending 800905 itr which provided preliminary clarification of THE action plan requirements Corrected table of implementation schedule also encl.
 EISENHUT, D Q Division of Licensing 80/09/19, 28pp.
- 8010310119 Confirms previous telcons & expresses agreement w/plan to re-inspect low pressure turbine discs during 1991 refueling outage. NRC is continuing analysis of fabrication & operation data for Westinghouse turbines
 CRUTCHFIELD. D. Operating Reactors Branch 5. 80/09/25. 2pp.
- 8010060R38 Updates 800610 itr by submitting info re auxiliary feedwater pumps to satisfy NRC requirements. Pump room embient conditions did not exceed environ qualification limits for safety-related equipment. Test date encl.

 COUNSILLE O Connecticut Yankee Atomic Power Co. 80/09/29. 14pp.
- 8010070356 Application to amend OL Forwards revision to App B of ETS to delete Section 4.2 re shad monitoring program Also forwards "Population Dynamics of American Shad (Alosa Sapidissima) in CT River, 1940-1977. "
 COUNSIL-N. C Connecticut Yankes Atomic Power Co 80/09/29. 3pp.
- --801007057(Proposed revision to App B of ETB to delete Section 4, 2 re shad monitoring program # Connecticut Yankes Atomic Power Co 80/09/30. 8pp.
- --8010070578 "Population Dynamics of American Shad (Alosa Sapidissima) in CT River, 1940-1977 " GRECOV. Connecticut: State of, 78/12/31 225pp.
-)10180530 Summary of 800904 meeting w/utils.8&W & NUS Corp re proposed upgrade meds to auxiliary feedwater sys. Agenda & 800808 memo entl
 VISBING.0.8. Operating Reactors Branch 4 80/09/30. 48pp.
- 8010130544 Bubaits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys. Seismically induced core meit due to loss of decay heat removal could be as much as six times more likely than MABH-1400 setimates MATTBON.R. J. Division of Bafety Technology. 80/08/08. 22pp.

- 8010100324 Submits comments on TMI action plan requirements. NRC should accept alternative means of training for mitigating core damage Util will submit valve test data by 810701 & plant specific analyses following completion of program COUNSIL. W 0 · FEE, W F. Connecticut Yankee Atomic Power Co COUNSIL. W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/01 6pp
- 8010310189 Requests that listed BEP topics be added to NRC 791116 listing of topics to be deleted from review due to inapplicability to plant Revised listing of applicable PHR DBE accident & transient groups encl. CRUTCHFIELD.D Operating Reactors Branch 5 80/10/01 5pp
- 8010100222 Discusses position on asymmetric LOCA loads, in response to NRC 780202 ltr Reactor cavity seal will not be subjected to forces creating missile hazard for max pipe-break opening considered in WCAP-7558 % WCAP-7558, Revision 1 COUNBIL.N.O.: FEE.W.F Connecticut Yankee Atomic Power Co 80/10/03. 2pp
- 8010150488 Informs of error in NRC evaluation of SEP Topic VIII-2, forwarded in DM Crutchfield 800820 Itr Error involves calculations used in determining diesel generator loading re Reg Guide 1 9 diesel generator loading 1 imits CQUNSIL. N.O. Connecticut Yankee Atomic Power Co 80/10/03 2pp
- 8010200472 Provides info re environ qualification of electrical equipment as partial fulfillment of license amend issued on BO0919 Eummaries of methodology used, final radiation data & oversize drawings encl COUNSIL-W O. Connecticut Yankes Atomic Power Co COUNSIL.W.O Northeast Nuclear Energy Co (subs. of Northeast Utilities) BO/10/09. 40ap.
- --B010200482 "Heating Ventilation & Air Conditioning Turbine Bldg"
 Merzenine Floor Plan: " as-built
 # Ebasto Services: Inc. (subs of Enserch Corp), 6797
 77/02/28 in
- --B0102004B3 "Heating, Ventilation & Air Conditioning Turbine Bldg Ground Floor Plan," as-built # Ebasto Services, Inc. (subs of Enserch Corp.) 6797 76/07/15.
- --8010200488 "General Arrangement Emergency Gas Turbins Generator."
 as-built
 4 Ebasco Bervices, Inc. (subs. of Enserch Corp.) 6797
 68/11/26 in
- --8010200472 "Heating Ventilation & Air Conditioning Flow Diagram.Turbi Bldg:Control Room & Byc Area." as-built # Ebasco Services. Inc (subs. of Enserch Corp.) 6797 78/11/20 jp.
- --8010200494 "Intake Structure Screens & Miscellaneous Steel," as-built 4 Ebasco Services, Inc. (subs, of Enserch Corp.), 7043. 48/11/25 1p
- --B010200497 "Lighting One-Line & Cabinet Diagrams," as-built.

 * Ebasco Services, Inc. (subs of Enserch Corp.) 7043.
 79/11/30 ip.
- --8010200502 "4160 Volt & 480 Volt Switchgear, One-Line Diagram, "
 as-built, Sheet 2,
 # Ebasco Services, Inc. (subt, of Enserch Corp.) 79/10/15 ip.
- ---9010200507 "480 Volt Miscellaneous Auxiliary Motor Control Ctrs, One--Line Diagram, " as--built, # Ebasco Bervices, Inc. (subs, of Enserch Corp.) 7043,
- --8010200509 "480 Voit Turbine Bldg Motor Control Ctrs.One-Line Wiring." Diagram " Sheet 2.

 4 Ebasco Services, Inc. (subs. of Enserch Corp.), 7043.
 79/07/02. is.
- 8010170396 Submits info re basis for conclusion that continued safe operation of facility is justified until seismic re-evaluation program is completed & implemented. Generic conservatisms in original plant design support conclusion COUNSIL. If O., FEE, M. F. Connecticut Vankee Atomic Power Co. 80/10/14 3pp.
- 8010240247 Forwards proposed revisions to RTB re util 800716 ltr to NRC. Desired flexibility of operation can best be accomplished by mod of X/G's based on more recent metagrological modeling data & reg guides.

 CDUNSIL, H Q. Connecticut Yankee Atomic Power Co 80/10/14. 20p.

- --8010240250 Proposed revisions to ETS,Pages 2 4-5 & 2 4-9,modifying X/Gs for gaseous waste effluents Technical Justification encl * Connecticut Yankee Atomic Power Co 80/10/16 4pp
- B010300372 Application for amend to License DPR-61 assuring adequate heat removal capability in all operating modes & providing redundancy w/respect to single failure considerations Fee encl COUNBIL.N G Connecticut Yankes Atomic Power Co 80/10/16 3pp
- --8010300377 Proposed changes to Tech Specs 3 3 for RCS operational components to assure adequate heat removal capability in all operating modes & provide redundancy w/respect to single failure considerations

 * Connecticut Yankee Atomic Power Co 80/10/16 11pp
- B010300417 Responds to NRC 800930 ltr requesting util installation of override-to-close capability for block valves by B01030. Mod does not justify cost of shutdown for installation Buittches will be installed before startup from hert cold shutdown CCUNSIL. W O Connecticut Yankee Atomic Power Co 80/10/24 3pp
- @ Inspection reports, IE Bullatins & correspondence
- 8010020629 Forwards IE Insp Rept 50-213/80-06 on 800409-ii No noncompliance noted SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/29 2pp
- --8010020636 IE Insp Rept 50-213/80-06 on 800409-11 No noncompliance noted Major areas inspected radiation protection program re refueling outage activities SERABIAN, J A , BAER, R E , KNAPP, P J Region 1, Philadelphia, Office of the Director 80/07/23 9pp
- 8010030313 Responds to IE Bulletin 80-19. No mercury-wetted relays in use at facfilties COUNBIL,N 0 . LEE,N F. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/08/26 ip
- 8010030274 Responds to IE Bulletin 80-15 Existing emergency notification sys revised to incorporate directive requiring notification of NRC operational ctr when phone discovered inoperable COUNSIL.W. O Connecticut Yankee Atomic Power Co. 80/08/27. 2pp.
- 8010240161 Forwards IE Insp Rept 50-213/80-07 on 800428-29 & 0505-0607 & notice of violation BRUNNER, E. J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/02 2pp.
- --8010240147 Notice of violation from insp on 800428-29 & 0505-0607, * Region 1, Philadelphia, Office of the Director 80/08/27 1
- --8010240176 IE Insp Rept 50-213/80-07 on 800428-29 & 0505-0607
 Noncompliance noted, failure to adhers to Tech Spec limits re
 noble gas release rates.
 KEIMIO,R R Region i. Philadelphia, Reactor Operations Nuclear
 Support Branch SMITH, T. H , ZIMMERMAN, R. P. Region i.
 Philadelphia, Office of the Director 80/08/27, 6pp
- 8010240127 Forwards IE Insp Rept 50-213/80-13 on 800714-15.No noncompliance noted ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/05. 2pp
- --8010240136 IE Insp Rept 30-213/80-13 on 800714-15 No noncompliance noted Major areas inspected smergency planning areas addressed in immediate action letter IAL 80-20 BORES, R.J. TERC.N.M. Region 1, Philadelphia, Office of the Director 80/08/28 App
- 8010020735 Responds to IE Bulletin 80-05 Original tank vent modified to divert overflow to diked radioactive drain area. COUNBIL.N G Connecticut Yankee Atomic Power Co 80/09/12 2pp
- 8010020744 Responds to IE Bulletin 79-02 Analysis, testing & mods to Category I pipe supports using concrete expension enchor bolts complete COUNSIGN CONTROLLY O Connecticut Yankes Atomic Power Go 80/09/12 2pp
- B010220021 Responds to IE Bulletin 80-20. "Failures of Westinghouse Typs W-2 Spring Return to Neutral Control Switches "
 Specified switches are used in containment air circulation fans, svc water pumps & charging pumps
 COUNBIL.W 0 , FEE.W F Connecticut Yankee Atomic Power Co COUNBIL.W 0, Northeast Nuclear Energy Co (subs of Northeast Utilities), B0/09/13 2pp.

- 8010220699 Ack receipt of 800729 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/80-08 BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/09/19 2pp
- --8010220701 Responds to NRC 800626 ltr re violations noted in 1E Inap Rept 50-213/80-08 Corrective actions, more definitive QA matl, equipment & parts list being developed GOUNSIL.W G Connecticut Yankee Atomic Power Co
- --8010220703 Forwards IE Insp Rept 50-213/80-08 on 800421-25 & notice of violation BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch 80/06/26 2pp.
- --8010220704 Notice of violation from insp on 800421-25
 * Region 1, Philadelphia, Office of the Director 80/06/20 App
- --8010220707 IE Insp Rept 50-213/80-08 on 800421-25 Noncompliance noted.
 failure to establish procedures for annunciators, failure to
 perform post-maint insp & tests for safety-related maint
 & failure to maintain maint records
 OREENMAN.E O. Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch CHUNG.J., ELUMBERO, N. Region 1, Philadelphia,
 Office of the Director 80/04/20 19pp
- 8010270242 Responds to IE Bulletin BO-18, "Haint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Min flow requirements are met for high pressure safety injection pumps.

 COUNSIL, H O Connecticut Yankee Atomic Power Co COUNBIL, H O, Northeast Nuclear Energy Co (subs of Northeast Utilities).

 BO/09/22 2pp.
- 8010270432 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested ORIER, B H Region i. Philadelphia. Office of the Director 80/07/26 ip
- 8010300114 Forwards Suppl 2 to IE Builetin 79-018, "Environ Qualification of Class IE Equipment." No written response required ORIER, B H Region i, Philadelphia, Office of the Director. 80/09/30 ip
- 8010240118 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required CRIER,B H Region i, Philadelphia, Office of the Director. 80/10/02 1p.
- B010280241 Forwards IE Info Notice B0-36. "Failure of Steam Cenerator Support Bolting " No specific action or response requested.
 ORIER, B. H. Region 1. Philadelphia, Office of the Director 80/10/10 10
- R Periodic operating reports & related correspondence
- 80:0150347 Forwards monthly operating rept for Sept 1980 ORAVEB.R. H Connecticut Yankee Atomic Power Co 80/10/10. 1p.
- --8010150369 Monthly operating rept for Sept 1980
 * Connecticut Yankse Atomic Power Co. 80/10/10. 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010170005 PNG-I-80-136 on 800926, technician inadvertently opened vol control tank sampling valve causing release of gaseous effluent from stack Licensee estimates release was 338% of Tech Spec instantaneous release limit.

 WHITE.J. KNAPP.P., SMITH.G. Region 1: Philadelphia, Office of the Diractor. 80/09/26 ip.
- 801003046B RO-80-13/iP on 800726 while at full power chemistry technician mistakenly opened vol control tank gas space sample valve resulting in gas release. Release rate exceeded allowable rate limit. Technician cautioned.

 ORAVES, R H Connecticut Yankee Atomic Power Co. 80/09/27. ip
- 8010130445 RO 50-213/80-07. on 800926, while obtaining monthly sample, wrong valve was opened, allowing redicactive gas to escape from vol control tank in excess of Tech Bpecs. Caused by technician error Bampling procedures will be revised.

 ORAVES, R. H. Connecticut Yankee Atomic Power Co 80/10/08. Opp.

- B010140484 RO 50-213/B0-07 on B00926 unplanned radioactive gas release occurred. Caused by opening wrong valva during monthly sampling due to misreading of tags 9858 & 985A Disciplinary action talen Valves retagged Rept from B00926 is invalid. ORAVES, R K Connect(cut Yankee Atomic Power Co 80/10/08. 3pp
- 8010280455 Forwards LER 80-014/03L-0 GRAVES.R H Connecticut Yankes Atomic Fower Go. 80/10/24. ip.
- --B010280323 LER B0-014/03L-0 on B00926, during surveillance testing of diesel fire pump, pump discharge pressure at 2500 RPM found below Tack Spec limit Caused by low operating RPM of diesel actor Adjustments made to increase motor RPM.
 TRAPOSIGN P. CHUNIS, J.A. Connecticut Yankee Atomic Power Co. B0/10/24 1p
- 8010280458 Forwards LER 80-015/03L-0.
 ORAVES, R. R. Connecticut Yantes Atomic Power Co 80/10/24. 1s.
- --B010280528 LER 80-015/03L-0 on 801020, while boiling down agrated drains tank waste evaporator in preparation for drumming, level indication was lost Caused by failed gastet on discharge piping of reboiler pump Gastet replaced TRA0010.R P. CHUNIB.J A Connecticut Yankee Atomic Power Co. 80/10/24 ip

POCKET 50-219 GYSTER CREEK NUCLEAR POWER PLANT F. Sacurity, medical, emergency & fire protection plans

- 8010070014 Forwards Suppl 3 to 780303 fire protection safety evaluation Proposed revised schedule for inetallation of alternate water supply to yard loop is acceptable Plans for alternate shutdown capability should be submitted by 801101. EISENHUT, D Q Division of Licensing 80/09/25. 3pp.
- --B010090015 Suppl 3 to fire protection safety evaluation # Division of Licensing 80/08/25 Spp.
- 8010200475 Notifies of delay in installation of alternate water supply a repeater/base station communication sys. Caused by equipment delivery delays a personnel shortage. Installation will be completed by 810201 & 8101011/respectively.

 FINFROCK, I R Jersey Central Power & Light Co 80/10/15. 2pp.
- Q Adjudicatory correspondence
- 8010300146 Forwards revised order correcting 800829 order for mod of CL which contained inaccurate refs Date of hearing accordingly revised EISENAUT, D @ Division of Licensing, 80/09/19, 3pp.
- ---8010300154 Order for mod of OL DPR-16, correcting 800829 order which contained inaccurate refs Response to NRC 800306 & 28 liers shall be subsitted by 801101 Request for hearing will not stay effectivenes. USB settion discharged EISCN-NUT. D. Q. Division of Licensing. 80/09/19. App.
- B010170687 Forwards order confirming util commitments to implement action re IE Bulletin 80-17, BTELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02 is
- --8010170673 Order confirming util commitments to implement action re IE Bulletin 80-17. STELLD.V. Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp
- 8010100132 Order granting extension until 801020 for Commission to determine whether to review ALAB-612. CHILK-S.J Office of the Secretary of the Commission. 80/10/03. ip.
- 8010210522 Order greating extension until 801103 for Commission to elect whether to review ALAS-512, CHILK, S. J. Office of the Secretary of the Commission. 80/10/17.
- SO10310458 Forwards affidavit re unresolved generic safety issues; in response to ASLB 800709 order, Info will be incorporated in future safety evaluation.

 HODDHEAD, C. P. Hearing Branch i. S0/10/30. Ip.
- --B010310484 Affidavit re unresolved generic safety istues, in response to ABLB 80090% order. Facility can continue to operate prior to ultimate resolution of six identified issues w/o endangering PAULBON, M. A. . Jersey Central Power & Light Co. 80/10/28, 36pp.

- J Insurance & indemnity information
- 8010280301 Requests endormement & copy of Amend 59 to Policy NF-164 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity), 80/09/24, 1p.
- 8010220423 Forwards copies of endorsements.w/forwarding ltrs.per NRC request.Endorsements 59.67.68.69 & 70 to NELIA Policy NF-164 & Endorsements 53.54 & 55 to MAELU Policy MF-44 encl. MOREAU.W N Ceneral Public Utilities OPU Bervice Corp 80/10/13 is.
- --8010220425 Forwards Endorsement 59 to NELlA Policy NF-164 OCRETY,H.F. General Public Utilities - OPU Service Corp 77/11/08 2pp
- P. Operating license stage documents & correspondence
- B010140095 Forwards Amend 49 to License DPR-16, safety evaluation & notice of issuance & availability CRUTCHF[ELD.D Operating Reactors Branch 5 80/08/20 2pp.
- --8010140101 Amend 49 to License DPR-16, incorporating 10CFR50, App 1 design objectives for gaseous effluents, CRUTCHFIELD, D. Operating Reactors Branch 5. 80/08/20 15pp
- --8010140123 Safety evaluation supporting Amend 49 to License DPR-16.
 * Office of Nuclear Reactor Regulation, Director 80/08/20, 5pp.
- ---B010140127 Notice of issuance & availability of Amend 49 to License DR-16. CRUTCHFIELD.D. Operating Reactors Branch 5 80/08/RO. 2pp.
- 8010010035 Requests revision to util 800814 proposed Tech 8pecs to include provisions for plant maint support CRUTCHFIELD, D. Operating Reactors Branch 5 80/08/25 2pp
- 8010220154 Forwards request for addl info necessary to evaluate inservice testing program.
 CRUTCHFIELD.D Operating Reactors Branch 5, 80/09/03, 13pp.
- B010200360 Forwards Amend 50 to License DPR-16, safety evaluation & notice of issuance & availability CRUTCHFIELD, D Operating Reactors Branch 5 80/09/15 3pp.
- --8010200364 Amend 50 to License DPR-i6, changing Tech Space to reflect establishment of General Public Utils Nuclear Group, responsible for operation & mgt of plant, CRUTCHFIELD, D. Operating Reactors Branch 5. 80/09/15, 26pp.
- --8010200368 Safety evaluation supporting Amend 50 to License DPR-16.
- --8010200372 Notice of issuance & availability of Amend 50 to License DRA-16. CRUTCHFIELD:D. Operating Reactors Branch 5. 80/07/15. 2pp.
- 8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT, D. O Division of Licensing, 80/09/17, 28pp.
- 8010270220 Confirms mgt meeting on 800925 at facility to discuss NRC assessment of regulatory performance at facility. CRIER.8 H Region 1, Philadelphia, Office of the Director 80/09/22. 2pp.
- B010090496 Informs that response re possibility of motor generator sets producing power of quality unacceptable for reactor protection sys has been found unacceptable Power supply should be modified. Reply requested, CRUICHFIELD.D. Operating Reactors Branch 5. 80/09/24, 3pp.
- 8010310532 Forwards Revision 1 of "SEP Review of Bafe Bhutdown Bys far Oyster Creek Nuclear Power Plant," including BEP Topics V-10.B, V-11.A, V-11.B, V11-3 to IX-3. Requests advisement if as-built conditions of facility differ. CRUTCHFIELD, D. Operating Reactors Branch 5, 80/09/25, 65pp.
- 8010090415 Forwards responses to NRC 800710 ltr requesting addl infe pp 8EP Topic III-5. R. pipe breaks outside containment. FINFROCK: I.R. Jersey Central Power & Light Co. 80/10/06. 46pp.

- BO10140244 Application for amend to provisional License DPR-16.App A, changing Tech Spacs re iodine removal efficiency & air filter flow distribution testing Certificate of Bvc encl FINFROCK, I R Jersey Central Power & Light Co B0/10/06 9pp.
- B010140252 Forwards technical summary rept, "Reactor Containment Bldg Integrated Leak Rate Test" FINRROCK,I R Jersey Central Power & Light Co 80/10/07 ip
- --B010140255 "Reactor Containment Bldg Integrated Leak Rate Test "CARROLL, J. T. Jersey Central Power & Light Co. B0/06/30, 52pp
- 8010220291 Notification of B01009 meeting w/util & Franklin Research Inst in Morristown.NJ to discuss licensee program on environ qualification of electrical equipment PAULBON.H. Operating Reactors Branch 5 80/10/08, 2pp.
- B01022042B Notification of B01009 meeting w/util in Morristown, NJ to discuss licensee program on environ qualification of electrical equipment PAULBON.W. Operating Reactors Branch 5. 80/10/08. 3pp
- B0102B0726 F0IA request for documents re evaluation or adequacy of Exxon critical heat flux correlation data concerning facility for 1973-1976 FIDELLIE, R. LeBoeuf, Lamb, Leiby & MacRae, 80/10/08 2pp.
- 8010230322 Summary of 800707 meeting w/util in Bethesda, MD re pipe break outside of containment. PAULSON.H.A. Office of Nuclear Reactor Regulation, Director 80/10/14 13pp
- 8010220388 Application for amend to License DPR-16 consisting of Revision 5 to Tech Spec Change Request 28, BALDASBARI.D. Jersey Central Power & Light Co 80/10/17. 5pp.
- ---8010220387 Tech Spec 4 3 for inservice insp of reactor coclant sys. 4 Jersey Central Power & Light Co. 80/10/17, 3pp.
- 8010280723 Responds to FOIA request for documents re evaluation or adequacy of Exxon critical heat flux correlation data concerning facility for 1973-1976, Forwards documents listed in App A. FELTON. J. M. Division of Rules and Records. 80/10/23 2pp.
- --8010280727 Safety evaluation supporting Amend 9 to License DPR-16 re Change 23 to Tech Spacs. * Office of Nuclear Reactor Regulation: Director. 75/05/24 13pc.
- --801028073; Forwards request for add1 info to complete review of Amend 76 to facility description & safety analysis rept concerning Core Cycle 5 fuel reload. Requests response by 750411. LEAR, O Uperating Reactors Branch 3 (Pre 791030). 75/04/02. 10pp.
- --8010280794 Lists supplemental questions which should be forwarded to util re Core Cycle 5 fuel reload.
 STELLO,V. Office of Nuclear Reactor Regulation, Director, 75/04/21, ip.
- --8010280736 Forwards request for add1 info for review & preparation of safety evaluation re Amend 76 re transient analysis of Core Gycle 5 fuel reload.

 STELLO,V Office of Nuclear Reactor Regulation, Director 78/04/21. 3pp.
- --B010280737 Forwards request for add1 info to continue review of Core Cycle 5 fuel reload, Requests response by 750424. LEAR, 0 Operating Reactors Branch 3 (Pre 791030). 75/04/21 Bpp.
- --8010280740 Discusses facility heat flux correlation data Correlation nonconservatively predicts heat flux, BN-1 correlation is not acceptable. Authorization to operate facility cannot be granted.
 PAULSGN: W. A. Operating Reactors Branch 3 (Pre 790625) 75/06/03. 2pp.
- --8010280742 Summary of 750505 meeting w/General Public Utils Svc Corp. Nuclear Svcs Corp & Exxon Nuclear Co in Bethesda.MD to discuss critical heat flux correlation. List of attendess encl.
 PAULSON, W. A. Operating Reactors Branch 3 (Pre 790425) 75/06/03. 300.

- --BOIOZBO745 Bummary of 75050B meeting w/General Public Utils Svc Corp & Exxon Nuclear Corp in Bethesda, MD to discuss NRC concerns recritical heat flux correlation, List of attendess encl PAULBON, W. A Operating Reactors Branch 3 (Pre 770625) 75/06/03. Sac
- --8010280748 Bummary of 750515 meeting w/util & Oeneral Public Utils Svcs Corp in Bethesda, MD to discuss util 750514 submittal proposing establishing ain critical power ratio thermal limit criteria for facility Gycle 5. List of attendees encl. PAULSON, W A. Operating Reactors Branch 3 (Pre 790625) 75/06/03 Spp
- --8010280750 Bummary of 750520 meeting w/util, General Public Utils Byc Corp & Pickard Loue Associates in Bethesda, MD to resolve differences between critical heat flux values calculated by NRC & by General Public Utils Byc Corp. W/list of attendees, PAULBON; N.A. Operating Reactors Branch 3 (Pre 790625) 75/06/05, 20p.
- 8010310574 Responds to 800925 ltr inviting comments on DES re comprehensive mgs plan for Finelends Natl Reserve, Plan has no significant radiological health & safety impacts & will not affect NRC activities. MULLER D. R. Assistant Director for Environmental Technology, 80/10/25, ib.
- 8010310458 Forwards affidavit re unresolved generic safety issues, in response to ABLB 800909 order. Info will be incorporated in future safety evaluation WQQDHEAD, C.P. Hearing Branch 1. 80/10/30. ip.
- --9010310484 Affidavit re unresolved generic safety issues, in response to ASLB 800707 order. Facility can continue to operate prior to ultimate resolution of six identified issues w/o endangering health & safety
 PAULSON, M. A. Jersey Central Power & Light Co. 80/10/28 36pp.
- Q Inspection reports, IE Bulletine & correspondence
- 8010010397 Forwards IE Insp Rept 50-219/80-24 on 800627, No noncompliance hoted, ORIER, B.H. Region 1. Philadelphia, Office of the Director, 80/08/07. 2pp.
- ~~8010010404 IE Insp Rept 50-219/80-24 on 800627. No noncompliance noted, Major areas inspected: emergency planning program procedures & representative records interviews w/personnel & inspector observations
 TERC:N M Region i, Philadelphia, Office of the Director.
 BORES,R J Region i, Philadelphia, Fuel Facility & Materials
 Bafety Branch. 80/08/05 App.
- 8010100026 Forwards IE Insp Rept 50-219/80-25 on 800709-0801. No noncompliance noted, 9RUNNER, E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Stanch. 80/08/20. 2pp.
- --B010100030 IE Insp Rept 50-219/80-25 on B00709-0801, No noncompliance noted, Major areas inspected: followup of operational events that occurred during insp.review of plant operations (startup) & log & record reviews.

 BRIODR.L., THOMABJ, Region 1, Philadelphia, Office of the Director. KENMOJR.R. Region i, Philadelphia, Reactor Operations Nuclear Support Branch, 80/08/19, 14pp.
- 8010030309 Responds to IE Bulletin 80-15. Power to emergency notification sys supplied through safety-related buses. Util expended 50 manhours on bulletin. FINFROCK, I.R. Jersey Central Power & Light Co. B0/08/27. 2pp.
- 8010060125 Responds to IE Bulletin 80-20. Westinghouse Type H-2 control switches are not used in any safety-related sys.
 FINFROCK, I R. Jersey Central Power & Light Co. 80/08/28, ip.
- 8010010652 Responds to IE Bulletin 80-17. Suppl 3, re partial loss of control air pressure causing partial opening of scram outlet valves w/o rod motion, Various procedural changes implemented to satisfy requirements of bulletin, FINFROCK, I.R. Jersey Central Power & Light Co. 80/08/29. 2pp.
- 8010010656 Responds to IE Bullebin BO-17, Buppl i, re BHR control rod failure to insert. Design improvements to screm discharge yol are under consideration & evaluation, FINFROCK, I.R. Jersey Central Power & Light Co. 80/08/29. 2pp.
- 8010010408 Ack receipt of 800820 itr informing NRC of steps taken to correct violations noted in Mgt Meeting Rept 50-219/80-18, ORIER, B. H. Region 1: Philadelphia, Office of the Director. 80/09/10. ip.

- --8010010414 Responds to NRC 800523 Itr re violations noted in Mgt Meeting Rept 50-219/80-18 Corrective actions acting supervisor of raduaste operations was appointed prior to 800701
 FINFRCK, [R Jersey Central Power & Light Co 80/08/20 1p.
 - FINFROCK, I R Jersey Central Power & Light Co BO/OB/20 1p.
- 8010010836 Responds to Suppl 1 to IE Sulletin 80-17 Describes mode to monitor scrae discharge water level. Continuous monitoring sys to be installed & operational by 801201 FINFRUCK.IR Jersey Central Power & Light Co 80/09/18 2pp
- 8010270201 Forwards response to IE Bulletin 80-11. "Masonry Wall Design " Attachment 1 to util 800707 ltr is revised per recommendations made during NRC 800806-07 site insp FINFROCK, IR Jersey Central Power & Light Co 80/09/19 7pp
- 8010240332 Ack receipt of 800903 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-219/80-19 & 50-219/80-21 SRUNNER; E.J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 80/09/23 ip.
- --8010240338 Responds to NRC 800811 ltr re violations noted in IE Insp Rept 50-219/80-19 Corrective actions Procedure 205 7 revised to incorporate positive means for control room operator to verify one-roof permissive jumper action ROSS.D A Jersey Central Power & Light Co 80/09/03 3pp.
- --8010240343 Forwards IE Insp Repts 50-219/80-19 & 50-219/80-21 on 800506-09, 13-14, 20-23 & 27-30 & notice of violation ORIER, B H Region 1, Philadelphia. Office of the Director, 80/08/11 2pp
- --8010240347 Notice of violation from insp on 800506-09,13-14,20-23 to 27-30

 * Region 1. Philadelphia. Office of the Director 80/08/07. ip
- --8010240351 IE Insp Repts 50-219/80-19 & 50-219/80-21 on 800506-09, 13-14,20-23 & 27-30. Noncompliance noted licensee action to place administrative controls on override of safety actuation signals during containment purging.

 KEIMIG.R Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. BRIGOS, L. THOMAS J. Region 1. Philadelphia, Office of the Director 80/08/07 lipp
- 8010300123 Forwards Suppl 2 to IE Bulletin 77-018, "Environ Qualification of Class IE Equipment " No written response required. GRIER, B. H. Region 1. Philadelphia, Office of the Director 80/07/30 1p
- 8010170687 Forwards order confirming util commitments to implement action re IE Bulletin 80-17.
 STELLO.V Office of Inspection & Enforcement, Office of the Director. B0/10/02 tp
- --8010170693 Order confirming util commitments to implement action re IE Bullstin 80-17 STELLO,V Office of inspection & Enforcement, Office of the Director. 80/10/02 7pp
- 8010240149 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER.3 H Region 1, Philadelphia, Office of the Director 80/10/02 p
- 8010280188 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested ORIER.8.H Region 1. Philadeiphia. Office of the Director 80/10/10. 19.
- R. Periodic operating reports & related correspondence
 - 1210417 Forwards monthly operating rept for Sept 1980 INFROCK: I.R. Jersey Central Power & Light Co. 80/10/15. 1p.
 - 110210425 Monthly operating rept for Sept 1980 SKLAR, J. B. Jersey Centrel Power & Light Co. 80/10/07. Spp.
 - 240477 Forwards revised monthly operating repts for Jul & Aug 1980 NFROCK, I R. Jersey Central Power & Light Co. 80/10/17. 1p.
 - 10240480 Revised monthly operating rept for Jul 1980. SKLAR, J B. Jersey Central Power & Light Co. 80/10/17. 2pp.
 - 10240485 Revised monthly operating rept for Aug 1980. EKLAR, J. 8 Jersey Central Power & Light Co 8D/10/17. 2pp.

- S Reportable occurrences, LERs & related correspondence
- 8010080565 PNO-I-ED-130 on 800911, Region 1 was notified by Ofc of Congressional Affairs of info received that facility had dumped radwaste at landfill Region 1 inquiries found rumor of dumping incorrect BRIQOS.L., KEIMIG.R., BRUNNER, E.J. Region 1, Philadelphia, Dffice of the Director 80/09/15 2pp
- 8010100374 PND-TMI-80-045 on 800915.NRC approved major changes in organization which establishes General Public Utils Nuclear Group & which includes revised plant staff organizations HAVERKAMP, D.R., FASANO, A.N., COLLINS, J.T. TMI Program Office 80/09/16 2pp
- 8010010420 PNO-I-80-i30A on 800916, member of NJ Ocean County Board of Chasen Fresholders held press conference to discuss rumored dumping of radwaste at offsite landfill County radiological officer found no abnormal activity levels BRIOGS, L. KEIMIO, R. BRUNNER, E. J. Region 1, Philadelphia, Office of the Director BO/09/17 ip
- 8010090222 PND-I-80-190A Ocean County.NJ radiological officer conducted radiation survey of landfill due to rumors of radwaste dumping No abnormal activity levels were detected BRIQOS, L. KEIMIO.R. BRUNNER.E J Region 1, Philadelphia, Office of the Director 80/09/17 ip
- 8010070155 Forwards Nonroutine Environ Operating Rept 50-219/80-7 FINFROCK, I.R. Jersey Central Power & Light Co. 80/09/19 [p.
- --8010070160 Nonroutine Environ Operating Rept 80-7 on 800901.02 & 04four individual dilution pump trips occurred in which inoperative or reserve pump could not be started within required 15 minutes Caused by component failure 4 Jersey Central Power & Light Co. 80/09/19. 2pp
- 8010030494 Nonroutine Environ Operating Rept 50-219/80-8 on 800910. second dilution pump was not placed into operation w/water temp esceeding 87 F for period more tht 2-h 15 minutes. Caused by damaged into arm motor bearing # Jersey Central Power & Light Co 80/09/25 3pp
- 8010140380 PND-I-80-137 on 800927, four individuals received skin & hair contemination when investigating fire alarm & hydrogen alarm in augmented offices bldg Decontamination was routine Licenses is investigating PLUMLELX, SMITH, Q H Region i, Philadelphia, Office of the Director 80/09/29 ip
- 8010070476 Forwards LER 80-041/03L-0 FIMFROCK, I R Jersey Central Power & Light Co 80/10/01 3pp
- --8010070486 LER 80-041/03L-0 on 800705,core spray sys 2 was removed free syc to repair leaking vent line on core spray booster pump "D". Caused by personnel using pipe as foot hold Pipe nipple replaced & sys returned to syc.
 CROSBY.P.J Jersey Central Power & Light Co 80/10/01 ip
- 8010090315 Forwards LER 80-040/03L-0 FINFRDCK, I. R. Jarsey Central Power & Light Co 80/10/01 3pp
- --8010090322 LER 80-040/03L-0 on 800904, north core spray sys snubber 31/4 feiled to lock in either tension or compression directions Caused by loose socket head screws permitting hydraulic fluid to leak, Snubber replaced & screws tightened OASBARRO, D.P. Jersey Central Power & Light Co. 80/10/01, ip
- 8010150470 Forwards LER 80-041/03L-0 FINFROCK,I R Jersey Central Power & Light Co. 80/10/07 3ep.
- --80(0150479 LER 80-042/03L-0: on 900911, high drywell switches IP-15A.

 IP-15B & IP-15C tripped at value greater than 2 0 psig as specified in Tach Specs Caused by instrument drift. Switches adjusted to trip within Tech Spec Indit.

 CROSBY, P. J. Jersey Central Power & Light Co 80/10/07 lp.
- 8010210493 Forwards LER 80-043/03L-0, FINFROCK, I. R. Jersey Central Power & Light Co 80/10/14, 3pp
- --8010210495 LER 80-043/03L-0 on 800925, during routine surveillance. reactor triple low water level sensor REIBD tripped at level less conservative than Tach Specs, Caused by sensor repeatability, Sensor raset GASBARRO, D. P. Jarsey Central Power & Light Co. 80/10/03. 1p.
- 8010310414 Forwards LER 80-045/03L-0, FINFRUCK, I.R. Jersey Central Power & Light Co 80/10/27 3pp

- ---B010310421 LER 80-045/03L-0 on 801002,core spray sys 1 was removed from svc to repair leaking vent line off suction of core spray pump NZO1C Caused by crack in 1/4-inch copper nipple Nipple removed & tee was plugged OASBARRO,D P Jersey Central Power & Light Co 80/10/21 1p
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8010010375 Forwards changes to security plan. Changes withheld (ref 100FRZ 770) SUNBER, J. J. Niagara Mohawk Power Corp 80/09/24 1p
- 8010220492 Forwards revised security plan Revision withheld (ref 100FR 790)
 SUNSER, J. J. Niagara Mohawk Power Corp 80/10/15 ip.
- B010310378 Forwards security plan & request for exemptions from code requirements Info withheld (ref 10CFR2 790).
 THOMABLE B. LeBoeuf, Lamb, Lsiby & MacRae 80/10/29 ip
- O Adjudicatory correspondence
- B010030205 Forwards 800919 order revising 800829 order for mod of OL.in entirety.
 EISENHUT, D. Q Division of Licensing. 80/09/19. 2pp
- --8010030208 Order revising 800829 order for mod of OL DPR-63.published in 800911 FR.in entirety Response to IE Bulletin 79-018 shall be submitted by 801101. Request for hearing will not stay effectiveness of order. USB petitions discharged. EISENHUT.D Q. Division of Licensing 80/09/19. App
- B010200280 Forwards order confirming util commitments to implement action re IE Bulletin 80-17

 STELLO, V Office of Inspection & Enforcement, Office of the Diractor. 80/10/02 1p.
- ---8010200283 Order confirming util commitments to implement action re IE Bulletin 80-17. BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02. 7pp,
- BO10280484 Requests fee remittance to 800630 polition to amend confirmatory order concerning approval to operate facility wwo rectrculation pump trip until maxt refueling outage.
 MILLER, W. O License Fee Management Branch.
- J. Insurance & indomnity information
- 8010280655 Requests Endorsements 32 & 33 to Policy MF-77 & Endorsements 38,37 & 40 to Policy NF-208, DINITZ, I Utility Finance Branch (formerly Antitrust & Indemnity), 80/09724, ip
- P. Operating license stage documents & correspondence
- 8010030170 Requests convening of hearing re util proposed installation of incinerator for radwasts vol reduction & informs of potential policy implications.

 DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director.

 BECY-79-383, 79/06/11. 33pp.
- 8010020013 Requests addl info for branch review of inservice testing progrem & meeting on 801007-08 at facility.

 BOBNAK,R J. Mechanical Engineering Branch. 80/09/17. 9pp.
- 8010060024 Forwards request for add1 info re inservice inep & inservice testing programs to be reviewed during 801007-08 site visit. IPPOLITO.T.A Operating Reactors Branch 2 80/09/19, 10pp
- B010200398 Forwards written commitment re installation of equipment to monitor water level in scram discharge vol.per NRC 800909 request Installation will include indication & alarm in control room
 LEMPGES.T. E Niagara Mohawk Power Corp. 80/09/19, 2pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Currected table of implementation schedule also encl. EISENHUT.D 9 Division of Licensing. 80/09/19, 28pp.

- B0100B0453 Requests add1 action re NRC 7B0B07 ltr ra deficiencies in Match.Unit 2 regulator sys design.Mods should be performed to provide fully redundant Class IE protection at interface of Monclass IE power supplies & reactor protection sys IPPOLITO.T A Operating Reactors Branch 2. B0/09/24 3pp
- 8010300647 Submits commitment to complete installation of equipment to continuously monitor water level in acrem discharge vol.per
 NRC request
 LEKPOES,T E Niagera Mohawk Power Corp. GD/09/24. 1p
- 8010070319 Informs that licensee will make all mods necessary to meet acceptance criteria on Mark I containment program by 821231 Notification will be in event analyses result in delay DISE, D. P. Niagara Mohawk Power Corp 80/09/27 ip
- 8010130360 Forwards ECCS outage rept for June 1975 June 1980 for safety-related sys which may be utilized to mitigate consequences of LUCA in response to NRC 800307 its Emergency condenser surveillance is only testing outage included DISE, D P Niagara Mohawk Power Corp 80/10/08 10pp
- 8010280484 Requests fee remittance re 800630 patition to amend confirmatory order concerning approval to operate facility w/o recirculation pump trip until next refueling outage MILLER. H O. License Fee Management Branch 80/10/09. 1p.
- 8010160515 Forwards, on behalf of util, application for amend to License DPR-63 & proposed Tech Spec changes re scram discharge voldraw.
 THOMAS, E. B. LeBoeuf, Lamb, Leiby & MacRee, 80/10/15. 1p
- ---B010160518 Application to amend License DPR-63, changing Tech Spec Bections 3 1,1 & 4,1,1 re scram discharge vol draw DISE, D.P Niagara Mohawk Power Corp B0/10/14 2pp
- --B010160520 Proposed changes to Tech Spsc Sections 3 1 1 & 4.1 1 re scram discharge vol draw Supporting info encl * Niagara Mohawk Power Corp. 80/10/14 6pp
- 8010280585 Forwards add1 info required for review of 790920 application for amend to OL allowing power operation w/up to two inoperable recirculation loops, DISE, D P Niagara Mohawk Power Corp. 80/10/22 dpp
- 8010310379 Informs that mode to scram discharge volomhich will bring scram sys into compliance w/criteria developed thus far by BHR Owners Bub-group, are scheduled to be implemented during next refueling outage in Har 1981.

 LEMPOES, T. E. Niagara Mohawk Power Corp 80/10/27 3pp.
- @ Inspection reports, IE Bulletins & correspondence
- 8010020105 Responds to IE Bulletim 80-17,8uppl 3 re control rods failure to insert at BMR Encl info demonstrates that continued operation does not present undue safety hazard Util expended 40 manhours on bulletin.

 LEMPOES,T E. Niagara Mohawk Power Corp 80/08/29. 3pp.
- B010020101 Responds to 1E Bulletin 80-17,8uppl 1 re control rods failure to insert at BHR Forwards study of potential designs for improving scram discharge sys. LEMPGES.TE Niagara Mohawk Fower Corp B0/09/02 4pp.
- 80:00:06:08 Responds to IE Bulletin 80-15 re emergency notification sys power sources. Emergency nofification phone sys is considered to be backed up by reliable power supply.

 LEMPOES: T. E. Niegera Mohawk Power Corp. 80/09/03. 3pp.
- 8010010852 Responds to IE Bulletin 80-20. Revision 1 No Westinghouse Type M-2 control switches are in use BARTLETT, J Niagara Mohawk Power Corp. 80/09/11. ip
- 8010040024 Forwards request for add1 info re inservice insp & inservice testing programs to be reviewed during 801007-08 wite visit.

 IPPOLITO T.A. Operating Reactors Branch 2 80/09/19. 10pp
- 8010200280 Forwards order confirming util commitments to implement action re IE Bulletin 80-17 STELLO.V. Office of Inspection & Enforcement, Office of the Director, 80/10/02. ip.
- ---8010200283 Order confirming util commitments to implement action re IE Bulletin 80-17. STELLO,V. Diffice of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.

- 8010240125 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 1p
- 8010280187 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bulting " No specific action or response requested GRIER.B H Region 1, Philadelphia, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010150404 Forwards monthly operating rept for Sept 1980 LEMPOES T E Niagara Mohawk Power Corp 80/10/08 1;
- --8010150406 Monthly operating rept for Sept 1980 ROMAN, T. W. Niegara Mohawk Power Corp 80/10/03 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010090481 RO 80-19 on 800827, during steady state operation, reactor bldg track bay outside door seals determined improperly installed Caused by damage from usage Sealing lugs repaired & properly installed on outside door # Niagara Mohawk Power Corp 80/08/28 ip
- B010200505 PND-I-80-132 on B00919, licensee plans shutdown to cold condition to investigate & repair leakage into drywell from unidentified source Startup is scheduled for B00922. HUBBON.S D. MARTIN.T T. BRUNNER,E J. Region 1, Philadelphia, Office of the Director B0/09/19 ip
- 8010080478 Forwards LER 80-020/03L-0.
 BARTLETT.J Niagara Mohawk Power Corp 80/09/29. 1p
- --8010080482 LER 80-020/03L-0 on 800830, while experiencing electrical storm during normal operation, loss of meteorological deta transmission to control room instruments occurred Caused by transcriver failure. Transcriver repaired & returned to svc HARRISON, P Niagara Mohawk Power Corp 80/09/29 2pp
- 8010200928 Forwards LER 80-021/03L-0, LEMPGES, T.E. Niagara Mohawk Power Corp. 80/10/08. 1p
- --80i0200335 LER 80-02i/03L-0 on 80091i.during normal operation.
 instrument calibr procedure for fire protection sys was not
 BORC approved within specified 7-day period Caused by
 personnel oversight. Tickler file will be established
 HARRISON.P Niagara Mohawk Fower Corp 80/10/08 ip
- 8010300458 Forwards LER 80-023/03L-0 BARTLETT, J Niagara Mohawk Power Corp. 80/10/21 1p
- ---8010300463 LER 80-023/03L-0 on 800922,111 absolute filter access cover was found off housing Caused by residual pressure in containment nitrogen inerting line pressurizing filter housing when torus venting initiated Cover reinstalled, HARRISON.P Niagera Mohawk Power Corp 80/10/20. 2pp
- 8010310448 Forwards LER 80-022/03L-0 BARTLETT, J Niagara Mohawk Power Corp. 80/10/24 1p.
- --B010310454 LER 80-022/03L-0 on B00927, low power range monitor detector failed rendering everage power range monitor 18 inoperable.

 Caused by internal shorting Low power range monitor will be replaced during next refueling HARRISON.P. Niagara Mohawk Power Corp 80/10/24 1p.
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR
- S. Reportable occurrences, LERs & related correspondence
- 8010070127 PNO-I-80-128 on 800707, portable gentry fell on summer work/
 study student working in reactor bldg causing fractured
 skull & internal injuries Reactor was shutdown. No rediction
 or contamination was involved.
 IROSKOSKI, N., CAPHTON, D., BRUNNER, E. J. Region i, Philadelphia,
 Office of the Director 80/09/09 1g.

- DOCKET 50-233 MEXICO RESEARCH REACTOR J Insurance & Indomnity information
- B0102B0720 Requests Endorsement 109 to Policy NF-34 Endorsement 47 to Policy HF-59 & Amends 29, 30,31 & 32 to Policy B-9 DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity). B0/09/24 ip
- DOCKET 50-234 TUNGSTEN NUCLEAR ROCKET CRITICAL FACILITY
- J Insurance & indemnity information
- 8010280720 Requests Endorsement 109 to Policy NF-34.Endorsement 47 to Policy MF-59 % Amends 29.30.31 % 32 to Policy B-9 DINITY. I Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24 1p
- DOCKET 50-235 ACCELERATOR PULSED FAST ASSEMBLY
- J Insurance & indemnity information
- B010280720 Requests Endorsement 109 to Policy NF-34, Endorsement 47 to Policy MF-59 & Amends 29, 30, 31 & 32 to Policy B-9.
 DINITZ. Utility Finance Branch (formerly Antitrust & Indemnity).
 B0/09/24. ip
- DOCKET 50-237 DREBBEN NUCLEAR POWER STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- B010020162 Requests resubmission of Revision 8 to util security plan Wispecific changes properly identified Original submittal unacceptable for review.

 CRUTCHFIELD, D Operating Reactors Branch 8 B0/09/10. 2pp
- 8010220437 Forwards IE Health Physics Appraisal Repts 50-237/80-13 & 50-249/80-17, notice of violation & significant appraisal findings KEPPLER, J G Region 3, Chicago, Office of the Director. 80/09/12
- --8010220442 Notice of violation from health physics appraisal on 800618-0702 Region 3, Chicago, Office of the Director, 80/08/29 ip.
- --801022048& IE Health Physics Appraisal Repts 50-237/80-13 & 50-249/80-17 Noncompliance noted laundered protective clothing in clean laundry storage bins read 22,000 counts per minute SCHUMACHER,M C , PAUL,R A , DESTMANN,M V. Region 3, Chicago, Office of the Director 80/08/29 47pp
- O Adjudicatory correspondence
- BO10020269 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment. Submittal of info required by BO1101 CRUTCHFIELD, D. Operating Reactors Branch 5 BO/08/29 2pp
- --8010020277 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT, D.G. Division of Licensing. 80/08/29. App.
- --B010020281 Order for mod of license requiring timely submission of inference of previously requested re-environ qualification of sefety-related electrical equipment EISENHUT.D 0. Division of Licensing 80/08/29. App
- 8010020026 Requests reviewer to provide testimony for Contentions 2 & 3 of second amended contentions of State of IL re spent fuel pool storage Reviewer should be identified by 800915 for 801117 hearing.

 IPPOLITO, T.A. Operating Reactors Branch 2 CRUTCHFIELD, D Operating Reactors Branch 5. 80/09/16, 1p.
- CODDARD, R J. Hearing Branch 2, 80/09/04, 2pp.

- 8010230279 Requests reviewer to provide testimony for Contention 5 of second amended contentions of State of IL re spent fuel pool storage. Reviewer should be identified by 800915 for 801119 heering IPPOLITO, T A Operating Reactors Branch 2 CRUTCHFIELD, D Operating Reactors Branch 5 80/09/16 ip
- 8010290330 Forwards add1 documents per informal discovery agreement H/o enci FITZ018B0NS,R Isham, Lincoln & Beala 80/09/24 ip
- B010020068 Enumerates name of util witnesses per agreement on informel discovery re ASLB B00909 memorandum & order.R Anderson will be deposed on 801027 State of IL witnesses will be available during who of B01110

 BTEPTOE
- 8010020740 Forwards util response to NRC technical review questions Update to 7805il licensing rept will be submitted shortly 8uggests that tentetive concessions for compramise be apart from formel record per rule of evidencs re sattlement 8TEPTGE, P Ishem, Lincoln & Beale 80/09/29 2pp
- 8010070611 Forwards listed discovery documents W/o encl FITZ01880N8,R Commissioners 80/09/30 1p.
- 8010070023 Notice of 801119-21 hearing in Morris, IL re proposed OL amends, ASLB will be composed of JF Nolfichairman & LW Little & FJ Remich, members limited appearance statements welcome MOLF, J, F Atomic Bafety and Licensing Board Panel. 80/10/01 2pp
- 8010090054 Informs of util intent to pull empty rack out of spent fuel pool to determine feastbility of decontamination using hydrolasing techniques, Related correspondence.

 STEPTOE: P.P. Isham, Lincoln & Beale. 80/10/02 2pp
- BOID200289 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02. 1p.
- --8010200274 Order confirming util commitments to implement action re IE Bulletin 80-17 BTELLO,V Office of Inspection & Enforcement, Office of the Birector 80/10/02 7pp
- --8010200297 Order confirming util commitments to implement action re IE Bulletin 80-17. BTELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.
- ---B010200302 Order confirming util commitments to implement action re IE Bulletin 80-17. BTELLO,V Office of Inspection & Enforcement, Office of the Director B0/10/02. 7pp
- --8010200306 Order confirming util commitments to implement action re IE Bulletin 80-17.
 BYELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 7pp
- 8010210222 Forwards orders confirming util commitments to implement ection re IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR."

 STELLO, V. Office of Inspection & Enforcement, Office of the Director 80/10/02, 2pp.
- 8010140511 Lists witnesses who will testify at proceeding. Listed individuals will be made aveilable for depositions. CODDARD, R. J. Hearing Branch 2 80/10/07 2ρρ.
- B010160032 Notice of appearance in proceeding Certificate of Bvc encl BCHERRIB, J. Natural Resources Defense Council. B0/10/10 Spp.
- 80:016:0036 Patition for Commission approval to delay environ qualification of electrical equipment until restart. Requests stay of NRC 800919 order requiring qualification by 80:101 STEPTOE.P. Commonwealth Edison Co. STEPTOE.P. Isham, Lincoln & Beale 80:10/14. 400
- ---8010200473 Forwards revised 800827 order re response to IE Bulletin 79-01B, correcting refs Date for which hearing may be requested also revised. EIBENNUT.D.O. Division of Licensing. 80/09/19. 2pp.

- 8010160778 Order directing licensee & NRC to inform ASLB by 801031 whether there is intention to pursue application. If intention exists, NRC shell inform ASLB of estimated dates of safety evaluation & EIS publication MILHOLLIN, 0 L Atomic Sefety and Licensing Board Panel 80/10/14 2nn
- 8010210523 Forwards eddl documents pursuent to informal discovery agreement Documents include Special Rept 28 & subsequent submittels & addendums re handling of spent fuel shipping cask & GA dept audits M/O encls FITZOIBBONS, R Isham, Lincoln & Beale 80/10/15 ip
- 8010230397 Forwards list of requested documents re internal eudits done by Leckenby. IE ections for GA/GC program & purchese orders between various contractors & subcontractors Related correspondence MURRAY, M J Illinois, State of BO/10/16 2pp
- 8010230464 Forwards add1 documents pursuant to informal discovery agreement per 801016 request. Documents ere specific portions of Comm Ed OA manual re 10CFR21 reporting procedures Related correspondence.

 BTEPTOE:P Isham
- 8010280535 Notice of appearance in proceedings. STEPTOE.P P Commonwealth Edison Co STEPTOE.P P Isham, Lincoln & Beale 80710/23 ip
- B010270385 Request for hearing re 800919 orders for mod of licenses requiring certain info on environ qualification of safety-related equipment in response to IE Bulletin 79-018. Urges suspension of effectiveness of orders. W/Certificate of Evc. STEPTOE, P. P. Commonwealth Edison Co. STEPTOE, P. P. I sham, Lincoln & Beale, 80/10/23 App
- J Insurance & indemnity information
- 8010280613 Requests Endorsement 109 to Policy NF-43 & Endorsement 87 to Policy HF-22 DINITZ/I. Utility Finence Branch (formerly Antitrust & Indemnity) BO/09/24 1p
- P Operating license stage documents & correspondence
- 7812080197 Discusses possible dangers of LOCA in containment purging during normal plant operation Requests commitment to either cease purging or limit purging to absolute min.not to exceed 90 hours par yr Forwards SRP & madel Tech Specs, ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29
- --7812080207 Model Tech Specs 3.6 1.8 & 4 6.1 8 re containment ventilation sys, including limiting conditions & surveillance requirements * Operating Reactors Branch 2 (Pre 790625) 78/11/29 2pp
- 8010010343 Forwards BEP Topic VIII-2, "Onsite Emergancy Power Bys Diesel Generator for Dresden Unit 2 " Compares facility against current NRC criteria for Itemsing CRUTCHFIELD, D Operating Reactors Branch 5 80/08/20. 2pp.
- --8010100142 "Onsite Emergency Power Bys Diesel Generator," SEP technical evaluation Topic VIII-2, for Dresden Unit 2 * Operating Reactors Branch 5. 80/08/20 10pp.
- 8010090536 Discusses topics to be added to 791116 listing of topics deleted from SEP review. Forwards revised listing of DBE accident & transient groups applicable to BMRs. w/inclusion of Group XI CRUICHFIELD, D Operating Reactors Brench 5 80/09/11. 7pp.
- 8010220387 Concludes that response to ECCS clad swelling & rupture.Task 8-47, is adequate. No further action necessary CRUTCHFIELD, D Operating Reactors Branch 5 80/09/11. 2pp.
- 8010220097 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule elso encl SISENHUT, D. O Division of Licensing. 80/09/19. 20pp.
- 8010060012 Discusses util response to NRC 791107 1tr re portions of ECCE evaluation models, Response is acceptable.

 IPPOLITO, T A Operating Reactors Branch 2 80/09/24. 2pp.

DOCKETED ITEMS

- 8010070240 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch. Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies t
- 8010100361 Submits list of current qualification programs for EPRI util squipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC applied. LAMKEN.D.C. Commonwealth Edison Co 80/09/24. 2pp.
- 8010140215 Responds to NRC 800812 ltr re BEP Topic V-11.A, Requirements for Isolation of High & Low Pressure Bys Facility conforms ex/licensing besis assumed in evaluation.

 JANECEK, R. F. Communical th Edison Co. 80/09/30. ip.
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements." Urgst NRC to consider weighing sach proposed revision against benefit of having plant changes implemented promptly. REED, C. Commonwealth Edison Co. 80/10/01, 8pp.
- 8010070354 Forwards info & drawings re undervoltage protection, in response to Questions 1,2,3,4 & 6 of NRC BOOBIG itr. Tech Bpecs changes identified in Questions 5 & 7 being evaluated, JANECEKAR F Commonwealth Edison Go. B0/10/01. 3pp.
- --B010070564 "Relaying & Metering Diagram 4 kV & 480 Volt Buses 148, 149, 138 & 139,"
 - Sargent & Lundy, Inc 3782 73/07/16 ip.
- --8010070570 "Bohamatic Diagram, Electronic Switching Bys Bus 149 " * Bargent & Lundy, Inc 78/06/06 ip.
- --8010070579 "Schematic Control Diagram, 4160 Volt Bus 13-1 Standby Diesel, 1/2 Feed Breakers,"

 + Bargent & Lundy, Inc. 79/10/01. 1p
- 8010150463 Ack receipt of proposal for installation of underfrain pips sus to minimize seepage effects from unit cooling late.
 FIORELLI.O. Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/10/02. 1p.
- --8010180665 Forwards copy of request for proposal to install underdrain (divorter) pipe sys for unit cooling late north dike.

 JANEGEK.R.F. Commonwealth Edison Co. 80/09/19 6pp.
- 8010280235 Forwards OE recommendations for Tech Specs changes for flow biased average power range monitor scram & rod block setdown Changes are due to NRC concern w/using total peaking factor as setdown factor for BHRs w/different fuel lengths.

 JANECEK: R. F. Commonwealth Edison Co. 80/10/03 Bpp
- 8010240203 Forwards proposed Tech Spec changes, per NRC 800707 request, Changes provide addl operational & surveillance requirements.

 JANECEK,R.F. Commonwealth Edison Co. 80/10/14 2pp,
- --B010240210 Revised Tech Epsc Pages 42,43,53,62 & new Page 61s for Dresden Units 2 & 3 & Pages 3,2/4,2-14,3,2/4,2-16,3,3/4,3-3 & 3,9/4,3-7 for Quad Cities Units 1 & 2, ** Commonwealth Edison Co. 80/10/14, 22pp.
- 8010290333 Application for amend to App A Tech Specs of Licenses DPR-19 to DPR-25, implementing fire protection made by revising Bections 3 12 to 4,12 of fire protection sys. Class I to III amend fees encl
 JANECEX,R.F. Commonwealth Edison Co 80/10/21. 2pp. Commonwealth Edison Co 80/10/21. 2pp.
- --8010270335 Proposed changes to App A Tech Specs, revising Sections 3.12 & 4.12 re limiting conditions for agerations & surveillance requirements of five protection sys.

 # Commonwealth Edison Co. 80/10/21. 29pp.
- 8010270366 Responds to NRC 800619 ltm re loss of offsite power survey status. Concludes that events reported in 791219 ltm have been misintenented in 791219 to complete

80/10/23, 3ps.

.eabouqeuce

ttance of Region 3 personnel and for whom permanent reconst requiring badge ice of the Director, 80/09/03.

ī

- 8010300597 Forwards IE Insp Repts 50-237/80-15 & 50-249/80-19 re 800921 meeting in Chicago, IL re cooling late dise seepage & ramedial measures to preclude further seepage & effects to dike structure.

 FIORELLI-0. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/03. 2pp
- --8010300600 IE Insp Repts 50-237/80-15 & 50-249/80-19 of 800821 meeting w/util in Chicago, iL re caping late dike seepage & remedial measures to preclude further seepage Related correspondence & documentation encl OALLAGHER, E. J. Region G. Chicago, Office of the Director, HAYES, D.M. Region G. Chicago, Reactor Construction & Engineering Support Branch 80/09/02 100pp
- B010090189 Forwards addl response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts."

 Load tests have been performed on concrete expansion anchors on all accessible safety-related piping sys

 JANECEK.R.F. Commonwealth Edison Co. 80/09/05 17pp.
- 8010200282 Forwards addl response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts." Load tests performed on concrete expansion anchors on all accessible safety-related piping sys

 JANECEK, R. F. Commonwealth Edison Co. 80/09/05 17pp
- 8010100241 Responds to 800818 request for add1 info re IE Bullstin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys," List of sys where pips atress levels exceed one-half of ultimate math stress will be provided monthly.

 JANECEK, R. F. Commonwealth Edison Co. 80/09/19 2pp
- 8010100250 Submits addi response to IE Bulletin 80-17 & Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR " Util will install continuous water level moniforing of scram discharge vols by 801201 JANECEK, R. F. Commonwealth Edison Co 80/09/19. 5pp.
- 8010280135 Ack receipt of 800918 itr providing add1 info re control rod drive design contained in IE Insp Repts 50-237/80-09 & 50-247/80-09 KEPFLER, J. G. Region 3, Chicago, Office of the Director 80/09/23
- --8010280163 Informs that walkdown of insert & withdrawal lines routing & support will be performed during next extended outage.

 Comparison will be made w/Guad Cities to verify design similarity. Beliemic reanalysis to be done if design differs.

 ABEL.J. B. Commonwealth Edison Co. 80/08/18 ip.
- 8010140133 Forwards Inst of Nuclear Power Operations, "Evaluation of Bresden Nuclear Power Station" STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/09/30. ip
- ---8010140137 Forwards Inst of Nuclear Power Operations, "Evaluation of Dresden Nuclear Power Station."

 KEPPLER, J. G Region 3, Chicago, Office of the Director. 80/09/6
- 8010160314 Forwards Suppl 2 to IE Bulletin 79-019. "Environ Gualification of Class IE Equipment," No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/30
- 8010200289 Forwards order confirming util commitments to implement action re IE Bulletin 80-17.

 STELLO.V. Office of Inspection & Enforcement. Office of the Director. 80/10/02. 1p.
- --8010200274 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 7pp.
- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 76 of 180 Control Rods to Fully Insert During Scram at BWR."

 BYELLOY, Office of Inspection & Enforcement, Office of the Director 80/10/02. 2pp.
- 8010220139 Responds to IE Bulletin 80-17. Suppl 3 re failure of contrel rods to insert at BWR. Procedures changed to specify that operator should manually scram reactor upon low scram air header pressure alarm.
 RAUSCH. T. J. Commonwealth Edison Co. 80/10/02 2pp

- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/10/02 is.
- 8010270037 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Dolting " No specific action or response requested. KEPPLER, J G Region 3, Ghicago, Office of the Director 80/10/10 to.
- 8010200673 Forwards revised 800829 order re response to IE Bullstin 79-01B.correcting refs Date for which hearing may be requested also revised EISENHUT.D Q Division of Licensing. 80/09/19 2pp
- B010310160 EN-B0-050 on B01020.notification of significant enforcement action & proposed imposition of civil penalty of \$40,000 will be issued Based on inattention to licensed duties while assigned to controls at Unit 3 BRYAN,8 E., MOSELEY.N.C. Office of Inspection & Enforcement, Office of the Director. B0/10/20. ip.
- 8010290120 Forwards IE Inep Repts 50-010/80-14,50-237/80-19 & 50-249/80-23 on 800922-26 & notice of violation withheld (ref 10CFR2.790), HIND.J A Region J. Chicago: Safeguards Branch, 80/10/22, 2pp.
- --8010290125 IE Insp Repts 50-010/80-16.50-237/80-19 & 50-249/80-23 on 800922-26 Noncompliance noted failure to maintain records of proper screening documentation on contractor personnel. Details withheld (ref 10CFR2 790).
 BELANDER, L., CHRISTOFFER, G. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Bafeguards Branch 80/10/21 2pp
- 8010310260 Ack receipt of B01006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-237/80-13 & 30-249/80-17 KEPPLER, J. O. Region 3, Chicago, Office of the Director, 80/10/22, 2pp.
- --8010310267 Responds to NRC 800912 ltr re violations noted in IE Insp Repts 50-237/80-13 & 50-249/80-17. Corrective actions: training session will be conducted re operation & use of laundry monitors REED, C. Commonwealth Edison Co. 80/10/06 13pp
- R Periodic operating reports & related correspondence
- B010210440 Forwards monthly operating repts for Sept 1980. BCOTT.D. J. Commonwealth Edison Co. 80/10/15, 1p
- --8010210441 Monthly operating repts for Bept 1980. CEISZKIENICZ,8 Commonwealth Edison Co. 80/10/01. 18pp.
- S. Reportable occurrences, LERs & related correspondence
- 8010090136 PNO-III-80-169: on 800904; reporter from Chicago Sun Times contacted NRC resident inspectors re allegations that 400,000 gallons of radioactive water leaked from station since Jul 1980.
 BARKER, J., DAVIS, A. B., REIMANN, F. W., Region 3, Chicago, Office of the Director 80/09/05. 2pp
- 8010090262 PNO-III-80-169A since 800905, extensive investigations by Region 3 & util personnel into allegations of radioactive release has not determined whether actual release of low level radioactive water occurred.

 DAVIS, A B., HEISHMAN, R.F., REIMANN, F H Ragion 3, Chicago, Office of the Director 80/09/10 2pp.
- 8010080608 PNO-III-80-176: potentially high press interest exists in results of Institute of Nuclear Power Operations insp of station. Summary of insp rept encl.

 8PE686ADR.R.L. & ETRABMAR J., KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/09/15. App.
- 8010070535 Forwards LER 80-034/03L-0. 80DTT, D. J. Commonwealth Edison Co. 80/09/26. ip.
- --8010070544 LER 80-034/03L-0. on 800908, during audit, noted records did not indicate performance of 1979 annual fire protection sys flush. Caused by lack of surveillance documentation. Flush procedure for 1980 performed in Aug.
 KORCHYNBKY.M. Gommonwealth Edison Co. 80/09/19. 1p.
- 8010270380 Forwards updated LER 79-017/01T-1, 800TT, D. J. Commonwealth Edison Co. 80/09/26, 1p.

- ~-B010270381 LER 79-017/01T-1.on 790327.measured leakage around containment isolation valves 23, 24, 60, 61, 62, & 63 was 1, 660 SGFH Caused by leaks in valve shaft seals & seats Valve replaced & shaft seals repaired.

 DUNEAR.J. Commonwealth Edison Co. 80/09/03 269.
- B010140489 Forwards LER 80-033/03L-0. BCOTT,D J Commonwealth Edison Co. 80/10/01. 1p.
- --8010140496 LER 80-033/03L-0. on 800904, during normal operation, frequency of water addition to torus increased Caused by leakage in 46 tubes in LPGI heat eschanger due to probable corrosion. Leaking tubes plugged & monthly leak checks inplemented, ROWLEY, E Commonwealth Edison Co. 80/09/29 19
- 8010150494 Forwards LER 80-036/03L-0, 800TT, D. J. Commonwealth Edison Co. 80/10/07 1p
- ~-8010150501 LER 80~036/03L-0 on 800911.QA audit revealed that 6-month functional test of Cardox sys heat detectors was not performed within allowable surveillance interval.Caused by personnel error.New tracking method developed.

 RORCHYNSKY.M. Commonwealth Edison Co. 80/10/02, 1p.
- 8010150506 Forwards LER 80-035/03L-O. 800TT, D. J. Commonwealth Edison Co. 80/10/07. ip.
- ---8010150515 LER 80-035/03L-0 on 800911.GA audit revealed control & computer room smoke detectors out of svc in excess of 14 days Caused by station fire marshall overlocking requirement of Tech Specs Smoke detector mod completed in Sept 1980.
 KORCHYNSKY.M Commonwealth Edison Co 80/10/05. 1p.
- 8010210520 Forwards LER 80-037/03L-0. 800TT, D. J Commonwealth Edison Co 80/10/08, 1p
- --B010210524 LER 80-037/03L-0 on 800915,0-8 control rod driveline (CRD) was tested for overtravel Overtravel alarm came up & rod position indication was lost Caused by CRD inner filter becoming detached CRD 9-8 will be replaced & overhauled, HOLLAND,P. Commonwealth Edison Co 80/10/07. 2pp.
- B010210655 Forwards updated LER B0-016/01X-1. BCOTT.D.J Commonwealth Edison Co. B0/10/0B. Ip.
- --B010210661 Updated LER 80-016/01X-1.on 800515.while conducting 300 psi primary sys hydrostatic leak insp during shutdown water was discovered dripping from LCPI check valve up stream drain line. Caused by inadequate piping support Mods initiated. ZIRWAB.K. Commonwealth Edison Co. 80/10/06. 2pp.
- 8010280448 Forwards LER 80-039/017-0. 800TT.D.J Commonwealth Edison Co. 80/10/16. 1p.
- ---8010280314 LER 80--039/01T-0: on B01011, during startup, HPCI steam supply valve failed to open from control switch. Caused by torque switch, type BMB-1; open & close contact being stuck open. Buitch replaced.
 ZIRNAB,K. Commonwealth Edison Co. 80/10/16. 2pp.
- DOCKET 50-240 HIGH TEMP. OAB COOLED CRITICAL EXPERIMENT
- J. Insurance & indomnity information
- 8010280720 Requests Endorsement 109 to Policy NF-34 Endorsement 47 to Policy MF-59 & Amends 29.30.31 & 32 to Policy B-9.
 DINITZ: I. Utility Finence Branch (formerly Antitrust & Indemnity).
 80/09724. ip.
- DOCKET 80-243 DREODN STATE UNIV. RESEARCH REACTOR
- G. Inspection reports, IE Bulletins & correspondence
- 8010300433 Forwards IE Insp Rept 50-243/80-05 on 800910-12.No noncompliance noted, CREMB,J.L. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch. 80/09/20. 2pp.
- --8010300438 IE Insp Rept 50-243/80-05 on 800910-12.No noncompliance noted, Major areas inspected; organization, logs & records, review & audit; requalification training, procedures, surveillance & experiments.
 CARLBON-J.D., WILLETT.D.J. Region 5, San Francisco, Office of the Director. STERNBERG, D.M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/25.

- 8010140094 Forwards IE Insp Rept 50-243/80-04 on 800818-19 No noncompliance noted Major areas inspected examination of activities re physical protection against industrial subotage & theft of SNM Encl withheld (ref 10CFR2.790) NORDERHAUO, L R Region 5, San Francisco, Safeguards Branch 80/10/01 in
- DOCKET 50-244 ROBERY EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- B010310256 Forwards review & changes to physical security program Program withheld (ref 100FR2, 790)
 MAJER, J E Rochester Gas & Electric Corp B0/10/27 ip
- Adjudicatory correspondence
- 8010300516 Forwards revised order correcting 800829 order for mod of OL which contained inaccurate rafe, Date of hearing accordingly revised EISENMUT, D Q Division of Licensing 80/09/19 3pp.
- ~-8010300822 Order for mod of OL DPR-18, correcting 800829 order which contained inaccurate refs Response to NRC 800306 & 18 ltrs shall be submitted by 80101 Request for hearing will not stay effectiveness UCS petition discharged EISENHUT D O Division of Licensing 80/09/19 6pp
- I. Financial information
- 8010080410 Forwards info re actual cash flow & certified financial statement for 1979 to support util guarantee that retrospective premium can be payed per Alternative Method 5 KOHBA:8 Rochester Que & Electric Corp 80/10/02. Spp.
- J. Insurance & indemnity information
- 8010090372 Forwards certified Endorsements 65 & 66 to NELIA Policy NF-170 & Endorsements 54 & 55 to MAELU Policy MF-47 Endorsements provide premium credit for Spring 1980 refueling shutdown & mend description of facility site. HHITE, L D Rochester Gas & Electric Corp. 80/10/03. Spp
- P Operating license stage documents & correspondence
- BOLCO1009: Requests add1 info re util 791206 itr re Ceneric Btudy B-23, "Degraded Orid Voltage " Calculated voltages for low voltage ac Class IE buses required CRUTCHFIELD. D Operating Reactors Branch 5 80/08/11. 2pp
- 8009160559 Responds to DL Ziemann 800425 itr re SEP Topics VI-10 A & VI-7, A 3 on testing of reactor trip sys & engineered safety features including response time testing & EGGS actuation, respectively feet Specs & test procedures enci HHITE/L. B Rochester Oas & Electric Corp 80/09/10 4pp.
- --8009160862 "Valve Interlock Verification-Feedwater Isolation " 8CHULER, T. R., BNDW, D. A. Rochester Gas & Electric Corp. 79/03/17 6pp
- --80091A0567 "Bafaty Injection Functional Test," ECHULER TR , SNOW, B. A. Rochester Cas & Electric Corp. 80/07/03.
- ~~8009160368 "Dissel Generator Luad & Safeguard Sequence Test."

 * Rochester Gas & Electric Corp. 80/06/26 23pp.
- ---8009160570 "Verification of Emargency Start Logic Auxiliary Feedwater Pumps " BCHULER, T.R., SNOW, R.A. Rochester Cas & Electric Corp. 80/03/17. 7pp
- --8009160574 "Process Instrumentation Reactor Protection Channel Trip Test " * Rechester Oss & Electric Corp. 80/07/30, 16pp.
- --8009160976 "Plant Safequard Logic Test A or B Train "
 # Rochester Gas & Electric Corp. 80/03/07, 11pp.
- --B009160577 "Post Accident Charcoal Filter Dampers."
 # Rechester Gas & Electric Corp 80/05/07, 9pp.
- --B009i60578 "Containment Post Accident Charcoal Filter Bypass Flow,"

 * Rochester Gas, & Electric Corp 80/04/09. 5pp.

- --8009160580 "Containment Fan Recirculation Unit HEPA Filter Bant Testing " # Rochester Gas & Electric Gorp 78/09/25 8pp
- --8009160382 "Containment Recirculation Fans Mass Air Flow Check "
 * Rochester Gas & Electric Corp 80/03/31 11pp
- 8010230403 Advises of review of response to NRC 791109 ltr re ECC8 evaluation models dealing w/fuel cladding swelling & incidence of rupture Util response is acceptable No further action is necessary CRUTCHFIELD.D Operating Reactors Branch 5 80/09/11 2pp
- 8010150629 Forwards request for add1 info re SEP Topics VI-7 B.VI-7 C. VI-10.VII-3.VIII-2 & VIII-3 W/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/09/16 1p
- 8010220099 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D © Division of Licensing 80/09/19 28pp
- 8010010719 Forwards info re SEP Topic 3-12.on environ qualification of electrical equipment, supplementing 800325 & 0610 submittals Addl info will be provided prior to 801101 Encls available in Central Files only.

 WHITE
- 8010020376 Forwards nonproprietary version of input listing of RELAP4-FLOOD input & nodalization diagram for RELAP4-FLOOD input re environ qualification of electrical equipment WHITE, L D Rochester Qas & Electric Corp 80/09/25 12pp
- 8010030375 Responds to NRC 800815 ltr re exposure of fuel assemblies & control rods during transfer while in refueling mode Revised Tach 80ecs will be revised to include min level requirement WHITE.L D Rochester Gas & Electric Corp 80/09/26 ip
- 9010150530 Bummary of 800704 meeting w/utils, B&W & NUS Corp re proposed upgrade mode to auxiliary feedwater sys Apanda & 800808 memo enci VISSING, G B. Operating Reactors Branch 4, 80/07/30 48pp
- --8010190544 Submits analysis & recommendations re plants w/o seism(call) qualified auxiliary feedwater sys Seismically induced core malt due to loss of decay heat removal could be as much as six times more likely than WASH-1400 estimates

 MATTBUN-R J Division of Safety Technology 80/08/08 22pp
- 80:01:00385 Notification of 80:1007 meeting w/util in Betheada, MD to discuss util review of equipment environ qualification rept NOWICKI, S. J. Operating Reactors Branch 5, 80:10:103 2pp
- 8010280420 Forwards comments on selected topics in preliminary clarification of TMI action plan requirements MAIER: J. E. Rochester Gas & Electric Corp. 80/10/22 6pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004040077 Forwards Waste Packaging Insp Rept 80-05 on 800319 No moncomplishes noted 8TOHR: J.P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/04/14. 2pp.
- --B0060400B2 Waste Packaging Insp Rept 80-05 on 800319. No noncompliants noted, Major areas inspected, shipping paper requirements, DDT placarding requirements, radiation levels, removable contamination & prohibited articles of contents POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/04. App
- 80:0020:13 Responds to IE Bulletin 79-14 re seismic analyses for as-built safety-related piping sys. Reports results of analysis for various piping configurations & support. WHITE: L D Rochester Gas & Electric Corp 80/08/25 2pp
- 8010020095 Responds to IE Bulletin 80-19 Mercury-wetted relays are not installed or planned for use in reactor protection sys. HHITE.L.D. Rochester Gas & Electric Corp. 80/08/27 ip
- 8010230112 Forwards IE Immp Rept 50-244/80-09 on 800609-0731 No nancompliance noted. BRUNNER,E.U. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/27, 2pp

ŧ į

11

1

, |

1 1

4.1

٠,

1

, 1

" //ji "] ii

- --8010230113 IE Insp Rept 50-244/80-09 on 800409-0731 No noncompliance noted. Major areas inspected operational safety verification, observation of physical security & qualification of training staff KISTER, H B , JOHNSTON, D F Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/08/26 70p
- 80:00:0825 Responds to IE Bulletin 80-15 re loss of emergency notification sys Emergency sys powered by 48-volt dc Procedure change initiated to require 1-hr notification One manhour expended on bulletin WHITE, L. D. Rochester Oas & Electric Corp 80:08/29 2pp
- 8010010788 Responds to IE Bulletin 80-18 re min flow through centrifugal charging pumps Station does not utilize centrifugal charging pumps
 HHITE, L. D. Rochester Gas & Electric Curp. 80/09/04. 1p
- 8010010666 Responds to IE Bulletin 79-13-Revision 2-re-cracking in feadwater sys piping volumetric & visual examinations of various feedwater piping performed & no recordable indications found WHITE, L D Rochester Oas & Electric Corp 80/09/05 2pp
- 8010010B31 Responds to IE Bulletin 80-20 Westinghouse Type H-2 control switches are used in safety-related applications Proposed wiring change to monitor neutral contact is being processed Continuity tests will be performed every 31 days WHITE,L D. Rochester Oas & Electric Corp. 80/09/10 2pp
- 8010270453 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested.

 ORIER, B H Region 1. Philadelphia. Office of the Director 80/09/26. 19
- BO10300637 Updates B00603 response to IE Bulletin B0-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sye (CVCB) Holdup Tanks." Comprehensive review of CVCB holdup sys design undertaken WHITE:L D Rochester Oas & Electric Corp B0/09/26 ip
- 8010240171 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required ORIER, B.H. Region 1. Philadelphia. Office of the Director 80/10/02 ip.
- 8010240052 Ack receipt of 800917 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/80-08 BRUNNER.E.J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/10/03 ip.
- --8010240055 Responds to NRC 800826 ltr re violations noted in IE Insp Rept 50-244/80-08. Corrective actions, control of engineering documents revised & directive issued re method of voiding incorrect log entries HHITE/L.D. Rochester Oas & Electric Corp 80/09/17. 3pp
- 8010240058 Forwards IE Insp Rept 80-244/80-08 on 800602-05 & notice of violation.
 BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/24 2pp.
- --8010240062 Notice of violation from insp on 800602-05.
 * Region 1, Philadelphia, Office of the Director 80/08/25 ip.
- --8010240044 IE Insp Rept 50-244/80-08 on 800402-05 Noncompliance noted: failure to provide timely as-built info to control room k failure to follow written procedure re making corrections on control room logs.

 NAPUDA.O , SIMONETTI.O , WIQQINS.J Region 1, Philadelphia, Office of the Director. 80/08/25 1ipp.
- 8010280219 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested ORIER, B. H. Region 1. Philadelphia, Office of the Director. 80/10/10. ip.
- B010310373 Notifies that test sleeves will be installed in steam generator tubes following completion of eddy current insparound B01114, Test sleeves part of overall program for alternative repair technique.

 WHITE:L.D. Rochester Gas & Electric Corp. 80/10/27, 1p.
- R. Periodic operating reports & related correspondence
- 8010230377 Forwards munthly operating rept for Bept 1980. SNOW, B. A. Rochester Oas & Electric Corp. 80/10/09. 1p.

- --8010230392 Monthly operating rept for Sept 1980
 MCNAMARA,A E Rochester Gas & Electric Corp 80/10/06 5pp.
- B Reportable occurrences, LERs & related correspondence
- 80:0050275 Forwards LER 80-007/03L-0 WHITE, L D Rochester Cas & Electric Corp 80/09/29 ip
- --8010060285 LER 80-007/03L-0 on 800829, controller TC-402R for Channel II did not respond to change in input Caused by faulty main amplifier bridge assembly & low limit transmitter Controller replaced & calibr EDOAR, C Rochester Oas & Electric Corp 80/09/29 ip
- 8010140477 Forwards LER 80-008/03L-0 WHITE, L. D Rochester Gas & Electric Corp 80/10/07 ip
- ~-8010140482 LER 80-008/03L-D on 800910, during PT-12 2 test for B emergency generator, bus 16 breaker did not close Caused by guide pin split end opening & binding control relay antipump release lever Split end closed EDOAR, C Rochester Gas & Electric Corp. 80/10/07. 1p

V Operator Examinations

8010160476 Submits plans, schedules & commitments in response to 800731 ltr re shift staffing interim criteria Will comply w/shift staffing criteria by 820701 Plans established for required licensed personnel.

WHITE, L D Rochester Gas & Electric Corp. 80/10/13 4pp.

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1
F. Security, medical, emergency & fire protection plans

BO1006030Z Forwards technical evaluation justifying adequacy of auxiliary boiler room concrete block wall protection to emergency diesel generator in event of explosion Requests NRC concurrence Supporting documentation encl. COUNBIL. H O Northeast Nuclear Energy Co (subs of Northeast Utilities). 80/09/25. 12pp

O Adjudicatory correspondence

- 8010020251 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment. Bubmittal of info required by 801101 CRUTCHFIELD.D. Operating Reactors Branch 5 80/08/29 2pp
- --8010020263 Order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT.D 0. Division of Licensing. 80/08/29 App.
- 8010170030 Forwards order confirming util commmitments to implement action re IE Bulletin 80-17
 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/10/02. ip.
- --B010170036 Order confirming util commitments to implement action re IE Bulletin 80-17 BTELLO,V. Office of Inspection & Enforcement, Office of the Director, B0/10/02 7pp.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- B010170319 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BNR Scram Sys "
 STAMPELOS, J. YOUNG, O. ZUKOR, D. ACR8 Advisory Committee on Reactor Bafeguards B0/08/08 1p.
- --B010170333 Interim preliminary draft rept to ACRB, "Review of Recent Haifunctions of BMR Scram Sys." # ACRS - Advisory Committee on Reactor Safeguards B0/08/08 119ps
- P. Operating license stage documents & correspondence
- 8010010747 Forwards SEP Technical Evaluation Topic VIII-2, "Emergancy Generators," as input to integrated safety assessment.
 Evaluation compares as-built facility design against NRC criteria.
 CRUTCHFIELD,D Operating Reactors Branch 5 80/08/20, 2pp.

- --8010010757 SEP Technical Evivation Topic VIII-2, "Emergency Generators for Milistone i"

 * Operating Reactors Branch 5. 80/08/20 11pp
- 0010100058 Advises of acceptable response to NRC 791109 ltr re ECCS evaluation models dealing w/evel cladding swelling & incidence of rupture. No further action necessary CRUICHFIELD. Operating Reactors Branch 5 80/09/11. 2pp.
- 8010090488 Forwards responses to 800623 itr concerning proposed design of post-accident sampling & analysis sys for facilities Requirement for obtaining pressurized samples can be CRUICHFIELD, D. Operating Reactors Branch 5 80/09/17 opp
- 8010220099 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EIBERHUT.D.O Division of Licensing 80/09/19. 28pp
- B010240051 Responds to NRC 800909 request re ultrasonic test monitoring of scram discharge vol Portable test monitoring of discharge vol increased to once per shift-w/no less than 6-h between surveillance COUNBIL. W O. Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/09/19. 2pp.
- 8010020504 Forwards 800702 NPDE8 renewal permit & Bections 316(a) & 316(b) approvals, issued 800611, to indicate util compliance w/state & federal statutes & regulations under Glean Hater Act of 1977 administered by GT Dept of Environ Protection COUNSIL.H Q. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL.H.Q. Northeast Utilities. 80/09/22. 31pp
- 8010080397 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys CRUTCHFIELD.D Operating Reactors Branch 5. 80/05/24 3pp
- 8010230177 Responds to 800926 request re intent to install permanent ultrasonic monitoring sys on scram discharge vol Installation will occur prior to returning to power operation following refueling outage COUNSIL.W C., LEE,W.F. Northeast Nuclear Energy Co (subs of Northeast Utilities). 80/09/26 1p
- 8010080444 Forwards application for amend of License DPR-21, incorporating revisions to Tech Space to permit facility to return to full power operation following seventh refueling outage scheduled for 801004, CDUNBILINO, FEE,W 9 Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/09/30, 3pp.
- --B0100B0447 Application for smend of License DPR-21, incorporating revisions to Tech Specs to permit facility to return to full power operation following seventh refueling outage schedule for B01004.

 ** Northeast Nuclear Energy Co. {qubs. of Northeast Utilities} 80/09/30. 2pp.
- 3010080459 Proposed changes to Tech Specs 3 7. limiting condition for operation & Tech Specs 4.7. surveillance requirements, for containment sqs.

 * Northeast Nuclear Energy Co. (qubs. of Northeast Utilities). 80/09/30 4pp.
- O10060319 Forwards OE 800929 ltr summarizing analysis critical array formation in response to NO Counsil 800904 ltr to DM Crutchfield proposing Tach 8psc changes to facilitate off-loading & reloading of fuel bundles w/o neutron sources COUNBIL.N.O., FEE.N.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/10/01. ip
- 10100324 Bubmits comments on TMI action plan requirements. NRC should coept alternative means of training for mitigating core mage Util will submit valve test dats by Bio701 & plant ecific analyses following completion of program.

 UNBILM.9., FEE.H.F. Connecticut Yanter Atomic Power Co.

 JNBILM.9. Northeast Nuclear Energy Co. (subs of Northeast Lifties). 80/10/01. 6pp.
- 0200472 Provides info re environ qualification of electrical guipment as partial fulfillment of license amend issued on 100919. Summaries of methodology used, final radiation data & versire drawings enci.
 OWNSIL. N O. Connecticut Yenkes Atomic Power Co. COUNSIL. N. Gothest Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, M. Q

- -B010200482 "Heating Ventilation & Air Conditioning Turbine Bldg: Mezzanine Floor Plan: "as-built <u>* Ebasic Bervices:</u> Inc. (subs. of Enserch Corp.), 6797
- --80102004B3 "Heating Ventilation & Air Conditioning Turbine Bidg. Oround Floor Plan," as-built 4 Ebasco Bervices, Inc (subs. of Enserch Corp.) 6797. 76/07/15 1p
- ~~8010200488 "General Arrangement Emergency Gas Turbine Generator," as-built # Ebasco Services, Inc (subs of Enserch Corp) 6797, 68/11/26 ip
- -8010200492 "Heating Ventilation & Air Conditioning Flow Diagram, Surk."
 Bidg, Control Room & Svc Area, " as-built
 # Ebasco Bervices, Inc (subs of Enserch Corp) 6797,
- --8010200494 "Intake Structure Screens & Miscellaneous Steel," as-built # Ebasco Services, Inc. (subs. of Enserch Corp.) 7043 48/11/23 1p.
- --8010200497 "Lighting One-Line & Cabinet Diagrams," as-built * Ebasco Bervices, Inc. (subs. of Enserch Corp.) 7043 79/11/30
- --8010230502 "4160 Volt & 480 Volt Switchgear, One-Line Diagram,"
 4x-built Sheet 2
 4 Ebasco Bervices, Inc. (subs. of Enserch Corp.), 79/10/18 |
- -8010200507 "480 Volt Miscellaneous Auxiliary Motor Control Cirs, One-Line Diagram," as-built + Ebasco Services, Inc. (subs. of Enserch Corp.), 7043
- ---8010200509 "480 Valt Turbine Bldg Hotor Cantrol Ctrs.One-Line Wiring Diagram " Bheet 2
 * Ebase Services, Inc. (subs. of Enserch Corp.), 7043 79/07/02
- 8010240255 Forwards responses to NRC 770602 request for info re BEP Topic IV-1, Organic Matls & Post-Accident Chemistry Includes info re protective coating sys inside containment, QA provisions & miscellaneous coating matls COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/10 5pp.
- B010300452 Application for emend to License DPR-21 revising integrated containment leak rate testing Tech Specs to be consistent w/current BHR 815, NUREG-0123, Revision 2, COUNBIL. W. On theset Utilities. B0/10/15 4pp
- ---8010300453 Revised Tech Specs Pages 3/4 7-5 through 3/4 7-8 for lice**

 amend re integrated lesk rate testing

 * Northeast Utilities 80/10/31 5pp
- 8010300419 Application to amend License DPR-21, incorporating Tech Special changes re scram discharge vol rod block functions to vent & drain valve surveillance requirements. Request is in response to NRC 800707 ltr to all BWRs Class III amend fee encl COUNSIL.N O. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 80/10/16 3pp
- --B010300422 Proposed Tech Specs 3.2 & 4 2 adding scram discharge yells block functions for add1 limiting conditions of operation & yent & drain valve surveillance requirements for increased reliability * Northeast Nuclear Energy Co. (subs. of Northeast Utilities) SO/10/16. 9pp
- 8010310326 Forwards comments re development of design & operational criteria for BMR scram discharge sys.Re-evaluation of scram discharge sys will be provided by 801215. COUNSIL.W C. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 80/10/24 Spp
- --8010310332 "BWR Scram Discharge Sys."

 Northeast Nuclear Energy Co (subs of Northeast Utilities).
 80/10/30 4pp

The second of the community of the second of

, , ,

1 3

> ri

.

The control of the co

- Inspection reports, IE Bulletins & correspondence
- 3010020276 Responds to IE Bulletin 80-17. Suppl 1 re failure of control rods to fully insert during scram Until permanent alarm sys installed, current daily surveillance requirements are adequate Util expended 20 mandays on bulletin COUNSIL. If 0 . FEE. IF Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/15 3pp
- 3010020756 Responds to IE Bulletin 80-15 Emergency notification sys powered by onsite PBX sys Bulletin investigation required 32 manhours CQUNBIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities) FEE,W F Northeast Utilities 80/08/25 3pp

3010030128 Forwards IE Mgt Meeting Repts 50-245/80-14 & 50-336/80-15 on 800805 Immediate Action Ltr 80-28 issued, based on results of discussion
ORIER, B, H Region 1, Philadelphia, Office of the Diractor,
80/08/26 2pp

- --B010030132 IE Mgt Heeting Repts 50-245/80-14 & 50-336/80-15 on 800805 Details withheld (ref 100FR2 790). MARTIN, W O , DEVLIN, J W , BHEPPARD, R E Region 1, Philadelphia, Bafeguards Branch 60/08/25 ip
- 1010030313 Responds to IE Bulletin 80-19 No mercury-wetted relays in use at facilities CDUNBIL,N 0 . LEE,M F Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/08/26 ip
- OCCOCOCOCA Responds to IE Bulletin BC-17. Suppl 3 re partial loss of control air sys pressure which could cause partial opening of scram outlet valves w/o rod motion Procedures implemented which satisfy requirements of bulletin CCOUNSIL. W O . FEE. W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/27. App
- 010020760 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts S0-245/80-06 & S0-336/80-04 Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/27 ip.
- -8010020763 Responds to NRC 800626 itr re violations noted in IE Insp Repts 50-245/80-06 & 50-336/80-04. Corrective actions, hanger number 413082 hydraulic snubber will be replaced. Item C details withheld (ref 10CFR2 790) CDUMBIL, W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/22 App.
- -8010020745 Forwards IE Insp Repts 50-245/80-06 & 50-336/80-04 on 800330-0503 & notice of violation.App A & B. App B details withheld (ref 10CFR2 790)
 BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/26 2pp.
- -8010020767 Notice of violation. App A & B. from insp on 800330-0503. App B details withheld (ref 10CFR2 790).

 ** Region 1, Philadelphia: Office of the Director. 80/06/03 2pp.
- -8010020771 IE Insp Repts 50-245/80-06 & 50-336/80-04 on 800330-0503 Noncompliance noted failure to wear dosimstry in accordance w/health physics procedures to meet snubber surveillance requirements & to comply w/security procedures. KEIMIO.R.R Region i. Philadelphia, Reactor Operations Nuclear Support Brench SHEDLOSKY.J T. ZIMMERMAN.R.P. Region i. Philadelphia, Defice of the Director 80/06/03 13pp.
- Di0020175 Advises that actions outlined in util 800811 ltr are in accordance w/Licensee Mecting IAL-80-28 Documentation recontrol, accounting & security procedures exempt from disclosure (ref 100FR2 770)
 GRIER. B. H. Region 1, Philadelphia, Office of the Director disclosur. QRIER.B.H Re
- Di0010713 Responds to IE Bulletion GO-17.Suppl 1.re failure of control rods to fully insert during scram at BWR Conceptual design changes for scram discharge vol & vent sys are being CGUNBIL, W. G., FEE, W. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/09/01, 3pp
- D10010078 Ack receipt of 800808 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-245/80-08.

 GRIER, B. H. Region i, Philadelphia, Office of the Director.
 80/09/04 ip

- -8010010084 Responds to NRC 800715 ltr re violations noted in IE Insp Rept 30-245/80-08 Corrective actions referenced valve checkoff list revised to show 1-10-12 valve locked in open position Surveillance form SP 1040-14 revised COUNSIL.N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/08 3pp
- --B010010089 Forwards IE Insp Rept 50-245/80-08 on 800602-06 & notice of BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/07/15 2pp
- --8010010095 Notice of violetion from insp on 800602-06 * Region 1, Philadelphia, Office of the Director. 80/07/14 1p
- --B010010100 IE Insp Rept 50-245/B0-08 on 800602-06 Noncompliance noted failure to maintain records of safety-related surveillance a perform inservice insp of referenced valves in accordance u/procedural instructions OREEMMAN, E Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BLUMBERO, N J. BHAUB, E T. Region 1, Philadelphia, Office of the Director 80/07/14 11pp
- 8010220021 Responds to IE Bulletin 80-20, "Failures of Westinghouse Tupe H-2 Bpring Return to Neutral Control Switches" Epecified switches are used in containment air circulation fans, svc water pumps & charging pumps (QUNSIL.H 0, FEE,H F Connecticut Yankee Atomic Power Co. COUNSIL.N 0 Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/15 2pp.
- HO10240196 Ack receipt of 800B22 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-245/80-09 & 50-336/80-06 MARTIN.W.O Region 1, Philadelphia, Safeguards Branch. 80/09/19.
- --8010240202 Responds to NRC 800801 ltr re violations noted in IE Insp Repts 50-245/80-09 & 50-334/80-06. Corrective actions. withheld (ref 100FR2 790). CCUNSILL W 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities). 80/08/22 2pp.
- --8010240205 Forwards IE Insp Repts 50-245/80-09 & 50-336/80-06 & on 800623-27 & 30 & 0701-03 & notice of violation Notice of violation withheld (ref 10CFR2. 790)
 MARTIN, N Q Region 1, Philadelphia, Bafeguards Branch 80/08/01
- --B010240217 IE Insp Repts 30-245/80-07 & 50-336/80-06 on B00623-27 & 30 & 0701-03 Nancompliance noted two doors found unsecured & two licensee vehicles found unlocked Details withheld (ref 10CFR2 7901 BHEPPARD, R. E., MCKEOHN, L. M. Region i, Philadelphia, Office of the Director. PEVLIN, J. W. Region i, Philadelphia, Safeguards Branch. 80/09/24 2pp.
- 8010170030 Forwards order confirming util commmitments to implement action re IE Bulletin 80-17.
 STELLO.V. Office of Inspection & Enforcement, Office of the Director, 80/10/02. ip.
- --8010170036 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO,V. Office of Inspection & Enforcement, Office of the Director 80/10/02, 7pp.
- 8010240128 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required.

 GRIER, B H Region 1, Philadelphia, Office of the Director, 80/10/02. 1p.
- 8010280173 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested QRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/10. 1p.
- 8010310364 Forwards BHR owners group design & operational criteria for scram discharge sys, in response to NRC 801001 request re IE Bullstin 80-17 Criteria assure safe & reliable operation of sys. COUNSIL,W G. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/10/24 7pp

R Pariodic operating reports & related correspondence

- 8010040270 Responds to NRC 800909 ltr requesting verfication of info on radioactive effluents Forwards revised semiannual effluent & waste disposal repts for 1978 GOUNSIL.H O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/09/26. ip.
- --8010060275 Revised "Bemiannual Effluent & Waste Disposal Rept for 1978," * Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/30. 2pp.
- --8010060278 Rayised "Semiannual Effluent & Wasta Disposal Rept for 1978."

 * Northeast Nuclear Energy Co (subs. of Northeast Utilities).
 B0/07/30. 5pp.
- 8010210426 Forwards monthly operating rept for Bept 1980, MRD02KA:E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/10/14. 1p.
- --8010210430 Monthly operating rapt for Sept 1980. HARRANI Q. Arkaness Power & Light Co. 80/10/01. App
- 8. Reportable occurrences: LERs & related correspondence
- 8010090325 Forwards LER 80-013/03L-0 MRDCZKA,E.J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/10/03 2pp.
- ---B010090335 LER B0-013/03L-0. on 800905 during drywell high pressure screw & containment isolation functional & calibr test, pressure awitch 2206-16218 tripped outside allowable band. Caused by setpoint drift. Switch tested & returned to svc. B191ARELLIM J Northeast Nuclear Energy Co (subs. of Northeast Utilities). B0/10/03 1p
- 8010090373 RO, on 800812, third quarter sample of dysters from within 500 ft of discharge exceeded control station average activities by greater than factor of 10 Caused by oyster trays located in quarry boundaries w/o near-field dilution.

 MRDG2KA.E.J. Northeast Utilities. 80/10/03 3pp.
- 8010090449 RO ETH-NR/D0-245/50-336/80-i:on 800812, excessive levels of Co-50, Co-60 & Ag-110m were observed in third quarter sample of dysters Caused by increased plant liquid discharges. Tech Specs will be revised.

 MRDCZKA, E. J. Northeast Utilities. 80/10/03. 3pp
- 8010140439 Forwards LER 80-013/03L-0. MRDCEKA, E. J. Northeast Utilities. 80/10/03, 2pj.
- ---8010140490 LER 80-013/03L-0; on 900908, while performing surveillance, drywell high pressure scram & containment isolation functional & calibr test-pressure switch 2206-16219 tripped outside allowable hand. Caused by instrument drift.

 BIGIARELLI, M. J. Northeast Utilities, 80/10/03, 1p.
- 8010130839 RD-BO-14/ip:on 801003, local leat rate surveillance testing program identified two MSIVs that could not meet acceptable leakage criteria. Cause not determined. Investigation in progress.

 MHDCZKALE J. Northeast Utilities. 80/10/06, 2pp.
- 8010230422 Forwards LER 80-014/01T-0. MRDCZKA: E. J. Northeast Utilities. 80/10/16 1p.
- --B010230428 LER B0-014/017-0: on B01005, during local leak rate surveillance testing two MSIVs were identified which could not meet required leak rate, Cause not determined.
 B101ARELL1.M. U. Northeast Utilities. 80/10/16
- 8010240407 RD ETB-NR/80-245/80-02:on 800922, offges hydrogen enalyzer weekly calibr chack surveillance found not performed within required time interval Caused by scheduling oversight. Technicians reminded to be cognizent of requirements. MRGGZKA, E. J. Northeast Utilities. 80/10/21, 2sp.
- 8010280386 RG ETS-NR/50-245/80-02:on 800922, at steady state power, discovered off-gas hydrogen analyzer weekly calibr check surveillance had not been performed within required interval Caused by scheduling oversight.

 MR0CZKA-E, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/10/21. ip.

- 8010280387 R0 80-16/1P: on 801023 results of visual & ultrasonic examinations of jet pump beams per IE Bulletin 80-07, indicated one rejectable beam & four beams of marginal condition frobably caused by stress corrosion cracking MRCCZMA.E J. Northeast Nuclear Energy Co (subs of Northeast Utilities), 80/10/24. Ip
- 8010300455 RO-80-16/1P: on 801023 results of visual & ultrasonic examinations of jet pump beams indicated one beam rejectable & four beams of marginal condition. Caused by intergranular stress corrosion cracking MROCZKA: E. J. Northeast Utilities 80/10/24. 2pp
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- O. Adjudicatory correspondence
- 8010210510 Order dunying NY State Energy Ofc & Citizens Committee for Protection of Environ petitions to review ALAB-405 & ALAB-561 re selimic issues. Notion to strike portions of NRC answer to petitions denied.

 CHILK, S. J. Office of the Secretary of the Commission. BO/10/17, 200.
- P Operating license stage documents & correspondence
- 8010010154 Ack response to NRC 791109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture.
 Response acceptable & no further action necessary.
 VAROA.S.A Operating Reactors Branch 1 80/09/12 2pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also enci. EIBENHUT.D 0. Division of Licensing. 80/09/19 28pp.
- 8010090236 Forwards request for add1 info re GA program re-evaluation Items addressed include extension of GA program to all items affecting safety.organizational independence & staffing & qualification requirements VARQA.8.A Operating Reactors Branch 1, 80/07/23 Spp.
- 8010150143 Summary of 800828 & 29 meeting w/BNL re progress on physics technical assistance program Topic outline encl DUNENFELD, M. Core Performance Branch. 80/09/29. 8pp.
- B010070605 Responds to NRC 800815 ltr re refueling procedures & Tech Specs. Facility complies w/new requirement re plant refueling procedures. Util will propose changes to Tech Specs to maintain consistency by 801107 ZARAKAS, P Consolidated Edison Co. of New York. 80/09/30 [p.
- BO101604B5 Bubmits summary of 800925 meeting w/NRC, Comm Ed, FABNY k Meetinghouse in Chicago, IL re schedule for Zion/Indian Point near-site study per 8A Varga request Requests NRC concurrence of suggested data for add meeting in Dec 1980. NAUGHTON, W. F. Commonwealth Edison Co. 80/10/06 5pp
- 8010100301 Forwards addl info re planned transition to LOPAR fuel Proprietary info withheld (ref 10CFR2 790) HIESEMARN, R. A. Consolidated Edison Co. of New York. 80/10/07
- 8010280272 Forwards request for add1 info re review of proposed testing program for facility.

 VARGA, B. A. Operating Reactors Branch 1, 80/10/14. 7pp.
- 8010240510 Supple 800922 ltr re manual sys level actuation features fall engineered safeguards sys Installation of pushbuttons will provide capability to initiate phase 8 function Mod contacts to be installed in reset relay circuitry ZARAKAB, P. Consolidated Edizon Co of New York. 80/10/17. Rpp.
- Q. Inspection reports: IE Bullstins & correspondence
- 8010030113 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/80-08, MARTIN, M. O. Region 1, Philadelphia, Safeguards Branch. 80/08/27. is.
- --8010030133 Responds to NRC 800708 itr re violations noted in IE into Rept 50-247/80-08. Corrective actions: withheld (ref 10CFR2, 770).
 ZARAKAB, 2 Consolidated Edison Co, of New York 80/08/04. If-
- --8010030138 IE Insp Rept 50-247/80-08 on 800518-23 & notice of violation. Notice withheld (ref 100FR2 790). MARTIN. W. O. Region 1, Philadelphia, Safeguards Branch. 80/07/08 Exp.

- --8010030142 IE Insp Rept 50-247/80-08 on 800518-23 Details withheld (ref 10CFR2 790) DEVLIN.J W. BAILEY.R.J Region 1. Philadelphia, Bafeguards Branch 80/07/01 ip
- B010010692 Responds to IE Bulletin B0-19 Unit 2 has no mercury-wetted relays in reactor protection sys Unit 1 is defueled & bulletin is not applicable ZARAKABJP Consolidated Edison Co of New York B0/08/30 ip
- 8010240127 Forwards IE Insp Rept 50-247/80-11 on 800730-0801. No noncompliance noted BRUNNERRE J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/02 2pp
- --8010240133 IE Insp Rept 50-247/80-11 on 800730-0801. No noncompliance noted. Major areas inspected. onsite & offsite routine & emergency mgt & technical resources capability & training & qualifications of personnel RRUNNER.E. J. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch. KIGTER.H B. REBELOWSKI, T. E. Region 1, Philadelphia. Office of the Director 80/08/29 11pp
- 8010240142 Forwards IE Insp Rept 50-247/80-07 on 800511-0628.No noncompliance noted, Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/09/03, 2pp
- --B01024014B IE Insp Rept 30-247/80-07 on 800511-062B No noncompliance noted Major areas inspacted; physical security, licenses implementation of strike plans & accident mitigation features meeting.

 KISTER.H. Region I, Philadelphia, Reactor Operations Nuclear Support Branch. REBELOHSKI.T., KENNY.T Region I, Philadelphia, Office of the Director 80/08/26 17pp
- 8010220049 Forwards response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Raturn to Neutral Control Builtches," Bulletin did not apply to Unit 1, Required testing completed at Unit 2 ZARAKASIP. Consolidated Edison Co. of New York 80/09/15 Spp.
- 8010300654 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Yaru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture," Unit 2 charging pumps are positive displacement, not centrifugal pumps IARAKAS, P. Consolidated Edison Co of New York 80/09/22, 2pp
- B010270217 Submits final response to IE Suiletins 78-12.78-12A & 78-12B, "Atypical Held Matl in Reactor Pressure Vessel Helds." Wastinghouse has filed proprietary C-E 770608 rept W/NRC addressing requested info.
 ZARAKAS.P. Consolidated Edison Co. of New York. 80/09/23, 2pp.
- PO10270434 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested. ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/09/26. 1p.
- 1010310491 Updates 800707 response to IE Bulletin 80-11. "Masonry Hall Design." Forwards lists of mechanical & electrical equipment attached to & in vicinity of surveyed walls. ZARAKAS,P. Consolidated Edison Co. of New York. 80/09/30. 8pp
- 1010240137 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required. GRIER, B.H. Region i, Philadelphia, Office of the Director. 80/10/02. ip
- 010280237 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Solting." No specific action or response requested, GRIERS H. Region 1, Philadelphia. Office of the Director. 80/10/10 ip.
- . Pariadic operating reports & related correspondence
- 010200310 Forwards changes, tasts & experiments for 1979 for Indian Point 2.Requirement is not applicable to Indian Point 1. IARAKAS.P. Consolidated Edison Co. of New York. 80/09/29. 22pp.
- DIGISO487 Forwards "Indian Point Generating station Entrainment & Near Field River Studies," 1978 annual rept. Affidavit of syc encl.
- ZARAKAS: P. Consolidated Edison Co. of New York. 80/10/09 3pp.
- -B010150508 "Indian Point Generating Station Entrainment & Near Field River Studies." 1978 annual rept.

 * Ecological Analysts: Inc. CON84H. 80/05/31. 400pp.

- 8010150447 Forwards spacies code list & info re circulating water temp. river water discharge & gross electrical output per Section 401 Certification for Sept 1980 MDNTLW A Consolidated Edison Co of New York 80/10/10. 18pp.
- 8010280393 Forwards monthly operating rept for Sept 1980
 ZARAKAB,P Consolidated Edison Co of New York, 80/10/14, 1p.
- --8010280395 Monthly operating rept for Sept 1980 EICH,E Consolidated Edison Co. of New York 80/10/08. Spp.
- 8010240425 Forwards tabulation of daily records of fish collections for Bapt 1980, Daily species code list, count & total weight encl. ZARAKAS.P. Commonwealth Edison Co. 80/10/15 éps.
- 8. Reportable occurrences, LERs & related correspondence
- 8010010519 RO 80-011/01 on 800924, containment spray pump switches placed in pull-out position to prevent inadvertent actuation during containment entry, Procedure has been revised to delete requirement to place switches in pull-out position. MONTI, H. A. Consolidated Edison Co. of New York. 80/09/23. 2pp.
- B010150493 Forwards LER 80-011/01T-0.
 ZARAKAS, P Consolidated Edison Co of New York. B0/10/08. 1p
- --8010150498 LER 80-011/01T-0 on 800924, both containment spray pump control switches placed in pull-out position to prevent inadvertant spray actuation. Caused by unresolved procedure questions. Interia procedure does not require switch pullout. MAKEPEACE. J. M. Consolidated Edison Co. of New York. 80/10/08. 2pp
- 8010240391 RD 80-012-01: on 801016, conflict between plant procedures & regulatory requirements discovered Test PT-013 requires valve 1841 be closed during testing of valves 876A & B. contrary to regulations Procedure revised.

 MONTI, M. A. Consolidated Edison Co. of New York. 80/10/16. 3pp
- 8010240392 RO 80-054/01P-O on 801016, fire pump failed to start on receipt of automatic signal Bituation recurred following day. Cause of failures is undetermined.

 MIDURAH.J Public Bervice Electric & Qas Co. of New Jersey 80/10/17, 2pp.
- OGCKET 50-249 DRESDEN NUCLEAR POHER STATION, UNIT 3

 F Sacurity, medical, emergency & fire protection plans
- B010220439 Forwards IE Health Physics Appraisal Repts 50-237/80-13 & 50-249/80-17, notice of violation & significant appraisal findings. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/09/12. 6pp.
- ---8010220442 Notice of violation from health physics appraisal on 800618-0702 * Region 3. Chicago, Office of the Director. 80/08/29. 1p
- --BD10220486 IE Health Physics Appraisal Repts 50-237/80-13 & 80-249/80-17. Noncompliance noted: laundered protective clothing in clean laundry storage bins read 22,000 counts per minute.
 BCHUMACHER, M. C., PAUL, R. A., DESTMANN, M. V. Region 3, Chicago, Office of the Director. 80/08/29. 47pp.
- Q. Adjudicatory correspondence
- 8010020026 Requests reviewer to provide testimony for Contentions 2 & 3 of second amended contentions of State of IL re spent fuel pool storage. Reviewer should be identified by 800915 for 801119 hearing.

 IPPOLITO.T.A. Operating Reactors Branch 2. CRUTCHFIELD.D. Operating Reactors Branch 5. 80/09/16 1p.
- ---B010020027 Forwards State of IL second amended contentions re spent fuel pool mod. Contentions 2-7 will be subj of litigation beginning S01117, Submits schedule for preparation of testimony, OCDOARD.R. J. Hearing Branch 2. S0/09/04. 2pp.
- BOI0230229 Requests reviewer to provide testimony for Contention 5 of second amended contentions of State of IL re spent fuel pool storage. Reviewer should be identified by 800915 for 801119 hearing.

 IPPOLITO, T.A. Operating Reactors Branch 2. CRUTCHFIELD, D. Operating Reactors Branch 5. 80/09/16. ip

- 8010290330 Forwards addl documents per informal discovery agreement W/o ancl. FITZOIRBONS.R Isham, Lincoln & Beale 80/09/24 ip.
- B010020065 Enumerates name of util witnesses per agreement on informal discovery re ABLB 800707 memorandum & order R Anderson will be deposed on B01027, State of IL witnesses will be available during who of B01110
 BTEPTDE
- B010020740 Forwards util response to NRC technical review questions Update to 7805il licensing rept will be submitted shortly Buggests that tentative concessions for compromise be apart from formal record per rule of evidence re-settlement BTEPTOE: P Isham, Lincoln & Beale B0/09/29 2pp.
- 8010070611 Forwards listed discovery documents.W/o encl FITZOIBBONS.R Commissioners 80/09/30 1p.
- 8010070023 Notice of 801119-21 hearing in Morris, IL re groposed OL emends ABLB will be composed of JF Wolfr, chairman & LW Little & FJ Remitch, mambers, Limited appearance statements welcome WOLF, JF Atomic Bafety and Licensing Spard Panel, 80/10/01 2pp
- 8010090054 Informs of util intent to pull empty rack out of spent fuel pool to determine feartbility of decontamination using hydrolasing techniques Related correspondence STEFTOE: PP Isham: Lincoln & Beale 80/10/02 2pp
- 8010200289 Forwards order confirming util commitments to implement action re IE Bulletin 80-17.
 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 19
- ---B010200297 Order confirming util commitments to implement action re IE BUlletin 80-17. STELLO.V Office of Inspection & Enforcement, Office of the Director 80/10/02. 7pp
- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17. "Failure of 76 of 185 Control Rode to Fully Insert During Scram at SWR "
 BTELLO, U. Office of Inspection & Enforcement, Office of the Director 80/10/02 2pp.
- BO10140511 Lists witnesses who will testify at proceeding Listed individuals will be made available for depositions. QUDDARD,R.J. Hearing Branch 2 80/10/07. 2pp.
- 8010160032 Notice of appearance in proceeding.Certificate of Syc encl. BCHERR, B J. Natural Resources Defense Council. 80/10/10 3pp
- 80101A0778 Order directing licensee & NRC to inform ABLB by 801031 whether there is intention to pursue application If intention exists: NRC shall inform ABLB of estimated dates of safety evaluation & EIS publication MILHOLLIN.G.L. Atomic Safety and Licensing Board Panel 80/10/14
- 8010210523 Forwards add1 documents pursuant to informal discovery agreement Documents include Special Rept 28 & subsequent submittals & addendums re handling of spent fuel shipping cask & OA dept audits. M/o encis.
 FITZOIBBONS:R. Isham, Lincoln & Beale. 80/10/15 ip.
- BO10230387 Forwards list of requested documents re internal audits done by Leckenby, IE actions for GA/GC program & purchase orders between various contractors & subcontractors, Related correspondence
 MURRAYM, J Illinois, State of. 80/10/16 2pp.
- 8010230464 Forwards addl documents pursuant to informal discovery agreement per 801016 request Documents are specific portions of Comm Ed QA manual re 10CFR21 reporting procedures. Related correspondence.

 STEPTOE, P Isham, Lincoln & Reele, 80/10/17 2pp
- 3010280535 Notice of appearance in proceedings.
 STEPTOE,P.P. Commonwealth Edison Co. STEPTOE,P.P. Isham, Lincoln & Beale, 80/10/23 ip
- B0102703B5 Request for hearing re 800717 orders for mod of licenses requiring certain info on environ qualification of safety—related equipment in response to IE Bulletin 77-01B, Urges suspension of effectiveness of orders, M/Certificate of Svc. STEFTOE, P.P. Commonwealth Edison Co. BTEPTOE, P.P. Isham, Lincoln & Beale 80/10/23. Spp.

- J Insurance & indemnity information
- 8010280613 Requests Endorsement 108 to Policy NF-43 & Endorsement 87 to Policy NF-22 DINITZ.I Utility Finance Branch (formerly Antitrust & Indennity) 80/07/24 p
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BO10170319 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Scram Sys" BTAMPELOS.J., YOUNO, &., ZUKOR.D ACRS -- Advisory Committee on Reactor Safeguards B0/08/08 1p
- --8010170333 Interim preliminary draft rept to ACRS, "Review of Recist Malfunctions of BMR Scram Sys"

 + ACRS Advisory Committee on Reactor Safeguards 80/08/08
- P Operating license stage documents & correspondence
- B010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also and EIBERHUT.D O Division of Licensing 80/09/19 28pp
- 8010050012 Discusses util response to NRC 791109 ltr re portions of ECCB evaluation models Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/24. 2pp
- 8010090240 Requests addl action re NRC 780807 ltr re deficiencies in Hatch. Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys IPPOLITO. T A Operating Reactors Branch 2. 80/09/24 3pp
- 8010100361 Submits list of current qualification programs for EPR1 util equipment qualification owners group resulting from B00917 meeting. Requests info re which program best fits NRC schedule.

 LAHKEN, D.C. Commonwealth Edison Co. 80/09/24 2pp
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Pian Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly.

 REEDIC Commonwealth Edison Co 80/10/01 Spp.
- 8010070554 Forwards info & drawings re undervoltage protection in response to Questions 1.2.3,4 & 6 of NRC 800813 itr Tech Specs changes identified in Questions 5 & 7 being evaluated. JANECEK:R F Commonwealth Edison Co. 80/10/01 3pp.
- 8010130663 Ack receipt of proposal for installation of underdrain pigs sys to minimize seepage effects from unit cooling lake FIDRELLI.O Region 3. Chicago, Reactor Construction & Engineeris; Support Branch 80/10/02 ip
- --8010180669 Forwards capy of request for proposal to install underfit.
 (diverter) pipe sys for unit cooling lake north dike
 JANECEK, R F Commonwealth Edison Co 80/09/19 App
- 8010280235 Forwards QE recommendations for Tech Specs changes for flesh blassed average power range monitor scram & rod block setdown. Changes are due to NRC concern w/using total peaking factor as setdown factor for BWRs w/different fuel lengths JANECEK.R F Commonwealth Edison Co. 80/10/03 8pp
- B010240203 Forwards proposed Tech Spec changes.per NRC 800707 request Changes provide addi operational & surveillance requirements.

 JANECEK.R F Commonwealth Edison Co 80/10/14, 2pp

- --8010240210 Revised Tech Spec Pages 42,43,55,62 & new Page 614 for Dresden Units 2 & 3 & Pages 3,2/4 2-14,3 2/4,2-16,3,3/4,3-3 & 3 3/4 3-9 for Quad Cities Units 1 & 2 * Communumenth Edison Co 80/10/14 22pp
- 8010290333 Application for amend to App A Tech Specs of Licenses DPA-P & DPR-25-implementing fire protection mode by revising Sections 3 12 % 4,12 of fire protection sys Class I & III amend fees encl.

 JANECEK,R F. Gommonwealth Edison Co. 80/10/21 2pp
- ---8010290336 Proposed changes to App A Tech Space, revising Sections II & 4.12 re limiting conditions for operations & surveillance requirements of fire protection sys # Commonwealth Edison Co. 80/10/21 29pp.

٦,

And the state of t

- 8010270366 Responds to NRC 800619 ltr re loss of offsite power survey status Concludes that events reported in 791219 ltr have been misinterpreted as no instances of partial or complete power loss have been observed JANECEK.R F Commonwealth Edison Co 80/10/29 3pp
- @ Inspection reports, IE Bulletins & correspondence
- 8010210908 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unesconted access in protected areas KEPPLER.J O Region 2. Atlanta. Office of the Director. 80/09/03
- 8010300597 Forwards IE Insp Repts 50-237/80-15 & 50-249/80-19 re 800821 meeting in Chicago, IL re cooling lake dike seepage & remedial measures to preclude further seepage & effects to dike structure FIDRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/03 2pp
- --8010300600 IE Insp Repts 50-237/80-15 & 50-249/80-19 of 800821 meeting w/util in Chicago, IL re cooling lake dike seepage & ramedial measures to preclude further seepage Related correspondence & documentation encl GALLACHER, E. J. Rayion 3, Chicago, Office of the Director HAYES, D. W. Rayion 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/02 100pp
- 8010090159 Forwards add1 response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts "
 Load tests have been performed on concrete expansion anchors on all accessible safety-related piping sys
 JANECEK,R F Commonwealth Edison Co 80/09/05 17pp
- BO10200282 Forwards add1 response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Load tests performed on concrete expansion anchors on all accessible safety-related piping sys
- B010100241 Responds to 800B1B request for add1 info re IE Bulletin 79-14. "Seismic Analysis for As-Buiit Bafety-Related Piping Bys." List of sys where pips stress levels exceed one-half of ultimate math stress will be provided monthly.

 JANECEK.R F. Commonwealth Edison Co 80/09/19 2pp
- BO10100250 Submits add1 response to IE Bulletin 60-17 & Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Util will install continuous water level monitoring of scram discharge vols by 801201 JANECEK.R F Commonwealth Edison Co 80/09/19 5pp.
- 8010280155 Ack receipt of 800818 ltr providing addl info re control rod drive design contained in IE Insp Repte 50-237/80-09 & 50-249/80-09 KEPPLERJ G Region 3: Chicago, Office of the Director 80/09/23.
- --9010280163 Informs that walkdown of insert & withdrawal lines routing
- 4. Support will be performed during next extended outage Comparison will be made w/Quad Cities to verify design similarity Beismic reanalysis to be done if design differs. ABEL.J.S. Commonwealth Edison Co. 80/08/18 1p
- BO10140133 Forwards Inst of Nuclear Power Operations, "Evaluation of Dresden Nuclear Power Station." STELLO.V. Office of Inspection & Enforcement, Office of the Director. B0/09/30 ip.
- --B010140137 Forwards Inst of Nuclear Power Operations. "Evaluation of Dresden Nuclear Power Station"
 KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/09/16.
 1p.
- 30:0160226 Forwards Suppl 2 to IE Bullatin 79-018, "Environ Qualification of Class IE Equipment." No written response required.

 KEPPLER, J O Region 3, Chicago, Office of the Director. 80/09/30, ip
- ₹010200289 Forwards order confirming util commitments to implement action re IE Bulletin BO-17
 BTELLO.V. Office of Inspection & Enforcement, Office of the Biractor, 80/10/02. ip.
- -8010200297 Order confirming util commitments to implement action re IE Bulletin 80-17. BYELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/02. 7pp.

- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR "
 STELLO. Office of Inspection & Enforcement, Office of the Director 80/10/02 2pp
- 8010220139 Responds to IE Bulletin 80-17. Suppl 3 re failure of control rods to insert at BMR Procedures changed to specify that operator should manually scram reactor upon low scram air header pressure alarm RAUSCH. T J Commonwealth Edison Co 80/10/02 2pp
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. O. Region 3, Chicago: Office of the Director BO/10/02 in
- 8010270039 Forwards IE Info Notice 80-35, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER.J O Region 3, Chicago, Office of the Director 80/10/10
- BO10310140 EN-B0-050. on B01020. notification of significant enforcement action & proposed imposition of civil penalty of \$40,000 will be issued Based on inattention to licensed duties while assigned to controls at Unit 3
 BRYAN.B E . MOSELEY.N C Office of Inspection & Enforcement, Office of the Director B0/10/20 lp
- 8010290120 Forwards IE Insp Repts 50-010/80-16, 50-237/80-19 & 50-249/80-23 on 800922-26 & notice of violation Notice of violation withheld (ref 10GFR2 790).

 HIND. J A. Ragion G, Chicago, Safeguards Branch 80/10/22 2pp
- --Bolo270125 IE Insp Repts 50-010/80-16,50-237/80-17 & 50-249/80-23 on 800922-26 Noncompliance noted: failure to maintain records of proper screening documentation on contractor personnel Details withheld (ref 10CFR 790).

 BELANDER, J. L. CHRISTOFFER. 9 Region 3, Chicago, Office of the Director HIND, J.A. Region 3, Chicago, Bafeguards Branch 80/10/21 2pp
- B010310260 Ack receipt of B01006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/80-13 & 30-249/80-17 KEPPLER, J O Region 3, Chicago, Diffice of the Director B0/10/22 2pp
- --8010310267 Responde to NRC 900912 ltr re violations noted in IE Insp Repts 50-237/80-13 & 50-249/80-17. Corrective actions, training session will be conducted re operation & use of laundry monitors, REED, C Commonwealth Edison Co. 80/10/06. 13pp
- R Periodic operating reports & related correspondence
- 8010210440 Farwards monthly operating repts for Bapt 1980 8COTT,D J Commonwealth Edison Co 80/10/15 ip.
- --8010210441 Monthly operating repts for Sept 1980. GEISZKIEWICZ,8 Commonwealth Edison Co 80/10/01. 19pp.
- B Reportable occurrences, LERs & related correspondence
- 8010070176 PNO-III-80-116 on 800620, unplanned release of liquid radioactive mati to IL River occurred over past two to three was Caused by tube leak in 38 low pressure coolant injection heet exchanger BARKER.J L . BPESBARD.R L . HEIBHMAN.R.F Region 3. Chicago. Office of the Director. 80/06/20. 2pp
- 8009080200 PNO-III-80-135 on 800719, unit manually scramed from approx 5% power to acquire test data required by IE Bulletin 80-17. Water held up in one scram discharge volume & presence not indicated Caused by stuck vacuum breaker in vent piping REIMANN.F. W. SPESSARD.R.L. HEIBHMAN.R.F Region 3. Chicago, Office of the Director. 80/07/21, 2pp.
- B010090136 PNO-III-80-169 on 800904, reporter from Chicago Sun Times contacted NRC resident inspectors re allegations that 400.000 gallons of radioactive water leaked from station since Jul 1980.

 BARKER, J Region G, Chicago, Office of the Director. 80/09/05.

- 8010090262 PNO-III-80-169A since 800905, extensive investigations by Region 3 & util personnel into allegations of radioactive release has not determined whether actual release of low level radioactive water occurred DAVIS.A B Region 3, Chicago, Office of the Director. 80/09/10 2pp
- 8010080638 PNO-III-80-176 potentially high press interest exists in results of Institute of Nuclear Power Operations insp of station Summary of insp rept encl SPESSARD, R L Region 3. Chicago, Office of the Director, 80/09/15 4pg
- 8010070603 Forwards LER 80-034/03L-0 80dTT, D. J Commonwealth Edison Co 80/09/26 ip
- --8010070612 LER 80-034/03L-0 on 800831.after control rod pulls,38 recirculation pump ran back from 42% to 22% speed Caused by failure of motor generator set speed controller model GE 50-5430 410-84 ZIPBE Controller replaced DUNBAR,J Commonwealth Edison Co 80/09/22 1p.

DOCKET 90-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- BO10060236 Provides updated schedule for implementation of fire protection mod Diesel oil transfer isolation sclenoid valves will not be installed until Apr 1981 due to vendor delay in delivery

 UHRIO.R E Fiorida Power & Light Co 80/09/23 1p.
- 8010130263 Submits info re 800507 cormitment to design reactor coolant pressure oil collection sys to prevent loss of operability of safety-related equipment during SBE Sys attachments will protect safety-related equipment UHRIO.R E Florida Power & Light Co 80/10/07 1p
- BO10210347 Forwards security plan, Revision 3 Revision withheld (ref 10CFR2 790) UNRIO, R E Florida Power & Light Co BO/10/13, 2pp
- 6010240216 Updates mod plans & provides addl info re fire protection plan.

 UHRIG.R E Florida Power & Light Co 80/10/20 3pp

G Adjudicatory correspondence

- 8010010074 Forwards supplemental response to Fioridians United for Safe Energy 800402 ltr refacility, enswering Questions 32-39 NRC reviews results of rupture of one steam generator tube Woregard to cause VAROA.8 A Operating Reactors Branch 1 80/09/10 2pp.
- BO10090299 Responds to B00730 petition on behalf of residents & homeowners in close proximity to facility requesting issuance of order to show cause why facility should not be shut down by 800731 for steam generator insp & repair Request denied DENTOK: H R Office of Nuclear Reactor Regulation, Director B0/09/18 3pp
- --B010080303 Director's decision under 10CFR2, 204 denying order to shut down facility by 800731 to perform steam generator insp & repair Operation of facility under terms of Amend 37 can continue w/o endangering health & safety of public.

 DENTON, H R Office of Nuclear Reactor Regulation, Director. 80/09/18, 14pp
- --8010080304 Notice of issuance of Director's decision under 10CFR2, 206 denying order to shut down facility by 800731 to perform steam generator insp & repair, DENTON-H R Office of Nuclear Reactor Regulation, Director 80/09/18 2pp
- BO10030312 Requests that resolution mentioned in motion for leave to participate be submitted Certificate of Svc encl.Related correspondence COLL.N A. Steel. Hector & Davis 80/09/29, 4pp
- 8010020715 Order granting extension until 801022 for Commission to elect whether to review Director's decision under 100FR2.204
 CMILK.S. J Office of the Secretary of the Commission. 80/09/30.
- 8010080637 Motion to participate in repair hearing process. Dade County 800902 Resolution R-1022-80 encl. Certificate of Svc encl. 8AUNDERS; B.L. Dade County, Fl. 80/10/01, 6pp.

- B010140520 Response stating no opposition to Dade County B00916 motion to participate as interested state Certificate of Svc encl GOLDBERG, B C Hearing Branch 2 80/10/07 3pp
- 8010280529 Order accepting Metropolitan Dade County,FL as participant in proceeding in present status. BDWERS,E,B Atomic Safety and Licensing Board Panel 80/10/27
- 8010290304 Informs that Commission has declined any review of Director's Decision DD-80-28 Decision became final agency action for purposes of judicial review on 801022 Judicial review can be sought in Court of Appeals until 801222 CHILK.S J Diffice of the Secretary of the Commission 80/10/27

H General correspondence

- 8010060019 Forwards facility emergency plan to Homestead,FL Civil Defense Director, W/o encl. ORDTENHUIS,M Operating Reactors Branch 1 80/09/23 1p
- 8010080332 Advises of organizational changes in Advanced Bys & Tachnology & OA Depts. Revision of topical GA rept will be transmitted upon completion
 UHRIO,R E Florida Power & Light Co 80/10/03 ip
- B010270539 Responds to 800725 ltr discussing DP Breland concerns resteam generator repair problems & formulation of evacuation plann EIS & safety evaluation being prepared to address issues Util emergency plan updated.
 DIRCKS.W. J Office of the Executive Director for Operations 80/10/07. 3pp.
- --8010270542 Forwards DP Breland 800602 ltr re repair of steam generals & formulation of emergency evacuation plans Requests response 8TONE.R Sanate 80/07/23 5pp
- B010280097 Responds to 800703 ltr discussing DP Breland concerns resteam generator repair problems & formulation of evacuation plan EIS & safety evaluation being prepared to address issues Util emergency plan updated.

 DIRCKE, NT Office of the Executive Director for Operations. 80/10/07 3pp.
- --8010280105 Forwards DP Breland 800602 Itr re repair of steam general: & formulation of emergency evacuation plans Requests response CHILES, L Benate 80/07/03 5pp
- J Insurance & indemnity information
- 8010280315 Requests Endorsement 40 to Policy MF-55 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 1p
- 8010140461 Forwards Endorsement 40 to MAELU Policy MF-55 FIELDER, J. March & McLennan, Inc., M & M Nuclear Consultants, Inc Div. 80/10/06, 2pp.
- P. Operating license stage documents & correspondence
- 8010010542 Application to amend Licenses DPR-31 & DPR-41, changing Teck Space re RHR sys testing frequency to 18 months UHRIG,R.E. Florida Power & Light Co. 80/07/22. 1p.
- --8010010544 Proposed Tech Spec 4 4.5, changing RHR sys testing frequing to 18 months. Supporting safety evaluation encl 4 Florida Power & Light Co 80/07/22. 3pp
- 8010010176 Ack response to NRC 791109 ltr re ECCS evaluation models dualing wifuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VARGA-S A. Operating Reactors Branch 1: 80/09/12. 2pp.
- 8010220079 Forwards errate sheets amending 800705 ltr which provides preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EIBENHUT, D. O Division of Licensing. 80/07/19. 28pp.
- 8010050309 Responds to NRC 800815 ltr re need to maintain at least 23 ft of water above irradiated fuel assemblies during refueling. Procedure change scheduled for implementation by 801031.
 UHRIO, R.E. Florida Power & Light Co. 80/09/23. 1p.

1

 $\{I,J\}$

- 80:00:06:69 Forwards add1 info re effluents from steam generator repair, per NRC 80:08:22 ltr Questions i=9 were previously answered Answers to Questions 9:10:i1 & 12 encl One oversize drawing encl UHRIG.R E Florida Power & Light Co 80:09/24 4pp
- --8010010671 "Cooling Canals Sys.Final Stage Layout Plan " # Bechtel Corp 78/06/01 1p
- 8010160704 Bummary of 800917 meeting w/util & Bechtel Corp reradiological espects of steam generator repair program GROTENHUIS.M. Operating Reactors Branch 1 80/09/24 10pp
- 8010010537 Forwards app representing complete listing of alternatives or clarifications that util is submitting for NRC review & subsequent inclusion in Topical QA Rept.FPLTQAR 1-76A UHRIG.R E Florida Power & Light Co 80/09/26 18pp
- 8010010549 Forwards supplemental info re 790131 request for amend to Tach Spec, allowing deletion of interim fuel residence time limits Requests NRC approval by 801130 UHRIO.R E Florida Power & Light Co 80/09/26. App
- 8010200245 Forwards request for add1 info re industrial exposure, offsite dose & accident evaluation for NRC review of steam generator repair program
 VAR00.6 A Operating Reactors Branch i 80/09/29 9pp
- BO10230017 "In-Plant Source Term Measurements at Turkey Point Station Units 3 & 4 "
 MANDLER, J H , CRONEY, S T E080 Idaho, Inc MOTES, B O Allied Chemical Corp FIN A-6075, NUREG/CR-1427 B0/09/30 600pp
 Available at 6P0 \$11 00
- 8010080223 Updates 800705 ltr re low fracture toughness in response to NRC 800727 questions Forwards partial response to questions & status of remaining items w/anticipated completion dates UHRIO.R E Florida Power & Light Co. 80/10/03. Spp
- 8010280182 Trip rept on 800930 to view intake canal sys & discharge area NRC preparing EIB re proposed steam generator repair of facility EYS will include coverage of endangered species plants affluents during repair program ORGYENHUIS, M Operating Reactors Branch 1 60/10/03 3pp
- BO10200317 Bubmits info re plans to prevent ECCB computational errors in response to NRC 800612 ltr Std procedure document for steam generator tube plugging analysis has been written GA audits indicated correction of previous errors

 UNRIO,R E Florida Power & Light Co 80/10/14 2pp
- 8010280297 Application to amend License DPR-31, permitting return to power operation Results of steam generator inspectonducted during Oct 1980 power outago forwarded Class III fee encl UHR10,R.E Florida Power & Light Co
- --8010280302 "Turkey Point 3 Steam Comerator Insp Program." * Florida Power & Light Co 80/10/22 34pp
- G Inspection reports. IE Bulletins & correspondence
- 8004080145 Forwards Waste Packaging Insp Rept 80-02A on 800206-08 No nuncompliance noted STCHAJP. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/24 5pp ,
- --8004080147 Waste Packaging Insp Rept 80-02A on 800206-08, No noncompliance noted Major areas inspected, DOT & NRC requirements including shipping paper DOT placard, radiation levels, marking & labeling POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/20, 4pp,
- 8010230089 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls." No written response required.

 D'REILLY, J P Region 2, Atlanta, Office of the Director, 80/08/29 to.
- B010150282 Forwards response to IE Bulletin 80-20 re 4-2 spring return to neutral control switches Sąfety-related sys using switches identified & test performed Longer term measures mod plan to be completed by second quarter 1981 UHRIG:R E. Florida Power & Light Co 80/09/16. 3pp

- 8010270502 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/26 to
- B010140092 Ack receipt of B0080B,090B & 15 ltrs informing NRC of steps taken to correct violation noted in IE lnsp Repts 30-250/80-18 & 50-251/80-18 WRPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/29 Ip
- --8010140099 Responds to NRC ltr.supplementing 800908 response.re
 violations noted in IE Insp Repts 50-250/80-18 &
 50-251/80-18 Corrective actions insp & repairs on sys
 identified in IE Bullatins 79-02 & 79-14 will be performed
 UHRIO.R E Florida Power & Light Co. 80/09/15 Spp
- --8010140104 Advises that util reviewed IE Insp Repts 50-250/80-18 & 50-251/80-18 & initiated coordination w/AE to disposition insp findings Followup rept scheduled for submittal by 800901
 UHRIO,R E Florida Power & Light Co 80/08/08 1p
- --8010140107 Forwards IE Insp Repts 50-250/80-18 & 50-251/80-18 on 800603-06 & notice of viglation MURPHY, C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/10 2pp.
- --8010140111 Notice of violation from insp on 800603-06
 * Region 2, Atlanta, Office of the Director 80/07/01 lp.
- --8010140115 IE Insp Repts 50-250/80-18 & 50-251/80-18 on 800603-06
 Noncompliance noted failure to follow concrete expansion
 anchor imsp procedure
 COMPTON,R M Region 2, Atlanta, Office of the Director,
 HERDY,A R Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/07/01 App
- 8010210795 Requests results of insps performed on discs in low pressure turbines at facilities prior to refurbishing of rotors by Westinghouse Number, location & depth of keyway & bore cracks should be provided VARQA, S. A. Operating Reactors Branch 1 80/07/27 2pp
- 8010160220 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required O'REILLY, J.P. Region 3, Chicago, Office of the Director 80/09/30
- 8010170010 Ack receipt of 800729 ltr informing NRC of steps taken to correct violations noted in 15 Insp Rapts 50-250/80-21 & 50-251/80-21 LEHIS R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/30
- ---Boj0170013 Responds to NRC B00630 ltr re violations noted in IE Insp Repts 30-250/80-21 & 30-231/80-21 Corrective actions, antirotation devices were installed on check valve & new GC inspactor checkoff list developed UHRIG.R E Florida Power & Light Co 80/07/29 4pp.
- --BoiOi70017 Forwards IE Insp Repts 50-250/80-21 & 50-251/80-21 on 800301-31 & notice of violation LEHIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/06/30 2pp
- --8010170021 Notice of violation from insp on 800501-31 * Region 2. Atlanta, Office of the Director 80/06/24 ip
- --8010170026 IE Insp Repts 50-250/80-21 k 50-251/80-21 on 800501-31 Noncompliance noted failure to follow housekeeping procedure & inadequate maint procedure VOOY-LOWELL.R. Region 2. Atlanta, Office of the Director MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/06/24. Spp
- 8010150570 Ack receipt of 800828 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/80-26 & 50-251/80-26. LEMIS.R.C. Repion 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/01.
- --8010150576 Responds to NRC itr re violations noted in IE Insp Repts 50-250/80-26 & 50-251/80-26. Corrective actions radioactive filter math disposed of per health physics procedure & cart labeled.
 URRIGR.E Florida Power & Light Co 80/08/28 2pp

- ~-8010150581 Forwards IE Insp Repts 50-250/80-26 & 50-251/80-26 on 800601-30 & notice of violation LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/01 2pp.
- --8010150586 Natice of violation from insp on 800601-30.
 e Region 2, Atlanta, Office of the Director 80/07/25 1p.
- --B0101303BB IE Insp Repts 50-250/80-26 & 50-251/80-26 on 800601-30 Noncompliance noted: improper storage of radioactive matl VOOT,R J., MARSH.R.J. Region 2, Atlanta, Office of the Director. MARTHN.R.D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/25. 6pp
- B010270552 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required Q'REILLY, J. P Region 2, Atlanta, Office of the Director 60/10/02 is.
- 8010290049 Forwards IE Info Notice 80-35. "Failure of Steam Generator Bupport Bolting." No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/10/10.
- 8010200484 Forwards into the inservice thesp program in response to NRC 800414 ltr. UHRIO,R E Florida Power & Light Co. 80/10/15 2pp
- 8010280297 Application to amend License DPR-Gi, permitting raturn to power operation. Results of steam generator inspectoducted during Cict 1980 power outage forwarded Class III fee enci UHRIO, R. E. Plorida Power & Light Co. 80/10/22 2pp.
- --8010280302 "Turkey Point 3 Steam Generator Insp Program "
 * Florida Power & Light Co. 80/10/22 34pp.
- 8010300446 Forwards results of steam generator inspa conducted during outage. Hessed on insp results, tube plugging program & previously submitted analysss return to full power for six months does not involve unreviewed sefety questions UHRIQ:R E. Florida Power & Light Co. 80/10/22. 3pp
- --8010300449 Bteam generator insp rept during Oct 1980 Hot & cold legs gauged. A steam generator small radius U-bends inspected & preventive plugging performed.
 4 Florida Power & Light Co. 80/10/22 33pp
- R. Periodic operating reports & related correspondence
- 6010180338 Forwards monthly operating repts for Sept 1780. SCHMIDT, A.D. Florida Power & Light Co. 80/10/04. ip.
- --8010150341 Konthly operating repts for Sept 1980 CHILBON, V T. Florida Power & Light Co. 80/10/04 13pp.
- B. Reportable occurrences: LERs & related correspondence
- 8010280686 Forwards updated LER 80-004/03X-1 8CHMIDT, A D Florida Power & Light Co 80/10/10 1p.
- ---8010260690 Updated LER 80-004/03X-1: on 800225, radiator tube leak on Emergency Diessi Cenerator A detected Frobable cause due to foreign object being forced into radiator by cooling fans & degradation induced by external snyfron. Leak repaired. PACE.P.L. Florida Power & Light Co. 80/10/10 2pp.
- 8010310395 Forwards LER 80-017/03L~0 SCHMIDT, A D. Florida Power & Light Co. 80/10/20. 1p
- -9010310398 LER 80-017/03L-0:en 800918; reactor power was tow Caused by partial ground on cable associated w/channel N-43 Cable will be replaced.
 PACEP.L. Florida Power & Light Co. 80/10/20. 1p.
- B010310428 Forward: LER 80-018/09L-0. BCHMIDT.A.D. Florida Power & Light Co. 80/10/22. ip.
- --8010310433 LER 80-018/03L-0; on 800926, furing recovery from unit trip, auxiliary feedwater sump A failed to completely deliver regulared flow to feed steam generator B. Gaused by water in pneumatic controls from interrument air sys.
 PACE.F.L. Floride Power & Light Co. 80/10/72. 1p.
- 8010310435 Forwards LER 80-019/017-0 80#MIDT, A D. Florida Fower & Light Co. 80/10/22. ip.

- --8010310441 LER 80-019/017-0 on 801008, during IE Bulletin 79-13 followup, review of radiographs & ultrasonic tests showed indication of cracking in feedwater notice to pips weld area on feedwater lines 3A:3B & 3C PACE, P L. Florida Power & Light Co 80/10/72 1p
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F. Security, medical, emergency & fire protection plans
- BD10D&0236 Provides updated schedule for implementation of fire protection mod Diesel oil transfer isolation solenoid valves will not be installed until Apr 1981 due to vendor delay in delivery

 UHRIO.R E Florida Power & Light Co 80/09/23 1p
- 8010150263 Submits info re 800507 commitment to design reactor cos pressure oil collection sys to prevent loss of operability of safety-related equipment during SSE Sys attachments will protect safety-related equipment UHRIO,R E Florida Power & Light Co 80/10/07 ip
- B010210347 Forwards security plan, Revision 3 Revision withheld (va. 100FR2 790). UHR10, R E Florida Power & Light Co 80/10/13 2pp
- 8010240216 Updates mod plans & provides addl info re fire protecti plan. UHRIQ,R.E. Florida Power & Light Co 80/10/20 3pp
- O. Adjudicatory correspondence
- 8010010074 Forwards supplemental response to Floridians United for Energy 800402 ltr re facility, answering Questions 32-38, NRC reviews results of rupture of one steam generator tube w/o regard to cause VAROA, B. A. Operating Reactors Branch 1, 80/09/10 2pp
- B010030312 Requests that resolution mentioned in motion for leave participate be submitted Cartificate of Svc encl.Related correspondence COLL.N.A. Steel. Hector & Davis. B0/09/29 4pp
- B010080637 Motion to participate in repair hearing process Dade Ca B00902 Resolution R-1022-80 encl. Certificate of Bvc encl BAUNDERS B.L. Dade County.Fl. 80/10/01, 6pp
- 8010140520 Response stating no opposition to Dade County 800916 at to participate as interested state. Certificate of Svc encl QCLDSERO. S C Hearing Branch 2 80/10/07. Spp.
- 8010280529 Order accepting Metropolitan Dade County,FL as partitly in proceeding in present status.
 BOYERB.E.S. Atomic Safety and Licensing Doard Panel 80/10/27
- H. General correspondence
- 8010060019 Forwards facility emergency plan to Homestead.FL Civil Dafense Director.W/o encl ORDTENHUIS.H Operating Reactors Branch 1. 80/09/23. ip
- 8010080332 Advises of organizational changes in Advanced Bys & Technology & GA Depts.Revision of topical GA rept will be transmitted upon completion
 UHRIO.R.C. Florida Power & Light Co. 80/10/03. 1p
- 6010270537 Responds to 800725 ltr discussing DP Breland concerns to steam generator repair problems & formulation of evacuation plan, EIS & safety evaluation being prepared to address issues. Util amergency plan updated.
 DIRCKS.W.J. Office of the Executive Director for Operations. 80/10/07. 3pg
- ---8010270542 Forwards DP Breland 800602 ltr re repair of steam spin & formulation of emergency evacuation plans Requests response.

 BTONE.R. Senate. 80/07/25. 5pp.
- 8010280097 Responds to 800703 ltr discussing DP Breland concerns to steam generator repair problems & formulation of evacuation plan.EIS & safety evaluation being prepared to address issues. Util emergency plan updated. DIRCKE, W. T. Office of the Executive Director for Operations. 80/10/07. Spp

- --8010280105 Forwards DP Breland 800402 itr re repair of steam generator 5 formulation of emergency evacuation plans Requests response CHILES, L. Senate 80/07/03 5pp
- J. Insurance & indemnity information
- 8010280315 Requests Endorsement 40 to Policy MF-55 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24 1p.
- 8010140461 Forwards Endorsement 40 to MAELU Policy MF-55 FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/10/06 2pp
- P Operating license stage documents & correspondence
- 80:00:0542 Application to amend Licenses DPR-31 & DPR-41, changing Tech Specs re RHR sys testing frequency to 18 months UHRIG.R.E Florida Power & Light Co 80/07/22 1p.
- --8010010544 Proposed Tech Spac 4 4 5 changing RHR sys testing frequency to 18 months. Supporting safety evaluation encl + Fioride Power & Light Co 80/07/22 Spp
- 8010010176 Ack response to NRC 79[109 ltr re ECCB evaluation models dealing w/fwel cladding swalling & incidence of rupture Response acceptable & no further action necessary VAROA.B. A Operating Reactors Branch 1 80/09/12
- B010220099 Forwards errata sheets amending 800905 ltr which provided proliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIBENHUT.D O Division of Licensing 80/09/19 28pp
- 8010060309 Responds to NRG 800815 Itr re need to maintain at least 23 ft of water above irradiated fuel assemblies during refueling Procedure change scheduled for implementation by 801031 UHRIG:R E Florida Power & Light Co. 80/09/23. 1p
- 8010010668 Forwards add1 info rs effluents from steam generator repair, per NRC 800822 ltr Questions 1-8 were previously answered Answers to Questions 9,10,11 & 12 encl One oversize drawing encl UHRIO,R E Florida Power & Light Co 80/09/24. 4pp.
- --8010010471 "Cooling Canals Sys.Final Stage Layout -- Plan." * Bechtel Corp. 78/06/01 ip
- 8010160704 Summary of 800917 meeting w/util & Bechtel Corp re radiological aspects of steam generator repair program OROTENHUIS,M Operating Reactors Branch 1 80/09/24 10pp.
- 8010010897 Forwards app representing complete listing of alternatives or clarifications that util is submitting for NRC review & subsequent inclusion in Topical QA Rept, FPLTQAR 1-76A.

 UHR10/R.E. Florida Power & Light Co 80/09/26, 18pp.
- 8010010549 Forwards supplemental info re 790131 request for amend to Tech Spec.ellowing deletion of interim fuel residence time limits Requests NRC approval by 801130 UHRIO, R E Florida Fower & Light Co 80/09/24 App.
- 8010200245 Forwards request for add1 info re industrial exposure, offsite dose & accident evaluation for NRC review of steam generator repair program VAROA,8 A Operating Reactors Branch 1 80/09/29, 9pp.
- B010230017 "In-Plant Source Term Measurements at Turkey Point Station Units 3 & 4 "
 MANDLER, J. W.; CRONEY, B. T. E080 Idaho; Inc. MOTES, B. Q. Allied Chemical Corp. FIN A-6075. NUREO/CR-1629, 80/09/30. 600pp. Available at OPO. \$11.00
- B0100B0223 Updates 800905 itr re low fracture toughness in response to NRG 800729 questions. Forwards partial response to questions is stabus of remaining items w/anticipated completion dates. UHRIQ, R. E. Florida Power & Light Co. 80/10/03. 5pp.
- 8010280192 Trip rept on 800930 to view intake canal sys & discharge area, NRC preparing EIB re proposed steam generator repair of facility, ETB will include coverage of endangered species plant affluents during repair program.

 GROTENHUIS.M. Operating Reactors Branch 1, 80/10/03. 3pp.

- B010200317 Bubmits info re plans to prevent ECCB computational errors in response to NRC 800612 ltr 8td procedure document for steam generator tube plugging analysis has been written. GA audits indicated correction of previous errors UHRIO, R E Florida Power & Light Co 80/10/14 2pp.
- Q. Inspection reports. IE Bullatins & correspondence
- 8010230089 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Habls " No written response required O'REILLY, J P Region 2: Atlanta: Office of the Director, 80/08/29 ip
- 80:0150282 Forwards response to 1E Bulletin 80-20 re W-2 spring return to neutral control switches Bafety-related sys using switches identified & test performed Longer term measures mod plan to be complated by second querter 1981 UHRIQ.R E Florida Power & Light Co 80/09/16. 3pp
- B010270502 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Consentation Decontamination " No specific action or response requested O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/09/26
- 8010140092 Ack receipt of 800808,0908 & 15 ltrs informing NRC of steps taken to correct violation noted in IE Insp Repts 80-230/80-18 & 50-231/80-18 HURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/29 ip
- --8010140099 Responds to NRC ltr.supplementing B0090B response, reviolations noted in IE Insp. Repts 50-250/80-18 & 50-251/80-18 Corrective actions insp. & repairs on systidentified in IE Bulletins 79-02 & 79-14 will be performed. UHRIG.R.E. Florida Power & Light Co. 80/09/15 Spp.
- --8010140104 Advises that util reviewed IE Insp Repts 50-250/80-18 & 50-251/80-18 & initiated coordination w/AE to disposition insp findings Followup rept scheduled for submittal by 800901 UHRIO, R.E. Florida Fower & Light Co 80/08/08 1p
- --B010140107 Forwards IE Insp Repts 50-250/80-18 & 50-251/80-18 on 800803-06 & notice of violation.
 MURPHY,C E Region 2: Atlants: Reactor Construction & Engineering Bupport Branch 80/07/10. 2pp.
- --8010140111 Notice of violation from insp on 800603-06.
 Region 2. Atlanta, Office of the Director 80/07/01. 1p.
- --8010140115 iE Insp Repts 50-250/80-18 & 50-251/80-18 on 800603-06.
 Noncompliance noted failure to follow concrete expansion
 anchor insp procedure
 COMPTON.R.M Region 2. Atlanta, Diffice of the Director
 HERDT.A.R. Region 2. Atlanta, Reactor Construction & Engineering
 Bupport Branch. 80/07/01 épp.
- B010210795 Requests results of insps performed on discs in low pressure turbines at facilities prior to refurbishing of rotors by Hestinghouse. Number, location & depth of keyway & bore cracks should be provided.

 VAROA.8.A. Operating Reactors Branch 1. B0/09/29. 2pp
- B010160220 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ qualification of Class IE Equipment." No written response required.

 O'REILLY, J. P. Region 3, Chicago: Office of the Director, 80/09/30, 1p.
- 8010170010 Ack receipt of 800729 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-21 & 50-251/80-21 & LENTS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/30. 1p.
- --8010170013 Responds to NRC 800630 ltr re violations noted in IE Insp. Repts 50-250/80-21 % 50-251/80-21. Corrective actions: antirotation devices were installed on check valve & new GC inspector checkoff list developed.
 UHR10, R.E. Florida Power & Light Co. 80/07/29. 4pp
- --8010170017 Forwards IE Insp Repts 80-250/80-21 & 50-251/80-21 on 800501-31 & notice of violetion. LEMIS,R.C., Region 2, Atlants, Reactor Operations Nuclear Support Branch, 80/05/30, 2pp.
- --8010170021 Notice of violation from insp on 800501-31.

 * Region 2, Atlanta, Office of the Director. 80/06/24. ip.

- --8010170026 IE Insp Repts 50-250/80-21 & 50-251/80-21 on 800301-31 Noncompliance noted failure to follow housekeeping procedure & inadequate maint procedure VUOY-LOWELL, R Region 2, Atlanta, Diffice of the Director. MARTIN,R. B Region 2, Atlanta, Reactor Operations Nuclear Support Branch 89/06/24 Spp
- 8010150570 Ack receipt of 800828 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/80-24 & 50-251/80-26 LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/10/01 lp
- --8010150974 Responds to NRC ltr re violations noted in IE Insp Repts 30-250/80-26 & 50-251/80-24 Corrective actions radioactive filter matt disposed of per health physics procedure & cart labeled UHRIO, R E Florida Power & Light Co 80/08/28 2pp.
- --8010150581 Forwards IE Insp Repts 50-250/80-26 & 50-251/80-26 on 800601-30 & notice of violation LEMIS,R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/88/01 2pt
- --8010180586 Notice of violation from insp on 800401-30 * Region 2, Atlanta, Office of the Director 80/07/25 ip.
- --G0101505BB IE Insp Repts 50-250/60-26 & 50-251/60-26 on B00601-30 Noncompliance noted improper storage of radioactive matl V001r. J. MARSH.R J. Region 2. Attanta, Office of the Director MARTIN.R D. Region 2. Attanta, Reactor Operations Nuclear Support Branch. B0/07/25 App
- 8010270352 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 to.
- B010270D49 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested, D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/10
- 8010240267 Forwards facility steam generator insp program planned for Nov 1980 UHRIGAR E Florida Power & Light Co. 80/10/20 5pp
- R. Periodic operating reports & related correspondence
- 8010150338 Forwards monthly operating rapts for Sept 1980 8CHMIDT, A D Florida Power & Light Co. 80/10/04 ip
- --8010150341 Monthly operating repts for Sept 1980. CHILSON, V T. Florida Power & Light Co 80/10/04. 13pp
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1
- @ Adjudicatory correspondence
- 8010200289 Forwards order confirming util commitments to implement action to IE Bulletin 80-17
 STELLOY Office of Inspection & Enforcement, Office of the Director 80/10/02, ip.
- --8010200302 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO.Y Office of Inspection & Enforcement, Office of the Director 60/10/02 7pp
- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 76 of 185 Control Robs to Fully Insert During Boram at BUR."

 STELLO.V Office of Inspection & Enforcement, Office of the Director, 80/10/02 2pp.
- B010160032 Notice of appearance in proceeding Certificate of Svc encl SCHERR, S. J. Natural Resources Defense Council. B0/10/10. 3pp
- 8010160778 Order directing licenses & NRC to inform ABLB by 801031 whether there is intention to pursue application. If intention exists, NRC shall inform ABLB of estimated dates of safety evaluation & EIS publication. HILHOLLIN, O.L. Atomic Safety and Licensing Board Panel. 80/10/14, 2cs

- 8010280535 Notice of appearance in proceedings. STEPTOE, P P Commonwealth Edison Co STEPTOE, P P Isham, Lincolti Beals 80/10/23 ip
- 8010290395 Request for hearing re 800919 orders for mod of licenses requiring certain info on environ qualification of safety-related equipment in response to IE Bulletin 79-018, Urges suspension of effectiveness of orders W/Certificate of 8vc STEPTOE, P.P. Commonwealth Edison Co. STEPTOE, P.P. Isham, Lincoln I. Beale 80/10/23 8pp
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 itr which provided preliminary clarification of THI action plan requirements. Gorrectad table of implementation schedule also encl. EISEMHUT.DO Division of Licensing 80/09/19 28pp.
- 8010040012 Discusses util response to NRC 791109 ltr re portions of ECCS evaluation models, Response is acceptable IPPOLITO, T A Operating Reactors Brench 2 80/09/24 2pp
- 8010090240 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch, Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Monclass IE power supplies & reactor protection sys. IPPOLITO, T A Operating Reactors Branch 2 80/09/24 Gpp.
- 8010100361 Bubmits list of current qualification programs for EPAL util equipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC scheduls.

 LAMKEN-D C Commonwealth Edison Co 80/09/24 2pp
- 8010090420 Forwards Revision 1 to Sections 3 & 4 of Inservice insp & testing program
 JANCECK: R F. Commonwealth Edison Co 80/09/30, 145pp
- --8010070425 "Diagram of Instrument Air Piping." Sheet 2.

 * Oeneral Electric Co FOX.8 C. Bargent & Lundy, Inc 4834-12 80/09/15. ip
- --8010090429 "Diagram of Svc Air Piping " * Oemeral Electric Co BAUER.S Sargent & Lundy, Inc 4834-12 80/04/25 ip
- --8010090432 "Diagram of Turbine & Dissel Oil Piping."

 * Owneral Electric Co. ROSTOWSKI, J Sargent & Lundgr Inc.
 4834-12 80/03/28, 1p
- --8010970435 "Diagram of Reactor Bldg Equipment Drains."
 # General Electric Go ALM.L Sargent & Lundy, Inc. 4834-12
 80/01/21 tp
- 8010070430 Comments on NRC 800705 ltr re "Preliminary Clarification of TMI Action Plan Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED, C. Commonwealth Edison Co. 80/10/01 5pp
- 8010070854 Forwards info & drawings rs undervoltage protection, in response to Guestions 1.2,3.4 & 6 of NRC 800813 itr Tech Specs changes identified in Guestions 5 & 7 being evaluated, JANECEK, R. F. Commonwealth Edison Co. 80/10/01. 3pp.
- --8010070979 "Schematic Control Diagram, 4;60 Volt Bus 13-1 Standby Diesel, 1/2 Feed Breakers."

 * Sargent & Lundy, Inc. 79/10/01, 1p.
- B010280295 Forwards GE recommendations for Tech Bpecs changes for flow biased average power range monitor scram & rod block satdown, Changes are due to NRC concern w/using total peaking factor as setdown factor for BMRs w/different fuel lengths.

 JANECEK, R. F. Commonwealth Edison Co. 80/10/03 8pp.
- B010240203 Forwards proposed Tech Spec changes, per NRC B00707 request. Changes provide addit operational & surveillance requirements.

 JANECEK.R.F. Commonwealth Edison Co. B0/10/14, 2pp.
- --8010240210 Revised Tech Spec Pages 42,43,55,62 & new Page 61e for Dresden Units 2 & 3 & Pages 3,2/4 2-14,3,2/4,2-16,3,3/4,3-3 & 3 3/4,3-9 for Guad Cities Units 1 & 2 # Commonwealth Edison Co. 80/10/14 22pp.

- G Inspection reports, IE Bulletins & correspondence
- 8010150085 Forwards IE Insp Repts 50-254/80-12 & 50-265/80-15 on 800606-0718 No noncompliance noted HEIBHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/19 2pp
- --8010150090 IE Insp Repts 50-254/80-12 & 50-265/80-13 on 800606-0718, No noncompliance noted Major areas inspected operational safety verification, maint observation, IE bulletin followup. LER followup & procedure verification.

 SPESSARO,R L , CHRIBSOTIMOS, N , DUPONT, E 0 Region 3, Chicago, Office of the Director 80/08/18 lipp
- 8010210016 Provides updated info me admittance of Region 3 personnel on facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER.J O Region 3. Chicago, Office of the Director 80/07/03
- 8010090159 Forwards addl response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expension Anchor Bolts " Load tests have been performed on concrete expension anchors on all accessible safety-related piping sys JANECEK.R F Commonwealth Edison Co 80/09/05. 17pp.
- BO10200282 Forwards add1 response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts "Load tests performed on concrete expansion anchors on all accessible safety-related piping sus
- B010140337 Forwards IE Insp Repts 50-254/80-21 & 50-245/80-23 on 800828 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Bafety Branch 80/09/10 2pp
- --8010160346 IE Insp Repts 50-284/80-21 & 50-265/80-23 on 800828 No noncompliance noted, Major areas inspected; confirmatory measurements including telcon & closeout of results of previous sample collection.

 JANUSKA:A 0 : PAPERIELLO.C J Region 3, Chicago, Office of the Director. 80/09/09. 4pp
- 8010010685 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-254/80-18 t 50-265/80-20

Region 3, Chicago, Bafequards Branch 80/09/12, 1p.

- --8010010493 Forwards response to NRC 800812 ltr re vigiations noted in IE Insp Repts 50-254/80-18 & 50-265/80-20, Corrective actions, security force issued ltr of instruction, Encl available in Central Files only ABEL, J S Commonwealth Edison Co 80/09/02 3pp.
- 80:00090090 Responds to IE Bulletin 80-13. "Cracking in Core Spray Spargers " No evidence of cracks identified during insp. KAUSCH:T.J. Commonwealth Edison Co. 90/09/16. ip
- E010010734 Ack receipt of 800708 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-17 & 50-255/80-17 DAVIS,A.B. Region 3, Chicago, Fuel Facility & Meterials Safety Branch 80/07/18, ip

- --8010010743 Forwards response to NRC 800818 itr re violations noted in IE Insp Repts 50-254/80-17 & 50-265/80-17, Corrective actions:meeting was held to discuss packaging & transportation requirements. All shipments will be inspected.

 ABEL, J B Commonwealth Edison Co. 80/09/08 3pp.
- B010100241 Responds to 800818 request for add1 info re IE Bulletin 79-14, "Seismic Analysis for As-Built Sefety-Related Piping Sys," List of sys where pipe stress levels exceed one-half of ultimate mati stress will be provided monthly.

 JANECEK.R.F. Commonwealth Edison Co. B0/09/19. 2pp.
- B010100250 Bubmits addl response to IE Bulletin 80-17 % Buppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BKR." Util will install continuous water level monitoring of scram discharge vols by 801201.

 JANECEK.R F. Commonwealth Edison Co. 80/09/19. Spp.
- 8010090420 Forwards Revision 1 to Sections 3 & 4 of inservice imap & testing program JANECEK.R.F. Commonwealth Edison Co. 80/09/30. 145pp.

- 8010160226 Forwards Buppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required
 KEPPLER, J G Region 3, Chicago, Office of the Director 90/09/30
- 8010200289 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 STELLO,V Office of Inspection & Enforcement Office of the Director 80/10/02 ip
- --- 8010200302 Order confirming util commitments to implement ection re IE Bulletin 80-17 STELLO.V Office of inspection & Enforcement, Office of the Director. 80/10/02 7pp
- 8010210222 Forwards orders confirming util commitments to implement action rs IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 8TELLO, Office of Inspection & Enforcement, Office of the Director 80/10/02 2pp
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required KEPPLER, J O. Region 3, Chicago, Office of the Director 80/10/02
- 8010290039 Forwards IE Info Notice 80-36, "Failure of Steam Camarator Support Bolting." No specific action or response requested KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- BO10130307 Forwards monthly operating repts for Bept 1980 KALIVIANAKIS.N Commonwealth Edison Co BO/10/01 1p
- ---BOI0150313 Monthly operating repts for Sept 1980 BROWN B., TUBBB.R Commonwealth Edison Co GO/10/01. 22pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010090285 PND-III-80-127 on 800702; plant was shut down to repair leaking feedwater check valve inside drywell. No Tech Spec limits were violated. Repairs estimated to be completed on DUPONT, B., SPESSARD, R. L., HEISHMAN, R. F. Region 3, Chicago, Office of the Director 80/07/03 ip.
- B010090258 PND-III-80-164A on 800919, no addl cracking in core spray piping has been identified other than pipe cracks previously identified Licenses intends to replace defective piping slbows w/different matl.

 CHRIBB0TIM05, N . BPESBARD, R L . DANIELB0N, D, Region 3, Chicago, Office of the Director. 80/09/19, 1p.
- 8010070500 Forwards LER 80-022/03L-0. KALIVIANAKIS-N. Commonwealth Edison Co 80/07/22 ip.
- --8010070509 LER 80~022/03L-0 on 800903, during callbr surveillance, temp switch T8 1-2371A tripped at 212 F rather than 200 F Caused by setpuint drift. Switch replaced STEFFEB.C Commonwealth Edison Co 80/09/22. ip
- 8010160345 Forwards five LERs 80-021/03L-0. KALIVIANAKIS,N. Commonwealth Edison Co. 80/07/22. 1p.
- --B010160352 First of five LERs B0-021/03L-0 on B00901, during main steam line local rate test valves AQ 1-0203-2A, AQ 1-0203-1B, AQ 1-0203-2B, AQ 1-0203-1B & AQ 1-0203-2D found to have laskage rates in excess of Fech Specs Cause not stated. TUBBS:R.C. Commonwealth Edison Cq. B0/09/19. 1p.
- --8010160358 Second of five LERs 80-021/03L-0; on 800919, during feedbater check valve local leak rate test leakage through feedwater check valve local leak rate test leakage through feedwater check valve 1-220-62A found excessive, Cause not stated. Valve will be repaired & tested before unit startup.
 WUNDERLICH J R Commonwealth Edison Co. 80709/22. ip.

DOCKETED ITEMS

- --8010160365 Third of five LERs 80-021/03L-0 on 800901, during main steem line frain local leak rate test, valve MD 1-220-1 found to have excessive leakage Cause not stated Valve will be repaired & tested before unit startup MURRAY, R Commonwealth Edison Co 80/09/22 ip
- --\$010160371 Fourth of five LERs 80-021/031-0 on 800903, during local leak rate test of drywell-suppression chamber vent exhaust, vol bounded by AD 1-1601-23, 24:60.61; A2 & 63 found to have excessive leakage Valva AD 1-1601-23 suspected leaking.

 KEHRET. D Commonwealth Edison Co 80/09/22 1p
- --8010160375 Fifth of five LERs 80-021/03L-0 on 800904 during local lack rate testing containment gurge vol bounded by valves AO 1-1601-21.22, 53 & 56 found to have excessive lask rate Cause not stated Containment purge valves will be repaired HANN-UM, D Commonwealth Edison Co 80/09/22 ip
- 8010070359 Forwards LER 80-020/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/09/24 1p
- --8010070367 LER 80-020/03L-0 on 800831 during electromatic relief valve operability surveillance GDS 201-1, electromatic relief valve i-203-38 failed to close Gaused by steam cutting of pilot valve allowing steam to leak out exhaust port.

 CLARK, D Commonwealth Edison Co 80/09/24 3pp.
- 8010140800 Farwards LER 80-023/03L-0
 KALIVIANAKIB:N Commonwealth Edison Co 80/09/29. ip.
- --8010140512 LER 80-023/03L-0 on 800910 fire barrier genetrations found w/o sealing in floor between cable spreading room & auxiliary electric room Caused by const parsonnel failure to follow core bore procedure Penetrations sealed HUNDERLICH, J.R. Commonwealth Edison Co. 80/09/29 ip
- 8010140440 Forwards LER 80-025/01T-0
 KALIVIANAKIB,N Commonwealth Edison Co BO/09/30 ip
- --8010140451 LER 80-025/01T-0 on 800913, ultrasonic insp revealed crack indications in three welds on core spray loop A & two welds on core spray loop B Caused by probable metallurgical failure. Elbows & short sections of pipe will be replaced CLARK, D O. Commonwealth Edison Co 80/09/23, 3pp.
- 8010210793 Forwards LER 80-024/03L-0. KALIVIANAKIS.N Commonwealth Edison Co 80/10/08 ip
- --8010210760 LER 80-024/03L-0 on 800914, during core unload, fuel bundle was removed while mource range monitor was reading less than min required by Tech Specs Caused by misunderstanding of recent Tech Spec change
 KNOESPEL, P D Commonwealth Edison Co 80/10/08. 3pp

DOCKET SO-255 PALISADED NUCLEAR PLANT F Security, medical, emergency & fire protection plans

- 8010150311 Requests that implementation dates for fire protection safety evaluation Mode 3 i 6 & 3 i 18 be changed to require implementation by first forced outage of sufficient duration or by Dct 1981 refueling outage H
- G. Adjudicatory correspondence
- 8010020235 Forwards orders which require submission of info to support environ qualification of safety-related electrical equipment. Submittal of info required by 801101 CRUTCHFIELD. D Operating Reactors Branch 5. 80/08/29. 2pp.
- --B010020246 Order for mod of license requiring timely submission of info praviously requested re environ qualification of safety-related electrical equipment EISENHUT, D O. Division of Licensing 80/08/29. App
- 8010300527 Forwards revised orders correcting 800929 orders for mod of OL & provisional OL which contained inaccurate refs Date of hearings accordingly revised.
 EISENHUT, D O Division of Licensing. 80/09/17, 4pp
- --8010300538 Order for mod of provisional OL, correcting 800829 order which contained inaccurate refs Response to NRC 800306 & 28 its shall be filed by 801101. Request for hearing will not stay order UCS petition discharged.
 EIGENHUT, D. G. Division of Licensing. 80/09/19 6pp.

- B010080440 Provides status rept of discovery & other prehearing matters re civil penalty proceeding per NRC 800229 memorandum & order Util is considering need for depositions of witnesses identified by NRC BIELANSKI, A P Isham, Lincoln & Seals 80/10/03 1p
- 8010150040 Motion to compel more specific answers from NRC to second round of Interrogatories i through 4 Requested info needed in detail in order to determine if discretion abused Cartificate of Svc encl Related correspondence BIELAWSKI, A P Consumers Power Co BIELAWSKI, A P Isham, Lincoln 6 Beale 80/10/04 9pp
- 8010210532 Response to NRC 800909 second round of interrogatories & requests for production of documents Witnesses not yet determined due to burden of proof falling on NRC re all issues except penalty Documents & Certificate of Svc encl BIELAMSKI, A P Consumers Power Co BIELAMSKI, A P Isham, Lincoln & Beale. 80/10/16, 34pp
- 8010300077 Response in opposition to CPC 801006 motion to compel agre specific answers to second set of interrogatories Answers dtd 800928 complete & responsive W/excerpts of interrogatories & answers & Certificate of 80c 80/10/27 12pp
- J Insurance & indemnity information
- 8010210447 Forwards Endorsement 58 to MAELU Policy MF-50 IRELAND. J H Consumers Power Co 80/10/16 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010280404 Forwards Revision 9 to FBAR resulting from seismic analysis of as-built safety-related piping FGGO, W O Consumers Power Co 80/10/24 1p
- ~-B0102B0604 Revision 9 to FBAR
 * Carolina Power & Light Co 80/10/24 5pp
- P Operating license stage documents & correspondence
- 7901300018 Advises that systematic evaluation program Topic VIII-2 A forwarded by 790109 its was for wrong unit Additionally, Topic VII-3 had typographical error on page 19 Forwards corrections
 ZIEMARNA D L Operating Reactors Branch 2 (Pre 790625), 79/01/22
 500.
- 7904120234 Forwards draft evaluation of systematic evaluation progree Topics XV-17.XV-18 & portion of XV-12 covering radiological consequences of steam generator tube failure HOFFMAN D P Consumers Power Co 79/04/06 3pp
- 7904170197 Forwards comments on draft evaluation of systematic evaluation program Tupics XV-17, XV-18 & portion of XV-12 HDFFMAN, D. P. Gonsumers Power Co 79/04/06 3pp.
- 79121800B1 Forwards draft evaluation of SEP Topic II-1 A, "Exclusion Area Authority & Control," SEP Topic II-1.B, "Population Distribution" & SEP Topic II-1 C, "Potential Hazards Due to Nearby Industrial Transportation & Military Facilities" ZIEMANN, D L. Operating Reactors Branch 2 (Fre 80042B). 79/11/27
- 8001020430 Notifies that util found no errors in SEP Topics [I-1.A. II-1 B & II-1 C during review performed in repsonse to NRC 79112P request HOFPMAN.D P Consumers Power Co 79/12/28 ip
- 8003270083 Requests list of refs for specific topics be provided to docketed info including VI-7 A 3.VI-7 B.VI-10.A.VII-1.A & VII-2.to aid NRC in SEP review Forwards Comm Ed 790326 itr submitting list of refs to aid NRC in review of SEP ZIEMANN.D t. Operating Reactors Branch 2 (Pre 800428) 80/02/44
- 8004010289 Bubmits ref list for BEP Topics VI-7. A. 3, VI-7. B. VI-10 A. VII-1 A & VII-2. in response to NRC 800214 request,
 HOFFMANN, D. P Consumers Power Co 80/03/26. 3pp.
- BOOBOA0107 Forwards current evaluation of SEP Topics III-10.A.III-103 VI-7.F.VIII-3.B.VIII-4 & XV-16.Requests notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD.D Operating Reactors Branch 5 80/07/11. 27pp

- 8010080578 Forwards Amend 60 to License DPR-20, safety evaluation & notice of issuance & availability
 CRUTCHFIELD, D Deprating Reactors Branch 5 80/08/21 2pp
- --8010080579 Amend 60 to License DPR-20.incorporating limiting conditions for operation & surveillance requirements for new fire protection equipment CRUTCHFIELD.D Operating Reactors Branch 5 80/08/21 12pp
- --B010080581 Safety evaluation supporting Amend 60 to License DPR-20.

 * Office of Nuclear Reactor Regulation, Director B0/08/21 4pp
- --8010080586 Notice of issuence & availability of Amend 60 to License DPR-20 CRUTCHFIELD: D Operating Reactors Branch 5 80/08/21 2pp
- B010230392 Advises of review of response to NRC 791109 ltr re ECC8 evaluation models dealing w/fuel cladding swalling & incidence of rupture Util response is acceptable. No further action is necessary CRUTCHFIELD, D Operating Reactors Branch 5 80/09/11 3pp.
- 8010150631 Forwards request for add1 info re SEP Topics VI-7 B.VI-7.C. VI-10.VII-3.VIII-2 & VIII-3 CRUTCHFIELD.D Operating Reactors Branch 5 80/09/16 3pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EISENHUT.D G Division of Licensing 80/09/19. 28pp.
- B010150530 Summary of 800904 meeting w/utils.8&W & NUS Corp re proposed upgrade mods to auxiliary feedwater sys Agenda & 800808 memo encl VIBBING.0.8. Operating Reactors Branch 4, 80/09/30 48pp
- ---8010130544 Submits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys Seismically induced core melt due to loss of decay heat removal could be as much as six times more likely than WASH-1400 estimates.

 MATTSON.R.J Division of Safety Technology 80/08/08, 22pp.
- B010170034 Immediate action ltr withdrawing B3% power level restriction from facility Personnel must be instructed & procedures updated to require instial auxiliary feedwater flow of 300 gpm to single steam generator KEPPLER, J Q Region 3, Chicago, Office of the Diractor, 80/10/01 ip.
- B0103i0203 Forwards Amends 35 & 41 to Licenses DPR-4 & DPR-20, respectively & notice of issuance & availability. CRUICHFIELD.D Operating Reactors Branch 5 80/10/01. 4pp.
- --8010310204 Amendà 35 % 61 to Licenses DPR-6 % DPR-20, respectively, adding license conditions to include approved safeguards contingency plan as part of licenses GRUTCHFIELD, D. Operating Reactors Branch 5. 80/10/01. 4pp
- --8010310210 Notice of issuance & availability of Amends 35 & 61 to Licenses DPR-6 & DPR-20, respectively CRUTCHFIELD, D. Operating Reactors Branch 5. 80/10/01 3pp
- 8010160601 Forwards "Environ Qualification of Safety-Related Electrical Equipment," in response to order for QL mod. Supplemental rept will be prepared & submitted prior to 801101.

 HDFFMAN, D.P. Consumers Power Co 80/10/07, 2pp.
- ---8010160603 "Environ Qualification of Safety-Related Electrical Equipment" * Consumers Power Co * Bechtel Gorp. 80/09/30 300pp.
- 8010100362 Forwards letdown line drawing which was unreadable in 800801 submittal re-seismic design. Drawing completes util response to NRC 801002 requests. Drawing available in Central Files only.

 MARUBICH: R M Consumers Power Co 80/10/08. 1p.
- 8010200555 Advises that no mods or procedure changes necessary re decay heat removal sys per NRC 800611 Tech Spec change request. Resulte based on response to IE Bulletin 80-12 submitted on 800801.
 HGFFMAN, D. P. Consumers Power Co. 80/10/16 2pp.
- 8010310353 Discusses util 800131 response to NRC 790925 loss of offsite power survey. Responses were very comprehensive resulting in more events being reported. High event rates also attributed to util having six transmission circuits.

 HOFFHAN, D. P. Gonsumers Power Co. 80/10/28, 4pp

- O Inspection reports: IE Bulletins & correspondence
- 8010230145 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployes badges are requested & personnel requiring badges for unescorted access in protected areas KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/03 4pp.
- 8010290241 Forwards notice of violation from IE insp on 800919-20, V Stello 800916 ltr to util & AEC criteria for determining noncompliances KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/16.
- --8010270258 Notice of violation from insp on 800919-20 * Region 3, Chicago, Office of the Director 80/09/16, 1p.
- 8010240029 Forwards IE Insp Rept 50-255/80-12 on 800729 & 0819-20 KEPPLER:J 0 Region 3. Chicago. Office of the Director 80/09/18 2pp.
- --8010240031 IE Insp Rept 80-255/80-12 on 800729 & OB19-20. Noncompliance noted failure to maintain containment integrity & failure to promptly rept significance of incorrect valve position. GTRECTER. J F., WOHLD, P., JORGENSEN, B. L. Region 3, Chicago, Office of the Director 80/09/17 9pp
- 8010080592 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifupal Charging Pumps Following Becondary Bide High Energy Line Rupture." Charging pumps consist of one variable capacity & two constant capacity-type pumps FROST.8 R Consumers Power Co 80/09/23 Spp.
- 8010270470 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested KPPLER.J G. Region 3, Chicago, Office of the Director. 80/09/25.
- BO10020307 Forwards info for review to resolve items of noncompliance re-security issue noted in IE Insp Rept 50-155/80-05, Item 1. Info withheld (ref 10CFR2 790) HOFFMAN.D P Consumers Power Co. 80/09/26. ip.
- 8010020367 Forwards final response to IEB-79-14, "Beismic Analysis for As-Built Bafety-Related Piping Sys " Pages of FBAR were revised & will be transmitted under separate cover Drawings will be available on aparture cards at PDR.

 HOFFMAN.D P Consumers Power Co 80/09/26, 24pp
- 8010070167 Responds to NRC 800916 ltr re violations noted in IE Insp. Rept 50-255/80-12. Corrective actions HPI8 & LPIB returned to normal power operation lineup. Operations personnel alerted to importance of individual responsibilities.

 DEWITT, R. B. Consumers Power Co. 80/09/26 7pp.
- B010160239 Forwards Suppl 2 to IE Builetin 79-018, "Environ Qualification of Class IE Equipment." No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/09/30
- B010280664 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications," No written response required KEPPLER.J Q. Region 3, Chicago, Office of the Director. 80/10/02 lp.
- 8010170533 Forwards IE Insp Rept 50-255/80-16 on 800908-12, No noncompliance noted HIND, J. A. Region 3, Chicago, Safeguards Branch 80/10/03. 2pp.
- --8010170538 IE Insp Rept 50-235/80-16 on BOD908-12. No noncompliance noted Major areas inspected security program audit, security organization & vital area physical barriers, Details withhald (ref 10CFR2 790).

 CHRISTOFFER. Q., KNICELEY, J. R. Region G. Chicago, Office of the Director. HIND, J. A. Region G. Chicago, Bafeguards Branch. 80/10/02. ip.
- BD10270022 Forwards IE Info Notice 80-36, "Failure of Bteam Generator Support Bolting " No specific action or response requested, KEPPLER.J.G. Region 3, Chicago, Office of the Director. BO/10/10, 1p.
- B010200440 Responds to IE Info Notice 79-22 Environ qualification of electrical equipment analysis/review was submitted on B01007. Commitment made in util B01009 itr is fulfilled. Util considers concerns of notice & NRC 790917 itr closed HOFFMAN. D P Consumers Power Co B0/10/16 ip.

- 8010270216 Forwards IE Insp Rept 50-259/60-15 on 800804-09, 11,12,14,15, 18-22 & 25-27 & notice of violation HEISHMAN,R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/28 2pp
- --8010290220 Notice of violation from insp on 800804-08,11,12,14,15,18-22 Region 3. Chicago, Office of the Director 80/09/23 1p
- --8010290224 IE Insp Rept 50-255/00-15 on 800804-08, 11, 12, 14, 15, 18-22 & 25-29 Noncompliance noted operation of plant w/inoperable safety-related snubbers & failure to meet deficiency reporting requirements URCENSEND L. HELLER, J. K., BOYD, D. C. Region 3, Chicago, Office of the Director 80/09/23 9pp
- R Periodic operating reports & related correspondence
- 8010150442 Forwards monthly operating rept for Sept 1780 KENNEDY, D M Consumers Power Co 80/10/09 ip.
- --8010150459 Monthly operating rept for Bept 1980 BODYKE,P J Consumers Power Co 80/10/01 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010140387 PNG-III-80-100 on 800524.plant achieved criticality after shutdown of more than sight months During shutdown, extensive const k mod work was completed including THI modes seismic restraint mode & replacement of boric acid heat tracing. Office of the Director. BOVD.D C. HEISHMAN, R.F. Region 3, Chicago, Office of the Director. BO/05/27 1p
- 8009030039 PNG-III-80-I28 on 800702, weld in generator seal oil filter failed causing gross less of oil into turbine bldg Turbine generator manually tripped causing reactor trip Safety sys appeared to have functioned w/o challenge to energency sys JORGINSEN, B. L., EGYD. D., REIMANN, F. Region 3, Chicago, Office of the Director. 80/07/03 1p.
- 8010090293 PMG-III-80-128A on 800709, plant was started up & while at low power reactor automatically shut down from high startup rate trip Caused by faulty instrument. During startup control rod B would not move Repairs are in progress.

 JOROSHBEN, B L BOYD, D RIDGMAY, K R. Region 3, Chicago, Diffice of the Director, 80/07/10 ip
- 8010080371 PNO-III-80-140:on 800728.licensee reported finding containment sump isolation valve CV 3030 open.Condition has potential to make high pressure injection pumps; containment apray pumps & low pressure injection pumps inoperable HELLER, J. 80YD, D. C., HEISHMAN, R.F. Region 3. Chicago, Office of the Director. 80/07/28 2pp
- 60100B0362 PNO-III-B0-144.on 800901.licenses reported unplanned release of radioactive gas Bource of release was failed rupture disc on wasta gas compressor. Amount released is small fraction of Tech Spec limits.

 BOYD.D G. HELLER.J. HEISHHAN.R.F. Region 3. Chicago, Office of the Director. 80/08/04. 2pp
- 8010100386 PNO-III-80-150. on 800812, unplanned gaseous release of 2 to 4 minutes occurred while transferring quench tank cover gas to gaseous waste holdup sys Release was within Tech Epec limits Licenses is investigating source of release BUYD. D. C. JURGENSEN. B. L., NEISPAAN, R. F. Region 3. Chicago, Office of the Director. 80/09/13 ip
- 8010090283 PNO-III-80-155: on 800819; licensee reported that survaillance test had been performed during power operation which should have been performed only while in cold shutdown RIDOMAY, R R. 80YD. D. C., HEIGHMAN, R. F. Region 3, Chicago, Office of the Director. 80/08/20 2pp
- 8010090245 PNO-III-80-159 on 800826, while operating at 88% power, plant was manually tripped because of loss of condensate & feedwater pumps. Recovery took 2.5-h to regain onscale readings of steam generator levels.

 JORGERSEN. B L , BOYD. D. C , MEJERMAN. R. F , Region 3, Chicago, Office of the Director 80/08/26 2pp
- 010090277 PNO-111-80-160: on 800827. If censes notified Region 3 that unit will be taken to cold shutdown for replacement of leaking control rod drive seals. Shutdown is expected to last approx five days.

 JORGENSEN: B. L. Region 3. Chicago, Office of the Director. 80/09/27.

- 6010090280 PNO-III-80-162 on 800831, labor contract expires Negotiation for new contract are continuing Possibility exists that strike might be called 800901 or later Strike would involve operations:maint & const personnel
 JOROENSEN.B , HOYD,D C , HEISHMAN,R F Region 3, Chicago, Office of
 the Director 80/08/29 2pp
- 8010080626 PNO-III-80-175 on 800912, wildcat strike was initiated Process at main gate are being honored by operations, maint & const personnel Plant will continue to operate staffed by mgt personnel Plant will continue to operate staffed by mgt personnel JCROENEER.B. DOVD.D. HEIBIMAN.R.F. Region 3. Chicago, Office of the Director 80/09/12 2pp
- 8010070501 Forwards LER 80-035/03L-0 WITHROW, 0 C Consumers Pawer Ca 80/07/30 ip
- --8010070520 LER 80-035/03L-0 on 800830 during return to svc after shutdown. Leakage discovered through presure relief valve caused by loose spring guide within solenoid assembly valve dus to failed breated joint Guide breate back onto plate HITHROW, G.C. Consumers Power Go 80/09/30 ip
- 8010070395 Responds to NRC 800904 immediate action 1tr re 800826 loss of feedwater event Changes to procedures & instruments have been made "Evaluation of Palisades Plant Waterhammer Test & Potential Waterhammer Effects" encl HOFFMAN. D P Consumers Power Co 80/09/30. 2pp
- --8010070609 "Evaluation of Palisades Plant Waterhammer Test & Potentia)
 Waterhammer Effects "
 # Combustion Engineering, Inc. 80/09/30 12pp
- 8010080666 Notification of 800730 meeting w/util to discuss 800628 event at facility & limits on auxiliary feedwater to preclude water hammer.

 MAHBACH-T V Operating Reactors Branch 5 80/07/30 2pp
- B010040305 Confirms util commitments made during 800930 meeting relows of feedwater event & potential feedwater hammer concern Steam generator dryout & hammerwater identification procedures will be implemented by 801031 HQFFMAN:D P Consumers Power Co 80/10/02 ip
- 8010210909 Part 21 rept re pipe supports w/partially or totally disangaged self-aligning rod and bushings furnished by ITT Orinell.Corner & Lada, Pacific Scientific-Kintech Div & NPS Industries
 WAHL, H W Bechtel Power Corp (subs. of Bechtel Corp.) 80/10/08
- 8010150503 Forwards LER 80-037/01X-0 HOFFMAN, D. P. Carolina Power & Light Co 80/10/10, 1p
- -8010150507 LER BO-037/01X-0.on 801009: found pipe support away strut bushings furnished by Corner & Lada: Inc may become loose or disengaged from clamp and Caused by mfg defect Bechtel is reviewing issue for corrective actions. * Consumers Power Co. 80/10/10 2pp
- E010160559 Forwards LER 80-036/01T-0 H0FFMAN, D P Consumers Power Co 80/10/13 1p.
- --B010160562 LER B0-036/01T-O on 800929,while testing C-81A vacuum degasifier pump, radioactive gaseous release occurred prior to required 15-day holdup. Cause not determined Release terminated by stopping vacuum pump # Consumers Power Co 80/10/13. 1p.
- 8010270171 Part 21 rept re pipe supports w/partially or totally self-aligning rod end bushings Info submitted to other Bechtel Power Divs on 801008 for review Rept will be provided if defect applies to other Bechtel projects. HAHL: H W. Bechtel Power Corp (subs of Bechtel Corp) 80/10/17
- 8010090338 PNO-III-80-140A licenses analysis indicates that all ECCS pumps on affected line would have been subj to air binding because containment sump valve CV 3030 had been improperly positioned to open position.
 HELLER, J., BDYD, D. C., HEISHMAN, R. F., Region 3, Chicago, Office of the Director, 80/07/30. 2pp.

DOCKET 50~256 UNIV OF MONTEVIDED RESEARCH REACTOR

- J Insurance & indemnity information
- 8010280662 Requests Endorsement 41 to Policy NF-198 & Endorsements 34 & 38 to Policy MP-36. DINITZ-I. Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24 19
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8010030396 Forwards info per NRC 800730 request re fire protection replication test program being conducted by Ofc of Nuclear Regulatory Research Addl info will be submitted by 801015 Package of 59 instrumentation & mechanical drawings encl HILLS.L M Tennessee Valley Authority 80/10/01
- --B010030397 Package of 59 instrumentation & mechanical drawings to be recalled at later date for microfilming * Tennessee Valley Authority B0/10/01, 59pp
- 8010210481 Forwards remaining info re response to NRC 800716 request for add1 info re fire protection sys tests & north wall of reactor blog at facilities Util statement of understanding re test program & 800730 meeting agreements encil MILLB, L K Tennessee Valley Authority, 80/10/15 19pp.

9 Adjudicatory correspondence

- 8010030076 Forwards 800919 order revising 800929 order for mod of OLs, in entirety
 EISENHUT, D. O Division of Licensing, 80/09/19, 2pp
- --8010030085 Order revising 800929 order for mod of OLs DPR-33.DPR-52 & DPR-68, published in 800912 FR, in entirety Info responsive to IE Bulletin 79-018 shall be submitted by 801101 Request for hearing will not stay effectiveness of order EISENHUT, D O. Division of Licensing 80/09/19 6pp
- B010210165 Forwards order confirming util commitments to implement action re IE Bulletin B0-17
 BTELLOI. V Office of Inspection & Enforcement. Office of the Director. 80/10/02. ip.
- --8010210170 Order confirming util commitments to implement action re IE Bulletin 80-17. STELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp.
- --8010210176 Order confirming off1 commitments to implement action re IE Bulletin 80-17 BTELLO,V. Office of Inspection & Enforcement, Office of the Director 80/10/02. 7pp.
- ---8Di02i0179 Order confirming util commitments to implement action re IE Bulletin 80--17. BTELLO,V. Office of Inspection & Enforcement. Office of the Borrotor 80/10/02. 7pp.

H General correspondence

- 8010280140 Responds to 800818 ltr re 8 Messer concerns of low level waste incineration. Forwards summary of TVA plans & actions re waste mot NRC has not received TVA application for authorization to incinerate low level waste DIRCKS.W J Office of the Executive Director for Operations DIRCKS, W J Of 80/10/01, 2pp.
- J Insurance & indemnity information
- 8010280662 Requests Endorsement 41 to Policy NF-198 & Endorsements 34 & 38 to Policy MF-36
 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24 ip
- 8010190420 Forwards Endorsement 9 to ANI Policy NF-247, Endorsements 34 & 38 to MAELU Policy MF-66 & Endorsement 41 to ANI Policy NF-198. Draft forwarding ltrs encl. FIELDERJ Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/10/08, 10pp.

- O Advisory Committee on Reactor Bafaquards reports & correspondence
- 8010170092 Notice of ACR6 Bubcommittee on Fluid Dynamics 800819-20 meeting in Inglewood.CA to review control rod drive insertion failures at Browns Ferry & scram discharge vol instrumentation failures at Brunswick & Hatch CHILK.S. J. Office of the Secretary of the Commission. 80/07/29
- 8010170319 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Scram Sys " BTAMPELOS.J ACRS Advisory Committee on Reactor Bafeguards 8D/08/08 ip
- --8010170333 Interim preliminary draft rept to ACRB, "Review of Recent Halfunctions of BWR Scram Bys"

 * ACRB Advisory Committee on Reactor Safeguards 80/08/08.
- P Operating license stage documents & correspondence
- 8010020650 Advises that amends requested by util 800806 ltr will not be issued prior to projected startup date of Unit 2. Comments & items for discussion encl.

 IPPOLITO.T A Operating Reactors Branch 2 80/09/11, 3pp.
- 8010020480 Forwards util program for resolving ATMS issue, Mods will be evaluated & implemented to reduce risk, Program can be implemented by 1985 at Browns Ferry, Bequoyah & Watts Bar & by fuel loading at Bellefonte, Hartsville & Phipps Bend, MiLLS, L.M. Tennessee Valley Authority 80/09/17. 5pp
- 8010220077 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also enci. EISERHUT.D.O. Division of Licensing 80/07/19 22pp.
- 8009300400 Forwards technical quastions re implementation of interim policy on 100FR30 & 51 HILLS,L.M Tennessee Valley Authority, 80/09/23 Spp
- 8010080534 Requests add1 action re NRC 780807 itr re deficiencies in Hatch,Unit 2 regulator sys design Hods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys IPPOLITO,T A Operating Reactors Branch 2, 80/09/24, 3pp,
- 8010100423 Confirms 800923 oral approval that leak tests of certain valves need not be performed until prior to entering Hode 2 & approval of leakage limit of 3 gpm per valve for two valves, FGU-74-1 & FGU-74-2; until 801024 TEDE8CO, R. L. Assistant Director for Licensing 80/10/02 ip.
- 8010240073 Forwards Amends 62 & 57 to Licenses DPR-33 & DPR-52, raspectively, safety evaluation & notice of issuance & availability IFPOLITO T.A Operating Reactors Branch 2 80/10/06 3pp.
- --8010240081 Amends 62 & 57 to Licenses DPR-33 & DPR-52, respectively. extending exposure range of max average planar linear heat generation rate vs average planar exposure from 30,000 MHd/T to 40,000 MHd/T. IPFOLITO.T A. Operating Reactors Branch 2. 80/10/06 10pp.
- --8010240086 Safety evaluation supporting Amends 62 & 57 to Licenses
 DPR-33 & DPR-52, respectively.

 # Office of Nuclear Reactor Regulation, Director. 80/10/06. 9pp.
- --B010240091 Notice of issuance & availability of Amends 62 % 57 to Licenses DPR-33 & DPR-52 respectively.

 IPPOLITOIT A. Operating Reactors Branch 2 80/10/06. 2pp.
- 8010090386 Forwards responses to NRC questions re proposed Tech Spec changes on containment hydrogen monitoring sys MILLS,L.M Tennesses Valley Authority 80/10/07. 3pp.
- 8010210588 Informs of change in plans for mods of electric sys & postponement of date for approval of requested license amend Util will not need approval of amend for Unit 2 startup & wishes to withdraw approval request.

 MILLS.L M. Tennessee Valley Authority. 80/10/14 ip.
- 8010200529 Application for proposed Tech Spec changes, amending Licenses DPR-33, DPR-52 & DPR-68 to clarify definition of "cold shutdown" to allow necessary reactor leak chetk during refueling outage.

 MICLS, L. M. Tennessee Valley Authority 80/10/16. 2pp.

- --8010200534 Proposed Tech Bpec changes, clarifying definition of "cold shutdown" re reactor leak check during refueling outage # Tennessee Valley Authority 60/10/16 5pp.
- 8010220505 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs re scram discharge vol vent & drain valves in response to NRC 800707 request.

 MILLS, L. H. Tennesses Valley Authority 80/10/16, 2pp.
- ~-8010220509 Proposed Tech Specs: Sections 3 0 & 4 0 re scram discharge vol vent & drain valves.

 # Tennesses Valley Authority. 80/10/16 20pp.
- 9010310333 Forwards response to NRC 801001 ltr re BHR scram sys Provides basis for continued operation of facilities HILLB.L.K Tennessee Valley Authority. 80/10/27 2pp
- Q. Inspection reports: IE Bulletins & correspondence
- 8005120223 Forwards Waste Pactaging Insp 80-03 on 800227-27 No noncompliance noted.

 BIOHR, J.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/03/20, 2pp.
- --8005120230 Waste Packaging Insp Rept 80-03 on 800227-29. No noncompliance noted Major areas inspected placarding requirements radiation levels marking & labeling requirements for packages.
 POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 80/03/17, 7pp.
- 8006040077 Forwards Waste Packaging Insp Rept 80-03 on 800319.No noncompliance noted 8TOMP.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch, 80/04/14. 2pp.
- ~-9006040082 Waste Packaging Insp Rept 80-05 on 800319. No noncompliance noted Major areas inspected shipping paper requirements, DOT placerding requirements, radiation levels removable contents to the prohibited articles of contents POTTER, J. P. Region 2. Ablanta, Fuel Facility & Materials Bafety Branch. 80/04/04 6pp.
- 8008060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance noted. 8TOMR.J.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/06/23. 2pp.
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16. No noncompliance noted. Major areas inspected; compliance w/NRC & DOT regulations.
 TROUT 9 L. Region 2, Atlanta, Puel Facility & Materials Bafety Branch, 80/06/23, 6pp.
- 8010060044 Ack util 800711 response to notice of violation & payment of proposed civil penelties. Specific corrective actions will be reviewed during subsequent insps.

 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/08/14. 2pp.
- 010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matts."

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/08/29. ip.
- 010020749 Forwards monthly statue rept for work related to IE Bulletin 79-14.
 MILLB, L.M. Tennessee Velley Authority, 80/09/09. 29pp.
- >10090102 Forwards response to IE Sulletin 80-20. "Failures of Heatinghouse Type H-2 Spring Return to Neutral Control Switches." None of subj switches found in safety-related applications to date investigation continuing.

 MILLS, L. M. Tennesses Valley Authority, 80/09/12, 10pp.
- BO10230479 Forwards IE Imap Rapts 50-259/80-30, 50-240/80-23 & 50-276/80-24 on BO0701-31. No mancampliance noted. LENIB.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Iranch. BO/09/12, 2pp.
 - 010230483 IE Insp Repts 50-259/80-30.50-260/80-23 & 50-296/80-24 on B00701-31.No noncompliance noted. Major areas imagected: operational safety. ROs. reactor trip followup & plant physical protection.
 BULLIVAN.R.F. CHABE.J.M. Region 2. Atlanta. Office of the Director. DANCE.N.G. Region 2. Atlanta, Reactor Operations Nuclear Support Franch. B0/07/11, 9pp.

- 8010270099 Forwards IE Insp Repts 50-259/80-33,50-260/80-26, 50-296/80-27 & 50-327/80-32 on 800811-13 No noncompliance noted. MURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 2pp
- --8010270107 IE Insp Repts 50-259/80-33,50-260/80-26,50-296/80-27 t 50-327/80-32 on 800811-13 No noncompliance noted Major areas inspected fallowup on nancompliances to 100FR21 procedures. BROWNLEE.V L Region 2, Atlanta, Office of the Director. COMLON.T.E Region 2, Atlanta, Reactor Construction & Engineering Support Brench. 80/09/11. 3pp
- 8010190320 Bubmits add1 response to IE Bulletin 80-17 re control red insertion failure. Installation of GE ultrasonic sys for water level indication to be completed Dec 1980. MILLS, L. M. Tennassee Valley Authority 80/09/19 1p
- 9010160194 Forwards Buppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No written response required.
 D'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/09/30.
- B010210165 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 STELLO.V Office of Inspection & Enforcement, Office of the Director. S0/10/02, 1p.
- --8010210170 Order confirming util commitments to implement action of Mulletin 80-17
 STELLO, V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required Q'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02
- 8010270066 Forwards IE Info Notice 80-36. "Failure of Bteam Generator Support Bolting." No specific action or response requested O'REILLY.J P. Region 2. Atlanta. Office of the Director. 80/10/10
- R. Periodic operating reports & related correspondence
- 8010150332 Forwards monthly operating repts for Sept 1980 ABERCROMSIE, H. Tennessee Valley Authority 80/10/10 1p.
- 9010160509 Forwards second monthly operating rept for Bept 1980
 ABERCROMBIE, H Tennessee Valley Authority 80/10/10 1p.
- --8010160511 Second monthly operating rept for Sept 1980, * Tennessee Valley Authority, 80/10/10, 110pp
- 801021034B Forwards corrected draft data re effluent & waste disposal sandannual rept for 1978 submitted w/RA Martfield 800919 ltr. Response to 800930 request for add1 info encl. MILLS.L.M Tennessee Valley Authority 80/10/16 17pp
- S Reportable occurrences. LERs & related correspondence
- 80:0140367 PNO-II-80-I36, on 80:0805, scram discharge vol water level alarm activated on Unit i indicating accumulation of 3 gallons in scram discharge vol instrument vol. Cause believed to be condensation in clean raduaste vent header. JULIAN, C., LEWIE, R.C. Region 2. Atlanta, Office of the Director 80/08/06. 2pp
- 8010030411 Confirms that Prompt Rept BFRU 80-62 re core power exceeding licensed-rated power of 3,293 MHt by 2 for approx 9 minutes on 800924, was not reportable.

 GALHOUN.J.R. Tennessee Valley Authority 80/09/26. 1p.
- 8010040329 Forwards LER 80-066/03L-0.
 GALHOUN, J. R. Tennessee Valley Authority. 80/09/29. 1p.
- --B010060335 LER B0-066/03L-0: on B00902, during normal operations, annunciation on torus hydrogen containment atmosphere monitor was observed. Gaused by failure of model 3,5 BS relay in safe direction. Monitor repaired & returned to svc. # Tennessee Valley Authority. B0/09/29 2pp.

ļį,

- S010080461 Forwards LER 80-070/011-0. CALHQUN, J R Tennessee Valley Authority 80/10/01 ip
- --8010080463 LER 80-070/011-0 on 800919, during review of core verification video tapes, peripheral bundle TV 382 at core location 11-06 discovered rotated 90 degrees from required position Caused by improperly oriented 7 x 7 fuel assembly CALMOUN, J R Tennessee Valley Authority 80/10/01.
- BO10070485 Forwards updated LER 80-056/03L-1 CALHOUN,J R Tennessee Valley Authority 80/10/03 1p
- --B010070490 Updated LER 80-056/03L-i. on 800711. Tech Spec limit for linear heat generation rate was exceeded in one node. Event has been re-evaluated as nonreportable, since unit was at steady state. * Tennessee Valley Authority 80/10/03 2pp.
- 8010150393 Forwards RO re Wheeler Reservoir water temp exceeding Tach Space limit. MILLS, L. M Tennessee Valley Authority 80/10/08. 2pp.
- --B010150398 Limiting conditions of operations violation rept. on 800928 & 29, Wheeler Reservoir water temp exceeded Tech Spec limit Gaused by thermal monitoring sys error. Unit 3 sys placed on cooling tower Design change requests being prepared * Tennessee Valley Authority. 80/10/08. 3pp.
- 8010150463 Environ RO 50-259/8073 on 800928 & 29 temp rise of Wheeler Reservoir between upstream & downstream thermal monitors exceeded Tech Space Caused by extensive rainfall & lower than normal ambient temp, adding to errors in prediction MILLS.L.M Tennesses Valley Authority. 80/10/08. Spp
- BO10210678 Forwards LER BO-073/017-0. CALHOUN, J. R. Tennessee Valley Authority BO/10/09. 1p.
- --8010210A95 LER 80-073/01T-0. on 900928 during steady state operation, river water temp peaked at 5 i F temp difference. Situation recurred next day Caused by incorrect river temp rise predictions Events are random occurrences

 * Tennessee Valley Authority. 80/10/09 2pp.
- BO1020040B Forwards LER BO-071/03L-0, GALHOUN, J. R. Tennessee Valley Authority, BO/10/14 1p.
- ---B010200417 LER 80-071/03L-0; on 800919, continuous air monitor, RM-90-250, declared inoperable as iodine channel indicated downscale Gaused by condensation in Model AH-331F (BF) sample line. Hoisture removed & sys returned to syc.

 * Tennessee Valley Authority 80/10/14 2pp
- B010210691 Forwards LER 80-072/03L-0 GALHOUN, J. R. Tennessee Valley Authority 80/10/20, ip.
- --B010210498 LER 80-072/03L-0:on 800924, during normal operation, RHR torus return valve FCV-74-71 was found to be insperable, Caused by grounded operator motor which caused breaker to trip Motor replaced. Tennesses Valley Authority 80/10/20, 2pp.
- 8010280468 Forwards LER 80-074/03L-0. CALHOUN, J. R. Tennessee Valley Authority. 80/10/23. ip.
- --8010280511 LER 80-074/03L-0; on 800924, during normal operation, seitmic monitor 8MA2 found inoperable Caused by failed printed wiring board 100935. Assembly repaired tested & returned to svc. Failure considered random. No further action planned Tennesses Valley Authority 80/10/23 2pp.
- 8010280563 Forwards LER 80-077/01T-0. CALHOUN, J. R. Tennessee Valley Authority. 80/10/23. 1p.
- --8010280968 LER 80-077/01T-0: on 801010, anchor bolts associated u/
 seismic restraints on RHRBW piping had been degraded by
 anth sattling in RHRBW tunnels, Caused by design error.
 Pipe restraints modified.
 # Tennessee Valley Authority. 80/10/23. 2pp.

- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8010030396 Forwards info per NRC 800730 request re fire protection replication test program being conducted by Offc of Nuclear Regulatory Research Add1 info will be submitted by B01015, Package of 39 instrumentation & mechanical drawings encl. MILLS,L.M Tennessee Valley Authority B0/10/01 250pp.
- --8010030397 Package of 59 instrumentation & mechanical drawings to be recalled at later date for microfilming * Tennessee Valley Authority, 80/10/01, 59pp,
- 8010210481 Forwards remaining info re response to NRC 800716 request for add1 info re fire protection sys tests & north wall of reactor bldg at facilities Util statement of understanding re test program & 800730 meeting agreements encl.

 MILLS,L,M Tennessee Valley Authority. 80/10/15. 19pp
- O Adjudicatory correspondence
- 8010030976 Forwards 800919 order revising 800929 order for mod of OLs. in entirety. EISENHUT,D.O Division of Licensing. 80/09/19. 2pg.
- --8010030085 Order revising 800929 order for mod of OLs DPR-33.DPR-52 & DPR-68.published in 800912 FR, in entirety, Info responsive to IE Bulletin 79-018 shall be submitted by 801101.Request for hearing will not stay effectiveness of order.
 EISENHUT, D O Division of Licensing. 80/09/19. App.
- 8010210165 Forwards order confirming util commitments to implement action re IE Bullstin 80-17.
 STELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02. ip.
- --8010210176 Order confirming util commitments to implement action re IE Bulletin 80-17.

 BTELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.

H General correspondence

- BO10280140 Responds to BO0818 Itr re B Messer concerns of low level waste incineration. Forwards summary of TVA plans & actions re waste mpt. NRC has not received TVA application for authorization to incinerate low level waste.

 DIRCKB.H J Office of the Executive Director for Operations. DIRCKB. H J DA 80/10/01. 2pp.
- J. Insurance & indomnity information
- 8010280662 Requests Endorsement 41 to Policy NF-198 & Endorsements 34 & 38 to Policy MF-56. DINITZ.1. Utility Pinance Branch (formerly Antitrust & Indemnity) 80/09/24. 1p.
- 8010150420 Forwards Endorsement 9 to ANI Policy NF-247, Endorsements 34 & 38 to MAELU Policy MF-66 & Endorsement 41 to ANI Policy NF-198 Draft forwarding ltrs encl. FIELDERJ. Mersh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/10/08. 10pp.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8010170092 Notice of ACRS Bubcommittee on Fluid Dynamics 800819-20 notion? Notice of ACM Buscommittee on Fibia Dynamics Souti?"20 meeting in Inglewood CA to review control rod drive insertion failures at Browns Farry & scram discherge vol instrumentation failures at Brunswick & Hatch.

 CHILKS J Office of the Secretary of the Commission. BO/07/29.
- P Operating license stage documents & correspondence
- 8010020550 Advises that amends requested by util 800806 ltr will not be issued prior to projected startup date of Unit 2. Comments & items for discussion encl.
 IPPOLITO.T.A. Operating Reactors Branch 2. 80/09/11. 5pp.
- 8010020480 Forwards util program for resolving ATMS issue. Mode will be evaluated & implemented to reduce risk. Program can be implemented by 1985 at Browns Ferry, Bequoyeh & Matte Bar & by feel loading at Bellefonts. Hartsville & Phipps Bend. MILLS.L.M. Tennessee Valley Authority. 80/09/17. Spp.

- 90:0220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implamentation schedule also encl EISENHUT.D O Division of Licensing 80/09/19 28pp
- 8010080534 Requests add1 action of NRC 780807 ito re deficiencies in Hatch.Unit 2 regulator sys design Mode should be performed to provided fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys. IPPOLITO.T A Operating Reactors Branch 2 80/09/24 3pp
- B010100423 Confirms 800923 orel approval that leak tests of certain valves need not be performed until prior to entering Mpde 2 & approval of leakage limit of 3 gap per valve for two valves.FCV-74-1 & FCV-74-2, until 801024
 TE0ESCO,R L. Assistant Director for Licensing 80/10/02 ip
- 8010240073 Forwards Amends 62 & 37 to Licenses DPR-33 & DPR-52, respectively safety evaluation & notice of issuance & availability IPPGLITO, T A Operating Reactors Branch 2 80/10/06 Spp
- --B010240081 Amends 62 & 57 to Licenses DPR-33 & DPR-52, respectively, extending exposure range of max average planar linear heat generation rate vs average planar supposure from 30,000 MHd/T; to 40,000 MHd/T IPPOLITO, T. A Operating Reactors Branch 2 80/10/06. 10pp.
- --8010240086 Safety evaluation supporting Amends 62 & 57 to Licenses
 DPR-33 & DPR-52, respectively
 # Office of Nuclear Reactor Regulation, Director 80/10/06, 9pp
- --8010240091 Notice of issuance & availability of Amenda 62 % 57 to Licenses DPR-33 & DPR-52, respectively.

 IPPOLITO, T A Operating Reactors Branch 2 80/10/06 2pp.
- 8010090386 Forwards responses to NRC questions re proposed Tech Spec changes on containment hydrogen monitoring sys MILLS.L H Tennessee Valley Authority 80/10/07 3pp,
- '10210588 Informs of change in plans for mods of electric ays & postponement of date for approval of requested license amend Util will not need approval of amend for Unit 2 startup & wishes to withdraw approval request,
- 10200529 Application for proposed Tach Spec changes, amending Licenses DPR-33, DPR-52 & DPR-68 to clarify definition of "cold shubdown" to allow necessary reactor leak check during Tennessee Valley Authority 80/10/16 2pp
- ---8010200534 Proposed Tech Spec changes, clarifying definition of "cold shutdown" re reactor leak check during refueling outage # Tennessed Valley Authority. 80/10/16 Spp
- BO10220905 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tach Epecs re-scree discharge vol vent & drain valves in response to NRC 800707 request.

 MILLS.L N Tennesses Valley Authority 80/10/16 2pp
- -8010220509 Proposed Tech Specs, Sections 3.0 & 4.0 re scram discharge vol vent & drain valves
 * Tennessee Valley Authority 80/10/16 20pp.
- 310310333 Forwards response to NRC 801001 ltr re BHR scram sys. Provides basis for continued operation of facilities MILLS.L M Tennessee Valley Authority 80/10/27
 - Inspection reports: IE Bulletins & correspondence
 - 0200697 Forwards IE Info Notice 80-02, "Clarification of Certain adultments of Exclusive Use Shipments of Radioactive REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/08/29.
 - 1020749 Forwards monthly status rept for work related to IE 111etin 79-14
 LLS:L N Tennessee Valley Authority. 80/09/09 29sp.
- 0070102 Forwards response to IE Bulletin 80-20, "Failures of estinghouse Type N-2 Spring Return to Nautral Control Buitches" None of subj switches found in safety-related applications to date. Investigation continuing MICLS: I M Tanbessee Valley Authority 80/09/12. 10pp.

- 8010230477 Forwards IE Insp Repts 50-257/80-30,50-240/80-23 & 50-294/80-24 on 800701-31 No noncompliance noted LEHIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/12. 2pp
- --8010230483 IE Insp Repts 50-259/80-30,50-260/80-23 & 50-296/80-24 and 800701-31 No noncompliance noted Major areas inspected operational safety, ROs, reactor trip followup & plant Physical protection

 SULLIVAN,R F , CHASE.J W Region 2, Atlanta, Office of the Director DANCE.H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 7pp
- 8010270099 Forwards IE Insp Repts 50-259/80-33,50-260/80-26, 50-296/80-27 & 50-327/80-32 on 800811-13 No noncompliance noted MURPHY,C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 2pp
- --8010270107 IE Insp Repts 50-259/80-33,50-260/80-26,50-276/80-27 t 50-327/80-32 on 800811-13 No noncompliance noted Major areas inspected fellowup on noncompliances re 10CFR21 procedures BROWNLEE.V L. Region 2. Atlanta, Office of the Director CONLON-T E Region 2. Atlanta, Reactor Construction & Engineering Buppart Branch 80/09/11 3pp.
- 80:0150320 Submits add1 response to IE Bulletin 80-17 re control regingertion failure Installation of QE ultresonic sys for water level indication to be completed Dec 1980
 HILLB.L.M Tennessee Valley Authority 80/09/19 ip
- 6010160194 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response o'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/30
- 8010210165 Forwards order confirming util commitments to implement action re IE Sutletin 80-17
 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/10/02 Ip
- -8010210176 Order confirming util commitments to implement action of [f Builetin 80-17 BTELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp
- 8010270530 Forwards 1E Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/10/02
- B010270046 Forwards IE Info Notice 80-36, "Failure of Steam Generator Bupport Bolting," No specific action or response requested D'REILLY, J. P. Region 2, Atlanta, Office of the Director B0/10/10
- R. Periodic operating reports & related correspondence
- 8010130332 Forwards monthly operating repts for Sept 1980 ABERCROMBIE, H Tennesses Valley Authority 80/10/10.
- --8010150335 Monthly operating repts for Sept 1980 GREEN.D , THOM, T Tennessee Valley Authority 80/10/02 27pp
- 8010160509 Forwards second monthly operating rept for Sept 1980 ABERCROMBIE: H Tennessee Valley Authority 80/10/10 tp.
- --8010160511 Second monthly operating rept for Bept 1980 * Tennessee Valley Authority 80/10/10 110pp
- 801021034B Forwards corrected draft data re effluent & waste disposal semiannual rept for 1978, submitted w/RA Hartfield 800919 ltr Response to 800930 request for add1 info enc! MILLS.L.M. Tennessee Valley Authority 80/10/16 17pp
- 8 Reportable occurrences. LERs & related correspondence
- 8010140367 PND-II-80-i36. on B00805, scram discharge vol water level alarm activated on Unit i indicating accumulation of 3 gallons in scram discharge vol instrument vol Cause believed to be condensation in clean radwaste vent header JULIAN-C., LEMIB.R.G. Region 2. Atlanta, Office of the Director B0/08/06. 2pp.
- 8010030369 Forwards LER 80-037/01L-0.
 GALHOUN, J. R Tennessee Valley Authority, 80/09/26 ip.

1

擅

The state of the s

羽

- --8010030373 LER 80-037/01L-0 on 800914.during fuel shuffling operations. fuel assemblies TZ 758 & TZ 399 were found to be misoriented 90 degrees Caused by operator error Corrective action included improved verification techniques 4 Tennessee Valley Authority 80/09/26 3pp
- 8010140365 Farwards LER 80-038/03L-0 CALHOUN, J R Tennessee Valley Authority 80/10/07 1p
 - -B010140371 LER 80-03B/03L-0 on 800911, during refueling dutage w/unit in cold shutdown.HPCI check valve 2-73-609 failed local leak rate test Caused by buildup of residual matl on body, causing disc of HCPI valve to be cocked open Matl removed Tennessee Valley Authority 80/10/07 2pp
- 8010150393 Forwards RU re Wheeler Reservoir water temp exceeding Tech Specs limit MILLS.L H Tennessee Valley Authority 80/10/08 2pp
- -8010150398 Limiting conditions of operations violation rept.on 800928 & 29.Wheeler Reservoir water temp exceeded Tech 8pec limit Caused by thermal monitoring sys error Unit 3 sys placed on cooling tower Design change requests being prepared # Tennessec Valley Authority 80/10/08 3pp
- B010130513 Forwards updated LER 80-037/01X-1 GALHOUN, J.R. Tennessee Valley Authority 80/10/09 ip.
- --8010150525 Updated LER 80-03L/01X-1 on 800914, during EOC-3 fuel shuffling operations, fuel assemblies TZ 758 & TZ 397 discovered misorionted 90 dagrees Caused by misorientation of 16 fuel assemblies during previous refueling outage # Tennessee Valley Authority 80/10/09 3pp
- 8010210702 Forwards LER 80-039/03L-0 CALHOUN, J R Tennesses Valley Authority 80/10/09 1p
- --B010210710 LER 80-039/03L-0.on 800916.drywell control air valve 2-FCV-32-62 could not be closed by handswitch Cause has yet to be determined * Tennessee Valley Authority 80/10/07 2pp.
- 8010210588 Forwards LER 80-040/01T-0 GALHOUN, J R Tennesses Valley Authority 80/10/14 tp
- ---B010210663 LER B0-040/01T-0 on B00929, five main steam relief valves failed to actuate within required 1% of set pressure during bench test Cause unknown Set pressure was reset & proper operation verified

 # Tennessee Valley Authority B0/10/14 2pp
- 8010270483 Forwards LER BO-041/01T-0, CALMOUN,J R Tannessee Valley Authority BO/10/21 ip
- --B010270491 LER B0-041/01T-0 on B01008, during fuel-shuffling operations, fuel was placed in cell 58-19 w/adjacent control rod 54-19 withdrawn Caused by deficient procedure for fuel support casting replacement Procedures will be revised # Tennessee Valley Authority B0/10/21 2pp
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans
- B010070454 Informs that info requested by NRC re Item 3.1 24, "Electrical Cable Penetrations," will be provided by contracted party & should be forwarded prior to 801201 UTLEY,E E Carolina Power & Light Co 80/10/02 ip
- P. Operating license stage documents & correspondence
- 80:00:010:64 Ack response to NRC 77:109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture. Response acceptable & no further action necessary VAROA.B A Operating Reactors Branch 1. 80/09/12. 2pp
- BOIO140147 Forwards Amend 49 to License DPR-23 safety evaluation & notice of issuance & availability
 VAROA,8 A Operating Reactors Branch 1 80/09/19. 2pp
- --B01014014B Amend 49 to License DPR-23, changing Tech Epecs re setpoints, calibr, surveillance requirements per mode including installation of degraded voltage protection sys for Class IE equipment VAROA/S A Operating Reactors Branch 1 B0/07/19. App

- --8010140151 Bafsty evaluation supporting Amend 49 to License DPR-23 LLL evaluation of proposed design mods & grid voltage degradation Tech Specs changes and # Office of Nuclear Reactor Regulation, Director 80/09/19, 2pp
- --B010140154 Notice of issuance & availability of Amend 49 to License DPR-23 VAROA.S A Operating Reactors Branch 1 B0/09/19 2pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D G Division of Licensing 80/09/19 28pp
- 8010020469 Requests amend to DPR-23-consisting of Teth Specs thanges re residual heat removal sys UTLEV.E E Carolina Power & Light Co 80/09/26 2pp
- --8010020471 Proposed Tech Specs 3 O, resolving concerns re residual heat removal sys operability during cold shutdown conditions & min refueling cavity water level required during refueling operations * Commonwealth Edison Co. 80/07/26 12pp
- 8010310217 Forwards Amend 30 to License DPR-23, safety evaluation & notice of issuance & availability
 VAROA:S.A Operating Reactors Branch 1 80/09/30 2pp
- --B010310220 Amend 50 to License DPR-23, providing for std provisions for special nuclear, source & byproduct matl & adding Tech Spec for testing & surveillance of sources
 VARGA: 8 A Operating Reactors Branch 1 80/09/30 Spp.
- --8010310224 Safety evaluation supporting Amend 50 to License DFR-23 * Office of Nuclear Reactor Regulation, Director 80/09/30 2pp
- --8010310228 Notice of issuance & availability of Amend 50 to License DPR-23 VAROA:8 A Operating Reactors Branch 1 80/09/30 2pp
- 8010100338 Forwards addl info requested by NRC 800321 ltr for bypass & reset of engineered safety features Fourteen oversize drawings enclavailable in Central Files only UTLEY,E E Carolina Power & Light Co 80/10/07 123pp
- 8010150423 Application to amend License DPR-23.correcting Tech Spec Tables 3 5-3 & 4 1-1 re installation of degraded voltage protection sys for Class IE equipment. UTLEV.E E Carolina Power & Light Co. 80/10/07. 2pp
- --8010150425 Corrected Tech Bpec Tables 3 5-3 & 4 1-1 re installation of degraded voltage protection eys for Class IE equipment + Carolina Power & Light Co 80/10/07 2pp
- 8010170547 Application for amend of License DPR-23, delating Tech Spec 4 14 & containing surveillance requirements for propane engine-driven pump. Revised Tech Specs will be submitted UYLEY.E. E Carolina Power & Light Co. 80/10/15 2pp.
- 8010200471 Forwards Tech Specs change re degraded grid voltage, allowing bypass of 480 volt emergency bus undervoltage trip feature at less than 2% reactor power Change necessary to start & stop reactor coolant pumps to control temp UTLEY.E E Carolina Power & Light Co 80/10/17. 2pp.
- --8010200476 Tech Specs Table 3 5 rs degraded grid voltage change # Garoline Power & Light Co 80/10/17 ip.
- B0102B0379 Discusses commitments made as result of 801015 meeting w/ NRC re followup steam generator insp. Info re steam generator chemistry control & improvements implemented will be provided within 30 days

 UTLEY, E Carolina Power & Light Co 80/10/22 2pp.
- G Inspection reports, IE Bulletine & correspondence
- 8003240244 Forwards Maste Package Insp Rept 79-06A on 791126-28 No noncompliance noted.

 8UTHERLAND.J.T Region 2, Atlanta. Fuel Facility & Haterials Safety Branch. 79/12/31. 2pp.
- ~-8003240287 Waste Packaging Insp Rept 79-06A on 791126-28.No noncompliance noted Major areas inspected, shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & DOT marking POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 79/12/12. 7pp

- 8010100251 Forwards IE Insp Rept 50-261/80-18 on 800722-31 No huncompliance noted. LEWIS.R.C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/08/26. 2pp
- --B010100254 IE Inep Rept 50-261/80-18 on 800722-91. No noncompliance noted. Major areas inspected operations review. LERs & open items KELL000:P J., HARDIN, A K Region 2: Atlanta, Office of the Director 80/08/26 4pp
- 8010200632 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Katis."

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29
- 8010240649 Forwards IE Insp Rept 50-261/80-19 on 800811-14 No noncompliance noted. LEWIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/11. 2pp
- --8010240453 IE Insp Rept 50-241/80-19 on 800811-14 No nancompliance noted Hajor areas inspected diesel generator units used as onsite electric power sys & review of IE Bulletin 80-06 MDON, B.T. Region 2, Atlanta, Office of the Director GUICK, D.R. Region 2, Atlanta, Reactor Operations Nuclear Support Brench 80/09/11. 4pp
- 3010270065 Forwards IE Insp Rept 50-261/80-22 on B00805-14 No Montcompliance noted LEWIB,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/09/11. Zpp
- --8010270068 IE Insp Rept 50-261/80-22 on 800805-14 No moncompliance noted Major areas inspected general plant operations, outstanding items & hydraulic supports & restraints.
 BROCKS,E H. Region 2. Atlanta, Office of the Director QUICK, D R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch.
 80/09/11. 5pp.
- 8010150212 RO on 800918, seismic stress analysis per IE Bulletin 79-14, revealed spray piping from containment penentrations in vessels to spray ring headers inadequately restrained to ensure sys operability after DBE Restraint ands initiated STARKEY,R B. Carolina Power & Light Co. 80/09/19. 1p
- 9010280267 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted BTDHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/09/19. 2pp
- -8010280274 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels. MACARTHUR, T C. POTTER, J P. Region R. Atlanta; Fuel Facility & Materials Safety Branch. 80/09/14 8pp
- 010180256 Responds to IE Bullstin 79-03A re weld defects in Type 304 stainless steel pipe spools Original piping spers reviewed & stress analysis performed Burvey revealed no autogenously welded meti used at 85% of allowable stress or higher.

 FURR:B J Carolina Power & Light Co 80/09/22, 2pp.
- >10150265 Responds to IE Bulletin 80-18 re maint of adequate min flow through centrifugal charging pumps after secondary side high energy line rupture. Specified concern does not apply because of differences in sys design.Field test review initiated. FURR.B.J Carolina Power & Light Co. 80/09/22 2pp.
- 1010270479 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination," No specific action or response requested D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/26. ip.
- 80:01:60:21 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/30. ip.
- 8010270301 Submits info re manpower expended for preparation of responses & corrective actions for IE Bulletins 80-15,80-16, 80-19, 480-20.
 FURR.S J Carolina Power & Light Co. 80/09/30. 2pp.

- 8010240286 Submits supplemental response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," re conditions identified in IE Insp Rept 50-261/80-21
 FURBLE J Carolina Power & Light Co. 80/10/02 3pp
- 8010270537 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02
- 801027005B Forwards 1E Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY.J P Region 2. Atlante. Office of the Director 80/10/10
- 8010280379 Discusses commitments made as result of 801015 meeting w/ NRC re followup steam generator insp Info re steam generator chemistry control & improvements implemented will be provided within 30 days

 UTLEY.E E Carolina Power & Light Co 80/10/22. 2pp.
- R. Periodic operating reports & related correspondence
- 60:0150445 Forwards monthly operating rept for Sept 1980 BFARKEY, R. B Carolina Power & Light Co 60/10/10 tp
- --8010180462 Monthly operating rept for Sept 1980
 WATFORD: M Caroline Power & Light Co 80/10/02 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010080439 PND-II-80-110 recent studies by licenses have found abnormalities in bluegill sunfish from Lake Robinson which provides cooling water for facility Analyses show no abnormal radioactivity in either lake water or fish.

 JENKINS, 9. R. Region 2. Atlanta, Office of the Director 80/06/17 is
- 8010070528 Forwards LER 80-021/017-0 8TARKEY, R B. Carolina Power & Light Co 80/10/02, tp.
- --B010070351 LER B0-021/OLT-0 on B0091B, containment spray piping analysis per IE Bulletin 79-14 indicated pips stresses under DE conditions over allowable Caused by differences between design as seismically analysed & as constructed STARKEY.R B. Carolina Power & Light Co 80/10/02 2pp
- E010070500 Forwards LER 80-022/01T-0.
 BTARKEY.R B. Carolina Power & Light Co 80/10/02 1p
- --8010070604 LER 80-022-01T-0 on 800918, during refueling outage, review at eddy current insp data revealed results in C-3 category defined by Tech Baces, Caused by defactive tubes in A & B steam generator inlets & outlets due to corrosion STARKEY, R B Carolina Power & Light Co. 80/10/02 3pp
- 8010200575 Forwards LER 80-020/03L-0. STARKEY, R. B Carolina Power & Light Co 80/10/15. lp.
- --B0102005B1 LER B0-020/OSL-0 on B00916, refueling periodic test PT-2.1 revealed that failure of A safety injection pump breaker to close during power operation would result in operation in degraded mode Caused by breaker alarm switch contact.

 STARKEY.R B Caroline Power & Light Co 80/10/15. 2pp.
- 8010270382 Forwards LER 80-023/03L-0. STARKEY, R B Carolina Power & Light Co 80/10/22. ip.
- --8010270383 LER 80-023/03L-0 on 800923 charcoal cells in control rose ventilation sys were found w/low charcoal levels Caused by improper loading procedures. Written procedures for filling cells are being devaloped.

 STARKEY.R 8 Carolina Power & Light Co. 80/10/22 2pp.
- DOCKET 80-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

 O Inspection reports, IE Bulletins & correspondence
- 8010200675 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls."

 SNIEZEK, J. H. Division of Fuel Facility & Materials Bafety. 80/08/29 in.

- B010010321 Ack receipt of B00821 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-262/80-02 MADBEN. Q L. Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/09/12 1p
- --8010010327 Responds to NRC 800813 ltr re violations noted in IE Insp Rept 50-262/80-02 Corrective actions license recertification requested & check of operating dates initiated & correctly nosted DIXON,DR Brigham Young Univ. 80/08/21 1p
- --8010010335 Forwards IE Insp Rept 50-242/80-02 on 800721-23 & notice of Violation
 MADBER 0 L Region 4. Dallas. Reactor Operations Nuclear Support
 Branch 80/08/13 2pp
- --BD10010339 Notice of violation from insp on 800721-23
 ** Region 4, Dallas, Office of the Director 80/09/13 ip
- --8010010344 IE Insp Rept 50-262/80-02 on 800721-23. Noncompliance noted failure of senior reactor operator to demonstrate knowledge & understanding of facility inactivity in excess of four conths
 - months MADSEN,C L. Region 4. Dallas, Reactor Operations Nuclear Support Branch QAGLIARDO,J E , DEAN, B R Region 4. Dallas, Office of t Director 80/08/15 7pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
- F Becurity, medical, emergency & fire protection plans
- BO10050229 Forwards Revision 2 of "Emergency Preparedness Evacuation Time Estimates " Revision provides evacuation time estimates based on more refined methodology MAYER.L. O Northern States Power Co. 80/09/26 ip
- --8010060235 Revision 2 of, "Emergency Preparedness Evacuation Time Estimates
 - Northern States Power Co 80/09/30 18pp
- BO1002064B Forwards "Emoke Bimulation Testing at Monticello Nuclear Generating Plant," conducted by Nuclear Technology, Inc Recommended detector changes will be completed by 801031 MAYER, L O Northern States Power Co 80/09/30 ip
- --8010020654 "Emoke Simulation Testing at Monticallo Nuclear Generating NEILBON, C., MARTIN, T.D. Nuclear Technology, Inc. (Nutech) 80/09/19 38pp
- 8010200465 Comments on change to mod proposed for Item 3 1 16 re fire protection safety evaluation Info regarding new seal design, availability & delivery under investigation Completion date scheduled for end of 1761 refu
- O Adjudicatory correspondence
- 8010030228 Forwards 800919 order revising 800829 order for mod of QL, in EISENHUT, D.G Division of Licensing, 80/09/19. 2pp
- -8010030235 Order revising 800829 order for mod of OL DPR-22 published in 800911 FR in entirety Response to IE Bulletin 79-018 shall be submitted by 801101 Request for hearing will not stay affectiveness of order UCS petitions discharged EISENHUT, D G Division of Licensing. 80/09/19. App
- 8010100127 Order granting extension until 801017 for Commission to review ALAB-611 CHILK, S. J. Office of the Secretary of the Commission. 80/19/03.
- 80:01703B4 Forwards identification & discussion of Categories A & B unresolved generic safety issues listed in NUREO-05:0 RO Bachmann notice of appearance, M Karman notice of withdrawal, KT Eccleston affidavit & Certification of Svc encl. BACHMANN, RO Rulemaking & Enforcement Division, 80/10/15 42pp.
- 8010210825 Order granting extension until 801103 for Commission to slect whether to review ALAB-611
 CHILK.S.J Office of the Secretary of the Commission 80/10/17.

- I Financial information
- 8010280437 Forwards 1979 actual cash flow & 1980 projected cash flow, par requirements of Reg Guide 9 4 H/o Annual Financial Rept 1979 CARLSON, L. R. Northern States Power Co. 80/10/20 2pp
- J Insurance & indomnity information
- 8010280296 Requests endorsement & copy of Amend 50 to Policy NF-174. DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- 8010070565 Forwards Endorsements 53 & 45 to NELIA Policy NF-174 & MAELU Policy MF-51.respectively JOHNSON, R O Northern States Power Co. 80/09/30 2pp
- 8010210492 Forwards Endorsement 55 to NGLIA Policy NF-174 & Endorsement 46 to MAELU Policy NF-51, JOHNSON, R O. Northern States Power Co. 80/10/16 3pp
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also entl EISENHUT.D.O Division of Licensing 80/09/19, 28pp. EISENHUT, D. O Division of Licensing
- 8010080613 Requests add1 action re NRC 780807 1tr re deficiencies in Hatch, Unit 2 regulator sys design Reactor protection sys power supply should be modified by end of next fueling IPPOLITO, T A Operating Reactors Branch 2 80/09/24 3pp
- 8010100275 Forwards revised Tech Spec Table 3 13 1 specifying fire detection instruments to be operable in each fire zone Table should be substituted in Exhibit 8 of 800731 amend request for License DPR-22 MAYER, L. G. Northern States Power Co 80/10/06. is
- ---B010100298 Proposed revised Tech Bpec, Table 3 13.1, specifying fire detection instruments to be operable in each fire zone
 * Northern States Power Co = 80/07/31. ip
- 8010160340 Forwards application for amend of License DPR-22 changing Tech Specs re-scram discharge vol Class III fee encl MAYER, L.O. Northern States Power Co. 80/10/10 1p
- ---8010160347 Application for amend of License DPR-22, changing Tech Specs, re scram discharge vol MAYER, L. O. Northern States Power Co. 80/10/10 Spp.
- --8010160351 Proposed changes to Tech Spacs, Sections 1 0,2 0 & 3 0 Te *Cram discharge vol * Northern States Power Co 80/10/10 9pp
- B0101604B3 Bubmits licensing fee determination for request to amend License DPR-22 re scram discharge vol Tech Specs in response to NRC 800707 ltr Northern States Power Co 80/10/10. 1p
- 80i0170384 Forwards identification & discussion of Categories A & B unresolved generic safety issues listed in NUREO-05i0 RO Bachmann notice of appearance. H Karman notice of withdrawal, KT Eccleston affidavit & Cartification of Svc encl.

 DACHMANN, R O Rulemaking & Enforcement Division 80/10/15. 42pp
- 8010220495 Advises that evaluation of Task A-31, "RHR Shutdown Requirements" will be completed by 810415 Facility has been reviewed for safe shutdown capability as part of fire protection review program HAYER, L. D. Northern States Power Co. 80/10/15 2pp
- 8010310424 Submits response to NRC 800507 ltr re addl Task II.K.S 13 requirements Separation of HPCI & reactor core isolation cooling initiation setpoints is unwarranted Util will reset function on high reactor vessel level trip MAYERIL C Northern States Power Co. 80/10/24 ip
- G. Inspection reports, IE Bulletins & correspondence
- 8010150133 Forwards IE Insp Rept 50-263/80-14 on 800602-30. No noncompliance noted.
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/07. 2pp.

- --B01015013B IE Insp Rept 50-263/80-14 on 800602-30 No noncompliance noted Major areas inspected control room operations, selected emergency sys. IE builetin & circular followup & transportation of tradiated fuel by truck LITTLE.N B . BROWN.C . MADISON.A Region 3. Chicago, Office of the Director 80/08/06 4pp
- 80:02:10053 Provides updated info re admittance of Region 3 personnel to facilities. Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unscorted access in protected areas.

 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/09/03 Bps
- 8010060112 Submits response to IE Sulletin 80-20 rs Westinghouse Type W-2 control suitches No switches of this type are used in safety-related sys OllBERTS.D.E Northern States Power Co. 80/09/12 ip.
- 8010060120 Bubmits response to IE Bulletin 80-17 Suppl 1. Scram discharge header monitoring sys described in NRC 800815 ltr has been installed & is operational ollBERTS.D E Northern States Power Co 80/09/12 2pp.
- 8010240037 Forwards IE Insp Rept 50-263/80-15 on 800701-31 No noncompliance noted HEIBHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/18 2pp.
- --Boig24003B IE Insp Rept 50-263/80-15 on 800701-31 No noncompliance noted, Major areas inspected control room operations, review of logs, selected emergency sys, followups of LERs, organization & administration & IE Builetin 80-17 BRDNN-C, H, MADIBON-A L, LITTLE, W S. Region 3, Chicago, Office of the Director, 80/09/15 5pp
- 8010160248 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.
 KEPPLER, J G Region 3, Chicago, Office of the Director. 80/09/30.
- 010280643 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications." No written response required. KEPPLER.J.C. Region 3. Chicago, Office of the Director. 80/10/02 10.
- 0010270035 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J G. Region 3: Chicago, Office of the Director 80/10/10, 1p.
- R. Periodic operating reports & related correspondence
- 8010150409 Forwards monthly operating rept for Bept 1980. MAYER, L O Northern States Power Co. 80/10/09. 1p.
- ---8010150411 Monthly operating rept for Sept 1980. MYRABO: A L Northern States Power Co. 80/10/09. 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8008060278 PNO-III-80-126 on 800702, pipe adapter developed chlorine leak on tank considered to be sapty Two plant attendents transported to hosp. Control room ventilation sys isolated & placed on rectroulation Reactor operation not affected BROWN.C.H., WARNICK.R.F., NEISHMAN.R.F. Region 3, Chicago, Office of the Director 80/07/02. ip.
- 010280526 Forwards updated LER 80-026/03L-1 MAYER, L. D. Northern States Power Co. 80/10/20. ip.
- -8010280533 Updated LER 80-026/03L-1: on 800817 during normal power operation, while performing surveillance test A0-2-86A, outboard MSIV exceeded required closure time & failed to close during later test Caused by actuator heat exposure. OVERLID: T. H. Northern States Power Co. 80/10/20, ip.

DOCKET 80-244 DOW CHEMICAL CO.

- H. General correspondence
- 8010080468 Informs of adding H Emmal. H Kochar & E Bickel to Reactor Degrations Committee. as of 800826. T Parsons was deleted from committee. Forwards resumes. H/o encls.

 MACKI.T. H. Dow Chemical Co. 80/09/25. 1p.

- J Insurance & indemnity information
- 8010280600 Requests endorsements & copy of Amend 10 to Policy B-34 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity) B0/07/24. 1p
- B010240411 Forwards advance premium std premium & reserve premium andorsements.effective 800101 Also forwards Amend 10 to Indemnity Agreement B-04 COALMELLIT N Dow Chemical Co 80/10/10 ip
- Q. Inspection reports, IE Bulletins & correspondence
- 8010290375 Forwards IE Insp Rept 50-264/80-02 on 800910-12 No noncompliance noted DAVIS:A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/09/24. 2pp
- --B010270403 IE Insp Rept 30-264/80-02 on 800910-12 No noncompliance noted Major areas inspected qualifications, audits, training, radiation protection procedures, instruments & equipment appears control LOVENDALE, P. C. Region 3, Chicago, Office of the Director FIBHER, H. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 80/09/22, 6pp

DOCKET 30-265 QUAD-CITIES STATION, UNIT 2

- O Adjudicatory correspondence
- 8010200289 Forwards order confirming util commitments to implement action re IE Suiletin 80-17. STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 Ip.
- --B010200306 Order confirming util commitments to implement action re IE Bulletin 80-17 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02, 7pp
- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 74 of 185 Control Rods to Fully Insert During Scram at BMR."

 STELLO, United of Inspection & Enforcement, Office of the Director 80/10/02. 2pp.
- 8010160032 Notice of appearance in proceeding Certificate of Svc encl SCHERR, B. J. Natural Resources Defense Council 80/10/10. Spp
- 8010160778 Order directing licensee & NRC to inform ABLB by 801031 whether there is intention to pursue application If intention exists./NRC shall inform ABLB of estimated dates of safety evaluation & EIB publication.

 HILHOLLIN,O L. Atomic Safety and Licensing Board Panel 80/10/14
- 8010280535 Notice of appearance in proceedings STEPTOE.P P Commonwealth Edison Co 80/10/23. 1p.
- 8010290385 Request for hearing re 800919 orders for mod of licenses requiring certain info on environ qualification of safety-related equipment in response to IE Bulletin 79-018, Urges suspension of effectiveness of orders. W/Certificate of Byc STEPTOE, P. P. Commonwealth Edison Co. 80/10/23 Spp.
- P. Operating license stage documents & correspondence
- 8010220099 Forwards strets sheets emending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUTED. 0 Division of Licensing. 80/09/19 28pp
- 8010060012 Discusses util response to NRC 791109 ltr re portions of ECCB evaluation models. Response is acceptable. IPPOLITO, T.A. Operating Reactors Branch 2, 80/09/24, 2pp
- 8010070240 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch.Unit 2 regulator sys design, Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys. IPPOLITO.T.A. Operating Reactors Branch 2, 80/09/24, 3pp.
- 8010100361 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from 800917 meeting. Requests info re which program best fits NRC schedule.

 LAMKEN. D. C. Commonwealth Edison Co. 80/09/24, 2pp.

- 8010090420 Forwards Revision 1 to Bections 3 & 4 of inservice insp & testing program
 JANECK, R F Gommonwealth Edison Co 80/09/30 145pp
- --8010090432 "Diegram of Turbine & Diesel Oil Piping " * General Electric Co ROSTOWSKI, J Sargent & Lundy, Inc 4834-12 80/03/28. 1p
- --8010090438 "Diagram of Instrument Air Piping," Sheet 2 * General Electric Go CERABAN,D A Bargent & Lundy, Inc 60/08/13 1p
- --8010090440 "Diagram of Bvc Air Piping." * General Electric Co. BRACHMAN, V Sargent & Lundy, Inc 4934-12 80/04/25, 1p
- 8010070430 Comments on NRC 900905 ltr re "Preliminary Clarification of TMI Action Plan Requirements." Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED
- 8010070554 Forwards info & drawings re undervoltage protection, in response to Questions 1,2,3,4 & 6 of NRC 800863 ltr Tech Specs changes identified in Questions 5 & 7 being evaluated JANECEK, R. F. Commonwealth Edison Co
- B010280235 Forwards QE recommendations for Tech Specs changes for flow biased average power range monitor scram & rod block setdown Changes are due to NRC concern w/using total peaking factor as setdown factor for BMRs w/different fuel lengths JANECEK.R F Commonwealth Edison Co. 80/10/03 Bpp.
- 8010240203 Forwards proposed Tech Spec changes, per NRC 800707 request Changes provide add1 operational & surveillance requirements. JANECEK, R. F. Commonwealth Edison Co. 80/10/14, 2pp
- --8010240210 Revised Tech Spec Pages 42,43,55,62 & new Page 61s for Dresden Units 2 & 3 & Pages 3 2/4 2-14,3 2/4 2-16,3 3/4 3-3 & 3 3/4,3-9 for Quad Cities Units 1 & 2 # Commonwealth Edison Co. 80/10/14 22pp.
- Q Inspection reports: IE Bulletins & correspondence
- 8010130083 Forwards IE Insp Repts 30-234/80-12 & 50-265/80-13 on 800808-0718. No noncompliance noted. HEISHMAN.R.F Region 3. Chicago, Reactor Operations Nuclear Support Branch. 80/08/19. 2pp
- ---8010150090 IE Insp Repts 50-234/80-12 & 50-265/80-15 on 800606-0718 No noncompliance noted Major a reas inspected operational safety verification maint observation, IE bulletin followup, LER followup & procedure verification.

 SPESBARD, R.L., CHRISSOTIMOS. N, DUPONT, S. G. Region G. Chicago, Office of the Director. 80/08/18 iipp.
- B010210016 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER, J. 9. Region 3. Chicago, Office of the Director B0/09/03 4pp.
- 8010090189 Forwards add1 response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
 Load tests have been performed on concrete expansion anchors on all accessible safety-related piping sys.

 JANECEK,R F Commonwealth Edison Co 80/09/05 17pp.
- B010200282 Forwards add1 response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts," Load tests performed on concrete expansion anchors on all accessible safety-related piping sys

 JANECEK, R. F. Commonwealth Edison Co. 80/09/05, 17pp,
- 8010140337 Forwards IE Insp Repts 50-254/80-21 & 50-245/80-23 on 800828 No noncompliance noted. DAVIS.A.E. Region 3. Chicago, Fuel Facility & Materials Safety Branch, 80/09/10 2pp
- --8010160346 IE Insp Repts 50-254/80-21 & 50-265/80-23 on 800828, No noncompliance noted Major areas inspected confirmatory measurements including telcon & closeout of results of previous sample callection.

 JANUSKA,A. 0. PAPERIELLO, C. J. Region 3, Chicago, Office of the Director. 80/09/09, 4pp

- BO10010685 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/80-18 & 30-265/80-20 HIND, J A Region 3, Chicago, Safeguards Branch BO/09/12 1p
- --8010010693 Forwards response to NRC 800812 ltr re violations noted in IE Insp Repts 50-254/80-18 & 50-265/80-20. Corrective actions security force issued itr of instruction Encl available in Central Files only ABELLJ 8 Commonwealth Edison Co 80/09/02 3pp
- 8010010736 Ack receipt of 800908 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-234/80-17 & 50-265/80-17 DAVIB:A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/09/18 1p
- B010100241 Responds to 800818 request for add1 info re IE Bulletin 79-14. "Seismic Analysis for As-Built Bafety-Related Piping Bys " List of sys where pipe stress levels exceed one-half of ultimate mat1 stress will be provided monthly JANECEK, R F Commonwealth Edison Co 80/09/19 2pp
- 8010100250 Bubmits addl response to IE Bulletin 80-17 & Buppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Util will install continuous water level monitoring of scram discharge vols by 801201 JANECEK.R F Gommonwealth Edison Co 80/09/19, 5pg.
- 8010090420 Forwards Revision 1 to Sections 3 & 4 of inservice insp & testing program JANECEK, R. F. Commonwealth Edison Co. 80/09/30, 145pp.
- 8010160226 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IR Equipment" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30 is.
- BO102002B9 Forwards order confirming util commitments to implement action re IE Bulletin BO-17 BTELLO. V Office of Inspection & Enforcement, Office of the Director BO/10/02 Ip
- --8010200306 Order confirming util commitments to implement action re IE Bullstin B0-17 STELLO,V Office of Inspection & Enforcement, Office of the Director B0/10/02 7pp
- 8010210222 Forwards orders confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 75 of 185 Control Rods to Fully Insert During Scram at BWR"
 BTELLO.V Office of Inspection & Enforcement, Office of the Director 80/10/02, 20p.
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/10/02.
- 8010270037 Forwards IE Info Notice 80-34, "Failure of Steam Generator Support Bolting " No specific action or response requested. KEPPLER: J 0 Region 3, Chicago, Office of the Director 80/10/10.
- R. Periodic operating reports & related correspondence
- 80:0150309 Forwards monthly operating repts for Sept 1980 KALIVIANAKIS,N Commonwealth Edison Co. 80/10/01, ip
- ---8010150313 Monthly operating repts for Bept 1980 BROWN, B , TUBBB, R Commonwealth Edison Co. Bo/10/01. 22pp.
- B Reportable occurrences, LERs & related correspondence
- BOi0100411 PNO-III-80-118 on 800622, during surveillance tests: pinhole lask found in emergency oil pump header of high pressure coolent injection sys. Bys declared inoperable & shutdown of unit begun.

 CKRISBOTINGS.N. SPESSARD.R.L., HEISHMAN.R.F. Region 3, Chicago, Office of the Director. 80/06/23 1p

- 8010020406 Forwards LER 80-020/03L-0. KALIVIANAKIS,N Commonwealth Edison Co 80/09/22. 1p
- --B010020417 LER 80-020/03L-0 on 800828 during suppression chamber to drywell seperation test:nitrogen makeup valve M0-2-16057-57 would not close. Caused by grounded windings on valve motor operator. Windings repaired & motor replaced.

 HANNUM.D Commonwealth Edison Co. 80/09/19 ip.
- 8010020425 Forwards LER 80-019/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/09/22 ip.
- --8010020436 LER 80-019/03L-0 on 800829, recirculation pump motor generator A field breaker opened Caused by failurs of control power transformer for recirculation motor generator A Transformer replaced KOPACZ, J Commonwealth Edison Co. 80/09/22, 2pp
- B010210304 Forwards LER 80-021/03L-0, KALIVIANAKIS,N. Commonwealth Editon Co. 80/10/05, 1p
- --8010210509 LER 80-021/03L-0. on 800914; core spray valve MO-2-1402-3A would not reopen from control room Caused by sticky torque switch on valve operator. Valve motor operator will be inspected during next outage MURRAY, R. Commonwealth Edison Co. 80/10/06, 2pp.
- 8010300441 Forwards LER 80-022/03L-0, KALIVIANAKIS,N Commonwealth Edison Co. BO/10/15. 1p.
- --8010300444 LER 80-022/03L-0 on 801005; isolation valves A0-2-203-1C & G0-2-203-1D had closure times of less than 3 seconds, Caused by spead control being out of adjustment, Valves ratimed. KEHRET, D. Commonwealth Edison Co. 80/10/15. 2pp.
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8003180348 Forwards draft of emergency plan, revising 791206 plan, which was submitted in response to NRC 791010 request.

 FAY.C. H. Hisconsin Electric Power Co 80/05/07. Lp.
- --8005150353 Preliminary draft of revised emergency plan. * Wisconsin Electric Power Co. 80/05/30. 300pp.
 - 17300440 Forwards emergency plan, revised draft, Jul 1980. TAY, C. W. Wisconsin Electric Power Co. 80/07/25. Ip.
 - 8007300444 Emergency plan preliminary draft.
 * Wisconsin Electric Power Co 80/07/31, 222pp.
- Oi0060031 Provides info re access of NRC & contractor personnel to facility to conduct appraisal of health physics program. Onsite phase scheduled for B00908 Requests that appropriate badges be authorized for personnel listed in Entli.
 KEPPLER.J. 9. Region 3: Chicago: Office of the Director. 80/08/21.
- 3007240644 Forwards Revision 13 to emergency plan manual. BURBTEIN, S. Misconsin Electric Power Co. 80/09/23, ip.
- --BOOT280647 Revision 13 to emergency plan manual.

 * Wisconsin Electric Power Co. BO/09/15. Spp.
- 8010230133 Ack receipt of 791207 & 800529 ltrs transmitting changes to security plan. Changes do not decrease safeguards effectiveness & are consistent w/provisions of IOCFR30, 34p. CLARK, R. A. Operating Reactors Branch 3. 80/09/26. 2pp.
- 8010210500 Forwards status of fire protection mode per Amende 39 k 44 to licenses DPR-24 k DPR-27. Justifications for schedule delays encl.
 BURDTEIN B. Wisconsin Electric Power Co. 80/10/13. 127pp.
- 8010240183 Forwards revisions to modified amended security plan. Revisions withheld (ref 10CFR2.790). BURSTEIN.B. Misconsin Electric Power Co. 80/10/21. ip.

- O Adjudicatory correspondence
- 8010020418 Responds to 800815 ltr re concerns of JC Neess of HI Environ Decade about tube degradation at facility Request for adjudicatory hearing referred to ASLB for determination DIRCKS/H. J. Office of the Executive Director for Operations 80/09/12 ip
- --8010020424 Requests response to encl ltr from JC Nesss of WI Environ Decade seeking adjudicatory hearing re facility tube degradation PROXMIRE. W Senate 80/08/15 7pp
- 8010020430 Responds to 800B15 ltr re concerns of JC Neess of WI Environ Decade about tube degradation at facility. Request for adjudicatory hearing referred to ASLB for determination DIRCKB.H J. Office of the Executive Director for Operations 80/09/12. 3as.
- ---8010020440 Requests response to encl itr from JC Nesss of WI Environ Decade seeking adjudicatory hearing re facility tube degradation. ZAELOCKI.C J House of Rep., Foreign Affairs 80/08/15. 7pp
- 80:0010135 Responds to 800826 itr expressing concerns re facility tube degradation. Since itr deals w/matters currently before ASLB which Commission may be called upon to review related Commission comment inappropriate MURRAY, J.P. Rulemating & Enforcement Division 80/09/17 ip
- 8010060085 Forwards order revising 800827 order for mod of OLs, in entirety.
 EIBENHUT, D. © Division of Licensing. 80/09/19. 2pp.
- --8010060090 Order revising 800829 order for mod of OLs DPR-24 & DPR-27 published in 800911 FR, in entirety Response to IE Bulletin 79-018 must be filed by 801101. Request for hearing will not stay affectiveness of order UCS petitions discharged. EIBENHUT, D. O Division of Licensing. 80/09/19 App
- B0100R0027 Responds to B00916 ltr expressing concerns re safety issues arising from degradation of steam generator tubes.

 Institution of adjudicatory hearings is being considered by ABLB upon request of BI Environ Decade W/Certificate of Svc.

 HURRAY: J P Rulemaking & Enforcement Division 80/09/30 2pp
- 8010080465 Expresses concern by MI DDJ over NRC handling of authorisation of facility power resumption Environ Decade 800825 request for hearing should be granted.
 81NDERBRAND.C. Wisconsin: State of 80/10/03 2pp.
- 8010240435 Discusses CA Sinderbrand 801003 concerns, NRC 800808 authorization & response to State of MI Environ Decade 800826 ltr re-facility operation resumption Certificate of svc encl GEARNOFF, O Shaw, Fittman, Potts & Trowbridge, 80/10/21 3pp
- J. Insurance & indemnity information
- BO102B0536 Requests Endorsements 52-55 to Policy NF-178.
 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity).
 80/09/24. 1p.
- 8010060312 Advises that Endorsements 52-55 to NELIA Policy NF-178 were sent to NRC on 770602 & 780206 Copies of 770602 & 780206 transmittals encl.

 DUNDAS: M. J. Wisconsin Electric Power Co. 80/09/30. ip
- --8010060315 Forwards Endorsements 52-55 to NELIA Policy NF-178 & Endorsements 43 & 44 to MAELU Policy NF-53 DUNDAS.M.J. Wisconsin Electric Power Co. 77/06/20 1p.
- --8010060316 Forwards Endorsements 54 & 55 to NELIA Policy NF-178 & Endorsements 1 to NELIA Binders EB18, EB19, XB18 & XB19 DUNDAS, N. J. Wisconsin Electric Power Co 78/02/06. Spp.
- P. Operating license stage documents & correspondence
- B010010045 Approves util response to NRC 791109 ltr re portions of ECC8 evaluation models dealing w/fuel cladding swelling & incidence of rupture. No further action required. CLARK, R. A. Operating Reactors Branch 3. 80/09/10, ip
- 8010220099 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT.D. 9. Division of Licensing. 80/09/19. Z8pp

- B010060354 Requests add1 90 days to provide info re adequacy of station distribution sys voltages per 8000901 ftr FAY: C W Misconsin Electric Power Co. 80/07/26 Ip
- 8010060385 Interim mod to Tech Spec Change Requests 42 & 58.Tech Spec 15 4 5 II.B 2 should be revised to delete procedural steps associated w/surveillance testing requirement of spray additive valve BLRSTEIN.S Wisconsin Electric Power Co 80/09/30 3pp
- 60:0270249 Requests recalculation of boron dilution event for cold shutdown w/RCS drained to half-pipe level & cold shutdown w/no reactor coolant pumps running Reanalysis & commitment to rayise procedures should be completed within &O days. CLARK.R A Operating Reactors Branch 1. 80/09/30 3pp.
- 8010280014 Grants 800725 request for interim relief from ABME Section XI inservice testing requirements re pump & test valve program, Compliance w/existing Tech Specs is required, pending NRC 4final evaluation, FR notice encl. CLARK, R A. Operating Reactors Branch 3, 80/09/30, 3pp.
- --BOIO2BODIB Notice of granting of relief from ABME Bection XI intervice testing requirements CLARK, R A Operating Reactors Branch 3. 80/09/30. 2pp.
- 8010220131 Advises that error in Westinghouse STS re depth of water in refueling cavity is not applicable to facilities.

 CLARK, R A Operating Reactors Branch 3. 80/10/01, 2pp.
- 8010380672 Partially denies 790918 request that info re mgt & technical staff capabilities be withheld (ref 100FR2 790). Forwards consultants' listing of util resources, List withheld tref 100FR2. 790) CLARK, R. A. Operating Reactors Branch 3. 80/10/06. 3pp.
- 801021054A Advises that annual refueling outage is rescheduled to 801114. Steem generator tube sleeves will be installed during outage to evaluate sleeving as repair procedure for steam generator tube degradation.

 BURGTEIN. 8. Wisconsin Electric Power Co. 80/10/14 ip.
- 8010210528 Advises of plans re Cycle 9 reload core Core will be designed to operate per nominal design perameters. Tach Brecs & current setpoints. Reload fuel mechanical & thermalhydraulic design for Cycle 9 will be unchanged BURSTEIN, B Wisconsin Electric Power Co. 80/10/14 2pp.
- BO10240517 Hesponds to NRC 800611 itr re proposed Tech Spec changes for all facilities to provide for redundancy in decay heat removal capability. Plant specs already address concerns & require no changes. BURSTEIN. B Wisconsin Electric Power Co 80/10/14 3pp.
- Q Inspection reports, IE Bulletine & correspondence
- 8010010859 Forwards IE Insp Repts 50-266/80-12 & 50-301/80-12 on BO0630-0730 & notice of violation. HEIBHMANR F. Region 3. Chicago. Reactor Operations Nuclear Support Branch. B0/08/22. 2pp.
- --8010010860 Notice of violation from insp on 800630-0730.
 # Region 3, Chicago, Office of the Director. 80/08/21 ip.
- --8010010863 IE Insp Repts 80-266/80-12 & 50-301/80-12 on 800630-0730. Noncompliance noted: failure to properly control protective clothing usage & access into controlled area. HARNICK.R.F. o QULDEMOND.N.Q. HAOUERR L. Region 3, Chicago, Office of the Director. 80/08/21. 9pp.
- 8Di0210043 Provides updated info re admittance of Region 3 personnel to facilities. Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas.

 KEPPLERIJ. 0 Region 3, Chicago, Office of the Director. 80/09/03. 4pp.
- 6010030521 Forwards 800606 response to IE Bulletin 80-06 w/cath of affirmation not previously submitted. FAY.C.H. Hisconsin Electric Power Co. 80/09/09, ip.
- 8010090172 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Qualification of number of Components could not be documented because of unaveilability of equipment qualification records. H/o encl. BURBTEIN.B. Wisconsin Electric Power Co. 80/09/12. 2pp.

- 8010100287 Ack receipt of 800702 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/80-10 & 50-301/80-10 KEPPLER, J. O. Region 3: Chicago, Office of the Director 80/07/19 in
- 8010270459 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Cenerator Decontemination "No specific action or response requested.

 KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/25, in
- 8010160245 Forwards Suppl 2 to IE Bulletin 79-018, "Environ dualification of Class IE Equipment," No written response required.

 KEPPLER, J. O Region 3, Chicago, Office of the Director 80/09/30, ip
- 8010200462 Responds to 800912 request for permission to perform eddy-current insp on several hot leg steam generator tubes. Insp may be scheduled during Nov outage. GA Reed should be contacted for scheduling & security details. FAY.C.H. Hisconsin Electric Power Co. 80/09/30. ip
- 8010280082 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required MEPPLER.J.O Region 3, Chicago, Office of the Director. 80/10/02, 1a.
- 8010290036 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested. KEPPLER. J. C. Ragion 3. Chicago, Office of the Director. 80/10/10.
- R. Periodic operating reports & related correspondence
- 8010130394 Forwards monthly operating repts for Bept 1980. FAY. C. N. Hisconsin Electric Power Co. BO/10/08. ip
- --B010180397 Monthly operating repts for Sept 1980, FAY, C. H. Wisconsin Electric Power Co. B0/10/03, Spp.
- 8010280401 Forwards computer printout of draft effluent & waste disposel semiannual rept for 1978, per RA Hartfield 801006 ltr. H/o encl.
 FAY: C. H. Wisconsin Electric Power Co 80/10/22 ip.
- B Reportable occurrences, LERs & related correspondence
- 8010140381 PNO-III-80-101: on 800521, Region 3 hotline to site was inoperable because microwave link had been redesignated for use in linkup for President Carter trip to State of MA. Sys was again operative on 800522.

 SHITH, J. D. WARNICK, R. F. HEISHMAN, R. F. Region 3, Chicago, Office of the Director. 80/05/22. 1p.
- B010100406 PNU-III-80-ii14:on 800609.operator discovered improper electrical lineup where two engineered safety feature huses were tied together improper electrical lineup was established for loss of ac power test on 800502.

 SMITH, J. D., HARNICK, F., HEISHHAN, R.F. Region D. San Francisco. Office of the Director, 80/06/10, 1p.
- 801010040B PNG-III-B0-111 on 800609, during power operation, operator found improper breaker lineup of main control board. Lineup was immediately corrected, Licensee is investigating.

 BHITH, J.D., WARNICK, R.F. Region 3, Chicago, Office of the Director.

 80/06/10. 1p.
- BO10020477 Forwards LER BO-010/03L-0. FAY, C. W. Wisconsin Electric Power Co. BO/09/18. ip.
- --8010020482 LER 80-010/03L-0, on 800827, during normal operation, after redundant containment spray pump recirculation phase suction valve maint, operability test was not performed. Caused by personnel failure to fully comprehend maint procedures. FAY, C. H. Wisconsin Electric Power Go. 80/09/18 3pp
- 8010180379 Forwards LER 80-011/03L-0 FAY, C. H. Hisconsin Electric Power Co. 80/10/06. 1p.
- --8010180384 LER 80-011/03L-0; on 800926, found that, Aug 1977-8ept 1980, containment spray sys spray additive valves were tested per ABME program regulraments instead of per Tech Specs, Caused by administrative stror re NRC 770926 ltr. FAY, C. H. Hisconsin Electric Power Co. 80/10/06, 3pp.

- DOCKET SO-267 FORT ST VRAIN NUCLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- 8009100240 Forwards Draft 3 of radiological emergency response planincluding response to NRC 800723 ltr Requests meeting w/NRC to evaluate 8/or accept util position as soon as possible WAREMOURG, D W Public Service Co. of Colorado 80/08/28 2pp
- 8010060162 Forwards emergency planning info for LPDR collection Math should be put in conspicuous place due to anticipated public interest M/o encls BOUDER, J L Division of Rules and Records 80/09/29 ip
- O Adjudicetory correspondence
- 8010100037 Forwards revised 600827 order for mod of license, correcting refs 155ENHUT, D. O Division of Licensing 80/09/19 2pp
- --B010100039 Revised order for mod of license, correcting refa EISENHUT, D G Division of Licensing 80/09/19 App
- J. Insurance & indemnity information
- 8010280607 Requests Endorsement 44 to Policy MF-49 & Endorsements 50 & 51 to Policy NF-192
 DINITZ:I Utility Finance Branch (formerly Antitrust & Indamnity).
 80/09/24 | Ip
- O10070532 Forwards Endorsement 44 to MAELU Policy MF-69 & Endorsements 50 & 51 to NELIA Policy NF-192.in response to NRC 800924 ltr OASCHLER, J. A Public Service Co of Colorado 80/09/30 1p.
- Operating license stage documents & correspondence
- B010210263 Submits engineering evaluation of hallom circulator water turbine speed valve 120 VAC bus configuration. No new safety considerations Configuration scheduled to be changed during 1981 refueling outage

 BHART.F E Public Service Co of Colorado B0/07/31 28p.
- 8010270099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected toble of implementation schedule also encl. EISERHUT.D G Division of Licensing 80/09/19 28pp
- B0100106B: Forwards "Test Evaluation Rept of Thermal Stress (T/8) Test for Core Support Graphits." "Test Evaluation Rept for POX Fracture Hechanics" S: "Generic-Graphite Design Hat! Properties "Repts available in Central Files only, LOPEZ-ARAMSULA General Atomic Co (subs of Quif Cil Co) 80/09/23 in
- 3010160535 Forwards application for emend of License DPR-34, changing Tech Space 2 0 & Tables 3 3 1 & 4 4-1 through 4 4-4 to revise instrument setpoints, LEE:O R. Public Service Co of Colorado 80/10/01, 2pp.
- --B010160541 Application for amend of License DFR-34, changing Tech Specs 2 0 & Tebles 3,3 1 & 4 4-1 through 4,4,4 to revise instrument setpoints LEEFO R Public Service Co. of Colorado 80/10/01. 11pp.
- --8010140543 Proposed changes to Tech Specs 2.0 & Tables 3 3.1 & 4.4-1 through 4 4-4 ravising instrument setpoints. Supporting documentation encl.

 * Public Service Co. of Colorado 80/10/01 52pp.
- 3010080464 Forwards application for amend of License DPR-34, changing Tech Specs Table 6 1-1 re in-core residence times of fuel test elements. Cless II fee encl
 LEE.G R Public Service Co. of Colorado. 80/10/03. 1p.
- --8010080467 Application for amend of License DPR-34, changing Tech Specs Table 6 1-1 re in-core residence times of fuel test elements. LEG.O R. Public Service Co. of Cotorado. 80/10/03, 7pp.

- ---BD10080472 Proposed Tech Spac Table 6 1-1 re in-core residence times of fuel test elements Safety analysis rept encl # Public Service Co of Colorado B0/10/03 50pp
- 8010220648 Orants 90-day extension for implementation of requirements for Amend 22 to OL MILLER, J.R. Standardization & Special Projects Branch 80/10/08.
- SO10210342 Requests extension until B01215 to provide requested Tech Spec changes re electrical power sys Extension will allow completion of evaluation of emergency power sys design & determination of extent of Tech Spec changes MAREMBOURGED Public Service Co of Colorado 80/10/15 1p
- 8010270361 Responds to NRC 800025 itr requesting review of power systs determine capacity of offsite sys Proposes plant mode resecond level voltage protection w/time delay & autometic bactup connection to offsite power SHART.FE Public Service Co of Colorado 80/10/20 3pp
- 8010270362 Withdraws 800829 request for hearing re NRC 800829 order amending License DPR-34 to require that certain info concerning environ qualification of Class IE electrical equipment be provided by 801101.
 FULLER, J K Public Service Co of Colorado 80/10/20 2pp
- 8010310388 Responds to NRC 800825 request for confirmation re acceptability of voltage conditions on facility electric distibution sys Five 230 kV transmission lines from separated power sys grid locations connected to switchyard BHART:F E Public Service Co of Colorado 80/10/24 App
- B010310579 Forwards list of applications for which fees are required.
 Requests fee submittal
 MILLER, H O. License Fee Management Branch 80/10/24 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8010230097 Submits supplemental response to IE Bulletin 79-14, "Heisaic Analysis for As-Built Safety-Related Piping Bys " No sys impairments identified to date Beismic analysis redocumentation program completion scheduled for Sept 1981.

 BHART, F. E. Public Barvice Co. of Colorado. 80/08/25 4pp.
- B010060173 Forwards IE Insp Rept B0-267/80-16 on B00811-18 & notice of violation MADBEN.O L Region 4: Dallas: Reactor Operations Nuclear Support Branch B0/08/29 2pp
- --B010060175 Notice of Violation from insp on 800811-15.
 * Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/08/28 ip.
- --8010060178 IE lnsp Rept 50-267/80-16 on 800811-15, Noncompliance noted failure to follow procedures

 JAUDOR: J P : WESTERMAN, T F Region 4, Dallas, Office of the Director, GAOLIARBOL J.E Region 4, Dallas, Reactor Operations Nuclear Support Branch, 80/08/28 Spp
- 8010200616 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matts," BNIEZEK, J.H Division of Fuel Facility & Materials Bafety B0/08/29 tp
- 8010230032 Responds to IE Bulletin 80-19, "Failures of Mercury-Wettes Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " No subj relays used in protective sys. Five men-hours expended LEEO R. Public Service Co of Colorado 80/09/08 1p.
- 8010280110 Forwards IE Insp Rept 50-267/80-18 on 800801-31 & notice of violation MADERNO L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/09/09, 2pp.
- --8010280115 Notice of violation from insp on 800801-31.

 ** Region 4, Dallas, Office of the Director 80/09/08. 1p.
- --8010280121 IE Insp Rept 50-267/80-18 on 800801-31 Noncompliance hatef failure to comply w/procedural requirements re control room activities
 DICKERSUN. M. W., COLLING. R. E., WESTERMAN, T. F., Region 4, Dallas, Office of the Director 80/09/08, 1p

- B010300014 Forwards IE Circular 80-21, "Regulation of Refueling Crews," No written response required BEYFRIT,K V. Region 4, Dallas, Office of the Director 80/09/10 10
- 8010230073 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Byring Return to Neutral Control Buitches " No switches installed in safety-related applications Six man-hours expended LEE, O R Public Bervice Co of Colorado 80/09/18 ip
- B010040153 Ack receipt of 800428 & 0829 ltrs informing NRC of steps taken to correct violation noted in IE Insp Rept 50-247480-10 MADSEN,O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/25 ip
- --9010060153 Responds to NRC 800725 itr violations noted in IE Insp Rept 50-267/80-10 Corrective actions procedure revised to correct errors in breaker positions & to clarify breaker designations LEE, O.R. Public Service Go of Colorado 80/08/29, 1p.
- BO10160089 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required.

 BEYFRIT,K V. Region 4, Dallas, Office of the Director, BO/09/30 in.
- 8010300347 Responds to 800827 order re environ qualification of siectrical equipment for station per IE Bulletin 79-018. Equipment is qualified w/criteria consistent w/IE Bulletin 79-018 criteria. Component tables encl FULLER, J K Public Service Co of Colorado 80/10/03. 150pp
- R Periodic operating reports & related correspondence
- 8010080334 Forwards monthly operating rept for Sept 1980. WAREMBOURG.D Public Service Co. of Colorado. 80/10/03 ip.
- --B010080337 Monthly operating rept for Sept 1780. QAHM, J. W. Public Service Co. of Calorado. 80/10/01. 6pp
- S Reportable occurrences. LERs & related correspondence
- 8010070401 Forwards LER 80-051/03L-0 WAREMBBURG.D Public Service Co. of Colorado 80/10/01. Spp
- --8010070407 LER 80-051/03L-0. on 800928, during testing, 5 of 12 helium circulator seal malfunction pressure differential switch units tripped outside Tech Spec limits Caused by dirt in electrical switches. Switches readjusted to proper trip point GAMM. J W. Public Bervice Co 'of Colorado. 80/10/01 lp.
- 8010070412 Forwards LER 80-048/03L-0
 WAREMBOURG.D. Public Service Co of Colorado. 80/10/01 5pp.
- --8010070416 LER 80-048/03L-0 on 800901, during surveillance test, all six ultrasonic noise channels were found inoperable. Microphone 4/or transmitter gain had been reduced to spurious trips. Cause not stated Qain returned to acceptable levels. QAHM. J W Public Service Co. of Colorado. 80/10/01. ip.
- 8010210711 Forwards LER 80-049/03L-0. WAREMEDURG:D Public Service Co. of Colorado. 80/10/01 Spp.
- --8010210719 LER 80-049/03L-0 on 800904.PCRV rupture disc, M-11702, satpoint set at 826 paig rather than 812 paig Caused by drift in Belleville washer operating point Threaded ring adjusted until rupture disc actuated at correct setpoint.

 OAHM.J.W Public Bervice Co. of Colorado. 80/10/01. 1p.
- 8010150505 Forwards LER 80-052/01L-0. WAREMBOURG.D Public Service Co. of Colorado 80/10/09. Spp
- --8010180817 LER 80-082/011-0, on 800928, found that releases from reactor bldg sump following releases from radioactive liquid waste sys could result in excessive radionuclide concentrations. Caused by capacity & location of oil separator.

 9ARM-J.W Public Service Co. of Colorado 80/10/09. 1p
- 8010210652 Forwards LER 80-050/03L-0 WAREHBOURG, D. Public Service Co of Colorado. 80/10/14. 4pp.

- --8010210454 LER 80-050/03L-0 on 800915 during piping audit, two hydraulic snubbers installed on Class I piping were not routinely tested Caused by snubbers omitted from testing table due to oversight Procedure revised QAHM, J W Public Service Co of Colorado 80/10/14 1p
- 8010280474 Forwards LER 80-055/03L-0
 WAREMBOURG, D Public Service Co of Colorado. 80/10/24 4pp
- ~-8010280479 LER 80~055/03L~0 on 800918; sampling requirements of 88 NR 1 i were not met for night shift Caused by personnel oversight Personnel have been reinstructed as to procedure importance GAM4.J W. Public Service Co of Colorado. 80/10/24 ip
- 8010280516 Forwards LER 80-054/03L-0 WAREMBDURG, D Public Service Co of Colorado 80/10/24 5pp.
- ---9010280951 LER 80-054/03L-0 on 800926, during maint shutdown period, scheduled surveillance showed eight hydraulic shubbers to be inoperable Caused by one ampty reservoir, two interference problems & five shubbers w/improper stroke GAMM, J W Public Bervice Co of Colorado. 80/10/24, ip
- 8010280527 Forwards LER 80-053/03L-0 WAREMEDURG,D Public Service Co. of Colorado, 80/10/24. Spp
- --R010280586 LER 80-053/03L-0 on 800926 during maint shutdown period.
 seminannual test of standby diesel generators revealed
 inoperability of 18 programmer Caused by Paulty wire
 position which impaded relay contact. Mire repositioned
 QAHK, J. U. Public Service Co of Colorado 80/10/24 ip
- DOCKET 80-269 OCONEE NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 9910010408 Forwards Revision 3 of safeguards contingency plan. Plan withheld (ref 10CFR2 790)
 PARKER, W O Duke Power Co 80/09/25 ip.
- Q Adjudicatory correspondence
- 8010270321 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment. EISENHUT.D Q Division of Licensing 80/09/19 2pp.
- --B010270334 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT.D.O. Division of Licensing. 80/09/19. App
- 8010140587 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in McQuire spent fuel pool, reported in encl Power Reactor Events, Certificate of Suc
- 8010240552 Response in opposition to Carolina Environ Study Group 801006 motion to reopen record to include Jul 1980 "Unplanned Boron Dilution," rept into evidence No new info presented.
 PORTER: H. L., MCOARRY, J. M. Duke Power Co. MCOARRY, J. M. Debevoise & Liberman. 80/10/21. 7pp
- --8010240562 Affidavit addressing activities associated w/demineralizer operation & effect of boron decreased concentration.

 Certificate of Bvc encl

 ORTH-M.C Duke Power Co 80/10/21 Spp
- 8010310306 Ack receipt of 801006 FR notice & requests hearing to protect interests.
 PORTER M. L. Duke Power Co 80/10/27 ip.
- P. Operating license stage documents & correspondence
- 8010090193 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 1 3, b, "Instrumentation for Detection of Inadequate Core Cooling," Guidelines re vessel water level must be developed to pravide operators where support, ROSS,D.F. Division of Systems Integration 80/09/09, 3pp.
- 8010020040 Forwards FR notice of proposed issuance of amends to facility Ols.per util 800723 application, changing Tech Specs to permit expansion of spent fuel storage capacity, REID.R.W. Operating Reactors Branch 4 80/09/19, 2pp.

- --8010020064 Notice of proposed issuance of amends to Licenses DPR-38. DPR-47 & DPR-55 Operating Reactors Branch 4 80/09/15 4pp
- 8010220099 Forwards errata sheets amending 800903 ltr which provided preliminary clarification of THI action plan requirements Corrected table of implementation schedule also enti EISENHUT.D 0 Division of Licensing 80/09/19. 28pp
- B010230411 Forwards evaluation of B00826 response to Lessons Learned Task Force Requirement 2 1.3 b re instrumentation for detection of inadequate core cooling insufficient effort provided re advance warning of inadequate core cooling. EISENHUT, D. O Division of Licensing 80/09/24 70p
- 8010070405 Informs that 801030 is expected date of completion for preparation & review of revised "Offsite Date Calculation Natural" & proposed process control program for solid waste ty: PARKER: W D Duke Power Co 80/09/30 ip
- 8010150530 Bummary of 800904 meeting w/utils.8kW & NUS Corp re proposed Upgrade mods to auxiliary feedwater sys Agenda & 800808 memo enci. VISSING G S Operating Reactors Branch 4 80/09/30 48pp
- --BOIOISO544 Submits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys Smismically induced core melt due to loss of decay heat removal could be as much as sit times more likely than NABH-1400 astimates MATISON:R J Division of Safety Technology 80/08/08 22pp
- 9010230589 Summary of 80082; meeting w/B&W reactor bunders group re abnormal transient operating guidelines program VISSINO.0 Operating Reactors Branch 4 80/09/30 29pp
- 3010090422 Application for amend to Licenses DPR-38.DPR-47 & DPR-55, changing Tech Specs & license conditions per NUREG-0578, in response to NRC 800702 request Discussion of applicability of ST6 & Class I & III fees enci
- --B010070428 Proposed revisions to App A Tech Specs, Sections 3,4 & 6, incorporating NUREO-0578, Category A requirements Proposed license conditions encl 4 Duke Power Co B0/10/02 22pp
- 8010210040 Forwards Amends 87.87 & 84 to Licenses DPR-38, DPR-47 & DPR-35, respectively, safety evaluation & notice of issuance & availability REID:R H Operating Reactors Branch 4 80/10/07 2pp
 - 8010210046 Amends 87,87 & 84 to Licenses DPR-38,DPR-47 & DPR-55, respectively, modifying reactor vessel pressure-temp operating limit curves to enable extension of operation from four to five affective full power yes REID,R.W. Operating Reactors Branch 4, 80/10/07 10pp.
- 80102t0050 Safety evaluation supporting Amends 67,87 & 84 to Licenset DPR-38.DPR-47 & DPR-55.respectively, * Office of Nuclear Reactor Regulation, Director 80/10/07 2pp
- 8010210054 Notice of issuance & availability of Amends 87.87 & 84 to Licenses DPR-38.DPR-47 & DPR-55, respectively REID.R.W Operating Reactors Branch 4. 80/10/07. 2pp
- 10270255 Advises that 791130 response to inadvertent safety injection during surveillance testing adequately addresses concerns stated in NRC 790921 ltr.
 REID.R W Operating Reactors Branch 4. 80/10/10 200 Operating Reactors Branch 4. 80/10/10 2pm
- 010170540 Application for amend of license revising Tech Epecs 3 0 & 3.1 re operating status of RCE & limiting condition for operation.

 PARKER, H O Duke Power Co. 80/10/14. 3pp
- --8010170544 Proposed Tech Spect 3 0 & 3.1 re operating status of RCS & limiting condition for operation,
 + Duke Power Co 80/10/14 2pp
- B010230404 Forwards description of spent fuel rack surveillance program supplementing info provided in util 800701 & 25 ltrs Discussions w/NRG indicated that info was needed to complete NRC review.

 PARKER, W. O. Dute Power Co. 80/10/15. 2pp.
- 8010240412 Application for amend of Licenses DPR-38, DPR-47 & DPR-55, submitted as proposed Yech Spec 6 6.2.1.per 800529 request. PARKER.W.O Duis Fower Co. 80/10/20 2pp

- --8010240415 Tech Spec 6 6 2 1 re ROs * Duke Power Co 80/10/20 3pp
- 8010310405 Application to amend OL revising Tech Specs Sections 3 6 & 4.4.1 re reactor bldg & containment leakage tests, respectively, to reflect code criteria Proposed change suppls 761120 submittal PARKER, W O Duke Power Co 80/10/24 ip
- --8010310407 Proposed Tech Specs Sections 3 & & 4 4 i rm reactor \$14g & containment leakage tests, respectively, to reflect code criteria Test requirements bases & justification for reverse direction testing enc)

 * Dute Power Co = 80/10/24 24pp
- @ Inspection reports, IE Bulletins & correspondence
- 7906200279 IE Insp Repts 50-269/79-11.50-270/79-11 & 50-287/79-11 pp 06200279 IE Insp Repts 30-2077/7711,00-2007/7711 & 00-2077/711 on 790301-29 No noncompliance noted Major areas inspected plant operations, followup of info notices, physical security & LER JAPE, F Ragion 2, Atlanta, Office of the Director 79/04/28 655
- 7909280230 IE Insp Repts 50-269/79-14.50-270/79-14 & 50-287/79-15 on 790501-31 Noncompliance noted failure to sample & analyze prior to liquid release & failure to follow procedures to maintain plant status
 WHITENER, H L Region 2, Atlanta, Office of the Director. 79/07/13
- B005230330 Forwards waste packaging insp rept on B00313-14, No noncompliance noted, BTOHR.J F Region 2. Atlanta, Fuel Facility & Materials Bafety Branch B0/04/07 2pp
- ---800523034i Waste packaging insp rept on 800313-14 No noncompliants noted Hajor areas inspected licenses-shippor vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DDT placerding requirement PDTER.J P Region 2. Atlanta, Fuel Facility & Materials Hafsty Branch 80/03/28. 4pp
- 8008060175 Forwards Haste Packaging Insp Rept 15000039/80-07 on 80051\$ & 16 No noncompliance noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/06/23 2gp
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 Na noncompliante noted Major areas inspectod/compliance w/NRC & DOT regulations. TROUP. G. Rogion 2: Atlanta: Fuel Facility & Materials Bafaty Branch 80/06/23 6pp
- B01023010B Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls," No unitten response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/08/29
- B010090203 Forwards Revision 4 to util 90-day response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" Info is finel & should replace all previous submittals H/o encl PARKER, N. O. Duke Power Co. 80/09/15 3pp
- 8010170204 Forwards 90-day response to IE Bulletin 79-018, "Environ Qualification of IE Equipment " Info included re master sys-components lists sys component evaluation & equipment required to maintain cold shutdown following LOCA PARKER, M. D. Duke Power Co. 80/09/15 410pp
- 8010010090 Ack recaipt of 800714 ltr informing NRC of steps taken to correct violation noted in IE Inap Repts 80-269/80-20. S0-270/80-15 & 50-287/80-14 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/09/16 ip
- --8010010090 Responde to NRC 800620 ltr re-violations noted in IE Insp. Repts 50-269/80-20, 50-270/80-15 & 50-287/80-14 Corrective actions: emergency procedure on boron dilution reviewed & reactivity balance procedure implemented PARKER-W.O Duke Power Co 80/07/14. Opp.
- --8010010102 Forwards IE Insp Repts 50-269/80-20,50-270/80-18 & 50-287/80-14 on 800501-30 & notice of violation LEWIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/06/23 2pp
- --8010010112 Notice of violation from insp on 800501-30.
 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch.
 80/06/20 2pp

- --8010010131 IE Insp Repts 50-269/80-20,50-270/80-15 & 50-287/80-14 on 800501-30 Noncompliance noted failure to maintain correct status of demineralizer & to provide data to determine shutdown margin

 JAPS, F. ORDERS, W.T. Region 2. Atlanta, Office of the Director

 MARTIN.R D. Region 2. Atlanta, Reactor Operations Nuclear Support

 Branch 80/06/20 App
- 8010130275 Forwards affidavit as suppl to 800827 response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " PARKER:N O Duke Power Co 80/09/16 ip
- BO10130314 Responds to IE Bulletin 79-14, "Beismic Analysis for As-Built Bafety-Related Piping Sys " DBE wet condition analysis performed & mod of branch pipes & header junction initiated in lieu of complex nonlinear el
- 8010010538 Forwards Figure 348-0-1477-RBB-Hi.supplementing 800919 response to IE Bulletin 79-14. "Beismic Analysis for As-Built Bafety-Related Piping Sys." Figure inadvertently omitted from original submittal PARKER, W O Duke Power Co 80/09/23 2pp
- B010140041 Ack receipt of IR Insp Repts 50-269/80-30,50-270/80-26 & 50-287/80-23 on 800801-31 No proprietary info PARKER, 80 Duke Power Co 80/09/24 ip
- --8010140046 Forwards IE Insp Repts 50-269/80-30,50-270/80-26 & 50-287/80-23 on 800801-31,No noncompliance noted LEWIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/17 2pp
- --8010140051 IE Insp Repts S0-269/80-30, 50-270/80-26 & 50-287/80-29 on 800801-31. No noncompliance noted Major areas inspected LERs, surveillance testing, instrument calibr, contaminated tendon galleries & physical security ORDERS, W. MYERS, D. Region 2. Atlanta, Office of the Director MARTINIR D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/17 9pp
- 8010270482 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/24
- 8010160286 Forwards Suppl 2 to IE Sullatin 79-018. "Environ Qualification of Class IE Equipment " No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30

- 8010270411 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/10/02
- 8010290052 Forwards IE Info Notice 80-36, "Failure of Steem Generator Support Bolting," No specific action or response requested, D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010210434 Forwards monthly operating repts for Sept 1780 PARKER, W O Duke Power Co 80/10/15 1p
- --8010210437 Monthly operating repts for Sept 1980 REAVIS, J. A Duke Power Co 80/10/15 16pp
- 5 Reportable occurrences, LERs & related correspondence
- 8010160748 PNU-II-80-ii5 on 800620, two 55-galion barrels containing approx 20 gallons each of contaminated waste oil were inadvertently mixed w/2000 gallons of uncontaminated waste oil Waste oil truck has been returned to plant for storage MARTIN.R. LEWIS.R C. Region 2, Atlanta, Office of the Director. 80/06/25 1p
- 8010170002 PND-II-80-116: on 800625, on Unit 3, cracks were identified in three of sixteen stude used to attach lower manuay cover to steam generator. Licensee has examined remaining stude & found addl cracks MARTIN,R., LEMIS,R.C. Region 2, Atlanta, Office of the Director. 80706/26 1p

- B010080443 Forwards LER 80-027/03L-0 PARKER, W O Duke Power Co 80/10/02 3pp
- -8010080445 LER 80-027/03L-0 on 800902, rod 8 of group 7 dropped resulting in reactor tilt in success of Tech Specs Caused by pin being pushed out of place in connector & allowing C phase on stator to open Repairs completed JONES, J L Dute Power Co 80/10/02 19
- 8010070537 Forwards LER 80-028/03L-0 PARKER: N O Duke Power Co 80/10. 80/10/03 200
- --B010070546 LER 80-028/03L-0 on B00903, high pressure syc water pump started due to lose of power to elevated level sensing switches Caused by lightning striking cable Lightning errestors replaced JONES, J L Duke Power Co 80/10/03 1p
- H010210951 Informs that LER B0-031 will be submitted by H01030 following investigation PARKER, N U Duke Power Co H0/10/16 2pp
- DOCKET 50-270 DODNEE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8010010508 Forwards Revision 3 of safeguards contingency plan, Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/09/25 1p
- O Adjudicatory correspondence
- 8010270321 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENMUT.D 0 Division of Licensing 80/09/19 2pp.
- ---8010270334 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EIBENNUT.D © Division of Licensing 80/09/19 App
- 8010140587 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in McGuire spent fuel pool, reported in encl Power Reactor Events Certificate of Svc encl
 RILEY, J L Carolina Environmental Study Group 80/10/06 12pp.
- 8010240552 Response in opposition to Carolina Environ Study Group 801006 motion to reopen record to include Jul 1980 "Unplanned Boron Dilution," rept into evidence. No new info PORTER, W L , MCGARRY, J. M Duke Power Co MCGARRY, J. M Debevoise & Liberman 80/10/21 7pp
- 8010310306 Ack receipt of 801006 FR notice & requests hearing to protect interests
 PORTER, W L Duke Power Co 80/10/27 ip.
- P Operating license stage documents & correspondence
- 8010090195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 i 3 b. "Instrumentation for Detection of Inadequate Core Cooling " Ouidelines re vessel water level must be developed to provide operators w/max support RQSS,D F Division of Systems Integration. B0/09/09. 3pp
- 8010020060 Forwards FR notice of proposed issuance of amends to facility Olssper util 800723 application changing Tech Brecs to permit expansion of spent fuel storage capacity REIDR.N. Operating Reactors Branch 4. 80/09/15
- --B010020064 Notice of proposed issuance of amends to Licenses DPR-38, DPR-47 t DPR-55
 REID,R W. Operating Reactors Branch 4 B0/09/15. 4pp.
- B010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implamentation schedule also encl EIBENHUTID 9. Division of Licensing. 80/09/19. 28pp.

- 8010230411 Forwards evaluation of 800826 response to Lassons Learned Task Force Requirement 2.1 3 b re instrumentation for detection of inadequate core cooling insufficient effort provided re advance warning of inadequate core cooling EIBENHUT.D O Division of Licensing. 80/09/24 7pp
- 8010070405 Informs that 801030 is expected date of completion for preparation & review of revised "Offsite Dose Calculation Hanual" & proposed process control program for solid waste PARKER, H. O Duke Power Co 60/09/30 ip
- 80(0150530 Bummary of 800904 meeting w/utils,8kW & NUS Corp re proposed upgrade mods to auxiliary feedwater sys. Aganda & 800808 memo VISSING G B Operating Reactors Branch 4. 80/09/30 48pp.
- --8010150544 Submits analysis & recommendations re plants w/o seismically qualified auxiliary feadwater sys Ssismically induced core melt due to loss of decay heat removal could be as much as six these more likely than MARH-1400 estimates.

 HATTSON.R J Division of Safety Technology, 80/08/08 22pp.
- 8010230587 Summary of 800821 meeting w/BiW reactor numers group re abnormal transient operating guidelines program VISBING.0 Operating Reactors Branch 4 80/09/30 29pp.
- 8010090422 Application for amend to Licenses DFR-38.DFR-47 & DFR-53, changing Tech Specs & license conditions per NUREG-0378, in response to NRC 800702 request. Discussion of applicability of 818 & Class I & III fees enci
- --BD10090428 Proposed revisions to App A Tech Specs, Sections 3.4 & 6. incorporating NAREO-0378, Category A requirements. Proposed license conditions encl
 # Dute Power Co 80/10/02. 22pp.
 - 10070387 Notifies that startup testing summary for facility Cycle 5 is being prepared & reviewed Summary will be east by PARKER, W. O. Duke Power Co 80/10/03, 10
- >10210040 Forwards Amends 87.87 & 84 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.
 REID.R.W. Operating Reactors Branch 4 80/10/07. 2pp
- B010210046 Amends 87,87 & 84 to Licenses DPR-3B.DPR-47 & DPR-55, respectively, modifying reactor vessel pressure-temp operating limit curves to enable extension of operation from four to five effective full power yrs.
 REID,R.H. Operating Reactors Branch 4, 80/10/07, 10pp
 - 8010210050 Safety evaluation supporting Amends 87,87 & 84 to Licenses DPR-38, DPR-47 & DPR-35, respectively
 4 Office of Nuclear Reactor Regulation, Director. 80/10/07 2pp
 - 8010210056 Notice of issuance & availability of Amenda 87.87 & 84 to Licenses DPR-38, DPR-47 & DPR-53, respectively. REID, R. W Operating Reactors Branch 4, 80/10/07. 2pp
 - 0270255 Advises that 791130 response re inadvertent safety injection uring surveillance testing adaquately addresses concerns tated in NRC 790921 ltr.

 ID.R. U Operating Reactors Branch 4 80/10/10 2pp
 - 170540 Application for amend of license revising Tech Specs 3 0 & 1 re operating status of RCS & limiting condition for levation peration ARKER,W D. Duke Power Co. 80/10/14, Spp
 - 010170344 Proposed Tech Specs 3.0 & 3.1 re operating status of RCS & limiting condition for operation * Duke Power Co. 80/10/14. 2pp
- 3230404 Forwards description of spent fuel rack surveillance program, supplementing info provided in util 800701 & 25 ltm. Discussions w/RC indicated that info was needed to caplete NRC review.

 FARKER.N.D. Dute Power Co. 80/10/15, 2pp.
- i) 240097 Forwards startup testing summary. No deviations between a leaved & predicted data were observed. Testing completed 8 0709.

 P. Wiker, H. O. Duke Power Co. 80/10/20 1p.
- 8 110240397 "Unit 2, Cycle 5, Startup Testing Summary."
 * Duke Fower Co 80/10/31, 13ep.

- B010240412 Application for amend of Licenses DPR-3B, DPR-47 & DPR-55, submitted as proposed Tech Spec 6 6 2 1, per 800529 request PARKER, W D Dute Power Co 80/10/20 2pp
- --8010240415 Tech Spec 6 6 2 1 re ROs
- 8010310405 Application to amend OL, revising Tech Specs Sections 3 & 4.4 i re reactor bldg & containment leakage tests, respectively, to reflect code criteria Proposed change supple 741130 submittal PARKER, W 0 Duke Power Co 80/10/24 ip
- --8010310409 Proposed Tech Specs Bections 3 6 & 4 4 1 re reactor blf: containment leakage tests, respectively, to reflect code criteria Test requirements bases & justification for reverse direction testing encl

 * Duke Power Co = 80/10/24 24pp
- O Inspection reports, IE Bulletins & correspondence
- 8008060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on BOO51 & 16.No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/23 2pp.
- --B00B060177 Waste Packaging Insp Rept 15000039/B0-07 on B00315 & 16. noncompliance noted Major areas inspected; compliance w/ARC & BOT regulations TROUP, 0 L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/06/23. 6pp.
- 8010230108 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls." No written response required O'REILLY,J P. Region 2, Atlanta, Office of the Director 80/09/29
- 8010090203 Forwards Revision 4 to util 90-day response to IE Bulletis 79-018, "Environ Gualification of Class IE Equipment." Info is final & should replace all previous submittals H/o encl PARKER, H O Duke Power Co. 80/09/15 3pp.
- 8010170204 Forwards 90-day response to IE Builetin 79-018, "Environ Qualification of IE Equipment." Info included re master systemponents lief, systemponent evaluation & equipment required to maintain cold shutdom following LOCA PARKER, H O Duke Power Co. 80/09/15 410pp.
- 8010010080 Ack receipt of 800714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-20, 50-270/80-15 & 50-287/80-14, LEHIB/R.G. Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch, 80/09/16, jp.
- -8010010070 Responds to NRC 800623 ltr re violations noted in 1E Inc. Repts 50-269/80-20,50-270/80-15 & 50-287/80-14 Corrective actions energency procedure on baron dilution reviewed & reactivity batance procedure implemented.
 PARKER, N O Duke Power Co 80/07/14. 3pp.
- --8010010102 Forwards IE Insp Repts 50-269/80-20,50-270/80-15 & 50-287/80-14 on 800501-30 & notice of violation. LEHIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/06/23 2pp
- --8010010112 Notice of Violation from insp on 800501-30.

 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/20 2pp
- --8010010131 FE Insp Repts 50-269/80-20,50-270/80-15 & 50-287/90-14 on B00501-30, Noncompliance noted failure to maintain correct status of demineralizer & to provide data to determine status of demineration of the Director shutdown mampin.

 JAPE, F., ORDERS, W. T. Region 2, Atlanta, Office of the Director MARTINIR. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. B0/06/20 App
- 8010130275 Forwards affidavit as suppl to 800827 response to IE Sulletin 80-15, "Possible Loss of Emergency Notification Stys (ENS) M/Loss of Offsite Power."

 PARKER, W. O., Duka Power Co., 80/09/16, 1p
- B010130314 Responds to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys." DBE wet condition analysis performed & mod of branch pipes & header junction initiated in lieu of complex nonlinear elastic-plastic analysis, PARKER, W. O. Duke Power Co 80/09/18, 2pp.

- BDiOO1053B Forwards Figure 54B-0-1477-RBB-Hi, supplementing 800919 response to IE Bulletin 79-14. "Seismic Analysis for As-Butit Safety-Related Piping Sys " Figure inadvertently amitted from original submittal PARKER, N D Dute Power Co 80/09/23 2pp
- 8010140041 Ack receipt of IE Insp Repts 50-269/80-30,50-270/80-26 & 50-287/80-23 on 800801-31 No proprietary info PARKER, W C Duke Power Ca 80/09/24 ip
- --B010140046 Forwards IE Insp Repts 50-269/80-30.50-270/80-26 & 30-287/80-23 on B00801-31 No noncompliance noted LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/09/17 2pp
- --B010140001 IE Insp Repts 50-269/80-30.50-270/80-26 & 50-287/80-23 on B00901-31 No noncompliance noted Major areas inspected LERs, surveillance testing instrument calibr contaminated tendon galleries t physical security ORDERS, H. MYERS, D. Region 2. Atlanta, Office of the Director HARTIN.R D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/09/17 9pp
- B010270492 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/26.
- 8010160296 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "No written response required.

 O'REJLLY, J P Region 2, Atlanta, Office of the Director 80/09/30
- 80(02704): Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 is
- 80:0270052 Forwards IE Info Notice 80-36, "Failure of Steam Generator Bupport Bolting " No specific action or response requested. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/10.
- R Periodic operating reports & related correspondence
- BO10210434 Forwards monthly operating repts for Best 1980, PARKER, N O Duke Power Co. 80/10/15 ip.
- --8010210437 Monthly operating repts for Sept 1980 REAVIS, J A Duke Power Co 80/10/13 14pp.
- B Reportable occurrences, LERs & related correspondence
- BOIO;6074G PNO-II-BO-ii9 on BOO620, two 59-gallon barrels containing approx 20 gallons each of contaminated waste oil were inadvertently mixed w/2000 gallons of uncontaminated waste oil Haste oil truck has been returned to plant for storage HARTEN, E. LEHIB, R. C. Region 2, Atlanta, Office of the Director. BO/O6/25 ip.
- 8010170002 PNO-II-80-116.on 800625.on Unit 3, cracks were identified in three of sixteen stude used to attach lower manway cover to steam generator Licensee has examined remaining stude & found add1 cracks MARTIN.R. LEWIS.R.C. Region 2, Atlanta, Office of the Director 80/06/26 ip
- B010210534 Forwards LER 80-015/03L-0 PARKER, W D Duke Power Co 80/10/16 2pp
- ~-B010210537 LER 80-015/03L-0 on B00916, valve 2LP21 failed to open during performance of engineered safeguard channel test Caused by loose setscrew on motor driven pinion Screw repaired JONES, J. L. Duke Power Co. B0/10/16 1p.
- E010240475 Forwards LER 80-016/03L-0. PARKER: N O Duke Power Co 80/10/20. 3pp.
- --8010240479 LER 80-016/03L-0 on 800920, concentrated boric acid storage tank (CBAST) pump declared inoperable Caused by failure of pressure relief valve on CBAST pump Valve replaced & sump pump returned to svc. JONES, J. L. Duke Power Co. 80/10/20. 1p.
- 8010280384 Forwards LER 80-018/01T-0 PARKER, W. C. Duke Power Co. 80/10/22, Spp.

- --B010280988 LER 80-018/01T-0 on B01008 humidity in west penetration room found to be above 70% limit Caused by steam leaks on two feedwater valves Leaking valves repaired & portable fans used to reduce humidity

 JONES, J L Duke Power Co B0/10/22 1p
- DOCKET 50-271 VERMONT VANKEE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- B010210793 Forwards NRC position on mods to be made at facility to resolve open items re proposed rule 10CFR50, concerning fire protection One underground fire pump discharge main should be relocated to provide adequate separation IPPOLITO.T A Operating Reactors Branch 2 80/09/30. 6pp
- O Adjudicatory correspondence
- 8010200614 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/02 lp
- --8010200620 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02, 7pp
- 8010210206 Forwards order confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "

 STELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 2pp
- H General correspondence
- 8010020449 Forwards responses to constituent questions re-facility in response to 800522 request Delay in response caused by heavy workloads & summer vacations
 DIRCKS.M J. Office of the Executive Director for Operations
 80/09/04 5pp.
- ---B0100205B4 Requests response to constituent questions re facility CONTE,8 0 House of Rep B0/05/22 1p.
- P Operating license stage documents & correspondence
- 8010020150 Confirms 800909 telcon re util actions to be taken for testing of scram discharge instrument vol level switches. Util will implement procedures which require functional test, efter each scram event, before returing to power ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/09/11 1p.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENKUT, D.O. Division of Licensing. 80/09/19, 28pp.
- 8010070263 Advises that util response re deficiencies in regulator sys for motor generator sets is inadequate. Mods should be parformed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies IPPOLITO.T.A Operating Reactors Branch 2 80/07/24, 4pp
- 8010030413 Advises that shift technical advisor implementation program is presently underway w/completion date of 810601. Program will result in group of highly trained individuals to meet NRC requirements & goal of maximizing safe operation.

 MARBOLAIB.L D Vermont Yankee Nuclear Power Corp. 80/09/29 ip
- 8010060262 Comments on summary rept re radioactive effluents in response to NRC 800911 request. Info in section entitled "Cas Effluents Elevated Release" misleading. Kr-85 not detected in offgas mix BMITH. R. L. Vermont Yankee Nuclear Power Corp. 80/10/01. ip.
- 8010060276 Responds to NRC 800507 ltr requiring BHR licensees w/HPCI & reactor core isolation cooling (RCIC) sys to evaluate separating HPCI/RCIC initiation setpoints & modify RCIC sys logic, BNR owners group info.per 800611 ltr is appropriate.

 BMITH-R L Vermont Yankes Nuclear Power Corp. 80/10/01, ip.
- 8010100218 Provides supplemental info on purge & vent valve operability. Info & test results supplied by valve manufacturer indicate that remaining purge & vent valves are capable of operating under most severe DBA flow conditions. SMITH.R.L. Vermont Yankee Nuclear Power Corp. 80/10/03. 2pp.

- 8010150867 Application for Suppl 1 to Proposed Change 89 to License DPR-28.changing Tech Specs 2 1.3 1 & 4 1 rs min critical heat flux ratio HEIDER.L.H Vermont Yankoe Nuclear Power Corp. 80/10/07, 4pg.
- --8010150271 Proposed changes to Tech Specs 2,1,3 1 & 4.1 re min critical heat flux ratio

 Vermont Yankee Nuclear Power Corp. 80/10/07. 6pp.
- 8010150461 Application for Suppl 1 to Proposed Change 86-1 to App A Tech Specs of License DPR-28 to reflect current organizational structure of util & Yankee Atomic Electric Co & to include shift technical advisor on table HEIDER, L. H. Varmont Yankee Nuclear Power Corp. 80/10/07. 2pp.
- --8010150468 Proposed Change 86-1, Suppl 1 to App A Tech Specs, Figures 6 1 1 & 6 1 2, reflecting current organizational structure of util & Yankee Atomic Electric Co & including shift technical advisor on onsite table of organization.

 * Vermont Yankee Nuclear Power Corp 80/10/07, 2pp
- 8010270393 Forwards request for addl info re evaluation of slectrical/ bypass aspects of engineered safety features & control sys as related to containment purge sys. IPPOLITO, T A Operating Reactors Branch 2 80/10/09. 4pp.
- 8010210318 Bubmits info on NRC task action plan Itam II K 3 27 re common ref for reactor vessel level instrumentation. Program can be completed by B10115. Proposed changes to Tech Specs will be submitted by 801114. SHITH,R L Vermont Yankee Nuclear Power Corp 80/10/10, ip.
 - 10200449 Forwards addi info re NRC review of Proposed Change 90 for tydrogen monitoring sys Info in schematic form & some valve numbers previously omitted also encl.
 HITH-R L Vermont Yankse Nuclear Power Corp. 80/10/14. 2pp.
 - 10210336 Responds to NRC 800707 ltr requesting scram discharge vol Tech Spec changes Util agrees that vent & drain velves be verified open min of once per month Requirement for control rod block on high water level scram bypase hot justified. SMITH.R.L. Vermont Yankee Nuclear Power Corp 80/10/14. 2pp.
- 8010230454 Clarifies 800725 schedule for installation of torus support saddles. Welding of saddles to pressure boundary to be completed during refueling outage. Tie-down to floor mat to be completed by end of yr SMITH, R.L. Vermont Yankes Nuclear Power Corp 80/10/17. lp.
- B010240449 Responds to NRC B01009 request for schedule to submit inforce electrical/bypass aspects of RHR/LPCI sys. Info will be provided by B01215.

 BNITH.R L. Vermont Vantes Nuclear Power Corp. B0/10/20 ip
 - 10270485 Forwards add1 drawings, in response to NRC & Franklin Research Ctr request for info re bypass & reset of angineered safety features Encl oversize drawings withheld (ref 100FR2.790)

 8M1TH,R.L Vermont Yankee Nuclear Power Corp. 80/10/20 2pp.
 - 10280221 Provides responses to NRC 801001 questions to BHR scram system as related to BHR owners group criteria Facility design meets general design criteria but certain systmate should be implemented to enhance systemicality.

 HEIDER: L. H. Vermont Yankee Nuclear Power Corp. 80/10/22. 2pp.
 - 10280418 Comments on CE generic ref analysis of effects of dc power supply failure on ECCB equipment availability, in response to NRC 800425 ltr. Generic analysis determined to be conservative for facility BMITH, R.L. Vermont Yankee Nuclear Power Corp. 80/10/22, 2pp.
- . Inspection reports. IE Bulletine & correspondence
- 8004040077 Forwards Waste Pickaging Insp Rept 80-05 on 800317.No noncompliance notes. 870HR.J.P. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 80/04/14. 2pp.
- --E0040400B2 Wasts Packaging Insp Rept 80-05 on 800319. No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & prohibited articles of contents. POTTER, J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/04/04. 6pp

- 8010080168 Advises that Item 3 contained in notice of violation issued w/IE Insp Rept 50-271/79-11 requires corrective action.
 Supporting documentation withheld (ref 10CFR2 790).
 MARTIN, W G. Region 1, Philadelphia, Safeguards Branch. 80/08/19
 2pp.
- 8010030513 Responds to IE Bulletin 80-19 Util does not use mercurywetted matrix relays in reactor protection sys CONMAY.W.F Vermont Yankee Nuclear Power Corp 80/08/22 1p.
- 8010030522 Responds to IE Bulletin 80-20 No Westinghouse Type H-2 control suitches used in safety-related applications CONHAY, W.F. Vermont Yankes Nuclear Power Corp. 80/08/22 (p.
- 8010010817 Responds to IE Bulletin 80-15 Mod to emergency notificative sys completed 800813. Bys presently supplied w/backup from plant security diesel generator. Util expended 272 manhours on bulletin.
 HEIDERIL. H. Vermont Yankes Nuclear Power Corp. 80/08/28 2pp
- 8010010677 Responds to IE Bulletin 80-16 Rosemount Model 1152D pressure transmitters will be used in two applications. Transmitters will not be subj to overrange conditions. HEIDER: L. H. Vermont Yankes Nuclear Power Corp. 80/08/29, 2pp
- 8010010760 Responds to IE Bulletin 80-11 re masonry wall design. 81sti was not used as load carrying members Addl info to be submitted by 810227. BMITH.R L. Vermont Yankee Nuclear Power Corp 80/09/04. 25p
- 8010240056 Updates 800815 response to IE Bullatin 80-17, Suppl 1.
 "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR." Continuous scram discharge vol monitor will be installed prior to startup after 1980 refueling.
 MARSOLAIS, L D Vermont Yankse Nuclear Power Corp 80/09/19, 3;
- 8010200614 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 8TELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 1p.
- --8010200620 Order confirming util commitments to implement action (4 & Bulletin 80-17.
 BYELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 7pp.
- 8010210206 Forwards order confirming util commitments to implement action re IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Screm at BWR"

 STELLOY, Office of Inspection & Enforcement, Office of the Director, 80/10/02. 2pp.
- 8010240175 Forwards IE Circular 80-22, "Confirmation of Employee dualifications" No written response required. ORIER, B H. Region 1, Philadelphia, Office of the Director. 80/10/02.
- B010240252 Ack receipt of 800915 ltr informing NRC of steps talen to correct violation noted in IE Insp Rept 50-271/80-05. BRUNNER, E. J. Region i. Philadelphia. Reactor Operations Nuclear Support Branch. B0/10/07 1p.
- --8010240262 Responds to NRC 800825 ltr re violation noted in IE Insj Rept 50-271/80-05. Corrective actions: proper radiological controls established'& more conspicuous posting & barricading put around process line. CONHAY. M. F. Vermont Yankee Nuclear Power Corp. 80/09/15. 3pp
- --8010240271 Notice of violation from insp on 800428-0516 % Region i, Philadelphia, Office of the Director, 80/08/49, Is
- 8010160381 Forwards Revision 5 to inservice insp program.
 SMITH,R.L. Vermont Yankes Nuclear Power Corp. 80/10/10. ip.
 - --8010160586 Revision 5 to inservice insp program.

 * Vermont Yankes Nuclear Power Corp. 80/10/01, 153pp.

i

- 8010280216 Forwards IE Info Notice 80-36. "Failure of Steam Cemerator Support Bolting " No specific action or response requested ORIER, B H Region 1. Philadelphia. Office of the Director 80/10/10 ip
- , B0102B0337 Discusses insp program re four modified surveillance assemblies Mod consisted of replacement of water rods w/spacer capture rods w/short-end plugs.Reduced wear rate can be attributed to short-end lower-end plug CONHAY, W.F. Vermont Yankes Nuclear Power Corp. B0/10/23 2p
 - R Pariodic operating reports & related correspondence
 - BO10150300 Forwards monthly operating rept for Bept 1980 CONNAY, W.F. Vermont Yankes Nuclear Power Corp. 80/10/07. 1p.
 - --8010150305 Monthly operating rept for Sept 1980.
 BEERS,F.C., BURGER,F.J. Vermont Yankee Nuclear Power Corp.
 80/10/07 App.
 - 8 Reportable occurrences, LERs & related correspondence
 - BO10080563 PNO-I-80-126, on 800908, IBEW set up picket at main entrance to station in protest over const practices at other plant sites. Plant operators are honoring picket line Licensed supervisory personnel are operating plant.

 RAYMOND, W J. MARTIN, T T, BRUNNER, E J. Region 1, Philadelphia, Office of the Director 80/09/08, 2pp.
 - 8010040251 Forwards LER 80-027/03L-0, MURPHY,H, Vermont Yankes Nuclear Power Corp. 80/10/03, 1p.
 - --8010060257 LER 80-027/03L-0. on 800704. during surveillance testing, D RHR-8W pump discharge check valve improperly seated. Caused by degradation of valve internals, Disc, arm, binge pin & gastets replaced, tested & returned to svc. HURPHY, W P Vermont Yankee Nuclear Power Corp. 80/10/03. 2pp.
 - BO10060263 Forwards LER 80~026/03L-0. MURPHY, W. Vermont Vantes Nuclear Power Corp. 80/10/03. 1p.
 - ---BD10060268 LER 80-026/03L on 800703, during normal operation, HPCI pump discharge valve indicating lights failed Caused by tripped overload relay Valve reset & cycled several times to verify proper operation HURPHY, H.P. Vermont Yankee Nuclear Power Corp. 80/10/03, 1s.
 - BO10150437 Forwards LER BO-028/03L-0.
 MURPHY, W P. Vermont Yankee Nuclear Power Corp 80/10/07. 1p.
 - --B01018044B LER B0-028/03L-0: on 80090B, discovered that continuous sample was not being drawn at environ air sample station AT2.3.

 Caused by fuse which blow at time of electrical storm Fuse replaced & station functionally checked.

 MURPHY.W.P. Vermont Yenkee Nuclear Power Corp 80/10/07. 1p.
 - 8010200399 Forwards LER 80-032/01P-0, MCRPHY,W.P. Vermont Yankee Nuclear Power Corp. 80/10/14. 1p.
 - --B010200404 LER 80-032/01P-0: on 801014, during core spray sparger visual insparsamicircular linear indication was observed on end face of junction box on C core spray sparger. Cause not determined. Investigations are in progress.

 HURPHY: W. P. Vermont Yankse Nuclear Power Corp. 80/10/14. ip.
 - B010200466 Forwards LER 80-033/01P-0, MURPHY, N. P. Vermont Yankee Nuclear Power Corp. B0/10/14. 1p.
 - ~~9010200469 LER 80-033/01P-0: on 801014, examination in accordance w/IE Bulletin 80-07 revealed crack in jet pump 8 hold down beam. Probable cause is intergranular stress corresion cracking. Hold down beam will be replaced.
 MURPHY.M.P. Vermont Yankee Nuclear Power Corp. 80/10/14. 1p.
 - B010270043 PND-I-80-152: on 801014; crack identified in core epray sparger upper "C" junction box. Three inch circular crack appears to have formed along heat affected zone of 3/4 inch diameter plug. Cause not determined. Investigation started. RAYMONO, W. J., COLLINS, B. J., MARTIN, T. T., Region i, Philadelphia, Office of the Director, 80/10/18, 2pp.
 - 8010230407 Forwards LER 80-029/03L-0. MURPHY, M. P. Vermont Yankes Nuclear Power Corp. 80/10/17. 1p.

- --8010230410 LER 80~027/03L-0.on 900918.discovered that average power range monitors were adjusted slightly nenconservatively Cause unstated Operating procedures corrected MRPHY.N.P Vermont Yenkes Nuclear Power Corp 80/10/17 ip.
- 8010310471 Forwards LER 80-037/01P-0 MURPHY.N. P Vermont Yankee Nuclear Power Corp 80/10/27 1p.
- --8010310478 LER 80-037/01P-0 on 801027, linear indication was discovered by ultrasonic testing at weld F3B on reactor cleanup water suction line CUM-18. Cause undetermined Addl examinations to be conducted by ABME MURPHY, W P Vermont Yankee Nuclear Power Corp 80/10/27 1p
- V Operator Examinations
- 8010280345 Responds to NRC 800731 ltr re revised interim criteria for shift staffing. Util will be in compliance w/ell revised criteria by 820701.
 CONMAY:N F. Vermont Yankee Nuclear Power Corp. 80/10/23, 1p
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 8009150235 Forwards revised emergency plan, in response to NRC questions LIBRIZZI.F.P. Public Service Electric & Qas Co. of New Jersey. 80/09/04. ip.
- --8009150341 Revised emergency plan
 * Public Service Electric & Qas Co. of New Jersey. 80/09/05,
 300pp.
- 8010100193 Forwards revisions to emergency plan, in response to NRC questions on revised swargency plan submitted 800904. LIBRIZZI.F.P Public Service Electric & Gas Co of New Jersey. 80/10/03 2pp.
- --8010100197 Revised emergency plan.

 * Public Service Electric & Gas Co. of New Jersey. 80/09/30.
 48pp.
- 8010100264 Forwards emergency plan manual implementation procedures. LIBRIZZI,F.P Public Service Electric & Gas Co of New Jersey. 80/10/09. 2pp
- --8010100273 Emergency plan manual implementation procedures Revision 12, BILVERIO, N.T., STILLMAN, J.R. Public Service Electric & Gas Co. of New Jersey, 80/08/18, 186pp,
- 8010310301 Forwards revised emergency plan in response to add1 NRC questions & to fulfill commitments made in 800904 revised emergency plan. Correspondence from county & state agencies encl.
 LIBRIZZI,F P. Public Service Electric & Oas Co. of New Jersey.
 80/10/21. 7pp.
- --8010310305 Revised emergency plan.

 * Public Service Electric & Gas Co of New Jersey. 80/10/21.
 15pp.
- O. Adjudicatory correspondence
- 8010310447 Initial decision, LBP-80-27, authorizing Director of Nuclear Reactor Regulation to make appropriate findings & issue DL amend allowing replacement of spent fuel storage racks. Will constitute final action in 45 days. Effective immediately, LAMB. J. C., SHOW. F. J., KILHOLLIN. C.L. Atomic Safety and Licensing Board Panel. 80/10/27. 48pp.
- J. Insurance & indemnity information
- 801022041B Forwards Endorsements 1 & 2 to NELIA Folicy E8-72. GDRREA.M.A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/10/17. 3pp.
- P. Operating license stage documents & correspondence
- 8010010179 Ack response to NRC 771109 itr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Response acceptable & no further action necessary. VARGA, S. A. Operating Reactors Branch 1. BO/09/12. 2pp.

- 8010200345 Forwards Amend 26 to License DPR-70 & notice of issuance & availability VARQA,8 A Operating Reactors Branch 1 80/09/15 3pp.
- --8010200349 Amend 26 to License DPR-70, including requirement to implement refeguerds contingency plan within 30 days of
 - NRC approval VARQA, S A Operating Reactors Branch 1 80/09/15 4pp.
- --8010200351 Notice of issuance & evailability of Amend 25 to Licanse DPR-70 VARQA,S A Operating Reactors Branch 1 80/09/15 2pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also enci EISENHUT, D O Division of Licensing 80/09/19 28pp
- 8010060271 Responds to NRC 800818 request for degraded grid voltage analysis info. Analysis was previously performed & submitted on 800303 & 791010. Requested assumption re start of Nonclass IE motor not valid for analysis LIBRIZZI,F P. Public Service Electric & Oas Co of New Jerssy. 80/09/24. 2pp
- --B010060279 Responds to NRC questions re degraded grid voltage protection at facility Proposed design for second level of undervaltage & related mati encl LIBRIZZI.F P Public Bervice Electric & Gas Co of New Jersey B0/03/03 10pp
- --B010060286 Submits analysis of electric power sys per NRC 770808 request. Offsite power sys & desite distribution sys of sufficient capacity & capability to automatically start & operate all safety loads LIBRIZZI: FP. Public Service Electric & Oas Cp. of New Jersey 79/10/10 App.
 -)70530 Hodifies 790112 commitment re storage of air breathing units pare cylinders Ten Scott SCBAs will be located at liological control point to syc entire controlled access a IRIZZI,F P Public Service Electric & Oas Co of New Jersey, /09/26 ip
 - 0080421 Responds to 800826 ltm re ravision of diesel fuel oil roogram
 _IBRIZZI,F P. Public Service Electric & Oas Co. of New Jersey
 80/09/30 200
- 3010270223 Ack receipt of 800930 ltr deteiling actions taken to upgrade GA of diesel oil used at factility. Actions will provide assurance desired & are acceptable VAROALB A. Operating Reactors Branch 1. 80/10/06 2pp
- 10210448 Forwards responses to NRC 800826 request for addl info re ollection of loggerhead & Kemp Atlantic Ridley sea turtles HISSIAS, J. A Public Service Electric & Gas Co, of New Jersey. 0710707 19pp
- 3300619 Forwards eix drawings re auxiliary feedwater sys at lacility, N/O entls. 1858-N J. Operating Reactors Branch 1. 80/10/09 ip
- 10210472 Forwards application for amend to License DPR-70, changing
- 10210472 Forwards application for amend to License DPR-70 changing hpp A Tach Specs re reactor coolant & refueling operations jections in response to NRC 800611 request Class III amend 'ee encl
- Tee enci
 19812ZI,F.P. Public Service Electric & Cas Co of New Jersey.
 10/10/15 ip
- IO10210475 Application for amend to License DPR-70, changing App A Tech Specs re reactor coolant & refueling operations 8CHNEIDER: FW Public Service Electric & Gas Co. of New Jersey 80/10/15 2pp
- Oi0210477 Proposed Tach Space 3/4.4 & 3/4.9 re RCS & refueling operations respectively, providing redundancy in decay heat removel capability in all modes of operation.

 # Public Service Electric & Gas Co. of New Jersey. 80/10/15
- 0290320 Application for amend of License DPR-70, changing Tech Specs e power distribution limits Class III fee encl. ISRIZZI.F P Public Service Electric & Gas Co. of New Jersey 0/10/20 3pp

- --B010290323 Proposed changes to Tach Specs 3/4 2 re power distribution limits

 * Public Service Electric & Oas Co. of New Jersey 80/10/20
 700
- 8010290334 Notifies of room change for 801029 sixth quarterly meeting w/EPA in Newark, NJ to discuss 316(b) demonstration & program changes re requested one-up program extension Meeting will be held in McCarter Board Room on fourth floor of tower SHISSIAS, J A Public Service Electric & Oas Co of New Jersey 80/10/23 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8010240868 Forwards IE Insp Rept 50-272/80-18 on 800716-18, No noncompliance noted BCHNEIDER, F. W. Region 1, Philadelphia, Office of the Director 80/08/26 2pp.
- --B010240574 IE Insp Rept 50-272/80-18 on 800716-18 No noncompliance noted, Major areas inspected qualification data for electrical equipment inside containment associated w/electrical sys.accumulator sys & steam generator sys, FINKLE.A E. Region 1. Philadelphia. Office of the Director, EBNETER.8 D Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/23 6pp
- 8010010603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-272/80-13 & 50-311/80-09 BRUNNER:E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/27, ip
- --8010010609 Responds to NRC 800724 ltr re violations noted in IE 1rs; Repts 50-272/80-13 & 50-311/80-09 Corrective actions addressed in LER 80-004/03L-0 SCHNEIDER, FW. Public Bervice Electric & Gas Co of New Jersey 60/09/15 2pp.
- --8010010416 Forwards IE Insp Repts 50-272/80-13 & 50-311/80-09 on 800401-30 & notice of violation BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/24, 2pp
- --8010010622 Natice of violation from insp on 800601-30
 * Region 1. Philadelphia. Office of the Director 80/07/18
- --801001063i IE Insp Repts 50-272/80-13 & 50-311/80-09 on 800601-30 Noncompliance noted simultaneous operation of two injection pumps contrary to Tech Spec 3 5 3 limits KEIM10.R R Region i, Philadelphia, Reactor Operations Nuclear Support Branch. NORRHOLH.L J. HILL.W M Region i, Philadelphia Office of the Director 80/07/18 17pp
- 8010020285 Responds to IE Builetin 80-15 Emergency notification sys but uninterruptible power source Lighting inverter is emergency power source Util expended 8 manhours on bulletin. SCHNEIDER: FW Public Service Electric & Qas Co of New Jerssy 80/08/29 3pp
- 8010040130 Responds to TE Bulletin 79-018 re environ qualification of Class IE equipment. Forwards table of potential deficiencies re equipment environ qualification Tabulation of required design changes is being prepared MIDURA: H. J. Public Service Electric & Oas Co. of New Jersey 80/09/02. 3pp.
- 8010010826 Responds to IE Bulletin 80-20 Three Westinghouse Type W-2 central switches are used for each unit, however, neutral switch contacts are not used SCHNEIDER, F H Public Service Electric & Cas Co of New Jersey, 80/09/05 ip
- 8010100097 Ack receipt of BOOS19 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-272/80-14 & 50-311/80-10 BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. BO
- --8010100061 Responds to NRC 800729 itr re-violations noted in IE Instruction Repts 50-272/80-14 & 50-311/80-10 Corrective actions' training group is developing formal means of evaluating operator response on simulator SCHREIDER.F W. Public Service Electric & Cas Co of New Jerses 80/08/19. 3pp.
- --B010100065 Forwards IE Imap Repts 50-272/80-14 & 50-311/80-10 on 800618-20 & notice of violation, BRUNNER/E.J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/29. 2pp

DOCKETED ITEMS

--8010100069 Notice of violation from insp on 800618-20
• Region i, Philadelphia, Office of the Director 80/07/11 lp

-1164

in

te |

10

Insp

15

10

har.

188

- --8010100075 IE Insp Repts 50-272/80-14 & 50-211/80-10 on 800618-20 Noncompliance noted failure of operators to review facility design changes & failure to maintain adequate records for requalification program
 BETTENHAUSEN.L., WIGGING, J T Region 1, Philadelphia, Office of the Director CAPHTON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/11 5pp
- 8010300224 Ack receipt of 800603 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-04 & 50-311/80-01.

 GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/19 ip
- --8010300241 Forwards IE Insp Rept 50-272/80-04 & 50-311/80-01 on 800128-31,0201.04-07 & 11-13 & notice of violation GRIER,B.H Region 1. Philadelphia, Office of the Director GO/05/06. 2pp
- --9010300245 Notice of violation from insp on 800128-31,0201,04-07 & 11-13
 * Region 1, Philadelphia, Office of the Director 80/05/04 3pp.
- --8010300263 IE lnsp Repts 50-272/80-04 & 50-311/80-01 on 800128-31,0201, 04-07 & 11-13 Noncompliance noted in areas of GA program implementation.GA/OZ administration.document/drawing controls & design changes & mods GREENMAN.E O, NAPUDA.O, SHMONETTI.O Region 1, Philadelphia, Office of the Director 80/05/04 14pp
- --8010300275 Forwards IE Insp Rept 50-311/80-01 on 800128-31,0201,04-07 & 11-13 & notice of violation W/o entl
 ORIER, B H Region i. Philadelphia, Office of the Director 80/05/06 2pp.
- 8010060188 Forwards notice of violation re failure to implement continuous visual surveillance of interface doors in response to 800320 order modifying license Ack receipt of 800414 ltr re corrective actions & civil penalty payment BTELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/09/23 App
- --8010040396 Notice of violation from enforcement meeting on 800418 recorrective actions in response to 800320 order modifying license # Office of Inspection & Enforcement, Office of the Director 80/09/23. 1pp
- 8010300540 Advises that util response to IE Bullstin 80-18, "Maint of Adequate Hin Flow Thru Centrifugal Charging Pumps Foliowing Bacondary Side High Energy Line Rupture," will be delayed until 800929

 30HNEIBER:F.# Public Service Electric & Gas Co of New Jersey.
- B010270451 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested ORIER. B.H. Region 1. Philadelphia. Office of the Director. B0/09/26 1p.
- 8010230200 Responds to IE Bullstin 80-18. "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Becondery Sids High Energy Line Rupture " Pumps will be shutdown if RCS pressure cannot be maintained below 2335 psig.

 80HNEIDER, F. W. Public Service Electric & Qas Co. of New Jersey.
- E0102302AB Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-16 & 50-311/80-12 BRUNNER.E.J Region 1. Philadelphia, Reactor Operations Nuclear Support Brench. 80/10/02 ip.
- --8050230276 Responds to NRC 800B19 itr re violations noted in IE Insp Repts 80-272/80-16 & 50-311/80-12 Corrective actions tags were released & valves were locked open GCHMEIDER.F.W Public Service Electric & Gas Co. of New Jersey, 80/09/19. 3pp,
- --8010230283 Forwards IE Insp Repts 50-272/80-16 & 50-311/80-12 on 800701-31 & notice of violation. BRUNNER,E.J. Region is Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/19 2pp.
- --8010230287 Notice of violation from insp on 800701-31.
 * Region 1, Philadelphia, Office of the Director. 80/08/18, ip.

- 8010240169 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required ORIER. B H Region i, Philadelphia, Office of the Director 80/10/02 1p
- 8010300475 Forwards documents pertaining to implementation of IE Bulletins 79-02,79-07 & 79-14 at facility in response to NJ Dept of Public Advocate request H/o encls RDSG/M.J. Operating Reactors Branch 1 80/10/09 3pp
- 8010280293 Forwards IE Info Notice 80-36. "Failure of Steam Gamerator Support Bolting " No specific action or response requested. CRIER.B.H Region 1. Philadelphia, Office of the Director 80/10/10 1p.
- R. Periodic operating reports & related correspondence
- 8010200377 Forwards monthly operating rept for Sept 1980 HIDURA:H J. Public Service Electric & Gas Go of New Jersey. 80/10/10 ip.
- ---8010200378 Honthiy operating rept for Sept 1980 HILLER, L. K. Public Service Electric & Gam Co. of New Jersey. 80/10/10. 19pp
- S. Reportable occurrences, LERs & related correspondence
- B0100B036B PNO-I-B0-110A on B00725, IBEW strike has been settled & pictet lines at corporate oft have been withdraum. Phone cables will be repeired as soon as picket lines at plant site are withdraum BRIGOS, L., KEIMIO, BRUNNER, E. J. Region 1. Philadelphia, Office of the Director B0/07/25 ip
- 8010030449 Forwards LER 80-047/03L-0. LIBRIZZI.F P. Public Service Electric & Gas Co. of New Jaraey 80/09/26. 1p
- --B010030454 LER B0-047/03L-0. on B00827. QC inspactor discovered fire barrier open between Units 1 & 2 w/no fire watch established Caused by contractor error Harning sign to be installed & training improved.

 RANDOLPH, J. K. #ublic Service Electric & Qas Co. of New Jersey, B0/09/24 20p.
- 8010060283 Forwards LER 80-048/03L-0. LIBRIZZI,F,P. Public Service Electric & Oak Co. of New Jersey. 80/09/29. 3pp.
- --8010060287 LER 80-048/03L-0 on 800830, during gower coastdown near end of fuel cycle, quadrant power tilt ratio was 1.03, exceeding Tech Spec limits Gaused by instrument drift & gower tilts. RANDDLPH, J. M. Public Service Electric & Qas Co. of New Jersey. 80/07/27, 1p.
- 8010060291 Forwards LER 80-049/03L-0. LIBRIZZI, F. P. Public Service Electric & Cas Co. of New Jersey. 80/09/29. ip.
- --8010060295 LER 80-049/03L-O on 800830, during normal operation, leak discovered in svc water supply to centrifugal charging pump 12 lube oil cooler Gaused by corrosion at T fitting in piping. Fitting replaced & pump returned to svc. RANDOLPH, J. M. Fublic Bervice Electric & Qas Co. of New Jersey. 80/09/29. 2pp.
- 8010040772 Forwards LER 80-041/03X-1. LIBRIZZI, F. P. Public Service Electric & Qas Co of New Jersey. 80/10/01 2pp.
- --B0100402B0 LER B0-041/03X-1: on 80070B, during normal operation safety injection pump ii declared inoperable because of water mixed w/lubricating oils. Caused by cooler tube failure. Tube plugged & tested satisfactorily RANDOLPH, J. M. Public Service Electric & Oas Co. of New Jersey. B0/10/01. 1p.
- 8010100327 Forwards LER 80-030/03L-0. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. B0/10/06. Jpp.

- ---8010100336 LER 80-080/03L-0 on 800908 discovered failed air particulate detector in reactor coolant leak detection sys. Caused by cracked sodium indide crystal Detector replaced & satisfactorily tested RAMPOLPH. J Public Service Electric & Oas Co of New Jersey 80/10/06 ip
- 8010200591 Forwards LER 80-052/03L-0 LIBRIZZI, F.P. Public Service Electric & Gas Co. of New Jersey 80/10/10 2pp
- --8010200552 LER 80-052/OGL-0 on 800910, record review prior to reactor startup revealed required inservice insp surveillance of valves had not bean completed during previous reactor shutdown Caused by improper surveillance scheduling, RANDOLPH, J M Public Service Electric & Gas Co. of New Jersey 80/10/10 1p
- 8010270040 PNG-I-80-151 on E01010, two util employees & health physics technician received exposures of 1,6,1 0 & 0 4 rems. Caused by withdrawal of in-core detector thimbles Exposure time cavity was 30 seconds
 PLUMLER K E , KEIMIOR , KNAPP, P J Region 1, Philadelphia, Office of the Director 80/10/14 2pp
- B010270376 Forwards LER 80-051/03L-0 LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey B0/10/21 3ps
- --8010270377 LER 80-051/03L-0 on 800923, both fuel handling eldg exhaust ventilation fans declared inoperable due to damaged V-belts Caused by installation of unmatched pair of V-belts. Problem resolved w/availability of proper spare parts RANDOLPH. J.M Public Service Electric & Qas Co of New Jerssy, 80/10/21 ig
- T. Hearing transcripts on non-antitrust matters
- 9010290146 Responds to 800616 ltr transmitting C Hill questions restisting safeguards to prevent spent nuclear fuel accidents to facility exemption from minimal safety sets DIRCKSIM. J. Office of the Executive Director for Operations 80/10/21 1800
- --8010290162 Add1 testimony presented before ASLB to correct & clarify 800710 testimony re loss of water from spent fuel storage pool PASEBAO,W F Accident Evaluation Branch. 80/10/21 3pp.
- DOCKET 50-273 BEZNAU NUCLEAR STATION, UNIT

 P Operating license stage documents & correspondence
- OiO200095 Forwards Transnuclear. Inc request for amend to License XRM-1675, increasing quantity of matl authorized by addi 52 245 kg U.enriched to 3.59% w/o max for use in Beznau II Reactor in Suitzerland W/o encl DEVINE. J.B Assistant Director for Export/Import & International Baseguards. 80/09729 ip
- OCCKET 50-274 U. 8 OEOLOGICAL SURVEY RESEARCH REACTOR
 3 Inspection reports, IE Sulletins & correspondence
- 3010140037 Forwards Waste Packaging Insp Rept 15000046/80-74 & notice of violation
 BROWN, 0 D Region 4. Delias, Fuel Facility & Materials Safety
 Branch, 80/09/02 2pp
- -8010140040 Notice of violation from insp on 800618, * Region 4. Dallas, Office of the Director 80/07/21. 2pp
- --8010140044 Forwards Waste Packaging Insp Rept 13000046/80-74 on 800618 One item of noncompliance w/DOT/NAC regulations identified. BOOK.M E. Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch. 80/07/22 ip.
- --B010140049 Waste Packaging Insp Rept 15000046/80-74 on 800618. Noncompliance noted: improper radioactive labels attached to two containers. Shipper to receive warning itr relitem of noncompliance FONO.F.T Region 5. Ban Francisco, Office of the Director THOMAS.R.D., B00K.H E. Region 5. San Francisco, Fuel Facility & Haterials Safety Branch. 80/07/21. 4pp.

- 8010030174 Forwards IE Insp Rept 50-274/80-01 on 800818 No noncompliance noted KELLY, J A F Region 4, Dailas, Office of the Director. 80/09/19 2nn
- --80100301B1 IE Insp Rept 50-274/80-01 on 800B18 No noncompliance noted Hayor areas inspected, security plan, protection of SNM, security organization & access control Datails withheld (ref 10CFR2 770)

 CALDMELL, R A . KELLY, J A F Region 4, Dallas, Office of the Director 80/09/16 1p
- 8010100085 Ack receipt of 800908 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-274/80-02 BROWN.0 D Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/10/02 ip
- --8010100089 Responds to NRC 800902 ltr re violations noted in IE lm; Rept 50-274/80-02 Corrective actions two separate radiation readings will be made by two different people on each waste container to be shipped MARRANZING. A P. Interior, Dept of, Geological Survey 80/09/08
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8Di0220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D O. Division of Licensing. 80/09/19 28pp.
- 8010080501 Forwards corrected pages for insertion into TERA Corp final rept, "Evaluation of Peak Horizontal Ground Acceleration Associated W/Hosgri Fault at Diablo Canyon Nuclear Power Plant"
 CRANE, P. A Pecific Oas & Electric Co. 80/10/02. ip.
- --8010080512 Corrected pages for insertion into "Evaluation of Preb Horizontal Ground Acceleration Associated W/Hosgri Fault at Diablo Canyon Nuclear Power Plant," final rept. * TERA Corp 80/10/02 17pp.
- 8010230615 Bummary of 800725 meeting w/util.Westinghouse.Pickard.Low & Garrick Inc & Franklin Research Ctr in Bethesda, MD re facility auxiliary feedwater sys reliability.List of attendess encl JABBOUR.K N Licensing Branch 3 80/10/07. 24pp.
- --8010230529 Summary of 800725 meeting w/util. Westinghouse & Frantiin Research Ctr in Bethesda, MD re auxiliary feedwater sys automatic initiation & flow indication List of attendees & clarification of flow indication encl.

 KENDALL, R. Instrumentation & Control Systems Branch. 80/07/29
- 8010280040 Forwards request for addl info re util 800703 application for Amend 85 to licensing application, which includes extensive revisions to Chapter 17 of FSAR. Outstanding items include composition & Function of onsite review group, TEDESCO, R L Assistant Director for Licensing 80/10/07, 7pp

1

ŀ

- 8010140310 Submits response to 800827 request re Guestions 1 & 2 concerning turbine disc. Response to 3 & 4 will be made separately. Affidavit & proprietary & nonproprietary versions of "Low Power Turbine Disc Info" encl CRANE.P. A. Pacific Cas & Electric Co 80/10/09. fipp.
- --8010140316 Nonproprietary version of "Low Power Turbine Bisc Info "
 # Westinghouse Electric Corp. 80/10/03. 75pp.
- B010(40345 Forwards response to NRC questions re design basis of auxiliary feedwater sys flow requirements & analysis that calculates relative value of sys reliability. "Reliability Analysis of Diablo Canyon Auxiliary Feedwater Bys" encl. CRANE, P. A. Pacific Gas & Electric Co. 80/10/09. 22pp.
- --8010140353 "Reliability Analysis of Diablo Canyon Auxiliary Feadesto 7 Sys," Revision 3 BLEY, D C., WHEELER, D M., CATÉ, C. L. Pickard Lowe & Garrick, Int PLO-0140 RS 80/09/30, 140sp.
- 8010270232 Notification of 801016-17 meeting w/util & Sandia Labs in Ban Luis ObisporCA to discuss reliability aspects of auxiliary feedwater sys MIRAQLIA.F J. Licensing Branch G. 80/10/09 4pp.

- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8010310504 Forwards NUREC-0475 Suppl 11.8ER for facilities Suppl discusses sys interaction program for seismically-induced events
 MIRAOLIA.F J Licensing Branch 3 80/10/02 5pp
- B010230005 Suppl 11 to SER

 * Office of Nuclear Reactor Regulation, Director NUREO-0675 Si1
 B0/10/31 25pp
- F Security, medical, emergency & fire protection plans
- 8010210045 Notification of 801021 meeting w/util. San Luis Obispo County officials, FEMA & State of CA Ofc of Emergency Sycs in BethesdayAD to discuss completion dates & rayiew of state & ideal emergency plans
 BUCKLEY, B C Licensing Branch 3 80/10/07 5pp
- 8010240403 Clarifies confusion re statements contained in l'eb 1980 emergency plan Mods made to emergency plan to reflect requirements of revised 10CFRSO.App E. & address NRC 800826 comments Third party agreements to be confirmed CRANE.P A Pacific Gas & Electric Co 80/10/17 2pp
- Q Adjudicatory correspondence
- 8010160192 Notification of contract execution, Mod 1 to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hoaring " Contractor, MM Newmark, HAIRSTON, C. A. Technical Assistance Contracts Branch FIN 8-6874 80/09/23 1p
- --8010160179 Mod 1.amending ecope of work.to "Technical Assistance in Preparation of NRC Appeal Brief on Diable Canyon Nuclear Power Plant Hearing " NEWMARK,N M N M Newmark Consulting Engineering Services DOUDHERTY, D 0 Technical Assistance Contracts Branch FIN B-6874 80/09/23 ip.
- B010210104 Staff response to ABLB request for supplemental positions on POKE's motion for low power testing. Btaff feels POKE has filed application sufficient to allow examination of fuel loading & low power testing proposal BAVIS.L D Hearing Branch 4 B0/07/25 16pp
- 8010030310 Requests permission to attend family religious calebration on 801100 or 09 Would be available for security plan hearing on 801111 if ASLAO decides to commence trial on that date.

 BROWNIH H Hill Christopher & Phillips 60/10/01 2pp.
- 80(0000385 Discusses facility security plan hearing location & facility integrity maint, CA state police could be made available to assist in security plan matts transportation & protection. BROHM H California: State of BROWN, H Hill Christopher & Phillips 80/10/01 2pp.
- 80(0030452 Order re util motion for low power testing containing min requirements to commence proceeding Concurs w/NRC re deferral of Class 9 accidents until resolution of seismic issues Contentions shall be filed by 801027. BONERS E 8 Atomic Safety and Licensing Board Panel 80/10/02 20p
- 8010070382 Responds to 801001 request for security plan hearing delay. Discusses ASLAB 800828 order terms re formal motions for procedural matters before ASLAB TOMPKINS.B A Atomic Safety and Licensing Appeal Panel. 80/10/03.
- B010210513 Forwards response of intervenor SLOMFP to NRC motion to compel answers to interrogatories CAMPRELL,R.A. Beymour & Willis. B0/10/03 1p
- --8010210518 Responds to NRC motion to compel answers to interrogatories
 ASLP 800718 order offered SLOMFP opportunity to prepare more
 presise contention at discovery close Related
 correspondence.
 WILLIS.H.M. Ban Luis Obispo Mothers for Peace WILLIS.H.M.
 Seymour & Willia 80/10/03. 3pp.
- B010080300 Motion requesting that CB Hanback be permitted to review security plan as third counsel. NRC & joint intervenors stated no opposition to such addition but PORE objected. Brought before ASLB w/o unanimity of ASLB 800828 order BROWN.H.H. r. LANPHER.L. C. California. State of. BROWN.H.H. Hill Christopher & Phillips. 80/10/06. 2pp.

- ---B0100B030B Amended affidavit of nondisclosure re licenses security plan HANBACK.C B California, State of HANBACK,C B, Hill Christopher & Phillips 80/10/06. 4pp
- 8010100139 Order consolidating & scheduling sequence of matters to be heard at seasmic proceeding per 800624 order TOMPKING, 8 A Atomic Bafety and Licensing Appeal Panel, 80/10/06, 3pp
- 8010140014 Order requesting parties' views re convening hearing on applicant premises, by 801013 TOMPKING, B.A. Atomic Safety and Licensing Appeal Panel. 80/10/06 2no
- BO10140056 Response in apposition to Governor Brown 801006 motion for addition of counsel Parties' stipulations must be adhered to Certificate of Byc encl NORTON, B Pacific Gas & Electric Co NORTON, B Bruce Norton, B00/10/09 3pp
- 8010160053 Request for clarification of ABLAB 801006 order Applicant should be allowed to present testimony first & present rebuttal testimony at end of hearing. Certificate of 8vc enci NORTON.8 Pacific Gas & Electric Go, NORTON.8 Bruce Norton. 80/10/10 App
- B010160583 Objects to proposal that security plen hearing be held at util headquarters in San Francisco.Ca.Hearing should be held either in Bethesda, MD or at federal bldg in Ben Francisco.

 ØEGROIOU.B © California, State of 80/10/10 ip
- 8010200630 Responds to ABLAB 800918 order re stipulations.NRC.Ban Luis Obispo Mothers for Peace.Governor Brown & applicant agree to stipulation re document authenticity List of documents encl. OLMBTEAD.W J. Hearing Branch 4 80/10/10 5pp
- 8010160344 Request for deferral of 801027 filing data until 801203 in response to ASLAS 801006 order Saismic hearing recommences on 801020; security plan hearing commences 801110 & security plan hearing discovery is still ongoing BROWN.H H . GEORGIQU.S S , LANPHER.L C California, State of, 80/10/13 2pp
- 8010220554 Notice of appearance in proceeding Certificate of Svc enci. REYNOLDS J R. Scenic Shoreline Preservation Conference, Inc. REYNOLDS J R. Center for Law in the Public Interest, 80/10/13
- 8010160852 Response to ASLAB 801006 order requesting views re holding security plan hearing on licensee premises. Decision should be left to ASLAB discretion/balancing convenience, Commission policy & security Certificate of Svc encl
 QLMSTEAD, N J Hearing Branch 4. 80/10/14 7pp
- 8010200174 Request for extension until 801124 to file contentions re applicant request for low power testing licance. Counsel will be accupied preparing for seismic hearing Certificate of Sycenci.
 PLEISCHAKER.D. San Luis Obispo Mothers for Peace. REYNOLDS.J., PHILLIPS.J. Center for Law in the Public Interset. 80/10/15. App.
- 8010200677 Order establishing schedule for evidence & testimony to be presented at 801020 hearing. Applicant will present testimony first & will have opportunity for rebuttal. Parties may make brief opening & closing statements
 HAGINS.E.E Atomic Safety and Licensing Appeal Panel. 80/10/15
- 80/0200692 Response to util 80/006 request for clarification. If util is allowed to present rebuttal testimony, all participants should be given same opportunity, Cartificate of Svc encl BROWN.H H , LANNHER, L. C. California, State of, BROWN, H. H. Hill Christopher & Phillips 80/10/15 3pp
- 8010220521 Forwards draft subpoens commanding HB Seed to testify before ASLAS. Certificate of Svc encl.
 CRANE.P.A. Pacific Gas & Electric Co. 80/10/15 5pp
- 8010210497 Request, submitted on behalf of Joint Intervenors, that NRC prepare supplemental EIB to consider consequences of Class 9 accident at facility. Study is needed to correct earlier decisions based on NRC erroneous position on accidents FLEIBCHAKER.D Fleischeker: D 8, 80/10/17. 4pp
- 8010210774 Urgss initiation of settlement procedure re application for fuel loading & low power testing Sugests 801103 meeting of parties in Bethesda:MD to develop & discuss stipulation SHAPAR:H.K. Office of the Executive Legal Director. 80/10/17, 2pp.

- 8010230691 Notice of appearance in proceeding Certificate of Svc enci BARTH.C A Hearing Branch 2 80/10/21 3pp
- B010280566 Order granting extension until 801203 for intervenors to file contentions Parties should meet prior to 801203 to discuss issues & possible stipulations BOMERS.E.S. Atomic Safety and Licensing Board Panel. 80/10/24. 2pp
- 8010300583 Notice of reconstitution of ASLS by appointing JR Kline as member instead of WE Martin LAZO:R M Atomic Safety and Licensing Board Panel 80/10/28 ip

H General correspondence

- 8010010411 Responds to 800625 ltr re flooding & emergency planning for area surrounding site. Plant design sufficient to withstand anticipated flooding Util compliance w/NUREG-0694 required prior to issuance of OL. NUREG-0694 excerpts encl 8CHMENCER. A Uperating Reactors Branch G. 80/09/15 14pp
- 8010220049 Responds to 800410 ltr re safety of facility re geologic faults in region.Fault being taken into consideration in licensing process. SCHMENGER:A Operating Reactors Branch 3 80/09/22. 3pp
- -8010220064 Expresses concern over safety of facility due to geologic faults in area.

 BYLVESTER: K Affiliation Unknown 80/04/10. 2pp
-)10240305 Ack receipt of RD Hershey 800818 New York Times article from CA Off of Governor which suggests NRC issues licenses regardless of health & safety factor. Allegations are false Comments on NRC public image & on facility licensing issue DIRCKS.H J Office of the Executive Director for Operations 80/09/25. ip
- 80102403i1 Discusses encl RD Hershey 800818 New York Times Article refacility licensing issue on behalf of CA Ofc of Ocvernor.
 Article conveys poor image of NRC licensing practices
 Expresses desire to cooperate during proceeding.
 GEDR0TOU.B.B. California, State of. 80/08/22 2pp.
- E)10070455 Discusses emergency procedures described in NUREO-0396, in response to 800604 ltr re W Anson concerns Potential emergency would be declared on basis of observable indications in control room DIRCKS M. J. Office of the Erecutive Director for Operations 80/09/29, 2pp.
- >10300376 Responds to P Vrana 771123 ltr to President Carter re ness for nuclear power plant const. Discusses procedures & document availability re need for electrical power & alternatives.

 MIRAGLIA:F. Licensing Branch 3. 80/09/30. 5pp
- 8010300430 Forwards P Vrans 791123 its addressed to President Carter re Nosgri fault proximity & severe earthquake effects on facility. & low level radiation & high level radwaste disposal affects. RATKOFF, C. L. Energy, Dept of. 80/01/22, 4pp
- OiO280343 Forwards CD Calsoyas requests for info re facility licensing, Includes requests for press releases, petitions, mesos & interview dates between NRC & Governor Brown of CA Requests NRC response COELHO.T House of Rep. 80/10/01. 7pp.
- 010240011 Responds to 800701 ltr urging denial of DL. Full consideration is being given to satsmic implications of local & regional peology of site, MRAGLIA: F. J. Licensing Branch 3, 80/10/07, 3pp.
- 010240172 Responds to encl 800330 ltr to President Carter urging denial of OL for facility. Hearings are held re environ matters before CP is issued. Response to concern re effects of low level radioactivity encl.
 MIRAGLIA.F J. Licensing Branch 3. 80/10/07. 7pp.

a a f

- B010270018 Responds to B00825 ltr re expediting facility licensing Further actions required by ASLB, ASLAB & Commission NRC working toward timely resolution of safety issues before license issuance DENION.NR Office of Nuclear Reactor Regulation, Director B0/10/08 2pp
- 8010140279 Responds to 800811 ltr forwarding N Scott request urging licensing of facilities. ASLS hearing dates of 801020 & 1110 set to discuss esismic & security lesues, respectively Fuel loading & low power testing review planned for 1981. DIRCKS, W J. Office of the Executive Director for Operations, 80/10/07 2pp
- 80:0150432 Requests that concerns about evacuation plans be included in facility licensing proceedings. Emergency plans available in county have not been updated since 1976
 BRUND-9.E. Affiliation Unknown 80/10/09 14pp
- 801027003B Responds to 800214 ltr to President Carter re ability of facilities to withstand earthquakes & effect of low level radiation. ASLB plans to reopen San Unofre hering record reselemic adequacy in first quarter of 1981 HIRAOLIA:F.J Licensing Branch 3. 80/10/16 3pp
- B010270244 Responds to 800923 ltr to HR Denton expressing concerns reoperator errors equipment maifunctions & potential for future accidents at nuclear plants. NRC is requiring applicants to respond to THI--related requirements HIRAOLIA: F. J Licensing Branch 3. 80/10/16 3pp
- 80i03i0594 Responds to 79i2i7 itr to President Carter re facility licensing Describes caronology since docketing in 1973 NRC presently working toward timely resolution of safety issues.

 MIRAOLIA.F J Resource & Schaduling Branch. 90/10/27 5pp

J Insurance & indemnity information

- 8010280647 Requests Endorsement 19 to Policy NF-228.
 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity).
 80/09/24. 1p
- Q Inspection reports: IE Bulletins & correspondence
- 8010090359 Forwards IE Insp Repts 50-275/80-10 & 50-323/80-04 on 800427-0502 & notice of violation SPENCER. 9 S. Region 5, Sen Francisco, Reactor Construction & Engineering Support Branch 80705/19 2pp.
- --8010070365 Notice of violation from insp on 800429-0502 * Region 5, San Francisco, Office of the Director. 80/05/15. 2pp
- --B010090370 IE Insp Repts 50-279/80-10 & 50-323/80-06 on 800429-0502 Noncompliance noted: failure to inspect Class IE raceway supports per NUREO-0578 pressurizer heater vital power supply mods.

 DIODES T Region 5, 8an Francisco, Reactor Construction & Engineering Support Branch. KIRSCH.D.F. Region 5, 8an Francisco, Office of the Director. 80/05/15, 9pp
- 9010270408 Forwards IE Circular 80-21, "Regulation of Refueling Crows."
 No written response required.
 ENGELKEN.R H. Region 5, San Francisco, Office of the Director.
 80/09/10. 1p.
- 8010270031 Responds to IE Bullstin 79-03A, "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Steel Pipe," Subj pipe fittings not subjected to stresses greater than 85% of max code allowable stresses at design temp. CKANE, P.A. Pacific Gas & Electric Go. 80/09/15. 2pp.
- 8010270033 Forwards response to IE Bulletin 80-16, "Potential Misapplication of Rossmount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes," Twenty-four transmitters installed in safety-related applications. GRANE, P. A. Pacific Gas & Electric Co. 80/09/15 4pp.
- 8010270132 Forwards IE Insp Rept 50-275/80-16 on 800801-31.No noncompliance noted. CREME. J.L. Region 3, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/15. 2pp.
- --8010270138 IE Imap Rept 50-275/80-16 on 800801-31. No noncompliance noted. Hayor areas inspected: preoperational testing, plant tour. IE circulars & operator training, young. T., BAOAGLIG. M., Region 5, San Francisco, Office of the Director. STERNSERQ.D.M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 80/09/12. 6pp.

- 8010230066 Forwards IE Insp Repts 50-275/80-16 & 50-323/80-08 on 800812-15 No noncompilance noted 8PENCER, 0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/16 2pp.
- --BOI0230077 IE Insp Repts 50-275/80-16 & 50-323/80-08 on 800812-15.No nancompliance noted Major areas inspected licensee action on previous insp findings GA audit & nonconformance rept review & Unit 1 mods HAYNES.R C Region 5. San Francisco. Reactor Construction & Engineering Support Branch KIRSCH.D F , ELIN.J C Region 5. San Francisco. Office of the Director 80/09/15 7pp
- 8010080365 Responds to IE Bulletin 80-20, "Failures of Westinghouss Type W-2 Spring Return to Neutral Control Switches " Review revealed no Westinghouse Type W-2 control switches used in safety-related components GRANE.P A. Pacific Oss & Electric Co. 80/09/22 ip
- 801027036B Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II, Two-Inch, Tray Adsorber Cells " Visual insp showed no evidence of screen/casing separation or sagging, CRANE, P A Pacific Cas & Electric Co 80/09/24 ip
- 80[0]60054 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required. EMORLKEN.R.H. Region 5, San Francisco, Office of the Director.
- 8010280025 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required ENGELKEN.R H. Region 5. San Francisco, Office of the Director
- BO10280022 Forwards IE Insp Rept 50-275/80-18 & 50-323/80-09 on BO0723-26 & 1003 No noncompliance noted BPENCER, 0.8 Region 5. Ban Francisco, Reactor Construction & Engineering Support Branch. BO/10/09 2pp
- --B010280026 1E Insp Rept 50-275/80-18 & 50-323/80-09 on 800923-26 & 1003 No noncompliance noted Major areas inspected licensee action on previous insp findings, IE bulletins, deficiency items & corrective actions for Ruskin fire damper problem. KIRSCH. D.F., NARBUT, P.P. Region 5. San Francisco. Office of the Director. HAYNES, R.C., Region 5. San Francisco, Reactor Construction & Engineering Support Branch. B0/10/08 11pp
- B010280029 Forwards IE Insp Rept 50-275/80-19 & 50-323/80-10 on 800901-30. No noncompliance noted. CREMB, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/10/09. 2pp
- --Boio280035 IE Insp Rept 50-275/80-19 & 50-323/80-10 on 800701-30, No nuncompliance noted Major areas inspected, preoperational testing, plant tour, preoperation test program controls, IE circulars & bulletins & operator training YOUNG, T., BAOAOLIO, M. Region 5, San Francisco, Office of the Disector Stenness, Disector Stenness, Disector Stenness, Disector Stenness, Disector Support Branch 80/10/07 App
- 8 Reportable occurrences, LERs & related correspondence
- 8010020626 Part 21 rept re possible defects in Westinghouse motor control ctrs supplied to facilities, originally discussed in util 780403 ltr to NRC. No possible defect or generic failure exists for seismically certified equipment KENNEDY. O P. Westinghouse Electric Corp 78/05/22 3pp.
- T. Hearing transcripts on non-antitrust matters
- 8010300037 Transcript of 801020 hearing re OL application in San Luis Obiago.CA.Pp 1-222 BALZMAN.R.S., BUCK, J. H. JOHNBON, W.R. Atomic Bafety and Licensing Appeal Panel 80/10/20 222pp
- 8010310019 Transcript of 801021 hearing re seismic issues in Ban Luis Obispo, CA. Pp. 223-461 * Atomic Safety and Licensing Board Panel. 80/10/21, 241pp.
- 8010310020 Transcript of 801023 hearing re seismic issues in San Luis Obispo: CA.Pg 665-915 Atomic Safety and Licensing Board Panel. 80/10/23 264pp.
- 8010310362 Transcript of 801024 hearing in San Luis Obispo, CA Pp 716-1188, Supporting documentation encl. 4 Atomic Bafety and Licensing Appeal Panel. 80/10/24. 700pp.

- 8010310004 Transcript of 801025 hearing re seismic issues in San Luis Obispo, CA, Pp. 1189-1498 * Atomic Safety and Licensing Soard Panel 80/10/25 242pp
- U Congressions1/Executive Correspondence
- 80i02801iB Provides info re issuance of low power testing license & full power OL ASLB hearings on seismic & security matters scheduled for 80i020 & 11iO, respectively, Issuance of licenses contingent upon completion of hearings DIRCKS, M J Office of the Executive Director for Operations 80/10/01 Spp
- --8010280123 Responds to 800331 ltr requesting delay in issuing low power testing permit until resolution of seismic.emergency planning security & THI-related issues Schedule of steps to be followed in acting upon application will be forwarded KAMMERER, C C Office of Congressional Affairs 80/04/27 ip.
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2 A. Application/construction stage documents & correspondence
- B0102B0372 Forwards OE evaluation of proposed mod to HPCI & reactor core isolation cooling sys on behalf of RWR owners group Concurs w/owners group assessment that setpoint changes will yield minimal reduction in thermal cycle history QALLAGHER, J. W Philadelphia Electric Co. B0/10/24 7pp.
- F Security, medical, emergency & fire protection plans
- 8010080541 Forwards revisions to facility for physical security plan Revisions withheld (ref 10CFR2 790). BRADLEY, E. J. Philadelphia Electric Co. 80/10/04 Gpp
- B010200394 Notification of B01022 meeting w/util at site to discuss open items re facilities fire protection review VERRELLI.D M Operating Reactors Branch 4 80/10/06 2pg.
- 8010270320 Forwards Suppl 3 to safety evaluation of fire protection program, resolving issues of 770523 evaluation & approving certain mods which should be expedited REID,R W Operating Reactors Branch 4 80/10/10, 2pp
- --8010270322 Suppl 3 to safety evaluation of fire protection program, resolving issues of 790523 evaluation & approving certain mods. Office of Nuclear Reactor Regulation, Director 80/10/10 4pp,
- G Adjudicatory correspondence
- 8010270307 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENHUT,0.0 Division of Licensing. 80/09/19 2pp.
- ---B010270309 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT.D. 0. Division of Licensing 60/09/19 App
- 8010200239 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02, ip
- --B010200247 Order confirming util commitments to implement action re IE BUlletin B0-17 STELLO,V. Office of Inspection & Enforcement, Office of the Director. B0/10/02, 7pp.
- --8010200252 Order confirming util commitments to implement action re IE 8011stin 80-17. BYELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.
- 8010220541 Forwards radon info in response to request. Info should be made available to ASLAB & parties in radon proceedings ELLETT.W.H. Environmental Protection Apency. 80/10/10. 150pp
- J Insurance & indemnity information
- 8010280292 Requests endorsements & copy of Amend 21 to Policy B-28 DINITZ, I. Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24. ip.

- B010240522 Responds to NRC 800924 ltr indicating that signed copy of Amend 21 to Indemnity Agreement 8-28 was never received Amend 21 was signed by co-owners & forwarded to J Saltzman on 791126
 BRADLEY, E. J Philadelphia Electric Co 80/10/09. ip
- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- B010170317 Forwards interim preliminary draft rept "Review of Recent Halfunctions of BWR Borem Sys " STAMPELOB, J ACRS — Advisory Committee on Reactor Safeguards B0/08/08, ip.
- --8010170333 Interim preliminary draft rest to ACRB, "Review of Recent Malfunctions of BUR Screm Bys "

 * ACRB Advisory Committee on Reactor Safeguards. 80/08/08
 1190n.
- P. Operating license stage documents & correspondence
- B010200393 Advises of possible delay in Dec 1980 planned operation of interin ultrasonic acram discharge vol level monitoring sys QE has revised shipping date to B01114 & advised that sys is prototype, GOONEY, M. J. Philadelphia Electric Co B0/09/18, ip.
- B010220099 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of THI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing. 80/09/19 28pp
- IO10060147 Forwards request for add1 info re adequacy of station electric distribution sqs voltages. Response should be submitted within 45 days.

 REID:R W Operating Reactors Branch 4 80/09/22 App.
- 8010080195 Forwards Amends 79 & 72 to Licenses DPR-44 & DPR-56: respectively, sefety evaluation & notice of issuance & availability REID: R W. Operating Reactors Branch 4 80/09/22. 2pp
- --8010080161 Amends 72 & 73 to Licenses DPR-56 & DPR-44, revising tables of containment isolation valves & safety-related enubbers to reflect aces completed or planned by licenses.
 REID.R W Operating Reactors Branch 4. 80/09/22 8pp.
- --8010080169 Safety evaluation supporting Amends 73 & 72 to License DFR-44 & DFR-56:respectively # Office of Nuclear Reactor Regulation, Director 80/09/22. 3pp.
- -B0100B0173 Notice of issuance & availability of Amends 73 & 72 to Licanses DPR-44 & DPR-56, respectively. REID, R. W. Operating Reactors Branch 4 B0/09/22 2pp
- 010080404 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch. Unit 2 regulator sys design Reactor protection sys power supply should be modified by end of next refueling outage REID.R W. Operating Reactors Brench 4. 80/09/24. 3pp
- 010020488 Forwards application to amend App A of Licenses DPR-44 & DPR-56, revising Tech Spec Sections 3 i & 4 1 re max average planer linear heat generation rate & reactor protector systems time fee forwarded BRADLEY, E. J. Philadelphia Electric Co 89/09/30 ip.
- -B010020490 Application to amend App A of Licenses DPR-44 & DPR-56, revising Yerh Spec Sections 3,1 & 4,1 rs max average planer linear heat generation rate & reactor protector sys response time. Certificate of Svc encl.

 BAUER, E. G., BRADLEY, E. J., BOYER, V. B Philadelphia Electric Co. 80/09/30. Spp.
- ---B010020493 Proposed amend to Tech Spec Sections 3.1 % 4.1 re max average planer linear heat generation rate & reactor protector sys response time. " Philadelphia Electric Co. 80/09/30, 7pp.
- -8010020494 Addends 2 to "LDCA Analysis for Peach Bottom Atomic Power Station Unit 3." # Qeneral Electric Co. NEDO-24082 ADD 2, 80/06/30, 7pp.
- -B010020495 Addenda & to "LUCA Analysis for Peach Bottom Atomic Power Station Unit 2."

 " General Electric Co. NEDG-24081 ADD &. B0/06/30. &ps.

- ED10200045 Confirms discussions to B01008 visit by Sandia Natl Lab & BAI to observe physical layout of plant to design of vent-filter sys.
 REID.R.W Operating Reactors Branch 4 80/10/01 2pp
- B010070339 Responds to NRC request for info re implementation of THI-2 action plan requirements. Initiation levels of HPCI & RGIC sys should be separated so that RGIC sys will initiate higher water level than HPCI sys
 OALLACHER, J H Philadelphia Electric Go 80/10/02. App
- 8010200458 Application for amend to License BPR-44 & BPR-56 consisting of change to Tech Space.
 ALDEN,W.M. Philadelphia Electric Co 80/10/03 ip
- --B010200461 Tech Specs 9 15 & 4 15 for seismic monitoring instrumentation & seismic monitoring instrumentation & surveillance requirements.

 * Philadelphia Electric Co 80/10/03. 2pp
- 8010270386 Requests fee remittance within 15 days after receipt of ltree 800808 application for review of proposed seismic monitoring instrumentation Tach Bapec MillER: W D. License Fee Management Branch 80/10/09. 1p
- B010200451 Forwards application for amend of Licenses DPR-44 & DPR-56, incorporating screm discharge vol valves surveillance requirements & reactor protection sys & control rodblock limit switches limiting conditions Class III fee encl BRADLEY, E. J. Philadelphia Electric Co 80/10/14 1p
- ---8010200457 Application for amend of Licenses DPR-44 & DPR-56, incorporating Tech Specs re stram discharge vol valves surveillance requirements & reactor protection sys limiting conditions, W/Certificate of Svc BAUER, E. Q., BRADLEY, E. J. Philadelphia Electric Co 80/10/10 700.
- --8010200464 Proposed Tech Specs, Sections 3 0 & 4.0, incorporating surveillance requirements re scram discharge vol valves & limiting conditions re reactor protection sys & control rod block limit switches # Philadelphis Electric Co. 80/10/10 9pp.
- 8010200584 Responds to NRC BOOB21 request for addl info re util 80032; request for amend to Tech Beacs Discusses degraded grid voltage proposed time delay relays BALTROFF,8 L Philadelphia Elsectric Co. 80/10/14 4pp
- 8010200406 Assesses util capability to implement near-term NRC action plan requirements (NUREQ 0660) & proposed schedule. Plan items re implementation statue.proposed implementation plan & current shift technical advisor training program encl. DALTROFF.8 L. Philadelphia Electric Co 80/10/15. 18pp.
- 8010210329 Withdraws 730617 application for amend of Licenses DPR-44 & DPR-56, as supplemented by 770225 ltr. Reactor core design improvements implemented at recent refueling outages are providing desired control rad withdrawal flexibility.
 BRADLEY,E J. Philadelphia Electric Co 80/10/16. 1p
- 80:10280372 Forwards GE evaluation of proposed mod to HPC1 t reactor core isolation cooling sys on behalf of BHR owners group Goncurs w/owners group assessment that setpoint changes will gield withings! reduction in thermal cycle history.

 GALLAGHER, U. W. Philadsiphia Electric Co. 60/10/24. 7pp
- 8010280423 Responds to NRC 801001 ltr re screm sys Study of long-tera sys reliability initiated. Results of evaluation & proposed mods will be submitted by 801215 GALLAOHER, J. W. Philadelphia Electric Co. 80/10/24. 3pp.
- Q. Inspection reports: IE Bulletine & correspondence
- 8006040077 Forwards Waste Packaging Insp Rept 80-05 on 800319. No nonceapliance noted.

 800810 J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/04/14. 2pp.
- --8004040082 Waste Packaging Insp Rept 80-05 on 800319. No noncompliant noted. Major areas inspected: whipping paper requirements, DOT placarding requirements, radiation levels: removable contamination & prohibited articles of contants. POTTER, U.P. Region 2, Atlanta, Fuel Pacility & Materials Bafety Branch. 80/04/04, 6pp.
- 901002005B Forwards IE Imap Repts 50-277/80-23 & 50-278/80-17 on 900701-03, No noncompliance noted. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/08/13. 2pp.

- --8010020067 IE Insp Regts 50-277/80-23 & 50-278/80-17 on 800701-03 No noncompliance noted Major areas inspected Class IE electrical equipment inside containment associated w/main steam & feedwater sys EBNETER, 8 D Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch FINKEL.A.E Region 1, Philadelphia, Office of the Director 80/08/11 18pp
- 80J0010803 Responds to IE Bulletin 80-17 All scram tests successfully performed. Facilities returning to Tech Spec reporting requirements for equipment operability.

 DALTROFF.S.L. Philadelphia Electric Go 80/08/21 App
- 8010020331 Responds to AL Finkle 800814 telcon re IE Bulletin 79-018 re environ qualification of Class IE equipment Discusses method used for review DALTROPF: 8 L Philadelphia Electric Co 80/08/26. 1p.
- 8010020203 Responds to IE Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys.

 BALTROFF, B.L. Philadelphia Electric Co 80/08/27, ip
- 601001020B Responds to IE Bulletin 79-26 re boron loss from BWR control rod blades Control blade subcriticality testing & shutdown aargin testing were performed DALTROFF, B. L. Philadelphia Electric Co. 80/08/28, 2pp.
- 80/00/07/7 Responds to IE Bulletin 80-17/8 Uppls 1 & 3/re failure of control rods to fully insert during scram at BMR. Various procedural changes implemented to satisfy requirements of tulletin.

 DALTROFF, B L. Philadelphia Electric Co. 80/08/29, 3pp.
- 6010010821 Responds to IE Bulletin 80-15 re emergency notification sys.
 Automatic transfer capability provides power from emergency
 bus Approx 80 manhours expended on bulletin.
 OMLTROFF, B. L. Philadelphia Electric Co 80/08/29 Spp
- 8010010107 Ack receipt of 800821 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-01 to 50-276/80-01 BRUNRER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch.
- --B010010116 Responds to NRC 800731 ltr re violations noted in IE Insp Repts 30-277/80-01 to 50-278/80-01. Corrective actions: required documentation completed for personnel w/o documetry DALTROFF.S L. Philadelphia Electric Co. 80/08/21 2pp.
- --8010010120 Forwards IE Insp Repts 50-277/80-01 & 50-278/80-01 on 800101-31 & notice of violation BRUNNER.E.J Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/31. 2pp
- --8010010136 IE Insp Repts 50-277/80-01 & 50-278/80-01 on 800101-31.
 Noncompliance noted failure to adhere to health physics procedural requirements to wear personnel dosimetry in controlled areas.

 HCCABE, E.C. Region 1. Philadelphia. Reactor Operations Nuclear Buppert Branch. OREENMAN. E.G., COWOILL, C.J. Region 1. Philadelphia. Office of the Director. 80/07/29, 10pp.
- 8010230623 Forwards IE Insp Rept 50-277/80-19 on 800611.No noncempliance hotes, BMITH.O.H. Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/09/08 2pp.
- --8010230628 IE Insp Rept 50-277/80-19 on 800611. No noncompliance noted. Major areas inspected:review of util evaluation of individual exposure to radiation; including protection procedures; surveys & personnel training.

 BAER, R. E. COSTELLOF, M. Region i. Philadelphia, Office of the Director, KNAPF, P.J. Region i. Philadelphia, Fuel Facility & Haterials Safety Branch. 80/09/04. 7pp.
- 8010240281 Forwards IE Insp Rept 50-277/80-25 on 800709-11 & 24.No noncompliance noted.
 CARLBON, R T. Region 1. Philadelphis. Reactor Construction & Engineering Support Branch. 80/09/09. 2pp.
- --8010240290 IE Insp Rept 50-277/80-25 on 800709-11 & 24.No noncompliance noted Major areas inspected:activities re core spray mod/capping of control rod drive hydraulic return line & documentation reviews of inservice insp.
 JERNIOAN.E.P. Region i. Philadelphia, Office of the Director.
 TRIPP.L.E. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/04. Spp.

- 8010010244 Responds to IE Bulletin 80-20 re Westinghouse Type N-2 control swtiches Switches are installed in safety-related applications, No safety-related function would be disabled by neutral contact failure OALLAOHER.J.W. Philadelphia Electric Co. 80/09/10. 3pp
- 8010100428 Ack receipt of 800905 ltr informing NRC of steps taken to correct violation noted in IE lnep Rept 80-277/80-27 & Waste Packaging Insp Rept 15000039/80-09 BMITH.0.H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/09/15 ip
- --80i0i0043i Responds to NRC 8008i4 itr re violations noted in IE Insp Rept 50-277/80-27 & Waste Packaging Insp Rept 15000039/80-09 Corrective actions installing permanent flip signs on front of all trailers used at facility 9ALLAOHER, J. H. Philadelphia Electric Co 80/09/05, 2pp.
- --8010100434 Forwards IE Insp Rept 50-277/80-27 on 800605 & notice of violation. Waste Packaging Insp Rept 18000039/80-09 also enci.

 BMITH O.H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/14 2pp.
- --8010100435 Notice of violation from insp on 800505.

 * Region 1, Philadelphia, Office of the Director, 80/07/28 1p
- --801010043B IE Inep Rept 50-277/80-27 on 800605 Noncompliance noted: failure to placard front of Vehicle w/radioactive sign. MACARTHUR.T.C. Region 1. Philadelphia. Office of the Director. POITER.J.P. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 80/07/28 1p.
- ---801010D441 Waste Packaging Insp Rept 15000039/80-09 on 800405. Noncompliance noted: failure to placard front of vehicle w/radioactive sign. MACARTHUR: T C , POTTER, J. P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/07/28. 3pp
- 8010200239 Forwards order confirming util commitments to implement action re IE Bulletin 80-17.
 BTELLO,V. Office of Inspection & Enforcement, Office of the Director 80/10/02 1p.
- ---8010200249 Order confirming util commitments to implement action of IE Bulletin BO-17. BYELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/10/02 7pp.
- --8010200252 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO.V. Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp.
- 8010240130 Forwards lE Circular 80-22, "Confirmation of Employee Gualifications." No written response required. CRIER. B.H. Region 1. Philadelphia. Office of the Director. 80/10/02 ip
- 8010230104 Responds to IE Bulletin 79-26. Revision 1. "Boron Loss from BHR Control Blades." Corrective actions fall into categories of addl safety analyses & control blade replacements. Approx 40 man-days expended for control blade replacements, DALTROFF.B.L. Philadelphia Electric Co. 80/10/06. 3pp.
- 8010280226 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting," No specific action or response requested. ORIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/10. ip.
- R. Periodic operating reports & related correspondence
- 8010100350 Forwards radioactive effluent data, w/corrections shown hased on calculation of quarterly releases, in response to RA Hartfield 800924 itr request for review & comment. DALTROFF, B. L. Philadelphia Electric Co. 80/10/07 14pp.
- 8010150375 Forwards monthly operating repts for Sept 1980. COONEY, M. J. Philadelphia Electric Co. 80/10/10. ip.
- ---8010130377 Monthly operating rapts for Bapt 1980.
 ALDEN, W H. Philadelphia Electric Co. 80/10/10. 9pp.

B Reportable occurrences, LERs & related correspondence

- B010080364 PNO-I-80-111 on 800725, contractor employee working on condensate demineralizer suffered contaminated puncture wound to right foot.

 MCCABE, E. , DRUNNER, E. J. Region 1, Philadelphia, Office of the Director 80/07/24 ip
- 8010080544 PNO-I-80-122 on 800815, unplanned release of gaseous radioactivity from Unit 3 reactor hidg vent occurred Peak release rate was 33% of Tech Spec limits Cause believed to be maifunction of Unit 2 offges sys OREENMAN.E. BRUNNER.E.J. Region i, Philadelphia. Office of the Director. 80/09/15 ip
- B010020475 LER B0-013/03L on B00904 during surveillance test of reactor core isolation cooling steam line high flow switches; outboard steam supply isolation valve failed to close. Caused by limit switch malifunction Switch repaired COONEY, M J Philadelphia Electric Co 80/09/24 ip
- 8010030361 Updated LER 78-030/03Z-1 on 781221. during surveillance test w/units at full power, time to reach rated voltage & frequency for E-2 & E-3 diesels was about 11 & 13 seconds, respectively Caused by wearing of Hoodward governors COONEY, M J Philadelphia Electric Co 80/09/26 1p.
- BO10030371 LER BO-016/03L-0 on B00707, during surveillance tasting M/unit at full power ECCS A channel logic relay failed to function properly w/simulated low reactor pressure Caused by dirty contacts on QC Type HFA relay Contacts cleaned, COONEY, M J. Philadelphia Electric Co 80/07/27 1p
- 8010270124 RO 2-80-20/1P on 800926. Breaker 52-3723 found in open condition following alarm alert Caused by accidental physical contact w/throw switch Feed immediately restored & sys returned to svc.
 ULLRICH W T Philadelphia Electric Co 80/09/29 2pp
- 80:0080487 LER 60-017/03L-0 on 800904, during surveillance test at full power, RHR B subsystem pump room cooler failed to start automatically Caused by improper adjustment of cell switch on pump breaker Breaker replaced & test completed COONEY.M J Philadelphia Electric Co. 80/09/30 ip
- 80:0140483 LER 80-019/03L-0 on 800906 during surveillance testing. primary centainment air sample flow discovered lost. Caused by short in coil of demo type solenoid valve which blew fuse common to all seven valves Coil replaced COONEY, M J Philadelphia Electric Co 80/10/06. 1p
- 8010210725 Forwards LER 80-020/01T-0 CDONEY, N J Philadelphia Electric Co 80/10/10, 3pp
- --8010210735 LER 80-020/01T-0 on 800926, breaker which supplies power to B standby liquid control was pump & Saquib valve found open.
 Caused by accidental tripping of pump breaker Breaker
 switches of all BBLC pumps locked
 COONEY, M J Philadelphia Electric Co. 80/10/10 ip
- 310270039 PNO-1-80-149 on 801010 unplanned release of 0 5 Ci of DIO270039 PNO-1-80-149 on B01010, unplanned release of 0 9 Ci of noble gas from site Caused by personnel error in opening valve on hydrogen analyser All five affected amployees to receive whole body counts.

 MCGABE, E. C. Region i, Philadelphia, Office of the Director, BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/10/10 ip
- HO1027035B LER 80-018/03L-0 on 800918, MPCI turbine steam line high flow trip instrument revealed that setpoint was 5 inches above Tech Spec limit Caused by setpoint drift of instrument. Instrument recallbr.

 COUNEY: M J Philadelphia Electric Co 80/10/17. 1p.
- O10270363 RD during design review at Limeric? Cenerating Station found instrument air piping to moisture controller not seismically qualified Jumper has been installed which bypasses moisture control contacts ULLRICH, H. T Philadelphia Electric Co 80/10/21 2pp
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8010080341 Forwards revisions to facility for physical security plan. Revisions withheld (ref 10CFR2 790) BRADLEY,E J. Philadelphia Electric Co 80/10/06 3pp

- 8010200394 Notification of 801022 meeting w/util at site to discuss open items to facilities fire protection review VERRELLI, D. M. Operating Reactors Branch 4 80/10/06, 2pp.
- 8010270320 Forwards Suppl 3 to safety evaluation of fire protection programs resolving issues of 790523 evaluation & approving certain mode which should be expedited, REIDR W Operating Reactors Branch 4 80/10/10 2pp
- --8010270322 Suppl 3 to safety evaluation of fire protection programmesolving issues of 790523 evaluation & approving certain Office of Nuclear Reactor Regulation, Director 80/10/10, 411
- O Adjudicatory correspondence
- 8010270307 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing 80/09/19 2pp.
- --B010270307 Revised order for mod of license requiring timely subalstle of info previously requested re environ qualification of safety-related electrical equipment EISENHUT.D.O Division of Licensing 80/09/19. App.
- 8010200239 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 STELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02. Ip
- 80[022054] Forwards radon info in response to request Info should be made available to ASLAB & parties in radon proceedings, ELLETT, W.H. Environmental Protection Agency. 80/10/10 150pp,
- J Insurance & indemnity information
- 8010280292 Requests endorsements & copy of Amend 21 to Policy 9-28 DINITA: I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- 8010240522 Responds to NRC 800924 ltr indicating that signed copy of Amend 21 to Indemnity Agreement 8-28 was never received.

 Amend 21 was signed by co-owners & forwarded to J Saltzman BRADLEY, E J Philadelphia Electric Co 80/10/09, ip.
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8010170317 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Scram Bys." 8TAMPELOB. J ACR8 Advisory Committee on Reactor Safeguards 80/08/08 ip.
- --8010170333 Interim preliminary draft rept to ACRB, "Review of Recent Malfunctions of BWR Boram Bys "

 # ACRB -- Advisory Committee on Reactor Bafegyards. 80/08/08.
- P Operating license stage documents & correspondence
- 8010200393 Advises of possible delay in Dec 1980 planned operation of interim ultrasonic scram discharge vol level monitoring sys.

 OE has revised shipping date to 801114 & advised that sys is prototype. COONEY, H J. Philadelphia Electric Co 80/09/18, ip.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D O Division of Licensing. 80/09/19. 28pp.
- 80100A0147 Forwards request for add1 info re adequacy of station electric distribution mys voltages Response should be submitted within 45 days.
 REID.R W Operating Reactors Branch 4, 80/09/22, 4pp.
- 8010080135 Forwards Amends 73 & 72 to Licenses DPR-44 & DPR-56: respectively, safety evaluation & notice of issuance & availability REIO.R.M. Operating Reactors Branch 4 80/09/22, 2pp.

- --9010080161 Amends 72 & 73 to Licenses DPR-56 & DPR-44, revising tables of containment isolation valves & safety-related snubbers to reflect mods completed or planned by licensee REID.R.W Operating Reactors Branch 4, 80/09/22 8pp
- --8010080169 Safety evaluation supporting Amends 73 & 72 to License DPR-44 & PPR-56, respectively a Office of Nuclear Reactor Regulation, Director 80/09/22 3pp
- --B0100B0173 Notice of issuance & availability of Amends 73 & 72 to Licenses DPR-44 & DPR-36, respectively REID,R.W Operating Reactors Branch 4, B0/09/22 2pp
- 8D100B0604 Requests add1 action re NRC 780B07 ltr re deficiencies in Hatch.Unit 2 regulator sys design Reactor protection sys power supply should be modified by end of next refueling sutage REID.R W Operating Reactors Branch 4 80/09/24 Spp
- 8010020488 Forwards application to amend App A of Licenses DPR-44 & DPR-56, revising Tech Spec Sections 3 1 & 4 1 re max average planar lifeser heat generation rate & reactor protector systemates time Fee forwarded BRADLEY, E. J. Philadelphia Electric Co 80/09/30, 1p.
- --B010020490 Application to amend App A of Licenses DPR-44 & DPR-56, revising Tech Spec Sections 3 i & 4 i re max average planar linear heat generation rate & reactor protector sys response time Certificate of Syc encl
 BAUER, E. Q., BRADLEY, E. J., BOYER, V. B. Philadelphia Electric Co. B0/09/30 Spp
- --8010020473 Proposed amend to Tech Spec Sections 3 1 & 4 1 re max everage planar linear hast generation rate & reactor protector sys response time * Philadelphia Electric Go 80/09/30 7pp.
- --B010020494 Addenda 2 to "LOGA Analysis for Peach Bottom Atomic Power Station Unit 3." * General Electric Go NEDO-24082 ADD 2 80/06/30 7pp.
- EO10200045 Confirms discussions re 801008 visit by Bandia Natl Lab & BAI to observe physical layout of plant re design of vent-filter sys REID:R N Operating Reactors Branch 4 80/10/01 2pp.
- 8010070339 Responds to NRC request for info re implementation of TMI-2 action plan requirements initiation levels of HPCI & RCIC sys should be separated so that RCIC sys will initiate higher water level than HPCI sys.

 GALLACHER, J. H. Philadelphia Electric Co. 80/10/02. 6pp.
- 8010200458 Application for amend to License DPR-44 & DPR-56 consisting of change to Tech Specs.
 ALDEN.H.M. Philadelphia Electric Co. 80/10/03. 1p
- --B010200461 Tech Specs 3.15 & 4.15 for seismic monitoring instrumentation & seismic monitoring instrumentation & surveillance requirements + Philadelphia Electric Co 80/10/03 2pp.
- BO\$0270386 Requests fee remittence within 15 days after receipt of 1tr re 800808 application for review of proposed seismic monitoring instrumentation Tech Bpec HillER N.O. License Fee Management Branch. 80/10/09. ip
- BO10200451 Forwards application for amend of Licenses DPR-44 & DPR-55, incorporating scram discharge vol valves surveillance requirements & reactor protection sys & control rodblock limit switches limiting conditions. Class III fee encl.
 BRADLEY,E J. Philadelphia Electric Co. 80/10/14, ip.
- --B010200459 Application for amend of Licenses DPR-44 & DPR-56, incorporating Tech Specs re scram discharge vol valves surveillance requirements & reactor protection sys limiting conditions. M/Certificate of Svc. BAUER, E. G., BRADLEY, E. J., Philadelphia Electric Co., 80/10/10, 7pp.
- --BDI0200464 Proposed Yech Brecs, Sections 3.0 & 4.0, incorporating surveillance requirements re scram discharge vol valves & limiting conditions re reactor protection sys & control red block limit switches.

 * Philadelphia Electric Co BO/10/10, 9pp.
- BO10200584 Responds to NRC 800821 request for add1 info re util 800921 request for amend to Tech Specs. Discusses degraded grid voltage proposed time delay relays.

 DALTROFF.S.L. Philadelphia Electric Co. 80/10/14. 4pp.

- 8010200404 Assesses util capability to implement near-term NRC action plan requirements (NUREO 0660) & proposed schedule.Plan items re implementation status, proposed implementation plan & current shift technical advisor training program encl DALTROFF, B L Philadelphia Electric Co. 80/10/15. 18pp.
- 8010210329 Withdraws 750617 application for amend of Licenses DPR-44 & DPR-56, as supplemented by 770225 ltr Reactor core design improvements implemented at recent refueling outages are providing desired control rod withdrawal flexibility BRADLEY, E. J. Philadelphia Electric Co. 80/10/16 ip
- 8010280372 Forwards QE evaluation of proposed mod to HPCI & reactor core isolation cooling sys on behalf of BHR owners group Concurs w/owners group assessment that setpoint changes will yield minimal reduction in thermal cycle history QALLAOHER, J. W Philadelphia Electric Co 80/10/24 7pp
- 8010280423 Responds to NRC 801001 ltr re-scram sys. Study of long-term sys reliability initiated. Results of evaluation & proposed mods will be submitted by 801215.

 GALLAGHER, J W Philadelphia Electric Co 80/10/24 3pp
- G Inspection reports: IE Bulletins & correspondence
- 8010020058 Forwards IE Insp Repts 50-277/80-23 & 50-278/80-17 on 800701-03, No noncompliants nated CARLSON, T Region 1, Philadelphia, Reactor Construction & Engineering Support Brench. 80/08/13 2pp
- --8010020067 IE Insp Repts 50-277/80-23 & 50-278/80-17 on 800701-09 No noncompliance noted Major areas inspected Class IE electrical equipment inside containment associated w/mein steam & feedwater sys EBNETER, S.D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch FINKEL, A.E., Region i, Philadelphia, Office of the Director 80/08/fil. 18pp
- 8010010803 Responds to IE Bulletin 80-17.All scram tests successfully performed Facilities returning to Tech Spec reporting requirements for equipment operability DALTROFF, B L Philadelphia Electric Co. 80/08/21. 6pp.
- 8010020331 Responds to AL Finkle 800814 telcon re IE Bulletin 79-018 re environ qualification of Class IE equipment. Discusses mathod used for review DALTROFF, BL Philadelphia Electric Co 80/08/26 ip.
- 8010020203 Responds to IE Bulletin 80-19, Mercury-wetted relays are not used in reactor protection sys
 DALTROFF, S.L. Philadelphia Electric Co 80/08/27. ip.
- 8010010707 Responds to 1E Bulletin 80-17. Suppls 1 & 3.re failure of control rods to fully insert during scram at BMR. Various procedural changes implemented to satisfy requirements of bulletin.

 DALTROFF, 8 L. Philadelphia Electric Co 80/08/29 5pp
- 8010010821 Responds to IE Bulletin 80-15 re emergency notification sys. Autometic transfer capability provides power from emergency bus. Approx 80 manhours expended on bulletin. DALTROFF,8.L. Philadelphia Electric Co. 80/08/29. Spp.
- B010010107 Ack receipt of 800821 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-01 & 50-278/80-01 BRUNNER,E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch.
- ---8010010116 Responds to NRC 800731 ltr re violations noted in IE Insp. Repts 50-277/80-01 & 50-278/80-01 Corrective actions: required documentation completed for personnel w/o dosimetry DALTROFF,8 L. Philadelphia Electric Co. 80/08/21. 2pp.
- --8010010120 Forwards IE Insp Repts 50-277/80-01 t 50-278/80-01 on B00101-31 & notice of violation BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/07/31. 2pp.
- --B010010126 Notice of violation from insp on 800101-31, # Region 1, Philadelphia, Office of the Director. B0/07/29 ip.
- --B010010136 IE Insp Repts 50-277/80-01 & 50-278/80-01 on 800101-31. Noncompliance noted: failure to adhere to health physics procedural requirements to wear personnel dosimetry in controlled areas.

 MCCABE, E. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, OREENMAN, E. C., COMGILL, C. J., Region 1, Philadelphia, Office of the Director 80/07/29, 10pp.

- B010010244 Responds to IE Bullotin B0-20 re Westinghouse Type H-2 control switches Bwitches are installed in safety-related applications No safety-related function would be disabled by neutral contact failure OALLAGHER.J W Philadelphia Electric Co 80/07/10 3pp
- B010200237 Forwards order confirming Util commitments to implement action re IE Bulletin 80-17 STELLO,V. Office of Inspection & Enforcement, Office of the Director 80/10/02 tp
- ~~8010200252 Order confirming util commitments to implement action re IE Bulletin 80-17 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp
- 8010240130 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER, B.M. Region 1, Philadelphia, Office of the Director 80/10/02 Ip
- 8010230104 Responds to IE Bulletin 79-26, Revision 1, "Boron Loss from BHR Control Blades " Corrective actions fall into categories of add1 safety analyses & control blade replacements. Approx 40 man-days expended for control blade replacements DALTROFF. S.L. Philadelphia Electric Co. 80/10/06 2pp
- 8010280224 Forwards IE Info Notice 80-34, "Failure of Steam Oenerator Support Solting "No specific action or response requested ORIER.B H Region 1, Philadelphia, Office of the Director. 80/10/10 1p
- R Periodic operating reports & related correspondence
- 710100350 Forwards radioactive effluent data, w/corrections shown based on calculation of quarterly releases in response to RA Hartfield 800724 ltr request for review & comment. DALTROFF.8 L. Philadelphia Electric Co. 80/10/07 14pp
- 010150375 Forwards monthly operating repts for Bept 1780 COUNEY, H J Philadelphia Electric Co 80/10/10. ip
- ---B010150377 Monthly operating repts for Gept 1980 ALDEN, W.M. Philadelphia Electric Co. 80/10/10 9pp.
- 6 Reportable occurrences. LERs & related correspondence
- B010080544 PNO-I-80-122 on 800815, unplanned release of gaseous radioactivity from Unit 3 reactor bigg vent occurred. Peak release rate was 33% of Tech Spec limits. Cause believed to be malfunction of Unit 2 offgas sys.

 OREENMAN.E., BRUNNER.E.J. Region 1, Philadelphia, Office of the Director 80/08/15, 1p
 - 10030366 Updated LER 80-014/03X-1 on 800608, during surveillance test s/unit at full power, outboard isolation valve M0-3-10-26B for B RMR containment spray failed to close Caused by stem tut jammed against drive sleeve, Nuts repositioned COUNEY, M. J Philadelphia Electric Co. 80/09/26 ip
-)10070496 LER 80-023/03L-0 on 800908 reactor water cleanup demineralizer water inlet temp switch did not actuate at 200 F Causad by setpoint drift Switch recalibr & satisfactorily tested COUNEY, M J Philadelphia Electric Co 80/09/30 ip.
-)10210668 LER 80-024/03L-0 on 800911. during daily test. Plou through primary containment gas campler was found to have stopped. Caused by pump failure due to open circuit in pump local control switch Buitch was replaced & pump tested Philadelphia Ejectric Co. 80/10/10 19
- NOIO270039 PNO-I-60-149: on BO1010, unplanned release of Q 5 Gi of noble gas from site Caused by personnel error in opening valve on hydrogen analyzer All five affected emplayees to receive whole body counts MGCABELE C Region 1. Philadelphia. Office of the Director BRUNNER, E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch BO/10/10 Ip
- 8010270375 LER 80-025/03L-0, on 800917, indication for 8V-3978A Q control switches was lost Caused by short in coil of Dymo Type solenoid valve which blew common fuse in control circuit for all sevel valves fore replaced, COONEY, M J Philadelphia Electric Co. 80/10/17 1p.

- BD10270545 PNO-I-80-153 on B01020.1 BP Ci noble gas release occurrif from ventilation stack shortly after mechanical vacuum pump start for maint of condenser vacuum during shutdown Pump stacted within five minutes investigation undermay MCCABE.E C Region i. Philadelphia, Office of the Director KNAPP.P J. BRUNNER.E J Office of Inspection & Enforcement, Office of the Director BO/10/20 ip
- 8010270363 RO during design review at Limerick Generating Station for instrument air piping to moisture controllar not seismically qualified Jumper has been installed which bypasses moisture control contacts

 ULLRICH, UT Philadelphia Electric Co 80/10/21 2pp
- 8010310443 LER 80-024/03X-1 on 800911.flow through primary contains to gas sampler stopped Caused by open circuit in sample sthaust pump local control switch Switch replaced COONEY.H J Philadelphia Electric Co 80/10/22 ip.
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F Security, medical, emergancy & fire protection plans
- 8010090497 Ack receipt of 800603 & 0718 security plan changes Plan is acceptable & will be withheld (ref 100FR2 790)

 VARGA, 8 A Deprating Reactors Branch I, 80/10/01 2pp
- 8010210019 Notification of 801027 meeting w/util in DethesdartD to discuss emergency response facilities ENGLE:L Operating Reactors Branch 3 80/10/01 3pp
- 8010310336 Forwards status of fire protection mods requiring completion by 801031, general project summary & design info. in response to NRC 790919 fire protection SER SYLVIA: R R Virginia Electric & Power Co 80/10/29 15pp
- H General correspondence
- 8010230652 Responds to 800626 ltr to FERC inquiring when plants will a operational Provides schedule for projected plant restart Cartificate of Svc encl DENFOLM R Office of Nuclear Reactor Regulation, Director 80/09/05 5pg
- J Insurance & indemnity information
- B0102B0230 Requests endorsement & copy of Amend B to Policy B-5a DINITZ.1. Utility Finance Branch (formerly Antitrust & Indeanity) B0/09/24
- P. Operating license stage documents & correspondence
- B010050172 Ack response to NRC 791109 ltr re ECCS evaluation asiels dealing w/fuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VARGA. B A Operating Reactors Branch 1 80/09/12 2pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedula also encl. EISENHUT, D. Q. Division of Licensing 80/09/19 28pq.
- 8010010678 Forwards "Evaluation & Critique of NUREO/CR-1980 "
 Document does not reflect importance in quality or
 applicability to nuclear power station control rooms
 EYLVIA, B. R. Virginia Electric & Power Co. 80/09/26 1p.
- --B010010498 "Evaluation & Critique of NUREO/CR-1580" # Virginia Electric & Power Co. B0/09/30 100pp
- 8010070180 Confirms that all 800101 to 0201 auxiliary feedwater sys commitments contained in 791108 ltr were completed within stated deadlines BYLVIA:B.R. Virginia Electric & Power Co 80/09/30 ip
- 8010070312 Responds to NRC request for updated status rept on reactivessel flange seal ring analysis Westinghouse owners group study offers rationale for not requiring installation of pipe break restraints

 BYLVIA, B R Virginia Electric & Power Co 80/09/30, 2pp.
- 8010070178 Informs NRC that Tech Brecs for engineered sefety system ventilation filters will be provided by 801031 SYLVIA-8.R. Virginia Electric & Power Co. 80/10/02 lp.

.

 $\beta_{\mathbf{q}}$

| .

4 1 .

0070378 Responds to NRC 800905 request for info re THI action plan squirement preliminary clarification Wastinghouse owners roup meeting w/NRC will determine addl effort required & s-evaluation will be submitted Deadline unrealistic yLVIA, B R Virginia Electric & Power Co 80/10/02 2pp

0980436 Forwards response to NRC 800928 ltr re auxiliary feedwater ys design basis info & pump flow verification Testing for poter driven Auxiliary Feedwater Pump 1-FH-P-3B is scheduled wiring upcoming fueling outage yk.VIA Virginia Electric & Power Co 80/10/06 2pp

0130248 Forwards draft summary data sheets for effluent & waste isposal repts Recommended changes are marked on sheets & resented in summation YUVIA:BR Virginia Electric & Power Co 80/10/10 19pp.

0200453 Informs that license amend application package in response o NRC 800411,0702 & 0815 ltrs will be delayed until on or bout 801115 due to difficulty of incorporating 8TB aquirements into nonstandard format of facility Tech Specs. YLVIA.B.R Virginia Electric & Power Co. 80/10/15 1p

0240446 Provides current status & schedule for implementing in-house eload licensing, to facilitate orderly review of probable icense amend proposals planned for third quarter 1981 & irst quarter 1982 Requests interim meeting. HOMAS, W N Virginia Electric & Power Co 80/10/17 Spp.

024045; Responds to NRC 90073; Itr re shift staffing requirements hift staffing determined in compliance w/criteria. YLVIA, BR Virginia Electric & Power Co 80/10/22 ip

031041; Application for amend of Licenses DPR-32 & DPR-37, adding ech Specs 3 22 & 4 20 re components of auxiliary entilation sus & changing Tech Specs 4 15 re IE Bulletin 9-14 & 4 68 re inservice insp Class III fee encl EROUSDNJ H Virginia Electric & Power Co 80/10/28 3pp

0310411 Application for amend of Licenses DPR-32 & DPR-37, adding ech Specs 3 22 & 4,20 re components of auxiliary entilation sys & changing Tech Specs 4 15 re IE Bulletin 9-14 & 4,18 re inservice insp.Class III fee encl EROUSON, J H Virginia Electric & Power Co. 80/10/28, Spp

010310417 Proposed Tech Specs adding Sections 3 22 & 4 20 re components of safety-related auxiliary ventilation sys & revising Tech Spec 4 15 re IE Bulletin 79-14 & Tech Spec 4 tS re inservice insp program, * Virginia Electric & Power Co 80/10/28 13pp

Inspection reports, IE Bulletins & correspondence

5120293 Forwards Waste Packaging Insp 80-03 on 800227-29 No oncompliance noted TOHR.J.P Region 2, Atlanta, Fuel Facility & Materials Bafety rench. 80/03/20 2pp.

005i20230 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted.Major areas inspected.placarding requirements; radiation levels, marking & labeling requirements for packages POTIERJP, Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/03/17 7pp

0090013 Forwards IE Insp Repts 50-280/80-27 & 50-281/80-31 on 00721-25 No noncompliance noted URPHY:C E Region 2: Atlanta, Reactor Construction & Engineering upport Branch. 80/08/25 2pp

010070019 IE Insp Repts 50-280/80-27 & 50-281/80-31 on 800721-25. No noncompliance noted. Major areas inspected: documentation review re IE Bulletin 79-018 response CONLON, TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch HARDNICK, R. J. Region 1, Philadelphia, Office of the Director 80/08/25 7pp.

0090149 Forwards IE Insp Repts 50-280/80-28 % 50-281/80-32 on 00729-0801 No noncompliance noted UMPHY.C.E. Region 2: Atlanta: Reactor Construction & Engineering Upport Branch. 80/08/25 2pp.

010090152 IE Insp Repts 50-280/80-28 & 50-281/80-32 on 800729-0801. No noncompliance noted Major areas inspected licensee action on previous insp findings, preservice insp records & LERs. HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch, CROWLEY, B.R. Region 2, Atlanta, Office of the Director, 80/08/19 ip,

- B010230090 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls "No written response required CIREILLY, J P Region 2, Atlanta, Office of the Director 80/08/29,
- 8010300360 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted BTOHR.JP Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/09/19. 2pp
- --B010300369 Waste Packaging Insp Rept 15000039/B0-15 on B00727-0B01
 No nencompliance noted Major areas inspected shipping paper,
 DOT placarding, resistion levels: removable contamination &
 DOT marking & labeling requirements for packages
 HACGRIHUR: T C Region 1. Philadelphia, Fuel Facility & Materials
 Safety Branch POTTER. J P Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch B0/09/16 Bpp
- 8010140099 Responds to IE Bulletin 80-18 To assure min flow from centrifugal charging pumps. Westinghouse will implement mods to boost pressure Response required 120 manhours GYLVIA, B R Virginia Electric & Power Co 80/09/26 2pp.
- 8010270497 Forwards IE Info Notice 80-94, "Boron Dilution of Reactor Coolant During Steam Consentor Decontamination " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/26
- 8010140130 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. BO/09/30
- 8010170214 Forwards 90-day response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Includes info remaster list of engineered safety feature sys flood level inside primarry containment from postulated accident BYLVIA, B.R. Virginia Electric & Power Co. BO/10/01. 300pp
- 8010200333 Ack receipt of 800905 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-23 & 30-281/80-26 LEWIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/10/01
- 8010070168 Informs that util will proceed w/proposed disassembly & insp program for reactor coolant pump supports in near future Results will be forwarded to NRC after insp is completed BYLVIA.3 R Virginia Electric & Power Go BO/10/O2 ip
- 8010270555 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/02
- 8010270060 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Boiting " No specific action or response requested O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 80102003B9 Forwards monthly operating repts for Sept 1980 & corrected rept for Apr 1980
 BYLVIA B. R Virginia Electric & Power Co 80/10/15 ip,
- --B010200392 Corrected monthly operating rept for Apr 1980. DUNN. B. D. Virginia Electric & Power Co. BD/09/14, 2pp
- --8010200396 Monthly operating repts for Sept 1980. COSTELLO:O J Virginia Electric & Power Co. 80/10/09 46pp.
- 8. Reportable occurrences, LERs & related correspondence
- 8010160669 PNO-II-80-124: on B00714, boilermaker employed by B&H died of heart attack Boilermaker was foreman for repair of oil fired auxiliery boiler HARDINA.K., KELLU00.P.J. Region 2, Atlanta, Office of the Director. 80/07/14. ip
- 8010010576 Forwards LER 80-060/03L-0 & LER 80-024/03L-0 WILSON J L. Virginia Electric & Power Co. 80/09/26 2pp

- --8010010380 LER 80-060/03L-O on 800831, low flow alarm was indicated for RM-QH-101/102 Process vent sys isolated Caused by failure of vacuum pump drive belt Belt replaced, pump & sys returned to svc MILSON, J L. Virginia Electric & Power Co 80/09/26 1p
- --B010010586 LER B0-024/03L-0 on 800828.w/unit in intermediate shutdown, inside trip valve TV-85-200A would not close & remain closed when control switch was released Caused by failure of close limit switch Limit eartch replaced
 WILSON.J L Virginia Electric & Power Co 80/09/26 2pp
- 8010080438 Forwards LER 80-066/03L-0 WILSON,J L. Virginia Electric & Power Co E9/10/02 ip
- --8010080441 LER 80-066/03L-0 on 800902, during monthly operational test of emergency diesel generator 1, base tank level dropped to 160 gallons w/o being replenished automatically from day tank Caused by stuck base tank control switch HILSON, J. Virginia Electric & Power Co 90/10/02 2pp
- 8010080395 Forwards LER 80-061/03L-0 WILSON, J.L. Virginia Electric & Power Co 80/10/03 ip
- --8010080399 LER 80-061/03L-0 on 800904, release valve, HCV-LK-104A, was not closed as required & 3% of A liquid waste test tank was released before release rate had been determined Caused by operator error MTLSON, J L Virginia Electric & Power Co 80/10/03 2pp
- B0101504B1 Forwards LER 90-053/03L-0 WILSON, J. L. Virginia Electric & Power Co. 80/10/09 1p
- --8010150486 LER 8D-053/03L-O on 800909, recirculation valve 1-R8-6 for outside recirculation spray pump 8 was found open Cause undetermined WILSON, J L Virginia Electric & Power Co 80/10/09 2pp
- B010200491 Forwards LERs 80-014/03L-0,80-044/03L-0,80-045/03L-0 & 80-025/03L-0.
 HILSON,J L Virginia Electric & Power Co 80/10/14. ip.
- --B010200499 LER 80-016/03L-0 on 800916.w/unit operating steady state at 100% power.TV-85-2018 would not remain closed when control switch was released. Cause undetermined, Inside trip valve closed & air secured to TV-65-2018.
 WILSON,J L. Virginia Electric & Power Co. 80/10/16. 2pp.
- --8010200506 LER 80-064/03L-0 on 800916.w/Unit 1 at cold shutdown & Unit 2 at 100% pawer.auxiliary bldg filter banks found to be less efficient than required Caused by settling of charcoal in filters Filters replaced WILSON.J.L. Virginia Electric & Power Co. 80/10/16 2pp.
- --8010200524 LER 80-025/03L-0 on 801003.w/Unit 2 at 100% power.periodic test 27D revealed that amperage for circuit 2A panel 10 was below acceptance criteria Gaused by damaged heat tracing tape. Verified that redundant circuit was operable WILBON, J. L. Virginia Electric & Power Co. 80/10/16 2pp
- ---8010200513 LER 80-065/03L-0 on 800917, w/unit at refueling shutdown, MOV-8W-1038 did not operate electrically during flush of recirculation spray heat exchangers Cause undetermined, but marine growth suspected Valve manually cycled WILSON, J L. Virginia Electric & Power Co. 80/10/16. 2pp
- 8010280558 Forwards LERs 80-058/03L-0 & 80-018/03L-0 WILSON, J L Virginia Electric & Power Co 80/10/23. ip.
- -8010280565 LER 80-068/03L-0 on 800923, radiation manitoring sampling pumps i-SN-P-3C & D were found to be inoperable. Caused by corraded pump impeller & seals Pumps will be removed, tested & inspected prior to startug WILSON. J. L. Virginia Electric & Power Co. 80/10/23 2pp.
- --8010270165 LER 80-018/03L-0 on 800924 charging pump ave water pump 2-8M-P-10A would not develop proper discharge head.Caused by buildup of matl that had been entrained in suction side of pump Pump inspected.cleaned & tested.
 WILSON,J L Virginia Electric & Power Co. 80/10/23. 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8010090497 Ack receipt of 800603 & 0718 security plan changes. Plan is acceptable & will be withheld (ref 10GFR2, 790).
 VAROA. 8. A Operating Reactors Branch 1. 80/10/01, 2pp.

- 8010210015 Notification of 801027 meeting w/util in Bethesda,MD to discuss emergency response facilities ENGLE.L. Operating Reactors Branch 3 80/10/01 3pp
- 9010310336 Forwards status of fire protection mods requiring completion by 801031, general project summary & design info, in response to NRC 790919 fire protection SER SYLVIA, B R Virginia Electric & Power Co 80/10/29, 15pp
- H Deneral correspondence
- 9010230652 Responds to 800626 ltr to FERC inquiring when plants will be operational Provides schedule for projected plant restart Certificate of Evc encl.

 DENION.H R Office of Nuclear Reactor Regulation, Director, 80/09/05 3pp
- J Insurance & Indomnity information
- 8010280230 Requests endorsement & copy of Amend 8 to Policy 8-54 DINITZ. I Utility Finance Branch (formerly Antitrust & Indeanit) 80/09/24 ip
- P Operating license stage documents & correspondence
- 80:00:10:72 Ack response to NRC 77:107 ltr re ECCS evaluation models desiing wifuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VAROA.S. A Operating Reactors Branch 1. 80/09/12, 2pp
- B010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EIBERHAUT, p 0 Division of Licensing B0/09/19, 20pp
- 8010010678 Forwards "Evaluation & Critique of NUREO/CR-1580 "
 Document does not reflect importance in quality or
 applicability to nuclear power station control rooms.
 874.VIA.8.8 Virginia Electric & Power Go 80/09/26 lp
- --B010010688 "Evaluation & Critique of NUREO/CR-1580 "

 * Virginia Electric & Power Co 80/09/30 100pp
- B010070180 Confirms that all 800101 & 0201 auxiliary feedwater tyte commitments contained in 791108 its were completed within stated dwadlines.
 BYLVIA: B R. Virginia Electric & Power Co 80/09/30. ip.
- B010070312 Responds to NRC request for updated status rept on reactor vessel flange seal ring analysis. Westinghouse owners group study offers rationals for not requiring installation of pipe break restraints.

 BYLVIA, B, R. Virginia Electric & Power Co 80/09/30 2pp.
- 8010070178 Informs NRC that Tech Specs for engineered safety system ventilation filters will be provided by 801031
 BYLVIA, B R Virginia Electric & Power Co 80/10/02. 1p
- 8010070378 Responds to NRC 800905 request for info re TMI action play requirement preliminary clarification Hestinghouse owners group mesting w/NRC will determine addleffort required & re-evaluation will be submitted Deadline unrealistic BYLVIA: B. R. Virginia Electric & Power Co 80/10/02 Rpp
- B01015024B Forwards draft summary data sheets for effluent & wasts disposal repts Recommended changes are marked on sheets & presented in summation BYLVIA B. R. Virginia Electric & Power Co. B0/10/10. 15pp.
- 8010200493 Informs that license amend application package in respense to NRC 800611.0702 & 0815 ltrs will be delayed until on or about 801115 due to difficulty of incorporating 8TB requirements into nonstendard format of facility Tech Brecs BYLVIA.B R. Virginia Electric & Power Co. 80/10/10 ip.
- 8010210350 Forwards steem turbine driven auxiliary feed water fumps and Urance test rept. 8YLVIAB.R. Virginia Electric & Power Co. 80/10/17. 9pp

- 8010240446 Provides current status & schedule for implementing in-house reload licensing, to facilitate orderly review of probable license amend proposals planned for third quarter 1981 & first quarter 1982 Requests interim meeting THOMAS.W N Virginia Electric & Power Co 80/10/17 Spp
- 8010240451 Responds to NRC 800731 ltr re-shift staffing requirements Shift staffing determined in compliance w/criteria, SYLVIA.B R Virginia Electric & Power Co 80/10/22 ip
- BOIO310411 Application for amend of Licenses DPR-32 & DPR-37, adding Tech Specs 3 82 & 4 20 re components of auxiliary ventilation sys & changing Tech Specs 4 15 re IE Bulletin 79-14 & 4 18 re inservice insp Class III fee encl FERGUSON, J H Virginia Electric & Power Co 80/10/28 3pp
- --8010310417 Proposed Tech Specs adding Sections 3 22 & 4 20 re components of safety-related auxiliary ventilation sys & revising Tech Spec 4 15 re IE Bulletin 79~14 & Tech Spec 4 18 re inservice insp program * Virginia Electric & Power Co 80/10/28 13pp

Q Inspection reports, IE Bulletins & correspondence

 $\vdash t_{0}$

VIII is

ai tei

4111

WI

Tegter

1.0114

P#111

łŧ

18610

441

- E010020266 Forwards IE Insp Rept 50-281/80-30 on 800724-25 No nancompliance noted MMRPHY:C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/22 2pp.
- --8010020273 IE Insp Rept 50-281/80-30 on 800724-25 No noncompliance noted. Major areas inspected seismic analysis for as-built safety-related piping sys & pipe support base plate designs using concrete expansion buits COMPTON. R.M., MODEMOS, L. Region 2, Atlanta, Office of the Director. HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/22 4pp.
- B010070013 Forwards IE Insp Repts 50-280/80-27 & 50-281/80-31 on 800721-23 No noncompliance noted. MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 2pp
- --8010090019 IE Insp Repts 50-280/80-27 & 50-281/80-31 on 800721-25 No noncompliance noted Major areas inspected documentation review re IE Bulletin 79-018 response CONLON, T. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARDWICK, R. J. Region 1. Philadelphia, Office of the Director 80/08/25 7pp.
- 8010090149 Forwards lE Insp Repts 50-280/80-28 & 50-281/80-32 on 800729-0801 No noncompliance noted MURPHY.C.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/08/25, 2pp
- --8010090152 IE Insp Repts 50-280/80-28 & 50-281/80-32 on 800729-0801, No noncompliance noted Major areas inspected, licensee action on previous insp findings, preservice insp records & LERs HERDT.A.R Region 2. Atlanta, Reactor Construction & Engineering Support Branch CROWLEY.B.R Region 2. Atlanta, Office of the Director. 80/08/19. lp.
- 8010230090 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Hatls "No written response required, O'REILLY, J.P., Region 2, Atlanta, Office of the Director, 80/08/29 200.
- 8010300360 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 Mo noncompliance noted.

 STORR: J P Region 2: Atlanta: Fuel Facility & Materials Bafety Branch. 80/09/19 2pp.
- --8010300369 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801
 No noncompliance noted Major areas inspected shipping paper,
 DOT placarding radiation levels, removable contamination &
 DOT marking & labeling requirements for packages
 MACARTHUR: T C. Region 1: Philadelphia: Fuel Facility & Materials
 Bafety Branch POTTER, J.P. Region 2: Atlants, Fuel Facility &
 Materials Safety Branch. 80/09/16. 8pp
- 80:0160099 Responds to IE Bulletin 80-18, To assure min flow from centrifugal charging pumps, Westinghouse will implement mods to boost pressure. Response required 120 membours SYLVIA, B R Virginia Electric & Power Co 80/09/26 2pp
- 8010270497 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontemination " No specific action or response requested.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/09/26

- 80:01:60:30 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/09/30 ip
- 8010170214 Forwards 90-day response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Includes info re master list of engineered safety feature sys flood level inside primary containment from postulated accident BYLVIA.B R Virginia Electric & Power Co B0/10/01 300pp
- 8010200333 Ack receipt of 800905 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-23 & 50-281/80-26 LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support
- BO1007016B Informs that util will proceed w/proposed diseasembly & insp program for reactor coalant pump supports in near future Results will be forwarded to NRC after insp is completed BYLVIA.B R Virginia Electric & Power Co. 80/10/02. 1p
- 8010270555 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 to.
- B010270060 Forwards IE Info Notice B0-36, "Failure of Bteam Generator Bupport Bolting " No specific action or response requested G'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/10/10
- R Periodic operating reports & related correspondence
- 8010200389 Forwards monthly operating repts for Sapt 1980 & corrected rept for Apr 1980
 SYLVIA, B. R. Virginia Electric & Power Go 80/10/15 ip
- --8010200396 Monthly operating repts for Sept 1980 COSTELLO, D J. Virginia Electric & Power Co 80/10/09. 46pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010160668 PNU-II-80-124. on 800714, boilermaker amployed by B&W died of heart attack Boilermaker was foreman for repair of oil fired auxiliary boiler HARDINA K , KELLOGG, P J Region 2, Atlanta, Office of the Director 80/07/14 ip
- 8010070307 PND-II-80-i41 on 800814, unit achieved criticality following extended outage for steam generator replacement. Reactor will remain at low power for 24-h to conduct physics testing. No further action anticipated.

 HARDIN, A. K., KELLUGO, P. J. Region 2, Atlanta, Office of the Director. 80/08/13 1p.
- 8010160588 PNO-II-80-144. on 800826, reactor trip & safety injection occurred due to spurious steam header to steam line differential pressure Caused by entrapped air in bypass around newly instelled polishing demineralizers JOHNSON. A. . KELLOGO, P. J. Region 2. Atlanta, Office of the Director 80/08/27 1p.
- 8010010576 Forwards LER 80-060/03L-0 & LER 80-024/03L-0.
 WILSON, J. L. Virginia Electric & Power Co. 80/09/26 2pp.
- --G010010586 LER 80-024/03L-0. on 800828, w/unit in intermediate shutdown, inside trip valve TV-88-200A would not close & remain closed when control switch was released. Caused by failure of close limit switch. Limit switch replaced WILBON, J L. Virginia Electric & Power Co 80/09/26 2pp
- 8010200491 Forwards LERs 80-016/03L-0,80-064/03L-0,80-065/03L-0 & 80-025/03L-0.
 WILBON, J L. Virginia Electric & Power Co. 80/10/16 ip
- ~-8010200499 LER 80-016/03L-0:on 800916.w/unit oparating steady state 100% power, TV-SH-201B would not remain closed when control switch was released. Cause undetermined Inside trip valve closed & air secured to TV-88-201B.

 WILSON, J. L. Virginia Electric & Power Co. 80/10/16. 2pp
- --B010200524 LER 80-025/03L-0 on 801003, w/Unit 2 at 100% power, period test 27D revealed that amperage for circuit 2A panel 10 was below acceptance criteria. Caused by damaged heat tracing tape Verified that redundant circuit was operable.

 WILBON, J.L Virginia Electric & Power Co. 80/10/16. 2pp

- 8010280558 Forwards LERs 80-068/03L-0 & 80-018/03L-0 WILBON-J.L. Virginia Electric & Power Co 80/10/23 is
- --8010270166 LER 80-018/03t-0 on 800924, charging pump svc water pump 2-SK-F-10A would not develop proper discharge head Caused by buildup of matl that had been entrained in suction side of pump Pump inspected, cleaned & tested WILSON, J. Virginia Electric & Power Co 80/10/23 2pp
- 8010280506 Forwards LER 80-028/03L-0 WILSON, J L Virginia Electric & Power Co 80/10/24 ip
- --8010280512 LER 80-028/03L-0 on 800926, w/unit at 100% power, reduction in svc water pressure to charging pumps experienced Caused by missing valve disk for check valve 2-84-112 Valve replaced.
 HILSON, J L Virginia Electric & Power Co 80/10/24. 2pp

DOCKET 50-282 PRAIRIE IBLAND NUCLEAR STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 9010070315 Forwards Revision 2 of "Emergency Preparedness Evacuation Time Estimates " Revision provides evacuation time estimates based on more refined methodology MAYER.L O. Northern States Power Co 60/09/26, ip
- --8010070316 Revision 2 of "Emergency Preparedness Evacuation Time Estimates, "

 * Northern States Power Co 80/09/30 18pp
- 8010100362 Requests extension until 810101 to comply w/NRC 790906 fire protection SER Mode will be made to penetration seal upgrade, turbine bidg structural steel coating, alternate shutdown capability & add fire dampers.

 YAYER.L.O Northern States Power Co. 80/10/03 4pp.
 - 10310355 Forwards "Pire Qualification Test on Retrofit Penetration leals:" in response to NRC 800906 ltr requesting eddl info equired by fire protection safety evaluation 4AYER-L O. Northern States Power Co. 80/10/24 2pp.
- -8010310371 "Fire Qualification Test on Retrofit Penetration Seals." PISH.M D SRI International 80/06/30 116pp
- 8010310456 Forwards Revision 6 to 780328 security plan, incorporating changes in organization; titles, qualifications & training Revision withheld (ref 10CFR2 790)
 MAYER, L O Northern States Power Co 80/10/28 ip.

Q Adjudicatory correspondence

- 10160624 Forwards revised 800829 order, correcting refs. Date for which hearing may be requested also revised.
 EISENHUT, D 0 Division of Licensing. 80/09/19 2pp
- 8010160630 Order directing licensee to respond fully & completely to IE Bulletin 79-018, re environ qualification of Class IE equipment.by 801101 EIGENHUT.D G. Division of Licensing 80/09/19 App
-)10280573 Order dismissing proceeding due to 800924 withdrawal of State of MN Pollution Control Agency 800409 petition to intervene.

 LAZO,R M Atomic Safety and Licensing Board Panel. 80/10/24 App.

Financial information

- D10280437 Forwards 1979 actual cash flow & 1980 projected cash flow, per requirements of Reg Ouide 9 4.4/d Annual Financial Rept 1979
 CARLECN, L. R. Northern States Power Go 80/10/20, 2pp.
- P Operating license stage documents & correspondence
- 8010220099 Forwards strata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EIBENHUT, D. Q Division of Licensing, 80/09/19, 28pp.
- 8010280711 Forwards Task Order 5 requested under NRC 05-80-251 for metallurgical analysis of tracking problem in steam generator support bolting at facility. Determination of cause is sesential for assessment of generic implications.

 JORDAN, E. L. Division of Reactor Construction Inspection. 80/07/24.

- 8010040303 Responds to NRC 800815 request for review of Tech Specs & procedures for possible revisions to assure that exposure of irradiated fuel assemblies & control rods cannot occur during transfer Tech Spec change will be requested MAYER.L O Northern States Power Co 80/09/30 1p
- 8010280588 Forwards request for info re containment sump design & effect on long-term cooling following LOCA.
 CLARK.R A Operating Reactors Branch 3 80/10/02 2pp
- 8010140333 Forwards corrected Page 2 to proposed Tech Specs of 800316 license amend request. MAYERL O Northern States Power Co 80/10/08 ip
- --8010140334 Corrected Page 2 to Tech Specs 3 12
 * Northern States Power Co 80/10/08, 1p.
- O Inspection reports, IE Bullstins & correspondence
- B010230140 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badges for unescorted access in protected areas KEPPLER.J O Region 3. Chicago, Office of the Director. B0/09/03 4sp.
- 8010060117 Bubmits response to IE Bulletin 80-20 re Westinghouse Type H-2 control switches. About 42 of subj switches are used in safety-related sys. Switches are tested monthly & after each use OILBERTG, D. E. Northern States Power Co. 80/09/12 ip
- 8010080551 Responds to IE Bulletin 79-14. "Geiamic Analysis for As-Built Safety-Related Piping Sys " Discusses physical & analytical insp procedures Analytical insp completion schedule, & discrepancy & resolution list encl OILBERTS, DE Northern States Power Co. 80/09/19 Spp.
- 8010100378 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/80-08 & 50-306/80-09 KEPPLER, J O Region 3, Chicago, Office of the Director. 80/09/23.
- --B0101003B1 Responds to NRC 800812 ltr re violations noted in IE Insp Repts 50-282/80-08 & 50-306/80-09 Corrective actions: radiation protection staff will be increased & visual dose rate indicators will replace chirpers. OILBERTS.D.E Northern States Power Co. 80/08/29. 3pp.
- 8010270466 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested.

 KEPPLER, J. G. Region G. Chicago, Office of the Director. 80/09/23, is
- 8010270140 Forwards IE Insp Repts 50-282/80-12 & 50-306/80-12 on 800703 & 0908-07. No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8010290144 IE Insp Repts 50-282/80-12 & 50-306/80-12 on 800723 & 0908-09. No noncompliance noted Hajor areas inspected: QA/QC program implementing procedures, work activities & nondestructive examination data of inservice insp. HARD.K.D. Region G. Chicago. Office of the Director. DANIELSON, D H. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/23. 7pp.
- 801016024B Forwards Suppl 2 to IE Bullstin 79-01B, "Environ Qualification of Class IE Equipment," No written response required. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/09/30. lp.
- 8010280643 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 80/10/02.

 1p.
- 8010220124 Responds to IE Bulletin 80-15. Emergency notification sys has been connected to safeguard power source w/backup power from battery.

 GILSERTS, D. E. Northern States Power Co. 80/10/03 2pp.
- S010270035 Forwards IE Info Notice 80-36, "Failure of Bteam Generator Bupport Bolting." No specific action or response requested. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 80/10/10.

- R Periodic operating reports & related correspondence
- 8010(50497 Forwards monthly operating repts for Bept 1980 MAYER, L. D. Northern States Power Co. 80/10/10 pp.
- --B0(0150502 Monthly operating repts for Sept 1780 HUNSTAD.A A Northern States Power Co 80/10/01 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8008060269 PNO-III-80-122 on 800630, util notified NRC that press release will be issued re slight primary-to-secondary leakage in steam generator Depration will continue as long as leakage remains within Tech Spec limit BUROESS.B., STRASMA.J. Region 3, Chicago, Défice of the Director, 80/06/30. 1p
- BOGS060274 PNO-III-80-123 on 800701, util notified NRC that primary-tosecondary leakage reported on 800627 increased, Licensee elected to shut unit down for steam generator exam & repair BURGE68, B. L., C. BOYD, D. C. Region 3, Chicago, Office of the Director, 80/07/01 ip.
- 8010070302 PNO-III-80-170: on 80070A, efforts to remove bolts from steam generator upper supports resulted in breaking two bolts.
 Ultrasonic examination of all of bolts identified addl defects. Cause could be stress corrosion cracking, FETERABEND, G., LITTLE, W., HEISHMAN, R.F. Region 3, Chicago, Office of the Director. 80/07/05 ip.
- 8010090274 PNO-III-80-170A:on 800908.ultrasonic test of Unit 2 bolts attaching column supports to staam generators resulted in 3 of 48 bolts w/defects Licensee has at least 5 of 6 good bolts per column & plans to start up Unit 2. FEIERABEND.C.E., LITTLE.W.8, HEISHMAN.R.F. Region G. Chicago, Office of the Director 80/09/08 ip
- 8010150450 Forwards updated LERs 80-010/03L-1.80-021/03L-1 & 80-024/03L-1 MAYER:L D Northern States Power Co. 80/10/08 ip.
- --8010150471 Updated LER 80-010/03L-1 on 800311, containment vacuum breaker isolation valve 11 opened at 0.57 psi rather than 0.5 psi Caused by drift in differential pressure switch. Betpoint adjusted & satisfactorily tested.
 HUNSTAD.A A Northern States Power Co. 80/10/08. 1p
- --B0101504B2 Updated LER 80-021/03L-1; on 800718, replacement of inverter i3 was stopped due to lack of seismic analysis for inverter mount Caused by personnel error. Improvement in design changs process initiated.

 HUNSTAD. A. A. Northern States Power Co. 80/10/08. ip.
- --8010180491 Updated LER 80-024/03L-0 on 800829, failed to perform intervice interpof safety injection notife to shell weld of both reactor vessels, Gaused by unavailability of test equipment Tech Bpec & ABME code revisions requested, KRUMPQB, P. J. Northern States Fawer Co. 80/10/08, 1p.
- 9010200450 Updated LER 80-10/03L dtd 801008, has been cancelled. MAYER, L. D Northern States Power Co. 80/10/13, ip.
- B010210552 Requests that 801008 update rept for LER 80-10 be disreparded Corrections made in 800417 update rept, MAYER.L.O Northern States Power Co. 80/10/13, 1p.
- BO10270364 Notifies that corrections for LER 80-10 should not have been included in 801008 ltr. Necessary corrections made in 800417 rept MAYER.L U Northern States Power Co. 80/10/13 1p.
- DOCKET 30-284 IDAHO STATE UNIV. RESEARCH REACTOR
 G. Inspection reports. IE Sulletins & correspondence
- 8010090225 Forwards IE Insp Rept 50-284/80-02 & notice of violation. MADSEN.O.L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/08/22, 2pp.
- ~~8010090228 Notice of violation from insp on 800724-25, m Region 4, Dallas, Office of the Director. 80/Q8/15. 1p.
- --8010070233 IE Insp Rept 50-284/80-02 on 800724-25 Noncompliance noted; failure to prepare written safety evaluation of facility design change.

 DEAN.S. 9 AGLIARDO, J. E., MADSEN.G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/08/15. 7pp.

- 8010030186 Ack receipt of 800909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-284/80-02. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 80/09/23, ip.
- ~-8010030194 Responds to NRC 800822 ltr re violations noted in IE Insp Rept 50-284/80-02 Corrective action formal safety evaluation re replacement of reactor shield tank low level scram switch will be written by 801031 WILSON, A E. Idaho State Univ 80/09/09 2pp
- DOCKET 80-285 FORT CALHOUN STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8010060270 Forwards revisions & sddl info re guard training & qualification plan. Revisions & info withheld (ref. 10CPR2. 790).

 **JDNES. M. C. | Gmaha Public Power District. | 80/09/23. 1p.
- 8010140337 Forwards evacuation time estimates, per 800131 commitment responding to Commission 791127 request JONES, W. C. Omeha Public Power District. 80/10/02, 16pp.
- B01024020B Forwards revised Chapter 4 of App 7 to security plan Revision withheld (ref 10CFR2.770). JONES, W. C. Gmaha Public Power District. B0/10/16. 1p.
- O. Adjudicatory correspondence
- 8010060003 Forwards order revising 800829 order for mod of OL, in entirety EISENHUT, D. O. Division of Licensing, 80/09/19, 2pp.
- --8010060004 Order revising 800829 order for mod of OL DPR-40 published in 800911 FR.in entirety. Response to IE Bulletin 79-018 must be filed by 801101, Request for hearing will not away affectiveness of order.

 EISENHUT. D O. Division of Licensing. 80/09/19. 6pp.
- J. Insurance & indemnity information
- GO10280559 Forwards Endorsements 41 & 47 to MAELU Policy HF-63 & NELIA Policy NF-207.respectively. PETERSEN, H E. Omeha Public Power District. 60/10/22 3pp.
- P. Operating license stage documents & correspondence
- 8010010141 Requests clarification within 45 days of responses to questions forwarded in NRC 800107 ltr re GA requirements concerning dissel generator fuel oil Response does not indicate diesel fuel oil program is part of GA program. CLARK, R. A. Operating Reactors Branch 3. 80/09/17. 2pp.
- 8010010147 Finds no further action warranted based on info provided in response to NRC 780713 ltr re facility control element assembly position indicating sys. Generic Issue B-15 re in-core poison rod growth is resolved for facility. CLARK.R.A. Operating Reactors Branch 3, 80/09/19, 2pp.
- BD10010482 Notifies that Generic lesue B-G7 is resolved for facility based on review of steam generator tube leaks & failures; eddy current testing & Tech Spec consistency w/BTS re steam generator tube insps.

 CLARK, R. A. Operating Reactors Branch G. 80/09/19. 2pp.
- 8010060344 Forwards XN-NF-807. Revision i, "Exxon Nuclear Co Setpoint Mathodology for C-E Reactors," in response to NRC request to resolve questions discussed at 800415 & 16 meeting re Exxon Nuclear Co setpoint methodology,

 JONES, H. G. Omaha Public Power District, 80/09/19, ip.
- ---8010060350 Revision 1 to *Exxon Nuclear Co Setpoint Methodology for G-E Reactors."
 NIELSEN.L.A., KRYSINSKI,T.L., STOUT,R.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-307 Ri. 80/07/18, 72pp.
- 8010220099 Forwards strata sheets amending 800908 ltr which provided praliminary clarification of TMI action plen requirements. Corrected table of implementation schedule also encl. EISENHUT. D. O. Division of Licensing. 80/09/19. 28pp.
- 8010090394 Forwards status rept re implementation of NUREO-0578 Catagory B tasks & util position re addl requirements of TMI-2 task action plan per NUREO-0560. Requests deferral until Bept 1981 for related tasks requiring dutages. JCNEB. M. G. Gmaha Public Power District. 80/10/06. 22pp.

- 8010160545 Forwards application for amend to License DPR-40, changing Tech Specs Sections 2 0.3 0 % 5 0 to assure control, isolation & actuation equipment operability per TMI-2 Lessons Learned requirements Fee & Certificate of Svc encl s LeBoeuf, Lemb, Leiby & MacRae 80/10/14 3pp
- --8010160549 Application to amend License DPR-40.changing App A Tech Byers Sections 2 0.3 0 & 5 0 to assure control.isolation & actuation equipment operability per TMI-2 Lessons Learned requirements JONES.W.C Omaha Public Power District 80/10/10 4pp
- --8010160555 Proposed Tech Specs. Sections 2 0.3 0 & 5 0 to assure control isolation & actuation equipment operability per TMI-2 Lessons Learned requirements Safety considerations, discussion & justification encl

 Dmahe Public Power District 80/10/10 25pp
- 8010310321 Provides exceptions or qualifications to response to NRC 800929 request for info needed to assess impact of operation of MC River aquatic blots Info package forwarded to consultants, Environ Science & Engineering as requested JONES, R A Omaha Public Power District 80/10/27 2pp
- G. Inspection reports. IE Bulletins & correspondence
- 8010210791 Responds to IE Bulistin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Min flow bypass line remains open during safety injection JONES, W C. Omaha Public Power District 80/08/05 1p.
- 8010210748 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type N-2 Spring Return to Neutral Control Switches " Control switches are not in use at facility JONES N C Dmaha Public Power District 80/08/08, ip
- 010010175 Forwards IE Insg Rept 50-285/80-11 on 600630-0729. No noncompliance noted MADSEN, OL Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/15, 2pp
- --8010010180 IE Insp Rept 50-285/80-11 on 800630-0729. No noncompliance noted Major areas inspected operational safety verification, post-refueling tests & annual energency drills KELLEY, D.L., HUNNICUTT, D.M. Region 4. Dallas. Office of the Director 80/08/13 4pp.
- 8010010064 Forwards IE Insp Rept 50-285/80-12 on 800728-31.No noncompilance notes MADSEN, G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/19 2pp
 - i010010072 IE Insp Rept 50-285/80-12 on 800728-31 No noncompliance noted Major areas inspected organizational attracture, qualifications of personnel in key mgt positions & calibr program for safety-related instrument sys YANDELL.L.A., JAUDON, J.P. Region 4, Dallas, Office of the Director CAQLIARDO, J.E. Region 4, Dallas, Reactor Gperations Nuclear Support Branch, 80/08/18 Spp.
 - *O240106 Forwards response to IE Bulletin 80~15, "Possible Loss of mergency Notification Sys (ENS) w/Loss of Offsite Power " tation package located & powered at local telephone oppony DNES, M C Omaha Public Power District, 80/08/25, 3pp.
- 10230085 Responds to 800724 request by submitting documentation re OC for work performed in response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." Util employed consultants for bulletin response J
- 3010200615 Forwards IE Info Notice 80-32, "Ctarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matis " SNIEZEK, J. H. Division of Fuel Facility & Materials Safety. 80/08/29, ip.
- 8010060111 Forwards IE Insp Rept 50-285/80-13 on 800729-30. No noncompliance noted a montempliance noted a montempliance noted a monte noted a

- --8010060113 IE Insp Rept 50-285/80-13 on 800729-30 No noncompliants noted Major areas inspected emergency tests & drills & followup on previous item of noncompliance BAIRD, J B Region 4, Dallas, Office of the Director BRDHR, Q D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/09/02 Spp
- 8010300028 Forwards IE Circular 80-21, "Regulation of Refueling Craws * No written response required.
 SEYFRIT, K V Region 4, Dallas, Office of the Director 10/09/10
- 801027042D Forwards IE Info Notice 80-34, "Doron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested,
 BEYFRIT,K V. Region 4, Dallas, Office of the Director, 80/09/26
- 8010160097 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment " No written response required SEVFRIT.K V. Region 4, Dallas, Office of the Director 80/09/30 lp
- 8010300492 Forwards Jan 1980 inservice insp rept JONES.W C Omaha Public Power District 80/10/16. 1p
- ---8010300508 Inservice insp rept on 800118-0611 Describes examinations performed on selected Class 1 & 2 components during Jan-Feb 1980 refueling outage
 KEYEB, D C , JONEB, W. C Dmaha Public Power District 80/10/03 330s
- R Periodic operating reports & related correspondence
- 8010200400 Forwards monthly operating rept for Sept 1980 JUNES, W.C. Umaha Public Power District. 80/10/10 1p
- --8010200402 Monthly operating rept for Sept 1980
 PATTERSON, T L. Comman Public Power District 80/10/10 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010030415 Forwards LER 80-020/03L-0 STEVENS.B C. Omeha Public Power District 80/09/17 1p
- --8010030418 LER 80-020/03L-0; on 800905, exial power distribution setpoints on D channel discovered out of tolerance in nonconservative direction Caused by dependent setpoint selection switch failure Switch cleaned & returned to svc. CORE, M Dmaha Public Power District 80/09/08 4pp.
- 8D10070504 Forwards LER 80-022/03L-0.
 BTEVENS,8 C Omaha Public Power District 80/09/17 ip
- --8010070511 LER 80-022/03L-0 on 800911, during safety injection ectuation signal surveillance test.868/VIA8 lockout failed to trip Gaused by burned coil Coil replaced w/spare & tested satisfactorily for proper operation.

 MUELLER, R Dmaha Public Power District 80/09/11 4pp
- 8010140480 Forwards LER 80-019/03L-0 BTEVENS,8 C. Omaha Public Power District. 80/10/03 ip.
- --8010140485 LER 80-019/03L-0:on 800904, seismic pipe restraints 818-624 '
 818-7 were inadvertently made inoperable at same time
 Restraints were being uppraded in response to IE Bulletin
 79-14 Restraint 818-7 was immediately made operable.
 DESPAIN.D. Omeha Public Power District. 80/10/03 4pp
- 8010140443 Forwards LER 90-023/03L-0. STEVENS,S C Omaha Public Power District. 80/10/07 ip.
- --8010140447 LER 80-023/03L-0 on 800908, during routine operations, pewer to lockout relay coil 86A1/CPHB was interrupted Caused by electrically opened contacts Contacts cleaned & burnished MUELLER, R. Omaha Public Power District. 80/09/26 4pp.
- 8010290374 Forwards LER 80-024/03L-0. STEVENS,8 C Omaha Public Power District, 80/10/23. 1p
- --8010270376 LER 80-024/03L-0: on 800726; while completing repairs on 8 charging pump. A charging pump became inoperable. Caused by packing cooling pump failure. Motor replaced OATES, W.O. Omaha Public Power District BO/10/21 4pp

- DOCKET 50-284 INDIAN POINT STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8010020558 Forwards addl info in response to questions re fire protection program review Dampers listed are presently under review to determine potential impact on safe operation Oversize drawings available in Central Files.

 BAYNE, J. P. Power Authority of the State of New York 80/09/26
 Bap
- 8010100315 Informs that 801003 request for extension of data for responses re facility security force training & qualification plan approved Request due to Safeguards Contingency Plan being approved & mended to OL.
 BAYNE, J P Power Authority of the State of New York 80/10/03 ip
- B010200456 Confirms B01002 telcon re NAC 770521 ltr on fire protection program Separation between redundant instrumentation cable trays inside containment not required Access to containment during operations severely limited ruling out fire hazards BAYNE, J. P Power Authority of the State of New York. S0/10/10 2pp
- 8010220342 Informs of transfer of contract security force personnel from Pinkerton Protective Svos. Inc to util Changes to security & safeguards contingency plans to reflect security organization will be provided under separate cover BAYNE, J. P. Power Authority of the State of New York. 80/10/14

O. Adjudicatory correspondence

- 8010210510 Order denying NY State Energy Ofc & Citizens Committee for Protection of Environ petitions to review ALAB-436 & ALAB-561 re seismic issues. Notion to strike portions of NRC answer to petitions denied.
 CHILK.B J. Office of the Secretary of the Commission. 80/10/17
 2pp
- H. General correspondence
- BOI0280376 Requests tha JP Beyne, OM Wilverding, 88 Zulla, JW Blake & CM Pratt be added to all correspondence distribution lists for facility
 WILVERDING, O. M Power Authority of the State of New York, 80/10/23
 200.
- J. Insurance & Indemnity information
- B010280695 Requests Endorsements 32 & 33 to Policy MP-77 & Endorsements 38.39 & 40 to Policy NF-208. DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- P. Operating license stage documents & correspondence
- 9010010141 Ack response to NRC 791109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture.
 Response acceptable & no further action necessary.
 VAROA:S A. Operating Reactors Branch 1 80/09/12. 2pp
- 3010140001 Summary of 800910 meeting w/util re sys interaction study. OLSHAN,L Operating Reactors Branch 1, 80/09/17 2pp
- 3010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D O Division of Licensing. 80/09/19. 28pp
- 3010080448 Advises of potential problem w/motor operated valves 1870 & 743 Util is required to amend Tech Spec Section 3.3.A.3 or demonstrate that spurious closing of either valve would not damage RHR pumps VAROA:6 A Operating Reactors Branch 1. 80/09/22. 2pp.
- 9010090256 Forwards request for add1 info re GA program re-evaluation.

 Items addressed include extension of GA program to all items affecting sefety-organizational independence & staffing & qualification requirements VAROA: S A Operating Reactors Branch 1. 80/09/23. 8pp.
- O:010100036 Forwards request for add1 info re util 800529 & 0623 responses re GA program. Add1 info requested within 30 days. VARGA: 8.A. Operating Reactors Branch 1. 80/09/23. 10pp.

- B010030417 Advises that util has completed review of Tech Specs & procedures re exposure of fuel assemblies & control rods, in response to NRC 800813 ltm Proposed Tech Spec changes will be submitted by 810101

 BAYNE, J P Power Authority of the State of New York 80/07/26 1p
- 8010070307 Forwards application for amend to License DPR-64, changing Tech Spacs to reflect Westinghouse BTS & adding definition of "operation in degraded mode " Application does not require licensing fee BAYNE, J P Power Authority of the State of New York 80/09/29 200
- --B010070309 Application to amend License DPR-64, changing Tech Specs to reflect Westinghouse BTS & adding definition of "operation in degraded mode." Discussion of Tech Specs deficiencies encl
 BAYNE, J.P. Power Authority of the State of New York B0/09/29
- --B010070311 Proposed Tech Specs reflecting Hestinghouse STS & adding definition of "operation in degraded mode" Bafety evaluation encl ** Power Authority of the State of New York 80/09/26 31pp
- 8010070286 Submits amend to facility procedures to permit storage of GA records in accordance w/terms of Reg Guide 1 88. Revision 2 Procedure replaces requirements of ANBI N45 2 9. Draft 15 ZULLA, B. B Power Authority of the State of New York 80/10/01.
- 8010100300 Forwards add1 info per 800602 commitment, in response to NRC 800411 ltr. Availability of power to engineered safety features instrumentation is continuously monitored Sensing circuits go from energized to de-energized state for action. BAYNE. J P Power Authority of the State of New York. 80/10/03 3pp
- 8010160485 Submits summary of 800925 meeting w/NRC.Comm Ed.PAENY & Hestinghouse in Chicago, IL re schedule for Zion/Indian Point near-site study per SA Varga request. Requests NRC concurrence of suggested date for addl meeting in Dec 1980 NAVQHTON, H. F. Commonwealth Edison Co. 80/10/06 5pp
- 8010150286 Responds to NRC 800827 ltr re inservice insp & inservice test programs Three items addressed.per 801002 teleon. BAYNE, J. P. Power Authority of the State of New York 80/10/09 286.
- 8010270037 Responds to FDIA request for three categories of info re fees for withdrawn CP & QL applications. Forwards App A documents. BECY-364A & JF Ahearns response sheet withheld (ref FDIA Exemptions 3) FELTON.J M Division of Rules and Records 80/10/15 2pp
- --8010270151 Notifies of completed assessment re review of costs for CP & OL actions, Data sheets used to determine fee charges encl.

 BERKON, H. N. Office of Nuclear Reactor Regulation, Director, 79/10/30. 4pp
- 8010280383 Forwards "Electrical Override/Bypass Aspects of Engineered Safety Features," in response to NRC 800929 ltm Oversize Drawing 9321-LL-31273, Sheet 7 encl.
 BAYNE, J P Power Authority of the Btate of New York 80/10/23 1700
- Q Inspection reports, IE Bulletins & correspondence
- 8010020224 Forwards IE Insp Rept 50-286/80-10 on 800708-11 No noncompliance noted. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/30, 2pp.
- --B010020231 IE Insp Rept 50-286/80-10 on B0070B-11 No noncompliance noted Major areas inspected, LOGA procedures & training of licensed operators HIQQINS, J. C. Region 1, Philadelphia, Offics of the Director, KIBTER: H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/28 7pp.
- 6010010345 Forwards IE Insp Rept 50-286/80-05 on 800315-0426 No noncompliance noted. BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/13 2pp

- --8010010352 IE Imap Rept 50-286/80-05 on 800315-0426 No noncompliance noted Major areas inspected, physical ascurity, monthly & periodic repts, spurious safety injection & action on previous inspections acted on previous inspection in Philadelphia, Reactor Operations Nuclear Support Branch REBELDUSKI, T. Region i, Philadelphia, Office of the Director 80/08/11 14pp
- 8010210299 Forwards IE Insp Rept 50-286/80-07 on 800426-0607 No noncompliance noted. BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Granch 80/08/20 2pp
- --8010210302 IE Insp Rept 50-286/80-07 on 800426-0607. No noncompliance noted Major areas inspected personnel changes physical security & turbine rotor disc REBELONEKI, T. KENNY, T. Region 1. Philadelphia. Office of the Director KIBTER, H. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/08/18, 14pp
- 8010020790 Forwards IE Insp Rept 50-286/80-09 on 800624-26, notice of violation & notice of proposed imposition of civil penalties STELLO, V Region 1, Philadelphia, Office of the Director. 80/08/22
- --B010020797 Natice of proposed imposition of civil penalty in amount of \$12,000 for item of noncompliance noted in IE insp on 800524-26.
 4 Office of Inspection & Enforcement, Office of the Director 60/08/22 ip
 - O240559 Forwards IE Insp Rept 50-286/80-09 on 800624-26 No oncompliance noted RIER.B # Region 1. Philadelphia. Offics of the Director. O/08/25 2pg.
 - 3010240565 IE Insp Rept 50-286/80-09 on 800624-26. Noncompliance noted failure to maintain radiation exposures w/10CFR20 101 limits, failure to provide personnel monitoring & failure to establish procedures for incore flux detector repair NIMITS, L. Region i. Philadelphia, Office of the Director KNAPP, P. J. Region i. Philadelphia, Fuel Facility & Materials Bafety Branch. 80/07/22 17pp
- 8010010673 Responds to IE Bulletin 80-15. Emergency notification sysbackup power supply was tested & procedures implemented to satisfy requirements of bulletin ZULLA,8 8 Power Authority of the State of New York 80/08/29
- 010020752 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-286/80-06.
 MARTIN.W C. Region 1, Philadelphia, Bafeguards Branch 80/09/10 to
- -8010020757 Responds to NRC 800815 ltr rs violation nated in IE Insg Rept 30-286/80-06. Corrective actions: withheld (ref 10CRR2 790) IVILLA: 8 8. Power Authority of the State of New York 80/08/15
 - 010020759 Forwards IE Insp Rept 50-286/80-06 on 800715-20 Details withheld (ref 100FR2 70)
 MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch, 80/07/21
 2pp
- 8010020762 IE Insp Rept 50-286/80-06 on 800715-20 Noncompliance noted: Inadequate protected area barriers, inadequate vital area lock sys component 5 detection aid intrusion sys component failure Details withheld (ref 10CFR2,790)

 DEVLIN, J H Region I, Philadelphia, 8afeguards Branch, MADDEN, H Region I, Philadelphia, Office of the Director 80/07/15, 1p.
- B010010221 Responds to IE Bullatin 80-20, Safety-related sys have Heatinghouse Type W-2 control switches No failures recorded to date Design mod to Install light in saries w/contact will be implemented. ZULLA/S 8. Power Authority of the State of New York. 60/09/12.
- 8010220300 Responds to NRC 800822 itr re violations noted in IE Insp Rept 50-286/80-09. Corrective actions: dept heads instructed in operation procedures & personnel sustaining overexposure assigned to nonradiation areas. BERRY, 0 T. Power Authority of the State of New York. 80/09/16.

- SO10270198 Responds to IE Bulletin 80-18, "Maint of Adequate Him Filts
 Thru Centrifugal Charging Pumps Following Secondary Side
 High Energy Line Rupture " Centrifugal charging pumps for
 high pressure safety injection have min flow bypass line
 ZULLA: S B Power Authority of the State of New York 80/09/19
- 8010270437 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested ORIER.B.H Region 1, Philadelphia, Office of the Director, 80/07/26. ip
- 8010240165 Forwards IE Circular 80-22, "Confirmation of Employee Ouglifications" No written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/10/02 ip.
- B010150286 Responds to NRC 800827 ltr re inservice insp & inservice test programs Three items addressed.per 801002 telcon BAYNE, J P Power Authority of the State of New York. 80/10/09 2pp
- 8010280231 Forwards IE Info Notice 80-36. "Failure of Steen Cenerator Support Bolting " No specific action or response requested ORIER, B. H Region 1. Philadelphia, Office of the Director 80/10/10 ip.
- R Periodic operating reports & related correspondence
- 8010150487 Forwards "Indian Point Generating station Entrainment & Nair Field River Studies." 1978 annual rept Affidavit of svc encl. ZARAMAB.P Consolidated Edison Co. of New York 80/10/09 3pp.
- ---8010180508 "Indian Paint Generating Station Entrainment & Near Field River Studies," 1978 annual rept * Ecological Analysts, Inc. CONB4H 80/05/31, 400pp
- 8010210412 Forwards monthly operating rept for Sept 1780, ZULLA.S S Power Authority of the State of New York. 80/10/10
- --8010210415 Monthly operating rept for Sept 1980. CONNELL,C Power Authority of the State of New York. 80/10/93
- 8010240425 Forwards tabulation of daily records of fish collections for Bapt 1980 Daily species code list count & total weight encl. ZARAKAS.P. Gommonwealth Edison Co 80/10/15 App
- S. Reportable occurrences, LERs & related correspondence
- B010080376 PNO-I-80-ii3 on 800731 unplanned release of gaseous radioactivity occurred due to leakage from charging pump Current info indicates that Tech Bpec limits were not exceeded.
 WHITE.U., BMITH, 0 , KEIMIO.R Region 1, Philadelphia, Office of the Director 80/07/31 2pp.
- DOCKET 50-297 OCCINEE NUCLEAR STATION, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8010010408 Forwards Revision 3 of safeguards contingency plan. Plan withheld (ref 10CFR2, 790)
 PARKER, W D Duke Power Co 80/09/25 ip.
- O. Adjudicatory correspondence
- 8010270321 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment.
 EISENHUT, D. O Division of Licensing 80/09/19 2pp.
- --8010270334 Revised order for mod of license requiring timely substitle of info previously requested re environ qualification of safety-related electrical equipment.
 EISENHUT.D 0. Division of Licensing. 80/09/19. App.
- 8010140587 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in McGuire spent fuel pool, reported in encl Power Reactor Events, Certificate of Svc encl.

 RILEY.J.L. Carolina Environmental Study Oroup, 80/10/06. 12pp

- 8010240552 Response in opposition to Carolina Environ Study Group 801006 mation to reopen record to include Jul 1980 "Unplanned Doron Dilution," rept into evidence No new info PORTER, W. L., MCGARRY, J. M. Duke Power Co. MCGARRY, J. M. Dabevoise &
- --8010240562 Affidavit addressing activities associated w/demineralizer operation & effect of boron decreased concentration. Certificate of Svc encl ORTH.N C. Duke Power Co 80/10/21 Spp
- B010310306 Ack receipt of B01006 FR notice & requests hearing to protect interests
 PORTER.H L Duke Power Co 80/10/27 ip
- P Operating license stage documents & correspondence
- 9010070195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 i 3 b. "Instrumentation for Detection of Inadequate Core Cooling " Ouidelines re vessel water level must be developed to provide operators wimax support ROS9.DF Division of Systems Integration 80/09/09 3pp.
- 8010020050 Forwards FR notice of proposed issuance of amends to facility CLs.per util 800728 application.changing Tech Bpecs to permit expansion of spent fuel storage capacity REID.R.W Operating Reactors Branch 4 80/09/15 2pp
- --B010020064 Notice of proposed issuance of amends to Licenses DPR-38, DPR-47 & DPR-35 REID,R.H. Operating Reactors Branch 4 80/09/15, 4pp
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISEMHUT.D Q Division of Licensing 80/09/19 28pp
- 8010230411 Forwards evaluation of 800826 response to Lessons Learned Task Force Requirement 2 1.3 b re instrumentation for detection of imadequate core cooling Insufficient effort provided re advance warning of inadequate core cooling EISENHUT.D G Division of Licensing 80/09/24 7pp.
- 8010070405 Informs that 801030 is expected date of completion for preparation & review of revised "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys PARKER, W D. Duke Power Co 80/09/30 1p
- 8010150530 Bummary of 800904 meeting w/utils:B&W & NUB Corp re proposed upgrade mods to auxiliary feedwater sys Agenda & 800808 memo encl
- VIESING.O S Operating Reactors Branch 4 80/09/30 48pp
- --B010150544 Bubmits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys Beismically induced core melt due to loss of decay heat removal could be as much as six times more likely than MABH-1400 estimates

 MATTRON,R J Division of Safety Technology 80/08/08 22pp.
- B010230589 Bummary of B00821 meeting w/B&N reactor owners group re abnormal transfent operating guidelines program. VISBING: C Operating Reactors Branch 4 B0/09/30 29pp
- 8010070422 Application for amend to Licenses DPR-38, DPR-47 & DPR-35, changing Tech Specs & license conditions per NUREG-0578, in response to NRC 800702 request Discussion of applicability of STS & Class I & III fees encl PARKER, N O Duke Power Co. 80/10/02 6pp
- --8010070428 Proposed revisions to App A Tach Specs.Sections 3,4 & 6, incorporating NVREO-0578, Category A requirements Proposed license conditions encl # Duke Power Co. 80/10/02 22pp
- 8010210040 Forwards Amends 87.87 & 84 to Licenses DPR-3B.DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability.

 REID.R W Operating Reactors Branch 4 80/10/07. 2pp.
- --8010210046 Amends 87,87 & 84 to Licenses DPR-38, DPR-47 & DPR-55, respectively, modifying reactor vessel pressure-temp operating limit curves to enable extension of operation from four to five effective full power yes REID.R W Operating Reactors Branch 4. 80/10/07, 10pp.

- --B010210050 Safety evaluation supporting Amends 87.87 & 84 to Licenses
 DPR-3B.DPR-47 & DPR-35.respectively
 * Office of Nuclear Reactor Regulation, Director 80/10/07, 2pp
- --8010210096 Notice of issuance & availability of Amends 87,87 & 84 to Licenses DPR-38,DPR-47 & DPR-55, respectively REID,R W Operating Reactors Branch 4, 80/10/07 2pp
- B010270255 Advises that 791130 response re inadvertent safety injection during surveillance testing adequately addresses concerns stated in NRC 790921 ltr
 REID.R W Operating Reactors Branch 4 80/10/10 2pp
- 8010170540 Application for amend of license revising Tech Specs 3 0 & 3 1 re operating status of RCS & limiting condition for operation PARKER, H O Duke Power Co BO/10/14 3pp
- --B010170544 Proposed Tech Specs 3 0 & 3.1 re operating status of RCS & limiting condition for operation

 4 Duke Power Co 60/10/14 2pp.
- 8010240412 Application for amend of Licenses DPR-38, DPR-47 & DPR-35, submitted as proposed Fech Spec 6,6 2 1,per 800529 request PARKER, N O Duke Power Co 80/10/20 2pp
- --8010240415 Tech Spec 6 6 2 1 re ROs. * Duke Power Go B0/10/20. 3pp
- B010310405 Application to amend OL, revising Tech Specs Sections 3.6 & 4 4 i re reactor bldg & containment leakage tests, respectively, to reflect code criteria Proposed change suppls 76130 submittal PARKER, 8 0 Dute Power Co 80/10/24, ip
- --B010310409 Proposed Tech Specs Sections 3 6 & 4 4 1 re reactor bldg & containment leakage tests, respectively, to reflect code criteria Test requirements bases & justification for reverse direction testing encl * Duke Power Co 80/10/24 24pp
- @ Inspection reports, IE Bulletins & correspondence
- 8008060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance moted, 8TOHR, J P Region 2. Atlants. Fuel Facility & Haterials Safety Branch 80/06/23 2pp
- --B00B060179 Waste Packaging Insp Rept 15000039/B0-07 on 800515 & 16 No noncompliance noted. Major areas inspected compliance w/NRC & DOT regulations Branch, 80/06/23 App.
- 8010230108 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive
 Matls. " No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/29.
- 8010090203 Forwards Revision 4 to util 90-day response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." Info is final & should replace all previous submittals, H/o encl PARKER: H O Duke Power Co 80/09/15 3pp
- 8010170204 Forwards 90-day response to IE Bulletin 79-018. "Environ Qualification of IE Equipment." Info included re master system components listings component evaluation & equipment required to maintain cold shutdown following LOCA. PARKER, W D Duke Power Co 80/09/15. 410pp
- 8010010080 Ack receipt of 800714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-269/80-20, 50-270/80-15 & 50-287/80-14
 LEWIS R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
- --8010010070 Responds to NRC 800623 ltr re violations noted in IE Insp Repts 50-267/80-20, 50-270/80-15 & 50-287/80-14 Corrective actions emergency procedure on boron dilution reviewed & reactivity balance procedure implemented, PARKER.W. 0 Duke Fower Co. 80/07/14, 3pp
- --8010010102 Forwards IE Insp Repts 50-269/80-20,50-270/80-15 & 50-287/80-14 on 800501-30 & notice of violation.
 LEMIB.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/23. 2pp.

- --8010010112 Notice of violation from insp on 800501-30

 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/20 2pp
- --B010010131 IE Insp Repts 50-269/80-20, S0-270/80-15 & 50-287/80-14 on B00501-30 Noncompliance noted: failure to maintain correct status of demineralizer & to provide data to determine shutdown margin JAPE.F. GRDERS, W.T. Region 2. Atlanta. Office of the Director. MARTIN.R D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/06/20 6pp
- 8010190275 Forwards affidavit as suppl to 800827 response to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " PARKER, H O Dute Power Co 80/09/16 ip
- B010150314 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys " DBE wat condition analysis parformed & mod of branch pipes & header junction initiated in lieu of complex nonlinear elastic-plastic analysis PARKER, W O Duke Power Co 80/09/18 2pp,
- BO1001053B Forwards Figure 54B-0-1477-RBB-HI, supplementing 800919 response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safaty-Related Piping Sys " Figure inedvertently omitted from original submittel PARKER, H O Duke Power Co 80/09/23 2pp
- 8010140041 Ack receipt of IE Insp Repts 50-249/80-30,50-270/80-26 & 50-287/80-23 on 800801-31 No proprietary info PARKER, U Duke Power Ca 80/09/24 ip
- --8010140046 Forwards IE Insp Repts 30-269/80-30, 30-270/80-26 & 50-287/80-23 on 800801-31 No noncompliance nated LEWISR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/09/17 2pp.
- --8010140051 IE Insp Repte 50-269/80-30,50-270/80-26 & 50-287/80-23 on 800801-31 No noncompliance noted Major areas inspected LERs, surveillance testing, instrument calibr, contaminated tendon gaileries & physical security ORDERS.W. HYERS.D. Region 2, Atlanta, Office of the Director MARTIN.R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/17, 9pp
- 8010270482 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/26
- 8010160286 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/09/30, is
- 8010270411 Forwards IE Circular 80-22. "Confirmation of Emplayer Qualifications " No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02
- 8010270052 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested D'REILLY. J P Region 2. Atlanta. Office of the Director 80/10/10.
- R Periodic operating reports & related correspondence
- 8010210434 Forwards monthly operating rapts for Sept 1980. PARKER, N D. Duke Power Co 80/10/15. ip
- -8010210437 Monthly operating repts for Sept 1980. REAVIS. J. A Dute Power Co. 80/10/15 16pp
- □. Reportable occurrences, LERs & related correspondence
- B010080435 PNO-II-80-i09 on B00614.reactor shutdown was commanced due to steam generator tube leak of 0.5 gallons/minute, On B00615.during shutdown.leak rate had increased to 8.4 gallons/minute, FALCONER.D.P.. MARTIN, R.D. Region 2, Atlanta, Office of the Director. 80/06/16.1p.

- 8010160748 PND-II-80-115 on 800620, two 55-gallon berreis containing approx 20 gallons each of contaminated wasts oil were inadvertently mixed w/2000 gallons of uncontaminated wasts oil wasts oil truck has been returned to plant for storage MARTIN.R Region 2. Atlanta, Office of the Director 80/06/25
- 8010170002 PNO-II-8D-116 on 800625, on Unit 3, cracks were identified three of sixteen study used to attach lower manual cover to steam generator Licenses has examined remaining study & found add I cracks
 MARTIN, R Region 2, Atlanta, Office of the Director 90/06/28
- 8010220035 Responds to 800715 memo re limiting conditions for operal for Class IE vital instrument buses Limiting conditions should be applied to reactors which do not address loss of Class IE 120 VAC vital instrument buses DENIDN.H M Office of Nuclear Reactor Regulation, Director 80/09/29 1p
- --8010220039 Advises that NRC review re Rencho Saco LER 80-028/017-01 RO 287/80-8 found lack of operational restrictions for Class IE vital instrument buses Requirements of limiting conditions for operation recommended MICHELSON, C Director's Office 80/07/15 1p
- 8010140324 Forwards LER 80-019/09L-0 PARKER, W D Duke Power Co 80/10/08 3pp.
- --9010140325 LER 80-013/03L-0 on 80070B, during annual insp of access hydraulic snubbers, one snubber found empty of oil Gause unknown. Reservoir of snubber found cracked Snubber removed, tested, repaired & reinstalled, Reservoir & oil ring replaced JONEB, J L Duke Power Co 80/10/08 1p
- DOCKET 50-289 THREE HILE ISLAND NUCLEAR STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans
- B010030007 Forwards Suppl 4 to fire protection markety evaluation in response to util 780113, 1101,770306, IB, 0827, 1228, 800319 & 0530 ltrs Suppl supports deletion of requirement to install curbs inside secondary shield of reactor bid NDVAK.T.M Assistant Director for Operating Reactors 80/09/19
- --8010030010 Safety evaluation. Suppl 4 re util 781013, 1101, 790306, 15, 0827, 1228, 800319 & 0330 submittals on open items & mods.

 * Assistant Director for Operating Reactors 80/09/19 16pp.
- --B010030011 STB re fire protection Westinghouse Electric Corp. 80/09/19. 15pp
- B010030402 Confirms D Mitchell telcon w/NRC re installed reactor coolant pump lubricating oil collection systo resolve outstanding fire protection issues.

 HUKILL, H D. Metropolitan Edison Co. 80/09/30 1p.
- 8010060339 Forwards security plan, Revision 7, Revision withheld (ref 10CFR2 790), ARNOLD, R C Metropolitan Edison Co 80/09/30 2pp.
- 8010210650 Forwards lists of accomplished actions in response to 800715 request re NRC essential personnel, Emergency access list for personnel will be revised & disseminated, Security advised of addition of NRC essential personnel W/o encl. ARNOLD.R.C. Metropolitan Edison Co. 80/10/14 2pp
- B010270383 Notice of 801027 informal meeting in Harrisburg, PA re state of NRC/FENA review of emergency preparedness & State of PA 801020 issues Cartificate of Svc ancl ZAHLER, RE Matropolitan Edison Go, ZAHLER, RE Bhaw, Pittman, Potts & Troubridge 80/10/24 4pp.
- Q. Adjudicatory correspondence
- 8010090543 Confirms 800806 telcon re need for space in Harrieburg,PA, Room reserved for use by ABLB for prehearing conference on 800812-13,
 PLEABANT,E.M Docketing & Services Branch 80/08/07. 1p.
- B010010467 Forwards Public Advances of NJ brief in support of rollad of util jevelized energy adjustment clause & Board of Public Utils position paper in response to NRC 770921 request for significant regulatory developments to 600 companies BMERNEY, L. E. Jersey Central Power & Light Co. B0/07/09. 1p.

- --8010010491 NJ Public Advocate brief in support of levelized energy adjustment clause rollback VAN NESB. B C. New Jersey, State of 80/09/08 41pp.
- 8010030493 Forwards "Fourth Info Request of Federal Executive Agencies" in response to NRC 790921 request for info re significant regulatory development affecting general public utils EHEENEY, L.E. Jersey Central Power & Light Co. 80/09/22 7pp
- 8010030099 Forwards 800925 order revising 800829 order for mod of OL, in entirety
 EIBEMHUT, D G. Division of Licensing 80/09/25 4pp
- --8010030107 Order revising 800727 order for mod of QL DPR-50 published in 800711 FR.in entirety Response to IE Bulletin 77-01D shall be submitted by 801101 Request for hearing will not stay effectiveness of order. UCB petitions discharged PURPLE.R A Division of Licensing 80/09/25 Opp
- 8010030442 Forwards two add1 exhibits for inclusion w/NRC copy of proposed Tariff 75 statements 1/2 exhibits filed w/PA Public Util Complesion on 800729

 BPRINGER E R. Pennsylvania Electric Co 80/09/25, 5pp
- 8010010710 Order denying UCS 800604 motion requesting reconsideration of Commission 800516 memorandum & order, CLT-80-16, repost accident hydrogen control issues. Separate visus of JF Ahearne & V Ollinsky encl CMILN:8 J Office of the Becretary of the Commission 80/09/26 788
- BD10140193 Notification of contract execution, "Furnishings for ASLB TML-1 Restart Hearing," awarded to Cole & Co MEDROW, L. A. Administrative Contracts Branch NRC-10-80-719 80/09/26 1p.
- --8010140197 Contract: "Furnishings for ASLB TMI-1 Restart Hearing." awarded to Cole & Co.
 BERMAN.L N Cole & Co. MATTIA: M J Administrative Contracts Branch. NRC-10-80-719 80/09/26 63pp
- 8010030111 Request for clarification of NRC 800905 ltr to licensees of operating plants, GL applicants & CP holders Fundamental questions raised re-compliance w/lessons learned requirements as condition to restart, H/Certificate of Svc WEI88, E.R. Union of Concerned Scientists WEI88, E.R. Sheldon, Harmon & Hsiss 80/09/30, 20pp.
- 8010030465 Memorandum & order relieving parties from requirements of ASLE 800617 order, in lieu of which parties shall agree upon hydrogen control contention. Licensee 800924 request for addl time for cross-examination plans granted BMITH, I. M. Atomic Safety and Licensing Board Panel 80/09/30 3pp
- 8010030477 Memorandum & order advising that only remaining nine util employees listed on Page 3.N 2.of ABLB 800924 memorandum & order will be cross-examined re alleged deferral of safety-related maint. Thi Alert trial brief due on 801003 SMITH. I.W. Atomic Bafety and Licensing Board Panel. 80/10/01. 2pp.
- ---8010030480 Requests issuance of subpoena duces tecum directed to D Qood for production of "Corrective Maint Component History Rept," cited by licensee in response to TMI Alert Interrogatory 5-6 ADLER, T. A. Widoff, Reager, Belkowitz & Adler. 80/09/24. ip
- BG10070011 Direct testimony re UCB Contention 9 Administrative procedures informing operator that safety sys has been deliberately disabled are inadequate a unreliable Profiqualifications anci, Related correspondence.
 POLLARD, R D. Union of Concerned Scientists 80/10/02, 16pp
- BO10070015 Direct testimony re UCB Contention 14 Explains significance of distinction between safety & nonsafety-grade sys & components. Prof qualifications & Certificate of Svc encl. Related correspondence POLLARD, R. D. Union of Concerned Scientists. 80/10/02. 15pp
- 8010070613 Outline of NRC testimony in response to UCS Contentions 6.7, 12 & 14.8holly Contention 13 & Environ Coelition on Nuclear Power Contentions 1(a),1(c),1(d) & remainder Certificate of Suc encl CUTGHIN.J.M. Hearing Branch 4. 80/10/02. 3pp.
- --8010070619 Testimany in response to UCB Contention 6 re reactor coolant pressure boundary compliance w/General Design Criteria 1.14.
 15 & GO. Operation prior to EPRI test completion will not endanger health & safety. Prof qualifications encl 2UDANS. J. J. Equipment Qualification Branch 80/10/02 10pp

- ---B010070624 Testimony in response to UCS Contention 9 Sypass & inoperable status indication sys is not needed per Reg Guide 1 47 criteria Prof qualifications encl BULLIVAN.D F Reactor Systems Standards Branch B0/10/02 App
- --8010070528 Testimony in response to UCS Contention 9. Bypass & inoperable status indication sys is not needed per Reg Ouids 1.47 criteria Prof qualifications encl HOGER.B A Assistant Director for Licensing, 80/10/02. 14pp
- --8010070432 Testimong in response to part of UCS Contention 12 Environ qualification of equipment will be determined by 810201 at which NRC will be able to take position on issue. Prof qualifications encl
 ROSZTOCZY, Z R Equipment Qualification Branch 80/10/02 App
- --8010070634 Tastimony in response to UCB Contention 14 Core cooling eys components need not be required to meet safety-grade design criteria Prof qualifications encl.
- CONRAN, J H Systems Interaction Branch 80/10/02 20pp
- --8010070636 Testimony in response to Sholly Contention 13 & Environ Coalition on Nuclear Power Contention is Computer sys not needed to make available info necessary to safely cope w/accident Prof qualifications encl
 JOYCE, J. P. Human Factors Engineering Branch, 80/10/02 8pp
- --8010070638 Testimony in response to Environ Goalition on Nuclear Power Contention (ic) Instrumentation control room receives feedwater transients or small break LODA signals based on measurements of parameters M/Prof qualifications
 SULLIVAN.D F. Reactor Bystems Standards Branch 80/10/02. 9pp
- --8010070637 Testimony in response to Environ Coalition on Nuclear Power Contention 1d Instruments that receive core cooling & containment isolation after small break LOCA are capable of onscale measurement during accidents W/prof qualifications.

 JENSEN. H. L. Reactor Systems Branch VOOLEMEDE, J C. Core Performance Branch SCOER, B A Assistant Director for Licensing 80/10/02 21pp
- --B010070645 Testimony in response to part of Environ Coalition on Nuclear Power contention 1(d) Means of monitoring radiation during accidents are capable of onscale radiation measurements Prof qualifications encl BTODDART,P G Effluent Treatment Systems Branch B0/10/02 App
- HO100B0422 Requests, on behalf of USC, transcript of facility restart proceedings
 WEIBSER Sheldon, Harmon & Weiss B0/10/02, 1p
- B010080240 Response in opposition to TMI Alert B00922 motion for surrebuttal testimony, Whather production of evidence should be made prior to along w/or following NRC & licensee testimony is not identified Certificate of 8vc encl.

 TROWNRIDGE, G.F. Metropolitan Edison Co. TROWNRIDGE, Q.F. Bhaw, Pittman, Potts & Trowbridge 80/10/03. 4pp
- 8010080281 Response in opposition to TMI Alert 800922 motion for appointment of expert to review work requests re maint practices. Intervenor failed to support claims despite ASLB order compelling replies to discovery. W/Certificate of Svc. TROWBRIDGE. 0 Metropolitan Edison Co. TROWBRIDGE. 0 Bhaw, Pittman. Potts & Trowbridge 80/10/03, App.
- 8010140012 Request for reconsideration of 791218 ruling rejecting Contention 17 calling for demonstration of resolution of all unresolved safety problems, based on ALAB-611 & ALAB-612. Cartificate of 8vc encl WEIS9,ER Union of Concerned Scientists WEIB9,ER. Sheldon, Harmon & Weiss. 80/10/03 6pp
- 8010140360 Notice of appearance in proceeding BELKCHITZ.L B. Three Mile Island Alert. SELKCWITZ,L B. Widoff, Reager, Belkowitz & Adier. 80/10/03. ip.
- --8010140565 Submits proposed sequence of witnesses to be examined by TMI Alert Related correspondence SELKONITZ-L.B Widoff, Reager, Salkowitz & Adler 80/10/03, 1p
- --B010140570 Forwards list of work requests that subposmed witnesses will be cross-examined upon Related correspondence.
 ADLER:T A Widoff, Reager, Selkowitz & Adler. B0/10/03. 2pp.
- --B0101405B3 Requests permission to withdraw subpoena issued to LL Kinther since Knoche can testify on subjitems 6ELKOWITZ.L B Widoff, Reager, Selkowitz & Adler 80/10/03. 1p.

- --B010140585 Testimony re use of computer summary to examine documents involved in evaluating work requests BDNETTI,D J Affiliation Unknown B0/10/03 3pp.
- 8010140612 Notice of correction of 800919 trial brief re D Good area of questioning Good will be questioned re corrective maint component history rept Certificate of Svc encl.

 ADLER.T A Widoff, Reager, Seltowitz & Adler 80/10/03 2pp
- B010070388 Response in support of licensee B00918 motion for dismissal of Aemodt Contention 5 & Environ Coalition on Nuclear Power Contentions 2-2 & 2-4 re emergency planning, Further spec of claims never provided, W/Certificate of Bvc ORAY, J R Hearing Branch 1. B0/10/06 App
- B010090057 Responds to UCS 800925 interrogatories re D0 Eisenhut 800905 ltr to licensees & applicants Ltr proposes, not imposes, changes in licensee requirements Full response will be prepared when position established, Certificate of Svc encl TOURTELLOTTE, J. Hearing Branch 4, 80/10/06. 4pp
- 8010090389 Forwards responses to NRC 790921 & 1109 data requests for info re regulatory developments in restart proceedings Responses to federal executive agencies info requests & exhibits filed in Oct 1980 encl SMEENEY, L E Jersey Cantral Power & Light Co. 80/10/06 21pp.
- 8010140491 Confirms 801003 telcon re exhibits & evidence.Licensse will provide requested work request summaries in discovery reading room on 801007 D Wise will testify on proposed budget cuts Related correspondence.

 BLAKE.E.L. Shew. Pittman, Potts & Trowbridge 80/10/06, 3pp.
- 8010140586 Positions on emergency planning contentions Civil defense warning sys must be upgraded Proceeding should test adequacy of federal planning & response capabilities Certificate of Syc encl.

 CARTER, K. H., ADLER, R. H. Pennsylvania, State of. 80/10/06 15pp.
- 8010150007 Response in opposition to UCS 800930 request for certification re schedule extension. UCS reading of Section III(2) of Commission 790809 order is legally incorrect & inconsistent Certificate of Evc encl.
 TROMBRIDGE, O.F. Metropolitan Edison Co. TROMBRIDGE, O.F. Shaw, Pittman, Potts & Trombridge 80/10/07, 7pp.
- 8010130035 Response in opposition to UCS 801003 motion to reconsider admissability of UCS Contention 17, rejected in ASLE 791218 order, Motion is inexcusably late, New info, providing bases for motion, not germane, Certificate of Evc encl.

 TROWBRIDGE, Q. F. Hetropolitan Edison Co TROWBRIDGE: Q. F. Shaw, Pittern, Potts & Trowbridge 80/10/07 7pp.
- B010160769 Response to NRC B00923 objections to Bholly Contention B researgency planning as revised B00908 Existence of 20-mile plans does not remove licenses obligation to evaluate plume exposure pathway zone Certificate of Bvc soil.

 BHOLLY.8. C Affiliation Unknown, B0/10/07. 7pp
- BO10140292 Forwards TMI work requests designated by TMI Alert as proposed sxhibits in BO1003 filing. Hatl forwarded in response to Memorandum & Order on TMI Alert Contention 5 of BO0924. Certificate of Boc & svc list encl.

 BLAME, E. L. Shaw, Pittman, Potts & Trowbridge, BO/10/09, 300pp.
- 3010150366 Patition of Public Utils of State of NJ to participate as interested govt agency in restart proceeding.

 DERMINE, T J New Jersey, State of, 80/10/09, 3pp.
- >10140527 Notice of withdrawal from proceeding SINGER, L. N. Hearing Branch 2. 80/10/10. 1p.
- H0150035 Response in opposition to TMI Alert 800922 motions for appointment of expert & for surrebuttal testimony Motion for independent expert rayiow should be denied per ALAB-123 (1973), Certificate of Syc encl. SHAWSON, D. T Hearing Branch 1. 80/10/10, 10pp.
- Dicisosti Response to ASLB BOO917 memorandum & order outlining schedule NRC intends to follow in preparing for remainder of proceeding JR Yourtellotte effidevit encl.

 TOWRTELLOTTE, J. Hearing Branch 4. BO/10/10, iipp.
- -- 8010150621 Affidavit re coordinating FEMA resources to answer intervenor contentions re offsite emergency plans & preparedness, Certificate of Svc enci.

 MCCONNELL, J. H. Federal Emergency Management Agency, 80/10/09, 4pp.

- 8010210767 Request for extension until 801030 to respund to emergency planning interrogatories, to licenses motion for sanctions & to NRC opposition to contentions. Reasons include unavailability of volunteer staff, UDHNSRUD, J H Environmental Coalition on Nuclear Power, 80/10/15 in
- 8010220526 Response in opposition to NRC & util replies re intervented revised emergency planning contentions Agrees to strike Contention 2 re licensee plan & Contention 12 re Dauphin County plan Certificate of Svc encl CUNNINOHAM.J D Newberry Township TMI Steering Committee CUNNINOHAM.J D Fex. Farr & Cunningham 80/10/16 App
- 8010230394 Forwards State of NJ 801002 decision & order denying util petition for rate increase, in response to NRC 790921 & 1109 requests for significant regulation developments in restart proceedings

 BHEENEY, L. E. J
- --8010230394 Board of Public Utils decision & order denying util paths for rate increase Util is ordered to continue w/current lavelized energy adjustment clause.

 BARBOUR, O. H., HYNES, E. H., CURRAN, B. A. New Jersey, State of 80/10/02 2pp.
- 8010220498 Memorandum & order scheduling 801030 emergency planning session re prehearing matters in restart proceeding BMITH.I.H. Atomic Safety and Licensing Board Panel. 80/10/17. 241
- S010270317 Add1 spec of Contention 5 re emergency planning for livestock evacuation Alloges that lives of farmors not adequately protested in area Certificate of Svc encl.

 AAMDDT.H M Affiliation Unknown S0/10/18 Opp.
- 8010220545 Memorandum for svc to parties forwarding 800912 telcon transcript w/D Basdekas re info on instrumentation control power.

 BMITH: I W. Atomic Safety and Licensing Board Panel B0/10/20 2/
- 8010240067 Formulation of unresolved emergency planning questions & consequences of subsequent resolution of issues. Submitted for immediate attention to facilitate preparation of testimony, Certificate of Svc encl Related correspondence CARTER, K.W., ADLER, R.W., Pennsylvania, State of 80/10/20 7pp
- 8010240977 Notice of appearance in proceeding. Certificate of Svc enti-CERMINE, T. J., DEGNAN, J. J. New Jersey, State of 80/10/20, 3pp
- 8010280013 Response in opposition to Environ Coalition on Nuclear Payer 801016 request for addition to respond to 800729 Interrogatories Renews 800918 motion to dismiss certain of intervenor contentions. Certificate of Syc ancl. ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge. 80/10/23 16pp.
- 8010270383 Notice of 801029 informal meeting in Harrisburg.PA re status of NRC/FEMA review of emergency preparedness & State of PA 801020 issues. Centificate of Evc encl. ZAHLER.R.E. Hatropolitan Edison Co ZAHLER.R.E. Shew. Pittman, Potts & Trowbridge. 80/10/24 4pp.
- 8010300051 Order granting participation as interested state agency to State of NJ Board of Public Utils SMITH, I. W Atomic Bafety and Licensing Board Panel 80/10/27 Sp
- 8010300687 Statement proposing schedule on emergency planning issues commencing w/hearing session on 801030 & ending w/testimony filing on 810216, Certificate of Svc encl IAHLER, R.E. Metropolitan Edison Co. ZAHLER, R.E. Bhaw, Pittan, Potts & Trowbridge. 80/10/27 12pp.
- H General correspondence
- S010140200 Responds to S00408 ltr to GSHA re proposal to monitor biola in THI vicinity Monitoring is being performed by private consulting firm & is adequate to detect damage to vegetation. NRC appreciates efforts & concerns.

 BALLARD, R. L. Environmental Engineering Branch 80/07/25. Ip
- BO09300413 Requests immediate startup of Unit 1. H/list of petitioners FOUCHE, R. E. Affiliation Unknown. 80/09/12, 1p.
- 8010020508 Recommends that util be directed to put Unit 2 back on line immediately & that cleanup of Unit 1 be accelerabed to enable operation within 1-yr. Govt red tape & scandal sheet techniques of news media should stop.

 KOHR, J. G. Affiliation Unknown 80/09/23 2pp.

- 8010200563 Forwards NRC 1979 Annual Rept in response to 800427 ltr to President Carter re atomic energy W/o encl SNYDER, B J. TMI Program Office 80/09/29 3pp
- 8010230094 Responds to 800626 ltr to President Carter expressing concern re venting of Kr-85 from TMI. Potential health impact on public from use of any proposed krypton removal strategy is negligible Relevant info forwarded Myo encl
 6NYDER. B J TMI Program Office 80/09/29 3pp
- 8010070457 Advises tht HD Hukill was appointed Director of TMI-i, replacing JO Herbein who has assumed position of Director of Nuclear Assurance Updated svc copy distribution list for TMI-i & 2.per 800410 ltr. enc!
 ARNOLD.R C Metropolitan Edison Co 80/09/30. 4pp
- 8010140120 Responds to 800904 ltr to President Carter re facility restart Status of activities remain unchanged per NRC 800922 response REID.R W Operating Reactors Branch 4 80/07/30 2pp
- 80102200B6 Responds to 800804 ltr to President Cartor & 800718 ltr re facility restart activities by forwarding NUREG-0680 which provides partial evaluation of licensee compilance w/items required for restart. REID.R W Operating Roactors Branch 4 80/09/30 1p
- --8010220367 Forwards H Obler B00804 ltr to President Carter for response EEAL.H M President of UB & Executive Offices. 80/08/07 2pp
- 8010180396 Urges expeditious facility restart to alleviate unnecessarily high electric bills.
 ME188,N., HE18EY.R., PATCHES.S. Affiliation Unknown. 80/10/06
- 8010230721 Responds to ltr expressing concern re delay in TMI-1 restart. Commission has created expeditious handling schedule of actions required for hearing process. Restart will occur in 1981 ENYOER, B J TMI Program Office 80/10/06 2pp
- --8010230722 Expresses concern re delay in TMI-1 restart. General Public Utils needs NRC assistance to restore financial integrity. LANBON, J D. Affiliation Unknown. 80/03/12 2pp.
- 8010270114 Responds to 800912 ltr to First Lady re delay in restarting TMI-1 Commission 800809 order identified items that must be resolved prior to restart Based on hearing process schedule, restart will not occur until sometime in 1981.

 ENYDER.B.J. TMI Program Office. 80/10/06. 3pp
- B0100B043: Expresses dismay re sudden NRC disclosure of 87 violations in plant sys. Questions timing of disclosure in view of restart proceedings.

 BACCR.C.O Affiliation Unknown B0/10/08. Gpp
- B010270050 Responds to B00323 ltr urging abandonment of facilities. Public hearing will be conducted re Unit 1 reopening. Util has not yet submitted proposal for overall recovery of Unit 2.4/a encl 770829 order 5 notice of hearing BNYDER, 8 J THI Program Office. B0/10/10. 2pp.
- --8010270094 Urges abandonment of facilities. Conventional power plant should be built.

 BERNSTEIN: M R Affiliation Unknown. 80/03/23 ip.
- 8010270059 Responds to 1tr opposing use of nuclear power & expressing concern re possibility of more accidents. Licensee has not ust submitted proposal for overall recovery of facility W/o enc! PA Dept of Health press release & 790809 order BNYDER, B. J THI Program Office. 89/10/10. 2pp.
- --8010270063 Expresses concern re possibility of another accident similar to TRI, Alternative energy sources should be utilized.
 ROCT.L D. Affiliation Unknown. 80/10/10, Rpp.
- B010280603 Responds to encl 800403 ltr to President Carter re future of facilities. Public hearing will be held re reopening of Unit 1 Util has not yet submitted proposal for overall recovery of Unit 2 M/o encl 770809 order SNYDER.B.J. TMI Program Office. 80/10/10. 3pp

- 8010280642 Responds to 800328 ltr opposing reopening of facilities. Public hearing will be held re reopening of Unit 1 Util has not yet submitted proposel for overall recovery of Unit 2 W/o encl documentation SNYDER: B J. TMI Program Office 80/10/10 2pp
- --8010280447 Opposes reopening of facilities & expresses concern re disposition of waste water CIANCIOSI.P Affiliation Unknown 80/03/28 2pp
- 8010220516 Urgss permanent shutdown of facilities. Util cannot safely operate nuclear power plant.
 CMESMAN.A Affiliation Unknown. 80/10/12 ip
- 8010280073 Responds to 800403 itr ra affects of radiation release Except for releases to Busquehanna River of liquids containing low or nondetectable levels of radioactivity, contaminated water release not permitted W/o encl. SNYDER, B, J TMI Program Office. 80/10/16 4pp
- ---8010280077 Deplores release of radioactivity into air.water & soil Requests development of alternative energy sources.
 BRINK.T. Affiliation Unknown. 80/04/05. ip.
- 8010280083 Responds to 800A27 telegram to President Carter re Kr-85 release, Purging method considered most effective alternative Public haaring re TMI-1 restart will be held. H/o enci NUREO-06A2 & 800A12 & 770B07 orders. ENYDER.8 J TMI Program Office. B0/10/16 4pp
- B010280030 Responds to 790731 ltr re effects of 790328 accident, Based on current info, no basis for Mat Ed license revocation Purging mathod considered most effective alternative. H/d encl NUREO-0662 & B00612 orders BNYDER, B J, TMI Program Office 80/10/20 3pp.
- --8010280033 Requests Met Ed license be revoked due to dumping of 4,000 gallons of Untested water into Susquehanne River. ROME, J Affiliation Unknown 79/07/31 2pp.
- I. Financial information
- 8010140499 Forwards responses to Items 11:13:14:15 & 18 of 800811 1tr re financial info Remaining items will be forwarded by 801013. HUKILL:H D Hetropolitan Edison Co. 80/10/09. 200pp.
- 8010220405 Responds to NRC 790921 % 1109 requests for update on significant regulatory developments affecting General Public Utils. Forwards info supporting various rate increase levels, executive summary & related util correspondence SHEENEY, L. S. Jersey Central Power & Light Co. 80/10/10. 25pp.
- J. Insurance & indemnity information
- 8010280307 Requests endorsements & copy of Amend 8 to Policy 8-64. DINITZ.I. Utility Finance Branch (formerly Antitrust & Indomnity). 80/09/24 1p.
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8010100097 Notice of postponement of ACRE Subcommittee 800805-06 meeting re facility restart. Meeting will be held in Oct 1980, CHILK, B. J. Office of the Sacretary of the Commission. 60/07/29.
- P Operating license stage documents & correspondence
- B0102302B0 Advises of review of 800129 memo transmitting proposed emergency pressure temp limits Limits are acceptable for 5 EFPY. NOONAN, V. 8 Engineering Branch. 80/02/11. ip.
- 8010090195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2.1 3.6. "Instrumentation for Detection of Inadequate Core Cooling." Guidelines re vessel water level must be developed to provide operators winax support. RDSB, D. F. Division of Bystems Integration. 80/09/09. Opp.
- 8010220229 Advises of review of response to 791109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture.Response acceptabls REID.R. H. Operating Reactors Branch 4. 80/09/09. 4pp.

- 8010030019 Forwards Amend 58 to License DPR-50, safety evaluation & notice of issuance & availability REID, R W Operating Reactors Branch 4 80/09/15 5pp
- --B010030022 Amend 58 to License DPR-50 revising Figure 6-1 of Tech Specs permitting establishment of General Public Utilities Nuclear Group & modifying plant staff organization REID.R H. Operating Reactors Branch 4 80/09/15, 8pp
- --8010030024 Safety evaluation supporting Amend 58 to License DPR-50
 * Operating Reactors Branch 4 80/09/15 3pp
- --B010030025 Notice of issuance & availability of Amend 58 to License DPR-50 REID:R W Operating Reactors Branch 4 80/09/15 2pp
- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D G. Division of Licensing 80/09/19 28pp
- 8010060092 Notification of 801008 & 09 sits visit for plant familiarization & preliminary review of design mod & separation of units BILVER.H Operating Reactors Branch 4 80/09/24 2pp.
- 8010230451 Forwards evaluation of B&W response to Lessons Learned Task Force Requirement 2 1 3.b re instrumentation for detection of inadequate core cooling. Insufficient effort provided re advance warning of inadequate core couling EISENHUT, D 0. Division of Licensing. 80/09/24 9pp.
 - :10020395 Requests status rept on enc1 revised list of outstanding Tech Spec change requests HUKILL. H D Metropolitan Edison Co 80/09/29, 2pp.
 - 40060208 Forwards App I suppl info re TLD map locations, onsite monitoring capabilities (TLD/ion chamber), drawings of TMI-1, restart rept Figure 7-1 & "Determination of Max Permissible Concentrations for Xe-133 & Xe-135 in Mater HUKILL, H. D. Metropolitan Edison Co BO/09/30 30pp
- 8010060211 Forwards Tech Bpec Change Request 95 constituting amend to App A of License DPR-50
 ARNOLD.R C Metropolitan Edison Co 80/09/30 ip.
- --8010060R14 Tech Baec Change Request 95 constituting amend to App A of License DPR-50 Cerfificate of Byc encl.
 ARNOLD,R.G Metropolitan Edison Co 80/09/30. 2pp.
- *B010060218 Proposed Change 95 to Tech Spece, Page 1-2 * Metropolitan Edison Co. 80/09/30. 2pp.
- 10060237 Forwards application for amend to App A Tech Specs of License DPR-90, consisting of Change Request 96, adding addlfire protection requirements ARNOLD, R. C. Metropolitan Edison Co. 80/09/30. 3pp
- -8010060244 Application for amend to App A Tech Specs of License DPR-50, consisting of Change Request 96,adding Tech Spec 3.18.7 for fire barrier panetration seals, ARMOLD R.C. Metropolitan Edison Co 80/09/30 lp
- -8010060250 Proposed Tech Specs 3.18.7 for fire barrier penetration seals. * Metropolitan Edison Co 80/09/30. 1p
- 010090391 Requests extension until 801024 for util response to NRC 800826 ltr re-control & handling of heavy loads due to extensive in-house reviews.

 HUKILLIN D Metropolitan Edison Co. 80/09/30. ip.
- 8010090418 Responds to NRC 800702 ltr re Tech Specs.Proposed Category A Tech Specs will be included in Chapter 11 of TMI-1 restart rept.submitted in amend by 801015.
 HUWILL.H D. Hetropoliten Edison Co. 80/09/30. ip.
- 8010170225 Application for Tech Spec Change 95 amending License DPR-50 to incorporate std definition of "operable." W/o Certificate of Bvc. ARNOLDIR.C. Metropolitan Edison Co. 80/09/30 2pp.
- --8010170232 Proposed Tech Spec Change 95, revising Section 1.3. to incorporate std definition of "operable," * Hetropolitan Edison Co. 80/09/30. ip.

- 8010230589 Summary of 800821 meeting w/8&W reactor owners group re abnormal transient operating guidelines program VISSING.G Operating Reactors Branch 4. 80/09/30 29pp
- 8010300202 "Technical Evaluation Rept.Adequacy of Station Electrical Distribution Sys Voltages.TMI-1," interim rept
 ROBERTS, E W E0%0 Idaho, Inc FIN A-6296 8010300202 80/09/30
- B010070323 Informs that study of reactor bldg spray sys not complete Revised submittal date for Tech Specs changed to B10101. HUKILL, H D Metropolitan Edison Co. 80/10/02 1p.
- 8010070542 Responds to 800704 ltr requesting schedules for safety evaluation open items re Opder Items 1.2,4.5 & 8 Encl table summarizes remaining open items HKKILL-H D Metropolitan Edison Co 80/10/02 opp
- B010070335 Forwards Amend 21 to restart rept HUKILL,H D Metropolitan Edison Co 80/10/03. ip
- --8010070338 Amend 21 to restart rept * Metropolitan Edison Co 80/10/03 150pp
- 8010170481 Forwards application for Tech Opec Change Request 34A, amending License DPR-50 ARNOLD,R C Metropolitan Edison Co 80/10/03 1p
- --8010170516 Application for Tech Spec Change Request 34A, amending License DPR-50 Certificate of Svc encl. ARNOLD,R G. Metropolitan Edison Co. 80/10/03. 4pp.
- --8010170518 Proposed Tech Spec Change 34A, revising Sections 3,4,5 % & # Apps A & B.to incorporate code requirements in response to NRC 781115 request w Hetropolitan Edison Co. 80/10/03. 100pp
- 8010240494 Forwards application to amend App A/B of License DPR-50 submitted as Tech Spec Change Request 34A ARNOLD,R C Metropolitan Edison Co. 80/10/03 ip
- --8010240500 Application to amend App A/B of License DPR-50, submitted at Tech Spec Change Request 34A
 ARNOLD, R C Metropolitan Edison Co BO/10/03 3pp.
- ---8010240598 Tach Spec Change Request 34A for Tech Spec Sections i i 3 12 3 re definitions, safety limits & limiting safety sys settings & limiting conditions for operation # Metropolitan Edison Co 80/10/03 78pp
- --8010240312 ET8 Sections 1-3 & 5 for facility * Metropolitan Edison Go 80/10/03 23pp.
- 8010200397 Notification of 801010 meeting w/util & MPR Associates in Washington,DC to discuss control room design review SILVER.H Operating Reactors Branch 4 80/10/06, 2pp.
- B010140462 Requests extension until B10131 to complete review of inadvertent reactor scram & safety injection discussed in NRC 790921 ter. Delay necessary to review incident during power operation HUKILL-H D. Metropolitan Edison Co. 80/10/08, 1p.
- 8010160490 Forwards review of Oyster Creek activities re TM1 Lessons Learned per NRC 790921 request SHEENEY.L.E Jersey Central Power & Light Co 80/10/08. 3pp
- 8010160013 Testimony on UCS Contention 5 re pressurizer power operates relief valve, block valve & associated circuits & controls Rept & prof qualifications encl Related correspondence. PDLLARD: R D Union of Concerned Scientists 80/10/10 22pp.
- --8010160014 "Loss of Reactor Coolant/Reactor Coolant Pressurs (Best)
 Break LOCA) Causing Automatic HPI, " Emergency Procedure
 1202-68. Certificate of Svc encl.
 4 Metropolitan Edison Co 80/06/30 33pp
- B010200423 Notifies that mine welds remain on IQBCC repair/replacement list Interim rept will be issued by B01114. Final rept anticipated after B01231, HUKILLH D. Metropolitan Edison Co. 80/10/14 ip,
- 8010200486 Submits mods to Tech Spec change Request 77A, adding spatt rainsp for crack growth at dome tendons in ring girder anchoring areas & changing wording of Section 4, 4, 2 1 i recontainment tendons
 HUKILL-H.D. Metropolitan Edison Co. 80/10/14, 2pp.

DOCKETED ITEMS

- 8010200460 Requests extension until 801024 to submit Tech Spec change request to modify Tech Specs re fire protection, in response to NRC 800919 ltr
 HURILL, H D Metropolitan Edison Co. 80/10/15 lp
- 80102:0445 Provides info re ance-through steam generator auxiliary feedwater nozzie thermal sleeve/collar weld attachment, in respense to 800610 inquiry Includes identification of probable failure mode, Interim actions & safety consequences HUKILL.H D Metropolitan Edison Co 80/10/17 App
- 8010210453 Submits info re once-through steam generator auxiliary facebeter notile thermal sleeve/coller weld attachment in response to NRC 800610 inquiry Sketch encl HUKTIL-H.D Metropolitan Edison Co. 80/10/17 4pp
- 8010210465 Forwards Amend 22 to "THI-1 Restart Rept " Amend provides info in response to NRC SER open items. HUKILL:H D Metropolitan Edison Co. 80/10/17 ip
- --B010210467 Amend 22 to "TMI-1 Restart Rept "
 a Hetropolitan Edison Co 80/10/17. 225pp
- 8010210474 Hodifies Tech Spec Change Request 91 re irradiation of surveillance capsules at Crystal River 3 Capsules removed from TKI-1 in 1976 should be inserted, irradiated & withdrawn per schedule shown in Table 4.22 R
- 8010240453 Responds to NRC 800507 itr & supplements 800630 initial response to add1 TMI-2 related requirements, Includes responses to shift manning requirements & revised scope & criteria for license examination.
 HUKILL.H D Metropolitan Edison Co. 80/10/20, 5pp.
- 8010300457 Forwards descriptions of sys changes from 770526 to present FBAR. Two items not listed in 770526 rept, OGL 0714, also encl. No procedure changes require FBAR mod No tests or experiments performed not described in FBAR.

 HUNIALL, H D Metropolitan Edison Co. 80/10/20, 12pp
- 8010240057 Testimony in response to ABLB Questions 6.a-6.c & 6 g through 6.k re emergency feedwater reliability. Evaluates effect of loss of ac power & non-nuclear instrumentation on operation. Prof qualifications encl. [APDDANNO.0 R. LANESE, L. C., TORGIVIA, J. A. Metropolitan Edison Co. 86/10/21, 23pp
- --8010240040 "TMI-1 Emergency Feedwater Bys " Certificate of Bys encl. * Hetropolitan Edison Co 80/10/21. 28pp
- 8010280482 Requests Tech Specs Change Request 96 fee cancellation & requests resubmittal per 800919 ltr. Change requests will be part of fire protection program at facility & therefore exampt from 100FR170 22 fee requirements.

 HUKILL.H D. Metropolitan Edison Co. 80/10/24 1p
- @ Inspection reports, IE Bulletins & correspondence
- 8010010171 Forwards IE lnsp Rept 50-289/80-15 on 800714-18. No noncompliance noted. BRUNNER: J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/11 2pp
- --8010010178 IE Insp Rept 50-287/80-15 on 800714-18 No noncompliance noted Major areas inspected properational test program, review requirements & administration. CAPHTON,D L. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch NICHOLAS.H. H Region 1. Philadelphia, Office of the Director 80/08/08. Spp
- 8010300018 Forwards 1E Insp Rept 50-289/80-17 on 800620-0710. No noncompliance noted. CARL80N.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/08/21. 2pp.
- --8010100021 IE Insp Rept 50-289/80-17 on 800620-0710. No noncompliance noted Major areas inspected; work activities & records associated w/Unit i restart program, tendon surveillance program & fire protection program.

 GAPELL. SAMDERS.M. Region i. Philadelphia, Office of the Director EBNETERS. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 80/08/20. 12pp.
- 8010060091 Discusses 800910 meeting w/util in TMI/NRC program ofc reoutstanding issues relative to IE Investigation Rept 30-320/79-10 & responses to items of noncompliance. GRIER/8 H. Region i, Philadelphia, Office of the Director 80/08/27. ip.

- 8010010203 Forwards response to IE Bulletin 80-10 re contamination of nonradioactive sys. Review of facility design & operational practices performed & procedure changes implemented.

 HERBEIN.J G Metropolitan Edison Co 80/09/02. 2pp.
- 8010010762 Responds to IE Bulletin 80-20 No Westinghouse Type H-2 control switches are used in safety-related circuits. HERBEIN, J O Metropolitan Edison Co 80/09/02 ip
- 8010060133 Responds to IE Bulletin 77-018 re environ qualification of Class IE equipment Forwards revised master list of equipment. Revised data sheets will be submitted by 801030 H/a encl HERBEIN.J O Metropolitan Edison Co 80/07/04 2pp
- 80100600BB Advises of cancellation of 800910 meeting at TMI/NRC program ofc Dutstanding issues re IE Investigation Rept 50-320/79-10 already discussed ORIER, BH Region 1, Philadelphia, Office of the Director 80/09/10 1g
- 8010200647 Responds to IE Bulletin BO-19. Revision 1. "Failures of Mercury-Wettad Matrix Relays in Reactor Protection Sys of Operating Nuclear Power Plants Designed by C-E " Bpecified relays are not utilized at facility HUKILL, H D Metropolitan Edison Co 80/09/16. 1p
- 8010240303 Ack receipt of 800828 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/80-03 & 50-320/80-03 MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/09/25
- --8010240309 Responds to NRC 800731 itr re violations noted in IE Insp Rapts 50-289/80-03 & 50-320/80-03 Corrective actions: withheld (ref 10CFR2 770), HERBEIN.J.O. Metropolitan Edison Co. 80/08/28. 1p
- --B010240315 Forwards IE Insp Repts 50-289/80-03 & 50-320/80-03 on 800201-0327 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/07/31
- --8010240322 IE Insp Repts 50-289/80-03 & 50-320/80-03 on 800201-0327. Noncompliance noted failure to limit access to protected area & vital area & failure to test personnel search equipment Details withheld (ref 10CFR2, 790). DEVLIN, J. W. Region 1, Philadelphia, Safeguards Branch SHEPPARD, R E. BAILEY, R. J. Region 1, Philadelphia, Office of the Director 80/03/21 2pp
- 8010270447 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested ORIER, B H. Region I. Philadelphia, Office of the Director 80/09/26 ip
- 8010230205 Responds to IC Bulletin BO-15, "Possible Loss of Emergency Natification Sys (ENS) w/Loss of Offsite Power " Review of ENS telephone installation was conducted in conjunction w/ Bell of PA HUKILL, H. D. Metropolitan Edison Co 80/09/29, 2pp
- 8010240139 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/02 ip.
- 8010080514 Responds to IE Bullstin 79-27 re loss of non-Class IE instrumentation & control power sys during operation Tests required to verify effects of combination of power loss on instrumentation & control functions completed HUKILL, H. D. Metropolitan Edison Co. 80/10/03. 1p
- BD102B0176 Forwards IE Info Notice BO-36. "Failure of Steam Cenerator Support Boiting " No specific action or response requested. CRIER, B H. Region 1. Philadelphia, Office of the Director BO/10/10. 1p
- R. Periodic operating reports & related correspondence
- BO10210427 Forwards monthly operating rapt for Bept 1980. HUKILL, H. D. Metropolitan Edison Co. 80/10/15. ip
- --8010210431 Monthly operating rept for Sept 1980. MITCHELL,D Q Metropolitan Edison Co 80/10/15 5pp

- 8 Reportable occurrences, LERs & related correspondence
- BOIO100374 PNO-TMI-80-045 on 900915, NRC approved major changes in organization which establishes General Public Utils Nuclear Oroup & which includes revised plant staff organizations HAVERKAHP, D.R., FASANO, A.N., COLLINS, J.T. TMI Program Office 80/09716. 2pp
- 8010080354 PNO-I-80-f31 on 800918, radio station KYW rebroadcast news repts of 790328 TMI-2 accident causing Region 1 employee to alert regional age BRIQOS, L. KEINIG, R. Region 1. Philadelphia, Office of the Birector 80/09/18 2pp
- 8009300506 RD 80-17 determined insufficient documentation to femonstrate that brakes on motor operators for purge valves AH-VIE & AH-VIE environmentally qualified Redundant valves fully qualified TOOLE.R J Metropolitan Edison Co 80/09/23 ip.
- 8010200516 R0 80-17 on 800923, determined that there is insufficient documentation to demonstrate environ qualification of brakes on motor operators for Purge Valves AH-VIE & AH-VIC Cause not stated Corrective action will be submitted TOOLE, R J Hetropolitan Edison Co 80/09/23 ip
- 8010150484 Forwards LER 80-017/017-0 HUK1LL, H D Metropolitan Edison Co 80/10/08 ip
- ---8010150492 LER 80-017/017-0 on 800923, during review, per IE Bulletin 79-01b, documentation to demonstrate that breaks on motor operators on purge valves AH-VIB/C & safety-related valves DH-V5A/B re environ qualified found insufficient HITCHELL.D G. Metropolitan Edison Co 80/10/08 3pp
- 710240489 RD 80-410 determined that replacement coils being installed in response to IE Bulletin 79-01A have a range lower than station battery voltage range Coils could gotentially fail if maintained at voltages above normal operating range FOOLE-R J Metropolitan Edison Co 80/10/20 2pp
- 10300577 PNQ-TMI-80-48 on 801020, licensee reported that two groups asked permission to use TMI observation cfr grounds for demonstration on 801021 Licensee denied permission. Two groups are TMI Alert & American Indian Movement CONTE, R. J., FASANQ, A. N. Office of Inspection & Enforcement, Office of the Director. 80/10/20 2pp

T. Hearing transcripts on non-antitrust matters

- B0101000047 Birect testimony re Anti-Nuclear Group Representing York Contention V (D) Resume.prof qualifications.supporting documentation & Certificate of Byc enc!
 BEYEA.J Anti-Nuclear Group Representing York 80/09/30 39pp
- 'iOiéOOi3 Testimony on UCS Contention 5 re pressurizer power operated relief valve.block valve & associated circuits & controls tapt & prof qualifications encl Related correspondence.
 'OLLARD-R D Union of Concerned Scientists 80/10/16 22pp
- i010160014 "Loss of Reactor Coolant/Reactor Coolant Pressure (Bmall Break LUCA) Causing Automatic HPI," Emergency Procedure 1202-46 Certificate of Svc encl W Hetropolitan Edison Co. 80/06/30 33pp
- 10200548 Forwards transcript of NJ Dept of Energy, Board of Public Itils 801007 hearing in Newark, NJ. IMEENEY, L. E. Jersey Central Power & Light Co 80/10/10. 1p
- i010200573 Transcript of NJ Dept of Energy,Board of Public Utils B01007 hearing in Newark,NJ re approval of rate increase for electrical svc & for amend to levelized adjustment clause & factor for such svc Pg in 327-1,468 * New Jersey: Btate of 80/10/07 142pp
- ·10210469 Forwards transcript of 801009 hearing in Newark,NJ re TMI-1 restart proceeding.

 8WEENEY,L E Jersey Central Power & Light Co. 80/10/10 1p
- --8010210471 Transcript of NJ Dept of Energy, Board of Public Utils 801008 hearing in Newart, NJ re approval of increase in rates for slectrical svc & amend to levelized energy adjustment clause & factor for such svc. Pp 1.549-1.618
 MARBHALL, S. O New Jersey, State of 80/10/09 70pp.
- 8010200199 Forwards testimony re UCB Contention & & ABLB Questions 1.3, 5.6 & 7 Certificate of Svc encl.
 CUTCHIN.J M Hearing Branch 2 80/10/14. 4pp.

- --8010200205 Testimony re ABLB question re UCS Contention 6 re ACS selfa & relief valves Question answered in NRC response to UCS Prof qualifications encl ZUDANS, J J Equipment Qualification Branch 80/10/14 30c
- --8010200209 Testimony rs NRC position on NUREO-0644 &/or NUREO-0640 Review will be completed & requirements will be issued in final form within next few wks Prof qualifications one! REID.R W Operating Reactors Branch 2 80/10/14 3pp
- --8010200216 Testimony re ASLB Question 3 re interim reliability evaluation plan (IREP) TMI-1 will not be included in IREP IREP intended to serve as procedural guidelines & will be ready by CYB1 Prof qualifications encl RQMSOME, F H Probabilistic Analysis Branch (Pre 791030) 80/10/14 4pp
- --8010200222 Testimony re ASLB Question 6 re emergency feedwater sys reliability Emorgency feedwater following main feedwater transient is not type of accident requiring safety-related equipment protection Prof qualifications encl.

 HERMIEL, J Auxiliary Systems Branch JENSEN. W Reactor Systems Branch LANTZ. E Office of Nuclear Reactor Regulation, Director 80/10/14 18pp
- ---B010200230 Testimony re ASLB Question 7 on NRC position on NVREG-Cédi Recommendations in Table 2 1 will be implemented as defined in RJ Mattson B00808 memo to Denton Implementation schedule not yet established Prof qualifications encl REID,R W Operating Reactors Branch 2 80/10/14 2pp
- B010200687 Testimony re ASLB questions on UCS Contention 12 about environ qualification of safety-related equipment IE Bulletin 79-01B investigation will reveal nonconformances Prof qualifications & Certificate of Svc encl BRAULKE.G R. General Public Utilities GPU Service Corp. 90/10/15
- B010210087 Forwards transcript of 801008 hearings in response to MRC 770921 & 1109 requests for info re significant regulatory developments affecting util in restart proceeding BWEENEY, L S Jersey Central Power & Light Co
- --8010210371 Yranscript of 801008 hearings before NJ DDE, Board of Public Utils, for rate increase Pp 1469-1548 * New Jersey, State of 80/10/08 80pp
- 8010230555 Transcript of 801015 morning evidentiary hearing in Harrisburg, PA re TMI-1 restart Pp 2,491-2,763 HR Denton 800705 memo clarifying TMI action plan requirements & significant change summary sncl 4 Atomic Safety and Licensing Board Panel 80/10/15 081pp
- 8010230545 Transcript of 801016 morning evidentiary hearing in Harrisburg,PA re TMI-1 restart Pp 2.764-3.008 * Atomic Safety and Licensing Board Panel 80/10/16 247pp
- 8010230548 Transcript of 801017 morning evidentiary hearing in Harrisburg.PA re TMI-1 restart Pp 3,007-3,111, * Atomic Bafety and Licensing Board Panel 80/10/17 105pp
- 8010240037 Testimony in response to ASLB Questions 6 a-6 c & 6 g through 6.k re emorgency feedwater raliability Evaluates effect of loss of ac power & non-nuclear instrumentation on operation Prof qualifications encl CAPODANNO, 0 R . LANESE, L C , YORCIVIA, J A Metropolitan Edison Ce 80/10/21 23pp.
- .8010300130 Transcript of 801021 morning evidentiary hearing in Harrisburg.PA re TMI-1 restart Pp 3,112-3,301 * Atomic Sefety and Licensing Board Panel 80/10/21 193pp
- BO10310477 Forwards transcript of 801020 hearing before NJ Board of Public Utils in response to NRC 790921 & 1109 requests to be kept informed of developments in restart proceeding BWEENEY, L E Jersey Central Power & Light Co 80/10/22, ip
- --8010310480 Transcript of 801020 hearing before Board of Public Utile at Newark-NJ.Pp 1619-1751

 * New Jersey- State of 80/10/20 133pp
- B010310545 Transcript of 801022 TMI-1 restart hearing in Harrisburg.FA Pp 3302-3516 * Atomic Bafety and Licensing Board Panel 80/10/22, 214pp

i

- 8010310541 Transcript of 801023 TMI-1 restart hearing in Harrisburg,PA
 - Pp 3517-3732 • Atomic Safety and Licensing Board Panel 80/10/23 215pp
- 8010310016 Transcript of 801024 restart hearing in Harrisburg.PA Pp. 3733-3827
 - * Atomic Safety and Licensing Board Panel 80/10/24 97pp

U Congressional/Executive Correspondence

- 8010280280 Responds to recommendations of GAQ rept EMD-80-89, "TMI Financial Fallout " NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIB re decontamination of TMI-2 prepared AMEARNE, J F Commissioners 80/10/07 2pp
- --B010280284 Responds to recommendations of GAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE, J.F. Commissioners 80/10/07. 2pp
- --B01028028B Responds to recommendations of QAG rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE.J F Commissioners 80/10/07 2pp
- --8010280289 Responds to recommendations of QAO rept EMD-80-89, "TMI Financial Failout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE, J.F. Commissioners 80/10/07 2pp
- --8010280274 Responds to recommendations of QAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE, J F Commissioners. 80/10/07 2pp
- --B010280278 Responds to recommendations of QAO rept EMD-80-89, "TMI Financial Fallout." NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE.JF. Commissioners 80/10/07 2pp
- --8010280303 Responds to recommendations of GAD rept EMD-80-89, "TMI Financial Fallout." NRC involved in reviewing technical info & hearing preparation of restart of TMI-1. Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE, J F Commissioners 80/10/07 2pp
- --B0102B0304 Responds to recommendations of GAO rept EMD-80-89, "TMI Financial Fallout " NRC involved in revisuing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIB re decontamination of TMI-2 prepared AHEARNE, J.F. Commissioners 80/10/07 2pp.

V. Operator Examinations

- BO10100299 Requests restart licensing exams be administered to approx 38 THI-1 licensed reactor operators & senior operators during 810420-0508 time frame Current training schedule outlined. HUKILL-H D Metropolitan Edison Co 80/10/03. 1p
- 8010220476 Commits to mitigating core damage training for manager, supervisor of operations, shift supervisor, shift foremen, control room operators, shift technical advisors & emergency directors Support staff training provided in specific areas HUKILL, H D Hetropolitan Edison Co. 80/10/08. 1p
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- BO10020314 Forwards add1 info re security force training & qualification plan, per NRC 800921 request Info withheld (ref 800FR2.790)
 MCR181,4 V Boston Edison Co. 80/09/18 ip
- 8010160657 Submits addl info re fire protection Items 3 1.7 % 3 2 4 Prior to implementation of listed mode. station security criteria was updated to require presence of two men in plant vital areas.

 MARISI, A. V. Boston Edison Co. 80/10/03. App.

- --8010160460 "Reactor & Turbine Bldgs.Floor Plan at Elevation 23 Ft.
 0 Inches Doors & Walls Fire Rating "
 * Bechtel Corp 6498-2 77/02/24 ip
- 801021061B Responds to NRC 801007 & 10 requests for add1 info re cable penstration fire stops qualification tests, test suggestions & Kerito cables Submits recommendations for upgrading fire seals Testing summary ent. MORISI.A V Boston Edison Co 80/10/13 17pp.
- 8010310401 Forwards replacement sheets to security plan Info withheld (ref 10CFR2,790) MORISI.A V Boston Edison Co. 80/10/24 1p

O Adjudicatory correspondence

- 8010080333 Forwards order for mod of license re environ qualification of safety-related electrical equipment IPPOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
- --B010080337 Order for mod of license re environ qualification of safety-related electrical equipment.
 EISENHUT, D 0 Division of Licensing 80/08/27 6pp
- 8010200627 Forwards order confirming util commitments to implement action re IE Bulletin 80-17.

 STELLO.V Office of Inspection & Enforcement. Office of the Director 80/10/02 lp
- --B010200631 Order confirming will commitments to implement action re IE Bullatin B0-17 BTELLO,V Office of Inspection & Enforcement, Office of the Director B0/10/02 7pp.
- 8010310451 Request for 20-day extension for util to plead for hearing on 800712 order for mod of license published in 801003 FR. DIONAN, T O Boston Edison Co DIONAN, T O Ropes & Oray 80/10/23, Zon

H General correspondence

- 8010100105 Discusses emergency planning regulations, in response to 800418 itr re L Boyd concerns FEMA is responsible for adequacy of emergency preparedness in states & communities around nuclear plants
 DIRCKS.W J Office of the Executive Director for Operations 80/09/30 2pp
- --B010100111 Requests response to encl L Boyd inquiry about emergency preparadness around facility, HECKLER, M M House of Rep 80/04/18 2pp
- J Insurance & indemnity information
- 8010280628 Requests Endorsement 36 to Policy MF-58
 DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity)
 80/09/24 ip
- 8010140340 Forwards Endorsements 52 & 54 to NELIA Policy NF-188 Endorsement 53 was returned for correction of error, FOULBHAM, P A Boston Edison Co 80/10/02 3pp
- 8010140304 Informs that Endorsement 36 to MAELU Policy MF-58 was submitted to NRC on 790116. In response to NRC 800924 itr Forwards PA Foulsham 790116 ltr & Endorsement 36 STOME: W 8 Boston Edison Co 80/10/03 1p.
- 8010310350 Forwards Endorsement 55 to NELIA Policy NF-188 & Endorsements 39,40 & 41 to MAELU Policy NF-58 FOULSHAM, P.A. Boston Edison Co. 80/10/21 5pp
- P Operating license stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT.D 0 Division of Licensing. 80/09/19 28pp
- 8010080376 Requests addi action re NRC 780807 ltr re deficiencies in Hatch.Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies & reactor protection sys. IPPOLITO.T A Operating Reactors Branch 2 80/09/24 3pp

- 8010020496 Proposed Change 80-5 to App A of License DPR-35, revising Tech Spec Section 6 0 "Administrative Controls:" to reflect recent mgt reorganization HOWARD, J E Soston Edison Co 80/09/29 3pp
- --8010020499 Proposed revision to Tech Spec Section 4 0. "Administrative Controls:" reflecting recent mgt reorganization.

 * Boston Edison Co 80/09/29 9pp
- 8010060318 Forwards drawings & info re manual override of engineered safety features of containment isolation valves, in response to NRC 800812 itr Responses to Items 1 & 2 will be provided by 801015 Eleven drawings available in Central Files only MORISI.A V. Boston Edison Co 80/09/29 3pp
- --9010060320 "Heating, Ventilation & Air Conditioning Temp Control Diagram for Control Room Cable Spreading & Computer Room " Bachtel Corp 6498 74/02/04 ip
- --8010060322 "Wiring Block Diagram Annunciation, Nuclear " # Bechtel Corp. 6498 78/09/07. 1p
- --8010060326 "Schematic Diagram Heating & Ventilation Sys Control Room, Computer Room & Access Control Room " + Bechtel Corp 6498 73/10/31. 1p
- --B010060328 "Schematic Diagram Heating & Ventilation Sys Control Room" * Bechtel Corp 4498 73/10/31. 1p
- --B010060932 "Panel C7 Annunciators " ** Bechtel Corp 6498 78/06/14 ip
- 8010070445 Provides implementation details of TMI-2 Task Force Lessons Learned short-term requirements for items having 801001 submittal date in response to NRC 801001 ltr MCRIBI, A. V Boston Edison Co 80/10/01, 2pp,
- 8010280001 Forwards Amend 43 to License DPR-35 & FR notice of issuance IPPOLITO.T.A Operating Reactors Branch 2 80/10/03 3pp
- --80i0280002 Amend 43 to License DPR-35, requiring licensee to implement & maintain safeguards contingency plan within 30 days of Commission approval [PPOLITO.T.A. Operating Reactors Branch 2 80/10/03, 2pp
- --8010280003 Notice of issuance of Amend 43 to License DPR-35 IPPOLITO T.A Operating Reactors Branch 2 80/10/03 1
- 8010270351 Suppls 800727 response to Items 1 & 2 of NRC 800812 Itr re bypass & reset of engineered safety features. MORIBLA V Boston Edison Co 80/10/10 2pp
- 8010270316 Forwards info re carbon dioxide sys design adequacy, to expedite resolution of generic technical concerns originally discussed in 800229 ltr Discrepancy re wtil position on carbon dioxide test was resolved during 801002 & 14 telcons. MORISI.A.V. Boston Edison Co. 80/10/20. 8pp
- Q. Inspection reports, IE Bulletins & correspondence
- 9010010378 Forwards IE Insp Rept 50-293/80-23 on 800528-29 No noncompliance noted GRIER.B.H. Region i, Philadelphia, Office of the Director. BO/08/08 Zpp
- --8010010382 IE insp Rept 50-293/80-23 on 800528-27 No noncompliance noted Major areas inspected; emergency planning procedures & representative records, interviews w/personnel & inspector observations observations
 TERG.N M. Region 1, Philadelphia, Office of the Director.
 BORES,R J. Region 1, Philadelphia, Fuel Facility & Materials
 Bafety Branch 80/08/05 7pp
- 8010030307 Responds to IE Bulletin 80-15 Installation of uninterruptible 120-volt ac power supply to audio circuits completed on 800731. Approx 16 manhours expanded on bulletin. ANDONINI, 0 C. Boston Eddson Co. 80/08/19. 2pp
- 8010010215 Responds to IE Bulletin 80-17 re BWR control rod failure to insert. Station procedures revised to require manual screm for drift of two rods in nine rod array & to provide for daily check of control rod drive temp MORIBI.A V. Boston Edison Co. 80/09/08 2pp.

- 8010010237 Responds to IE Bulletin 80-14 re degradation of scraa discharge vol capability Station procedures are being prapared to periodically test vent & drain valves MORIBIA V Boston Edison Co 80/09/10 2pp
- 8010030098 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/80-22, Response withheld (ref 10CFR2 790) MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch 80/09/10.
- --8010030101 Forwards IE Insp rept 50-293/80-22 on 800527-0603 & hotels of violation Notice withheld (ref 100FR2 790)

 MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/07/24
- --8010030104 IE Insp Rept 50-273/80-22 on 800527-0603, Noncompliance noted failure to implement access control procedure Details withheld (ref 10CFR2 790)
 DEVLIN,J W. Region 1, Philadelphia, Office of the Director SHEPPARD, R. E. Ragion 1, Philadelphia, Safeguards Branch 80/07/14 ip
- 8010220094 Responds to Item B 1 of IE Bulletin 80-17. Suppl 1, "Failura of 76 of 185 Control Rods to Fully Insert During Scram at BWR." Scram discharge header monitoring instrumentation will be installed by 801107 Boston Edison Co 80/09/16 1p
- 8010270111 Immediate action ltr confirming 800919 telcon re standby gas treatment sys operability Lists actions to be taken by 800925 GRIER, D. H. Region 1. Philadelphia, Office of the Director
- B010270213 Submits addl info re design details of scram discharge header monitoring instrumentation in response to IE Bulletin B0-17 re failure of control rods to insert during scram at MACHON, R.D Boston Edison Co 80/07/25 1p
- 8010200627 Forwards order confirming util commitments to implement action re IE Bulletin 80-17 SYELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/02. 1p.
- --8010200631 Order confirming util commitments to implement action to IE Bulletin 80-17 STELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp
- 8010240116 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required ORIER, B M. Repion 1, Philadelphia, Office of the Director 80/10/02. ip.
- 8010280233 Forwards IE Info Notice 80-35. "Failure of Steam Cenerator Support Bolting " No specific action or response requested ORIER, B. H. Region 1, Philadelphia, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010160466 Forwards monthly operating rept for Sept 1980 MACHON, R D. Boston Edison Co 80/10/01, ip
- --8010160469 Monthly operating rapt for Sept 1980 UHITNEY, O. O. Boston Edison Co 80/10/10 6
- 8010240237 Forwards "Annual Rept of Tests. Changes or Experiments, Jul 1979-June 1980 " MCRIGI, A, V Boston Edison Co 80/10/20 1p.
- --8010240240 "Annual Rept of Tests, Changes or Experiments, Jul 1979-Jula Boston Edison Co. 80/10/20 12pp
- 8. Reportable occurrences. LERs & related correspondence
- 8010080330 PNO-1-80-117 on 800801.D safety relief valve failed to each on four successive attempts while testing Valve is two stage Target Rock safety relief Plant was placed in cold shutdown for repairs, Failure mechanism not found ROBERTS, K., MARTIN, T. T., BRUNNER, E. J., Region 1, Philadelphia, Office of the Director 80/08/01. ip.

8010060237 Forwards LER 80-057/03L-0 MACHOM, M Boston Edison Co 80/09 80/09/23 is --8010060246 LER 80-059/03L-0 on 800912, review revealed standby gas treatment sys filters had not been sampled after 720-h of sys operation Caused by inadequate procedure definition Filters sampled & analysed ORAHAM.E T Boston Edison Co 80/09/23 ip 801001050& Forwards LER 80~064/03L-0 MACHON R D Boston Edison Co 80 80/09/29 15 --B010010911 LER B0-064/03L-0 on B00829, reactor bldg airlock doors were momencarily opened due to failure of electrical interlock Caused by defective microswitches which actuate door interlock Microswitches replaced HCLQUQHLIN, M T Boston Edison Co B0/09/29 ip 8010010667 Forwards LER 80-065/03L-0 MACHON, R D Boston Edison Co 80/09/29 ip --8010010674 LER 80-065/03L-0 on 800828, while inerting drywell, discovered that nitrogen purge supply isolation valve AO 50338 would not close via control switch Caused by defective solenoid vent valve Valve repaired GRAHAM.E T Boston Edison Co 89/09/27 ip 8010020453 Forwards LER 80-063/03L-0 MACHON, R D Boston Edison Co 80. 80/09/29 1p --8010020462 LER 80-063/03L-0 on 800828, reactor coolant lask detection air sampling sys (C-19) declared inoperable Caused by excessive moisture in sample lines Valve packing leak will be overhauled during refueling outage MCLDUGHLIN, M T Beston Edison Co 80/09/29 ip. 8010090347 Forwards LER 80-066/03L-0 MACHOR R D Boston Edison Co 80/09/30 ip --8010070352 LER BO-066/03L-O on B00901, during surveillance testing, diesel fire pump was declared inoperable, Caused by broken governor control assembly Assembly repaired & returned to MCLDUGHLIN, M. T Boston Edison Co 80/09/30 ip 8010210712 Forwards LER 80-068/03L-0 MACHQN,R D Boston Edison Co 90. 80/09/30 1p --8010210722 LER BO-068/03L-0 on 800924, lagging of reactor protection sysmotor generator set current & voltage was inadvertently terminated during last refueling outage. Caused by inadequate station procedures Procedures 2 1 15 revised

Boston Edison Co 80/09/30 ip 8010070518 Forwards LER 80-062/03L-0 MACHON,R D Boston Edison Co. 80/ 80/10/03. 1p --B010070327 LER B0-062/03L-0.on B00903.following surveillance testing.
A diesel generator declared inoperable due to snapped fuel
line in area of diesel generator cylinder 9R Caused by
severed fuel crossover T type connector
HCLQUOHLIN.M T Boston Edison Co B0/10/03. ip. 8030140454 RD 80-047/01X-0 on 801002, NRC was notified that analytical reanalytis of RHR 8ys B indicated that as-built configuration would not remain functional during 88E. Caused by design error Beismic anchor is being modified.

QRAHAM, E T Boston Edison Co. 80/10/03 1p E010170007 FND-1-80-145 on 801007, while at 96% power, A safety relief valve opened w/o apparent cause Operators were unable to close valve & menually scrammed reactor, Preparations underway to investigate problem.

MARTIN.T., BRUNNER.E J Region I, Philadelphia, Office of the Director. 80/10/07. ip

8010210547 LER 80-069/01X-0:on 801007, w/unit at 96% steady state power,

reactor vassel 203-3A safety relief valve opened Caused by excessive nitrogen supply pressure Pressure resulted in leakage through solenoid valve into valve diaphragm MCLOUGHLIN:H T. Boston Edison Co. 80/10/10 2pp

B010210715 Forwards LER 80-067/01T-0, MAGHDN.R.D Boston Edison Co. 80/10/10 1p

```
--8010210724 LER 80-067/017-0 on 801002, analytical reanelysis of 8 RHR sys indicated that as-built configurations of sys would not remain functional during BSE Caused by design error Beismic anchor modified to meet criteria GRAHAM, E. Y Boston Edison Co 80/10/10 ip
 8010310501 RD 80-049/01X-0 on 801007. w/reactor at 96% steady state
      power operation, reactor vessel relief valve RV 203-3A opened Caused by high nitrogen pressure resulting in leakage into diaphragm of valve Pressure reduced MCLQUOHLIN.H T Boston Edison Co BO/10/10 2pp
 8010200429 Forwards LER 80-071/03L-0
MACHON, R D Boston Edison Co 80/10/14 1p
 --8010200431 LER 80-071/03L-O on 800914.A train of standby gas treatment
sys declared inoperable as main stack radiation levels had
increased Caused by sys trip Belts & bearings replaced, fan
lubricated & returned to svc.
MCLOUOHLIN.M T Boston Edison Co 80/10/14 ip
 B010210536 RO 80-070/01X-0 on 801010, during steady state operation, 480 volt breaker B204 tripped twice within 10 minutes, de-energizing 480 volt bus B14 Cause unknown, Bus B14 was immediately returned to svc by closing breaker B204 MCLOUGHLIN, M T Boston Edison Co 80/10/14 ip
8010210854 RD 80-072/01X-0.on 801014, during steady state operation, mgt review revealed that reactor protection sys trip level setting was miscalibrated to nonconservative level Caused by calculation error Monitors were immediately recalibrated MCLQUOHLIN, M T. Boston Edison Co. 80/10/15.
8010220511 Forwards LER 80-054/03L-1,
MACHON, R. D. Boston Edison Co 80/10/15 ip,
   -B010220536 LER 80-054/03L-1 on 800916.Attachment 2 to LER 80-054/03L-0
           found to incorrectly indicate that nuclear operations manager is member of ORC Caused by oversight by preparer. Revised Attachment 2 encl
           ORAHAM, E T Boston Edison Co 80/10/15 2pp.
8010280497 Forwards LER 80-073/03L-0
MACHON, R D Boston Edison Co. 80/10/17 ip.
--8010280503 LER 80-073/03L-0 on 800917. ogt review of records revealed that monthly surveillance test 8P74-41, visual insp of energy piping outside containment was not performed within required interval Caused by scheduling error HCLOUGHLIN. M T. Boston Edison Co. 80/10/17 1p.
8010240410 Forwards LER 80-069/017-0
MACHON, R D Boston Edison Co 80/
                                                                                          80/10/20 lp
---B01024041B LER 80-069/01T-O on B01007 reactor vessel valve RV 203-3A opened Caused by high nitrogen pressure resulting in leakage past seat of valve 3-way, solenoid control valve into diaphragm of relief valve. Nitrogen pressure reduced MCLDUGHLIN.M T Boston Edison Co 80/10/20 2pp.
B010280407 Forwards LER 80-074/04L-0
MACHON, R D Boston Edison Co. 80/10/22 1p
---8010280414 LER 80-074/04L-0 on 790125,0228 & 0301.condenser delta T, difference between intake & discharge canals sea water tamp, exceeded Tech Specs, Caused by condenser tube sheet fouling & low tide Power reductions & condenser backwashes initiated MCLGUGHLIN.M T Boston Edison Go 80/10/22, 4pp.
8010280490 Forwards LER 80-070/017-0
MACHON, R D Boston Edison Co 80/10/22, 1p
--8010280494 LER 80-070/01T-0 on 801010,480 volt breaker 52-204 tripped twice within 10 minutes de-energizing 480 volt bus 814, disabling loop A of RBCCM. Cause unknown Breaker closed, bus returned to sev & 100p A returned to normal.

MCLGUOHLIN,M T. Boston Edison Co 80/10/22, ip.
B010280574 Forwards LER 80-076/03L-0, MACHON, R. D. Boston Edison Co. B0/10/24 1p
--8010280579 LER 80-076/03L-0 on 800923.flow integrator FQ 7032 for drywell floor sump pump was not operating. Cause undetermined.
           MCLQUGHLIN,M T Boston Edison Co 80/10/23 1p
```

- DOCKET 90-274 MICHIGAN STATE UNIV RESEARCH REACTOR J Insurance & indemnity information
- G. Inspection reports. IE Bulletins & correspondence
- 8010080228 Forwards IE Insp Ropt 50-294/80-03 on 800811-13 & notice of HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Bupport Branch B0/08/29 2pp.
- --8010080237 Natice of violation from insp on 8008(i-13 * Region 3, Chicago, Office of the Director, 80/08/28, lp.
- --8010080250 IE Insp Rept 50-294/80-03 on 800811-13 Noncompliance noted requalification training exam frequency & frequency of surveillance & testing exceeded specified time limits RIDOMAY, K R, BOYD, D C Region 3, Chicago, Diffice of the Director. 60/08/28 6p
- B010160690 Ack receipt of B00922 ltr informing NRC of steps taken to correct violation noted in B00829 ltr.

 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/10/03 ip.
- --B010140497 Responds to NRC 800829 ltr re violations noted in IE insp on 800811-13 Corrective actions:reactor safety committee will audit maint records to ensure that testing & surveillance procedures are performed in timely manner TERRY, B H Hichigan State Univ 80/09/22 ip
- 3CRET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
- Security, medical, emergency & fire protection plans
- JOIO140283 Forwards add1 info requested in NRC 800324 ltr re fire protection program Fifty oversize facility & instrumentation drawings encl.to be recalled at future date MAUCHION.H F Commonwealth Edison Co 80/09/30 82pp.
- Q. Adjudicatory correspondence
- B010070017 Decision affirming ABLB resolution on corresion issue re storage pool mod.LBP-80-7 State of IL position re failure to impose Tech Specsinegligent loss of water & failure to properly access makeup water TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 80/10/02.
 -)10280535 Notice of appearance in proceedings STEPTOE, P P Commonwealth Edison Co. 90/10 80/10/23 10
 - 110290388 Request for hearing re 800919 orders for mod of licenses requiring certain info on environ qualification of safety-related equipment in response to IE Bulletin 79-018. Urges suspension of effectiveness of orders WZertificate of Svc 87EPTDE.P.P. Commonwealth Edison Co. 80/10/23. 8pp.
 - Operating license stage documents & correspondence
 - 10200624 Forwards request for NRC approved route for shipment of spent fuel rods, Encl withheld (ref 10CFR2.790) THINNES, R Q NL Industries, Inc. 80/08/14 1p.
- O10210144 Confirms 800819 telcon we use of facility docket number Concurs on use of docket number for advance route approval. THINNERS R O N. Industries, Inc. 80/08/19 ip
- j010010151 Ack response to NRC 791109 ltr re ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture Response acceptable & no further action necessary. VAROALB A Operating Reactors Branch 1. 80/09/12 2pp.
- 8010090281 Forwards info re-status of facility action plan items during 800317-0915. Forty licensing actions completed during period & 12 added.
 REEVEB.E.A. Operating Reactors Branch 1. 80/09/19 4pp.

- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENKUT, D.G. Division of Licensing 80/09/19 28pp
- B010080458 Forwards request for add1 info re GA program re-evaluation Outstanding items include organizational independence, staffing & qualification requirements & QA involvement in operational activities. Operating Reactors Branch 1 80/09/23 9pp
- BO10090234 Forwards request for add1 info re GA program re-evaluation Items addressed include extension of GA program to all items affecting safety, organizational independence & staffing & qualification requirements VARGA.8 A Operating Reactors Branch 1 80/09/23 Bpp
- B010020286 Forwards repts on equipment environ qualification confeints list of additions, deletions or significant changes to 800602 rept & revised responses to draft interim technical avaluation rept NAU9HTDN, W F. Commonwealth Edison Co. 80/09/24 2pp ,
- --8010020271 "Equipment Environ Qualification Review Responses to Draft 1
 Interim Technical Evaluation Rept for Zion Station-Units I &
 2 "
 - # Sargent & Lundy: Inc 80/09/19 200pp
- --8010020278 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Bhutdown, Zion Station Units 1 & 2." Vols 1-3. # Bargent & Lundy, Inc 80/07/19 800pp
- 8010070597 Proposes to combine responses to NRC requests re amend to Tach Specs concerning decay heat removal capability & min level of water over irradiated fuel Combined responses will be submitted by 801031

 NAUGHTQN, H. F. Commonwealth Edison Co 80/09/24, 2pp
- 8010090552 Notification of 800925 meeting w/util in Chicago, IL to discuse schedules for task action items & reliability study & to introduce new NRC project manager. REEVEB, E Operating Reactors Branch 1 80/09/24 2pg.
- 8010100361 Bubmits list of current qualification programs for EPR1 util aquipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC LAMKEN, D. G. Commonwealth Edison Co. BO/09/24 2pp.
- 8010230127 Forwards revised resubmittal of facility rept for review W/o enc.. NERSES,V Mechanical Engineering Branch SO/09/26, ip
- B010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements" Urgas NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED, C. Commonweelth Edison Co 80/10/01 5pp.
- 8010070534 Forwards info & drawings re undervoltage protection, in response to Questions 1,2,3,4 & 6 of NRC 800813 ltr. Tech Specs changes identified in Questions 5 & 7 being evaluated. JANECEM.R.F. Commonwealth Edison Co. 80/10/01 3pp
- --8010070564 "Relaying & Metering Diagram 4 FV & 480 Volt Buses [48:147 138 & 137. Sargent & Lundy, Inc 3782 73/07/16 ip
- ---B010070570 "Schematic Diagram Electronic Switching Sys Sus 149."
 * Sargent & Lundy, Inc. 70/06/06 ip.
- 8010180427 Application to amend Licenses DPR-39 & DPR-48, changing Applitech Specs to reflect Westinghouse STS requirements.
 Itemization of changes & Class I-II amend fees encl.
 NAUOHION. H. F. Commonwealth Edison Co. 80/10/03. 7pp
- --- 8010150436 Proposed changes to App A Tech Specs to reflect Nestingless "
 BTS requirements. Deferred & nonapplicable Tech Specs items w/justification encl.
 # Gommonwealth Edison Co. 80/10/03 28pp
- 8010160485 Bubmite summary of 800925 meeting w/NRC.Comm Ed.PABNY k Westinghouse in Chicago, IL re schedule for Zion/Indian Point near-site study per SA Varga request.Requests NRC concurrence of suggested data for addit meeting in Dec 1980 NAUGHTON.H F Commonwealth Edison Co. 80/10/06, 5pp

ď

- 10220550 Forwards add1 environ qualification info as followup to preliminary draft response to App D of technical evaluation rest provided to NRC at 800827 meeting Util will continue to subait info upon availability Oversize drawings enc! RAVOHTOUR: W F Commonwealth Edison Co 80/10/04, 450pp
- B010220552 "Bingle Line Diagram 4160 & 480 Volt Engineered Bafeguard Sys Buses " 4 Sargent & Lundy, Inc. 3782 76/12/06 ip
- 8010220558 "Key Diagram 4160 Volt Switchgear Engineered Safeguard Sys Bus 147 & 148 " * Sargent & Lundy, Inc 3782 73/07/16 1p
- 8010220350 "Key Diagram 4160 Volt Switchgear Engineered Safeguard Bys Bus 149 " 4 Sargent & Lundy, Inc. 3782 73/07/16 ip
- 3010220565 "Key Diagram 480 Voit Switchgear Engineered Safeguard Sys Buses 137 & 138 " • Sargent & Lundy, Inc 3782 79/03/13 1p.
- MINORAGE PRov. Disease 480 Unit Switchness Engineered Referent Su
- 3010220569 "Key Diagram 480 Volt Switchgear Engineered Bafeguard Bys Bus 139," 4 Bargent & Lundy, Inc. 3782, 73/07/16, ip
- 0010220573 "Key Diagram 480 Volt Auxiliary Bldg Engineered Safeguard Bys Motor Control Ctr 1371." * Bargent & Lundy, Inc. 3782 73/07/16, 1p.
- 010220574 "Key Diagram 480 Volt Auxiliary Bldg Engineered Bafeguard Bys Motor Control Ctr 1981A " 4 Bargent & Lundy, Inc. 3782 73/07/16 1p
- 0010220575 "Key Diagram' 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 13818 "

 * Bargent & Lundy, Inc 3782 77/04/28 ip.
- 010220377 "Key Diagram. 480 Volt Crib H8E Engineered Safeguard Sys Motor Control Ctr 1382 & 1392 " 4 Sargent & Lundy, Inc 3782-3 73/07/16 1p.
- 010220579 "Kgy Diagram: 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 1383A " + Bargent & Lundy, Inc. 3782 73/07/16 1p.
- 010320581 "Key Diagram. 480 Volt Auxiliary Bldg Engineered Bafeguard Bys Motor Control Ctr 1372." * Bargent & Lundg, Inc 3782. 73/07/16. ip
- 010220582 "Key Diagram' 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 13938 " • Bargent & Lundy: Inc. 3782 77/08/30 ip
- 010220585 "Key Diagram 480 Volt Auxiliary Bldg Engineered Bafaguard Bys Motor Control Ctr 1391-PT1." * Bargent & Lundy, Inc. 3782, 74/12/13, 1p
-)j0220596 "Mey Diagram: 480 Volt Auxiliary Bldg Engineered Bafeguard Bys Hotor Control Ctr 1391-PT2 " * Bargent & Lundy, Inc. 3782 73/07/16. 1p
- NO220588 "Bingle-Line Diagram: 4160 & 480 Volt Engineered Bafeguard Sys Buses."

 Sargent & Lundy, Inc. 3838 79/04/16 1p.
- 110220594 "Key Digram: 4160 Volt Switchgear Engineered Safeguard Sys Sys 247 & 248 " 4 Sargent & Lundy, Inc. 9898 79/08/02. 1p.
- H0220397 "Key Digram 4160 Volt Switchgear Engineered Safeguard Sys Bus 249."

 * Sargent & Lundy, Inc. 3838 73/08/02. 1p.
- 10220604 "Key Digram 480 Volt Switchgear Engineered Safeguard Sys Buses 237 & 238."

 + Sargent & Lundy, Inc. 3782. 79/04/16. 1p.
- 10220508 "Key Digram. 480 Volt Switchgear Engineered Safeguard Sys 8us 237." • Sargent & Lundy, Inc. 3838. 74/07/09 1p.
- 10220611 "Key Digram. 480 Volt Auxillary Bldg Engineered Bafeguard Bys Motor Control Ctr 2381A." • Bargent & Lundy. Inc. 3838. 73/08/02. 1p

- --8010220612 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafeguard 8ys Motor Control Ctr 23918 " 4 Sargent & Lundy, Inc. 3838 74/12/10 1p
- --8010220615 "Key Digram 480 Volt Crib HSE Engineered Bafaguard Sys Motor Control Bys 2382 & 2392 " * Bargent & Lundy, Inc. 3838. 73/08/02 1p
- --8010220617 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafeguard Sys Motor Control Ctr 23838 " * Sargent & Lundy, Inc. 3838 79/04/28 1p
- --B010220619 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafoguard Bys Motor Control Ctr 2393A " * Bargent & Lundy, Inc. 3838 77/09/16, 1p
- --8010220621 "Key Digram 480 Volt Auxiliary Bidg Engineered Bafeguard Sye Motor Control Ctr 2372" 4 Bargent & Lundy, Inc. 3830 73/08/02 1p
- --8010220622 "Key Digram 480 Volt Auxiliary Bldg Engineered Sefeguard Sys Motor Control Ctr 23938 " * Bargent & Lundy, Inc. 3838 79/04/16 1p
- --8010220625 "Key Digram. 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 2391 PT1 " * Sargent & Lundy. Inc 2838 73/08/02 ip.
- --8010220626 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafeguard Sye Motor Control Ctr 239: FT2 " Bargent & Lundy: Inc 3839 73/08/02, 1p
- --8010220630 "Key Digram. 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 2371 PT1." * Sargent & Lundy: Inc 3838 80/06/23 1p.
- --8010220636 "Key Digram 480 Volt Auxiliary Bldg Engineered Enfequard Sys Motor Control Ctr 2371 PT2 " * Bargent & Lundy, Inc. 3838. 73/08/02, ip.
- --8010220641 "Key Digram 480 Volt Auxiliary Bldg Engineered Safeguard 84 Motor Control Ctr 2383A PT1 " * Bargent & Lundy, Inc. 3838, 80/06/23, 1p
- 8010300481 Forwards evaluation of control rod guide thimble wear in PMRs. Issue is resolved for 15x15 fuel assemblies designed by Hestinghouse for facility VAROA.8.A. Operating Reactors Branch 1. 80/10/06. 4pp.
- 8010270300 Summary of 800925 meeting w/util & Westinghouse re schedules for facility task action items & reliability study & introduction of new project manager REEVES, E A. Operating Reactors Branch 1. 80/10/09, 4pp
- B010210460 Forwards facility probabilistic risk assessment draft, "Zion 1 & 2 Component Failure & Haint Data Sections B. 1.B 2 & b. 3." per B01006 schedule Requests limited dissemination NAUGHTON, M. F Commonwealth Edison Co B0/10/14 1p.
- --8010210464 Facility probabilistic risk assessment draft, "Zion 1 & 2 Component Failura & Meint Data Bactions B.1.B 2 & B.3." * Pickard Lowe & Garrick, Inc. 80/10/07 76pp.
- B010270345 Forwards responses to NRC B00923 request for add1 info re GA program upgrade review. Info includes extension of GA program to all items affecting safety & involvement of GA organization in operational activities.

 ABEL, J. S Commonwealth Edison Co 90/10/17. 15pp
- BO10280287 Application for amend to Licenses DPR-39 & DPR-48, changing Tech Specs 3 B 7 & 4.8 7 re operability of svc water pumps. Change suppls B00523 request for license amend NAUGHTON.N.F. Commonwealth Edison Co. 80/10/22. 2pp.
- ---8010280273 Proposed changes to Tech Specs 3 8,7 & 4,8,7 re operability of svc water pumps, Change suppls 800523 Tech Spec change.

 # Commonwealth Edison Co. 80/10/22. 2pp,
- 8010310280 Provides add1 info re steam generator J-tube installation. Installation schedule has been reessessed, J-tubes on 10 & 1A steam generators should be installed during next Unit i refueling outage & mods to Unit 2 in 1781 refueling outage. REED.C. Commonwealth Edison Co. 80/10/23 2pp
- 8010310347 Application for amend to Licenses DPR-39 & DPR-48 consisting of changes to Tech Specs.

 NAUQHTON:W F. Commonwealth Edison Co. 80/10/24, 2pp.

- --8010310349 Revised Page 9 to Tech Spec 1 3 for chemical effluent * Commonwealth Edison Co 80/10/24 4pp
- G Inspection reports. IE Bulletins & correspondence
- B010140161 Forwards IE Insp Repts 50-275/80-14 & 50-304/80-14 on B00601-0731 & notice of violation HEIBHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch B0/08/19 2pp
- --B010140144 Notice of violation from insp on 800601-0731
 * Region 3, Chicago, Office of the Director 80/08/18 ip
- --8010140168 lE Insp Repts 50-295/80-14 & 50-304/80-14 on 800601-0731
 Noncompliance noted violation of discharge dilution
 requirements
 XORLERIJ E , BPESSARD.R L , KEY.W J Region 3, Chicago. Office of
 the Director 80/08/18 16pp
- 8010210030 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER.J Q Region 3, Chicago, Office of the Director 80/09/03
- 8010090159 Forwards add1 response to IE Bulletin 79-02, "Pige Support Base Plate Designs Using Concrete Expansion Anchor Bolts"
 Load tests have been performed on concrete expansion anchors on all accessible safety-related piging sys
 JANECEK.R F Commonwealth Edison Co 80/09/05 17pp
- 8010200282 Forwards add1 response to 1E Bulletin 79-02, "Pipe Support Base Plata Designs Using Concrete Expansion Anchor Bolts" Load tests performed on concrete expansion anchors on all accessible safety-related piping sys

 JANECEKIR F. Commonwealth Edison Co 80/09/05 17pp
- B010100241 Responds to B00818 request for add1 info re IE Bulletin 79-14. "Seismic Analysis for As-Built Bafety-Related Piping Sys " List of sys where pipe stress levels excead one-half of ultimate mat1 stress will be provided monthly JANECEK.R.F Commonwealth Edison Co 80/09/19. 2pp
- 8010080600 Responds to IE Bulletin 80-18, "Haint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture "Permanent mod uill be installed on discharge of each centrifugal charging pump RAUBCH, T J Commonwealth Edison Co 80/09/22 8pp
- 8010270472 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coulant During Steam Generator Decontamination " No specific action or response requested KEPPLER, J & Region 3, Chicago, Office of the Director 80/09/25.
- 8010170313 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-14 to 50-304/80-14 HEISHMAN, R.F., Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/26 ip.
- --8010170318 Responds to NRC 800809 ltr re violations noted in IE Insp Repts 50-295/80-14 & 50-304/80-14 Corrective actions changes implemented to consolidate chemistry & operating surveillance & sus operating instructions ABEL. J. B. Commonwealth Edison Co. 80/09/09 2pp
- 8010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30.
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required KEPPLER, J O. Region 3, Chicago, Office of the Director 80/10/02
- 8010270039 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested. KEPPLER, J. O. Region G. Chicago, Office of the Director. 80/10/10.

- S Reportable occurrences, LERs & related correspondence
- B010100412 PNO III-80-109 on 800602, unit shut down to perform mods on control valves of steam generator anubbers Shutdown is estimated to be 24-h KOHLER, JE , BOYD, D C Region 3, Chicago, Office of the Director B0/06/02 2pp
- 8010020478 Forwards LER 80-040/03L-0 GRAESSER, K L Commonwealth Edison Co 80/07/22 1p
- --8010020484 LER 80-040/03L-0 on 800619, during normal operation, topp D overpower/overtemp delta T channel 1T-431 found erratic, initiating alarms & bistable trips Caused by noisy output from low level amplifier 1TM4318 (Hagan Model 18)

 JENKINS, R V Commonwealth Edison Co 80/09/22 ip.
- 8010020532 Forwards LER 80-039/03L-0 ORAESSER, K. L. Commonwealth Edison Co. 80/09/22 ip
- --8010020537 LER 80-039/03L-0 on 800303, during monthly containment isolation valve operability test, Pressurized liquid space sample valve iA0V-8893595 failed to close, placing sys in degraded mode of operation Cause not determined BINGGELI, B Commonwealth Edison Co 80/09/22 ip
- 8010140452 Forwards updated LER 80~024/03X~1 GRAESSER, K. L. Commonwealth Edison Co. 80/10/03 1p
- ---8010140457 Updated LER BO-026/03X-1 on BO0715, during normal operation, pipe tunnel iodine monitor IRT-PRO7B failed low, Caused by natural end of life of photomultiplier tube Part replaced Monitor functionally tested & returned to svc AKER, R E Commonwealth Edison Co. BO/10/03 1p
- 8010140426 Forwards LER 80-041/03L-0 ORAESSER, K. L. Commonwealth Edison Co. 80/10/06 1p
- --8010140431 LER 80-041/03L-0 on 800829, during normal operation, caller erad monitor iRE-0015 could not be completed within 6-month interval Caused by delay in callbr gas delivery Storeroom low limit reviewed Maint was reinstructed AKER, R E Commonwealth Edison Co 80/10/06 ip
- 8010210644 Forwards LER 79-095/03L-0 GRAESBER, K. L. Commonwealth Edison Co. 80/10/10 ip
- --8010210451 LER 79-095/03L-O on 800718.while performing stiel power distribution monitoring sys (APDMS) surveillance w/P250 computer, surveillance frequency exceeded Tech Spec limit by 10 minutes Caused by operator error MERTOGUL.R Commonwealth Edison Co 80/10/10 ip
- ---B010210488 LER 80-042/03L-0. on 800712, area monitor for auxiliary big heating, ventilation & air conditioning filter area found reading erratically & produced periodic alarms. Cause not datermined. Monitor functionally tested & returned to svc AKER, R E Commonwealth Edison Co 80/10/10. 1p
- 8010300346 Notifies that util 791106 response adequately addresses NRC 790921 concerns re inadvertent safety injection during surveillance tests VAROA:8 A Operating Reactors Branch 1 80/10/15. 2pp
- DOCKET 50-296 BROWNS FERRY NUCLEAR PONER STATION, UNIT 3
 F. Security, medical, emergency & fire protection plans
- 8010030396 Forwards info per NRC 800730 request re fire protection replication test program being conducted by Ofc of Nuclear Regulatory Research, Addl info will be submitted by 801015. Package of 59 instrumentation & mechanical drawings encl MILLB.L.M. Tennessee Valley Authority. 80/10/01 250pp.
- ~-8010030397 Fackage of 59 instrumentation & mechanical drawings to 3s recalled at later date for microfilming.

 * Tennesses Valley Authority. 80/10/01 59pp
- 8010210481 Forwards remaining info re response to NRC 800716 request for add1 info re fire protection sys texts & north wall of reactor bldg at facilities Util statement of understanding re test program & 800730 meeting agreements enc!
 MILLB.L M. Tennessee Valley Authority 80/10/15 17pp

Q Adjudicatory correspondence

- BOID030076 Forwards 800919 order revising 800929 order for mod of OLs. in antirety EISENMUT.D Q Division of Licensing 80/09/19 2pp
- --80100300B5 Order revising 800929 order for mod of OLs DPR-33, DPR-52 & OPR-6B, published in 800912 FR. in entirety Info responsive to IE Builetin 79-018 shall be submitted by 801101 Request for hearing will not stay effectiveness of order EISENHUT, D O Division of Licensing 80/09/19 App
- 8010210165 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 STELLO,V Office of Inspection & Enforcement, Office of the Director. 80/10/02 ip
- --8010210179 Order confirming util commitments to implement action re IE Bulletin 80-17 BTELLO.V. Office of Inspection & Enforcement, Office of the Director 80/10/02 7pp

H General correspondence

- 8010280140 Responds to 800818 ltr re B Messer concerns of low level waste incineration Forwards summary of TVA plans & actions re waste mgt NRC has not received TVA application for authorization to incinerate low level waste DERCKG-W-J Office of the Executive Director for Operations 80/10/01 2pp
- J Insurance & indomnity information
- B010150420 Forwards Endorsement 9 to ANI Policy NF-247. Endorsements 34 & 38 to MAELU Policy MF-66 & Endorsement 41 to ANI Policy NF-198 Draft forwarding itrs encl FIELDER, J. Marsh & McLennan, Inc., H & H Nuclear Consultants, Inc. Div. 80/10/08 10pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8008130232 Natice of ACRS Subcommittee on Fluid Dynamics 800819-20 againg in Inglewood, CA to review control rod drive insertion failures at Browns Ferry & scram discharge vol instrumentation failures at Brunswick & Hatch CHILK S J Office of the Secretary of the Commission. 80/07/30, 200
- B010170317 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Scram Bys " STAMPELDBJ ACRS - Advisory Committee on Reactor Bafeguards 80/08/08 ip
- --8010170303 Interim preliminary draft rept to ACRB, "Review of Recent Halfunctions of BWR Scram Sys" & ACRS - Advisory Committee on Reactor Safeguards. GO/08/08. 119ps.
- P Operating license stage documents & correspondence
- 8010020480 Forwards util program for resolving ATMS issue. Mode will be evaluated & implemented to reduce risk. Program can be implemented by 1985 at Browns Ferry, Bequoyah & Matts Bar & by fuel loading at Bellefonts. Hartsville & Phipps Bend. MILLS.L N Tennessee Valley Authority 80/09/17 5pp
- B010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EIEENHUT, D 9 Division of Licensing. 80/09/19 28pp.
- B010080534 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch.Unit 2 regulator sys design Mods should be performed to provide fully redundant Glass IE protection at interface of Monclass IE power supplies & reactor protection sys. IPPOLITO, T. A. Uperating Reactors Branch 2. 80/09/24 3pp
- 8010100423 Confirms 800923 oral approval that leak tests of certain valves need not be performed until prior to entering Mode 2 teapproval of leakage limit of 3 gpm per valve for two valves: FCV-74-1 th FCV-74-2, until 801024.

 TEDESCORE L Assistant Director for Licensing. 80/10/02. 1p.
- B0100903BA Forwards responses to NRC questions re proposed Tech Spec thanges on containment hydrogen monitoring sys. HILLB:L M. Tennessee Valley Authority. B0/10/07. 3pp

- 8010290165 Forwards rept "Interim Equipment & Procedures to Detect Mater in Scram Discharge Vol " Rept supple 800628 memo on potential interaction between scram & control air sys MICHELBON.C Director's Office 80/10/07 ip
- --8010290317 "Interim Equipment & Procedures at Browns Ferry to Detect Water in Boram Discharge Vol " LANIK.O Director's Office 80/09/30 40pp
- 8010210483 Application to amend License DPR-68, consisting of changes to Tech Specs to reflect analyses of rod withdrewal & fuel loading errors documented in facility 800827 Suppl 3 reload licensing submittal Requests approval of change by 801212 MILLS.L M Tennesses Valley Authority 80/10/14. 2pp
- --8010210484 Tech Specs 3 5 & 4 5 re core & containment cooling sys, linear heat generation rate for rod withdrawal & fuel loading s Tennessee Valley Authority 80/10/14 5pp
- 8010200529 Application for proposed Tech Spec changes, amending Licenses DPR-33. DPR-52 t DPR-68 to clarify definition of "cold shutdown" to allow necessary reactor leak check during refueling outage MILLS.L M Tennessee Valley Authority 80/10/16 2pp
- --8010200534 Proposed Tech Spec changes; clarifying definition of "cold shutdown" re reactor leak check during refueling outage.

 # Tennessee Valley Authority 80/10/16 Spp
- 8010220505 Application to amend Licenses DPR-33.DPR-52 & DPR-68, changing Tach Specs re scram discharge vol vent & drain valves in response to NRC 800707 request MILLS,L M Tennessee Valley Authority 80/10/16. 2pp
- --8010220509 Proposed Tech Spacs. Sections 3 0 & 4.0 re acram discharge vol vent & drain valves # Tennessee Valley Authority 80/10/16. 20pp.
- 8010220375 Application for amend to License DPR-68 consisting of changes to Yech Spacs. MILLB.L M Tennessee Valley Authority 80/10/17 Rpp
- --8010220379 Tech Spac 3.79 for auxiliary electrical sys reflecting addition of 480 volt motor generator sets to supply reactor motor operated valve boards 3D & 3E standard Tennessee Valley Authority 80/10/17 App
- B010310333 Forwards response to NRC B01001 ltr re BWR scram sys. Provides basis for continued operation of facilities HILLS, L. M. Tannessee Valley Authority 80/10/27 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Hatls"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/29, ip
- B010020749 Forwards monthly status rept for work related to IE Bulletin 79-14 MILLS.L M Tennessee Valley Authority B0/09/09. 29pp
- 8010090102 Forwards response to IE Bulletin 80-20, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches " None of subj switches found in safety-related applications to date. Investigation continuing.
 MILLS.L.M. Tennesses Valley Authority. 80/07/12. 10pp
- 8010230479 Forwards IE Insp Repts 50-259/80-30,50-260/80-23 & 50-296/80-24 on 800701-31 No noncompilance noted, LEWIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/12 2pp
- ---B0102304B3 IE Insp Repts 50-259/80-30, 50-240/80-23 & 50-294/80-24 on B00701-31 No noncomplience noted Major areas inspected, operational safety ROs reactor trip follows & plant physical protection.

 BULLIVAN, R. F., CHABE, J. W. Region 2, Atlanta, Office of the Director. DANCE H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/09/11 7pp.
- 8010270099 Forwards IE Insp Repts 50-259/80-33, 50-260/80-26, 50-296/80-27 & 50-327/80-32 on 800811-13. No noncompliance noted. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/12. 2pp.

DOCKETED ITEMS

- --B010270107 IE Insp Repts 50-259/B0-33,50-260/B0-26,50-296/B0-27 & 50-327/B0-32 on B00B11-13 No noncompliance noted Major areas inspected:followup on noncompliances re 10CFR21 proceduras BROWNLEE.V L Region 2. Atlanta, Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 50/09/11 3pp
- 80(0150320 Submits add1 response to 18 Bulletin 80-17 re control rod insertion failure Installation of GE ultrasonic sys for water level indication to be completed Dec 1980 MILLS.L.M Tennessee Valley Authority 80/09/19 ip.
- 8010160194 Forwards Suppl 2 to JE Sulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30 is
- 8010210165 Forwards order confirming util commitments to implement action re IE Bulletin 80-17
 BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/02. ip
- --8010210179 Order confirming util commitments to implement action re IE Bulletin BO-17 BTELLO.V. Office of Inspection & Enforcement, Office of the Director. BO/10/02 7pp
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 is
- 8010270066 Forwards IE Info Notice 80-36. "Failure of Steam Cemerator Support Bolting " No specific action or response requested O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/10 to
- 9 Periodic operating reports & related correspondence
- 110150332 Forwards monthly operating repts for Sept 1980
 ARERCROMBIE, H Tennessee Valley Authority, 80/10/10, 1p.
- 8010180335 Monthly operating rapts for Sept 1980 GREEN, D., THOM, T. Tennessee Valley Authority. 80/10/02. 27pp.
- 010140509 Forwards second monthly operating rept for 8ept 1980. ABERCROM81E.H. Tennesses Valley Authority 80/10/10 is
- --8010160511 Second monthly operating rept for Sept 1780 * Tennessee Valley Authority. 80/10/10. 110pp
- 8010210349 Forwards corrected draft data re effluent & waste disposal semiannual rept for 1979, submitted w/RA Hartfield 800919 ltr.Response to 800930 request for addl info enci.
 MILLS.L.M Tennesses Valley Authority. 80/10/16, 17pp.
 - Reportable occurrences, LERs & related correspondence
- 10200636 PNO-II-80-1198 on 800628,76 of 185 centrol rods failed to fully insert dus to accumulation of water in acram discharge col. Extensive investigations & tests failed to identify auts of accumulation of water in discharge vol DANCE.H C r LEWIS,R. C. Region 2, Atlanta, Office of the Director, 30/07/14, 1p
- 0140367 PNO-II-80-136 on 800805, scram discharge vol Water level larm activated on Unit 1 Indicating accumulation of 3 silons in scram discharge vol instrument vol, Cause ballaved a ba condensation in clean radwasts vent header.

 LIAN-C. Region 2, Atlanta: Office of the Director. 80/08/06/9p.
-)9190438 Forwards LER 80-033/03L-0. |ALHOUN:J.R Tennessee Valley Authority 80/09/12. 1p.
- 1009170448 LER 80-033/03L-0: on 800815; during normal operation at steady state power. Unit 28 & 20 RHR heat exchanger radiation alarm was received. Probably caused by leaking gasket due to loose flange nuts resulting from thermal cycling & vibration.

 **Tennessee Valley Authority 80/09/12. 2pp.
- 10050299 Forwards LER 80-036/03L-0. CALHOUN, J. R Tennesses Valley Authority. 80/09/29. 1p.

- --8010060307 LER 80-036/03L-0 on 800915 during surveillance testing discovered diesel generator 3A would not trip to idle speed from loaded condition. Caused by sheared pin on pinion gear used for adjusting Woodward governor. Governor replaced, a Tennessee Valley Authority 80/09/29 2pp
- 80100603t0 Forwards LER 80-037/03L-0 GALHOUN, J R Tennesses Valley Authority 80/09/30 ip
- ---8010050314 LER 80-037/03L-0 on 800909 during normal operation while surveillance testing, hydrogen analyzing sys H2M-76-39 would not calibr to specs Caused by instrument failure Hydrogen analyzing sys will be changed to newly designed sys.

 * Tennessee Valley Authority 80/09/30 2pp.
- 8010140383 Forwards LER 80-038/03L-0 CALHOUN, J R Tennessee Vallay Authority 80/10/06 1p
- --8010140390 LER 80-038/03L-0 on 800907 during surveillance testing/KS// 3-FCV-i-26 closed too fast. Caused by low oil level in hydraulic cylinder. One gallon of oil added & flow control valve adjusted to obtain correct valve speed. * Tennessee Valley Authority 80/10/06 2pp
- 8010150393 Forwards RO re Wheeler Reservoir water temp exceeding Test Bases limit MILLB:L H. Tennessae Valley Authority. 80/10/08 2pp

8

8

9

8(

8(

80

80

80

90

--1

- ---8010190378 Limiting conditions of operations violation rept on 800924, 27. Wheeler Reservoir water temp exceeded Tech Spec limit Caused by thermal monitoring sys error. Unit 3 sys placed on cooling tower Design change requests being prepared.

 * Tennessee Valley Authority 80/10/08, 3pp.
- 8010210682 Forwards LER 80-039/03L-0 GALHGUN, J. R Tennessee Valley Authority 80/10/17 ip
- --8010210489 LER 80-039/03L-0. on 800920, 480-volt 8D Bd 3A normal fastip breaker failed to close on transfer from alternate breaker. Gaused by misalignment of breaker secondary disconnects w/stationary contact on compartment chassis
 * Tennessee Valley Authority 80/10/17 2pp
- DOCKET 50-278 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8010230703 Forwards IR Health Physics Appraisal Rept 80-298/80-07. motice of violation & significant appraisal findings. SEYFRIT.K. V Region 4. Dallas. Office of the Director 80/09/08
- --8010230705 Notice of violation from health physics appraisal on 800505-16 # Region 4: Dallas, Office of the Director. 80/09/03 2pp
- --8010230709 IE Health Physics Appraisal Rept 50-298/80-07 Noncoapiling noted staff qualification not in accordance w/Tach Specs & improper selection of respiratory protection squipment. BAIRDJ B . EVERETTI. J . BORST.F. J. Region 4. Dallas. Office of the Director 80/09/05 46pp.
- O Adjudicatory correspondence
- 9010030090 Forwards B00919 order revising 800829 order for mode of CL in entirety.

 EISENNUT.D.C. Division of Licensing 80/09/19. 2pp.
- --8010030095 Order revising 800919 order for mod of OL DPR-46.publik! in 800911 FR. in entirety Info responsive to IE Bullstin 79-018 shall be submitted by 801101. Request for hearing will not stay effectiveness of order. UCB petitions discharged. EISENHUT. D G. Division of Licensing 80/09/19. App.
- 8010200227 Forwards order confirming util commitments to implement action at facility re IE Bulletin 80-17. "Failure of 75 of 185 Control Rods to Fully Insert During Scram at BMR." STELLOV. Office of Inspection & Enforcement, Office of the Director 80/10/02. 2pp
- --B01020023& Order confirming util commitments to implement action H B Bulletin 80-17, "Failure of 76 of 195 Control Rods to Fully Insert During Scram at BHR." STELLO,V Office of Inspection & Enforcement, Office of the Director. B0/10/02, 7pp.

P Operating license stage documents & correspondence

- 6010220099 Forwards errata sheets amending 800909 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also encl EISEEWAUT.D O Division of Licensing 80/09/19 28pp
- BOSCOB0390 Requests add1 action re NRC 780807 ltr re deficiencies in Hatch Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Monclass IE power supplies & reactor protection sys IPPCLITO.T A Operating Reactors Branch 2 80/09/24 3pp
- E010150376 Submits modified completion schedule resulting from discussions & changes in contractor assistance to effect mod Drywell & torus mods will be completed before 820430 Completion date five months sooner than previous schedule PILANT, J & Nobraska Public Power District B0/10/06 ip
- BO10240431 Forwards request that TMI-2 Lessons Learned radiological Tech Bpecs be medified Submits info required per 800702 request PILANT, J M. Nebraska Public Power District 80/10/15 7pp
- B010200327 Application for amond of License DPR-46, changing Tech Specs 3 3 C.4 3 C & Tables 3 2 C & 4 2 C, in response to IE Bulletin B0-14. "Degradation of BWR Scram Discharge Vol Capability "Class III fee encl PICANT, J H Nebraska Public Power District B0/10/21 3pp
- --B0102803BO Proposed changes to Tech Specs 3 3 C,4 3 C & Tables 3 2.C & 4 2 C re scram discharge vol Vent & drain surveillance & control rod block scram discharge vol limit switches * Nebraska Public Power District B0/10/21 7pp
- 8010280381 Responds to 801001 ltr re screm sys Concurs that mods are required for long term reliability Subgroup formed to develop design & performance criteria for hardware & procedural changes needed to assure sys reliability, PILANI, J M Nebraska Public Power District 80/10/22 3pp
- G Inspection reports, IE Sulletins & correspondence
- 8010160093 Responds to IE Bulletin 80-15 Emergency notification sys phones powered by local telephone company not onsite power Three menhours expended on bulletin PILANT, J H Nebraska Public Power District 80/08/06. 3pp
- 6010280072 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Switches " Control suitches are not in use at facility PILANT, J ft Nebraska Public Power District 80/08/06. 1p
- 8010220249 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by G-E " Mercury-wetted relays are not used at facility PILANT.J M Nebraska Public Power District 80/08/06 1p.
- 8010240323 Bubmits addi response to IE Bulletin 80-17, Buppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR " Two check valves are installed parallel on each header Mods change as-built conditions.
 PICANT, J M Nabraska Public Power District 80/08/11 1p.
- 8010210276 Responds to Items Bi & B2 in IE Bulletin 80-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BBR " Plans to install ultrasonic water level monitoring sys are underway PILART, J H Nebraska Public Power District 80/08/15. 2pp
- --8010210280 Responds to Item A in IE Bulletin 80-17, Suppl i, "Failure of 75 of 185 Control Rods to Fully Insert During Screw at BWR." Analysis & review of as-built scraw discharge vol & associated vent & drain sys is completed FILANT, J M Nebraska Public Power District 80/08/12. 3pp.
- 8010010007 Forwards IE Insp Rept 50-298/80-11 on 800722-26 & 0804-07 & notice of violation MADSEN.O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8010010012 Notice of violation from insp on 800722-26 & 0804-07. * Ragion 4, Dallas, Office of the Director. 80/08/18. 2pp

- --8010010017 IE Insp Rept 50-298/80-it on 800722-26 & 0804-07
 Noncompliance noted failure to control fire doors &
 maintain fire barrier integrity
 SPANOLER.R O Region 4, Dallas, Office of the Director.
 MADSEN.G L , WESTERMAN.T F Region 4, Dallas, Reactor Operations
 Nuclear Support Branch 80/09/18 12pp
- B010230065 Responds to Items 1 & 2 of IE Bulletin 80-17, Buppl 3, "Failure of Control Rods to Insert During Scram at BMR " Procedures implemented to require listed functional tests after each scram event prior to return to power PILANT. J M Nebraska Public Power District 80/08/27 2pp
- 9010200418 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matts"

 BNIEZEK, J H Division of Fuel Facility & Materials Safety, 80/08/29 ip
- 8010300029 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required SEYFRIT, K. V Region 4, Dallas, Office of the Director, 10/09/10 ip.
- 8010240126 Responds to IE Bulletin 80-17. Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Updates status of planned installation of continuous level monitoring of scram discharge vol PILANTIJ M Nebraska Public Power District 80/09/11, 3pp.
- 8010010002 Ack receipt of 800905 itr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-298/80-11 MADSEN.O L Region 4. Dellas, Reactor Operations Nuclear Support Branch 80/09/16 ip
- --8010010006 Responds to NRC 800818 ltr re violations noted in IE Insp. Rept 50-295/80-11 Corrective actions approved fire barrier was installed & maint & use of fire doors will be periodically discussed w/personnel PILANT, J N Nebraska Public Power District, 80/09/05 4pp.
- B010230039 Confirms 800917 telcon agreement re IE Bulletin 80-17, to perform surveillance procedure to monitor residue water on scram discharge vol on shift basis Tests started on shift basis on 800918 LESSOR, L C Nebraska Public Power District 80/09/18 1p
- 8010160117 Forwards Suppl 2 to IE Sulletin 79-01B. "Environ Qualification of Class IE Equipment" No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/09/30
- 8010R00227 Forwards order confirming util commitments to implement action at facility re IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BHR " BTELLD, Unifice of Insertion & Enforcement, Office of the Director 80/10/02 2pp
- --8010200236 Order confirming util commitments to implement action re IE Bulletin 80-17. "Feilure of 76 of 185 Control Rods to Fully Insert During Scram at BKR " STELLO, V Office of Inspection & Enforcement, Office of the Director 80/10/02. 7pp
- 8010270535 Confirms 801008 telcon informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/80-14. SEYFRIT,K. V Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/10/09. 1p.
- --8010270547 Forwards IE Insp Rept 50-298/80-14 on 800915-18 Details withheld (ref 100FR2 790) KELLY, J A. Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/10/10. 2pp
- --8010270551 IE Insp Rept 50-278/80-14 on 800915-18 Noncompliance hoted; security procedures Details withheld (ref 100FR2 770). CALDWELL, R. A., KELLY, J. A. Region 4, Dellas, Office of the Director. 80/10/09. 1p
- BO10280327 Application for amend of License DPR-46, changing Tech Specs 3, 3, C, 4 3 C & Tables 3 2 C & 4, 2 C, in response to IE Bullstin BO-14, "Degradation of BWR Scram Discharge Vol Capability." Class III fee enci PILANT, J, M Nebraska Public Power District. 80/10/21. 3pp.
- R. Periodic operating reports & related correspondence
- 8010140312 Forwards monthly operating rept for Bept 1980. LEGBOR.L.C Nebreska Public Power District. 80/10/03. ip

- --B010140315 Monthly operating rept for Sept 1980
 BALLINGER, P. L. Nebraska Public Power District, 80/10/03 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010070294 Forwards LER 80-033/03L-0, LESSOR, L C Nebreska Public Power District 80/09/08 2pp
- --8010070298 LER 80-033/03L-0 on 800828 during routine surveillance testing, drywell supply inboard isolation valve PC-232MV failed in mid-position Caused by broken operator contact cam cam replaced Damaged cam returned to Limitorque CONVERSE, W.E. Nebraska Public Power District 80/09/08 ip
- 8010070480 Forwards updated LER 80-022/03L-1 LESSOR.L G Nebrasta Public Power District 80/09/12 2pp.
- --B010070491 LER 80-022/03L-0.on 800629 during normal operation while discharging RHR to radwaste inboard throttle isolation valve RHR-HD-57 could not be manually or ramotely operated Caused by seat jamming disc Seat replaced & valve ordered DOAN,P.F Nebraska Public Power District, 80/09/12 2pp
- 8010210633 Forwards LER 80-034/03L-0 LESBOR, L. C Nebraska Public Power District 80/10/01 2pp.
- ---8010210637 LER 80-034/03L-0 on 800708, furing routine insp.4160-volt breaker RRR ID found not capeble of closing automatically. Caused by failure of GE Magna Blast 4160 VAC breaker to charge rendering pump inoperable Suitch replaced. BEDNAR, L.F. Nebraska Public Power District 80/10/01 ip.
- 8010210645 Forwards LER 80-035/03L-0 LESSOR, L C Nebraska Public Power District 80/10/01 2pp.
- --8010210649 LER 80-035/03L-0 on 800917 during surveillance testing, gasket in oil supply to MPCI stop valve actuator failed, causing shutdown of MPCI sys Caused by gasket of improper matl being used observed being used observed being used. Casset replaced w/gasket of proper matl FLANNIGAN, R Nebraske Public Power District 80/10/01 ip
- 8010210708 Forwards updated LER 80-030/03L-1 LE650R.L C Nebrasta Public Power District 80/10/03 2pp
- --8010210717 Updated LER 80-030/03L-1 on 800813 normal surveillance testing of RHR motor operated valves RHR-MG-34E revealed RHR 8 loop suppression gool cooling inboard throttle valve inoperative due to key failure between motor gear & shaft. DOAN.P.F Nebraska Public Power District. 80/10/03 19.
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
 - Security, medical, emergency & fire protection plans
- J05150348 Forwards draft of emergency plan, revising 791206 plan, which was submitted in response to NRC 791010 request FAY, C W Wisconsin Electric Power Co 80/05/07 tp
- ~8005;50353 Preliminary draft of revised emergency plen.
 * Wisconsin Electric Power Co 80/05/30, 300pp.
- 007300440 Forwards emergency plan revised draft.Jul 1980. FAY.C H. Wisconsin Electric Power Co 80/07/25. 1p
- ~8007300444 Emergancy plan preliminary draft
 * Wisconsin Electric Power Co 80/07/31 222pp.
- 010060031 Provides into re-access of NRC & contractor personnel to facility to conduct appraisal of health physics program. Unsite phase scheduled for 800708 Requests that appropriate badges be authorized for personnel listed in Encl I KEPPLERIJ. 9 Region 3, Chicago, Office of the Director. 80/08/21.4pp.
- 09260644 Forwards Revision 13 to emergency plan manual. BURBTEIN B. Wisconsin Electric Power Co. 80/09/23, ip
- 9009260647 Revision 13 to emergency plan manual # Wisconsin Electric Power Co. 80/09/15. Spp.
- 010230133 Ack receipt of 791207 & 800329 ltrs transmitting changes to security plan Changes do not decrease safeguards effectiveness & are consistent w/provisions of 10CFR50.54p. CLARKR.A. Operating Reactors Branch 3. 80/09/26. 2pp.

- 8010210500 Forwards status of fire protection mods per Amenda 39 % 40 to Licenses DPR-24 & DPR-27 Justifications for schedule delays encl BURBIEIN B Wisconsin Electric Power Co 80/10/13 127pp
- 8010240183 Forwards revisions to modified amended security plan Revisions withheld (ref 10CFR2 770) BURBTEIN, 8 Wisconsin Electric Power Co 80/10/21 1p
- @ Adjudicatory correspondence
- 8010060085 Farwards order revising 800829 order for mod of UL1, in smitracty.
 EXECUTION O. Division of Licensing 80/09/19 2pp
- --8010060090 Order revising 800829 order for mod of OLs DPR-24 \$ ff)-2 published in 800911 FR, in entirety. Response to IE Bulletin 79-018 must be filled by 801101 Request for hearing will not stay effectiveness of order UCB petitions discharged EISENHUT, D O Division of Licensing 80/09/19 6pp.
- J Insurance & indemnity information
- 8010280636 Requests Endorsements 52-55 to Policy NF-178 DINITZ, I. Utility Finance Branch (formerly Antitrust & Indeanity) 80/09/24 1p
- 8010040312 Advises that Endorsements 52-55 to NELIA Policy NF-178 virasent to NRC on 770402 & 780206 Copies of 770402 & 780206 transmittals encl DUNDAR-M. J. Wisconsin Electric Power Co. 80/09/30 ip
- --8010060315 Forwards Endorsements 52-55 to NELIA Policy NF-178 & Endorsements 43 & 44 to MAELU Policy MF-53 DUNDAB, W J. Wisconein Electric Power Co 77/06/20 is
- --8010060316 Forwards Endorsements 54 & 55 to NELIA Policy NF-178 & Endorsements 1 to NELIA Binders EB18, EB19, XB18 & XB19 DUNDAS, N J Hisconsin Electric Power Co. 78/02/06, Spp
- P. Operating license stage documents & correspondence
- 8010010045 Approves util response to NRC 791109 ltr re portions of ECS evaluation models dealing w/fuel cladding swelling & incidence of rupture. No further action required CLARK.R.A. Operating Reactors Branch J. 80/09/10
- 8010220099 Forwards errata sheets amending 800905 ltr which previse preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D. O Division of Licensing 80/09/19, 28pp.
- 8010060354 Requests add1 90 days to provide info re adequacy of shifter distribution sys voltages per 800908 ltr. FAY.C.W. Wisconsin Electric Power Co 80/09/26 ip.
- 8010060355 Interim mod to Tech Spec Change Requests 42 & 58 Tech Spec 15.4.5 II B.2 should be revised to delete procedural steps associated w/surveillance testing requirement of spray additive valve.

 BURBIEIN.8 Wisconsin Electric Power Co 80/09/30 3pp
- B010270249 Requests recalculation of boron dilution event for cold shutdown w/RCS drained to helf-pipe level & cold shutdown w/no reactor coolant pumps running Reanalysis & commitment to revise procedures should be completed within 60 days. GLARK.R.A Operating Reactors Branch 1. B0/07/30 3pp.
- 8010280014 Orants 800725 request for interim relief from ASHE Stills XI inservice testing requirements re pump & test valve program Compliance w/existing Tech Specs is required, pending NRC final evaluation. Fr notice enci.

 CLARK, R A. Operating Reactors Branch 3. 80/09/30. 3pp
- --8010280018 Notice of granting of relief from ABME Section XI Institute testing requirements.

 CLARK, R. A. Operating Reactors Branch 3 80/09/30. 2pp
- 8010220151 Advises that error in Westinghouse STS re depth of water it refueling cavity is not applicable to facilities. CLARK.R.A. Operating Reactors Branch 3. 80/10/01. 2pp.
- 8010280572 Partially denies 790918 request that info re agt 4 technical staff capabilities be withheld (ref 100FR2.790). Forwards consultants' listing of util resources, List withheld (ref 100FR2.790).

 CLARK, R. A. Operating Reactors Branch 3. 80/10/06. 3pp.

- 8010240517 Responds to NRC 800611 ltr re proposed Tech Spec changes for all facilities to provide for redundancy in decay heat removal capability Plant specs already address concerns & require no changes BURSTEIN.8 Wisconsin Electric Power Co 80/10/14 3pp
- 4 Inspection reports, IE Bulletins & correspondence
- 8010010859 Forwards IE Insp Repts 50-266/80-12 & 50-301/80-12 on 800630-0730 & notice of violation HEISHKAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/22 2pp
- --8010010860 Notice of violation from insp on 800430-0730 '
 Region 3, Chicago, Office of the Director 80/08/21. ip
- --8010010863 IE Insp Repts 50-266/80-12 & 50-301/80-12 on 800630-0730
 Noncompliance noted failure to properly control protective
 clothing usage & access into controlled area
 HARRICK,R F., GULDEMOND, & O., HAGUE,R L. Region 3, Chicago, Office
 of the Director 80/08/21 9pp
- 8010210043 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescarted access in protected areas KEPPLER, J O. Region 3: Chicago, Office of the Director, 80/09/03
- 8060030521 Forwards 800604 response to IE Bulletin 80-06 w/oath of affirmation not previously submitted FAY.C.W. Wisconsin Electric Power Co 80/09/09, 1p
- 8010080172 Forwards response to IE Builetin 79-018 re environ qualification of Class IE equipment Qualification of number of components could not be documented because of unavailability of equipment qualification records W/o encl BURBTEIN, S. Wisconsin Electric Power Co. 80/09/12 2pp.
- BO10100289 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/80-10 & 50-301/60-10 KEPPLER.J.O Region 3: Chicago. Office of the Director. 80/09/19
- BOID270459 forwards IE Info Notice 80-34, "Doron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested KEPPLER.J O Region J. Chicago. Office of the Director. 80/09/25.
- B010160245 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required KEPPLER, J. G Region 3, Chicago, Office of the Director 80/09/30
- 8010280082 Forwards IE Circular 80-22, "Confirmation of Employee Gwalifications" No written response required, MEPPLER, J. O Region 3, Chicago, Office of the Director 80/10/02 10.
- 8010270036 Forwards IE Info Notice 80-36, "Failure of Steam Generator Buppart Bolting," No specific action or response requested KEPPLER, J @ Region 3, Chicago, Office of the Director 80/10/10, 16.
- R Pariodic operating reports & related correspondence
- BO10150374 Forwards monthly operating repts for Bept 1980. FAY.C. W. Wisconsin Electric Power Co 80/10/08. 1p
- --8010150397 Monthly operating repts for Sept 1980. FAY, C W Wisconsin Electric Power Co 80/10/03. App.
- 3010280401 Forwards computer printent of draft effluent & waste disposed semiannual rept for 1978, per RA Hartfield 801006 ltr. H/e encl FAY.G.W. Hisconsin Electric Power Co. 80/10/22 ip
- 3. Reportable occurrences, LERs & related correspondence
- 1010140381 FNO-III-80-101: on 800521, Region 3 hotling to site was inoparable because microwave link had been redesignated for use in lintup for President Carter trip to State of WA Sys was again operative on 800522.
 SMITH. J. D. , WARNICK, R. F., HEISHMAN, R. F. Region 3, Chicago, Office of the Director. 80/05/22, 1p.

- 8010100406 PNO-III-80-111A on 800609, operator discovered improper electrical lineup where two engineered safety feature huses were tied together improper electrical lineup was established for loss of ac power test on 800502 SMITH. J D . MARNICK.R F . HEIBHMAN.R F Region 5, San Francisco, Office of the Director 80/06/10 ip
- 8010100408 PNO-III-80-111 on 800609, during power operation, operator found improper breaker lineup of main control board Lineup was immediately corrected Licensee is investigating EMITH.J D. WARNICK.R.F. Region 3, Chicago, Office of the Director 80/06/10 1p
- 8010090191 PNO-III-80-114 on 800618, licensee discovered that when routine safeguards logic test was conducted w/one dissel generator out-of-svc.reduction in capability of engineered safety features occurred SMITH.J D . HAQUE.R . HEISHMAN, R F Region 3, Chicago, Office of the Director. 80/06/18 2pp
- 8010090194 PNO-III-80-115 on 800619, licensed discovered that during surveillance test of RMR systapability to provide low head injection is lost if power is lost.

 SMITH.J D , HEISHMAN, R F , WARNICK, R F Region 3, Chicago, Office of the Director 80/06/19 2pp
- 8010070961 Forwards LER 80-008/017-0 FAY, C. W. Wisconsin Electric Power Co. 80/09/26. 1p
- --8010070369 LER 80-008/01T-0 on 800912:following trip from full power, main steam stop valve B failed to close upon receiving close signal Caused by deposit buildup on valve shaft &/or hardening of gland packing FAY.C W. Hisconsin Electric Power Co 80/09/26 Opp
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- B010150390 Advises that Emergency Response TLDs received environ surveys completed & deployment begun. Util will not notify upon deployment completion Refs util 800307 & 0528 ltrs. Affidavit encl
 BRIGHT.R.M. Florida Power Corp. 80/10/07 2pp
- G. Adjudicatory correspondence
- 8010270337 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment.

 EIBENHUT, D 0 Division of Licensing, 80/09/19 2pp.
- --B010270343 Revised order for mod of license requiring timely submission of info previously requested to environ qualification of safety-related electrical equipment EIBENNUT.D 0. Division of Licensing 80/07/19 App
- P Operating license stage documents & correspondence
- 8010090195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 i.3 b, "Instrumentation for Detection of Inadequate Core Cooling " Quidelines re vessel water level must be developed to provide operators what support ROSB, D. F. Division of Systems Integration 80/09/09. 3pp.
- 8010010B14 Expresses apologies for not responding appropriately to 800730 ltr & forwards fee for facility. Revised analysis is unnacessary BRIOHT, R. M. Florida Power Corp. 80/07/16 ip
- 801001005B Forwards Amend 33 to License DPR-72, safety evaluation & notice of issuance & availability
 REID,R W. Operating Reactors Branch 4 80/09/17, 2pp.
- ---B010010104 Amend 33 to License DPR-72 revising Tech Spec requirements for insp of steam generator tubes in areas distinguished by unique operating conditions or physical const REID:R.W Operating Reactors Branch 4 80/09/17 10pp
- --B010010111 Bafety evaluation supporting Amend 33 to License DPR-72.

 * Operating Reactors Branch 4, 80/09/17 3pp.
- --8010010114 Notice of issuance & availabilty of Amend 33 to License DPR-72. REID.R.W. Operating Reactors Branch 4. 80/09/17. 2pp.

- B010220099 Forwards errata sheets amending B00905 itr which provided preliginary clarification of THI action plan requirements Corrected table of implementation schedule also encl EIBENHUT.D O Division of Licensing. 80/09/19. 28pp
- 8010090529 Forwards Amend 34 to license DPR-72, safety evaluation & notice of issuance & availability REID:R.W. Operating Reactors Branch 4. 60/09/24. 2pp
- ---8010090834 Amend 34 to License DPR-72, modifying Tech Specs to delete gower cutoff requirement of Tech Specs 3/4 i 3 S, xenon reactivity for currently authorized power level REID,R H Operating Reactors Branch 4 80/09/24 10pp
- ~~8010090537 Safety evaluation supporting Amend 34 to License DPR-72 * Office of Nuclear Reactor Regulation, Director 80/09/24 2
- --- 8010070540 Notice of issuance & availability of Amend 34 to License DPR-72 REID.A W. Operating Reactors Branch 4 80/09/24, 2pp
- 8010230456 Forwards evaluation of 800904 response to Lessons Learned Task Force Requirement 2 1 3 b re instrumentation for detection of inadequate core cooling. Insufficient affort provided re advance warning of inadequate core cooling. EISENHUT, D O Division of Licensing 80/09/24. 7pp.
- 8010100365 Forwards Amend 35 to License DPR-72, & notice of issuance & availability.
 REID.R W Operating Reactors Branch 4 80/09/27, 2pp.
- --B010100370 Amend 35 to License DPR-72, modifying App B of Tech Specs to revise Definition 1.6 on emergency need for power & to delete Bection 2 1 regarding change in temp across confenser & confenser discharge temp.

 REIO, R W Operating Reactors Branch 4 80/09/29, 9pp.
- -- 9010100372 Notice of Issuance & availability of Amend 35 to License REID:R W Operating Reactors Branch 4 80/09/29 2pp
- 8010150530 Summary of 800904 meeting w/utils, BtW & NUS Corp re proposed upgrade mods to auxiliary feedwater sys Agenda & 800808 memo enci. VISSINO,O 8 Operating Reactors Branch 4 80/09/30 48pp.
- --8010150344 Bubmits analysis & recommendations re plants w/o setemically qualified auxiliary feedwater sys. Betamically induced core mait due to loss of decay heat removal could be as much as aix times more likely than WABH-1400 estimates HATTEON. R. J. Division of Safety Technology. 80/08/09. 22pp.
- 8010210252 Forwards comments re Interim Reliability Evaluation Program Operator procedures should be implemented Initiation of feed & bleed & switchover following LOGA, among other actions: should be stressed, NOVAK.T M Assistant Director for Operating Reactors, 00/09/30
- 8010230589 Summary of 800821 meeting w/BkW reactor owners group re-abnormal transient operating guidelines program. VISSING.9. Operating Reactors Brench 4, 80/09/30, 27pp.
- B010210631 Requests further info before adequately addressing specific constraints on plent operation re Tech Specs on seas redundancy utilized to remove decay heat, Util will submit Tech Specs change within 60 days of receipt of response.

 BRIGHT.R.M Florida Power Corp 80/10/16 2pp.
- O. Inspection reports, IE Bulletins & correspondence
- 1008120223 Forwards Waste Packaging Inep 80-03 on 800227-29, No noncompliance noted. Atlanta, Fuel Facility & Materials Befety Branch, BO/03/20, 2pp.
- -8005120230 Waste Packaging Insp Rept 60-03 on 800227-29. No noncoopliance noted Major areas inspected placarding requirements radiation levels, marking & labeling requirements for packages. POTTER.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/03/17. 7pp.
- 010230067 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matia." No written response required.
 0/REILLY, J. P. Ragion 2. Atlants, Office of the Director. 80/08/29.

- 8010010040 Ack receipt of 800722 ltr informing NRC of steps taten to correct violations noted in IC Insp Rept 50-302/80-23 LEWIG.R.C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 1p
- --8010010047 Forwards IE Insp Rept 50-302/80-23 on 800903-30 Notice of violation & insp details witheld (ref 10CFR2 790), LEMIS/R.C. Region 2. Atlanta, Reactor Operations Nuclear Supply Branch 80/06/27 2pp
- --8010010052 IE Insp Rept 30-302/80-23 on 800505-30 Noncompliance with failure of security guards to search personnel after sounding of weapons alarm Details withhold (ref 100FR2 790) BIETKA: T.F., SMITH.B.W. Region 2. Atlanta, Office of the Direct. MRTIN:R.D. Region 2. Atlanta, Reactor Operations Nuclear Buju-Branch. 80/06/27 10.
- 8010150668 Interim response to IE Bulletin 80-18. Data compilation is analysis for maintaining min flow through centrifugal pumps will be completed on 801010 BRIGHT, R. M. Florida Power Corp. 80/09/22. 2pp
- 9010270494 Forwards IC Info Notice 80-34, "Boron Bilution of Rest!" Coolant During Steam Cenerator Decontamination " No spoilfic action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/41
- 8010060317 Responds to notice of appraisal findings & notice of violation re respiratory protection program. Corrective actions respiratory protection program upgraded & personnel required to carry survey instrument in high radiation areas, HANCOCK, J. A. Florida Power Corp. 80/09/30 9pp.
- 8010160201 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30
- 8010270567 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required.

 O'REILLY, J. P Region 2, Atlanta, Office of the Director 90/10/82
- 8010290048 Forwards IE Info Notice 80-36, "Failure of Steam Centrals: Support Bolting " No specific action or response requests: O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/11
- G010310182 Ack receipt of 801003 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-302/80-30. LEHIG.R G Region 2. Atlanta. Reactor Operations Nuclear Syspet Branch. G0/10/21 19.
- ---B010310107 Responds to NRC 800911 ltr re violations noted in IE laj Rept 80-302/80-30, Corrective actions revision to plant procedure & list of discrepancies is hand carried weekly to bldg svc supervisor HANCOCK, J. A. Florida Power Corp. 80/10/03 3pp.
- --8010310192 Forwards IE Insp Rept 50-302/80-30 on 800811-15 & seller Violation.
 LEHIB.R C Region 2, Atlanta, Reactor Operations Nuclear Suppol Branch. 60/07/11. 2pp.
- --9010310194 Notice of violation from insp on 800811-15.
 * Region 2, Atlanta, Office of the Director. 80/09/10. 2pp
- --8010310177 IE Insp Rept 50-302/80-30 on 800811-15 Nancompliant Aitr failure to translate design inputs into drawings, failure to follow housekeeping procedures & failure to document procedure review. BELIBLE, Q A., FREDRICKBON, P., RUHLMAN, W. A. Region 2: Atlanti. Office of the Director. 80/09/10 26pp
- 8010280569 Submits supplemental response to items of noncompliance noted in IE Insp Rept 50-302/80-25. Procedural revisions made requiring personnel assigned to respiratory program to have baseline whole body count prior to initial assignment. HANGOCK, J. A., PDDLE, D C. Florida Power Corp. 80/10/22 989.
- R. Periodic operating reports & related correspondence
- 8010200405 Forwards monthly operating rept for Bept 1980. BRIGHT,R M. Florida Power Corp. 80/10/14. ip.
- --BOIOR00407 Monthly operating rept for Bept 1980. CULVER, M. W. Florida Power Corp. 80/10/06.

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

- BO10160651 PNG-II-80-129 on 800728 contaminated reactor coolant DIDIONAL PRO-11-BU-127 on BUD-220 contaminated reactor Co-bactflowed through plant nitrogen sys & approx 10 gallons leaked from relief valve in plant tank farm outside restricted area. Licensee declared Class A emergency. CHARTINI, Region 2, Atlanta, Office of the Director 80 80/07/28.
- BOIO210741 Forwards LER 80-040/04L-0. HANCOCK J A Florida Power Corp 80/09/15 ip
- --B010210747 LER 80-040/04L-0 during Aug, samples discovered not taken from test well 4 for Aug Cause attributed to elimination of test well sites dus to canal mod const. Sept sampling will include test well 4.
 HEMANDEZ.V A Florida Power Corp. 80/09/15 2pp.
- BO10060227 Forwards LER 80-037/03L-0. HANCOCK, J. A Florida Power Corp 80/10/01. ip.
- --9010060232 LER 80-037/03L-0 on 800903, during pump operability test, DHV-i10 would not function as required Caused by electrical short in valve operator motor. Motor repaired & reinstalled. HUV-23 control transformer replaced. HERNANDEZ, V. A Florida Power Corp 80/09/26, 2pp.
- BO10070285 Forwards Special Rept 80-1. MANGCKIJ A Florida Power Corp 80/10/01. 1p.
- --8010070270 Special Rept 80-1 on 800715, during Hode 1 power operation, meteorological monitoring instrumentation channels were not restored to operability for more than 7 days. Gaused by const effort which required relocation of cables.
 4 Florida Power Corp. 80/09/26. 1p
- B010200473 Forwards LER 80-039/03L-0 HANCCCK.J.A Florida Pawer Corp. 80/10/14. ip.
- --B010200477 LER B0-039/03L-0 on B00917 auxiliary bldg ventilation exhaust fan Failed Caused by failure of two blades in fan assembly Fan motor was repaired & new fan assembly installed.

 NEUBCHAEFER: E Florida Power Corp. B0/10/06 2pp.
- BO10200479 Forwards LER 80-038/03L-0 HANGCK, J A Florida Power Corp. 80/10/14. 1p.
- --- B010200485 LER B0-038/03L-0. on B00916. during ECCB pump operability test/DHV-111 B decay heat pump discharge throttle valve would not control flow in automatic. Caused by roller nut not angeging actuating cam Roller nut adjusted.
 NEUSCHAEFERIE. Florida Power Corp. B0/10/04. 2pp.
- BO10280397 Special Rept 60-2 on B00923 discovered that fire protections deluge & sprinkler sys test was not completed in required surveillance interval. Caused by misinterpretation. Employee appointed to track & schedule required surveillances. FANCOCK, J. A. Plorids Power Corp. 80/10/16 2pp.
- BOE0280531 Forwards LER 90-040/04L-1. HAMCOCK, J A. Florida Fower Corp 80/10/24. 1p
- --B010280710 LER 80-040/04L-1: on 800807, discovered that samples were not obtained for Aug from Test Hell 4. Caused by elimination of test well sites due to canal mod const. Test Hell 4 Te-stablished on 800806.

 HEINANDY, VA. Florida Power Corp. 80/08/20, 2pp.

J. Operator Examinations

- 3010280370 Submits into re licensed operator training program, in response to NRC 800328 ltm. Increased emphasis on reactor & plant transients currently underway.
 HANGOCK J A Florida Power Corp. 80/09/15. 2pp.
- MCKET 50-304 ZION NUCLEAR POHER STATION, UNIT 2 Security, medical, emergency & fire protection plans
- 3010140253 Forwards add1 info requested in NRC 800324 ltr re fire protection program. Fifty oversite facility & instrumentation drawings encl. to be recalled at future date. NAUOHTUN.N.F. Commanusaith Edison Co. 80/09/GO. 82pp.

O Adjudicatory correspondence

- 8010070017 Decision affirming ABLB resolution on corrosion issue re storage pool mod.LBP-80-7. State of IL position re failure to impose Tech Space, negligant loss of water & failure to properly access makeup water TOMPKINS.B A. Atomic Safety and Licensing Appeal Panel. 80/10/02.
- 8010280585 Notice of appearance in proceedings 8TEPTGE, P.P. Commonwealth Edison Co. 80/10/23 1p.
- 8010270385 Request for hearing re 800717 orders for mod of licenses requiring certain info on environ qualification of safety-related equipment in response to IE Bulletin 77-01B. Urges suspension of effectiveness of orders M/Certificate of Svc. STEPTOE: P P. Commonwealth Edison Co. 80/10/23. Spp.
- P Operating license stage documents & correspondence
- 8010010151 Ack response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VAROALS, A. Operating Reactors Pranch 1 80/09/12. 2pp.
- 8010090281 Forwards info re status of facility action plan items during 800317-0915. Forty licensing actions completed during period & 12 added REEVES.E.A Operating Reactors Branch 1, 80/09/19 4pp.
- 8010220099 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D. Q. Division of Licansing. 80/09/19. 28pp.
- B0100B045B Forwards request for add1 info re GA program re-evaluation. Outstanding items include organizational independence, staffing & qualification requirements & GA involvement in operational activities. Operating Reactors Branch 1. 80/09/23. 9pp.
- 8010090256 Forwards request for add1 info re GA program re-avaluation Items addressed include extension of GA program to all items affecting safety, organizational independence & staffing & qualification requirements, VARQA: S. A. Operating Reactors Branch 1. 80/09/R3. 8pp.
- B010020286 Forwards repts on equipment environ qualification containing list of additions, deletions or significant changes to 800602 rept & revised responses to draft interim technical evaluation rept NAVOHTON, M. F. Commonwealth Edison Co 80/09/24. 2pp.
- --80:0020291 "Equipment Environ Qualification Review Responses to Draft Interim Technical Evaluation Rept for Zion Station-Units 1 & 2."
 - Bargent & Lundy, Inc. 80/09/19. 200pp.
- --8010020298 "Environ Qualification of Class IE Equipment & Addl Equipment Recognized as Essential for Safe Shutdown, Zion Station Units i & 2," Vols 1-3, * Bargent & Lundy, Inc. 80/09/19. 800pp.
- BO10070387 Proposes to combine responses to NRC requests re-based to Tech Specs concerning decay heat removal capability & min lavel of water over irradiated fuel, Combined responses will be submitted by 801031.

 NAUQHTON, M. F. Commonwealth Edison Co 80/09/24. Rpp.
- 8010090552 Notification of 800925 meeting w/util in Chicago, IL to discuss schedules for task action items & reliability study & to introduce new NRC project manager. REEVEG.E. Operating Reactors Branch i. 80/09/24. 2pp.
- 8010100361 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from 800917 meeting. Requests info re which program best fits NRG achedule. LAMKEN, D. C. Commonwealth Edison Co. 80/09/24. 2pp
- 8010230127 Forwards revised resubmittal of facility rapt for review. W/o encl. NERSES, V. Machanical Engineering Branch. 80/09/26. 1p.
- 8010070430 Comments on NRC 800908 itr re "Preliminary Clarification of TMI Action Plan Requirements." Urges NRC to consider weighing each proposed revision against benefit of having stant changes implemented promptly.
 REED, C. Commonwealth Edison Co. 80/10/01. Spp.

- B010070554 Forwards info & drawings re undervoitage protection, in response to Questions 1.2.3.4 & 6 of NRC 800813 ltr. Tech Space changes identified in Questions 5 & 7 being evaluated JAMECEN, R F Commonwealth Edison Co
- 8010150427 Application to amend Licenses DPR-39 & DPR-48 changing App A Tech Bpecs to reflect Hestinghouse BTB requirements Itemization of changes & Class I-II amend fees encl. NAUOHTON: W F Commonwealth Edison Co 80/10/03 79p
- --8010150436 Proposed changes to App A Tech Specs to reflect Westinghouse 878 requirements Deferred & nonapplicable Tech Specs itams w/justification encl * Commonwealth Edison Co. 80/10/03 28pp
- 8010160485 Submits summary of 800925 meeting w/NRC.Comm Ed.PAGNV & Westinghouse in Chicago. IL re schedule for Zion/Indian Point near-site study per SA Varga request Requests NRC concurrence of suggested date for add1 meeting in Dec 1980 NAUGHTON. W F. Commonwealth Edison Co. 80/10/06 5pp
- 8010220550 Forwards addl environ qualification into as followup to preliminary draft response to App D of technical evaluation rapt provided to NRC at 800827 meeting Util will continue to submit into upon availability Oversize drawings and NAUGHTON, H F Commonwealth Edison Co 80/10/06 450pp
- --8010220588 "Single-Line Diagram 4160 & 480 Volt Engineered Safeguard Sargent & Lundy, Inc 3838 79/04/16 ip
- --8010220594 "May Digram 4160 Volt Switchgear Engineered Safeguard Sys Bus 247 & 248." * Sargent & Lundy, Inc. 3838 79/08/02 Ip
- ~8010220597 "Key Digram 4160 Volt Buitchgear Engineered Bafeguard Sys Sargent & Lundy, Inc. 3638. 73/08/02 1p
- 801022040B "Key Digram: 490 Volt Switchgear Engineered Safeguard Sys Bus 239 " * Bargent & Lundy, Inc 3838. 74/07/09 1p.
- --8010220611 "Key Digram 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Cantrol Ctr 2381A " Sargent & Lundy, Inc 3838 73/08/02 tp
- --8010220612 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafeguard 8ys Motor Control Ctr 23818." # Bargent & Lundy, Inc. 3838 74/12/10 1p.
- --8010220615 "Key Digram 480 Volt Crib HSE Engineered Bafeguard Bys Hotor Control Sys 2302 & 2392 " 4 Sargent & Lundy, Inc. 3830 73/08/02. ip.
 - 8010220617 "Key Digram 480 Volt Augiliary Bldg Engineered Bafeguard Bys Motor Control Ctr 23838 " + Bargent & Lundy, Inc 3838 79/04/28. 1p.
 - 8010220619 "Key Digram: 480 Volt Auxiliary Bldg Engineered Bafeguard Sys Hotor Control Ctr 2393A " * Sargent & Lundy, Inc 3836 77/09/16 ip

 - 801022062! "Key Digram: 480 Volt Auxiliary Bldg Engineered Safeguard Sys Hotor Control Ctr 2372" 4 Sargent & Lundy. Inc 9838 73/08/02 (p
 - 8010220622 "Key Digram, 480 Volt Auxiliary Bldg Engineered Bafeguard Bys Motor Control Ctr 23938 " * Sargent & Lundy, Inc. 3838 79/04/16, ip.
 - 8010220625 "Key Digram 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 2391 PT1." * Sargent & Lundy, Inc. 3838. 73/08/02 ip
- -9010220626 "Key Digram 480 Volt Auxiliary Bldg Engineered Bafaguard Sys Motor Control Ctr 2391 PT2 " * Bargent & Lundy, Inc. 3838 73/08/02, ip.
- -8010220630 "Key Digram: 480 Volt Auxiliary Bldg Engineered Safeguard Sys Motor Control Ctr 2371 PT1 " * Sargent & Lundy, Inc. 3838, 80/06/23 ip.
- --8010220636 "Key Digram: 480 Volt Autiliary Bldg Engineered Safeguard Sys Motor Control Ctr 2371 PT2." 4 Sargent & Lundy: Inc. 3838 73/08/02. ip.

- --8010220641 "Key Digram.480 Volt Auxiliary Bldg Engineered Bafagpa's Sys Motor Control Ctr 2383A PT1 " * Sargent & Lundy, Inc. 3838 80/06/23 (p
- 8010300481 Forwards evaluation of control rod guide thimble wear in PKRs Issue is resolved for 15x15 fuel assemblies designed by Hestinghouse for facility VAROA, 8 A Operating Resolves Branch 1 80/10/06, 4pp
- B010270300 Summary of 800925 meeting w/util & Westinghouse re schefilm for facility task action items & reliability study & introduction of new project manager REEVES E A Operating Reactors Branch 1 80/10/09 4pp
- 8010210460 Forwards facility probabilistic risk assessment draft. 'Net 1 & 2 Component Failure & Maint Date, Sections B 1,8 2 & b 3." per 801006 schedule Requests limited dissemination. NAUGHIGN.W.F. Commonwealth Edison Co. 80/10/14 ip.
- --B010210464 Facility probabilistic risk assessment draft. *Zien i & ? Component Failure & Maint Data Sections B 18.2 & B 3 * * Pickard Lowe & Carrick. Inc. B0/10/07 96pp
- 8010290345 Forwards responses to NRC 800923 request for addl into to OA program upgrade review Info includes extension of GA program to all items affecting safety & involvement of OA organization in operational activities

 ABEL, J, B Commonwealth Edison Co 80/10/17. 15pp
- 8010280287 Application for amend to Licenses DPR-37 & DPR-48, then IPg Tech Specs 3 8 7 & 4 8.7 re operability of svc water pumps Change suppls 800529 request for license amend. NAUGHTON. W F Commonwealth Edison Co 80/10/22 2pp
- --8010280293 Proposed changes to Tech Specs 3 8.7 4 4 6 7 re operability of syc water pumps. Change supple 800523 Tech Spec change.

 * Commonwealth Edison Co 80/10/22 Zpp.
- 8010310343 Forwards "Reactor Containment Bldg Integrated Lest Rate Test."

 GRAESSER, K L. Commonwealth Edison Co. 80/10/22 1p.
- -8010310346 "Reactor Containment Bldg Integrated Leak Rate Test * AINGER: K A , MARIANYI.J J Commonwealth Edison Co 80/09/26 50pp
- 8010310280 Provides add1 info re steam generator J-tube instellation Installation schedule has been reassessed J-tubes on 1D & IA steam generators should be installed during next Unit 1 refueling outage & mods to Unit 2 in 1791 refueling outage REED, C. Commonwealth Edison Co 80/10/23. 2pp.
- 8010310347 Application for amend to Licenses BPR-39 & DPR-48 confilly of changes to Tech Specs
 NAUGHYON.H F Commonwealth Edison Co 80/10/24. 299.
- --8010310349 Revised Page 9 to Tech Spec 1.3 for chemical efficient # Commonwealth Edison Co 80/10/24 Spp.
- A Inspection reports, IE Bullstins & correspondence
- 8010140161 Forwards IE Insp Repts 50-275/80-14 & 50-304/80-14 on 800601-0731 & notice of violation. HEISHMAN.R.F Region 3, Chicago, Reactor Operations Nuclear Support parach, 80/08/19, 2pp.
- --8010140164 Notice of violation from insp on 800601-0731 * Region 3. Chicago. Office of the Director 80/08/
- --8010140168 IE Insp Repts S0-295/80-14 & 50-304/80-14 on 800&0[-073] Noncompliance noted: violation of discharge dilution requirements. KOHLER, J. E., SPEBSARD, R. L., KEY, W. J. Region 3, Chicago, Office II the Director 80/08/18, 16pp.
- 8010210030 Provides updated info re admittance of Region 3 personnel Plog10030 Provides updated into re sometement for whom permanent to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring hadge for unsscorted access in protected areas.

 KEPPLER, J O. Region G. Chicago: Office of the Director 80/09/03
- 8010090159 Forwards addl response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Load tests have been performed on concrete expansion anchors on all accessible safety-related piping sys.

 JANECEK.R.F. Commonwealth Edison Cd. 80/09/05. 17pp.

- 8010200282 Forwards addl response to IE Bulletin 79-02. "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts "Load tests performed on concrete expansion anchors on all accessible eafaty-related pipting sys.

 JANECEK.R F Commonwealth Edison Co. 60/09/05 17pp
- 8010010184 Forwards IE Insp Rept 50-304/80-20 on 800820-22 No noncompliance noted HIND, J A Region 3, Chicago, Safeguards Branch 80/09/10 2pp
- --8010010193 IE Insp Rept 50-304/80-20 on 800820-22 No nencompliance noted Major areas inspected facility organization & operation; measurements & inventory control Details withheld tref 10CFR2 790)
 HIND. J.A. Region 3, Chicago, Bafeguards Branch FINLEY, A.G., PATTERSON, J.P. Region 3, Chicago, Office of the Director 80/09/09
- BOIO100241 Responds to BOOBIB request for addl info re IE Bulletin 77-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " List of sys where pipe stress levels acced one-half of ultimate math stress will be provided monthly JANECEK, R f Commonwealth Edison Co BO/09/17 2pp
- 8010080600 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Permanent mod will be installed on discharge of each centrifugal charging pump RAUSCH.T J Commonwealth Edison Co 80/09/22 Spp
- 8010270472 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coalant During Steam Generator Decontamination " No specific action or response requested KEPPLER, J O Region 3. Chicago, Office of the Director 80/09/25
- 8010170313 Ack receipt of 800909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-293/80-14 & 30-304/80-14 MEISHMANR F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/09/26. Ip
- --8010170318 Responds to NRC 800809 ltr re violations noted in IE Insp Repts 50-295/80-14 & 50-304/80-14 Corrective actions changes (mplemented to consolidate chemistry & operating surveillance & sys operating instructions ABEL, J & Commonwealth Edison Co 80/09/09 2pp
- B010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER.J & Region 3, Chicago, Office of the Director 80/09/30
- B0102B0527 Forwards IE Circular B0-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director. B0/10/02 to
- 8010270037 Forwards IE Info Notice 80-36. "Failure of Steam Generator Bupport Bolting " No specific action or response requested KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/10/10
- B Reportable occurrences, LERs & related correspondence
- BOJOGYO197 PND-III-80-139 on 800727.unit resumed operation following 86 day refueling & maint outage.Work included.TMI mod. , turbine overhaul.reactor coolant pump smal replacement & work associated w/humerous IE bulletins.
 SPESSABD.R L . HEISHIAN.R F Region 3. Chicago. Office of the Director 80/07/28. ip
- 3010100422 PND-III-80-147 on 800809, unit was shut down due to loss of main generator stator cooling water. During 800810 startup two reactor trips occurred due to feedwater irregularities Unit remains in hot standby for stator cooling pump repairs. KOM.ER.J. SPESBARD.R.L., HEISHMAN,R.F. Region 3, Chicago, Office of the Director 80/08/ii 1p
- 1010090255 PNG-III-80-166 on 800903 unit tripped from 93% power due to lou steem generator level caused by feedwater pump trip Mater Ammer occurred while steem generator level was below feed ring causing safety injection actuation KOMLER.J.E., SPESBARD.R. L. HEIGHMAN.R F Region 3, Chicago, Office of the Director 80/09/03 2pp.
- 1010210535 Forwards LER 80-024/79X-0.

 CRAESSER, K L Commonweelth Edison Co. 80/10/10. 1p.

- ~~8010210541 LER 80-024/99X-0 on 800723. while putting safaguards back in syc.safety injection was actuated from Train B only Caused by procedural change which confused operator Procedure clarified CLARK, B Commonwealth Edison Co 80/10/10 ip
- B010300346 Notifies that util 791106 response adequately addresses NRC 790921 concerns re inadvertent safety injection during surveillance bests VAROA.8 A Operating Reactors Branch 1 80/10/15 2pp
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- BOIOO30391 Forwards Revision 2 to industrial sabotage security manual Plan withheld (ref 10CFR2 790) MATHEMS.E R Wisconsin Public Service Corp BO/07/30 3pp
- G010270023 Notification of B01020 meeting w/util in Bethesda:MD to discuss physical security licensing considerations for facility Proposed Agenda encl LIGCIARDD:R D Operating Reactors Branch 1 B0/10/07 3pp
- 8010300550 Provides info re access of NRC & contractor personnel to facilities for conducting appraisal of health physics program Onsite phase of appraisal is scheduled to begin 801020 KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/08
- 8010200330 Requests written clarification re protection factors contained in NUREO-0694 w/relation to existing or proposed shielding requirements concerning emergency operations facility criteria Also requests meeting w/NRC MATHEMS, E. R. Historisin Public Service Corp. 80/10/13. 2pp

H General correspondence

- SO10100114 Responds to 800523 ltr re RH Leyse concerns about 800430 news article on NRC approach to emergency planning around nuclear plants Major program of Upgrading state of emergency preparedness ongoing since Summer 1979
 DIRCHS: N J Office of the Executive Director for Operations 80/09/23 2pp
- --8010100118 Requests info re encl news article submitted by RH Leyse on NRC approach to emergency planning around nuclear plants ROTH T House of Rep. 80/05/23 2pp
- J Insurance & indemnity information
- B010280631 Requests Endorsement 31 to Policy MF-71 DINITZ.1 Utility Finance Branch (formerly Antitrust & Indemnity). 80/09/24 ip
- 8010070572 Forwards Endorsement 37 to MAELU Policy MF-71 & advance premium & std premium Endorsement 46 to Policy MF-204.
 MATHEMS.E R Wisconsin Public Service Corp 80/10/01 , 3pp.
- P Operating license stage documents & correspondence
- 8010010041 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability" Util position will remain in effect pending completion of NRC long-term review VARGA-8 A. Operating Reactors Branch 1 80/09/10 2pp
- 80:00:00:0069 Forwards NRC evaluation of control rod guide thimble wear issue in facilities designed by Westinghouse Issue resolved for facility 14:14 fuel assemblies designed by Westinghouse, VAROA, 8 A Operating Reactors Branch 1. 80/09/10 App.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing. 80/09/19 28pp
- B010070410 Informs that requests for revisions to Tech Bracs are currently under consideration Review expected to be completed by B01117. Bubmittal re requests & proposed Tech Bracs should be made with 801124.

 MATHEWS, E. R. Wisconsin Public Service Corp 80/10/01. 1p.

- 8010140328 Forwards response to 800905 telcon re possible causes of measured differences in certain symmetric thimble pairs. Update to Cycle & startup rept, including flux maps will be
 - SCHROCK.C A Wisconsin Public Service Corp 80/10/06 95pp
- 8010200480 Forwards add1 info re 800804 "Kewaunes Plant Cycle VI Startup Rept" power distribution measurements in form of revision to rept Revision includes only Pages 20-37 & table of contents
 MATHEWS, E R Wisconsin Public Service Corp 80/10/14
- --8010200489 Revised "Kewaunee Plant Cycle VI Startup Rept " Includes table of contents ⊅ Pages 20-37 only ≠ Wisconsin Public Service Carp 80/10/08 42pp
- 8010210502 Forwards add1 info re degraded grid voltage protection, per NRC 800905 request Tech Spec revisions requested in Item 4 of Itr are currently under in-plant & corporate ofc review One oversize drawing encl MATHEKS,E R Hisconsin Public Service Corp 80/10/14 App
- ---8010210509 "Integrated Logic Diagram Diesel Cenerator Electric " Sheet Pioneer Service & Engineering Co 80/06/13 1p
- 8010270376 Forwards request for info re containment sumps & insulation, to aid in evaluation performance of containment sumps for operating reactors
 VAROA.S.A Operating Reactors Branch 1 80/10/14 4pp
- 8010210450 Forwards add1 info re auxiliary feedwater sys, in response to NRC 800818 itr MATHEWS, E R Wisconsin Public Service Corp 80/10/17 App
- Q Inspection reports. IE Bulletins & correspondence
- 8010160182 Forwards IE Insp Rept 50-305/80-16 on 800701-03,07-11,14-18, 21-25 & 28-31 No moncompliance noted HIEBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/26 2pp
- --BoloidoiB7 IE Insp Rept 50-309/80-16 on 800701-03.07-11.14-18.21-25, 28-31 No noncompliance noted Major areas inspected operational safety verification monthly surveillance observation & followup on IE bulletins & circulars WARNICK.R F. CHOULES.N C. NELBON.R L. Region 3. Chicago, Office of the Director. B0/08/22 App
- 8010210034 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent monemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER. J G Region 3. Chicago, Office of the Director, 80/09/03 4 D D
- 801003053B Submits response to 1E Bulletin 80-15 re loss of emergency notification sys wilcoss of offsite power Verified that plant has hothline powered from onsite power source MATHEMS.E R Wisconsin Public Service Corp 80/09/11 2pp
- 8010060118 Ack receipt of 800902 ltr re violations noted in IE Insp. Rept 50-305/80-10 80th items were noncompliances & response re corrective actions should be submitted KEPPLER. J 0 Region 3. Chicago. Office of the Director 80/09/19
- --8010060121 Responds to NRC 800807 ltr re violations noted in IE Insp Rept 50-305/80-10 Noncompliance re automatic start of diese) generator should be retracted MATHEWS.E.R Wisconsin Public Service Corp 80/09/02. 2pp
- 8010080635 Responds to IE Bulletin 80-20, "Failures of Hestinghouse Type W-2 Epring Return to Neutral Control Buitches." Containuity check performed on safety-related switches Contact continuity indicator mods to be completed by 801010 MATHEWS.E R Wisconsin Public Service Corp 80/09/19 2pp
- 8010090512 Responds to IE Bulletin 80-18. "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture." Min flow requirements for high head injection pumps addressed FBAR analyses remain valid MATHEMS.E R Wisconsin Public Service Corp 80/09/22 2pp
- 1010090494 Responds to IE Bulletin 80-11, "Masonry Wall Design " Masonry Walls in Class 1 areas are nonload bearing, interior, single width design const Walls are reinforced in horizontal & vertical directions. MATHEMS.E.R Wisconsin Public Service Corp 80/09/23 Spp.

- B010200296 Informs that review of records for IE Bulletin 79-618 equipment qualification has taken longer than expected #fill submit appropriate into by 801010 MATHEMS.E R Wisconsin Public Service Corp 80/09/24 [p
- B010270477 Forwards IE Info Notice 80-34, "Boron Dilution of Reacts: Coolant During Steam Generator Decontamination " No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director 80/07/
- 8010160264 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No written response required KEPPLER. J G Region 3. Chicago. Office of the Director DO/09/30
- 8010280078 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER. J.O. Region 3, Chicago, Office of the Director 80/10/02
- 8010240265 Ack receipt of 800820 itr informing NRC of steps tatem to correct violations noted in IE Insp Rept 80-305/80-15 Hatter remains item of noncompliance KEPFLER.J O Region 3. Chicago. Office of the Director 80/10/03
- --8010240272 Responds to NRC 800728 itr re violations noted in 1E Irm Rept 50-303/80-15 Disputes items of noncompliance MATHENS.E R Wisconsin Public Bervice Corp 80/08/20 200
- B010270037 Forwards IE Info Notice B0~34, "Failure of Steam Consepts: Support Holting " No specific action or response requested KEPPLER, J. G. Region 3, Chicago, Office of the Director B0/10/10
- 8010300216 Forwards addi info in response to IE Bulletin 79-018 "Qualification of Class IE Equipment " All equipment necessary to accident mitigation & maint of stable hot standy condition will operate in intended manner MATHEMS: E R Wisconsin Public Service Corp 80/10/10 80pp
- R Periodic operating reports & related correspondence
- #8010140459 Forwards monthly operating rept for Sept 1980 MATHEWS, E. R. Wisconsin Public Service Corp. 80/10/06
- B Reportable occurrences, LERs & related correspondence
- 8010100288 PND-111-80-105, on 800529, licensee reported crack in lay-ag DN 2 low pressure turbine rotor Westinghouse analysis concuded that crack will not be critical for 5 to 9 yrs Plant is shutdown for refueling & maint CHOULESIN, WARNICK,R F Region 3, Chicago, Office of the Director 80/05/30
- 8010090183 PND-III-80-117 on 800620, during low power physics test-les is team generator level reactor trip occurred due to low level condition On 800621, w/reactor shutdown during cooldown, safety injection signal occurred & B diesel failed to start NELSON, R. L., WARNICK, R. F., HEISHMAN, R. F. Region 3. Chicago Office of the Director 80/06/23 2pp
- 8008250073 Discusses hold down holts on support columns on stead generators found shorter than required by original design Licenses should attempt to remove & replace all boilting w/ thread engagements less than 2 25 inches HERMANN.R A Division of Reactor Operations Inspections 80/07/14.
- --BOOB2500BO PNO-III-80-104 as result of review per NUREO-0577. III. III. hold down bolts on support columns on steam generators IA & IB found shorter than apparently required by original design Evaluation ongoing to determine corrective action. CHOULES. N. C. . WARNICK.R. F. Region 3. Chicago, Office of the Director BOOM CONTROL OF THE PROPERTY OF 80/05/30.
- 8010070287 PND-III-80-156 on 800819, during electrical storm intimates buses 1 & 4 were lost reactor tripped & safety injection & containment isolation were initiated On 800820, electrical fire occurred on bus between reserve auxiliary transformer NEL80N.R.L. WARNICK.R.F. HEISHMAN.R.F. Region 3, Chicago, Office of the Director 80/08/20 Rep.

- 8010090297 PNO-III-80-156 on 800819, reactor tripped & safety injection & containment isolation were automatically initiated Caused by loss of instrument buses 1 & 4 during electrical storm Plant will shut down while faulted buses are repaired NELSON,R L , WARNICK,R F , HEIGHMAN,R F Region 3, Chicago, Office of the Director 80/08/20 2pp
- 801.0070276 PNG-III-80-1564 on 800819, lightning believed to have caused fuses on instrument bus inverters 1 & 4 to blow resulting in automatic reactor shutdown safety injection & containment is quation Inverter fuses replaced & busses returned to svc NELSON.R L. WARNICK.R F. HEISHMAN.R F. Region 3. Chicago, Office of the Director 80/08/21 2pp
- 801.0280446 Farwards LERs 80-032/03L-0 & 80-033/03L-0 & updated LER 80-019/03X-2 HATHERS E R Wisconsin Public Service Corp 80/10/24 ip
- --BO10280543 LER 80-032/03L-0 on 800925 valve plug from RCS loop B bypass valve dislodged & restrictd flow in hot loop of RCS bypass. Caused by failure: through normal user of mechanical connection between valve plug & stem Valve replaced SMCKER.C B Wisconsin Public Service Corp 80/10/24 ip
- --B010280548 LER 80-033/03L-0 on 801001, during startup operations, condensate water storage tank (CBT) level went below Tech Epec Italt. Caused by normal water usage during startup Mateup water sys output increased & tank level normalized BHOKER, C B Wisconsin Public Service Corp 80/10/24 ip
- --90:0280554 Updated LER 80-019/03K-2 on 800611.during surveillance testing shield bldg ventilation syst check damper 88V-10A failed to fully open Caused by instrument drift 88V-10A controller setpoint adjusted NALEPKA.D S Wisconsin Public Service Corp. 80/09/26 1p
- COCKET 50-304 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8010070319 Forwards Revision 2 of "Emergency Preparedness Evacuation Time Estimates," Revision provides evacuation time estimates based on more refined methodology MAYER, L. O. Northern States Power Co. 80/09/26, 1p
- --BO10070316 Revision 2 of "Emergency Preparedness -- Evacuation Time Estimates " -- Northern States Power Co. 80/09/30 18pp
- 8010100262 Requests extension until 810101 to comply w/NRC 790906 fire protection BER Mods will be made to penetration seal upgrade, turbine bldg structural steel coating, alternate shutdown capability & addi fire dampers HAYERLO Northern States Power Co 80/10/03 4pp.
- 8010310355 Forwards "Fire Qualification Test on Retrofit Penetration Seals." in response to NRC 800906 ltr requesting add1 inforaquired by fire protection safety evaluation MAYER.L O Northern States Power Co 80/10/24 2pp.
- --80;0010371 "Fire Gualification Test on Retrofit Penetration Seals " FISH.H D SRI International 80/06/30 116pp.
- 8010G:10456 Forwards Revision 6 to 780328 security plan, incorporating changes in organization, titles, qualifications & training Revision withheld (ref 10cFR2 790), MAYER, L. O. Northern States Power Co. 80/10/28 1p.
- 0. Adjudicatory correspondence
- 80:0160624 Forwards revised 800829 order, correcting refs. Data for which hearing may be requested also revised EIBENNUT, D. Q. Division of Licensing 80/09/19 2pp.
- --BOED160630 Order directing licensee to respond fully & completely to BE Bulletin 79-018 re environ qualification of Class IE equipment, by 301101 EISENHUT, D Q. Division of Licensing 80/09/19. App.
- B010280373 Order dismissing proceeding due to 800724 withdrawal of State of MN Pollution Control Agency 800409 petition to intervens. LAZU.R.H. Atomic Safety and Licensing Board Panel 80/10/24. 4pp

- I Financial information
- 8010280437 Forwards 1979 actual cash flow & 1980 projected cash flow, per requirements of Reg Quide 9 4 W/o Annual Financial Rept 1979
 CARLSON, L. R. Northern States Power Co. 80/10/20 2pp
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D G Division of Licensing 80/09/19 28pp
- BO102B07ii Forwards Task Order 5 requested under NRC 05-B0-251 for metallungical analysis of cracking problem in steam generator support bolting at facility Determination of cause is essential for assessment of generic implications

 JORDAN, E. Division of Reactor Construction Inspection 80/09/24

 Ann
- B010060303 Responds to NRC 800815 request for review of Tech Specs & procedures for possible revisions to assure that exposure of irradiated fuel assemblies & control rods cannot occur during transfer Tech Spec change will be requested MAYER, L O Northern States Power Co 80/09/30 1p
- 8010280388 Forwards request for info re containment sump design & seffect on long-term cooling following LOCA CLARK.R A Operating Reactors Branch 3 80/10/02 Rpp
- 8010140333 Forwards corrected Page 2 to proposed Tech Specs of 800516 license amend request MAYER, L. D. Northern States Power Co. 80/10/08 1p
- --8010140334 Corrected Page 2 to Tech Specs 3 12
 * Northern States Power Co 80/10/08 1p
- O Inspection reports, IE Bulletins & correspondence
- 8010230140 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested to personnel requiring badges for unsecreted access in protected areas.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director, 80/09/03 4pp
- B0100A0117 Submits response to IE Bulletin 80-20 re Westinghouse Type H-2 control switches. About 42 of subj switches are used in safety-related sys Switches are tested monthly & after each use OILBERTS, D E Northern States Power CO 80/09/12 1p
- 8010080651 Responds to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Discusses physical & analytical insp procedures Analytical insp completion schedule: & discrepancy & resolution list encl OILBERTS, D E Northern States Power Co 80/09/18. Spp.
- 8010100375 Ack receipt of 800829 itr informing NRC of steps taken to correct violations noted in IE lnep Repts 50-282/80-08 & 50-306/80-09 KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/23.
- --80101003Bi Responds to NRC 800Bi2 ltr re violations noted in IE Insp Repts 50-282/80-08 & 50-306/80-09 Corrective actions, radiation protection staff will be increased & visual dose rate indicators will replace chippers QILBERT8;D.E. Northern States Power Co. 80/08/29 Spp
- 8010270466 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Cenerator Decontamination " No specific action or response requested KEPPLER, J @ Region 3, Chicago, Office of the Director. 80/09/25, in
- 8010270140 Forwards IE Insp Repts 50-282/80-12 & 50-306/80-12 on 800703 & 0708-07 No noncompliance noted FIDRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8010270144 IE Insp Repts 50-282/80-12 & 50-304/80-12 on 800723 & 0708-07. No noncompliance noted Major areas inspected: 9A/QC program implementing procedures work activities & nondestructive examination data of inservice insp. HARD, K. D. Region 3: Chicago. Office of the Director. DANTELEON, D. H. Region 3: Chicago, Reactor Construction & Engineering Support Branch. 80/07/23 7pp.

- 8010160248 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30
- 8010280643 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/02
- B010220124 Responds to IE Bulletin 80-15 Emergency notification sys has been connected to safeguard power source w/bactup power from battery OILBERTS,D E Northern States Power Co B0/10/03 2pp
- 8010290035 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/10 ip
- R Periodic operating reports & related correspondence
- 8010150497 Forwards monthly operating repts for Sept 1980 MAYER: L D Northern States Power Co 80/10/10 1p
- --B010150502 Monthly operating repts for Bept 1780. HUNSTAD, A A Northern States Power Co. 80/10/01 9pp
- B Reportable occurrences: LERs & related correspondence
- 8010090274 PNO-III-80-170A on 800908, ultrasonic test of Unit 2 bolts attaching column supports to steam generators resulted in 3 of 48 bolts w/defects Licenses has at least 5 of 6 good bolts per column & plans to start up Unit 2, FEIERABEND, C E. LITTLE, H B. HEIERHAMN, R F. Region 3, Chicago, Office of the Director 80/09/08, ip
 - 9200540 Forwards LER 80-026/03L-0 YER, L O Northern States Power Co 80/10/15 ip
 - 10200548 LER 80-026/03L-0 on 800916, while performing fire protection nod work in auxiliary feedwater pump 22, workman accidentally bumped overspeed trip mechanism; tripping valve & making pump inoperable for 15 minutes Caused by personnel error HUNSTAD.A A Northern States Power Go 80/10/15 ip
- .0210492 Forwards LER 80-027/03L-0 HAYER.L O Northern States Power Co 80/10/17 1p
- --8010210705 LER 80-027/03L-0:on 800919, steam flow transmitter 2FF-474 found reading low Caused by zero adjustment shift in Barton Model 384 differential pressure transmitter Transmitter recalibr Transmitters scheduled to be replaced HUNSTAD. A A Northern Btates Power Co 80/10/17 1p
 - TT 50-309 MAINE YANKEE ATOMIC POWER PLANT
 - writy, medical, emergency & fire protection plans
 - NISB Provides Bureau of Civil Emergency Preparedness w/comments to proposed brochures re offsite emergency preparedness concerning facility Documents provide good level of all for education, into & background.

 MES, B K Emergency Preparedness Program Office. BQ/09/16 23pp
 - 10150165 Forwards Bureau of Civil Emergency Preparedness proposed brockures re offsite emergency preparedness info concerning facility Requests comment COTE.L A Haine, State of 80/08/18 19pp
 -)220187 Ack receipt of BOOBIA comments on two proposed emergency 'aparedness informational brockures. Comments were taken sto consideration during NRC review (IMES.B K Emergency Preparedness Program Office. BO/07/16 ip
 - 10220207 Submits comments re two proposed amergency preparedness informational brochures Major objections include inclusion of pronuclear rhetoric & lack of public input Related documentation encl.

 GARRETT, E Q Affiliation Unknown 80/08/19, 35pp.
- 10200342 Forwards summary of completed fire protection requirements. doss stations, fire barrier penetration seals, administrative ontrols & switchgesr room floor penetrations have been completed since 1980 refueling, w/o subsequent NRC review GROCE, R. H. Haine Yankee Atomic Power Co. 80/10/14. 2pp.

- Q Adjudicatory correspondence
- BO10080344 Forwards order revising 800829 order for mod of OL.in antirety, EISERVUT, D 0 Division of Licensing 80/09/19 2pp
- --B0100B034B Order revising B00B29 order for mod of OL published in B00911 FR. in entirety Response to IE Bulletin 79-01B must be filed by B01101 Request for hearing shall not stay effectiveness of order UCS petitions for relief discharged EIBENKUT.D G Division of Licensing B0/09/19 Opp
- B010010646 Notifies that several typographical errors exist in MSC B00611 response to contentions filed by Bensible ME Power re spent fuel Lists corrections to last sentence of MRC position statement following Contention 2 & to conclusion MCGURREN, H J Hearing Branch 1 B0/09/29 2pp
- 8010030474 Status rept per ASLB 800714 order re spent fuel pool compaction Proposed Change 70, Suppl 1 contemplates creation of short-term storage capacity accommodating full core rejection through freestanding rack Certificate of 80c encl DIGNAN, T 0 Maine Yankee Atomic Power Co 80/09/29 4pp
- 80:10150075 Request for order requiring renotice of significantly increased & modified spent fuel pool compaction & storage scheme Certification of Svc encl
 MILLER.D S Sensible Maine Power 80/10/08 2pp
- 8010270449 Requests fulfillment of campaign promises & oath of of: re direction of ME Atty General to intervene in util request for long-term nuclear waste storage site within ME MILLER, D S Miller, D S 80/10/19 ip
- 8010300073 Response in opposition to Sensible ME Power 601008 selict for FR notice of significantly increased & modified spent fuel pool compaction & storage ASLB has no authority to order such renotice Certificate of Svc encl DIONAN, T.O., OADLR K. Haine Yankee Atomic Power Co. DIONAN, T.Q. Ropes & Gray 80/10/24 3pp
- 8010300065 Response in support of Sensible ME Power 801008 requisit that util 800929 amended proposal of significantly increased & modified spent fuel pool compaction & storage be published in FR. Wyroposed FR notice & Certificate of Buc MGOURREN, H J Hearing Branch 3 80/10/28 10pp
- H General correspondence
- 8010020381 Provides info on util high level wasts storage expansion is response to 800730 request re MW Roth concerns Many nuclear facilities found expansion mandatory due to lack of availability of commercial reprocessing or waste storage DIRCHS.W J Office of the Executive Director for Operations 80/09/12 2pp
- 8010200515 Discusses NRC 800902 response to 800609 ltr re plant Boothbay Marbor is on end of 12 mile peninsula In case of accident escape would require travel to within 2 1/2 miles of facility License should not be granted Map encl MILLER, E 8 Affiliation Unknown 80/10/14 2pp
- P Operating license stage documents & correspondence
- 8010220077 Forwards errata sheets amending 800705 ltr which provided proliminary clarification of TMS action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O. Division of Licensing 80/07/17 28pp
- B010060331 Application for amend to License DPR-36, changing Tech Spite & FSAR for increased long-term spent fuel pool storage capacity & use of short-term spent fuel storage rack Bupporting data encl JOHNSON, N P Maine Yankee Atomic Power Co 80/09/29 13pp
- 8010300437 Forwards NRC positions re degraded grid voltage protection Concludes that ME Yankee not in full compliance w/ requirements. Response required within 30 days CLARKeR A. Operating Reactors Branch 3 80/10/02, 3pp
- 8010140204 Application for Proposed Change 79 to License DPR-36, changing Tech Specs Sections 3 3.3.8 % 3 13 re RCS operational components, reactor core energy removal & refueling operations Cless III fee encl
 JUHNBON, W. P Maine Yankee Atomic Power Co 80/10/03 3pp

- -B010140210 Proposed Tech Specs 3 3.3 8 & 3 19 re RCS operational components, reactor core energy removal & refueling operations ns Yankee Atomic Power Co 80/10/03 App
- BO 5 0 240 393 Forwards design info re upgrading of automatic auxiliary freedwater sys initiation circuitry from control to safety grade Includes reason & description for change & design automate auxiliary for the safety for the sa Criteria ORDGE,R H Haine Yankee Atomic Power Go 80/10/17 4pp
- Inspection reports: IE Bulletins & correspondence
- BOI 0100055 Forwards IE Insp Rept 50-309/80-10 on 800707-0806 No roncompliance noted BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/08/22 2pp
- -- E010100059 IE Insp Rept 50-309/80-10 on 800707-0806. No noncompliance noted Major areas inspected shift logs & records, physical security & licensee action on selected previous insp findings LAZARUS,W , SUETLAND,P Region i, Philadelphia, Office of the Director MARTIN.T Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/18 10pp
- BO 10010245 Ack receipt of 800714 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 50-309/80-09 MARTIN-N 0 Region 1. Philadelphia, Safeguards Branch 80/08/27.
- --B010010251 Responds to NRC 800623 ltr re violations noted in IE Insp Rept 50-309/80-08. Corrective actions withheld (ref 1005R2 790) MODDV: DE Maine Yankee Atomic Power Co. 80/07/14 ip
- --B010010297 Forwards IE Insp Rept 90-309/80-08 on 800519-22 & notice of violation Notice of violation withheld (ref 100FR2, 790) MARTIN. N O Region 9, San Francisco, Safeguards Branch, 80/04/23
- --- BO10010264 IE Insp Rept 50-309/80-08 on 800519-22 Noncompliance noted. explosive detector not capable of detecting test source & unlocked access control area door Details withheld (ref HADDEN, W Region i, Philadelphia, Office of the Director DEVLIN, J W Region i, Philadelphia, Bafeguards Branch 80/06/20
- 8010010720 Responds to IE Bulletin 80-20. Wastinghouse Type W-2 control switches are not used.
 MODDY, D. E. Keine Yankse Atomic Power Co. 80/09/04. 1p
- BO1-0270191 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Min flow bypass line remains open in each operation mode to assure min cooling flow MOODY,D E Maine Yankee Atomic Fower Co 80/09/19 2pp
- EOLO270442 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No apacific action or response requested ORIER B H Region i, Fhiladelphia, Office of the Director, BO
- ED10290186 Ack receipt of 800904 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-309780-09 GRIER, B.H. Region 1. Philadelphia: Office of the Director. GO/09/29.
- ---BO10290189 Responds to NRC 800814 ltr re violations noted in IE Insp. Rept 50-309/80-09 Corrective actions operators directed to test emergency diesel generator in opposite train within 2-h of removing secondary pump from svc. MO009Y:D E Maine Yankee Atomic Power Co. 80/09/04. 2pp
- --- GO 10290196 Forwards IE Insp Rept 50-309/80-09 on 800602-0702 & notice of violation BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/14 2pp.
- -- BO10290203 Notice of violation from insp on B00602-0702
 ** Region 1. Philadelphia, Office of the Director 8 80/08/13, 1p
- -- GO E0290209 IE Insp Rept 50-309/80-09 on 800602-0702 Noncompliance noted failure to test redundant safeguards equipment when required.

 LAZARUS: M J , BHETLAND: P. D Region i. Philadelphia. Office of the Director MARTINIT. Y Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 80/08/13. 7pp.

- 8010240141 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER,8 H Region 1, Philadelphia, Office of the Director 80/10/02 ip
- 8010280210 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested
 GRIER, B H Region i, Philadelphia, Office of the Director
 80/10/10 ip
- R Periodic operating reports & related correspondence
- 8010150400 Forwards monthly operating rept for Sept 1980 MDGDY, D E Majne Yankse Atomic Power Co 80/10/10 1
- --8010150402 Monthly operating rept for Sept 1980
 BEERB, F. C. Maine Yankse Atomic Power Co. 80/10/10. 6pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010070218 PNO-1-80-140 negotiations between labor & plant mgt have not produced new contract or extension Current contract expires at midnight & strike is possible. Strike would include reactor operators & other nuclear technicians SMETLAND, P D , MARTIN.T. T. BRUNNER.E. J. Region 1, Philadelphia, Office of the Director 80/09/30. 1p
- B010140437 Forwards LER 80-017/01T-0
 WGBD, E C, Mains Yankes Atomic Power Co 80/10/02 ip.
- --8010140442 LER 80-017/017-1 on 800822, during steady state power, 25,000 gallon blended makeup made to RWST Boron sample indicated concentration of 1.704 ppm 16 ppm below Tech Spec required value of 1.720 ppm Gaused by insufficient sample BRINKLER, J E Maine Yankee Atomic Power Co 80/09/19 2pp
- U Congressional/Executive Correspondence
- GO:00:00:21 Responds to GOOB:2 Itr re possibility of ME electricity consumers paying part of costs for facility decontamination Options for financing decontamination under evaluation DIRCKS, M J Office of the Executive Director for Operations 80/09/29 ip
- --B010100125 Requests comments on possibility of ME electricity consumers paying part of costs for facility decontamination Amend was unanimously adopted by Senate during NRC FYBI authorization, to require NRC/OAD to study util financial viability MITCHELL, Q. J Senate B0/08/12. 1p.
- V. Operator Examinations
- B010270360 Responds to NRC B00731 1tr re min shift crew staffing requirements Benior reactor operator 1 reactor operator training initiated. Licenses will meet interim criteria for shift staffing prior to 820701 deadline
 MODDY, D E Maine Yankee Atomic Power Co 80/10/21 ip
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION: UNIT 2 F Security, medical, emergency & fire protection plans
- 8009150235 Forwards revised emergency plan, in response to NRC questions. LIBRIZZIF P Public Service Electric & Oas Co. of New Jersey 80/09/04. ip
- --8009130341 Revised emergency plan * Public Service Electric & Gas Co. of New Jersey 80/09/05. 300pp.
- B010100193 Forwards revisions to emergency plan, in response to NRC questions on revised emergency plan submitted 800904. LIBRIZZI,F.P. public Service Electric & Gas Co. of New Jersey 80/10/03. 2pp.
- -B010100197 Revised emergency plan. # Public Service Electric & Cas Co. of New Jersey B0/09/30. 48pp.
- B010100264 Forwards emergency plan manual implementation procedures. LIBRIZZI.F P Public Bervice Electric & Qas Co. of New Jersey 80/10/03. 2pp

- --8010100293 Emergancy plan manual implementation procedures. Revision 12 BILVERIO.N T , BTILLKAN, J R Public Bervice Electric & Cas Co of New Jersey 80/08/18 186pp
- 8010310301 Forwards revised emergency plan in response to addi NRC questions & to fulfill commitments made in 800904 revised emergency plan. Correspondence from county & state agencies ent!

 LIBRIZZI-F P. Public Service Electric & Gas Co. of New Jersey 80/10/21 7pp
- --8010310305 Revised emergency plan 4 Public Service Electric & Oas Co. of New Jersey. 80/10/21 15pp
- J. Insurance & indemnity information
- 8010220418 Forwards Endorsements 1 & 2 to NELIA Policy E8-72 CORREA,M A. Karsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 80/10/17 3pp
- P Operating license stage documents & correspondence
- 8010220099 Forwards errets sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule giss enci. EIBEMHUT, D. O Division of Licensing 80/09/19 28pp.
- 8010030015 Approves util 800910 request re baiver of experience requirement for individuals w/o special training to serve as shift technical advisors during 6-menth interim period. MIRAOLIA.F J Licensing Branch 3 80/09/24. 2pp.
- 8010060271 Responds to NRC 800918 request for degraded grid voltage analysis info Analysis was previously performed & submitted on 800303 & 791010 Requested assumption re-start of Nonclass IE motor not valid for analysis LIBRIZZI,F.P. Public Service Electric & Qas Co of New Jersey, 80/09/24. 2pp
- --B010060279 Responds to NRC questions re degraded grid voltage protection at facility. Proposed design for second level of undervoltage & related metl encl. LIBRIZIEF P Public Bervice Electric & Que Co. of New Jersey 80/03/03. 10pp
- --8010060286 Submits analysis of electric power sys per NRC 790808 request Offsite power sys & onsite distribution sys of sufficient capacity & capability to automatically start & operate all safety loads LIBRIZZI, F. Public Bervice Electric & Gas Co. of New Jersey. 79/10/10. 4pp.
 - Di60486 Submits info re leak rate testing of RCS pressure isolation slvss. Includes interim program, long-term program & valve assification
 TTL. R. L. Public Service Electric & Oas Co. of New Jersey, 109/29 2pp
 - \$0516 Forwards add1 info re util 800918 environ qualification aw per NUREO-0588 Encl provides summary listing in terms affety significance for Category 1 1 & 1.2 Items re LOCA in steam line break qualification profiles.

 R.L. Public Service Electric & Oas Co of New Jersey, /O1. 70s.
 - 27 Requests that GA list provided in 800909 submittal be orated into FBAR within 30 days
 D.R.L. Assistant Director for Licensing, 80/10/06. 2pp.
 - 13 Forwards Amend 3 to License DPR-75, safety evaluation & of Issuance & availability. IA.F. J. Licensing Branch 3. 80/10/10, 2pp.
 - vi4 Amend 3 to License DPR-75, deleting requirement for util to ertain tubes in steam generators prior to exceeding er [A.F.J. Licensine Branch 3. 80/10/10. 12mp.
 - 16 Safety evaluation supporting Amend 3 to License DPR-75, "* of Nuclear Reactor Regulation: Director, 80/10/10, 3pp.
 - Notice of issuance & availability of Amend 3 to License
 C. Licensing Branch 3. 80/10/10. 2es.

- 801021038D Responds to NRC 800611 itr re recommended Tach Sper charges under joint NRC/util review re issuance of full power OL for Unit 2. Since no changes will be incorporated into Unit 2 Tech Specs, no amend request required LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/10/15 ip
- 8010290334 Notifies of room change for 801029 sixth quarterly meting w/EPA in Newarth NJ to discuss 315(b) demonstration to program changes are requested one-up program extension Meeting will be held in McCarter Board Room on fourth floor of towar SHISSIAS, JA Public Service Electric to Gas Co. of New Jersey 80/10/23 2pp
- 801030021B "BER, Inservice Testing Program, Salem Nuclear Cenerating BEation Unit 2." Interim rept COOK, T. L., HANEK, J. F. EG&O Idaho, Inc. FIN A-6265 8010300218 80/10/31. 48pp
- Q Inspection reports, IE Bullstins & correspondence
- 8010010603 Ack receipt of 800815 itr informing NRC of steps teken to correct violations noted in 1E Inep Rept 50-272/80-13 & 50-311/80-07 RRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/27. ip
- --B010010609 Responds to NRC 800724 ltr re violations noted in 1E Insp.
 Repts 50-272/80-13 & 50-311/80-07 Corrective actions
 addressed in LER 80-004/03L-0
 BCHNEIDER, F H Public Service Electric & Cas Co of New Jersey
 80/08/13 2pp
- --B010010616 Forwards IE Insp Repts 50-272/80-13 & 50-311/80-09 on BD0601-30 & notice of violation BRUNNER.E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch B0/07/24. 2pp
- --8010010622 Notice of violation from inep on 800601-30
 * Region I, Philadelphia, Office of the Director. 80/07/19 is
- --B010010631 IE Insp Repts 50-272/80-13 & 50-311/80-09 on B00601-30 Noncompliance noted: simultaneous operation of two injection pumps contrary to Tech Bpec 3 3.3 limits KEIMIG.R.R. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch, NORRHOLH.L.J., HILL.W.M. Region 1. Philadelphia, Office of the Director 80/07/18 17pp
- 8010020285 Responds to IE Bulletin 80-15. Emergency notification systems uninterruptible power source. Lighting inverter is emergency power source. Util expended 8 manhours on bulletin. BCHNEIDER, F.M. Public Service Electric & Que Co of New Jersey. 80/08/29 3pp
- 8010230532 Forwards IE Insp Rept 50-311/80-11 on 800490-0802 No noncompliance noted BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 80/09/02 2pp.
- ---B010230539 IE Insp Rept 50-311/80-11 on B00630-0802. No nonempliants
 moted, Major areas inspected startup test program,
 precriticality startup testing & preparation for & conduct
 of initial criticality
 BETTENHAUSENL Region 1, Philadelphia, Office of the Director
 CAPNTON, D. L. Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch. 80/08/29. 9pp
- 8010010826 Responds to IE Bulletin 80-20 Three Hestinghouse Type R-2 central switches are used for each Unit, however, neutral switch contacts are not used 80theEDER, F.M. Public Service Electric & Gas Co. of New Jerssy. 80/09/05. 1p.
- 8010100057 Ack receipt of 800819 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-272/80-14 k 50-311/80-10 BRUNNER,E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/09/12. 1p.
- --B010100061 Responds to NRC 800729 ltr re violations noted in 18 hip Regts 50-272/80-14 & 50-311/80-10, Corrective actions: training group is developing formal means of evaluating operator response on simulator.

 SCHNEIDER: F W. Public Service Electric & Gas Co. of New Jersey 80/08/19. 3pp.
- --8010100065 Forwards IE Insp Repts 50-272/80-14 & 50-311/80-10 on 800618-20 & notice of violation. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/29. 2pp.

1

1

- --8010100069 Notice of violation from insp on 800618-20 • Region 1, Philadelphia, Office of the Director, 80/07/11 ip
- --B010100075 IE Insp Repts 50-272/80-14 & 50-311/80-10 on 800618-20.

 Noncompliance noted failure of operators to review facility design changes & failure to maintain adequate records for requalification program

 BETYEMHAUSER, L. WICOINS, J.T. Region i, Philadelphia, Office of the Director CAPHTON, D.L. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/11 5pp
- 8010300224 Ack receipt of 800603 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-04 & 50-311/80-01 GRIER,8 H Region i, Philadelphia, Office of the Director cover:9 is.
- --8010300241 Forwards IE Insp Rept 50-272/80-04 & 50-311/80-01 on 800128-31,0201,04-07 & 11-13 & notice of violation.
 QRIER:B H. Region i, Philadelphia, Office of the Director 80/05/06 2pp
- --8010300245 Notice of violation from insp on 800128-31,0201,04-07 & 11-13. * Resion 1, Philadelphia: Office of the Director 80/05/04 3pp
- --ED10300253 IE Inep Repts 50-272/80-04 & 50-311/80-01 on 800128-31,0201, 04-07 & 11-13 Noncompilance noted in areas of GA program implementation, GA/GC administration, document/drawing controls & design changes & mods. GREENMAN.E.O., NAPUDA.O., SIMONETTI.O. Region 1, Philadelphia, Office of the Director. 80/05/04, 14pp.
- --8010300275 Forwards IE Insp Rept 50-311/80-01 on 800128-31,0201,04-07 & 11-13 & notice of violation. W/o encl. QRIER.B.H Region i, Philadelphia, Office of the Director. 80/05/06. 2pp
- 801005018B Forwards notice of violation re failure to implement continuous visual surveillance of interface doors in response to 800320 order modifying license Ack receipt of 800414 ltr re corrective actions & civil penalty payment BTELLO. V Office of Inspection & Enforcement, Office of the Director 80/07/23 3pp
- --B010060356 Notice of violation from enforcement meeting on B00418 re corrective actions in response to B00320 order modifying license # Office of Inspection & Enforcement. Office of the Director B0/09/23. ipp
- 8010300640 Advises that util response to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Fumps Following Becondary Side Migh Energy Line Rupture," will be delayed until 800929.

 BCHNEIDER,F.W. Public Bervice Electric & Oas Co of New Jersey. BR/100/23. 10
- 8010270451 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coolent During Steam Generator Decontamination." No specific action or response requested GRIER, B.H. Region i. Philadelphia. Office of the Director 80/09/26. ip
- 8010230200 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture "Pumps will be shutdown if RCS pressure cannot be maintained below 2335 psig.
 BCHNEIDER,F, W. Public Service Electric & Qas Co. of New Jersey.
 BO/09/29. 2pp
- 8010230268 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-272/80-16 & 50-311/80-12 BRUNNERE J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/10/02 1p.
- --8010230276 Responds to NRC 800819 ltr re violations noted in IE Insp Repts 50-272/80-16 & 50-311/80-12, Corrective actions: tags were released & valves were locked open. 801MEDDER, F. W. Public Service Electric & Oas Co. of New Jersey. 80/09/19. 3pp.
- ---9010230283 Forwards IE Imap Repts 50-272/80-16 & 50-311/60-12 on 800701-31 k notice of violation. BRUNNER.E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/19. 2pp

- --B010230294 IE Insp Repts 50-272/B0-16 & 50-311/80-12 on 800701-31.

 Noncompliance noted entry into operating Mode 3 while excaeding Tech Bpsc limiting condition for operation NORRHOLM.L J. HILL,W M Region 1. Philadelphia, Office of the Director KEIMIG-R.R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/09/18 9pp
- 8010240169 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/10/02 ip.
- 8010280223 Forwards IE Info Notice 80-36. "Failure of Bteam Generator Bupport Bolting." No specific action or response requested ORIER.B H Region 1. Philadelphia, Office of the Director, 80/10/10 ip
- R Pariodic operating reports & related correspondence
- 8010200382 Forwards monthly operating rapt for Bept 1980 MIDURA.H.J Public Service Electric & Qas Co of New Jersey 80/10/10 1p.
- --8010200384 Monthly operating rept for Sept 1980
 MILLER,L. K. Public Service Electric & Gas Co. of New Jersey
 80/10/10 5pp.
- S. Reportable occurrences, LERs & related correspondence
- B0100B0368 PNQ-I-80-i10A.on B00725, IBEW strike has been settled & picket lines at corporate ofc have been withdrawn Phone cables will be repaired as soon as picket lines at plant sits are withdrawn BRI008L.. KEIM10, R., BRUNNER, E. J. Region 1, Philadelphia, Office of the Director, B0/07/25. 1p.
- 80100A0219 Forwards LER 80-029/03L-0. LIBRIZZI,F P Public Service Electric & Cas Co of New Jersey 80/09/29 3pp
- --B010060234 LER 80-029/03L-0.on 800830, during cooldown, Channel I pressurizer overpressure protection sys relief valve failed to open Caused by faulty open limit switch on relief valve Bys depressurized & vented Limit switch replaced. RANDOLPH, J M Public Service Electric & Oas Co of New Jersey 80/09/27 1p
- 8010100340 Forwards LER 80-030/03L-0. LIBRIZZI,F.P. Public Service Electric & Gas Co of New Jersey 80/10/06. 3pp
- --B01010034B LER B0-030/03L-0; on B00907, during cold shutdown, both safety injection pumps were made operable at same time. Caused by supervisor error. Bupervisor counseled.

 RANDDLPH.J.M Public Bervice Electric & Oas Co of New Jersey.
 B0/10/06 lp.
- V Operator Examinations
- BOI0160510 Submits supplemental info re degraded core training per NRC BOOPSE request Training will be provided for licensed senior reactor operators, reactor operators, shift technical advisors & emergency duty officers, MITTL, R.L. Public Service Electric & Oas Co. of New Jersey BO/10/06. 1p.
- DDCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
 F. Security, medical, emergency & fire protection plane
- B010210290 Notification of B01009 meeting w/util in Bilver Bpring.MD to discuss security plan related info, GARNER,D J. Operating Reactors Branch 4 B0/09/24, ip.
- 8010070187 Forwards revised guard training & qualification plant incorporating comments in NRC 800826 ltr.Plan withheld (ref 10CFR2.790). MATIMOR.J.J Bacramento Municipal Utility District, 80/10/01. ip.
- B01014046B Requests add1 clarification re NRC role at various emergency facilities. Includes function description of role each NRC member is to perform at Technical Bupport Ctr & how each is to respond to util nuclear operations mgt. MATTIMOE, J. J. Sacramento Municipal Utility District. B0/10/02 2pp.

- 8010140473 Requests NRC position on emergency operations facility habitability criteria per NUREO-0696 requiring ventilation sys w/HEPA & charcoal filters Facility location reduces possibility of exposures in excess of criteria Graphs encl MATTIMOE. J J Sacramento Municipal Utility District B0/10/02
- 8010160581 Requests clarification of proposed Revision 2 to Reg Guide 197 requirements for placement of offsite real time radiation monitors MATTIMDELU J Bacramento Municipal Utility District 80/10/02 ip
- B010270260 Advises that review of emergency plan indicates addl info & revision are required within 30 days
 REID.R W. Operating Reactors Branch 4, B0/10/10 Jpp

G Adjudicatory correspondence

- 8010270282 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENMUT, D 0 Division of Licensing 80/09/19 2pp
- ~-8010270287 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EJSENHUT.D O Division of Licensing 80/09/19 App
- P Operating license stage documents & correspondence
- M01007D195 Reaffirms NRC position re YMI Lessons Learned short-term requirement 2 i.3 h, "Instrumentation for Detection of Inadequate Core Cooling " Guidelines revessel water level must be developed to provide operators u/max support RDSS,D F Division of Systems Integration 80/09/09 3pp
- B010010570 Forwards fee for application for proposed Amend 71 to License DPR-54 MATTINGE, J. J. Bacramento Municipal Utility District 80/09/11 2pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing 80/09/19 28pp
- B010010567 Forwards fee required for proposed Amend 70 to License DPR-54
 MATIMOE, J J Sacramento Municipal Utility District 80/09/22.
- Ol0230425 Forwards evaluation of 800828 response to Lessons Learned Task Force Requirement 2 i 3.6 re instrumentation for detection of inadequate core cooling Insufficient effort provided re advance warning of inadequate core cooling EISENHUT, D. 0 Division of Licensing 80/09/24 8pp
- 010220225 Forwards request for add1 info re adequacy of onsite electric power distribution sys REID,R N Operating Reactors Branch 4 80/09/25 3pp
-)10220400 Forwards questions re proposed Amend 68 to Tech Specs. REID,R.W Operating Reactors Branch 4 80/09/25 4pp
- 010140157 Responds to 800128 ltr re proposed reactor cavity annual seal plate storage Relocation to storage area remote from differential pressures generated within reactor cavity following postulated LOCA is acceptable REID,R.W Operating Reactors Branch 4 80/09/29 3pp
- 80)0150530 Summary of 800904 meeting w/utils, BLW & NUS Corp re proposed upgrade mods to auxiliary feedwater sys. Agenda & 800808 memo encl
 VIBSING.0 S. Operating Reactors Branch 4 80/09/30 48pp.
- 80102305B9 Summary of 800B21 meeting w/88N reactor owners group re abnormal transient operating guidelines program VISSING.O. Operating Reactors Branch 4 80/09/30 29pp
- 8010160480 Ack receipt of NRC 800815 ltr NRC determination that present failure mode of atmospheric dump valves following failure of integrated control sys is correct Problem will be corrected w/auxiliary feedwater sys upgrade per 800904 presentation MATTIMOE, J. J. Sacramento Municipal Utility District 80/10/06. 1p.

- BO10150426 Responds to NRC B00924 request for review of data re radioactive math released in 1978 Corrected data encl Cites rept format inconsistency & inadequate method of providing average beta & gamma energies in calculating restrictions MATTIMOE, J J Sacramento Municipal Utility District 90/10/07
- --8010150433 Forwards draft data re radioactive releases in 1978 a requests review by 801008 Final rept re releases from plants in 1978 per Reg Ouide 1 21 reporting criteria will be sent Util corrected data and HARTFIELD,R A Licensee Operators Evaluation Branch 80/07/26
- 8010170445 Application for Amend 72 of License DPR-94, changing Tech Specs Sections 3 0.4 0 & 6.0 re emergency power supply, valve position indication instrumentation for inadequate core cooling & containment isolation class III fee enci MATTIMOE, J J Sacramento Municipal Utility District 80/19/08 2nd
- --8010170531 Proposed Amend 72 changing Tech Spacs Sections 3 0.4 0 % 6 0 re emergency power supply requirements valve position indicating instrumentation for inadequate core cooling, containment isolation 6 auxilary feedwater sys * Sacramento Municipal Utility District 80/10/08 23pp
- 8010200527 Gomments on NRC 800905 itr clarifying TMI action plan requirements & providing implementation schedule More organized design approach to requirements should be taken w/some flexibility in final clarification MATTIMDE, J J Bacramento Municipal Utility District 80/10/09
- QD10280426 Responds to NRC 800410 request for amend re proper definition of term operable Discusses Tech Specs 3 3 2, specifically written to prevent safety sys single Pailure criteria MATTIMOE, J J Sacramento Municipal Utility District 80/10/20
- 8010280497 Forwards response to NRC 800223 & 1023 requests for results of thermal heatup tests from cold shutdown to verify proper integrity of valve internals Zero leakage through boundary valves indicated
 MATTIKOE, J J Sacramento Municipal Utility District 80/10/24
 2an
- Q. Inspection reports, IE Bulletins & correspondence
- 8010230184 Responds to IE Bulletin 80~19, Revision 1, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by G-E " Specified relays are not used at facility HALBRIDGE, W C Sacrementa Municipal Utility District, 80/08/27 in
- 8010300690 Suppls 800725 response to IE Sulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Transmitter function at facility is not safety-related WALBRIDDE, W C Bacramento Municipal Utility District 80/08/28 200
- 8010170045 Forwards supplemental IE Insp Rept 50-312/80-15 on 800414-18,21-25 & 0505-08 STELLO,V. Office of Inspection & Enforcement, Office of the Director. 80/09/03 4pp
- --8010170050 Supplemental IE Insp Rept 50-312/80-15 on 800414-18:21-25 L 0505-08 Major areas inspected licensee mgt controls in eleven areas App A withheld (ref 10CFR2 790) ODDY, A T. Region 1, Philadelphia, Defice of the Director HINCKLEY, D O Region 2, Atlanta, Office of the Director HUNTER, D R Region 3, Chicago, Office of the Director 790s
- 8010290398 Forwards IE Circular 80-21, "Regulation of Refusling Cress": No written response required ENGELKEN,R. H. Region 5, San Francisco, Office of the Director 30/09/10 1p
- 8010080292 Informs that licensee unable to meet 60-day response requirement to IE Bullentin 80-18 Requests Figure 1 of Attachment B to complete required calculations Response will be submitted by 801030
 BOSBENMAIER.W Secremento Municipal Utility District 80/09/11 in

77

- 8010080373 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review revealed total of four switches in safety-related applications BDSSENMAIER, W Sacramento Municipal Utility District 80/09/15
 - BÖSSENMAIER,W Sacramento Municipal Utility District 80/09/15 Zon
- 8010090185 Act receipt of 800806 & 0903 ltrs informing NRC of corrective actions taken in response to NRC 800716 ltr re insp findings CREMS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/22 ip
- --B01009D187 Forwards deferred response to notices of violation & deviation discussed in NRC 800716 ltr Corrective actions const of bldg housing planned-records mgt say underway & 2-ur periodic review of procedures to be updated MATTIMDE, J. J. Sacramento Municipal Utility District 80/09/03 &pp
- --8010090190 Forwards response to notices of violation & deviation discussed in NRC 800716 ltm Corrective actions technical assistant staff increased to prevent recurrence of review oversight & required audits to be performed HALBRIDGE, N C Bacramento Municipal Utility District 80/08/06 1909
- 80:016:0076 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No written response required EKSELKETAR H Region 5. San Francisco, Office of the Director 80/09/29. 1p
- 8010150060 Ack receipt of 800916 ltr informing NRC of steps taken to correct deviations noted in IE Insp Rept 80-312/80-21 CREMS, J. L. Region J. Ban Francisco, Reactor Operations Nuclear Bupport Branch 80/10/01 ip
- --Boioi300A4 Responds to NRC 800B14 ltr re deviations noted in IE Insp Rept 50-312/80-21 Corrective actions improper overtime training will terminate when sufficient operations personnel have been licensed. BOSSENMAIER. H Bacramento Municipal Utility District 80/09/14 22p
- ---8010130070 Forwards IE Insp Rept 50-312/80-21 on 800707-11 & notice of deviation GREWS, J. L. Region 5, Ban Francisco, Reactor Operations Nuclear Bupport Branch 80/08/14 2pp
- --8010150073 Notice of deviation from insp on 800707-11 * Region 5. San Francisco, Office of the Director 80/08/07 ip
- --8010150079 IE Insp Rept 50-312/80-21 on 800707-11. Noncompliance noted full strength shift crews not maintained during 1979 resulting in training procedures not being properly conductive to learning.

 FAULKENBERRY, B. Region 5. San Francisco, Reactor Operations Nuclear Support Branch ZWETZIO, G. B. Region 5. San Francisco, Office of the Director 80/08/07 Spp
- B010280031 Forwards IE Circular B0-22, "Confirmation of Employee Qualifications " No written response required EMBELKEN,R H Region 5: San Francisco, Office of the Director B0/10/02 ip
- B0102i044B Responds to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys " Accessible portion of line re stress problem 60A,B & C inspected & no discrepancy W/selamic analysis found Revised summary sheet encl MATTIKUE,J J Bacramento Hunicipal Utility District 80/10/10 Jpp
- 8010300019 Ack receipt of 801001 ltr informing NRC of steps taken to correct violations moted in LE Insp Rept 50-312/80-24. CREMS, J L Region 3, Ban Francisco, Reactor Operations Nuclear Support Branch 80/10/14. ip.
- --8010300017 Responds NRC 800912 ltr re violations noted in IE Insp Rept 30-312/80-24 Corrective actions: recruiting personnel to perform audits of facility activities. KATTIMOE, J. J Bacramento Municipal Utility District. 80/10/01. 2pp
- ~-8010300019 Forwards IE Insp Rept 50-312/80-24 on 800818-22, notice of violation & notice of deviation CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/12 2pp.
- --E010300021 Notice of violation from insp on 800818-22.
 * Region 5: San Francisco: Office of the Director. 80/09/11. ip.

- --8010300022 Notice of deviation from insp on 800818-22 * Region 5, San Francisco, Office of the Director 80/09/11 ip
- --8010300024 IE insp Rept 50-312/80-24 on 800818-22 Noncompliance noted failure to audit conformance w/certain Tech Spec requirements & failure to review audit repts at scheduled meeting in timely manner ZWETZIG.0 B Region 5. San Francisco, Office of the Director FAULKHOBERRY, B Region 9. San Francisco, Reactor Operations Nuclear Support Branch 80/09/11 8pp
- R Periodic operating reports & related correspondence
- 8010150294 Forwards monthly operating rapt for Sept 1980 RDDRIGUEZ,R J Sacramento Municipal Utility District 80/10/03
- --8010150278 Monthly operating rept for Sept 1780 HOLLINOSWORTH Sacramento Municipal Utility District 80/10/03
- 8 Reportable occurrences, LERs & related correspondence
- 9010090153 PNO-V-90-045 on 800813.licensee informed resident inspector of problems w/mein turbine thrust bearing trip sys Plant has been in cold shutdown ½ length of shutdown is unknown FAULKENBERRY.B , ZWETZIG.O B Region 5. San Francisco, Office of the Director. 80/08/14 ip
- 8010040300 Forwards LER 80-041/03L-0 MATTIMOE.J J Sacramento Municipal Utility District 80/09/22 20p
- ---8010060306 LER 80-041/03L-0 on 800823 diesel generator 8 did not achieve rated voltage of 4,160 volts Caused by voltage regulator Unit was reset & successfully tested COLOMSO,R.W Sacramento Municipal Utility District 80/09/22 ip
- B010220035 Responds to 800715 memo re limiting conditions for operation for Class IE vital instrument buses Limiting conditions should be applied to reactors which do not address loss of Class IE 120 VAC vital instrument buses
 BENION.H R Office of Nuclear Reactor Regulation, Director 80/09/29 ip
- --B010220039 Advises that NRC review re Rancho Beco LER B0-028/01T-0 & R0 287/80-B found lack of operational restrictions for Class IE vital instrument buses Requirements of limiting conditions for operation recommended MICHELSON, C. Director's Office 80/07/19 ip
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8010010963 Notifies that 801001 scheduled completion data for tests will not be met due to delay in NRC review of util proposed fire test criteria
 TRIMBLE D C Arkansas Power & Light Co 80/09/23 1p.
- B010070510 Requests extension until 801101 for implementation of fire protection safety evaluation Items 3 2,3.16,3 5,3 7,3.11, 3 12,3 14 % 3 18 will not be complete by 801001 TRIMBLE.D C Arkansas Power & Light CO B0/09/26 3pp
- 8010070293 Notifies that security sys has been operable since 801001 TRIMBLE.D.G Arkenses Power & Light Co 80/10/01 1p
- 8010080331 Submits response to fire protection safety evaluation Item 3 16 re fires degrading safe shutdown sys through associated circuits. Anticipated failure modes of associated Class IE circuits will not degrade safe shutdown sys open-ability.

 TRIMBLE.D C. Arkaness Power & Light Co 80/10/02 2pp
- 8010280644 Responds to fire protection safety evaluation Item 3 2 Proposed configuration of marinite board fire barriers to be installed in manholes enci Redundant syc water pump cables will be wrapped w/thermal barrier tape TRIMBLE.D C Arkansas Power & Light Co 80/10/21 8pp.
- --8010280648 Revision A to "Electrical Hire & Cable Isolation Barrier Matls Test for Susquehanna Steam Electric Station, Units 1 & 2 for Bechtel Power Corp."

 ALBA: A . BURROHB: A . SHIPHAY. O. Hyle Laboratories. 80/07/28 200pp

O Adjudicatory correspondence

- BO10270207 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENHUT, D G Division of Licensing 80/09/19 2pp
- --B010270212 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment SISENHUT, D O Division of Licensing 80/09/19. App
- 8010280472 Requests 1-wk extension of time to request hearing on 800919 orders to respond to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment " imminent issuance of Suppl 3 to subj builetin may resolve util concerns REYNOLDS.N S Debevoise & Liberman 80/10/23 2pp
- 8050310432 Notifies of util withdrawal of 801023 request for extension to petition for hearing on orders for mod of facility licenses re environ qualification of Class IE equipment IE 8011eth 79-018.80ppl 3 revises requirements of orders REYROLDS.N S Bebevoise & Liberman 80/10/30 ip.
- P Operating license stage documents & correspondence
- 8010090195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 i 3 b. "Instrumentation for Detection of Inadequate Core Cooling " Ouldelines re vessel water level must be developed to provide operators w/max support ROSS.D F Division of Systems Integration 80/09/09 3pp
- 8010220099 Forwards errata sheets amending 800909 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGERHUT, D O Division of Licensing 80/09/19 28pp
- B010230447 Forwards evaluation of 800826 response to Lessons Learned Task Force Requirement 2 i 3 b re instrumentation for detection of inadequate core cooling Insufficient effort provided re advance warning of inadequate core cooling EISENHUT.D 0 Division of Licensing 80/09/24 7pp
- 3010070280 Advises that plant procedures re waste gas sys hydrogen dioxide limits have been modified Haste gas sys will be returned to Region A within 24-h upon entry into Region D. Modified Tech Specs will be submitted by 801031
 TRIMBLE, D C Arkansas Power & Light Co 80/09/26 3pp
- 801007030B Forwards request for Tech Back change to reflect personnel reorganization Fee encl CAYANAUCH, W. Arkansas Power & Light Co. 80/07/29 2pp
- --B010070310 Proposed Tech Specs, Eection 6, reflecting personnel reorganization 4 Artaness Power & Light Co 80/09/29 25pp.
- 010150530 Bummary of 800904 meeting w/utils, B&W & NUB Corp re proposed upgrade mods to auxiliary feedwater sys. Agenda & 800808 memo enc!
 VISSING. 0 6 Operating Reactors Branch 4 80/09/30 48pp
- -8010150544 Submits analysis & recommendations re plants w/o seismically qualified auxiliary feedwater sys Seismically induced core melt due to loss of decay heat removal could be as much as six times more likely than MARH-1400 estimates
 MATISON,R J Division of Safety Technology 80/08/08 22pp.
- 3010230389 Summary of 800821 meeting w/88W reactor owners group re abnormal transient operating guidelines program VISSING.O. Operating Reactors Branch 4 80/09/30 29pp
- SOLUZIO454 Comments on new TMS action plan requirements Use of Reg Ouide 1 77. Revision 2: as basis of design requirements for instrumentation is inappropriate, TRIMBLE, D.C. Arkensas Power & Light Co 80/10/07 8pp
- 8010170512 Corrects util 800926 ltr re waste gas sys hydrogen/oxygen limits Corrected limits are 66.5% of relief valve setting for Units I & 2 TRIMBLED C Arkansas Power & Light Co 80/10/08. ip
- 8010280488 Requests fee remittance within 15 days re proposed Tech Baec changes for facility diverse reactor bldg isolation MILLER, W. O. License Fee Management Branch 80/10/09, ip.

- 8010200443 Forwards preliminary feedwater sys upgrade design into re NUREG-0978 Basic design concept was explained in 800904 meeting w/NRC Requests review of encl proposal by 801205 Drawings in Central Files Aperture cards in PDR TRIMBLE, D C Arkansas Power & Light, Co 80/10/15 24pp
- 8010220477 Responds to NRC questions re util 800927 reorganization Teck Spec change request Functions of operations assessment superintendent plant controller, special projects & health physics consultant outlined TRIMBLE, D C Arkansas Power & Light Co 80/10/16 4pp
- 8010280331 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment for next 2 yrs Util review underway in response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "TRIMBLE, D C Arkaneas Power & Light Cp 80/10/16 2pp
- B010290337 Forwards Class 3 amend fee in response to NRC B00814 & 1609 1 tes TRIMBLE, D C Arkansas Power & Light Co 80/10/20 1p
- --B010270337 Requests processing of util 801020 itr w/fee DIGOB, R M License Fee Management Branch 80/10/27 Lp
- B0103102R6 Responds to Tech Spec changes proposed by Revision 3 to NUREO-0103 & Revision 1 to NUREO-0202 re administrative controls. Forwards proposed Tech Specs & Class III & I amend request per 10CFR170 22 CAVANAUGH. W Arkensas Fower & Light Co 80/10/20 4pp
- --8010310274 Proposed changes to Tech Specs 6 11 1 & 6 11 2 for Unit 11 6 12 1 & 6 12 2 for Unit 2, implementing stricter administrative controls in high radiation areas.

 4 Arkansas Power & Light Co 80/10/20 2pp
- 8010240396 Forwards BAW-1623, "Control Rod Guide Tube Wear Heasureman Program," in response to NRC 780713 & 791123 requests TRIMBLE, D C Arkansas Power & Light Co 80/10/21 \$p
- 8010310394 Responds to NRC info request on RCS pressure isolation that is valves Submits dates of last visual internal insp & individual hydrostatic test & next plant outage TRIMBLE, D.C. Arkanses Fower & Light Co. 80/10/24, 2pp
- 8010310345 Informs of implementation plans re NURE9-0578 Category 8 requirements Unit 2 presently meets Category 8 requirements for Items 2 1 5,2 1 7 & 2 1 7 b Status of other items encl TRIMBLE, D C Arkensas Power & Light Co 80/10/27 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8010160712 Responds to IE Bulletin 80-16 Transmitters installed at facility do not have output codes affected by bulletin, TRIMBLE,D C Arkansas Power & Light Co. 80/07/31 3pp.
- B010210246 Notifies that complete response to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies," wil be provided by B00818, upon receipt of hydramotor actuator info from ITT TRIMBLE, D C Arkansas Power & Light Go. B0/07/31 lp.
- 8010200621 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls "
 SNIEZEK, J H Division of Fuel Facility & Materials Safety 80/08/29 in
- 8010240024 Forwards IF Insp Repts 50-313/80-15 & 50-368/80-15 on 800722-0821 & netice of violation.
 MADSEN.0 L. Region 4. Dallas, Reactor Operations Nuclear Suspent Branch 80/09/03 2pp
- --8010240024 Notice of violation from insp on 800722-0821 * Region 4, Dallas, Office of the Director 80/09/03 ip
- --8010240028 IE Insp Repts 50-313/80-15 & 50-368/80-15 on 800722-0021 Noncompliance noted anticontaminated clothing sampled found to have contamination levels exceeding established limit of Q. i mmem/hour JOHNBOR, W D., CALLAN, L J Region 4, Dallas, Office of the Director HUNNICUTT, D.M Region 4, Dallas, Reactor Operations Nuclear Support Branch, 80/09/03, 14pp
- 8010240112 Responds to 1E Bullstin 80-15, "Possible Loss of Emergency Notification Sys (EMS) w/Loss of Offsite Power " Insp. conducted on 800627 to verify that EMB is powered onsite TRIMBLE, D, C Arkaneas Power & Light Co 80/09/03 2pp

- BO10210600 Forwards IE Mgt Meeting Repts 50-313/80-14 & 50-368/80-14 on BO0820 No noncompliance noted Performance evaluation encl MADSEM.0 L Region 4, Dallas, Reactor Operations Nuclear Support Branch BD/07/05 6pt
- --8010210605 IE Mgt Heeting Repts 50-313/80-14 & 50-368/80-14 on 800820 No noncompliance noted Major areas discussed activities at site from 790101 to 800819 CALLANIE J. (SAGLIARDOJ E. HUNNICUTT.D M Region 4. Dallas, Office of the Director 80/09/05 4pp
- 8010270333 Responds to IE Bulletin 80-22 No Westinghouse Type W-2 switches are installed on any safety-related equipment at facilities TRIMBLE.D.C. Arkenses Power & Light Co. 80/09/09 ip
- 8010300025 Forwards [E Circular 80-21, "Regulation of Refueling Crews" No written response required SEYFRIT,X V Region 4, Dallas, Office of the Director 80/09/10
- 8010010021 Ack receipt of 800827 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-11 & 50-368/80-11 MADSEM,0 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 60/09/12 ip
- ---8010010024 Responds to NRC 800808 ltr re violations noted in IE Insp Rests 50-313/80-11 % 50-368/80-11 Corrective actions Tech Specs change will be submitted, allowing entry into Mode 3 w/one pressurizer safety valve inoperable TRIMBLE.D C Arkansas Power & Light Co 80/08/27 Spp
- GO10240085 Updates 800703 response to IE Bulletin 80-11. "Masonry Wall Design ' Schedule for completion of enci testing program to determine shear strength of monitor in collar joints has been delayed to 810316 CAVANAUGH, W. Arkansas Power & Light Co. 80/09/15 7pp
- GO10230081 Forwards response to 600829 request to re-evaluate & describe actions to be taken re IE Info Notice 80-06.
 "Notification of Significant Events" Util notification requirement expanded
 TRIMELE,D C Arkansas Power & Light Co 60/09/16. 5pp
- BO10270424 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coolant During Steam Cenerator Decontamination " No specific action or response requested BEYFRIT.X V Region 4. Dallas. Office of the Director BO/09/26
- BO10160095 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required SEYFRIT, X V Region 4, Dallas, Office of the Director 80/09/30 ip
- 80(027057) Discusses IE insp on 800617-20 & 0714-18 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO.V Office of Inspection & Enforcement, Office of the Director 80/10/20. 2pp
- --8010270577 Notice of proposed imposition of civil penalty in amount of \$21.500 OO for Item of noncompliance noted in IC insp on \$00517-20 & 0714-18

 Office of Inspection & Enforcement, Office of the Director \$0710/20
- 8010280472 Requests 1-wk extension of time to request hearing on 800919 orders to respond to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Imminent issuance of Suppl 3 to subj bulletin may resolve util concerns REYNOLDS:N S Debevoiss & Liberman 80/10/23 2pp.
- A Periodic operating reports & related correspondence
- BO19010516 Forwards intake impingement monitoring data for Aug 1980 TREMBLE, D. C. Arkansas Power & Light Co. 80/09/26 1p
- --B010010517 Intake impingement monitoring data for Aug 1980. * Arkansas Power & Light Co. 80/09/19 10pp

- 8010210420 Forwards monthly operating rept for Sept 1980 TRIMBLE.D C Arkansas Power & Light Co 80/10/15 Ip
- --8010210423 Monthly operating rept for Sept 1980 BRAMLETT, L S Arkansas Power & Light Co 80/10/15 App
- 8010310381 Forwards intake impingement monitoring results for Sept 1980 TRIMBLE D C Arkansas Power & Light Co 80/10/27 4pp
- S Reportable occurrences. LERs & related correspondence
- 8010090150 PNO-IV-80-027: on 800821. all offsite telephone communication; including microwave systwas lost for 3-h because of forest fire near plant site Caused by heat damage to aerial telephone lines JDHNSON; N D . HANNICUTT, D M . MADSEN, O L Region 4, Dalles, Office of the Director 80/08/22 2pp
- 8010070620 Forwards LER 80-016/03X-1 TRIMBLE.D C Arkansas Power & Light Co 80/08/27 1p
- --8010070625 LER 80-016/03X-1 on 800611.during hydrogen purge sys surveillance testing of Loop B.proper flow through sys was unobtainable Caused by ladging of rost scale in hydrogen check vaives HPA-4.HPA-10 & HPA-128 Val
- 8010090168 PNO-IV-80-030 on 800905, steam generator tube leak was indicated by N-16 detector & increase in main stack off gas monitor Plant was shut down when leak was confirmed JOHNBON, W D , HUNNICUTI.D M , MADSEN, G L Region 4, Dallas, Office of the Director 80/09/05 ip
- 8010070138 PNO-IV-80-032 on 800703, uncontrolled release of radioactive gases through plant stack occurred when during cooldown letdown, sys relief valve lifted & remained open about 5 minutes Estimated release loss than Tech Bpcc limit JORSON N D , HUNNICUTI D M , MADSEN G L Region 4, Dalias, Office of the Director 80/09/08, lp
- B010010494 Forwards updated LER B0-024/03X-1 TRIMBLE, D. C Arkansas Power & Light Co B0/09/24 1p
- --8010010500 Updated LER 80-024/03X-1.on 800706.at start of P-7A surveillance.emergency feedwater pump tripped on overspeed Caused by 5 of 8 studs holding governor steam valve to turbine being broken All bolts replaced BRAMLETT.L S Arkansas Power & Light Co 80/09/25 2pp
- 8010070617 Forwards LER 80-031/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/09/25 ip
- --8010070623 LER 80-031/03L-0 on 800827.during monthly surveillance test. excessive smake observed in emergency diesel generator turbo charger exhaust flange Caused by exhaust gas contact w/ insulation.due to loose bolts & gasket SHIVELY.C N Arkansas Power & Light Co 80/09/25 ip.
- 8010070540 Forwards LER 80-032/04L-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/10/01 1p
- --8010070549 LER 80-032/04L-0 on 800905, during cooldown following steam generator tube leak, excessive release of radioactive matls in gaseous wastes occurred Caused by premature lifting of letdown relief valve PSV-1236 Valve was readjusted SHIVELY, C N Arkansas Power & Light Co 80/10/01 ip
- 8010070573 Forwards LER 80-034/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/10/01 ip
- --8010070582 LER 80-034/03L-0 on 800905 during normal operation, small primary to secondary leak developed from steam generator E24A Caused by flow induced vibration crack in Tube 74-2 Tube was plugged & unit returned to svc BHIVELY, C N Arkansas Power & Light Co 80/10/01 1p
- 8010220218 PN8-IV-80-011 on 801001, bomb threat received by Russellville Police DeptrAR No evacuation planned Little Rock Air Force Base dispatched search team consisting of bomb disposal experts KELLY, J. Region 4, Dallas, Office of the Director 80/10/01 ip
- 8010070540 Forwards LER 80-033/03L-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/10/02 1p.

- --8010070567 LER 80-033/03L-0 on 800906 during normal cooldown operations, RCB makeup block valve failed to close fully on command Caused by high differential across valve resulting in operation of close torque limit switch SMITH M Arkansas Power & Light Co 80/10/02 1p
- 8010170238 Forwards updated LER 80-024/03X-2 TRIMBLE, D C Arkansas Power & Light Co 80/10/09 ip
- --8010170245 Updated LER 80-024/03X-2 on 80070A during emergency feedwater pump turbine drive surveillance pump tripped on overspeed Gaused by five broken studs which hold governor steam valve to turbine All studs replaced BRAMLETTLE 9 Arkansas Power & Light Co 80/10/09 2pp.
- 8010200706 EN-80-049 on 801020, notice of violation & notice of proposed imposition of civil penalties of \$21,500 will be issued Action based on alleged noncompliance re continuing failure to effectively implement mot controls BROCKETT.T W. THOMPSON.D. Office of Inspection & Enforcement, Office of the Director 80/10/16 ip
- 8010280546 Forwards updated LER 80-027/03X-1 TRIMBLE, D.C. Arkantas Power & Light Co. 80/10/16 1p
- --8010280552 Updated LER 80-027/03X-1 on 800725, average gross gas release rate for Grd quarter was exceeded Caused by presence of 0 19% failed fuel & two shutdouns Attempts will be made to repair or replace failed fuel BRAMLETT/L S Arkansas Power & Light Co 80/10/16 ip
- 8010280522 Forwards LER 80-037/03L-0 TRIMBLE,D C Artansas Power & Light Co 80/10/23 ip
- --8010280572 LER 80-037/03L-0 on 800929, during monthly surveillance of lead hydrogen purge sys. supply fam VSF-30A flow slowly degraded & exhaust fam VEF-37A tripped Caused by sticking check valves & restricted filters Valves cleaned BRAMLET7.L 8 Arkansas Power & Light Co 80/10/23 2pp
-)10280583 Forwards LER 80-036/03L-0
 TRIMBLE, D C Arkansas Power & Light Co 80/10/23 1p
- -8010280591 LER 80-036/03L-0 on 800929.πuclear instrumentation calibr was not performed within 24-h of 10% power change Caused by gersonnel error Personnel reacquainted ω/proper procedure BRAMLETT.L 8 Arkansas Power & Light Co 80/10/23 ip
- 8010300571 PNO-IV-80-37 on 801023.unidentified male fell into intake canal of Unit 1.outside facility exclusion area Body removed by ambulance HUNNICUTT,D M , JOHNSON,W D Region 4. Dallas, Office of the Director 80/10/23 1p
- 8010280444 Forwards LER 80-035/49X-0
 TRIMBLE, D C Arkansas Power & Light Co 80/10/24 ip
- --8010280536 LER 80-035/99X-0 on 800916, during investigation of svc water condition, flow check & cooling coil indicated southwest side of coolers VCC2C & D were partially restricted. Caused by buildup of Asian clams Engineering evaluation is continuing SHIVELY. C N Ariansas Power & Light Co 80/10/02 ip
- DOCKET 90-315 DONALD C. COOK NUCLEAR POHER PLANT, UNIT 1

 Security, medical, emergency & fire protection plans
 - 10150303 Forwards request for addl info re 791107 emergency plan VAROA: 8 A Operating Reactors Branch I 80/09/19 18pp
- >10280431 Bubmits add1 info re revited emergency planning objectives in NUREG-0654 per B00919 ltr Final version will be issued for use by FEMA in mid-Oct to early Nov Revised plan will be submitted to NRC by B10102 HUNTER
- Financial information
- 8010210370 Forwards Annual Rept 1979 Projected cash flow for 1980 enci HUNTER:R S Indiana & Michigan Electric Co 80/10/16 2pp

- J Insurance & indemnity information
- 8010280273 Requests Endorsements 33 & 34 to Policy NF-206 & Endorsements 40 & 41 to Policy MF-79
 DINITZ.1 Utility Finance Branch (formerly Antitrust & Indeanty) 80/09/24 ip
- P Operating license stage documents & correspondence
- 8010010029 Forwards final "Technical Evaluation Rept on Degraded Grid Protection for Class IE Power Sys for DC Cook Nuclear Plant Unit 1 " VAROA.S A Operating Reactors Branch 1 80/09/10 1p
- 8010010439 Forwards Amend 41 to License DPR-58 safety evaluation k FR notice of issuance VARQALB A Deparating Reactors Branch 1 80/09/11 2pp
- --8010010443 Amend 41 to License DPR-58, revising pressure-temp operations limits for facility pressure vessel VARGA/S A Operating Reactors Branch 1 80/09/11 5pp
- --8010010447 Safety evaluation supporting Amend 41 to License DFR-58 # Office of Nuclear Reactor Regulation, Director 80/09/81 288
- --8010010450 Notice of issuance of Amend 41 to License DPR-38 VARGA: 8 A Operating Reactors Branch 1 80/09/11 2pp,
- 8010010191 Ack response to NRC 791109 ltr re ECCS evaluation models dealing w/feel cladding swelling & incidence of rupture Response acceptable & no further action necessary VARGA-B A Operating Reactors Branch 1 80/09/12 2pp
- 80i0220099 Forwards errata sheets amending BOD905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EISERNHUT, D © Division of Licensing 80/09/19 28pp
- 8010070518 Requests response, under eath or affirmation on plans & schedules re implementation of further hydrogen control measures at facilities Description of interim hydrogen control sys & assurance of protection should be provided EISENHUT.D O Division of Licensing 80/07/22 2pp
- 8010020497 Discusses depth of water coverage over irradiated fuel during Mode 6 operation Based on wording of 800815 ltr.util does not meet condition of at least 23 ft of water Revisions to Tech Specs 3 4 9 10 will be formally submitted MUNTER.R 8. Indiana & Michigan Electric Co 80/09/26 3pp
- 8010080432 Forwards responses to Items II K 3 30 & II K 3 31 of 803993 ltr re-preliminary clarification of TMI action plan requirements DOND,A J. Indiana & Michigan Electric Go 80/10/01 2pp
- 8010180412 Responds to NRC 800922 ltr re hydrogen control measures & setting up schedules for NRC review of interim & longer term measures Describes research program re ice condenser containments structural analysis & conceptual design study HUNTER, R 8 Indiana & Michigan Electric Co 80/10/07 3pp
- 8010160934 Requests that WCAP-9748 & WCAP-9749, submitted 800530,be east part of facility dockets Investigation concluded that realistically postulated flaw will not propagate around circumference of pipe & cause guil lotine break HUNTER,R 8 Indiana & Michigan Electric Co 80/10/08 Jpp.
- Q Inspection reports, IE Bulletins & correspondence
- 8010010711 Forwards IE Insp Rept 50-315/80-10 during June-Jul 1990 to notice of violation FIDRELLI, O Region 3, Chicago: Reactor Construction & Engineering Support Branch 80/08/29, 2pp
- --8010010714 Notice of violation from inap during June-Jul 1980 * Region 3: Chicago, Office of the Director 80/08/27, Ip.
- --B010010722 IE Insp Rept 50-313/80-10 during June-Jul 1980 Noncompliants noted, failure to develop & implement inductrination & training program for GC inspectors KEY.M.J. DANIELSON.D.H. Region 3, Chicago, Office of the Director. 80/08/27. 10pp

- 8010020260 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Facilities do not utilize subj relays MALDNEY, 0 P Indiana & Michigan Electric Co 80/09/02 ip
- 8010210026 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER, J O Region 3. Chicago, Office of the Director 80/07/03 4pp
- 8010010349 Forwards IE Insp Repts 50-315/80-14 & 50-316/80-13 on 800818-22 & notice of violation Notice of violation withheld (ref 10CFR2 790) NRND, J A Region 3, Chicago, Safeguards Branch 80/09/11 2pp
- --B010010356 IE Imsp Repts 50-315/80-14 & 50-316/80-13 on B00818-22 Noncompliance noted failure to conduct proper personnel screening & vital area barrier degraded Failure to maintain adequate isolation zone Datails withheld (ref 10CFR2 790) MIND. J.A. Region 3, Chicago, Bafeguards Branch MADEDA, T.J., CHRIBTOFFER, O. Region 3, Chicago, Office of the Director 80/09/10 2pp
- 8010200340 Forwards response to IE Bulletin 80-18, "Maint of Adequate Hin Flow Through Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Calculations outlined in bulletin encl performed for centrifugal pumps, HUNTER, R. B. Indiana & Hichigan Electric Co. 80/09/23 3pp
- 8010270473 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Comiant During Steam Generator Decontamination " No specific action or response requested KEPPLER.J O Region 3, Chicago, Office of the Director 80/09/25
- 8010180230 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required REPPLER, J. C. Region 3, Chicago, Office of the Director 80/09/30 is
- 8010280036 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/10/02 is.
- 8010290020 Forwards IE Info Notics 80-36, "Failure of Steam Ownerator Bupport Bolting." No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director. 80/10/10 ip
- R Periodic operating reports & related correspondence
- 8010140234 "Semiannual Redicactive Efficient Release Rept, Jan-June 1980 " • Indiana & Michigan Power Co. 80/06/30 83pp
- 8010200412 Forwards monthly operating rept for Sept 1980 SHALLER, D V Indiana & Michigan Power Co 80/10/14 1;
- --8010200415 Monthly operating rept for Sept 1980
 OLLETT.W T Indiana & Michigan Power Co 80/10/06 Spp
- 8 Reportable occurrences, LERs & related correspondence
- 8010080360 PNO-III-80-174 on 800709, licensee reported that state officials at Barnwell, 8C waste burial site found free standing liquid in Hittman liner containing radwaste solidified w/urea formaldehyde.
 PECK.C. C., FISHER, H.L. Region 3, Chicago, Office of the Director.
 80/09/11, Spp
- 8010980403 Forwards LER 80-022/03L-0 SHALLER.D. V. Indiana & Michigan Electric Co 80/10/01 1p
- --8010080515 LER 80-022/03L-0 on 800906, during normal operation, low flow alarm received on radiation monitors R-11 & 12 indicating insparable monitor, Caused by L-100 shaft coupling failure. Coupling replaced, air monitor tested & returned to svc BRDWN, M S. Indiana & Michigan Electric Co 80/10/01. 1p
- 8010090369 Forwards LER 80-023/03L-0 BHALLER, D. V. Indiana & Michigan Electric Co. 80/10/03 ip

- --B010090371 LER 80-023/03L-0 on B00916.steam generator 2 channel 3 level indication was found to be indicating 6% lower than other channels Caused by pinhoie leak in impulse line at socket weld Repaired & returned to svc
- 8010210664 Forwards LER 80-024/03L-0 SHALLER.D V Indiana & Michigan Electric Co 80/10/16 ip
- --8010210671 LER 80-024/03L-0 on 800917 during ice condenser insp. 21 intermediate deck doors found frozen shut Caused by excess ice due to moisture condensing on top deck door divider beams Design change initiated to insulate beams PIEHL.R H Indiana & Michigan Electric Co 80/10/16 ip
- 9010300447 Forwards LER 80-025/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/10/21 1p
- --8010300450 LER 80-025/03L-0 on 800727, glycol isolation valve would not fully close Cause undetermined Valves exercised & functioned correctly MURPHY, C E Indiana & Michigan Electric Co 80/10/21 ip
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8010150303 Forwards request for add1 info re 791107 emergency plan VAROA, 8 A. Operating Reactors Branch 1 80/09/19 18pp
- 8010280431 Bubmits add1 info re revised emergency planning objectives in NUREO-0454, per 800719 itr Final version will be issued for use by FEMA in mid-Out to early Nov Revised plan will be submitted to NRC by 810102
 HUNIER, R B Indiana & Michigan Electric Co 80/10/23 2pp
- I Financial information
- 8010210370 Forwards Annual Rept 1979 Projected cash flow for 1980 anci HUNTER, R 8 Indiana & Michigan Electric Co 80/10/16 2pp
- J Insurance & indemnity information
- B010280273 Requests Endorsements 33 & 34 to Policy NF-204 & Endorsements 40 & 41 to Policy NF-79 DINITZ. Utility Finance Branch (formerly Antitrust & Indemnity) B0/09/24 ip
- P Operating license stage documents & correspondence
- B010010191 Ack response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture. Response acceptable & no further action necessary VARQA.B A Operating Reactors Branch I B0/09/12 2pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIBENHUT, D Q Division of Licensing 80/09719 28pp.
- 8010010537 Forwards proposed Tech Spec change for Section 3,1,1,4 re moderator temp coefficient Plant transient reanalysis results reflecting proposed change encl HUNIER,R 8 Indiana & Hichigan Electric Co 80/09/22. 3pp
- --8010010541 Tech Spec change for Section 3.1,1,4 re moderator temp coefficient * Indiana & Michigan Electric Co 80/07/22 lp.
- --8010010543 "Bafety Analysis for Operation of DC Cook Unit 2 w/Positive Moderator Coefficient"
 + Westinghouse Electric Corp 80/09/22. 35pp.
- BO100303BB Authorizes incorporation of proprietary & nonproprietary versions of Westinghouse rept re Barton 1 Lot 1 pressure & differential pressure transmitter suppl testing into DC Cook, Unit 2 GL HUNIER, R 8 Indiana & Michigan Electric Co. B0/09/22 2pp
- 8010090518 Requests response under oath or affirmation on plans & schedulas re implementation of further hydrogen control measures at facilities. Description of interim hydrogen control sys & assurance of protection should be provided. EISENHUT.D 0. Division of Licensing. 80/09/22. 2pp

- 8010020497 Discusses depth of water coverage over irradiated fuel during Mode 6 operation Based on wording of 800815 ltr.util does not meet condition of at least 23 ft of water Revisions to Tech Specs 3 4 9.10 will be formally submitted HUNTER.R 8 Indiana & Michigan Electric Co 80/09/26 3pp.
- 8010080432 Forwards responses to Items II.K 3 30 & II K 3.31 of 800905 ltr repreliminary clarification of TMI action plan requirements
 DDMD.A.J. Indiana & Michigan Electric Co 80/10/01 2pp
- 8010150412 Responds to NRC 800922 ltr re hydrogen control measures & setting up schedules for NRC review of interim & longer term massures. Describes ressarch program re ice condenser containments, structural analysis & conceptual design study, HUNTER, R. 8. Indiana & Michigan Electric Co 80/10/07. Spp
- 8010160534 Requests that MCAP-9748 & MCAP-9749, submitted 800630, be made part of facility dockets Investigation concluded that realistically postulated flew will not propagate around circumference of pipe & cause guillotine break HUNTER, R 8 Indiana & Michigan Electric Co. 80/10/08. 3pp.
- Q Inspection reports, IE Bulletine & correspondence
- 8010020260 Responds to IE Bulletin 80-17. "Failures of Mercury-Hettad Matrix Relays in Reactor Protective 89s of Operating Nuclear Power Plants Designed by 6-E " Facilities do not utilize subj relays.
 MALOREY, 0-P Indiana & Michigen Electric Co. 80/07/02 ip
- 8010210026 Provides updated into re-admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas.

 KEPPLER, J. 0 Region 3, Chicago, Office of the Director 80/09/03.
- 8010010349 Forwards IE Insp Repts 50-315/80-14 & 50-316/80-13 on 800818-22 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND.J A Region 3, Chicago, Bafeguards Branch. 80/09/11. 2pp.
- --B010010335 IE Insp Repts 50-315/80-14 & 50-316/80-13 on 800B18-22 Noncompliance noted failure to conduct proper personnel screening & vital area barrier degraded Failure to maintain adequate isolation zone Details withheld (ref 10CFR2.790). HND, J A Region 3. Chicago. Bafeguards Branch HADEDA-T J. CHRISTOFFER: O Region 3. Chicago, Office of the Director. B0/09/10 2pp.
- B010200340 Forwards response to IE Bulletin 80-18. "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Ruyture." Calculations outlined in bulletin ent performed for centrifugal pumps HUNTER:R S Indiana & Michigan Electric Co 80/09/23 3pp.
- 8010270473 Forwards IE Info Notice 80-34. "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested KEPPLER.J G Region 3. Chicago. Office of the Director. 80/09/25. is

10160230 Forwards Buppl 2 to 1E Bullstin:79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J G. Region 3. Chicago, Office of the Director 80/09/30. in.

0280036 Forwards IE Circular 80-22, "Confirmation of Employee valifications." No written response required. EFPLER.J. 9 Region 3, Chicago, Office of the Director. 80/10/02.

D290020 Forwards IE Info Notice 80-36. "Failure of Steam Generator upports Bolting." No specific action or response requested. ZPPLER. J. O Region 3. Chicago, Office of the Director. 80/10/10.

Periodic operating reports & related correspondence

10140234 "Semiannual Radioactive Effluent Release Rept, Jan-June 1980," — Indiana & Michigan Power Co. 80/06/30, 83pp,

10200407 Forwards monthly operating rapt for Sept 1780. BHALLER, D.V. Indiana & Michigan Electric Co. 80/10/14 1p

- ~~8010200410 Monthly operating rept for Sept 1980. OILLETT, N. T. Indiana & Michigan Electric Co. 80/10/06, 7pp
- S. Reportable occurrences. LERs & related correspondence
- 8010090267 PNO-III-80-120 after planned shutdown on 800627, South Bert, IN TV news reporter inaccurately reported safety injection wistuck rod & pump failure at facility MASSE, R.E., STREETER, J. Region 3, Chicago, Office of the Director 80/06/30 ip
- 8010080360 PND-III-80-174, on 800909, licensee reported that state officials at Barnwell, SC waste burial site found free standing liquid in Hittman liner containing radwaste solidified w/urea formaldehyde PECK, C. C. FISHER, W.L. Region 3, Chicago, Office of the Director. 80/09/11. 2pp
- 8010090356 Forwards LERs 80-031/03L-0 & 80-032/03L-0 BHALLER:D, V Indiana & Michigan Electric Co 80/10/03 1p
- --8010070362 LER 80-031/03L-0 on 800702; bistable for containment pressure hi-hi protection set II tripped at 3 1005 paig. exceeding limiting conditions for operation Gausad by instrument drift Bistable adjusted & returned to svc DELONO, B. D. Indiana & Michigan Electric Co. 80/10/03. ip
- ---B010070368 LER 80-032/03L-0 on 800704, while returning east RHR gusp to it was after maint, pump became unstable & declared inoperable Caused by air in sys during fill & vent Procedure changed & problem eliminated.

 MURPHY.C. E Indiana & Michigan Electric Co 80/10/03, 3pp I
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
 F Security, medical, emergency & fire protection plane
- 8010270363 Forwards fire protection review status, safety evaluation of acceptable items & NRG requirements on mods needed at facility to resolve open items that would meet proposed App R requirements to 105R50 re fire protection.

 CLARK, R. A. Operating Reactors Branch 3 80/10/02. 3pp
- --8010270364 Bafaty evaluation of acceptable fire protection items Item 3.2 5 re drain sys backflow protection is only partially acceptable # Division of Licensing. 80/10/02 lipp
- B010310269 Provides add1 mnds to fire hexards analysis re protection of sits shutdown equipment inside containment Mods include addition of reactor coolant pump motor lube oil collection sys & fire detection in cable trays in reactor pump bay. LUNDVALL: A E. Baltimore Gas & Electric Co 80/10/28 ip
- O. Adjudicatory correspondence
- B010130643 Forwards corrected Pages 1-5 of B00829 order for mod of license Date for which hearing may be requested also revised.

 EISENHUT, D G Assistant Director for Licensing B0/09/19, 2pp.
- --8010150645 Corrected Pages 1 through 5 of 800829 order modifying items. # Assistant Director for Licensing. 80/09/19. Spp.
- J. Insurance & indomnity information
- 9010280263 Requests Endorsements 30 & 35 to Policy NF-16 & Endorsement 29 to Policy MF-76.
 DINITZ, I. Utility Finance Branch (Pormerly Antitrust & Indemnity) 80/09/24.
- P. Operating license stage documents & correspondence
- 8010010709 Discusses review of util response to NRC 791109 ltr re ECC\$ svaluation models, dealing w/fuel cladding swelling & 'incidence of rupture. Response is acceptable. No further action is necessary.

 CLARK.R.A Operating Reactors Branch 3. 80/09/10. 2pp.
- 8010080327 Forwards request for add1 info re util 790603,0831 & 800315 proposed spent fuel pool mod for facility CLARK,R,A. Operating Reactors Branch 3. 80/09/12. 3pp

- 8010080241 Forwards Amends 47 & 30 to Licenses DPR-53 & DPR-69, respectively, safety evaluation, EIA & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/09/19 3pp
- --- 8010080246 Amends 47 & 30 to Licenses DPR-53 & DPR-69, respectively, increasing spent fuel storage capability to max 1,760 fuel assemblies, using high density borated spent fuel racks, CLARK, R. A. Operating Reactors Branch 3 80/09/19, 10pp.
- --8010080252 Safety evaluation supporting Amends 47 & 30 to Licenses OPR-53 & DPR-69, respectively 4 Operating Reactors Branch 3 80/09/19 13pp.
- --8010080257 EIA suggesting Amends 47 & 30 to Licenses DPR-53 & DPR-69. respectively a Dearting Reactors Branch 3 80/09/19. 18pp
- --8010080250 Notice of issuance & availability of Amends 47 & 30 to Licenses DPR-53 & DPR-59, respectively Negative declaration entl. CLARK, R, A Uperating Reactors Branch 3, 80/09/19 2pp
- BO10220099 Forwards errate sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encil EtBENHUT,D.0 Division of Licensing, 80/09/19, 28pp.
- BOIO160513 Discusses mod of Cycle 5 license application to reflect only NRC approved methodologies. Submits list of sections changed by mod & sections that will not be affected by proposed change. LIPPOLD, H J Baltimore Gas & Electric Co 80/10/07. 2pp.
- 8010200418 Forwards Class IV fee re util 800922 application to amend OL to allow operation during fifth cycle.
 ASH.R.F. Baltimore Qas & Electric Co. 80/10/10. 1p
- 9 Inspection reports: IE Bulletins & correspondence
- BOIO020282 Forwards IE Insp Repts 50-317/80-08 & 50-318/80-08 on 800A01-30 No noncompliance noted. BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/28 2pp.
- --8010020270 IE Insp Repts 50-317/80-08 & 50-318/80-08 on 800601-30, No noncompliance noted Major areas inspected control room & accessible portions of auxiliary, turbine, syc & intake bldgs.
 ARCHITZEL, R. E., CALLAHAN, C. J. Region 1, Philadelphia, Office of the Director. MCGABLE.E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 60/07/18 12pp.
- 8010230661 Forwards IE Insp Repts 50-317/80-06 & 50-318/80-06 on 800501-91 CRIER, B H Re 80/08/19 2pp Region i. Philadelphia, Office of the Director.
- --B010230664 IE Insp Repts 50-317/80-06 & 50-318/80-06 on 800501-31. Nancompliance noted:fatilure to rept auxiliary feedwater systhoperability & fatilure to prevent smoking behind control panels Datails withheld tref 10CFR2.790) ARCHITZEL,R. Region I. Philadelphia, Office of the Director. ACCABE.E.C. Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/21, 16pp.
- BOLOO20184 Responds to IE Bulletin BO-20 Westinghouse Type W-2 control switches are not used in any application LUMOVALL.A.E. Builtimore One & Electric Co. BO/OB/21 [p.
- 8010020211 Responds to 1E Bullatin 80-15 re loss of emergency notification sys w/loss of offsite gower Loss of offsite power would render local equipment & emergency notification sys inosperable. Mods to power supplies to be complete 800708. LUNDVALLA.E Beltimore Gas & Electric Co. 80/08/21 ip.
- 8010240144 Forwards IE Insp Repts 50-317/80-11 & 50-318/80-10 on 800701-31. No noncompliance noted BRUNNER.E.J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/08/28 2pp.
- --B010240153 IE Insp Repts 50-317/80-11 & 50-318/80-10 on 800701-31 No nancompliance noted Major areas inspected; control room & accessible portions of auxiliary, turbine & syc & intake MCGABE.E.C. Region i, Philadelphia, Reactor Operations Nuclear Support Branch, ARCHITZEL, R. E., GALLAHAN, C. J. Region 1, Philadelphia, Office of the Director, 80/08/25, 9pp.

- 8010010177 Ack receipt of 800509,14 & 0805 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/80-01.50-318/80-01.50-317/80-02 & 50-318/80-02 ORIER. B H Region i, Philadelphia, Office of the Director. GRIER, B H Re 80/09/05, 1p.
- --8010010190 Responds to NRC 800422 ltr re violations noted in IE Insp Repts 50-017/80-02 & 50-018/80-02. Corrective actions: established procedural requirements for making specific estimates of offsite doses from unplanned releases. LUNOVALL.A. E. Baltimore Que & Electric Co 80/05/09, Spp
- --8010010194 Responds to NRC 800422 ltr re violations noted in IE Inap Repts 50-317/80-01 & 50-318/80-01. Corrective actions: revising action statements of Tech Specs to limit time any redundant piece of equipment or sys
- --8010010201 Responds to IE Insp Repts 50-317/80-01, 50-318/80-01, 50-317/80-02 & 50-318/80-02, Corrective actions. Tech Specs will be interpreted more narrowly w/regard to loss of redundant safety functions LUNDVALL.A.E. Beltimore Cas & Electric Co. 80/08/05. 3pp.
- --8010010182 Forwards IE Insp Repts 50-317/80-01 k 50-318/80-01 on 800204-27 & notice of violation. BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/04/22. 2pp.
- --8010010207 Notice of violation from insp on 800204-29.

 * Region i, Philadelphia, Office of the Director. 80/04/18, 2pp.
- --8010010213 IE Insp Repts 80-317/80-01 t 80-318/80-01 on 800204-29. Noncompliance notes, failure to make prompt rept following simultaneous inperabliity of all Unit 2 diesel generators. HCCABE, E.C. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. ARCHITZEL, R. Region 1, Philadelphia, Office of the Director. 80/04/18. 12pp.
- 8010240268 Forwards response to IE Bulletin 80-11, "Masonry Hall Design " Three stacked block shield walls were identified as having possible impact on safety-related sys. Halls have been removed. H/o encle
 LUNDVALL: A E. Baltimore Oas & Electric Co 80/09/23, 2pp.
- 8010270428 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Opporator Decontemination." No specific action or response requested. ORIER, B.H. Region 1. Philadelphia, Office of the Director 80/09/26 ip.
- 8010240123 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required, ORIER, B. H. Region 1, Philadelphia, Office of the Director, 80/10/02 1p.
- 8010280243 Forwards 1E Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/10. ip.
- R. Periodic operating reports & related correspondence
- 8010230434 Forwards monthly operating repts for Bept 1980. MERSON, S. D. Baltimore Cas & Electric Co. 80/10/18, 1g
- --8010230438 Monthly operating repts for Bapt 1980, MERBON, S.D. Baltimore Cas & Electric Co. 80/10/15, 2ipp.
- 8. Reportable occurrences: LERs & related correspondence
- 8010160207 RD 80-48(U-1):on 800904, while control room air control room air control room air control was undergoing maint, compressor for air conditioner if tripped on overload. Cause is under investigation, Plant procedures are being revised to require operability check. RUSSELL.L. S. Baltimore Oas & Electric Go 80/09/04. ip.
- 8010030398 Forwards LER 80-051/01T-0 RUSSELL,L.S. Baltimore Oas & Electric Co. 80/09/24. ip
- --B010030399 LER 80-051/01T-0; on B00911; during normal operation, while performing post maint check of control room air conditioning Unit 11:both Units 11 & 12 Pailed. Cause not stated, Design sys re-evaluated & operability check procedures revised, HENDERLICH, R.L., PENCE, H.B. Baltimore Oas & Electric Co. B0/09/24, 2pp.

- 801004031; Forwards LER 80-050/03L-0 RUSSELL, L 8 Baltimore Gas & Electric Co 80/10/01 1p
- --8010060313 LER 80-030/03L-0 on 800901, while performing operation to fill 12A safety injection (SI) tank, SI tank exceeded high level limit Cause of rapid rise in tank level not determined DAVIS, S M , RIZZO, P O Baltimore Cas & Electric Co, 80/10/01
- 8010140392 Forwards LER 80-093/01T-0 RUSSELL, L B Baltimore Cas & Electric Co 80/10/03 1p.
- --B010140402 LER 80-053/01T-0 on 800926, during survey of masonry wall design, three stacked shielding walls were identified as having possible impact on safety-related sys Caused by installation prior to implementing mod centrol program DENTON, R E Baltimore Gas & Electric Co 80/10/03 2pp
- 8010220629 PNO-I-80-147 on 801008, plant emergency declared when multiple radiation alarms were received Indicates radiation levels returned to normal in 5 minutes Licensee attributes event to instrument problems MCCABE, E. C., BRUNNER, E. J. Region 1, Philadelphia, Office of the Director 80/10/09 ip
- 8010210476 Forwards LER 80-052/03L-0. RUSSELL, L B Saltimore Cas & Electric Co 80/10/17 ip
- --8010210684 LER 80-052/03L-0 on 800917, during normal operation, 12 saltwater/svc water heat exchanger was taken out of svc to investigate & repair tube leak Tube was found & plugged HENDERLICH, R L. RAYBURN, C L Baltimore Gas & Electric Co 80/10/17 1p
- BO10240421 Forwards LER 80-047/03L-0
 RUSSELL, L B Baltimore Gas & Electric Co 80/10/17. 1p
- --B01024042A LER 80-047/03L-0 an 800920, sump drain i-MOV-5463 failed to shut Caused by blown fuse in controller Fuse replaced LAGIEWSXI.J S , RIZZO,P Q Baltimore Gas & Electric Co 80/10/17
- 8010280571 RO 80-58 (U-1) on 801021, control room air conditioning unit 12 tripped w/air conditioning unit 11 out of svc for maint Cause unstated Air temp remained within design limit Description of failure & corrective action forthcoming, RUSSELL.L B Baltimore Get & Electric Co 80/10/23 ip
- 8010310320 RO 80-58, on 801021 w/control room air consistioning unit is out of svc for maint, unit 12 sys tripped Sys restarted by reset button Filter trains remained operable during event Complete rept w/corrective actions will be forwarded RUSSELL.L.B. Baltimore Gas & Electric Co. 80/10/23 ip
- 8010310330 Forwards LER 80-054/03L-0 RUSSELL,L B Baltimore Gas & Electric Co B0/10/24. ip
- --B010310359 LER 80-054/03L-0:on 800925, engineered safety features actuation sys pressure channel 2D indicated deviation of greater than 0 16 volts Caused by oscillating output signal, isolating transmitter I-E/E-102A Instrument replaced MERNERLICH, R E , RIZZO, P O Baltimore Oas & Electric Co. 80/10/25 1p
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8010270363 Forwards fire protection review status, safety evaluation of acceptable items & NRC requirements on mods needed at facility to resolve open items that would meet proposed App R requirements to 100FR50 re fire protection.

 CLARK.R.A. Operating Reactors Branch 3. B0/10/02, 3pp
- --8010290364 Safety evaluation of acceptable fire protection items. Item 3.2 5 re-drain sys backflow protection is only partially acceptable # Division of Licensing 80/10/02 11pp.
- 8010310263 Provides addi mods to fire hazards analysis re protection of site shutdown equipment inside containment. Mode include addition of reactor coolant pump motor lube oil collection sys & fire detection in cable trays in reactor pump bay.

 LUNDVALL.A E. Baltimore Gas & Electric Co 80/10/28. jp

- O Adjudicatory correspondence
- 8010180643 Forwards corrected Pages 1-5 of 800829 order for Fod of license. Date for which hearing may be requested also revised EISENHUT, D G Assistant Director for Licensing 80/09/19 259
- --B010150645 Corrected Pages 1 through 5 of 800829 order modifying license + Assistant Director for Licensing. 80/09/19 5pp
- J Insurance & indemnity information
- 8010280263 Requests Endorsements 30 & 35 to Policy NF-16 & Endorsement 29 to Policy MF-76 DINITZ. 1 Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 19
- P Operating license stage documents & correspondence
- B010010709 Discusses review of util response to NRC 791109 ltr re ECC symbol sy
- 8010080329 Forwards request for additinfo resutil 790603.0831 to 800111 proposed spent fuel pool mod for facility CLARK.R A Operating Reactors Brench 3 80/09/12 3pp
- 8010080241 Forwards Amends 47 & 30 to Licenses DPR-53 & DPR-69, respectively, safety evaluation, EIA & notice of issuance & availability, CLARK, R A Operating Reactors Branch 3 80/09/19 3pp.
- --8010080246 Amends 47 & 30 to Licenses DPR-53 & DPR-69, respectively, increasing spent fuel storage capability to max 1,760 fuel assemblies, using high density borated spent fuel racks. CLARK:R A Operating Reactors Branch 3 80/09/19, 10pp.
- --B0100B0252 Safety evaluation supporting Amends 47 % 30 to Licenses DPR-53 % DPR-69-respectively + Operating Reactors Branch 3 80/09/19 13pp
- --8010080237 EIA supporting Amends 47 & 30 to Licenses DPR-53 & DPR-69, respectively + Operating Reactors Branch 3 80/09/19 18pp
- --8010080260 Notice of issuance & availability of Amends 47 & 30 to Licenses DPR-53 & DPR-49, respectively Negative declaration encl CLARK, R. A Operating Reactors Branch 3. 80/09/19 2pp.
- B010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EIBENHUT.D 0 Division of Licensing 80/09/19. 28pp.
- Q Inspection reports, IE Bulletins & correspondence
- 8010020282 Forwards IE Insp Repts 30-317/80-00 & 50-318/80-08 on 800&01-30 No noncompliance noted BRUNNER, E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/28 2pp
- --8010020290 IE Insp Repts 50-317/80-08 & 50-318/80-08 on 600601-30 No noncompliance noted Major areas inspected; control room & accessible portions of auxiliary, turbine, svc & intake bldgs ARCHITZEL, R E , CALLAHAN, G. J Region i, Philadelphia, Office of the Director MCCABE, E C Region i, Philadelphia, Reactor Operations Nuclear Support Branch SO/07/18, 12pp.
- 8010230661 Forwards IE Insp Repts 80-317/80-06 & 50-318/80-06 on 800501-31 GRIER, B H Region 1, Philadelphia, Office of the Director. 80/08/13 2pp.

- 8010020184 Responds to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in any application LUNDVALL, A E Baltimore Gas & Electric Co 80/08/21 ip
- 8010020211 Responds to IE Bulletin 80-15 re loss of emergency notification sys w/loss of offsite power Loss of offsite power would render local aquipment & emergency notification sys inoperable Mods to power supplies to be complete 800708 LUNDVALLA E Baltimore Oas & Electric Co 80/08/21 1p
- B010240144 Forwards IE Insp Repts 50-317/80-11 & 50-318/80-10 on 800701-31 No noncompliance noted.
 BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/28 2pp
- --B0i0240153 IE Insp Repts 80-317/80-11 % 50-318/80-10 on 800701-31 No noncompliance noted Major areas inspected control room & accassible portions of auxiliary, turbine & svc & intake % 169s
 MCCABE,E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch ARCHITZEL,R E, CALLAHAN,C J Region 1, Philadelphia, Office of the Director 80/08/25 7pp
- 8010010177 Ack receipt of 800309,14 & 0805 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-317/80-01.50-318/80-01.50-317/80-02 & 50-318/80-02 QRIER, B H Region 1, Philadelphia, Office of the Director. 80/09/09. 1p
- --8010010190 Responds to NRC 800422 Itr re violations noted in IE Insp Repts 30-317/80-02 & 50-318/80-02 Corrective actions established procedural requirements for making specific estimates of offsite doses from unplanned releases LUNDVALL. A E Baltimore Gas & Electric Go. 80/05/09 5pp
- --8010010194 Responds to NRC 800422 ltr re violations noted in IE Insp Repts 50-317/80-01 & 50-318/80-01 Corrective actions reviring action statements of Tech Bases to Limit time any redundant piece of squipment or sys can be out of svc LUNDVALL, A.E. Baltimore Gas & Electric Co 80/05/14, Spp
- --B010010201 Responds to IE Insp Repts 50-317/B0-01, 50-318/B0-01, 50-317/B0-02 & 50-318/B0-02 Corrective actions. Tech Bpecs will be interpreted more narrowly w/regard to loss of refundant safety functions
 LUNDVALL.A E Baitimore Gas & Electric Co B0/08/05 3pp.
- --8010010182 Forwards IE Insp Repts 50-317/80-01 & 50-318/80-01 on 800204-29 % notice of violetion. BRUNKER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 80/04/22 2pp
- --8010010207 Natice of violation from insp on 800204-27.

 4 Region 1, Philadelphia, Office of the Director. 80/04/18 2pp
- --B010010213 IE Insp Repts 50-317/80-01 & 50-318/80-01 on 800204-29, Noncempliance noted, failure to make prompt rept following staultaneous inoperability of all Unit 2 diesel generators, MCCABE, E.C., Region 1, Philadelphia, Reactor Operations Nuclear Buppert Branch. ARCHITELIR, Region 1, Philadelphia, Office of the Director. 80/04/18 12pp.
- 8010240268 Forwards response to IE Bulletin 80-11, "Masonry Wall Dasign," Three stacked block shield walls were identified as having possible impact on safety-related sys. Walls have been removed. W/d encis. LUNDVALL, A E Baltimore Gas & Electric Co. 80/09/23 2pp
- 8010270428 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested ORIER, 8. H Region 1, Philadelphia, Office of the Director 80/09/24 ip
- 8010240123 Forwards IE Circular 80-22, "Confirmation of Employee dvalifications " No written response required GRIER, 9. H Region 1, Philadelphia, Office of the Director. 80/10/02 1p
- 8010280243 Forwards IE Info Notice 80-36. "Failure of Steam Cemerator Support Bolting." No specific action or response requested ORIER.B. H Region i, Philadelphia, Office of the Director. 80/10/10 1p.
- A Periodic operating reports & related correspondence
- 8010230434 Forwards monthly operating repts for Sept 1980, MERSON, 8 D. Baltimore Gas & Electric Co. 80/10/15. 1p

- --8010230438 Monthly operating repts for Sept 1780
 HERSON, 8 D Baltimore Gas & Electric Co 80/10/15 2ipp
- 8 Reportable occurrences, LERs & related correspondence
- 8010160207 RO 80-48(U-1) on 800904, while control room air conditioner 12 was undergoing maint, compressor for air conditioner 11 tripped on overload Cause is under investigation Plant procedures are being revised to require operability check RUSSELL, L B Baltimore Oas & Electric Co 80/09/04 ip
- 8010060252 Forwards LER 80-039/03L-0 RUSBELL-L B Baltimore Oas & Electric Co 80/09/29 ip
- --8010060261 LER 80-039/03L-OL on 800829, channel C pressurizer pressure high trip setpoint discovered out of spec. Caused by pressure transmitter 2-PT-102C isro-shifting low LAOIEWSKI.J 8, RIZZO,P 0 Baltimore Oes & Electric Co 80/09/29
- 8010060265 Forwards LER 80-040/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/10/01 ip
- --B010060273 LER 80-040/03L-0 on B00701, control element assembly 34 dropped to bottom of core Electrical test disclosed no cause Review of rod drop occurrences underway HENDERLICH, R L , RIZZO, P Baltimore Oas & Electric Co B0/10/01
- 8010160567 Forwards LER 80-042/03L-0 RUBSELL, L B Baltimore Oas & Electric Co 60/10/10 ip
- ---9010160573 LER 80-042/03L-0 on 800715, during surveillance testing, safety injection sys hydraulic snubbers 2-52-33 h 2-52-53A determined inoperable. Caused by stripped tube fitting at yalve block on snubber 2-52-53A Snubbers removed & replaced LAOIEMBKI.J S , MIERNICKI.M H. Baltimore Gas & Electric Co 80/10/10 10
- GOIO160463 Forwards LER BO-03B/03X-1 RUBBELL, L B Baltimore Oas & Electric Co BD/10/14 1p.
- --8010160465 LER BO-03B/03X-1 on 800818, while reducing power due to saltwater leak, steam generator blowdown pH dropped to 6 6, below Tech Spec limit of 7 5 Caused by inadvertent lab technician action Affected personnel reinstructed LAOIEMBKI, J S., SPECIALE, J R Baltimore Cas & Electric Co 80/10/14 2pp
- 8010200432 Forwards LER 80-043/03L-0 RUSSELL. L B Baltimore Cas & Electric Co 80/10/14 1p
- --B010200434 LER 80-043/03L-0 on B00914; during normal operation, 228 safety injection tank level indication became erratic Cause not known Bench test revealed no malfunction Level transmitter replaced recalibr & returned to svc. LAOIEMBKI, J. B., RIZZO, P.O. Baltimore Qas & Electric Co. 80/10/14
- BOJO210666 Forwards LER 80-041/03L-0 RUSSELL, L. B. Baltimore Cas & Electric Co. 80/10/15. 1p
- --8010210672 LER 80-041/03L-0 on 800919, while performing preventive maintroontrol element assembly (CEA) 9 dropped into core gause undetermined. Electrical test of CEA performed & racorded traces analysed.

 WEMDERLICH, R L , RIZZO, P 0 Baitimore Oas & Electric Co 80/10/15.
- 8010280571 RO 80-58 (U-1) on 801021, control room air conditioning unit 12 tripped w/air conditioning unit 11 out of svc for maint. Cause unstated Air temp remained within design limit Description of failure & corrective action forticoming. RUBBELL.L. B Baltimore Cas & Electric Co 80/10/23. ip
- 8010310320 RD 80-58, on 801021 w/control room air conditioning unit 11 out of svc for maint, unit 12 sys tripped. Bys restarted by reset button, Filter trains remained operable during event. Compilete rept w/corrective actions will be forwarded. RUSSELL, L. B. Baltimore Qas & Electric Co. 80/10/23 lp
- 8010310310 Forwards LER 80-044/03L-0, RUSSELL, L, B Baltimore Cas & Electric Co 80/10/24. 1p

- B010310315 LER 80-044/03L-0 on 800924, angineered safety features actuation sys 22 8018 Channel 2F indicated deviation of greater than 0 1 volts Caused by failure of signal isolator 2-E/E-1023C Unit replaced w/spare HENDERLICH, R 1, RIZZO, P Q Baltimore Cas & Electric Co 80/10/24 ip.
- ICKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 Security, medical, emergency & fire protection plans
- 010200655 Immediate Action Ltr 80-31 Confirms 800916 telcon re emergency preparedness capabilities for facility Actions to be taken include reviews of emergency plan implementation procedures & emergency organization ORIER, B H Region i, Philadelphia, Office of the Director 80/09/17 2pp
- 010060339 Forwards security plan, Revision 7 Revision withheld (ref 10CFR2 790) ARNOLD, R C Hetropolitan Edison Co 80/09/30 2pp
- 010210650 Forwards lists of accomplished actions in response to B00715 request re NRC essential personnel Emergency access list for personnel will be revised & disseminated Security advised of addition of NRC essential personnel (1/o encl ARNOLD, R, C Metropolitan Edison Co 80/10/14 2pp

Adjudicatory correspondence

- 010240331 Informs Commission of DOT decision disclaiming NRC authority to make license amends effective until completion of advisory hearing EILPERIN.B F Office of the General Counsel SECY-A-80-126 BO/08/29 2pp
- 8010240337 Brief re intervenors 8 Bholly & DE Hossler & People Against Nuclear Energy petitions for review of NRC authority to make license amends effective until completion of adjudicatory hearings Certificate of Bvc encl HOGRMAN, J M. Justice, Dept of, Attorney General's Office, BTEENLAND, P R , STRAUSS, D A Justice, Dept of 80/08/29 27pp
- 80i0240344 Brief in response to DOJ decision disclaiming NRC authority to make license amends effective until completion of adjudicatory hearings Intervenors petitions for review should be denied. Certificate of Evc encl.
 BICKWITL FILPERIN, B.F., SLAGOIE, E.L. Office of the General Counsel. 80/08/29 34pp
- MODIOOOI Advises that progress has been achieved in reaching informal resolution among parties re proposed contentions Evidence of agreement will be provided when available GDLDHERG.8,C. Hearing Branch 4 80/09/30 ip.
- 010030456 Forwards Commission 800726 statement of policy re util 800723 petition for deferral of cease & desist requirement 8TEPHENS.C R Docketing & Services Branch 80/10/01. 1p.
- 8010030458 Statement of policy in response to util 800923 petition for stay of cease & desist requirements re use of revenues for uninsured cleanup & restoration Environ requirements supersed state requirements in event of conflict # Commissioners. 80/10/01 1p
- 10140532 Notice of withdrawal from proceeding SINGER,L.N Hearing Branch 2 80/10/10 1p.
- 10220541 Forwards radon info in response to request Info should be made available to ABLAB & parties in radon proceedings. ELLETT.H.H Environmental Protection Agency 80/10/10 150pp

General correspondence

- idi40200 Responds to 800408 ltr to OSHA re proposal to monitor biota in TMI vicinity Monitoring is being performed by private consulting firm & is adequate to detect damage to vegetation, NRC appreciates efforts & concerns. BALLARD, R L, Environmental Engineering Branch 80/07/25, 1p.
- 10020508 Recommends that util be directed to put Unit 2 back on line immediately & that cleanup of Unit 1 be accelerated to enable operation within 1-yr Qovt red tape & scandal sheet techniques of news media should stap KOHR: J.C. Affiliation Unknown. 80/09/23, 2pp

- 8010100279 Forwards NUREO-0662 in response to citizen itr re radwaste disposal at facility EPA responsibility for long-term environ radiation surveillance provides for continuous monitoring program W/o encl SNYDER.8 J TMI Program Office 80/09/26 2pp
- 8010030408 Responds to 800214 ltr expressing dissatisfaction w/events occurring since TMI accident Remedial actions outlined BNYDER-B J TMI Program Office 80/09/29 3pp
- 8010200257 Responds to 1tr expressing concern re effects of TMI accident Potential physical health impact on public from using any proposed Kr-85 removal strategy is negligible Relevant documents forwarded K/o encls
 SNYDER, B J TMI Program Office 80/09/27 3pp
- --- 8010200261 Expresses concern re effect of TNI accident on public SAVINI, F , SAVINI, B , SAVINI, S Affiliation Unknown 80/09/29
- 8010200563 Forwards NRC 1979 Annual Rept in response to 800427 ltr to President Carter re atomic energy W/o encl SNYDER.B J TMI Program Office 80/09/29 3pp
- 8010240131 Responds to encl 800326 ltr to President Carter, suggesting federal govt responsibility for TMI cleanup operations
 Licenses has primary responsibility for decontamination operations SNYDER:BJ TMI Program Office 80/09/29 4pp
- 8010270079 Responds to 800710 ltr to President Carter re offects of accident & venting of Kr-85 from reactor bldg Offsile collective dose associated w/releases from accident represent minimal risks W/o encl documentation SNYDER.B J TMI Program Office 80/09/29. 4pp
- --8010270083 Forwards JR Ulium 800710 itr to President Carter expressing concern re releases from accident at facility & venting of krypton gas Requests response SEALMM President of US & Executive Offices 80/07/18 3pp
- 8010280089 Responds to B00627 telegram to President Carter re Kr-85 release Purging method considered most effective alternative M/o enci NUREG-0662 & 800612 orders SNYDER.B J THI Program Office 80/09/29, 3pp
- 8010270201 FDIA request for reason & data TMI Commission used to base public health & safety conclusions & amount of gas vented from facility BOYLE-J C Affiliation Unknown 80/09/29 ip
- 6010070457 Advises tht HD Hukill was appointed Director of TMI-1, replacing JG Herbein who has assumed position of Director of Nuclear Assurance Updated svc copy distribution list for THI-1 & 2:per 800410 ltr. encl
 ARNDLD.R C Metropolitan Edison Co 80/09/30 App
- 8010220030 Responds to itr expressing concern re venting of Kr-85 from TMI-2 Cormission findings indicate that potential physical health impact from use of Kr-83 venting strategies is negligible Relevant documents forwarded Wo encls SNYDER.B J TMI Program Office 80/09/30 2pp.
- --B010220032 Expresses concern re possible correlation between venting of Kr-85 from TM1-2 % son's illness KUNKEL:H Affiliation Unknown 80/09/30, 1p
- 8010100107 Responds to 800804 ltr re TMI accident NRC amended regulations to upgrade requirements for emergency planning around nuclear facilities W/o encl NUREC-0662 & EPA dose assessments SNYDER.B J TMI Program Office 80/10/01 1p
- 8010150094 Responds to BOOBOB ltr to HR Denton re contaminated water at TMI Every effort is being made to ensure public health & safety N/o encl programmatic EIS
 SNYDER:B J. TMI Program Office B0/10/01 1p
- 8010280072 Responds to 800B18 inquiry re Frix concerns over purging of radioactive Kr-85 gas. Forwards 800612 temporary license mod. 800612 memorandum & order discussing rationale for decision & Vols 1 & 2 of NUREO-0662 re decontamination W/o encl DIRCKS.W U Office of the Executive Director for Operations 80/10/03 4pp
- 8010230431 Responds to 800324 ltr re effects of low level radiation. Ionizing radiation has effect on human body directly proportional to level of dose.

 SNYDER.B.J TMI Program Office. 80/10/06 2pp

- --8010230433 Requests info on long-term effects of low level radiation.
 BIRD, W.H. Affiliation Unknown 80/03/24 1p
- 8010230439 Responds to encl 800402 ltr to HR Denton re timing of placing TMI-2 into eve NRC requires successful completion of licensing requirements prior to declaration of commercial operation SNYDER, B J TMI Program Office 80/10/06 3pp
- 8010230450 Responds to encl 800318 ltr to President Carter expressing concern re util decision to withdraw dividend payments NRC has final authority to decide who assumes responsibility for facility when licensee cannot continue operation SNYDER, B J TMI Program Office 80/10/06 4pp
- 8010230453 Responds to 791003 telegram re use of EPICOR-II & storage of water at TMI NRC does not permit discharge of water processed by EPICOR-II Releases to Susquehanna River contain low or nondetectable levels of radioactivity SNYDER, B J. TMI Program Office 80/10/06 2pp
- --8010230457 Expresses concern on util pressure for NRC approval of EPICOR-II for processing wastewater Full environ review of all processing & disposal alternatives is necessary prior to approval WOHLBEN/A, B. Lancaster, PA 79/10/03 3pp
- 8010230463 Responds to enci 800305 ltr to President Carter re custs resulting from TMI accident State public util commissions & FERC have primary responsibility re alectricity rates SNYDER, B J. TMI Program Office 80/10/06 4pp
- B010230638 Responds to 790402 itr to President Carter re nuclear power plant safety Entombment of TMI-2 reactor bidg insufficient due to need for removal of fuel NRC has undertaken extensive efforts to improve emergency preparedness SNYDER, B J. TMI Program Office B0/10/06 App.
- --B010230645 Forwards E Mikofelvy 790402 ltr to President Certer offering suggestions on nuclear power safety. Requests response ZINN,P K President of US & Executive Offices 79/04/11 2pp
- B01023070B Responds to B00327 ltr sypressing concerns re effects of radiation from TM1-2 Offsite collective dose indicated minimal risk to population BNYOER, B. J. TMI Program Office 80/10/06 2pp.
- --8010230712 Expresses concerns re radiation release at facility ADAMB. J Affiliation Unknown. 80/03/27 2pp
- 8010270077 Responds to 800328 ltr re accident All licensed operators at BLW facilities received special training & written exam on transient situations, Long-term commitments are being developed by NRC Licensing Branch SNYDER, S. J. TMI Program Office 80/10/06 2pp
- --8010270080 Disapproves of NRC handling of accident & resulting consequences.

 ©ERVABIO:B Affiliation Unknown. 80/03/28 2pp
- 8010270095 Responds to 1tr to First Lady re radiation effects on children & pregnant women. Studies indicate that accident resulted in min risk to offsite population Forwards NUREG-0558 & news release W/o encl SNYDER. B J. TMI Program Office 80/10/06. 7pp.
- 8010270120 Responds to 800804 itr to President Carter re suggestion for evacuation notification NRC/FEMA Steering Committee developed criteria to upgrade all emergency plans. Licensee plans provide for prompt notification

 BNYDER, B. J. TMI Program Office. 80/10/06 4pp
- 8010270123 Responds to 800403 ltr to President Carter re use of federal funds for TMI cleanup. NRC has statutory authority to ensure that public health & safety will be protected should util be unable to carry out responsibilities.

 SNYDER, B J TMI Program Office 80/10/06. 2pp.
- 8010270042 Responds to 800514 itr re info made available to public re accident & public involvement w/nuclear plants President's Commission on Accident at TMI included members of public M/o encl summary of NURCO-0558 & info on licensing SNYDER,B.J TMI Program Office, 80/10/10. 2pp.
- ---8010270045 Expresses concern re dissemination of info re accident to public & participation of public in decisionmaking process. MACNAIR.8 Affiliation Unknown, 80/05/14, 2pp

- 8010270050 Responds to 800323 ltr urging abandonment of facilities. Public hearing will be conducted re Unit 1 respening Util has not yet submitted proposal for overall recovery of Unit 2 W/o encl 790829 order & notice of hearing SNYDER: B J TMI Program Office 80/10/10 2pp
- --8010270054 Urges abandonment of facilities Conventional power plant should be built BERNSTEIN M R Affiliation Unknown 80/03/23 ip
- 8010270089 Responds to 1tr opposing use of nuclear power & expressing concern re possibility of more accidents Licensee has not yet submitted proposal for overall recovery of facility W/o encl PA Dept of Health press release & 790807 order SNYDER, D J THI Program Office 80/10/10 2pp
- --8010270063 Expresses concern re-possibility of another accident similar to THI Alternative energy sources should be utilized ROOT, L. D. Affiliation Unknown 80/10/10 2pp
- 8010270067 Responds to 791120 ltr to President Carter requesting investigation of personnel error in TMI accident.President's Commission on Accident at TMI concluded that no sabotage was involved. M/o encl notice of violation.

 ENYDER: 3 J. TMI Program Office 80/10/10 2pp
- --8010270073 Forwards JA Housil 791120 ltr to President Carter requesting investigation of personnel error re accident. SEAL M M. President of US & Executive Offices 79/12/27. 2pp
- 8010270087 Responds to 800330 ltr to DR Muller re use of energy sources other than nuclear power DOE is agency responsible for R&D of alternative resources of energy BNYDER, B J TMI Program Office 80/10/10 3pp
- ---B010270092 Opposes licensing of new nuclear power plants. Funding should be increased for alternative sources of energy. HANSEN.R Affillation Unknown B0/03/30 19
- 8010270097 Responds to encl ltr to President Carter re health effects of accident at facility Offsite collective dose associated w/releases from 790328-0407 represents minimal risks. W/o encl NUREG-0558 summary & PA Dept of Health press release GNYDER, D. J. TMI Program Office 80/10/10 2pp
- 8010280603 Responds to encl 800403 ltm to President Carter me future of facilities. Public hearing will be held me reopening of Unit 1. Util has not yet submitted proposal for overall recovery of Unit 2 U/o encl 790809 order.
 SNYDER, B J TMI Program Office 80/10/10. 3pp.
- 8010280642 Responds to 800328 ltr opposing reopening of facilities Public hearing will be held re reopening of Unit 1 Util has not yet submitted proposal for overall recovery of Unit 2 Hz/a and documentation SNYDER.B. J. TMI Program Office. 80/10/10 2pp
- --8010280447 Opposes reopening of facilities & expresses concern re disposition of waste water, CIANCIOS1,P Affiliation Unknown, 80/03/28 2pp
- 8010220516 Urgss permanent shutdown of facilities. Util cannot safely operate nuclear power plant.
 CHEBHAN, A Affiliation Unknown 80/10/12 ip
- B0102B0073 Responds to B00403 ltr re effects of radiation release Except for releases to Busquehanna River of liquids containing low or nondetectable levels of radioactivity, contaminated water release not permitted W/o encl SNYDER, B J. TMI Program Office. 80/10/16 App
- ---BO10280077 Deplores release of radioactivite into air,water & soil.
 Requests development of alternative energy sources.
 BRINK:T Affiliation Unknown 80/04/05. ip.
- 8010280083 Responds to 800629 telegram to President Carter re Kr-85 release. Purging method considered most effective atternative. Public hearing re TMI-1 restart will be held H/o encl NUREO-0662 & 800612 & 790809 orders 8NYDER, B J TMI Program Office 80/10/16 4pp.
- 8010280134 Responds to 800610 ltr re decontamination of reactor bldg atmosphere, NUREQ-0662, Vols 1 & 2. Commission 800612 order for temporary license mod & Commission 800612 memorahdum & order encl. N/o encls
 DENION, H R. Office of Nuclear Reactor Regulation, Director. 80/10/16 10pp.

- 8010230369 Discusses need to educate citizens about nuclear power as viable energy alternative
 BIRD.H H Affiliation Unknown 80/10/18 ip
- 8010280030 Responds to 790731 ltr re effects of 790328 accident Based on current info,no basis for Met Ed license revocation Purging method considered most effective alternative H/o enci NURE9-0662 & 800512 orders
 SNYDER. II J TMI Program Office 80/10/20 3pp
- --8010280033 Requests Met Ed license be revoted due to dumping of 4,000 gallons of untested water into Susquehanna River ROHE, J Affiliation Unknown 79/07/31 2pp
- 8010290046 Responds to FBIA request for reason & data TMI Commission used to base public health & safety conclusions & amount of gas vented from facility Documents are available in PDR Estimates 2 4 million of gas vented from facility FELTON.J M. Division of Rules and Records 80/10/22 1p
- J Insurance & indemnity information
- 8010280307 Requests endorsements & copy of Amend 8 to Policy B-64 DINITZ.I Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24 Ip
- 8010140424 Forwards facility indemnity fee for 800928-810927.in response to NRC 800826 invoice HOVEY.Q K Metropolitan Edison Co 80/10/06 2pp
- P Operating license stage documents & correspondence
- 8010030305 Responds to NRC 800718 ltr (TMI-80-109) re evaluation of EPICOR-II wastes Comments on supply of info, details of util evaluation drawings & liner fabrication & surveys Drawings withheld (ref 10CFR2 790) HOVEY, O K Metropolitan Edison Co 80/09/04 7pp
- 8010140280 Requests 90-day extension for comment period to avaluate BES re facility cleanup.

 SMITH.P Newberry Township TMI Steering Committee B0/09/08 ip
- 8010140286 Requests 90-day extension for comment period on DES refacility cleanup KIRCKNER.P Affiliation Unknown 80/09/10 ip
- BO10140617 Requests 90-day extension of comment period public hearings, Citizens Advisory Committee & funds to support independent scientific research for DES refacility cleanup MUSBER,M Affiliation Unknown 80/09710 2pp.
- 8010140290 Requests 90-day extension for comment period on DES refacility cleanup GDL092EN.M S Affiliation Unknown 80/09/12 ip.
- 8010020069 Advises that util decontamination method considered extensive enough to require written safety evaluation Raquests schedule of submittal within two wis SNYDER/B J TMI Program Office 80/09/15 2pp.
- 3010140275 Requests 90-day extension for comment period on DES re facility cleanup BUCHTER:R Affiliation Unknown 80/07/15 1p.
- 3010220410 Requests, on behalf of Little Energy Task Force, extension of time period for comment on NUREG-0683, draft programmatic EIB re decontamination & waste disposal at facility, to 90 days or more HAFNER, B Affiliation Unknown 80/09/16 1p
- 8010220414 Requests extension of time period for comment on NUREO-0683, draft programmatic EIB re decontamination & waste disposal at facility, to 90 days or more, GARRARD-8 Affiliation Unknown 80/07/17 ip
- 90:022045: Requests extension of time period for comment on NUREO-0683, draft programmatic EIS re decontamination & waste disposal at facility, to 90 days or more KOVACS,D J. Affiliation Unknown 80/09/18 ip
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing 80/09/19 28pp

- 8010220403 Requests extension of time period for comment on NUREG-0683, draft programmatic EIS re decontamination & waste disposal at facility, to 90 days or more ELLIDTIC W Affiliation Unknown 80/09/19 1p
- 8010010641 Notifies that submerged demineralizer sys description document will be forwarded by 800930 HOVEY.O K Metropolitan Edison Co 80/09/23 ip
- B010270214 Four itrs requesting extension of 45-d44 period for public comment on programmatic EIS re cleanup GALLAGHER, J. ZIRNITE, P. Affiliation Unknown MCCONNAUGHHAY Maryland, State of B0/09/25 4pp
- 8010070428 Responds to 800915 ltr re EPICOR I operation Wastewater will be transferred per Procedure 3104-4 7 & EPICOR I operations will be performed per Procedure 3104-4 3 HOVEY, G K Hetropolitan Edison Co 80/09/26 2pp
- B010070447 Advises of tentative schedule for next containment bldg entry on B01016 Activities planned for entry include radiation surveys in areas of core flood tanks & air cooler & repair of personnel airlock HDVEY, O K Metropolitan Edison Co 80/09/29 ip
- B010240050 "Answers to Frequently Asked Questions About Cleanup Activities at THI-2" SKYDER, B J THI Program Office NUREO-0732 80/09/30 34pp Available at 0FD \$2.25
- B010220075 Responds to State of PA 800911 request for extension of comment period for NURCO-0683, draft programmatic EIS redecontamination of TMI-2 FR notice granting extension to 801120 encl AHEARNE, J F Commissioners 80/10/01 ip
- --8010220081 Notice of extension until B01120 for comment period re NUREG-0583 draft programmatic EIS for decontamination of THI-2 SNYDER, B. J. THI Program Office 80/09/18 2pp
- --B010220090 Requests extension until 801120 for comment on draft programmatic E18 for decontamination of TMI-2 THORNBURG, H D Pennsylvania, State of 80/09/11 1p
- 80i0100343 Forwards responses to NRC 800822 comments & questions re EPICCR-11 resin solidification program HQVEY.G.K. Metropolitan Edison Co 80/10/03 15pp
- 8010140418 Forwards diagram presenting decision logic for disposal of EPICOR-II & low activity 8D8 liners Current review indicated that most probable near-term action relates to solidification of low activity EPICOR-II liners W/o encl, HOVEY, O K Metropolitan Edison Co 80/10/06. 2pp
- 8010240276 Responds to encl 800328 itr to President Carter re TMI safey concerns Comment period for programmatic EIS was extended to 801120.

 RNYDER, B J TMI Program Office 80/10/06 2pp
- B010240582 Forwards federal, state & local comments re draft programmatic EIS re decontamination & disposal of radwaster resulting from TMI-2 accident List of comments encl SNYDER, B J TMI Program Office B0/10/06 2pp
- --8010240890 Comments on draft programmatic EIS re TMI decontamination program Document does not guarantee absence of risk re TMI cleanup, or solve radwaste disposal problem PAREDNS.C H Affiliation Unknown 80/09/12 ip
- --8010240595 Comments on draft programmatic EIS re TMI decontamination program Public welfare should recieve priority over corporation profits.

 LASRABCA: C., J Affiliation Unknown 80/09/19 1p.
- ---B010240599 Comments on draft programmatic EIB re TMI decontamination program BOT suggests Route BI as safer road for waste transport to WA disposal site KETCHUM.A 0 Pennsylvania. State of B0/10/06 2pp.
- --8010240605 Comments on draft programmatic EIB re TMI decontamination program Health study of duration should be part of repair & recovery operation
 DOHERTY, J F Doherty, J F 80/09/26. 1p

- --8010240609 Statement by MD Ad Hoc Committee on TMI re draft programmatic EIB re TMI decontamination program Problem of how & where to dispose of wastes was inadequately considered MAY.K. Affiliation Unknown 80/09/30 App
- --8010240616 Comments on draft programmatic EIS re TMI decontamination program Radioactive water should be promptly processed to avoid potential accidental release of highly contaminated water into Chesapeake Bay
 KELLY,N 9 Chesapeake Bay Foundation 80/09/30 7pp
- --8010240620 Testimony at NRC public hearings re draft programmatic EI8 for decontamination of TMI NRC safety stds for tritium based on outdated dosage calculations that grossly underestimate toxicity to human life
 8TILLMAN.I N Affiliation Unknown 80/10/06 App
- --8010240623 Comments on draft programmatic EIB re TMI decontamination program Sections on psychological stress are counterproductive Draft is misleading due to implication that recipient can perceive radiation damage GDLDSERGER, L. JENKINS, A. SACKEIM, H. New York Univ. 80/09/16
- BO10270524 Responds to BO0917 ltr re H Hocker suggestion that public funds be made available to intervenors in NRC proceeding on facility cleanup Use of NRC FYB1 funds for intervenors is problibited by statute
 KAHMERER.C Office of Congressional Affairs BO/10/08 ip
- --B010270529 Requests consideration of encl H Hocker ltr re draft programmatic EIS & use of public funds for facility cleanup, BCHWEIKER, R B Senate B0/09/17 ip
- B010160488 Discusses NRC 800201 imposition of specific limits re processed water storage tank isotope concentration, Proposes radionuclide concentrations to satisfy all criteria & administrative controls for processed water storage tanks HOVEY, OK Metropolitan Edison Co. 80/10/09. 2pp
- E010160508 Discusses proposed joint mgt review of TMI-2 cleanup activities First meeting is scheduled for 801010 at PA Dept of Environ Resources Lists proposed agenda topics ARNALDAR C Metropolitan Edison Co E0/10/09 2pp
- 8010280654 Responds to 791017 ltr re use of EPICOR-II water treatment sys at facility Period for public comment on environ assessment was announced in FR on 790820 & ended 790920. H/o encl documentation SNYDER, B J TMI Program Office 80/10/10 2pp
- --8010280660 Opposes use of EPICOR-II waste treatment sys at facility STRICKLER.D Affiliation Unknown 79/10/17. ip.
- 8010200438 Notifies that safety evaluation of submerged demineralizer sys per 10CFRSO 59 will be submitted on 801201.in response to NRC 800913 ltr All requested safety evaluation elements were previously addressed in 800410 submittal HOVEY.0 K Metropolitan Edison Co 80/10/13 4pp
- 8010200452 Responds to NRC 800718 ltr re Rogovin Rept rafs Extension requested until 801021 to suppl 800824 response for Items 1,5,6 & 9
 HOVEY, G K Metropolitan Edison Co 80/10/13 ip
- 8010210640 Responds to NRC 800713 request for safety evaluation resutil proposed submerged demineralizer sys Util 800410 technical evaluation rept describes sys & analysis results & meant for NRC review & approval Bafety evaluation ready by 801201.

 HDVEY: 6 K Metropolitan Edison Co 80/10/13 5pp
- 8010270356 Forwards ltrs commenting on programmatic EIS re TMI-2 decontamination received subsequent to 801006 transmittal ltr 8NYDER, B J TMI Program Office 80/10/15 6pp
- --8010290357 Comments on draft EIB re facility radwaste decontamination & disposal Army does not have any projects, studies or proposed studies in immediate facility area or downstream from plant. Illegible ltr sncl
 TRIESCHMAN,W E Army, Dept of, Corps of Engineers 80/09/25. 3pp
- --8010290358 Comments on draft EIS re facility raduaste decontamination & disposal # Susquehanna Valley Alliance 80/10/06 5pp.

- --B010290389 Comments by Council of Environ on draft EIS re facility radwaste decontamination & disposal Adverse affects upon state resources not anticipated Reserves right to comment further if radwastes are transported through state JACKSON, J B Virginia, State of B0/10/01 9pp
- --8010270360 Protests inaffectiveness of public comment procedure provided for NUREO-0683 re TMI-2 decontemination RANDALL, W 8 Affiliation Unknown 80/07/29 ip
- --8010290361 Comments on draft EIS re facility radwaste decontamination & disposal Document is very disappointing appears to be excessive in regulatory obstruction & should be rejected RANDALL,W B Affillation Unknown 80/09/30 4pp
- 8010310423 "TMI-2 Recovery Quarterly Progress Rept, Jul-Bept 1980 " HDVEY: © K Metropolitan Edison Co 80/09/30 140pp
- 8010210507 Forwards Revision i to "Bys Description of Submerged Demineralization Bys " HOVEY.O K Metropolitan Edison Co 80/10/16 2pp.
- --801021050B Revision i to "Sys Description of Submerged Demineralization Sys" * Matropolitan Edison Co. 80/10/03 100pp
- 8010230500 Documents submission of submerged demineralizer systems description to JB Wiebe of TMI Program Ofc HDVEY, G K Metropolitan Edison Co 80/10/16. 1p
- BO1024042B Requests 2-wk extension to complete contingency plan for transfer & storage of contaminated water in facility containment bldg sump Plan will be submitted on 801031 ANNOLD,R C General Public Utilities GPU Service Corp 80/10/17.
- 8010280403 Informs that licensee is in final process of developing contingency plan for transfer & storage of contaminated water in containment bldg sump. Hill require addi 2 wks to complete development of plan Hill file plan by 801031.

 ARNGLD, R C Metropolitan Edison Co. 80/10/17 ip
- 8010280428 Suggests 801029 as date for meeting w/NRC to discuss plans re EPICOR-II first stage liner sampling per NRC 801003 ltr HOVEY, O K General Public Utilities OPU Service Corp. 80/10/20, io.
- B010270321 Forwards preliminary radiological data developed during 800723 & 15 re-entries into reactor containment Also forwards preliminary sketches of radiation survey data acquired during 801014 re-entry.

 RUDDLPH:R L Bechtel National/Inc. 80/10/23 16pp.
- Q Inspection reports, IE Bulletins & correspondence
- E010130300 Forwards IE Insp Repts 50-320/80-10 & 50-320/80-14 on 800317-0411 Waste Packaging Insp Rept 13000046/80-72 also encl ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/12 2pp.
- --B0101B0511 IE Insp Repts 50-320/B0-10 & 50-320/B0-14 on B00317-0411.
 Noncompliance noted failure to use leak resistant containers for radioactive liquid shipments & failure to comply w/ authorized packaging for Type A shipment fASANGA N : THONUS L H , BHANBAKY, M.M. Region 1, Philadelphia, Office of the Director 80/07/30 App.
- --8010150518 Waste Packaging Insp Rept 15000046/80-72 on 800610.
 Noncompliance noted: loose locking ring & broken weld observed on shipping containers
 ZURAKONSKI, P Region 5. San Francisco, Office of the Director THOMAS, R. D. BOOK, H. E. Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch 80/06/30 App.
- BO10010407 Informs that IE Insp Rept number 50-320/79-i1 is unused number in TMI-2 insp numbering chronology.
 BRUNNERE J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch BD/08/26 ip
- 8010060091 Discusses 800910 meeting w/util in THI/NRC program of a reoutstanding issues relative to IE Investigation Rept 50-320/79-10 & responses to items of noncompliance GRIER, B.H. Region i, Philadelphia. Office of the Director 80/08/27. ip
- B010060140 Responds to IE Bulletin 80-19 Referenced mercury-wetted relays not used in reactor protection sys.

 HOVEY, 9 K. Metropolitan Edison Co 80/08/29 1p.

- 8010060145 Responds to IE Bulletin 79-21 re temp effects an level measurements. Bys being used during recovery is external to containment & is not susceptible to conditions described in bulletin.
 HDVEY-O K Metropolitan Edison Co 80/08/29 ip
- 8010010733 Responds to IE Bulletin 79-25 re failure of Westinghouse BFD releys. BFD relays in use are of four pole type & problem does not relate to four pole relays. HOVEY.0 K. Metropolitan Edison Co. 80/09/08. 1p.
- 8010040088 Advises of cancellation of 800910 meating at TMI/NRC program ofc Dutstanding issues re IE Investigation Rept 50-320/79-10 already discussed ORIER, B.H. Region i, Philadelphia, Office of the Director 80/09/10 12
- 8010200005 Responds to IE Bulletin 79-28, "Possible Halfunction of NAMCO Hodel EA180 Limit Switches at Elevated Temps." Specified switches are not utilized at facility. HOVEY.Q K Hatropolitan Edison Co. 80/09/13 ip.
- 8010200375 Responds to IE Bulletin 79-24, "Frozen Lines." Prior to Hinter 1980-81, all depts will be instructed to review winterization protection.
 HOVEY.G K Metropolitan Edison Co. 80/07/15 ip.
- 8010270182 Responds to IE Bulletin 80-12, "Decay Heat Removal Bys Operability " Since facility can safely operate in loss to ambient cooling mode, no corrective action is necessary, HOVEY, O K Metropolitan Edison Co 80/09/22 2pp
- B010240303 Ack receipt of B00828 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/80-03 & 50-320/80-03.

 MARTIN.W. O. Region i. Philadelphia, Safeguards Branch. B0/09/23.
- --8010240307 Responds to NRC 800731 ltr re violations nuted in IE Insp Repts 50-289/80-03 & 50-320/80-03. Corrective actions: withheld (ref 10CFR2 790) HERBEIN, J O. Metropolitan Edison Co 80/08/28, 1p.
- ---8010240315 Forwards IE Insp Repts 50-289/80-03 & 50-320/80-03 on 800201-0327 & notice of violation Notice of violation withheld (ref 10CFR2.790).
 MARTIN-W O. Region 1, Philadelphia, Safeguards Branch. 80/07/31
- --8010240322 IE Insp Repts 50-289/80-03 & 50-320/80-03 on 800201-0327 Noncompilance noted failure to limit access to protected area & vital area & failure to test personnel search area & visa, area & railors to test product search aquipment Details withheld (ref 10CFR2 790).
 DEVLIN.J.W. Region i, Philadelphia, Safeguards Branch.
 BHEPPARD.R.E., BAILEY, R.J. Region i, Philadelphia, Office of the Director. 80/08/21. 2pp.
- 8010270447 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolent During Steem Generator Decontamination." No specific action or response requested. ORIER, B. H. Region i, Philadelphia. Office of the Director. 80/09/26 1p.
- 8010230205 Responds to 1E Bulletin 80-15. "Possible Loss of Emergency Notification Bys (ENS) w/Loss of Offsite Power " Review of ENS telaphone installation was conducted in conjunction w/ Bell of PA.
 HUKILL-H.D. Metropolitan Edison Co. 80/09/29. 2pp.
- B010230212 Responds to IE Bulletin B0-10, "Contamination of Nonradioactive Bys & Resulting Potential for Ummonitored, Uncontrolled Release & Radioactivity to Environ " Evaluation results will be submitted by B01130.
 H0VEY, 9 K. Metropolitan Edison Co. 80/09/30. ip. 80/09/30. ip.
- 8010230306 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Buitches," Buitches function as local permissive switches in unit & as control switches in control room, HOVEY, Q. K. Metropolitan Edison Co. 80/09/30, 2pp.
- 8010240139 Forwards JE Circular 80-22, "Confirmation of Employee Qualifications " No written response required. GRIER. B. H. Region 1. Philadelphia, Office of the Director. 80/10/02. ip.
- 8010310021 Responds to IE Bulletin 80-18, "Meint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture." Further investigation may be necessary re makeup & purification sys. HOVEY, G. K. Metropolitan Edison Co. 80/10/07. 1p.

- 8010300279 Ack receipt of 800925 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/80-09 GRIER, B H Region I. Philadelphia, Office of the Director 80/10/08 ip
- --8010300287 Responds to NRC 800805 ltr re violations noted in IE Insp. Rept 50-320/80-09. Corrective actions procedures revised to ensure positive control of cutting, welding, grinding & open riammwork HOVEY,O.K Matropolitan Editon Co 80/09/25. 3pp.
- --8010300310 Forwards IE Insp Rept 50-320/80-09 on 800427-0531 & notice Of violation

 GRIER B H Region 1, Philadelphia, Office of the Director 80/08/05. 2pp.
- --8010300323 Notice of violation from insp on 800427-0531
 * Region 1, Philadelphia, Office of the Director. 8 80/07/21 3pp
- --8010300337 IE Inep Rept 50-320/80-09 on 800427-0531, Noncompliance
- 8010280176 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested ORIER, B.H. Region 1. Philadelphia. Office of the Director, 80/10/10 1p
- R Periodic operating reports & related correspondence
- 8010170345 Forwards monthly repts of aquatic studies for Feb-Jul 1980. HICKEY, C.R. Environmental Engineering Branch. 80/09/11. 1p.
- --8010170347 "Aquatic Study Monthly Rept for Feb 1980." Prepared for NARDACCI.O A. Ichthyplogical Associates, Inc. 80/09/11 19pp
- --8010170349 "Aquatic Study Monthly Rapt for Mar 1980." Prepared for Met Ed NARDACCI,Q A Ichthuological Associates, Inc 80/09/11 26pp
- --8010170352 "Aquatic Study Monthly Rept for Apr 1980 " Prepared for Het Ed. NARDACCI, G. A. Ichthwological Associates, Inc. 80/09/11, 28pp.
- --- 8010170353 "Aquatic Study Monthly Rept for May 1980." Prepared for NARDACCI, C A Ichthyological Associates, Inc. 80/05/31, 31pp
- --8010170355 "Aquatic Study Monthly Rept for June 1980 " Prepared for nev Es. NARDACCI:Q.A Ichthyological Associates;Inc 80/09/11. Gipp
- --8010170357 "Aquatic Study Monthly Rept for Jul 1980 " Prepared for Met Ed NARDACCI,O A — Ichthyological Associates, Inc. BO/09/11 29pp.
- 8010030535 Forwards weekly status rept for wk of 800914-20 COLLINS.J. T. TMI Program Office. 80/09/22 6pp
- E0101607t5 Forwards status rept for wk of 800921-27. COLLING, J T. TMI Program Office, 80/09/29, 6pp
- 8010220136 Forwards waskly status rept for wk ending 801004 COLLINS, J T. TMI Program Office, 80/10/06 5pp.
- 8010220431 Forwards "TMI-2 Recovery Quarterly Progress Rept for Period Ending 800930 * HOVEY, Q.K. Matropolitan Edison Co. 80/10/15, 1p.
- --8010220432 "TMI-2 Recovery Quarterly Progress Rept for Period Ending * Metropolitan Edison Co. RR-02-80 80/10/15 138pp
- 8010310418 Forwards third quarterly rept for Jul-Sept 1980. Includes radiation safety program rept per Tech Specs & 9, 1, 4. HOVEY, O. K. Hetropolitan Edison Co. 80/10/15 1p.
- 8010270277 Forwards data compiled by PA Dept of Environ Resources reactual measured levels of radionuclides in river fishes & other blots for Oct-Dec 1979
 BALLARD R. L. Environmental Engineering Branch. 80/10/21. App.

- 8010280433 Forwards Page 4-5 to third quarterly rept, inadvertently omitted from original document DECK,D A Metropolitan Edison Co 80/10/23 tp
- --8010280435 Page 4-5 to third quarterly rept.
- BOLO310375 Forwards Pg 4-5 of third quarterly rept which was inadvertantly omitted from rept Requests that page be inserted accordingly DECK. D A Metropolitan Edison Co 80/10/23, 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 8010140374 PNO-TMI-80-039 on 800708, health physics technician was taken offsite in ambulance due to injuries sustained to head while working in auxiliary bidg. Upon leaving site, individual was conscious & not contaminated CONIE, R J., FABAND, A N., COLLING, J.T. THI Program Office. 80/07/08 10
- 8010140357 PNO-TMI-80-040 on 800716, containment personnel airlock 2 inner door was successfully opened. Upon closure of inner door, seal rings failed leakage test Licensee & NRC review of matter continues.

 CONTE,R J., FABANDIA, N Region 1, Philadelphia, Office of the Director, COLLING.J T TMI Program Office 80/07/16, 1p.
- 8010140350 PND-TMI-80-040A on 800716, containment bldg personnel airlock inner door seals failed to pass seal leakage test.

 Bubsequent measures to correct leakage failed to mest leakage criterion. CONTE:R J., FABANO.A.N Region 1: Philadelphia: Office of the Director, COLLING.J T TMI Program Office BO/07/17 1p
- 8010100419 PNO-THI-80-041 on 800719, while dewatering used filter liner, leaking hose connection spilled 5 gallons contaminated water in area for spent filters Area contaminated was approx 2x4 ft. Licensee plans to decontaminate area, BARLEY, W., FASANO, A., COLLING, J. THI Program Office, 80/07/21, 1p.
- 8010100417 PNO-TMI-80-042 on 800723 Met Ed engineers made first postaccident entry into reactor blog Entry leated 20 minutes & was limited to sector between shield ring & wall Each antrant received less than 300 millirem KALMANO, FASANO, A COLLING, J THI Program Defice. 80/ THI Program Office, 80/07/23 ip
- 8010100415 PNO-TMI-80-043 on 800808.RCS boundaries were extended bayond containment bidg. Decay heat sys valves were opened to permit future openation of mini decay heat removal sys. POINDEXTER.T.C., BELLAMY.R.R., COLLINS.J.T. THI Program Office 80/08/08. ip
- 8010230214 RO 80-38/1P; on 800825, per GA Kunder & RJ Conte conversation, auxiliary bidg air cleanup sys evaluated as being inoperable Flowrate failed to mest min flowrate requirement. Condition has existed more than 7 days. Details to follow. HOVEY, O.K. Metropolitan Edison Co. 80/08/26. ip.
- 8010140308 RO confirms 800909 conversation between QA Kunder of util & RJ Corterresident inspector, re failed in-core thermacouple M-9. Further details will be included in followup rept MOVEY, 9 K Metrapolitan Edison Co 80/09/10 ip
- #010100374 PND-TMI-80-045 on 800915, NRC approved major changes in organization which establishes General Public Utils Nuclear Ordey & which includes revised plant staff organizations. HAVERKAMP, D. R TMI Program Office. 80/09/16. 2pp.
- G0100B0356 PNO-I-B0-131: on 800918, radio station KYW rebroadcast news repts of 790328 TMI-2 accident causing Region 1 employee to alert regional mgt BRIQGS.L., KEINIO,R., Region 1, Philadelphia, Office of the Director 80/09/18. 2pp.
- 8010030409 Forwards LER 80-039/03L-0. HOVEY, Q K. Metropolitan Edison Co. 80/09/22. 1p
- --8010030412 LER 80-039/03L-0 on 800822, during 4331-8A2 surveillance test-two bottles in cable & transformer rooms fire suppression sys observed below halon content min Gaussd by procedural deficiency, Low main bank bottle replaced. CHAPLIN.S. Metropolitan Edison Co. 80/09/22 2pp.
- 8010010484 Forwards cancelled LER 80-038 HOVEY, Q. K. Metropolitan Edison Co. 80/09/24. 1p.
- --8010010409 LER 80-038 has been cancelled. # Metropolitan Edison Co. 80/09/24.

- B010090401 R0 B0-044/IP on B00924, during planned reactor bldg entry, leak rate test of outer door on Personnel Airlock I revealed that door did not meet required limits Door could not be returned to svc within 24-h Details will follow HDVEY. O K Metropolitan Edison Co B0/09/26 1p
- 8010080471 Forwards LER 80-043/03L-0 HGVEY, C K Metropolitan Edison Co BO/10/02 1p
- --8010090474 LER 60-043/03L-0 on 800902 during operation of auxiliary bldg ventilation sys B train fan 8D tripped Caused by circuit breaker malfunction. Breaker replaced & fan returned to svc CHAPLIN,8 D Metropolitan Edison Co 80/10/02
- 8010140413 Notifies that LER 80-040/03L-0 will be submitted by 801008 HOVEY, Q K Metropolitan Edison Co 80/10/06 2pp.
- 8010200419 Forwards LER 80-042/03L-0 HGVEY, O K Metropolitan Edison Co 60/10/09 ip
- --- 8010200422 LER 80-042/03L-0. on 800909, during surveillance procedures, RCB flow instrument discovered out of calibr & declared inoperable. Caused by electronic component drift Instrument recalibr & surveillance completed.

 CHAPLIN. B. D. Hetropolitan Edison Co. 80/10/09. 2pp
- B010200424 Forwards LER 80-041/01L-0 HGVEY, Q. K. Metropolitan Edison Co 80/10/09, ip
- --B010200426 LER 80-041/OIL-0 on 800909, M-7 incore thermocouple exhibited arretic behavior. Cause of failure not known. No action will be taken re failure.

 CHAPLIN 8 D. Metropolitan Edison Co. 80/10/07, 2pp
- 8010210527 Forwards cancelled LER 80-040 HOVEY, Q K. Metropolitan Edison Co B 80/10/09 200.
- --B010210528 LER 80-040 has been cancelled. COLLING, M Metropolitan Edison Co. 80/10/09. ip.
- 8010270046 PND-THI-80-047 on 801016, third entry into reactor bldg by three health physics technicians & two maint men. Max exposure less than 500 mrems Radiological surveys performed & photographs taken at 305 & 347 ft elevations KALHAN, O. BELLAMY, R., COLLINB, J., Region I, Philadelphia, Office of the Director. 80/10/16 2pp.
- 8010300577 PNO-TM1-80-48 on 801020, licenses reported that two groups asked permission to use TMI observation of groups asked permission to use TMI observation of groups demonstration on 801021 Licensee denied permission. Two groups are TMI Alert & American Indian Movement CONTE.R.J., FAJANO.A.N. Office of Inspection & Enforcement, Office of the Director 80/10/20 2pp
- 8010310426 Forwards LER 80-044/01L-0 HOVEY, O K. Metropolitan Edieon Co 8D/10/27 ip
- --B010310439 LER 80-044/01L-0 on 800925, seals of personnel airlock 1 outer door failed seal leak rate test Caused by maifunctioning door seals. Beals replaced & tested satisfactorily.

 CHAPLIN.B D Metropolitan Edison Co 80/10/27 2pp.
- T. Hearing transcripts on non-antitrust matters
- 8010220138 Transcript of IE 790517 interview w/JP Donnachie radiation chemistry technician at facility at time of accident Pp 1-65. DONNACHIE, J. P. Hetropolitan Edison Co. 79/05/17, 66pp.
- 8010220101 Transcript of JE 790620 interview w/WA Yeager, Instrument Man B at facility at time of accident Pp 1-38 YEAGER, W. A Metropolitan Edison Co. 79/06/20. 39pp.
- B010310006 Forwards transcript of B01006 meeting in Lancaster PA w/Busquehanne Valley Alliance & Lancaster Mayor A Morris redraft programmatic EIS re decontamination of fecility SNYDER.B. J TMI Program Office B0/10/27. 2pp.
- --9010310010 Transcript of 801006 public meeting in Lancaster/PA regarding NRC draft programattic EIS re decontamination of facility.Pp 1-127.

 * TMI Program Office. 80/10/06. 129pp

DOCKETED ITEMS

U Congressional/Executive Correspondence

- 8010280280 Responds to recommendations of QAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AHEARNE, J F Commissioners 80/10/07 2pp
- --8010280284 Responds to recommendations of GAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIB re decontamination of TMI-2 prepared AHEARNE, J. F. Commissioners 80/10/07 2pp
- --8010280288 Responds to recommendations of GAD rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TKI-1 Draft programmatic EIS re decontamination of THI-2 prepared AHEARNE, J F Commissioners 80/10/07 2pp
- --B010280289 Responds to recommendations of QAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIR re decontamination of TMI-2 prepared AHEARNE, J F Commissioners B0/10/07 2pp
- --8010280294 Responds to recommendations of GAO rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EES re decontamination of TMI-2 prepared AMEARNE, J F Commissioners 80/10/07 2pp
- --8010280278 Responds to recommendations of GAD rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIB re decontamination of TMI-2 prepared AHEARNE, J F Commissioners 80/10/07 2pp
- -B010280303 Responds to recommendations of GAO rept EKD-80-89, "TMI Financial Fallout." NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic ELS re decontamination of TMI-2 prepared AHEARNE, J F Commissioners 80/10/07 2pp
- ---8010280304 Responds to recommendations of CAD rept EMD-80-89, "TMI Financial Fallout" NRC involved in reviewing technical info & hearing preparation re restart of TMI-1 Draft programmatic EIS re decontamination of TMI-2 prepared AMEARNE, J.F. Commissioners. 80/10/07 2pp
- 8010300535 Advises that info contained in 800710 ltr has been incorporated into IE investigation of info flow from facility on 770328

 AHEARNELJF Commissioners 80/10/16 lp
- --8010300539 Advises that info contained in 800910 ltr has been incorporated into IE investigation of info flow from facility on 790328
 AHEARNE, J.F. Commissioners 80/10/16 ip
- 8010270495 Responds to 800828 ltr re handling & disposal of radwastes from facility. High activity wastes will be stored on site until technology & facilities are developed by DOE to handle such wastes Draft programmatic EIS encl W/o encl AHEARNE. J. F. Commissioners 80/10/21 4pp

V Operator Examinations

- 8010150385 Forwards PA State Univ program for training of facility operators in response to NRC 800328 ltr Only 4 of 27 control manipulations applicable to plant in cold shutdown Approval requested for program substitution W/o encl HDVEY. 0 K Metropolitan Edison Co 80/10/07 3pp
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1
- F. Becomity, medical, emergency & fire protection plans
- 8010210352 Forwards amend to security plan, removing Nov 1977 revision of Chapter 10 t adding interim security measure Amend withheld (ref 10CFR2 790) HIDNER, H A. Georgia Power Co 80/10/03 ip

G Adjudicatory correspondence

- 8010270313 Forwards revised order for mod of license which requires submission of infe to support environ qualification of safety-related electrical equipment EISENHUT, D 0 Division of Licensing 80/09/19 2pp
- --8010270317 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EISENHUT, D 9 Division of Licensing 80/07/19 App
- B010310317 Discusses IE insp on 600714 & forwards order imposing civil penalty of \$4,000 DEYGUNG.R C Office of Inspection & Enforcement, Office of the Director 80/09/24 2pp
- --8010310323 Order imposing civil penalty in amount of \$4,000 for item of moncompliance noted in IE insp on 800714
 DEYDUNO.R C Office of Inspection & Enforcement. Office of the Director 80/09/24 opp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8010240213 Application to amend Licenses DPR-57 & NPF-5, changing FSAR, App A. Section 17 2 commitment to clarify intent to apply only to safety-related equipment Proposed fee determination, revised FSAR pages & Class I & II amend fees encl WIDNER, W A. Georgia Power Co 80/10/15 App
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8008130292 Notice of ACRS Subcommittee on Fluid Dynamics 800819-20 meeting in Inglewood.CA to review control rod drive insertion failures at Browns Ferry & scram discharge vol instrumentation failures at Brunswick & Hatch CHILK.S J Office of the Secretary of the Commission 80/07/30 2pp
- 8010170317 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Boram Bys." BTAMPELOS, J ACRB - Advisory Committee on Reactor Bafeguards 80/08/08, ip
- ---8010170333 Interim preliminary draft rept to ACRS, "Review of Recent Malfunctions of BMR Scram Sys " * ACRS -- Advisory Committee on Reactor Safeguards 80/08/08 11900
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENRUT, D O Division of Licensing 80/09/19 28pp
- 8010210201 Forwards Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively, & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/10/01 3pp
- ---8010210207 Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively, to include requirement to maintain safeguards contingency plan to be implemented within 30 days REID.R U Operating Reactors Branch 4. 80/10/01 4pp
- --8010210212 Notice of issuance & availability of Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively REID,R # Operating Reactors Branch 4, 80/10/01 2pp
- BO101503B1 Responds to request for add1 info re sys voltage study Add1 analysis results of steam voltage conditions encl Util has modified voltage protection scheme for safety-related buses WIDNER, W A Georgia Power Co 80/10/09 1Bpp.
- BO10210612 Responds to NRC S00707 ltr requesting Tech Spec mods re scram discharge vol Present Tech Specs essume control drive sys operability & scram discharge vol piping is sized to assure complete scram Mods will not increase reliability HIDNER.W.A Georgia Power Co. 80/10/10, 1p
- B01023041B Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs re reactor protection sys electric power monitoring for Unit 1 & operability & surveillance of ac distribution sys Unit 2 Class III fee encl WIDNER, N. A. Georgia Power Co. B0/10/15. 2pp

- --8010230491 Proposed Tech Specs 4 9.3 8 & 4 8 re reactor protection sys electric power monitoring for Unit 1 & operability & surveillance of ac distribution sys for Unit 2 Proposed fee determination encl * Georgia Power Co 80/10/15
- 8010240213 Application to amend Licenses DPR-57 & NPF-5, changing FSAR, App A, Section 17 2 commitment to clarify intent to apply only to safety-related equipment Proposed fee determination, revised FSAR pages & Class I & II amend fees encl WIDNER, W A Georgia Power Co 80/10/15 6pp
- BOIO310341 Responds to BO1001 request re participation in development of scram sys design & performance criteria Not active member in subgroup considering criteria Plans to consolidate reviews of design rather than performing separate reviews WIDNER.W A Georgia Power Co BO/10/24 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8003240244 Forwards Waste Package Insp Rept 79-06A on 791126-28 No NGAMERT : Name of the Common o
- --B003240287 Waste Packaging Insp Rept 79-05A on 791125-28 No noncompliance noted Major areas inspected shipping paper requirements, DDT placarding requirements, radiation levels, removable contamination & DOT marking POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/12/12 7pp
- 8010170271 Forwards IE Insp Repts 50-321/80-33,50-366/80-33, 50-424/80-11 & 50-425/80-11 on 800730-31 & 0804 No noncompliance noted MURPHY, G E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 2pp
- --B010170278 IE Insp Repts 50-321/80-33,50-366/80-33,50-424/80-11 & 50-425/80-11 on 800730-31 & 0804 No noncompliance noted Major areas inspected followup on items relative to 100FR21 BROWNLEE.V L. Region 2. Atlanta. Office of the Director CONLON.T E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/08/21. 3pp
- B010200628 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls." O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/29
- 8010090273 Confirms schedule of masonry wall evaluations, in response to IE Bulletin 80-11, "Masonry Hall Design " Change is necessitated by delay in receipt of computer code used for wall re-evaluations
 WIDNER, H A Georgia Power Co 80/09/16 1p
- 8010160041 Forwards order imposing civil monetary penalty per util 800714 response to 800619 notice of violation & notice of proposed imposition of civil penalty.

 DEYOUNG: C Office of Inspection & Enforcement, Office of the Director 80/09/24. Opp
- ---B010160047 Order imposing civil monetary penalty in amount of \$4,000 for item of noncompliance noted in 800619 notice of violation re excessive radiation exposure rate inside cab of vehicle transporting waste
 DEYOUNG.R G Office of Inspection & Enforcement, Office of the
 Director, 80/09/24 App
- 8010310317 Discusses IE insp on 800714 & forwards order imposing civil panalty of \$4,000 DEYQUNO.R C Office of Inspection & Enforcement, Office of the Director, 80/09/24, 2pp
- --8010310323 Order imposing civil penalty in amount of \$4,000 for item of noncompliance noted in IE insp on 800714

 DEYQUNO.R C. Office of Inspection & Enforcement, Office of the Director. 80/09/24 6pp.
- 8010140003 Ack receipt of 800910 ltr informing NRC of steps taken to correct violations noted in IE lnep Repts 80-321/80-31 & 50-326/80-31 LEMIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/29
- --8010140005 Responds to NRC 800815 ltr re violations noted in IE Insp Repts 30-321/80-31 & 30-366/80-31. Corrective actions proper valve lineup for major flow paths & min flows of all ECGB sys verified HIDNER, W. A. Georgia Power Co. 80/09/10. 2pp

- -801014000B Forwards IE Insp Repts 30-321/80-31 & 30-366/80-31 on 800610-0714 & notice of violation LEVIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/13 2pp
- --8010140010 Notice of violation from insp on 800610-0714
 * Region 2. Atlanta. Office of the Director 80/08/ 80/08/15 1p
- --8010140013 IE Insp Repts 50-321/80-31 & 50-366/80-31 on 800610-0714 Noncompliance noted failure to properly align valves in safety sys & failure to correct seismic deficiencies in timely manner ROSERS.R F Region 2 Atlanta, Office of the Director DANCE,H (Region 2 Atlanta, Reactor Operations Nuclear Support Branch 80/08/15 7pp
- 8010160157 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Class JE Equipment" No written response O'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/30
- 8010130340 Responds to IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Review produced completed computer analyses of three stress models & partial computer analyses of seven stress models. But analyses of seven stress models." HIDNER, N A Georgia Power Co 80/10/01 ip
- 8010270349 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02
- 8010240003 Ack receipt of 800919 & 23 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-321/80-28 & 30-366/80-28 O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/09
- --8010240005 Responds to NRC 800719 telcon re violations noted in IE Insp. Repts 50-321/80-28 & 50-366/80-28 Corrective actions preparation of document index to identify authorized drawings or manuals re-safety-related plant procedures.
 MILLER: H J Georgia Power Co 80/09/23 7pp
- --8010240007 Responds to NRC 800822 ltr re violations noted in IE Insp Repts 50-321/80-28 & 50-366/80-28 Corrective actions manager of GA will be provided closer access to company executives concerned w/activities re nuclear safety MILLER.J.H Georgia Power Co 80/09/15 17pp
- --8010240009 Forwards IE Insp Repts 50-321/80-28 & 30-366/80-28 on 800707-11:14-18 & 22-24 & notice of violation D'REILLY,JP Region 2, Atlanta, Office of the Director 80/08/22, 2pp
- --8010240010 Notice of violation from insp on 800707-11,14-18 & 22-24 * Region 2, Atlanta, Office of the Director 80/08/22 7pp
- --8010240012 IE Insp Repts 50-321/80-28 & 50-365/80-28 an 800707-11,14-18 & 22-24. Noncompliance noted failure to execute/establish insp program failure to reaudit deficient areas & failure to respond to audit finding repts
 BELISLE.O. A. FREDRICKSON.P., PRICE.D 8 Ragion 2, Atlanta, Office of the Director 80/08/22 49pp
- 8010290047 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested O'REILLY. J.F. Region 2. Atlanta. Office of the Director 80/10/10.
- 8010210303 Forwards payment of civil penalty per NRC 800924 order re excessive radiation exposure rate inside tractor cab of vehicle transporting waste to Barnuell SC, WIDNER:N A. Georgia Power Co 80/10/15 ip
- R. Periodic operating reports & related correspondence
- 8010170412 Forwards "Annuel Environ Surveillance Rept, 1977." MANRY, M Georgia Power Co 80/03/28 ip
- ---BD10170422 Forwards "Annual Environ Surveillance Rept.1979 "
 MANRY.M Georgia Fower Co 80/03/28 ip.
- --9010170431 "Annual Environ Surveillance Rept.1979 " # Georgia Power Cp B0/03/28 240pp.

- 8010210418 Forwards monthly operating rept for Sept 1780. MANRY, M Georgia Power Co 80/10/10 ip
- --B010210421 Monthly operating rept for Sept 1980 UNDERNOOD, P.R. Georgia Power Co. B0/10/10 6pp
- 8 Reportable occurrences. LERs & related correspondence
- 8010160797 PNO-II-80-117 on 800626, following spurious reactor trip. MPCI started as designed but tripped on high steam flow differential pressure signal. HPCI was manually placed in svc Licenses is investigating cause TAYLOR, PA. JULIAN, CA. Region 2, Atlanta, Office of the Director 80/04/26 19
- 8010160374 PNO-II-80-122 on 800706, leaking cracks were found in spool piece in reactor water cleanup eys. Facility will be placed in cold shutdown to effect repairs Licensee is evaluating cracks
 TAYLOR.P.A., DANCE, H.C. Region 2, Atlanta, Office of the Director 80/07/08 ip
- 8010170100 EN-80-023A on 800924, order was issued imposing civil penalty of \$4,000 based on item of noncompliance re excessive radiation levels in transport vehicle BRDCRETT,T., THOMPSON,D Office of Inspection & Enforcement, Office of the Director 80/09/24 ip.
- 8010080433 Forwards LER 80-105/03L-0. MANRY, H Georgia Power Co 80/10/02 fp
- --8010080437 LER 80-105/03L-0 on 800906.D RHR svc water pump had vibration readings outside ABME limits Apparently caused by establishment of extremely low ref data Vendor established new ref data for pump. C0001N.C L Georgia Power Co. 80/10/02 2pp.
- 8010160479 Forwards LER 80-110/03L-0 MANRY, M Georgia Power Co. 80/10/09 1p
- --B0101604B2 LER 80-110/O3L-0 on 800919. HPCI min flow valve, 1E41-F012 failed to close on signal Caused by Aschanical interlock on opening contractor binding which would not allow closing contractor to sickup Contractor repaired & returned to svc NIX, R. T. Georgia Power Co B0/10/09 2pp
- --8010220474 LER 80-108/03L-0 on 800919.HPCI sys failed to pass operability test & tripped on steam line high differential pressure Cause unknown NIX.R T Georgia Power Co 80/10/14 2pp.
- 8010220500 Forward: LER 80-107/03L-0 MANRY, M. Georgie Power Co. 80/10/16, ip
- ---8010220506 LER 80-109/03L--0 on 800919; rolling overhead fire door in dissel generator room 1A was found nonfunctional. Caused by buildup of grease on closing mechanism. Responsible person counseled to apply light coat of grease COGGIN, C. L. Georgia Power Co. 80/10/16. 2pp.
- 8010280673 Forwards LER 80-107/03L-0 MANRY, M Georgia Power Co 80/10/16. 1p.
- --8010280681 LER 80-107/03L-0 on 800918; safety relief valve tail pipe pressure switch FT&C surveillance found not performed at required one month frequency, Caused by inadvertent oversight by surveillance scheduling personnel.

 C0001N:C.L. Georgia Power Co. 80/10/16 2pp.
- V Operator Examinations
- 8010280385 Forwards revised license requalification program in response to NRC 800329 request re operator training & licensing. MANRY, H Georgia Power Co 80/09/12. 1p.
- --8010280389 License requalification program.
 4 Georgia Power Co. 80/09/12. 8pp.

- DOCKET 50-322 BHOREHAM NUCLEAR POWER STATION

 A Application/construction stage documents & correspondence
- 7902090343 Forwards QE topical rept NEDD-24010-2, Suppl 2, "Bases for Criteria for Combination of Earthquake & Other Transient Responses by the Square-Root-Sum-Of-The-Squares Method "Rept is provided on behalf of Mark 2 owner's group 80BDN, L J General Electric Co , Nuclear Energy Products Div 79/02/05 1p
- --7902090367 Suppl 2 "Basis for Criteria for Combination of Earthquake & Other Transient Responses By the Square-Root-Sum of The Squares Method " Discusses method for combining multiple peak dynamic responses for blasts & marthquakes KENIEDY-R P., NEWMARK,N H , ENOLISH,W F General Electric Co NEDO-24010-2-01 78/12/31 30pp
- 8010070495 Summary of 800805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads Discussion topics, attendance & meeting handouts encl ANDERSON, C J Generic Issues Branch 80/08/29 98pp
- 8010060102 Summary of 800704-05 maeting w/Mart II owners in Bethesda, MD re long-term propram chugging & lateral loads Attendance list & handouts encl ANDERSON, C J Generic Issues Branch 80/09/12 45pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing 80/09/19. 28pp
- 8010270238 Notification of 801008 meeting w/representatives from Mark II owners group in Bethesda.MD to discuss Mark II plants chugging load spec ANDERSON.C Generic Issues Branch 80/09/22 ip
- 8010210973 Forwards Amend 37 to application for OL.consisting of Revision 17 to FBAR UP Novarro affidavit encl NOVARRO, J.P. Long Island Lighting Co. 80/10/09 2pp
- --B010210476 Amend 37 to application for QL, consisting of Revision 19 to FBAR * Long Island Lighting Co 80/09/30 180pp
- O. Adjudicatory correspondence
- 8010020036 Forwards Commission 800926 order re THI-1 restart proceeding.denying UCB motion for reconsideration of CLI-80-16.H/O encl BDRDENICK.B M Hearing Dranch 3 80/09/30 ip
- 8010140523 Forwards Bhoreham Opponents Coalition, NRC & Long Island Lighting Co motion for acceptance of 80C Contention 6(a)(i) t for extension to complete particularitation. LATHAM, 8, B Twomey, Latham & Schmitt 80/10/06 ip.
- --B010140529 Motion for acceptance of author Contention &(a)(i) re QA/QC. Motion still requires NRC & util signatures, approving newly worded contention. Requests addl &0 days to pursue informal discovery & particularization process LATHAM.8 B Bhoreham Opponents Coalition, B0/10/06, 3pp.
- --8010140533 Revised Contention 6(a)(i) re GA/GC + Shoreham Opponents Coalition 80/10/06 2pp.
- 8010160324 Forwards fourth stipulation dtd 801009 re 8uffolk County contentions EARLEY, A F Hunton & Williams 80/10/10, 1p
- --8010160527 Fourth stipulation re Suffolk County contentions REVELEY, H. T.: EARLEY, A F Hunton & Williams. 80/10/09. 3pp.
- 8010160575 Confirms that NUREO/CR-0570, IE Bulletin 80-07 & Suppl 1 & IE Insp Repts 50-322/80-09, 11, 13 & 15 were given to recipient at 801007 meeting.
 BORDENICK, B. M Hearing Branch 4, 80/10/14 2pp
- 8010220513 Forwards executed NRC & Shoreham Opponents Coalition joint motion for acceptance of Shoreham Opponents Coalition Contention & & for extension to complete particularization.

 EARLEY, A F Hunton & Williams 80/10/17 1p

- 80(0300572 Order accepting Suffolk County, applicant & NRC fourth stipulation re Buffolk contentions Recommends continuing efforts to resolve differences & sharpen issues BOWERB, E S Atomic Safety and Licensing Board Panel 80/10/27 ip
- 8010300576 Order accepting executed stipulation re Bhoreham Opponents Coalition Contention 6(a)(i) & granting 60-day extension for parties to consider intervenor Contention 19
 BOWERS, E S Atomic Safety and Licensing Doard Panel 80/10/27 ip.

H General correspondence

- 8010230720 Responds to 800520,0527 & 0710 ltrs to Allan, Fuqua & Strickler, respectively, re IC Investigation Rept 50-322/79-24 criticisms Ofc of Inspector & Auditor failed to find supportive evidence re allegation of inspector misconduct STELLO, V Office of Inspection & Enforcement, Office of the Director 80/08/12 2pp
- 8010030378 Informs that correspondence for nuclear responsibilities should be addressed to MS Pollock WOFFORD, A W Long Island Lighting Co 80/09/30 1p
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8010210473 Forwards Amend 37 to application for OL, consisting of Revision 19 to FSAR JP Novarro affidavit encl NOVARRO, J P Long Island Lighting Co 80/10/09 2pp
- --8010210476 Amend 37 to application for OL.consisting of Revision 19 to FSAR 4 Long Island Lighting Co 80/09/30 180pp

M Antitrust correspondence

- B010070334 Forwards info for antitrust review of OL application, updating & superseding 751231 antitrust info per Reg Guide 9.3 NOVARRO, J P Long Island Lighting Co 80/09/30 130pp
- O Inspection reports, IE Bulletins & correspondence
- BOSO0700B1 Responds to BOO520,27 & O710 ltrs documenting criticisms of IE Insp Rept 50-322/79-24 re allegations of const irregularities Allogations received responsible investigation No evidence found to support Allegations STELLO,V Office of Inspection & Enforcement, Office of the Director BO/08/12 2pp
- --B010090087 Comments on IE Insp Rept 50-322/79-24 Validity of five conclusions is questionable THORNBURO.H D Division of Reactor Construction Inspection B0/05/22 2pp
- --8010070079 Buggests that Ofc of Inspector & Auditor be requested to conduct full investigation into allegations of const deficiencies at facility Accusations cannot be substantiated W/o encl ltr & memos GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/13 ip.
- --8010070105 Discusses review of IE investigation into allegations of const deficiencies at facility No further action by Ofc of Inspector & Auditor is contemplated No indication that statements made to investigators were mati
- --8010070110 Discusses investigation into allegations of const deficiencies at facility Provides comments on five issues in LK Chong 800210 ltr Requests any correspondence from IE to LK Chong FORTUNA, R A Office of Inspector & Auditor 80/07/18 3pp
- --9010090119 Responds to NRC request for summary of grounds for criticism of IE investigation of alleged deficient const practices.

 Itemizes rept & provides info to support comment Related documentation encl
 GHQNQ.L K. Affiliation Unknown 80/07/10, 5pp
- --8010070124 Comments on scope methodology & findings of IE Insp Rept 50-322/79-24 re allegations of const defects at facility NRC should correct deficiencies & consider larger implications of labor practices & GA/GO deficiencies CHONO.L.K. Affiliation Unknown 80/05/20 11pp

- 8010020292 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/79-12 CARLSON,R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/21 ip
- --8010020230 Responds to NRC 791012 ltr re violations noted in IE Insp. Rept 50-322/79-12 Corrective actions battery room ventilation control panels PNL-VC16-18 evaluated & revised per F6AR.Paragraph i7 i 58. WQFFGRD.A W Long Island Lighting Co 80/08/01 2pp
- 8010210317 Forwards IE Insp Rept 50-322/80-12 on 800721-24 No noncompliance noted CARLEON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8010210322 IE Insp Rept 50-322/80-12 on 800721-24. No noncompliance noted Major areas inspected status of outstanding items & concerns re bolting of structural steel & const of biological shield wail MARRDN-L. Region i. Philadelphia. Office of the Director MCGAUGHY,R W. Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/20 7pp
- 801002070B Ack receipt of 800914 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/79-07 CARLSON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/29 ip
- --8010020714 Responds to NRC 800701 ltr re violations noted in IE Insp. Rept 50-322/79-07 Corrective actions provides status of raceway/cable separation analysis & requests meeting w/Dfc of Nuclear Reactor Regulation NQVARRO.J P long Island Lighting Co 80/08/14 Rpp
- B010240119 Forwards IE Insp Rept 50-322/80-13 on 800707-0810.No noncompliance noted BRUNNERS J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/04 2pp
- --8010240124 IE Insp Rept 50-322/80-13 on 800707-0810 No noncompliance noted Major areas inspected comparison of as-built plant to FSAR descriptions, review of test & operating procedures & followp on previous findings
 KISTER, H B Region I. Philadelphia. Reactor Operations Nuclear Bupport Branch H1001NS.J.C., PETRONE, C D Region I. Philadelphia. Office of the Director 80/07/03 6pp.
- 8010020322 Responds to IE Bulletin 80-16. Rosemount Model 1151 & 1152 pressure transmitters are used in several safety-related applications. Evaluations of applications per bulletin, expected to be completed within 30 days NOVARRO, J P Long Island Lighting Co 80/09/12 2pp.
- 8010240147 Forwards IE Circular 80-22. "Confirmation of Employee Gualifications " No written response required ORIER.B H Region I. Philadelphia, Office of the Director 80/10/02. 19
- 8010280248 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director, 80/10/10 1p
- DOCKET SO-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of Emplementation schedule also encl EISENHUT, D.O. Division of Licensing 80/09/19, 28pp
- BOIOOBO901 Forwards corrected pages for insertion into TERA Corp final rept. "Evaluation of Peak Horizontal Ground Acceleration Associated W/Hosgri Fault at Diablo Canyon Nuclear Power Plant"

 GRANE, P. A. Pacific Gas & Electric Co BO/10/02. 1p.
- --8010080512 Corrected pages for insertion into "Evaluation of Peak Horizontal Ground Acceleration Associated W/Hosgri Fault at Diablo Canyon Nuclear Power Plant," final rept # TERA Corp 80/10/02. 17pp
- 8010230615 Summary of B00725 meeting w/util.Westinghouse.Pickerd.Lowe & Garrick Inc & Franklin Research Ctr in Bethesda.MD refactility auxillary feedwater sys reliability List of attendees encl.

 JABBOUR.K N. Licensing Branch 3. 80/10/07 26pp

ľ

- --B010230629 Bummary of B00725 meeting w/util.Westinghouse & Franklin Research Ctr in Bethesda.MD re auxiliary feedwater sys automatic initiation & flow indication List of attendees & clarification of flow indication encl KENDALL.R Instrumentation & Control Systems Branch B0/07/29
- B0102B0040 Forwards request for add1 info re util 800903 application for Amend 85 to licensing application, which includes extensive revisions to Chapter 17 of FBAR Gutstanding items include composition & function of onsite review group TEDESCO,R L Assistant Director for Licensing 80/10/07 7pp
- BOID140310 Submits response to 800827 request re Questions 1 & 2 concerning turbine disc Response to 3 & 4 will be made separately Affidavit & proprietary & nonproprietary versions of "Low Power Turbine Disc Info" encl
 CRANE,P A Pacific Qas & Electric Co 80/10/09 11pp
- --8010140314 Nonproprietary version of "Low Power Turbine Disc Info "

 # Westinghouse Electric Corp 80/10/03 75pp
- 8010140345 Forwards response to NRC questions re design basis of auxiliary feedwater sys flow requirements & analysis that calculates relative value of sys reliability "Reliability Analysis of Diablo Canyon Auxiliary Feedwater Sys" encl CRANE, P. A. Pacific Oas & Electric Co. 80/10/09 22pp
- --BOSD140353 "Reliability Analysis of Diablo Canyon Auxiliary Feedwater Sys," Revision 3 BLEY,D C., (HHEELER,D H., CATE,C t. Pickard Lowe & Garrick, Inc PLO-0140 R3 80/09/30 140pp
- 8010270252 Notification of 801016-17 meeting w/util & Sandia Labs in Ban Luis Obiepo.CA to discuss reliability aspects of auxiliary feedwater sys MIRAGLIA:F J Licensing Branch 3 80/10/09 4pp
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B010310504 Forwards NUREO-0675 Suppl 11. SER for facilities Suppl discusses sys interaction program for seismically-induced events
 HRRACLIA.F J Licensing Branch 3 80/10/02 5pp
- 8010230005 Huppi 11 to SER

 * Office of Nuclear Reactor Regulation, Director NUREG-0675 S11 80/10/31 25pp
- F Security, medical, emergency & fire protection plans
- 8010210045 Notification of 801021 meeting w/util. San Luis Obispo County officials. FEMA & State of CA Ofc of Emergency Svcs in Bethesda. MD to discuss completion dates & review of state & local emergency plans
 BUCKLEY. B C Licensing Branch 3 80/10/07 Spp
- 8010240403 Clarifies confusion re statements contained in Feb 1980 emergency plan. Mods made to emergency plan to reflect requirements of revised 10CFR30.App E. & address NRC 800826 comments Third party agreements to be confirmed CRANE.P A Pacific Oas & Electric Co 80/10/17, 2pp
- G Adjudicatory correspondence
- 8010160192 Notification of contract execution Hom 1 to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing " Contractor NM Newmark HAIRSTON, CA Technical Assistance Contracts Branch FIN 8-687480/09/23 1p
- --8010160199 Mod 1, amending scope of work, to "Technical Assistance in Preparation of NRC Appeal Brief on Diablo Canyon Nuclear Power Plant Hearing " NEWMARK, N R N. Newmark Consulting Engineering Services DOUGHERTY, D O Technical Assistance Contracts Branch FIN 8-6874 80709723 ip
- 8010210104 Staff response to ASLB request for supplemental positions on PG&E's motion for low power testing. Staff feels PG&E has filed application sufficient to allow examination of fuel loading & low power testing proposal DAVIS.L D. Hearing Branch 4. 80/09/25, 16pp
- 8010030310 Requests permission to attend family religious celebration on 801108 or 09 Would be available for security plan hearing on 801111 if ASLAB decides to commence trial on that date BROWN H H Hill Christopher & Phillips. 80/10/01. 2pp.

- 8010030385 Discusses facility security plan hearing location & facility integrity maint GA state police could be made available to assist in security plan matls transportation & protection BROWN.H H California, State of BROWN.H H Hill Christopher & Phillips 80/10/01 2pp
- 8010030452 Order re util motion for low power testing containing min requirements to commence proceeding Concurs w/NRC re deferral of Class 9 accidents until resolution of seismic issues Contentions shall be filed by 801027 BOMERS.E S Atomic Safety and Licensing Board Panel 80/10/02 2pp
- 8010070392 Responds to 801001 request for security plan hearing delay Discusses ASLAB 800828 order terms re formal motions for procedural matters before ASLAB TONEKINS, 8, A Atomic Safety and Licensing Appeal Panel 80/10/03
- 8010210513 Ferwards response of intervenor SLOHFP to NRC motion to compel answers to interrogatories CAMPBELL,R A Seymour & Willis 80/10/03 19
- --8010210318 Responds to NRC motion to compel answers to interrogatories ABLP 800918 order offered SLOHFF opportunity to prepare more precise contention at discovery close Related correspondence WILLIB.H M Ban Luis Obispo Mothers for Peace. WILLIB.H M Baywoor & WILLIB. H M Seymour & WILLIB.
- 8010080300 Motion requesting that C8 Hamback be permitted to review security plan as third counsel NRC & joint intervenors stated no apposition to such addition but PORE objected Brought before ASLB w/o unanimity of ASLB 800828 order BROWN, H H , LAMPHER, L C California, State of BROWN, H H Hill Christopher & Phillips B0/10/04 2pp
- --B0100B030B Amended affidavit of nondisclosure re licensee security plan HANBACK,C B Celifornia, State of HANBACK,C B Hill Christopher & Phillips 80/10/06 4pp
- 80:0:00039 Order consolidating & scheduling sequence of matters to be heard at seismic proceeding per 800624 order TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/10/06 Jap
- B010140014 Order requesting parties' views re convening hearing on applicant premises, by B01013
 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel B0/10/06
- 8010160056 Response in opposition to Governor Brown 801006 motion for addition of counsel Parties' stipulations must be adhered to.Certificate of Bvc enci NORTON E Pacific Gas & Electric Co NORTON, B. Bruce Norton 80/10/09 Opp
- B0i0160053 Request for clarification of ABLAB B0i006 order Applicant should be allowed to present testimony first & present rebuttal testimony at end of hearing Certificate of Bvc encl
 NORTON, B Pacific Quest Ejectric Co
- 8010160593 Objects to proposal that security plan hearing be held at util headquarters in San Francisco.CA Hearing should be held either in Bethesde.MD or at federal bldg in Ban Francisco GEOROIGU.B S California, State of 80/10/10 ip
- 8010200630 Responds to ASLAB 800918 order re stipulations NRC, San Luis Obispo Mothers for Peace, Governor Brown & applicant agree to stipulation re document authenticity List of documents encl GLMSTEAD, W J Hearing Branch 4 80/10/10 5pp
- 8010160544 Request for deferral of 801027 filing date until 801203 in response to ASLAB 801006 order Brismic hearing recommences on 801020; security plan hearing commences 801110 & security plan hearing discovery is still ongoing BROWN.H H , OECROIOU.B S , LANPHER, L C. California, State of 80/10/13 2pp.
- 8010220854 Notice of appearance in proceeding Certificate of Svc encl. REYNOLDS, J.R. Scenic Shoreline Preservation Conference, Inc. REYNOLDS, J.R. Center for Law in the Public Interest. 80/10/13 556

- BOIO160552 Response to ASLAB 801006 order requesting views re holding security plan hearing on licensee premises Decision should be left to ASLAB discretion, balancing convenience. Commission policy & security Certificate of Svc encl

 CLMSTEAD, H J Hearing Branch 4 80/10/14 7pp
- BO10200174 Request for extension until B01124 to file contentions re applicant request for low power testing license Gounsel will be occupied preparing for seismic hearing Certificate of Bvc ancl FLEIBCHAKER, D. San Luis Obispo Mothers for Peace REYNDLDB, J. PHILLIPB, J. Center for Law in the Public Interest. B0/10/15. App
- G010200677 Order establishing schedule for evidence & testimony to be presented at 801020 hearing Applicant will present testimony first & will have opportunity for rebuttal Parties may make brief opening & closing statements
 HAGING, E.E. Atomic Safety and Licensing Appeal Panel 80/10/15
- 8010200682 Response to util 801006 request for clarification If util is allowed to present rebuttal testimony, all participants should be given same opportunity Certificate of Svc encl RROWN, H H. LAMPHER, L. C. California, State of BROWN, H H. Hill Christopher & Phillips 80/10/15 Spp
- B010220521 Forwards draft subpoena commanding HG Seed to testify before ABLAB Cartificate of Svc ancl CRANE, P. A Pacific Gas & Electric Co 80/10/15 5pp
- BO10210497 Request, submitted on behalf of Joint Intervenors, that NRC prepare supplemental EIB to consider consequences of Class 9 accident at facility Btudy is needed to correct earlier decisions based on NRC erroneous position on accidente FLEIBCHAKER, D Fleischaker, D B 80/10/17 4pp
- 8010210774 Urges initiation of settlement procedure re application for fuel loading & low power testing Suggests 801103 meeting of parties in Bethesda. MD to develop & discuss stipulation SHAPAR. H K Office of the Executive Legal Director 80/10/17 2pp
- 80(023068) Notice of appearance in proceeding Cartificate of Byc encl BARTH.C.A Hearing Branch 2 80/10/21 3pp
- 8010280566 Order granting extension until 801203 for intervenors to file contentions Parties should meet prior to 801203 to discuss issues & possible stipulations BOKERB, E. S. Atomic Safety and Licensing Board Panel 80/10/24
- 8010300585 Notice of reconstitution of ASLB by appointing JR Kline as mamber instead of ME Martin LAZO,R,M Atomic Bafety and Licensing Board Panel 80/10/28 ip

H Qeneral correspondence

- B010010411 Responds to B00625 itr re flooding & emergency planning for area surrounding site Plant design sufficient to withstand anticipated flooding Util compliance w/NUREO-0694 required prior to issuance of CL NUREO-0694 excerpts encl BCHWENGER, A Operating Reactors Branch 3 B0/09/15 14pp
- B010220069 Responds to B004iO ltr re safety of facility re geologic faults in region Fault being taken into consideration in licensing process BCHMENCER.A Operating Reactors Branch 3 B0/09/22 3pp
- --8010220064 Expresses concern over safety of facility due to geologic faults in area.
 SYLVESTER.K Affiliation Unknown 80/04/10 2pp.
- 8010240305 Ack receipt of RD Hershey 800818 New York Times article from CA Ofc of Governor which augusts NRC issues licenses regardless of health & safety factor Allegations are false Comments on NRC public image & on facility licensing issue.
 DIRCKS.NJ Office of the Executive Director for Operations.
 80/09/25 1p
- --B010240311 Discusses encl RD Hershey 800B18 New York Times Article re facility licensing issue, on behalf of CA Ofc of Governor Article conveys poor image of NRC licensing practices Expresses desire to cooperate during proceeding OEDROIGU, B S California, State of 80/08/22 2pp
- 8010070455 Discusses emergency procedures described in NUREG-0376, in response to 800604 ltr re W Anson concerns Potential emergency would be declared on basis of observable indications in control room.

 DIRCKS W J Office of the Executive Director for Operations 80/09/29, 2pp

- B010300376 Responds to P Vrana 791123 ltr to President Carter re need for nuclear power plant const Discusses procedures & document availability re need for electrical power balternatives

 MIRAGLIA, F Licensing Branch 3 80/09/30 Spp
- --8010300430 Forwards P Vrana 791123 ltr addressed to President Carter re Nosgri fault proximity & severe earthquake effects on facility, & low level radiation & high level radwaste disposal effects RATKOPF,C L Energy, Dept of 80/01/22 4pp
- 8010280343 Forwards CD Calsayas requests for info re facility licensing Includes requests for press releases, petitions, memos & interview datas between NRC & Governor Brown of CA Requests NRC response COELHO.T House of Rep 80/10/01 7pp
- 80102400il Responds to 80070i ltr urging denial of OL Full consideration is being given to seismic implications of local & regional geology of site MIRAGLIA.F J Licensing Branch 3 80/10/07 3pp
- 8010240172 Responds to encl 800330 ltr to President Carter urging denial of DL for facility Hearings are held re environ matters before CP is issued Response to concern re effects of low level radioactivity encl MIRAGLIA
- B010140469 Responds to 800710 ltr to NRC urging immediate licensing of facility Further action required by ASLB Appeal Board & NRC. NRC is working toward timely resolution of safety issues DENIGNH R. Office of Nuclear Reactor Regulation, Director 80/10/08 Bpp.
- --8010140476 Urges immediate licensing of facility Requests info re status of licensing procedure & suggestions on how industry concerns can be most appropriately expressed OTLEB.P.B Affiliation Unknown 80/07/10 2pp
- 8010270018 Responds to 800825 ltr re expediting facility licensing Further actions required by ASLB ASLB & Commission NRC working toward timely resolution of safety issues before license issuance DENTON-HR Office of Nuclear Reactor Regulation, Director 80/10/08 200
- B010140298 Responds to 8008ii ltr forwarding N Scott request urging licensing of facilities ASLB hearing dates of 801020 & 1110 set to discuss seismic & security issues, respectively. Fuel loading & low power testing review planned for 1981 DIRCKB, N J. Office of the Executive Director for Operations 80/10/09 2pg
- B0i0190432 Requests that concerns about evacuation plans be included in facility licensing proceedings Emergency plans available in county have not been updated since 1976
 BRUND.G E Affiliation Unknown 80/10/09 14pp
- 8010270038 Responds to 800214 itr to President Carter re ability of facilities to withstand earthquakes & offect of low level radiation ASEB plans to reopen Ban Onofre hearing record re seismic adequacy in first quarter of 1981 MIRAQLIA.F.J Licensing Branch 3 80/10/16 3pp
- B010270244 Responds to B00923 itr to HR Denton expressing concerns reoperator errors, equipment maifunctions & potential for future accidents at nuclear plants NRC is requiring applicants to respond to TMI-related requirements MIRAGLIA: F J Licensing Branch 3 80/10/16 3pp.
- 8010310584 Responds to 791219 ltr to President Carter re facility licensing Describes chronology since docketing in 1973 NRC presently working toward timely resolution of safety issues, MIRAQLIA,F.J Resource & Scheduling Branch 80/10/27 5pp
- J Insurance & indemnity information
- 8010280649 Requests Endorsement 19 to Policy NF-228
 DINITZ, I Utility Finance Branch (formerly Antitrust & Indemnity).
 80/09/24. 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8010070337 Forwards IE Insp Repts 50~275/80-10 & 50~323/80-04 on 800427-0502 & notice of violation SPENCER,O.S. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/05/19, 2pp.

- --8010090365 Notice of violation from insp on 800429-0502 * Region 5, San Francisco, Office of the Director 80/05/15
- --B010090370 IE Insp Repts 50-275/80-10 & 50-323/80-06 on 800429-0502
 Noncompliance noted failure to inspect Class IE raceway
 supports per NUREG-0578 pressuriser heater vital power
 supply mods
 DODDS,R T Region 5, San Francisco, Reactor Construction &
 Engineering Support Branch KIRSCH,D F Region 5, San Francisco,
 Office of the Director B0/05/15 7pp
- 8010270408 Forwards IE Carcular 80-21, "Regulation of Refueling Crews." No written response required ENGELKEN,R H Region S. San Francisco, Office of the Director 80/07/10 ip
- 8010270031 Responds to IE Bulletin 79-03A: "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " Subj pipe fittings not subjected to stresses greater than 85% of max code allowable stresses at design temp CRANE, P A Pacific Oas & Electric Co 80/09/15 2pp
- 8010270033 Forwards response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Twenty-four transmitters installed in safety-related applications CRANE, P A Pacific Qas & Electric Co 80/09/15 App
- B010230066 Forwards IE Insp Repts 50-275/80-16 & 50-323/80-08 on B00812-15 No noncompliance noted EPENCER.0 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 80/09/16 2pp
- --8010230077 IE Insp Repts 50-275/80-16 & 50-323/80-08 on 800812-15 No noncompliance noted Major areas inspected licensee action on previous insp findings QA audit & nonconformance rept review & Unit 1 mods HAYHES,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch KIRSCH, D F. ELIN, J D. Region 5, San Francisco, Office of the Director 80/09/15. 7pp
- 8010080365 Responds to 1E Bulletin 80-20, "Failures of Westinghouse Type H-2 Spring Return to Neutral Control Switches " Review revealed no Westinghouse Type W-2 control switches used in safety-related components GRANE, PA Pacific Oas & Electric Co 80/09/22 ip
- 8010270368 Responds to IE Bulletin 80-03. "Loss of Charcoal from Std Type II. Tuo-Inch.Tray Adsorber Cells " Visual insp showed no evidence of screen/casing separation or sagging GRANE.P A Pacific Oas & Electric Co 80/09/24 ip
- 8010160054 Ferwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required ENGELKEN, R H Region 5, Ban Francisco, Office of the Director. 80/09/29 ip
- 8010280025 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications" No written response required ENGELKEN.R.H Region 5, Han Francisco, Office of the Director 80/10/02 ip
- 6010280022 Forwards IE Insg Rept 50-275/80-18 & 50-323/80-09 on 800923-26 & 1003 No noncompliance noted. 8PENCER.0 8 Region 3, San Francisco. Reactor Construction & Engineering Support Branch 80/10/09 2pp
- --BOIO280026 IE Insp Rept 50-275/80-18 & 50-329/80-09 on 800923-26 & 1003 No noncompliance noted Major areas inspected licensee action on previous insp findings. IE builtatins, deficiency items & corrective actions for Ruskin fire damper problem KIRSCH,DF : NARBUT.P P Region 5. San Francisco, Office of the Director HAYNES,R C Region 5. San Francisco, Construction & Engineering Support Branch. 80/10/08 11pp.
- 8010280029 Forwards IE Insp Rept 50-275/80-19 % 50-323/80-10 on 800901-30 No noncompliance noted CREMS.J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/10/09. Zpp.
- --8010280035 IE Insp Rept 50-275/80-19 & 50-323/80-10 on 800901-30 No noncompliance noted Major areas inspected preoparational testing-plant tour-preoparation test program controls/IE circulars & bullatins & operator training YOUNO.T: BAOAOLIO, M. Region 5, Ban Francisco, Office of the Director. BIERNBERO/D, M. Region 5, Ban Francisco, Reactor Operations Nuclear Bupport Branch 80/10/07.

- 8 Reportable occurrences, LERs & related correspondence
- 8010020626 Part 21 rept re possible defects in Westinghouse motor control ctrs supplied to facilities originally discussed in util 780403 ltr to NRC No possible defect or generic failure exists for seismically certified equipment KENNEDY.O P. Westinghouse Electric Corp 78/03/22 3pp
- T Hearing transcripts on non-antitrust matters
- 8010300037 Transcript of 801020 hearing re CL application in San Luis ObispocCA Pp 1-222 BALZMAN,R S , BUCK,J H , JOHNBON,W R Atomic Safety and Licensing Appeal Panel 80/10/20 222pp
- 8010310019 Transcript of 801021 hearing re seismic issues in San Luis Obispo.CA Pp 223-461 * Atomic Safety and Licensing Board Panel, 80/10/21 24ipp
- 8010310020 Transcript of 801023 hearing re seismic issues in San Luis Obispo.CA Pp 665-915 + Atomic Bafaty and Licensing Board Panel. 80/10/23 264pp
- Heavile delete and entertains heart and the property and
- E010310362 Transcript of B01024 hearing in San Luis Obispo, CA. Pp 916-1188 Supporting documentation encl * Atomic Safety and Licensing Appeal Panel B0/10/24 700pp
- 8010310004 Transcript of 801025 hearing re seionic issues in Ban Luis Obispo.CA Pp 1189-1498 * Atomic Bafety and Licensing Board Panel 80/10/25 242pp
- U Congressional/Executive Correspondence
- B010280118 Provides info re issuance of low power testing license & full power DL ABLE hearings on seismic & security matters scheduled for B01020 & 1110. respectively. Issuance of licenses contingent upon completion of hearings.

 DIRCKS-H J Office of the Executive Director for Operations 80/10/01. 3pp
- --8010280123 Responds to 800331 ltr requesting delay in issuing low power testing permit until resolution of seismic emergency planning, security & TMI-related issues. Schedule of steps to be followed in acting upon application will be forwarded KAMMERER.C C. Office of Congressional Affairs 80/04/27 ip
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2
- O Adjudicatory correspondence
- B010030213 Forwards 800919 order revising 800829 order for mod of Oles in entirety EISENMUTID. 9. Division of Licensing 80/09/19 2pp.
- --8010030223 Order revising 800827 order for mad of OLe DPR-71 & DPR-62 published in 800912 FR. in entirety Response to IE Bulletin 79-018 must be filled by 801101 Request for hearing will not stay effectiveness of order VOB petitions discharged EISENHUT, D Q. Division of Licensing 80/09/17 opp.
- J Insurance & indemnity information
- B010280623 Requests Endorsement 33 to Policy NF-218 & Endorsement 30 to Policy NF-80.
 DINITZ: Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ig
- 8010070352 Forwards Endorsement 30 to MAELU Policy MF-80 & Endorsement 33 to NELIA Policy NF-219 in response to 800924 ltr Endorsements originally forwarded on 770425.

 ORAHAM N E Carolina Power & Light Co 80/10/01 ip.
- --8010070335 Notifies that Endorsement 30 to MAELU Policy MF-80 & Endorsement 33 to NELIA Policy NF-218 have not been received info requested as soon as possible.

 DINITI, I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- Advisory Committee on Reactor Safeguards reports & correspondence
- 800B130252 Notice of ACRB Subcommittee on Fluid Dynamics 800B17-20 meeting in Inglewood CA to raview control rod drive insertion failures at Browns Ferry & stram discharge volinstrumentation feilures at Brunswick & Hatch CHILK, B. J. Office of the Secretary of the Commission. 80/07/30. 2pp.

- 8010170319 Forwards interim preliminary draft rept "Revisw of Recent Malfunctions of SUR Scram Sys " STAMPELOS, J ACRS - Advisory Committee on Reactor Safeguards 80/08/08 ip
- --B010170333 Interim preliminary draft rept to ACRB. "Review of Recent Malfunctions of BWR Scram Bys "

 4 ACRB Advisory Committee on Reactor Bafeguards 80/08/08 1170p
- P Operating license stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Carrected table of implementation schedule also encl EISENHUT. p 0 Division of Licensing 80/09/19 28pp
- 8010080621 Requests add1 action re NRC 780807 1tr re deficiencies in Hatch, Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Monclass IE power supplies & reactor protection sys IPPGLITO-T A Operating Reactors Branch 2 80/09/24. 3pp
- 8010020063 Advises that util response to Items 2 & 3d of NRC 800316 request for add1 info re adequacy of station electrical distribution sys voltage will be provided by 810105 UTLEY, E E Carolina Power & Light Co 80/09/26
- B010160517 Requests that commitment to meet requirements of NUREQ-0378 re-containment water level indication monitoring mod be deferred until refueling outage beginning 820306 Mark I mods will also be completed during outage
 UTLEY.E.E Carolina Power & Light Co 80/10/10 1p
- B010240405 Bubmits test procedure for validation of adequacy of electrical sys voltage, per 801002 telcon between util, NRC & United Engineers & Constructors Test will be completed by Nov 1980 & results submitted by 810100

 UTLEY, E. E. Carolina Power & Light Co. 80/10/15 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010160097 Forwards IE Insp Repts 50-324/80-11 % 50-325/80-12 on 300310-14 % 0329-0403 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/06/13, 200
- --8010160061 IE Insp Repts 50-324/80-11 & 50-325/80-12 on 800310-14 & 0329-0403 Noncompliance noted failure to keep workers informed of radiation levels, failure to label containers of radioactive math & failure to post high radiation area.

 STOHR.J.P Region 2. Atlanta, Fuel Facility & Materiale Safety Branch JACKSON.L L. WRAY.J R Region 2, Atlanta, Office of the Director 80/06/13 34pp
- 80080&0175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16. No noncompliance noted 8TOHR, J P Region 2, Atlanta. Fuel Facility & Materials Bafety Branch. 80/06/23 2pp
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 86.No noncompliance noted Major areas inspected/compliance w/NRC & DOT regulations
 TROUP: O. L. Ragion 2. Atlanta, Fuel Facility & Materials Bafety
 Branch 80/06/23 App
- B010030541 Ack util 800703 response to notice of violation & payment of proposed imposition of civil penalties. Corrective actions rereadiation protection & control of redioactive matls will be reviewed during subsequent insps.

 BTELLO.V. Office of Inspection & Enforcement, Office of the Director. 80708/20 2pp
- 8010200632 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matia."

 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/29.
- B010240219 Forwards IE Insp Repts 80-324/80-30 & 50-325/80-33 on 800701-31, No noncompliance noted. LEWIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/04 2pp.

- --8010240228 IE Insp Repts 30-324/80-30 & 50-325/80-33 on 800701-31 No noncompliance noted Major areas inspected control room operations, plent logs, physical security barriers, radiation protection, raduate shipments & organizational changes.

 KELL030,P J Region 2, Atlanta, Reactor Dperations Nuclear Support Branch, DUZTB, J.E., DAVIB, M J Region 2, Atlanta, Office of the Director 80/09/04 6pp
- 8010130346 Suppls response to IE Bulletin 80-17 re control rod insertion failure. Hanual & automatic scrams performed satisfactorily Test performed as presquisites to scram survey indicate no blockage in discharge vent & drain lines FURR. B J Carolina Power & Light Co. 80/09/19 4pp
- 8010280267 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted BTOHR: J P. Region 2. Atlanta: Fuel Facility & Materials Safety Branch. 80/09/19. 2pp.
- ~-8010280274 Waste Packaging Insp Rept 15000039/80~15 on 800727-0801
 No noncompliance noted Major Areas inspected shipping paper
 requirements.DOT placarding requirements radiation levels
 HACATHUR.T.C., POTYER.J.P. Region 2. Atlanta, Fuel Facility &
 Haterials Bafety Branch 80/09/16 Bpp
- 8010080570 Responds to IE Bulletin 80-16, "Potential Hisapplication of Rosemont, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes "Rosemont 1152 transmitters used in Class IE applications No safety violations noted COOK, J W Consumers Power Co 80/09/22 1p
- 8010210270 Submits response to Item 3 in IE Bulletin 79-26, "Boron Loss from BWR Control Blades," Shutdown margin testing conducted prior to initial startup verified that withdrawal of control rods did not result in criticality FURR.B J. Carolina Power & Light Co. 80/09/25. 3pp.
- 8010150661 Ack receipt of BOOB14 & O911 ltrs informing NRC of steps taken to correct violation noted in IE Insp Reats 50-324/80-18 & 50-325/80-21.

 HURPHY, C.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/09/29. 19
- --8010150666 Supplemental response to 800814 response to NRC 800725 ltr re violation noted in IE Insp Repts 50-324/80-18 & 50-325/80-21 Corrective actions training for electricians & technicians on IM-SI requirements will be improved.

 TOLLISON.E. A Carolina Power & Light Co 80/09/11 2pp
- --8010150669 Forwards IE Insp Repts 50-324/80-19 & 50-325/80-21 on 800528-30 & 0609-12 & notice of violation.
 MURPHY,G.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/25. 2pp.
- --8010150672 Notice of violation from insp on 800528-30 & 0609-12 # Region 2: Atlanta, Office of the Director. 80/07/25 1p.
- --B010150471 IE Insp Repts 50-324/80-18 & 50-325/80-21 on 800528-30 & O409-12. Noncompliance noted failure to follow maint instruction HI 31-4. "Termination of Electrical Cables & Internal Wiring"

 CONLONIT.E.: HARDWICK.R.J. Region 2. Atlants: Reactor Construction & Engineering Support Branch 80/07/25. Bpp.
- 8010160121 Ferwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/09/30,
- 8010230357 Responds to noncompliance noted in IE Insp Repts 50-324/80-29 & 50-325/80-32 Repts contain proprietary info. Corrective steps: inspe required by IE Bulletins 79-02 & 79-14 were performed. Review will be completed by 801115. TOLLISGN.A.C. Carolina Power & Light Co. 80/10/01. 3pp.
- 8010270537 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/02, ip.
- 8010310125 Informs of approving 1979 insp program reviewed by Franklin Research Ctr re conformance w/recommendations discussed in NUREO-0312 Agrees w/contractor recommendation to develop insp program for control rod drive line apron. IPPOLITO.T.A. Operating Reactors Branch 2. 80/10/09, 2pp.
- --8010310132 Hafety evaluation supporting contractor technical evaluation rept findings re 1979 feedwater & control rod drive line nossle insp program for Unit 1.
 * Division of Engineering 80/10/09. 1p.

- --8010310169 Technical evaluation rept, "Feedwater Notitle Cracking Brunsuick Steam Electric Plant Unit 1" PRIDR.J E Franklin Institute/Franklin Research Center NRC-03-79-118 80/10/09 4pp
- --8010310175 Safety evaluation supporiting contractor technical evaluation rept findings is 1979 feedwater & control rod drive line nozzle insp program for Unit 2 • Division of Engineering 80/10/09 1p
- --8010310179 Technical evaluation rept. "Feedwater Nossle Cracking Bruhswick Steam Electric Plant Unit 2 " FRIOR, J E Franklin Institute/Franklin Research Center NRC-03-79-118 80/10/09 4pp
- 8010270058 Forwards IE Info Notice 80-36. "Failure of Steam Generator Bupport Bolting " No specific action or response requested O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/10/10
- 8010290392 Ack receipt of 801001 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-29 & 30-325/80-32 MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/16 ip
- --8010290397 Forwards IE Insp Repts 50-324/80-29 & 50-325/80-32 on B00805-07 & notice of violation HURPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --8010270399 Notice of violation from insp on 800805-07
 # Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/08/29 ip
- --8010290407 IE Insp Repts 50-324/80-29 & 50-325/80-32 on 800805-07 Noncompliance noted inadequate anchor bolts on control rod drive line piping & inadequate design of supports MODENOS. L. Region 2. Atlanta. Office of the Director HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/29 4pp
- R Periodic operating reports & related correspondence
- B010150386 Forwards corrections to draft data for "Effluent & Haste Bispoxel Semiannual Rept for 1978." Forwarded by NRC 800924 litr TOLLISON.A C Carolina Power & Light Co 80/10/07 ip.
- --8010180389 Corrected draft data for "Effluent & Waste Disposal Semiannual Rept for 1978" * Carolina Power & Light Co 80/10/07 16pp
- 8010150316 Forwards monthly operating repts for Sept 1980 TOLLISON.A C Carolina Power & Light Co 80/10/08 ip
- --8010130319 Monthly operating rapts for Sept 1980. HILLIS.E Carolina Power & Light Co 80/10/02 11pp
- S Reportable occurrences, LERs & related correspondence
- 8010140689 PNO-II-80-146 on 800905, Region 2 issued confirmation of action ltr to licensee documenting actions to correct apparent problems in licensee personnel dosimetry program HOSEY.C H . GIBSON, A F. Region 2. Atlanta. Office of the Director 80/09/05 ip.
- B010060209 Forwards LER 80-059/03L-0 TOLLISON,A C Carolina Power & Light Co E0/09/23 ip
- --8010060213 LER 80-059/03L-O. on 800903, during RHR sys flow calibr. PT 55 8PC.square root transmitter 2E11-FY-333B found not responding properly Caused by Sefective resistor, R5, in transmitter circuitry Resistor replaced TQLLISON, A C Carolina Power & Light Co 80/09/23 ip
- 8010070441 Forwards LER 80-065/03L-0 TOLLISON, A C Carolina Fower & Light Co 80/09/30 1p.
- --8010070449 LER 80-065/03L-0: on 800904, during normal startup, containment atmospheric monitor, 2-CAC-AT-1259, discovered not running due to low sample flow through analyzer units Caused by open relay contact in monitor photohelic gauge TOLLISON, A. C. Carolina Power & Light Co. 80/09/30, 2sp
- 8010070593 Forwards LER 80-060/03L-0 HARTFIELD.R.A Carolina Power & Light Co 80/09/30. ip

- --8010070601 LER 80-060/03L-0 on 800903, during reactor startup following completion of routine refueling outage, control rod 38-27 could not be withdrawn beyond position 46 Causa not yet determined TOLLISON, A.C. Carolina Power & Light Co. 80/09/30 1p
- 8010070547 Forwards LER 80-052/03L-0 TOLLISUB A C Carolina Power & Light Co 80/10/01 ip
- --8010070558 LER 80-052/03L-0 on 800903, during reactor startup following refueling outage, several control rods were found to have position undication problems Caused by defective transistors in probe buffer cards Transistors replaced TQLLISON, A C Carolina Power & Light Co 80/10/01 2pp
- 8010100325 Forwards LER 80-064/03L-0 TOLLISON, A C Carolina Power & Light Co 80/10/03 1p
- --B010100332 LER B0-064/03L-0 on B00905, during normal surveillance reactor low water level initiation annunciator alarmed while all reactor level infications showed normal readings Caused by ercess wire grounded to switch housing cover.

 TDLLISON, A C Garolina Power & Light Co 80/10/03. 2pp
- 8010100335 Forwards LER 80-066/03L-0 TOLLISON: A C Carolina Power & Light Co. 80/10/03 1p
- --8010100341 LER 80-066/03L-0 on 800905, during normal operation low suction pressure for RHR BM A loop observed Caused by tripped circuit breaker to motor cooler outlet valves Breaker reset & sys returned to syc TOLLISON, A C Carolina Power & Light Co 80/10/03. 1p
- --8010140472 LER 80-068/03L-0 on 800909, during reactor startup, HPCI systumbine control valve 2E41-V9 would not open w/auxiliary oil pump running Caused by cracked electronic governor reverse actuator assembly plug & affected components replaced TOLLISON, A C Carolina Power & Light Co 80/10/03 2pp
- 80:01503:0 Forwards LER 80~069/03L-0 TOLLISON:A C Carolina Power & Light Co 80/10/07. 1p.
- --8010150521 LER 80-049/03L-0 on 800907, reactor core isolation cooling flow indicator registered no flow w/turbine running at 280 psig reactor pressure Caused by installation of improper square root converter module. Proper converter installed.
 TOLLISON. A. C. Carolina Power & Light Co 80/10/07 2pp
- 80:0150520 Ferwards LER 80-070/03L-0 TOLL380N: A C Carolina Power & Light Co. 80/10/07 ip.
- --8010150526 LER 80-070/03L-0 on 800910 during performance of automatic depressurization sys (ADS) valve test ADS valve 2-B21-F013E did not actuate Caused by Broken valve actuator solenoid coil wire Coil replaced TOLLISON. A C. Carolina Power & Light Co. 80/10/07 2pp
- 8010200588 Forwards LER 80-061/03L-0 TOLLISON, A C Carolina Power & Light Co. 80/10/09 1p
- --8010200597 LER 80-061/03L-0 on 800919, during shutdown operations, motor operated suppression pool exhaust valve 2-CAC-V22 would not shut from RTOB Caused by dirty switch contacts in 490-volt power supply breakers to valve motor operator TOLLISON, A C Cerolina Power & Light Co 80/10/09 ip.
- 8010210674 Forwards LER 80-063/03L-0 TOLLISON: A C Carolina Power & Light Co 80/10/10. 1p
- --B010210680 LER 80-063/03L-0 on 80091B, while inerting drywell, primary containment gaseous analyser 2-CAC-AT-1259 found tracking improperly, Caused by instrument drift Analyser recalibr Mod written to replace monitors
 TOLLISON, A C Carolina Power & Light Co. 80/10/10 2pp,
- 8010240463 Forwards LER 80-072/03L-0. TOLLISON: A C. Carolina Power & Light Co. 80/10/10. 1p
- --8010240472 LER 80-072/03L-0 on 800915, during auto scram test, control rod 38-15 took 13-s to insert fully varsus specified requirement of 7-s. Cause is undetermined Bubsequent test was satisfactory
 TOLLISON, A. C. Carolina Power & Light Co. 80/10/10. 2pp.

- 8010210498 Forwards LER 80-071/03L-0 TOLLISON, A C Carolina Power & Light Co 80/10/15 1p
- --8010210501 LER 80-071/03L-0 on 800915, during required HPC1 & reactor core injection cooling, suppression pool level exceeded 27 inches Caused by torus high level alarm being out of calibr Setpoint reset & operating procedures revised TOLLISON, A C Carolina Power & Light Co 80/10/15 ip
- 8010210567 RQ in reviewing containment atmospheric dilution systematical determined relay in logic circuit does not meet FSAR requirements Operating procedures revised to include jumpering of contacts
 TOLLISON.A C Carolina Power & Light Co 80/10/16. 4pp
- 8010240548 RO 80-072 on 801019, relay found existing in logic circuit for both units which does not meet single active failure criteria of containment atmospheric dilution sys TOLLISON.A C. Carolina Power & Light Co 80/10/16 3pp
- 80(0280570 Forwards LER 80-067/03L-0 TOLLISON: A C Carolina Power & Light Co 80/10/22 1p
- --8010280576 LER 80-067/03L-0 on 800923, following reactor scram, reactor core isolation cooling injection valve 2851-F013 would not fully open Caused by missing electrical jumper Jumper installed TOLLISON, A C Carolina Power & Light Co 80/10/22, 2pp
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
- BOICO30213 Forwards BO0919 order revising BO0929 order for mod of DLs. In antirety, EIEENHUT, D O Division of Licensing BO/09/19 2pp
- --8010030223 Order revising 800829 order for mod of OLs DPR-71 & DPR-62 published in 800912 FR. in entirety Response to IE Bulletin 79-018 must be filed by 801101 Request for hearing will not stay affectiveness of order UCS petitions discharged EISENHUT, D 0 Division of Licensing 80/09/19 App
- J Insurance & indemnity information
- B010280629 Requests Endorsement 33 to Policy NF-218 & Endorsement 30 to Policy NF-80.
 DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity)
 80/09/24 1p
- 8010070352 Forwards Endorsement 30 to MAELU Policy MF-80 & Endorsement 33 to NELIA Policy NF-218, in response to 800724 ltr. Endorsements originally forwarded on 770425 ORAHAM.M.E. Carolina Power & Light Co. 80/10/01 lp
- --B010070385 Notifies that Endorsement 30 to MAELU Policy MF-80 & Endorsement 33 to NELIA Policy NF-218 have not been received Info requested as soon as possible DINITZ.I, Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip.
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- SDOBISD252 Notice of ACRS Bubcommittee on Fluid Dynamics \$00819-20 maeting in Inglewood, CA to review control rod drive insertion failures at Browns Ferry & scram discharge volinstrumentation failures at Brunswick & Hatch.

 CHILK, S. J. Office of the Secretary of the Commission 80/07/30. 2pp
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheats amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EIGENHUT.D. O Division of Licensing. 80/09/19 28pp
- 8010080621 Requests add1 action re NRC 780807 ltr re deficiencies in Match, Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Monclass IE power supplies & reactor protection sys.

 IPPOLITO, T.A. Operating Reactors Branch 2 80/09/24 3pp
- 8010020363 Advises that util response to Items 2 & 3d of NRC 800516 request for add! Info re adequacy of station electrical distribution eys voltage will be provided by 810105 UTLEY, E. E. Carolina Power & Light Co 80/09/26 1p

- 8010130399 Forwards Amend 30 to License DPR-71.safety evaluation & notice of issuance & availability
 IPPOLITO T A Operating Reactors Branch 2 80/09/29 2pp
- --8010150361 Amend 30 to Litense DPR-71, changing safety-relief valve setting Tech Spocs by extending effective end date until completion of T-quencher mod IPPOLITO,T A Operating Reactors Branch 2 80/09/29 4pp
- --80i0150362 Safety evaluation supporting Amend 30 to License DPR-7i • Operating Reactors Branch 2 80/09/29 2pp
- --8010150343 Notice of issuance & availability of Amend 30 to License DPR-71 IPPOLITO.T A Operating Reactors Branch 2 80/09/29 2pp
- B010240405 Submits test procedure for validation of adequacy of electrical sys voltage, per B01002 telcon between util, NRC & United Engineers & Constructors Test will be completed by Nov 1780 & results submitted by B10130

 UTLEY, E Carolina Power & Light Co 80/10/15 3pp
- 8010210479 Bubmits info re mod containment purging Hod complete on Unit 1 Mod scheduled to be completed on Unit 2 during snubber insp outage 810028 UTLEY/E C Carolina Power & Light Co 80/10/16 2pp
- G Inspection reports, IE Bulletins & correspondence
- B0040B0145 Forwards Waste Packaging Insp ftept 80-02A on 800206-08 No noncompliance noted BTOHR.JP Region 2. Atlanta. Fuel Facility & Materials Bafety Branch 80/02/26 Spp
- --8004080147 Waste Packaging Insp Rept 80~02A on 800204-08 No noncompliance noted Major areas inspected DDT & NRC requirements including shipping paper DDT placard radiation levels, marking & labeling POTTER, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/20 App
- 8005120223 Forwards Maste Packaging Insp 80-03 on 800227-29 No noncompliance noted STOHRJ P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/20 2pp
- --8005120230 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major ereas inspected placarding requirements-radiation levels-marking & labeling requirements for packages POTTER, J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 8010160097 Forwards IE Insp Repts 50-324/80-11 & 50-325/80-12 on 800310-14 & 0329-0403 O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/06/13 20h
- --8010160061 IE Insp Repts 50-324/80-i1 & 50-325/80-i2 on 800310-14 & 0327-0403 Noncompliance noted failure to keep workers informed of radiation levels failure to habel containers of radioactive math & failure to post high radiation area BYOHR. J P Region 2. Atlanta: Fuel Facility & Materials Safety Branch JACKBONL L., WRAY, J R Region 2. Atlanta, Office of the Director 80/06/13 36pp
- 8008060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16.No noncompliance noted. 8TOHR.J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/06/23. 2pp
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance noted. Major areas inspected; compliance w/NRC & DOT regulations TROUP, O.L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/23. 6pp
- 8010030541 Ack util 800703 response to notice of violation & payment of proposed imposition of civil penalties. Corrective actions reradiation protection & control of radioactive matis will be reviewed during subsequent insps
 STELLO.V. Office of inspaction & Enforcement, Office of the Director 80/08/20. 2pp
- 8010200632 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matle," O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 19

- 010240219 Forwards IE Insp Repts 30-324/80-30 & 50-325/80-33 on 800701-31 No noncompliance noted LEWIB.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/04 2pp
- -8010240228 IE Insp Repts 50-324/80-30 t 50-325/80-33 on 800701-31 No noncompliance noted Major areas inspected control room operations, plant logs, physical security barriers, radiation protection, radwaste shipments to organizational changes KELLOGO, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. DUZYS, J E , DAVIS, M J Region 2, Atlanta, Office of the Director. 80/09/04 6pg
- 010150346 Suppls response to IE Bulletin 80-17 re control rod insertion failure Manual & automatic scrams performed satisfactorily Test performed as prerequisites to scram survey indicate no blockage in discharge vent & drain lines FURR, B J. Carolina Power & Light Co. 80/09/19. 4pp
- 010280267 Forwards Haste Packaging Insp Rapt 15000037/80-t5 on 800727-0801 No noncompliance noted STOHR,J P. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/09/19 2pp
- --8010280274 Waste Packaging Insp Rept 15000039/80-15 on 900727-0801
 No noncompliance noted Major areas inspected shipping paper
 requirements.DUT placarding requirements.radiation levels
 MACARTHUR.T C. POTTER.J P. Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch. 80/09/16 8pp
- 3010240047 Responds to Item 3 of IE Bulletin 79-26, "Boron Loss from BWR Control Blades " Shutdown margin testing verified that full withdrawal of any control rod did not result in criticality FURR.B J Carolina Power & Light Co. 80/09/28 3pp.
- 010150661 Ack receipt of 800814 & 0911 ltrs informing NRC of steps taken to correct violation noted in IE insp Repts 30-324/80-18 & 50-325/80-21 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/27. ip
- -8010150666 Supplemental response to 800814 response to NRC 800725 ltr re violation noted in IE insp Repts 50-324/80-18 & 50-325/80-21 Corrective actions, training for electricians & technicians on MP-31 requirements will be improved. TOLLISON, E.A. Carolina Power & Light Co. 80/09/11 2pp
- -8010150569 Forwards IE Insp Repts 50-324/80-18 & 50-325/80-21 on 800528-30 & 0609-12 & notice of violation HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp.
- -8010150672 Notice of violation from insp on 800828-30 & 0609-12, * Region 2. Atlanta. Office of the Director 80/07/25 ip
- -8010180671 IE Imap Repts 50-324/80-18 % 50-325/80-21 on 800529-30 % 0609-12 Noncompliance noted failure to follow maint instruction MI 31-4. "Termination of Electrical Cables & Internal Wiring "
 CONLON-T E. HARDWICK.R.J Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25. 5pp
- 010160121 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director. 80/09/30.
- 010230357 Responds to noncompliance noted in IE Insp Repts 50-324/80-29 & 50-325/80-32.Repts contain proprietary info Corrective steps.imsps required by IE Bulletins 77-02 & 77-14 were performed.Review will be completed by 801115. TOLLISONA C. Carelina Power & Light Co. 80/10/01. 3pp
- 010270537 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. BO/10/02
- 010070297 Updates 800602 response to IE Bulletins 79-07 & 79-14 re seismic analysis of safety-related piping. All identified short-term mods are complete. Completion of 30 inaccessible long-term mods rescheduled for Mar 1781 FURR. B. J. Carolina Power & Light Co. 80/10/03. ip
- 010310125 Informs of approving 1979 insp program reviewed by Franklin Research Ctr re conformance w/recommendations discussed in NUREG-0312 Agrees w/contractor recommendation to develop insp program for control rod drive line apron IPPOLITO.T A Operating Reactors Branch 2. 80/10/09 2pp

- --8010310177 Technical evaluation rept, "Feedwater Nozzle Cracking Brunswick Steam Electric Plant Unit 2 " PRIOR.J E Franklin Institute/Franklin Research Center NRC-03-79-118 80/10/09 4pp
- B010290058 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Boiting " No specific action or response requested D'REILLY.J P Region 2 Atlanta, Office of the Director B0/10/10 is
- 8010290392 Ack recaipt of 801001 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-29 & 50-325/80-32 MURPHY, C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch
- --8010270377 Forwards IE Insp Repts 50-324/80-29 & 50-325/80-32 on 800805-07 & notice of violation MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --8010270399 Notice of violation from insp on 800805-07.

 * Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/29 ip
- --8010290407 IE Insp Repts 50-324/80-29 & 50-325/80-32 on 800805-07 Noncompliance noted inadequate anchor bolts on control rod drive line piping & inadequate design of supports MODENOS,L. Region 2. Atlanta. Office of the Director HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/29 4pp.
- R Periodic operating reports & related correspondence
- 8010150386 Forwards corrections to draft data for "Effluent & Waste Disposal Semiannual Rept for 1978," forwarded by NRC 800924 ltr TOLLIBON, A C Carolina Power & Light Co. 80/10/07 lp
- --B0101503B9 Corrected draft data for "Effluent & Waste Disposal Semiannual Rept for 1979," 4 Carolina Power & Light Co. 80/10/07 16pp
- 8010130316 Farwards monthly operating repts for Bept 1980 TOLLISON, A C Carolina Power & Light Co 80/10/09 ip.
- --8010180318 Monthly operating repts for Sept 1980 WILLIS, E Carolina Power & Light Co 80/10/02 11pp
- 8 Reportable occurrences, LERs & related correspondence
- BOIO1606B9 PND-11-80-146. on BOO905. Region 2 issued confirmation of action itr to licensee documenting actions to correct apparent problems in licensee personnel dosimetry program HOSEY. C. M. OIBSDN. A. F. Region 2. Atlanta. Office of the Director BO/09/05. 1p
- 8010060292 Forwards updated LER 80-044/03L-1 TOLLIBON:A C Carolina Power & Light Co 80/09/26 ip
- --8010060278 Updated LER 80-044/03L-i on 800422 during normal operation while swapping suctions for containment atmosphere control monitor. I-CAC-AT-1263, RIP valve X57-B did not indicate full closure Caused by binding of X57-B.

 TOLLISON: A C Caroline Power & Light Co 80/07/26. ip
- B010070557 Forwards LER 80-048/03L-0
 TOLL188N.A C Garolina Power & Light Co. 80/09/30. ip
- --8010070366 LER 80-048/03L-0 on 800901.during rad-block monitor blocks.
 A rod-block monitor trip actuated at less than required setpoint Caused by instrument drift Monitors recalls TOLLISON.A C. Carolina Power & Light Co
- 8010070575 Forwards LER 80-071/03L-0 TDLLISON: A. C. Carolina Power & Light Co 80/09/30. ip.
- --8010070586 LER 80-071/03L-0 on 800903, core auxiliary cooling monitors 1260,1261,1262 % 1269 were not working w/suction valves to each monitor from drywell in closed position. Caused by open feeder breaker. Breaker closed & monitors returned to normal TQLLI80N, A.C. Carolina Power & Light Co 80/09/30 2pp
- 8010140481 Forwards LER 80-072/03L-0. TOLLISON.A.C. Garolina Power & Light Co. 80/10/03 ip

- --B010140487 LER 80-072/03L-0 on 800907, during surveillance of oxygen channel, containment atmosphera recorder 1-CAC-AR-1259 was indicating erratically Caused by oxygen channel of analyzer being out of calibr Analyzer recalibrated & returned to svc TOLLISON, A C Carolina Power & Light Co 80/10/03 2pp
- 8010150504 Forwards LER 80-074/03L-0
 TCLL180N.A C Carolina Power & Light Co 80/10/07 in
- --8010150529 LER 80-074/03L~O on 800914.during performance of primary containment leak rate testing, inner airlock door seals would not hold required pressure for specified time Caused by slight door misalignment Door strongbacks installed TOLLISON, A C Garolina Power & Light Co 80/10/07 ip
- BO10150523 Forwards LER 80-075/03L-0 TOLLISON.A.C Carolina Power & Light Co 80/10/07 ip
- --8010150531 LER 80-075/03L-0. on 800912 during performance of main steamline isolation valve closure functional test reactor protection sys logic relay, 071-H3E, did not de-energize Caused by stuck contacts in valve position limit switch TQLLISON, A C Caroline Power & Light Co. 80/10/07 2pp
- 8010210647 RD in reviewing containment atmospheric dilution systetermined relay in logic circuit does not meet FSAR requirements Operating procedures revised to include jumpering of contacts
 TOLLIEON A C. Garolina Power & Light Co 80/10/16 App.
- 8010240548 RD 80-072 on 801015, relay found existing in logic circuit for both units which does not meet single active failure criteria of containment atmospheric dilution sys TOLLISON A.C Carolina Power & Light Co 80/10/16 3pp
- 8010280538 Forwards LER 80-080/03L-0. TDLLISON, A.C. Carolina Power & Light Co. 80/10/23 ip
- --8010280542 LER 80-080/03L-0 on 800923 low level switch 1-821-LI8-N031A-2 failed to actuate Caused by sticking switch actuator Switch actuator Button actuator was cleaned. TOLLI80N.A C Carolina Power & Light Co. 80/10/23. 2pp
- 8010280402 Forwards LER 80~083/03L~0 TOLLISON, A C. Carolina Power & Light Co 80/10/24 ip.
- --8010280406 LER 80-083/03L-0 on 800926, during normal surveillance, containment atmospheric monitor oxygen analyzer i-CAC-ATH-1259-2 observed indicating upscale. Caused by loss of sample flow to analyzer due to excessive condensation in line.
 TQLLISON.A C. Carolina Power & Light Co 80/10/24. 2pp

DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1

- F. Security, medical, emergency & fire protection plans
- B00925032B Forwards certification of FEMA findings & determination remulti-jurisdictional radiological emergency response plan.
 FEMA correspondence & rept also encl.
 CAMM.F A. Federal Emergency Management Agency. 80/08/07. 1p
- --8009250327 Associate Director findings & determination that state plans & preparedness including local plans are adequate to protect health & safety of public Related FEMA correspondence & rept shcl CAKM.F. A Federal Emergency Management Agency. 80/08/07 45pp
- --8009230330 "Evaluation of TN Multi-Jurisdictional Radiological Emergency Response Plan, Plant Sequoyah, " NEWTON, F Federal Emergency Management Agency, 80/08/04, 59pp

O. Adjudicatory correspondence

- 8010240017 Forwards Director's decision under 100FR2,206 denying 800328 patition re operation of Unit 1. DENTON.H R. Office of Nuclear Reactor Regulation: Director. 80/10/08. 2pp.
- --8010240023 Director's decision under 10CFR2 206 denying intervenor The NRC petition for revocation of license to conduct low power test program at facility. Containment integrity is not safety concern during low power testing.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

 80/10/08. Spp.

- 8010270038 Order granting extension until 801112 for Commission to elect whether to review Director's 801008 decision denying enforcement action under 100FR2 206 CMILK.8 J. Office of the Secretary of the Commission 80/10/24
- J Insurance & indomnity information
- BD102B0639 Requests Endorsement 9 to Policy NF-247
 DINITZ.I Utility Pinance Branch (formerly Antitrust & Indomnity)
 80/09/24. ip
- 8010080412 Forwards Endorsement 1 to MAELU Policy XB-66 FIELDER.J. Marsh & McLennan.Inc , H & H Nuclear Consultants, Inc Div. 80/09/24 2pp
- 8010150420 Forwards Endorsement 9 to ANI Policy NF-247, Endorsements 34 & 38 to MAELU Policy MF-66 & Endorsement 41 to ANI Policy NF-198 Draft forwarding itrs encl FIELDER, J. Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/10/08 10pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8010170084 Comments on 800709 ACRS subcommittee meeting re facility hydrogen problems Several physical processes could contribute to non-uniform hydrogen concentrations in containment CATTON. I ACRS Advisory Committee on Reactor Bafeguards 80/07/23 2pp
- 8010200659 Submits comments on Class 9 Subcommittee 800828 meeting re hydrogen problem Convenience should not be only criteria for igniter location BEALER L Affiliation Unknown 80/09/02 ip
- P Operating license stage documents & correspondence
- G010170249 Responds to B00808 memo on manpower expended on facility DL review Manpower expenditure records are incomplete & do not cover work done by NRC consultants & contractors Wrong charge codes used re specific licensing action BCHMENCER, A Licensing Branch 2 B0/09/16 3pp.
- 8010020480 Forwards util program for resolving ATNB issue Mods will be avaluated & implemented to reduce risk Program can be implemented by 1983 at Browns Ferry, Bequoyah & Watts Bar & by fuel loading at Bellefonte, Hartsville & Phipps Bend, MILLG, L M Tennessee Valley Authority 80/09/17. Spp
- 8010240566 Forwards License DPR-77, authorizing facility operation at 100% power upon completion of certain related const items Also forwards notice. "Discussion of Environ Effects of U Fuel Cycle" & Apps A & B.Tech Specs (NUREO-0620 & 0658) EISENHUT.D.O., Division of Licensing, 80/09/17. 3pp
- ~-8010240569 License DPR-77 for facility
 DENTON:H R Office of Nuclear Reactor Regulation, Director
 80/09/17. 13pp.
- --8010240575 Notice of issuance of facility DL SCHWENCER, A Licensing Branch 2. 80/09/17 2pp.
- 8010220099 Forwards errata sheets amending 800908 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EIBENHUTID Q Division of Licensing 80/09/19 28pp
- 8010070235 Confirms NRC visit on 801006-10 re preliminary control room evaluation Items to be reviewed include grouping of displays & layout panels. Preliminary human factors assessment should be performed prior to visit TEDEBCO.R.L Assistant Director for Licensing. 80/09/24 Spp.
- --8010070240 Discusses 800204-08 Essex Corp human engineering evaluation of control room. Control room exhibited design & procedural features contradictory to human engineering stds. MALLORY.K. Essex Corp. 80/03/10. 3pp
- 8010060241 Advises that util will not provide add1 staff after completion of startup at 50% power level, as required by BER. Section 13.2 Operators will have gained sufficient experience to continue program w/o add1 support MILLS, L. M Tennessee Valley Authority. 80/09/29. ip
- 8010080393 Revision 1 to facility Tech Epecs, App A to Licanse DPR-77 # Office of Nuclear Reactor Regulation, Director. NUREG-0658 R1 B0/09/30 500pp. Available at NTIS \$9,00

- B010070470 Forwards "Test Rept Verification of Adequacy of Calculations for Sequevah AC Auxiliary Power Syo," in response to Position 4 for Guestion B 33 Rept demonstrates adequacy of calculational methods used to design power sys MILLS.L M Tennessee Valley Authority B0/10/03 2pp
- ---8010070479 "Test Rept Verification of Adequacy of Calculations for Bequoyah AC Auxiliary Power Sus " * Tennessee Valley Authority 80/10/02 13pp
- B010200271 Bafety evaluation re temp effect on main steam safety valve setpoint Upgrade of exhaust fan & control sys to meet safety grade & Class IE electrical & Instrumentation requirements is not necessary

 * Office of Nuclear Reactor Regulation, Director, 80/10/08 3pp
- --8010200277 Bubmits add! info we mod to heating.ventilation & air conditioning sys by TVA to resolve main steam safety valve setpoint change BENNETTA B Division of Reactor Construction Inspection BO/06/19 5pp
- 80:0150370 Requests NRC confirmation of util interpretation of Tech Specs 4 4 3 2 4 re ultrasonic insp techniques & clarification of insp intervals after cold shutdown MILLS.L.M Tennessee Valley Authority 80/10/09 2pp
- 8010290247 Notification of 801016 meeting in Betheada: MD to discuss adequacy of TVA test program re protection against breach of containment BCHHENGER: A Licensing Branch 2 80/10/10 2pp
- B010270172 Notification of 801016 masting w/util in Bethesda, MD to discuss util grogram & schedules on hydrogen control to meet license requirements by 810131 STANLE-C Licensing Branch 2 80/10/15 Spp.
- 8010210996 Informs that investigation of inplace attachments to masonry walls has been completed & compliance w/design criteria verified hasonry wall investigation extended to other wall const Results will be transmitted by G10202 MILLS.L H Tennessee Valley Authority 80/10/14 ip.
- 8010270331 Documents 801013 telcon between C Stable of NRC & DL Lambert of Util Facility does not have dewatering sys for seismic Category I structures
 HILLS.L H Tennessee Valley Authority 80/10/20 ip
- G Inspection reports, IE Bulletins & correspondence
- 8010140018 Forwards IE Insp Rept 50-327/80-20 on 800501-31 & notice of violation Notice of violation withheld (ref 100FR2 790) LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 60/06/26 3pp
- --8010140027 IE Inep Rept 50-327/50-20 on 800501-31 Noncomplience noted failure to positively control personnel access into vital area JULIAN. C Region 2. Atlanta. Office of the Director DANCE. H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/26 Gpp
- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls " O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/29 Ip
- 8010170046 Forwards IE Insp Rept 50-327/80-35 on 800814-15 No noncompliance noted O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/02 2pp.
- --8010170052 IE Insp Rept 50-327/80-35 on 800814-15 No noncompliance noted Major areas inspected-util withholding info from ACRB during 800709-11 maetings OIRARD, E.H., VILLIAMSON, E.L., MARSH, R.J., Region 2, Atlanta, Office of the Director 80/09/02 9pp.
- 8010010020 Ack receipt of 800819 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-327/80-21.

 MURPHY-C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/09/10 ip
- --8010010023 Forwards IE Insp Rept 30-327/80-21 on 800624-26 & notice of violation MMRPHy.C.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/07/25 2pp.

- --8010010024 Notice of violation from insp on 800624-26 * Region 2. Atlanta, Office of the Director 80/07/18 ip
- --8010010028 IE Inep Rept 50-327/80-21 on 800624-26 Noncompliance noted failure to implement approved written procedures for pipe analysis isometric walkdown & engineering evaluations MODENOS.L. Region 2. Atlanta, Office of the Director HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/18 Spp
- 8010270097 Forwards IE Insp Repts 50-259/80-33, 50-260/80-26, 50-296/80-27 & 50-327/80-32 on 800811-13 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 2pp
- --B010270107 IE Insp Repts 50-259/80-33.50-260/80-26.50-296/80-27 & 50-327/80-32 on 800811-13 No noncompliance nated Major areas inspected followup on noncompliances re 10CFR21 procedures BROMNLEE, V L. Region 2, Atlanta, Office of the Director 80/09/11 3pp
- 8010080371 Responds to IE Bulletin 80-20, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches " Lists safety-related sys using Westinghouse-type switches Addl info to be reported by 801215 MILLB.L M Tennessee Valley Authority 80/09/16 3pp
- BD10020259 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-327/80-20 App A to insp rept withheld (ref 10CFR2 790) KENNA, W B Reylon 2: Atlanta, Safeguards Branch 80/09/18 2pp.
- 8010070074 Forwards response to IE Bulletin 80-18. "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Will submit results of analysis by 801017 MILLB.L M Tennessee Valley Authority 80/07/22 App
- 8010170107 Ack receipt of 800902 itr informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-488/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11 & others MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --8010170123 Responds to NRC 800806 ltr re violations noted in IE Inap Repts 50-327/80-24,50-328/80-15 & others Corrective actions GA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLG.L M Tennessee Valley Authority, 80/09/02 14pp
- 8010270408 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/26
- 80:0160:94 Forwards Suppl 2 to IE Bulletin 79-0:8, "Environ Gualification of Class IE Equipment" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/09/30.
- 8010170027 Ack receipt of 800915 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-327/80-25 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/09730 jp.
- ---8010170031 Responds to NRC 800821 ltr re violations noted in IE Insp Rapt 80-327/80-25.Corrective actions outage & maint employees have been informed of importance of vital area barriers MILLS/L.M Tennessee Valley Authority, 80/09/15 3pp
- --B010170035 Forwards IE Insp Rept 50-327/80-25 on 800601-0705 & notice of violation
 LEWIS,R C. Region 2: Atlanta, Reactor Operations Nuclear Support Branch. 80/08/21 2pp
- --8010170037 Notice of violation from insp on 800601-0705
 # Region 2, Atlanta, Office of the Director 80/08/21, ip
- --8010170041 IE Insp Rept 50-327/80-25 on 800601-0705 Noncompliance noted failure to positively control personnel access into vital areas & failure to properly perform critical sys temporary alteration COTTLE,W T. BUTLER, S.D. Region 2, Atlanta, Office of the Director. DANCE,H C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/21 lipp.

- 8010270530 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications" No written response required O'RELLLY, J. P Region 2. Atlanta, Office of the Director 80/10/02.
- 8010270395 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-327/80-27 KENNA,W B Region 2, Atlanta, Safeguards Branch 80/10/09 ip.
- --B010270396 Responds to NRC 800905 ltr re violations noted in IE Insp Rept 50-327/80-27 Corrective actions withheld (ref 10CFR2, 790) MILLS:L M Tennessee Valley Authority 80/09/30 ip
- --8010270397 Forwards IE Insp Rept 50-327/80-27 on 800811-15 & notice of violation Details & notice of violation withheld (ref 10CFR2 790) KENRA,N B Region 2: Atlanta: Bafeguards Branch. 80/09/05 2pp
- --8010270379 IE Insp Rept 50-327/80-27 on 800811-15 Noncompliance noted security plan & program audit, security organization & physical barriers Details withheld (ref 10CFR2 790) TILLHAN, A. HOHELL, J. MCGUIRE, D. R. Region 2. Atlanta, Office of the Director 80/09/05 ip
- 8010290066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Boiting " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/10, is
- 6010280442 Forwards response to deficiency noted in IE Insp Rept 50-327/80-34 on 800926 re failure to provide requelification training for personnel assigned to fire brigade. Requelification training provided for personnel MILLS.L M. Tennessee Valley Authority 80/10/20 2pp
- R Periodic operating reports & related correspondence
- B010220453 Forwards "Environ Radioactivity Levels Bequoyah Nuclear Plant Annual Rept, 1979 " MAXWELL.R.B. Tennessee Valley Authority 80/09/05 App.
- --8010220455 "Environ Radioactivity Levels Sequoyah Nuclear Plant Annual Rept.1979, " * Tennessee Valley Authority RH-80-7-802 80/08/31 51pp
- 8010130326 Forwards monthly operating rept for Bept 1780 BALLENTINE, J. M Tennessee Valley Authority. 80/10/08 ip
- --8010150330 Monthly operating mept for Sapt 1780
 BALLENTINE, J M , DUPREE, D Tennessee Valley Authority, 80/10/08.
- 8 Reportable occurrences, LERs & related correspondence
- 8010080442 PNO-II-80-iii on 8006i7, motor operated disconnect breaker in 161-kV switchyard failed under load resulting in loud noise & flash which was seen by local residents Plant was not affected & no loss of offsite power occurred TAYLOR.P A. LEWIS.R.C. Region 2. Atlants. Office of the Director. 80/06/17 1p.
- 8010090327 PNO-III-80-ii3 on 800623, while heating up plant for initial criticality, inadvertent actuation of safety injection occurred, caused by manual opening of main steam isolation valves All equipment functioned as expected JULIAN.C. LEHIB.R.C. Region 2. Atlanta, Office of the Director. 80/06/24 ip
- 80i0170016 PNO-II-80-138 on 800807, Chem-Nuclear, Inc found 25 gallons of low level liquid in solidified radwaste shipping cask upon arrival at Bernwell 8C Urea formaldehyde solidification had partially failed & released some liquid radwaste POTTER, J. STOHR, J.P. Region 2, Atlanta, Office of the Director 80/08/08 ip
- 8010160633 PNO-II-80-139 on 800814.manual reactor trip was initiated to terminate continuous withdrawal of control rod bank D All control rods inserted normally on trip.Licensee investigation is in progress.

 DANCE.H G , LEHIB.R C, Region 2, Atlanta: Office of the Director 80/08/14, ip.
- 8010070592 Forwards LER 80-088/03L-0 CALHOUN, J. R Tennesses Valley Authority 80/10/01, ip

- --8010070598 LER 80-088/03L-0 on 800902.util was advised that insulated control cable to MS valves.to AFNPT,AFW 80 level control valves & MFW isolation valves required replacement Caused by failurs to meet environ temp qualifications.

 COTTLE,W T : OELBTON.A H Tennessee Valley Authority 80/10/01 ip
- 8010080385 Forwards LER 80-148/03L-0 CALHOUN, J R Tennessee Valley Authority 80/10/02 1g
- --B0100B0392 LER B0-14B/O3L-O on B00904, shield bldg vent monitor declared inoperable due to loss of sample air flow Caused by worn out sample pump drive belt Belt replaced & monitor returned to svc HEREFORD, J. M. Tennessee Valley Authority B0/10/02 ip.
- 8010210498 Discusses RO 50~327/8069,re inadvertent initiation of safety injection signal. No followup supplied after initial 800603 telecopy to NRC Util has determined event is not reportable per Tech Specs CALHOUN, J. R Tennesses Valley Authority, 80/10/06 ip
- B010210727 RO B0-069 inadvertent initiation of safety injection signal occurred but did not result in water injection into RCS Causad by sys lineups utilized for overpressure protection CALHOUN, J R Tennessee Valley Authority B0/10/06 2pp
- 8010210514 Forwards LER 80-157/03L-0 CALHOUN, J R Tennessee Valley Authority 80/10/10 ip
- --8010210517 LER 80-157/03L-0 on 800911, containment isolation valve FCV-61-192 took 20-s to stroke closed Caused by ice buildup No subsequent problems have been experienced COTTLE.H T , KIRK.O B Tennessee Valley Authority 80/10/10
- 8010210634 Forwards updated LER 80-141/01X-1. CALHOUN, J R Tennessee Valley Authority 80/10/10 1p
- --B010210697 Updated LER B0-141/OlX-1.on B00829, defect found in canopy within heat affected zone adjacent to seal weld, Caused by absence of O-ring Fault has been ground out & well repaired COTTLE, H T , KIRK, O B. Tennessee Valley Authority B0/10/10.
- 8010210434 Forwards updated LER 80-114/01X-1 CALHOUN, J R Tennessee Valley Authority, 80/10/14 ip
- --8010210642 Updated LER 80-i16/01X-1 on 800711 containment integrity violated when outer door opened while inner door was ajar. Caused by personnel error Letch design changed to prevent latch from blocking door open COTTLE.W T , KIRK, G. B. Tennessee Valley Authority 80/10/14 2pp
- 8010210669 Forwards updated LER 80-065/03X-1 CALHDUN,J R Tennesses Valley Authority. 80/10/14 1p
- --B010210479 Updated LER B0-065/03X-1 on B00430, two 16-inch & two 20-inch mechanical penetration fire barriers were discovered to be breached leading from reactor bldg into emergency gas treatment sys filter room Caused by personnel error. COTTLE, H T , KIRK, O B. Tennessee Valley Authority B0/10/14 20b
- BO10210493 Forwards updated LER BO-018/01X-1 CALHOUN, J.R. Tennessee Valley Authority BO/10/14. 1p.
- --B010210497 Updated LER 80-018/01X-1 on B00326, exposed cables inside containment between penetrations & conduit found not qualified to re-evaluated new post-LOCA max dose level of 4 7508 rads Caused by unqualified cable, COTTLE, W T , KIRK, Q. B, Tennessee Valley Authority, B0/10/14, Zoo.
- 8010210696 Forwards updated LER 80-007/01%-2 CALHOUN, J. R. Tennesser Valley Authority 80/10/14 1p
- --8010210703 Updated LEH 80-007/01X-2 on 800315, engineering found that incorrect valve operator weights were used for seismic analysis of component cooling water sys valves, Caused by incorrect weights shown on drawings COTTLE-M.T., KIRK, G.B. Tennessee Vailey Authority. 80/10/14 2pp.

- 8010210369 Third revised final deficiency rept re spent fuel pool gates QA aspects of gate integrity will be verified or certificates of compliance will be obtained from fabricators. Nature & welds will be inspected & tested MILLS.L M. Tennessee Valley Authority 80/10/15. Spp
- 8010210635 Forwards updated LER 80-135/01X-1 CALHOUN, J R Tennessee Valley Authority, 80/10/15. 1p
- ---B010210441 Updated LER 80-135/01X-1 on 800711, ice condenser compartment temp erceeded Tech Spec limit of 27 F Caused by ice condenser inlet doors being open due to differential pressure created by both lower compartment doors being open KIRK, O B , COTTLE, W Y Tennessee Valley Authority. 80/10/15 ip
- BO10210690 Forwards LER 60-113/01T-0 CALHOUN, J. R Tennessee Valley Authority. 80/10/15 ip.
- --9010210697 LER 80-113/01T-0 on B00926, while exiting containment through upper containment airlock, employee allowed inner door to slam & bounce back_Latch then closed blacking door sign. Caused by improper adjustments on door operating mechanism ANTHONY, J M . COTTLE, H T. Tennessee Valley Authority 90/10/15.
- B010210701 Forwards updated LER 80-028/01X-1 CALHOUN, J. R Tennesses Valley Authority 80/10/15, 1p
- --B010210714 Updated LER 80-020/01X-1.on 800411.main steam header pressure transmitters [-PT-1-28.-9A.-98.-20A.-20B & 278 found to lack environ qualification Causad by design error. COTTLE.W.T. KIRK.O B Tennessee Valley Authority. 80/10/15.
- 8010210590 First interim deficiency tept re analysis of intermediate pipe break locations resulting in break locations shift. Util is evaluating possible consequences of postulated breaks for RHR sys MILLB:L H Tennessee Valley Authority, 80/10/16 2pp.
- 8010210659 Forwards LER 80-156/01T-0. CALHOUN, J. R Tennessee Valley Authority. 80/10/17. ip
- --8010210465 LER 80-154/01T-0. on 801005, technician noticed leakage under 3 reactor coolant pump Leak came from seal injection line. Causad by Vibration or inadvertent shysical damage. Line replaced & addl pige supports installed COTTLE, FT., KIRK, O.B. Tennessee Valley Authority. 80/10/17 35p.
- 8010270349 Forwards updated LER 80-022/03X-1.
 CALHGUN.J R. Tennesse Valley Authority 80/10/21. ip.
- --8010270353 Updated LER 80-022/03X-1:on 800318, sample isolation valves i-FCV-90-108:-109,-110;-114,-115 & -116 closed. Caused by isolation of nonessential control air to sample valves Control air restored to sample valves GOTTLE, W. T., WILKEY, A M Tennesses Valley Authority, 80/10/21.
- 8010280465 Forwards LER 80-041/03X-2. GALHOUN, J. R. Tennessee Valley Authority, 80/10/22, 1p.
- ---8010280308 LER 80-041/03X-2.on 800430.w/unit in Mode 5, sample isolation valves 1-FCV-90-108, 109, 110 H. 114, 115 & 116 closed Gaused by isolation of nonessential control air to sample valves. Upgrading air supply to sample valves. COTTLE, W. T., WILKEY, A. H. Tennessee Valley Authority, 80/10/22 ip.
- 8010280518 Forwards updated LER 80-019/1X-1. CALHOUN, J. R. Tennessee Valley Authority, 80/10/23. 1p
- --8010280362 Updated LER 80-019/01X-1: on 800326, in Mode 6 w/all fuel loaded, determined that leakage of unfiltered outside air endangers habitability of control room, Possibly caused by isolation dampers. Two Sampers added.
 COTTLE, N T., KIRK, Q.B. Tennessee Valley Authority. R0/10/23.

- DOCKET 50-329 SEGUDYAH NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATHS issue Mode will be evaluated & implemented to reduce risk Program can be implemented by 1965 at Browns Ferry, Sequoyah & Matts Bar & by fusi loading at Bellefonte. Hartsville & Phipps Bend MICLS,L M Tennessee Valley Authority 80/09/17 5pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT.D Q Division of Licensing, 80/09/19 28pp
- 8010200271 Safety evaluation re temp effect on main steam safety valve satpoint. Upgrade of exhaust fan & control sys to meet safety grade & Glass IE electrical & instrumentation requirements is not nacessary & Office of Nuclear Reactor Regulation, Director 80/10/00 3pp.
- 8010300495 Amend 1 to License SNM-1863, changing expiration date to 810331 or upon conversion of CPPR-73 to OL. PAGE,R. Q. Uranium Fuel Licensing Branch. 80/10/08 1p
- B010290247 Notification of 801016 meeting in Bethesda, MD to discuss adequacy of TVA test program re protection against breach of containment.

 BCHMENCER.A. Liransing Branch 2 80/10/10 2pp.
- 8010290172 Notification of 801016 meeting w/util in Bethesda. MD to discuss util program & schedules on hydrogen control to meet license requirements by 810131.
 STAHLE-C. Licensing Branch 2. 80/10/15. 3pp.
- 8010270331 Documents 801015 telcon between C Stable of NRC & DL Lambert of util-Facility does not have dewatering sys for seismic Category I structures.

 HitLS,L H Tennessee Valley Authority, 80/10/20, 1p
- J Insurance & indemnity information
- 9010150420 Forwards Endorsement 9 to ANI Policy NF-247. Endorsements 34 & 38 to MAELU Policy MF-66 & Endorsement 41 to ANI Policy NF-198. Preft forwarding ltrs encl NF-198. Preft forwarding ltrs encl FIELDER, J Marsh & McCennan, Inc , H & M Nuclear Consultants, Inc Div. 80/10/08 10pp.
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BD10170084 Comments on BO0709 ACRB subcommittee meeting re-facility hydrogen problems. Several physical processes could contribute to non-uniform hydrogen concentrations in containment. CATTON.I. ACRB Advisory Committee on Reactor Safeguards. B0/07/23. 2pp.
- 8010200659 Submits comments on Class 9 Subcommittee 800828 meeting re hydrogen problem. Convenience should not be only criteria for igniter location. BEALE.R.L. Affiliation Unknown. 80/09/02. ip.
- P. Operating license stage documents & correspondence
- 8010070470 Forwards "Test Rept: Verification of Adequacy of Calculations for Bequoyah AC Auxiliary Power Sys." in response to Position 4 for Question 8 33. Rept demonstrates adequacy of calculational methods used to design power sys.
 MILLS.L.M. Tennessee Valley Authority. 80/10/03. 2pp.
- ---8010070479 "Test Rept:Verification of Adequacy of Calculations for Bequoyah AC Auxiliary Power Bys." # Tennesses Valley Authority. 80/10/02. 13pp.
- 8010200271 Bafety avaluation re temp affect on main steam safety valve setpoint, Upgrade of exhaust fan & control sys to meet safety grade & Class IE electrical & instrumentation requirements is not necessary.

 Office of Nuclear Reactor Regulation, Director 80/10/08, 3pp.
- --8010200277 Bubmits add1 into re mod to heating, ventilation & air conditioning sys by TVA to resolve main steam safety valve satpoint change.
 BENITI:A.B. Division of Reactor Construction Inspection.
 BO/06/19. 5pg.

- 8010210596 Informs that investigation of inplace attachments to mesonry walls has been completed & compliance w/design criteria verified. Masonry wall investigation extended to other wall const Results will be transmitted by 810202 MILLS, L.M. Tennessae Valley Authority 80/10/16 ip
- O Inspection reports. IE Bulletins & correspondence
- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Hatls " O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29, is
- B010240235 Forwards IE Insp Rept 50-328/80-19 on 800806-08.No honocompliance noted fWRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/09/04. 2pp.
- --8010240241 IE Insp Rept 50-328/80-19 on 800804-08. No noncompliance noted Major areas inspected electrical cable work activities termination activities & instrumentation components & sys activities CCNLON.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch, GIBBONS.T D. Region 2. Atlanta, Office of the Director, 80/09/04, 3pp.
- B010080391 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Lists affaty-related sys using Westinghouse-type switches, Addl info to be reported by B01215, Mills, L. M. Tannessee Valley Authority 80/09/16. 3pp.
- 8010170107 Ack receipt of 800702 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 30-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-519/80-11 & others.

 MURRHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/26. 2pp
- --9010170123 Responds to NRC 800806 ltr re violations noted in IE Insp. Repts 50-327/80-24,50-328/80-15 & others Corrective actions. GA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies. MILLS.L.M. Tennessee Valley Authority 80/09/02 14pp
- 8010160184 Forwards Suppl 2 to IE Sullatin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/09/30 is
- 8010270530 Forwards IE Circular 80-22. "Confirmation of Employee Ovalifications." No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/10/02.
- 8010270046 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested. O'REILLY, J P. Region 2, Atlanta, Office of the Director. 80/10/10.
- R Periodic operating reports & related correspondence
- B010220453 Forwards "Environ Radioactivity Levels Sequoyah Nuclear Plant Annual Rept, 1979, " MAXHELL, R B. Tennessae Valley Authority, B0/09/05, App
- --8010220455 "Environ Redioactivity Levels -- Hequoyah Nuclear Plant Annual Rept.1979 "
 Tennessee Valley Authority RH-80-7-802. 80/08/31 51pp
- B. Reportable occurrences, LERs & related correspondence
- 8009100414 First interim deficiency rept re incorrect valve weights in auxiliary feedwater piping. Two types of water level control valves had discrepancy in valve weights compared to data used in piping analysis, Util reanalysing piping sys.
 MILLERLM. Tennessee Valley Authority. 80/09/04, 2pp.
- 8009300395 Fourth interim deficiency rept re upper head injection hydraulic isolation valve accumulator weighing sys. Util will delay design changes proposed by Westinghouse until further testing completed, MILLB, L. M. Tennessee Valley Authority. 80/09/25, ip.

- 8010160523 Second interim deficiency rept re possible inadvertent boron dilution while on residual heat removal sys Hestinghouse final evaluation is recommendations will be completed by Jan. 1981 Next rept will be forwarded by 810206 MILLS, L.M Tennessee Valley Authority 80/10/08 ip
- 8010210369 Third revised final deficiency rept re spent fuel pool gates. GA aspects of gate integrity will be verified or certificates of compliance will be obtained from fabricators Matis & welds will be inspected & tested MILLE-L M. Tennesses Valley Authority. 80/10/15 3pp.
- 8010210405 Final deficiency rept re evaluation of sensing line connections to process piping. Reanalysis of effected process piping found no hardware changes necessary No generic implications found at other plants
 MILLB.L H. Tennessee Valley Authority 80/10/16. 2pp
- 8010210560 Second interim deficiency rept re incorrect insulation weight used in piping analysis Cause not stated. Util is evaluating as-constructed insulation drawings to determine impact on seismic analysis
 MILLS.L. H. Tennessee Valley Authority, 80/10/16. 1p.
- 8010210590 First interim deficiency rept re analysis of intermediate pipe break locations resulting in break locations shift. Util is evaluating possible consequences of postulated breaks for RHR sys
 MILLB.L M Tennessee Valley Authority. 80/10/16 2pp
- 6010280427 Final deficiency rept re failure to use correct valve weights in piping analysis Caused by discrepancy batwaen valve weights & input data used in piping analysis. Auxiliary feedwater piping reanalysed. Required mods will be made. MILLB, L M. Tennessee Valley Authority. 80/10/22. 2pp.
- B0102B0J6B Final deficiency rept re containment vacuum relief valve pnaumatic operators Valves being replaced by assemblies from Hartsville plant Completion expected by B01201 HILLB.L M. Tennessee Valley Authority B0/10/23 2pp.
- 8010280076 Final deficiency rept re safety injection sys train B flow defect Caused by cavitation at RHR heat exchanger outlet valves Cavitation sliminated by opening valves to 79F in tafety injection sys injection mode MILLS.L. M. Tennessee Valley Authority 80/10/23. Rpp.
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT.D.O Division of Licensing. 80/09/19. 20pp
- 8009300507 Forwards affidavit acknowledging distribution of Amand 82 to CP & OL application.Revision ii to environ rept. CODK, J H. Consumers Power Co. 80/09/22. App
- B010030495 Forwards description of BMW computer program AUX-1 used for analyzing steam generator performance following auxiliary feedwater sys actuation. Analyses performed w/program will be utilized in licensee response to NRC Question 211.184. CQGK.J.W. Consumers Power Co. B0/09/22. 17pp.
- 8010070529 Forwards "Bending Stresses in Underground Piping Due to Differential Soil Settlement," profiled in 800401 response to NRC request, BATES, J D Rockwell International Corp., Energy Systems Div 80/10/01. ip.
- --8010070837 "Bending Stresses in Underground Piping Due to Differential Soil Settlement."

 * Rockwell International Corp., Energy Systems Div. 80/09/19, 1490.
- 8010210300 Responds to util 800222 ltr questioning fee determination re application for Amend 72 to CP. No new math has been presented to cause departure from previously stated NRC position Frompt payment is expected, MILLER. H. O. License Fee Management Branch. 80/10/02, 1p.
- 8010220008 Responds to util 800722 1tr questioning fee determination for Amend 72 NRC position stands. Prompt payment is requested.
 MILLER, W.O. License Fee Management Branch. 80/10/02, ip.

- 8010280592 Recommends two acceptable approaches to establishment of acceptable seismological input parameters Top of natural glacial till is appropriate location for vibratory ground motion input for site
 TEDESCO.R L. Assistant Director for Licensing 80/10/14 4os
- 8010310494 Forwards Amend 2 to CPPR-81 & CPPR-82 & notice of issuance & availability MRRADLAF Licensine Branch 3 80/10/20 2pp
- --B010310497 Amend 2 to CPPR-B1 & CPPR-B2, authorizing addition of antitrust conditions
 FISSNAULD D 0 Division of Licensing 80/10/20 22pp
- --BO10310500 Notice of issuance & availability of Amend 2 to CPPR-B1 & CPPR-B2 MIRAOLIA.F Licensing Branch 3 80/10/20 2pp.
- BO10310376 Forwards updated & modified svc lists re facility proceedings & CP application Buggests that NRC keep svc lists up to date BRUNNER.E J Consumers Power Co 80/10/28 17gp.
- F Becurity, medical, emergency & fire protection plans
- 8010280266 Forwards "Evacuation Clear-Timb Estimates for Areas Near Midland.HI Nuclear Power Plant " Times presented in study represent evacuation w/no emergency plan in effect. COOK, J W Consumers Power Co 80/10/20 ip
- 8010310402 Forwards Revision 3 to security plans training & qualification plan & safeguards contingency plans.Plans withheld (ref 10CFR2 790) COOK.J W Consumers Power Co 80/10/23 2pp
- @ Adjudicatory correspondence
- 8010020041 Notice of 801021-22 deposition of D Horn,T Cook & O Keeley of CPC, in Midland.MI re issues of ABLB 791206 order & contentions of intervenors Stamiris & Harren, Cartificate of Svc encl PAYON.W Hearing Branch 2 80/09/29 App.
- 8019020735 Amended notice of Oct 1980 depositions of D Hood, L Heiler & J Kane of NRC & JM Simpson M Lewhead & R Erickson of Corp of Engineers re issues of ABLB 791205 order & contentions of Stamiris & Warren Certificate of Svc encl FARNELL, A. 8 Consumers Power Co FARNELL, A. 8 Isham, Lincoln & Beale 80/09/29 App
- 8010030127 Ack receipt of 800922 notice of deposition & request for production of documents Intends to cooperate despite noncompliance w/regulatory requirements. Notice amended to provide that documents will be w/deponents during deposition PATON; H D Hearing Branch 2 80/10/01. 1p
- Ol0100045 Notice of 801007.08.09,14.15 & 16 depositions of D Hood, L Helier, J Kane, JH Simpson, H Lawhead & R Ericison, respectively Certificate of Svt encl FARNELL, A S Consumers Power Co FARNELL, A B Isham, Lincoln & Beale, 80/10/01 4pp
- 8010100048 Designation of IE Srunner, MI Miller, RQ Zamarin & AB Farnell
- at persons on whom ave should be made in OL & drder modifying CP proceedings JL Bacon ME Gibbs & CA Bartelman should be deleted from sve list Certificate of Bvc encl. FARNELL A.S. Consumary Power Co FARNELL A.S. [4ham, Lincoln & Beale, 80/10/01 3pp
- 8010060013 Requests repts of meetings held in last three months of 1974 & 1975-79 & GA resumes discussed in ABLB (nittle) decision: LBP-74-71: Peragraph 76 PAYON, N. D. Hearing Branch 2. 80/10/02. ip
- 8010070409 Notice of 801028-29 depositions of H Ferris, 8 Afifi & J Wanzeck of Bechtel Associates re issues stated in ASLE 791206 order & contentions agreed upon by intervenors Stamaris & Warren. Certificate of Byc enci. PATON.W.D Hearing Granch 2 80/10/06. 4pp
- OiOi40508 Interrogatories soliciting info re performance of lab tests on plant fill samples & discrepancy in magnitude of loading stress indicated in Figure 2 of 800914 rept & info previously supplied, Cartificate of Syc ancl. PATON.W.D. Hearing Branch 4. 80/10/09. 4pp.

- 8010190017 Amended notice of deposition Deposition of D Horn will be taken on 801021, of T Cook on 801022 & of O Keeley on 801022 Certificate of Svc encl PATON.N D Hearing Branch 4 80/10/10 4pp
- 8010190966 Amended notice of deposition Deposition of W Ferris will be taken on 801028.5 Afifi on 801027 & J Wanteck on 801029 Certificate of Svc encl PATON.W D Hearing Branch 4 80/10/10 4pp
- 8010140758 Response in opposition to B Stamiris 800923 amended petition to intervene Contention 4c Contention fails to satisfy specificity requirement Certificate of Svc encl FARNELL. A S Consumers Power Co FARNELL. A S Isham, Lincoln & Seale. 80/10/10 4pp
- 8010160597 Forwards D Hond & L Heller 801007-09 depositions W/o encl JDNF8.8 H Hearing Branch 2 80/10/14 ip
- 8010160605 Response in support of B Stamiris 801010 amended petition to intervene & of B Stamiris 800724 Contention 4c re soil settlement remedial actions Certificate of Svc encl JONES.D H Hearing Branch 2 80/10/14 4pp
- 8010270503 Advises that applicant & NRC discovery will take longer than time stated at 800910 prehearing conference Status will be reported periodically PATON:W D Hearing Branch 2 80/10/24 ip
- B0102B0\$95 Order re B00910 prehearing conference granting # Stamiris & BK Warren petitions & denying WH Marshall.PA Race,SD Reist et al petitions to intervene Consolidation of OL & license mod proceedings granted W/accepted contentions
 BECHNOEFER.C Atomic Bafety and Licensing Board Panel 80/10/24
- 8010300038 Forwards exhibits of J Kane 801014,15 & 16 deposition W/o encl PATON W D Hearing Branch 2 80/10/27 1p
- 8010300042 Forwards D9 Hood 801007 deposition W/o encl PATON: W D | Hearing Branch 2 80/10/27 1p
- 8010300054 Forwards exhibits of D Horn 801021-22 deposition: T Cooke 801022 deposition & B Keeley 801023 deposition W/o encl JONES, B W Hearing Branch 2 80/10/27 1p
- 8010300062 Advises that CPC reply to NRC 800827 requests re dewatering info.will be filed on 801031 in form of addition to CPC 80021% responses re plant fill PATON.W D Hearing Branch 2 80/10/28 ip
- 8010310376 Forwards updated & modified svc lists re facility proceedings & CP application Euggests that NRC keep svc lists up to date BRUNNER.E.J. Consumers Power Co. 80/10/28 17pp
- H General correspondence
- 8010170210 Forwards licenses 800714 ltr re-correlation strength test sampling frequency Reply is consistent w/NRC position BCHMENGER, A Licensing Branch 3 80/10/03 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010240204 Amend 83 to FEAR.Revision 30, Vol 1, revising & supplementing application for CP & DL Util position re NUREO-0667, NUREO-06494 & IOCFRBD 54(f), "Responses to Post-TMI-2 Issues & Events," encl COOK, J W Consumers Power Co 80/10/21, 650pp
- ---B010240214 Amend 89 to FSAR.Revision 30.Vol 2.revising & supplementing application for CP & OL CODX, J. W. Consumers Power Co. 80/10/21 600pp
- --8010240221 Amend 83 to FSAR, Revision 30, Vol 3, revising & supplementing application for CP & OL, CBOK, J W. Consumers Power Co. 80/10/21, 500pp
- --8010240230 Amend 83 to FSAR.Revision 30.Vol 4, revising & supplementing application for CP & DL. Addendum NRC open items encl. COUK. J. N. Gonsumers Power Co. 80/10/21 400pp.
- 8010310384 Forwards Certificate of Svc of Amend 83, consisting of Revision 30 to FSAR, to application for CP & OL BRUNNER, E J. Consumers Power Co 80/10/27 2pp.

- O Inspection reports, IE Bulletins & correspondence
- BO10160324 Forwards 1E Insp Repts 50-329/80-26 & 50-330/80-27 on B00801-31 No noncompliance noted FIORELLI,O Region 3. Chicage, Reactor Construction & Engineering Support Branch BO/09/10 2pp
- --8010160332 IE Insp Repts 50-327/80-26 & 50-330/80-27 on 800801-31 No noncompliance noted Major areas inspected examination of site conditions & detensioning of reactor vessel holddown balts

 CODK, R. J. KNDP, R. C. Region 3, Chicago, Office of the Director 80/07/07 3pp
- B010230674 Forwards IE Insp Repts 50-329/80-23 & 50-330/80-24 on 800919-22 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/15 2pp
- --B010230677 IE Insp Reptx 50-329/80-23 & 50-330/80-24 on 800B19-22 No noncompliance noted Major areas inspected const schedules, outstanding items of noncompliance, new util GA organization & examination of site const activity
 BUTPHIN,R N , KNOP,R C Region 3, Chicago, Office of the Director B0/09/15 3pp
- 8010240325 Forwards IE Insp Repts 50-329/80-25 & 50-330/80-24 on 800827-29 No noncompliance noted FIORELLI.6 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/09/15 2pp
- --B010250330 IE Insp Repts 50-329/80-25 & 90-330/80-26 on 800827-29
 No noncompliance noted Major areas inspected containment
 prestressing sys work activities, Midland soil issues &
 quality records
 HAYEB,D W Region 3, Chicago, Reactor Construction & Engineering
 Bupport Branch OALLACHER.E J , LANDSHAN,R B Region 3, Chicago,
 Diffice of the Director 80/09/12 5pp
- B010080570 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemont, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Rosemont 1152 transmitters used in Class IE applications No safety violations noted, COOK, J W Consumers Power Co 80/09/22 1p
- 8010090179 Responds to IE Bulletin BO-20, "Failures of Westinghouse Type H-2 Spring Return to Neutral Control Switches " Specified switches are not used in currently designed safety-related applications COOK, J W Consumers Power Co 80/07/22 tp
- BD1016025B Forwards Suppl 2 to 1E Bulletin 79-01B, "Chviron Qualification of Class IE Equipment" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/30
- 8010280034 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J C Region 3, Chicago, Office of the Director 80/10/02 to
- 8010290021 Forwards IE Info Notice 80-36, "Failurs of Steam Generator Support Bolting " No specific action or response requested.

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- BO10030218 Forwards Quarterly Rept 31 re CPPR-81 & CPPR-83 activities for Oct-Dec 1980 CDOK.J N. Consumers Power Co. 80/09/03 38pp
- 8010290352 Forwards monthly rept for Bept 1980 per ALAB-106 & Amend 1 to CP CODK.J W Consumers Power Co 80/10/25 400pp
- S. Reportable occurrences, LERs & related correspondence
- 8010100373 PNO-III-80-106 on 800530, Washington, DC news media reported problem w/installation of some instrumentation sys Refers to drawing inconsistencies re cross-preferencing of instrumentation wiring Corrective actions being taken.

 KNOP, R.C. FIGRELLIO Region 3. Chicago, Office of the Director.
 80/05/30 ip

- 8010020615 Part 21 rept re dampers shipped to facilities Dampers classified as nonsafety-related equipment & do not have potential to create substantial safety hazard Ref to 10CFR21 is retracted Affected customer & project list encl SLOAN,D E American Warming & Ventilating, Inc. 80/09/18 App
- 8010020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DSRV 12. DSRV 16 & DSRV 20 built before Feb 1780
 MARTINI, D H Transamerica Delaval. Inc 80/09/19 2pp
- B010060260 Forwards monthly rept for Aug 1980, per ALAB-104 Bechtel nonconformance repts, log rept sheets, quality action requests, mgt corrective action repts & B&W noncomformity, audit finding & corrective action repts also encl COBK. J W Consumers Power Co 80/09/22 200pp
- 8010200332 Ack receipt of 800909 interim deficiency rept re containment internal structures coating deficiency Will review final rept on matter upon receipt rept on matter upon receipt fightell, O Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/29 lp
- --8010200335 Interim deficiency rept re containment internal structures coating deficiency Progress made in isolating factors contributing to delamination condition & formulating corrective action program Next rept to be filed by 801103 CODX.J U Consumers Power Co 80/07/07 lp
- 8010170195 Ack receipt of 900919 interim deficiency rept re high energy line break analysis restraint design Finel rept will be reviewed pending receipt FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/30 lp
- 8010210072 Ack receipt of 800919 interim deficiency rept re component qualification test documentation review FIDRELLI, C. Region 3. (hicago, Reactor Construction & Engineering Support Branch 80/09/30 ip
- --B010210077 Interim deficiency rept re component qualifications test documentation review Util has developed program re qualification of safety-related electrical equipment Next rept will be forwarded by 801205 COOK, J N Consumers Power Co 80/09/19 45pp
- 8010210009 Part 21 rept re pipe supports w/partially or totally disengaged self-allgning rod end bushings furnished by ITT Orine: i.corner & Leda.Pacific Scientific-Kintech Div & NPS Industries WANE.H W Bechtal Power Corp (subs of Bechtal Corp) 80/10/08 4pp
- 8010200463 Interim rept re overstressed condition in letdown coaler supports Analyses of letdown coaler supports based on notifications are being conducted by manufacturer & B&W Interim or final rept will be sent on or before 801230 COQK, J H Consumers Power Co 80/10/10 1p
- 8010200301 Interim deficiency rept re potentially unsafe condition re tripping of reactor coolant pumps during certain primary sys high void fraction conditions Plant design will be modified to incorporate safety grade automatic trip circuitry. CODK, J W Consumers Power Co 80/10/10 2pp.
- B010270171 Part 21 rept ro pipe supports w/gartially or totally selfaligning rod end bushings Info submitted to other Bechtel Power Divs on B01008 for review. Rept will be provided if defect applies to other Bechtel projects. MARL, H W Bechtel Power Corp (subs of Bechtel Corp), 80/10/17
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISERHUT. D O Division of Licensing 80/09/19. 28pp.
- B010030485 Forwards description of R&W computer program AUX-1 used for analyzing steam generato; performance following auxiliary feedwater sys actuation. Analyses performed w/program will be utilized in licensee response to NRC Guestion 211 184 COOK.J W Consumers Power Co 80/09/22 17pp

- B010070529 Forwards "Bending Stresses in Underground Piping Due to Differential Soil Settlement," profiled in B00401 response to NRC request BATES.JD Rockwell International Corp., Energy Systems Div B0/10/01 ip
- --8010070339 "Bending Stresses in Underground Piping Due to Differential Soil Settlement " * Rockwell International Corp . Energy Systems Div 80/09/19
- 8010210300 Responds to util 800222 ltr questioning fee determination re application for Amend 72 to CP No new math has been presented to cause departure from previously stated NRC position Prompt payment is expected MILLER.W.O. License Fee Management Brench 80/10/02 lp
- 8010220008 Responds to util 800722 ltm questioning fee determination for Amend 72 NRC position stands Prompt payment is requested MILLER, W.O. License Fee Management Branch 80/10/02 ip
- BO10280692 Recommends two acceptable approaches to establishment of acceptable seismological input parameters Top of natural glacial till is appropriate location for vibratory ground motion input for site
 TEDESCORR L Assistant Director for Licensing. BO/10/14 4pp.
- BO10310494 Forward: Amend 2 to CPPR-B1 & CPPR-B2 & notice of issuance & availability
 MIRADLIAF Licensing Branch 3 80/10/20 2pp
- --8010310497 Amend 2 to CPPR-81 & CPPR-82. authorizing addition of antitrust conditions
 EISENHUT, D G Division of Licensing 80/10/20 22pp
- --B010310500 Notice of issuance & availability of Amend 2 to CPPR-81 & CPPR-82 HIRADLIA.F Licensing Branch 3 80/10/20 Zpp
- 8010310376 Forwards updated & modified svc lists re facility proceedings & CP application Suggests that NRC keep svc lists up to date BRUNNER,E J Consumers Power Co 80/10/28 17pp
- C. Utility Environmental Report (£R), amends & correspondence
- 8009300507 Forwards affidavit actnowledging distribution of Amend 82 to CP t OL application. Revision ii to environ rept. COOK, J N Consumers Power Co 80/09/22 4pp
- F Security, medical, emergency & fire protection plans
- 8010280266 Forwards "Evacuation Ciear-Time Estimates for Areas Near Midiand, HI Nuclear Power Plant." Times presented in study represent evacuation w/no emergency plan in effect COOK, J.W. Consumers Power Co. 80/10/20 ip
- O10310402 Forwards Revision 3 to security plan, training & qualification plan & safeguards contingency plan Plans withheld (ref 10CFR2, 790) COOK. J W Consumers Power Co BO/10/23 2pp

Adjudicatory correspondence

- 10020041 Notice of 801021-22 deposition of D Horn.T Cook & G Keeley of CPG.in Midland.MI re issues of ABLB 791206 order & ententions of intervenors Stamiris & Warren. Certificate of ce encl.

 ATON.W Hearing Branch 2 80/09/29 4pp.
- OD20736 Amended notice of Oct 1980 depositions of D Hond, L Heller & J Kane of NRC & JH Simpson, H Lawhead & R Erickson of Corp of Engineers re issues of ABLB 791206 order & contentions of Stamiris & Harren, Certificate of Evc encl. FARNELL, A S. Consumers Power Co. FARNELL, A S. Isham, Lincoln & Beale 80/09/29 App
- 110030127 Ack receipt of B00922 notice of deposition & request for production of documents Intends to cooperate despite noncompliance w/regulatory requirements. Notice amended to provide that documents will be w/deponents during deposition PATON:W D Hearing Branch 2. 80/10/01. ip.

- B010100045 Notice of B01007,08,09,14,15 & 16 depositions of D Hood, L Heller, J Kane, JW Bimpson, W Lawhead & R Erickson, respectively Certificate of Svc encl FARNELL, A G Consumers Power Co FARNELL, A S Isham, Lincoln & Beals 80/10/01 4pp
- 80i010004B Designation of IE Brunner, MI Miller, RG Zamarın & AB Farnell as persons on whom svc should be made in OL & order modifying CP proceedings JL Bacon, ME Gibbs & GA Bartelman should be deleted from svc list Certificate of Svc encl FARNELL, A B Consumers Power Co FARNELL, A B Isham, Lincoln & Beale 80/10/01 3pp
- B010060013 Requests repts of meetings hald in last three months of 1974 & 1975-79 & GA resumes discussed in ASLB initial decision, LBP-74-71, Paragraph 76 PATON, W D Hearing Branch 2 B0/10/02 1p
- 8010070409 Notice of 801028-29 depositions of W Ferris, S Afifi & J Wanzeck of Bechtel Associates re issues stated in ABLB 791205 order & contentions agreed upon by intervenors Stameris & Warren Certificate of Svc encl PATON, W D Hearing Branch 2 80/10/06 4pp
- 8010140908 Interrogatories soliciting info re performance of lab tests on plant fill samples & discrepancy in magnitude of loading stress indicated in Figure 2 of 800914 rept & info previously supplied Certificate of Svc ancl PATON:W D Hearing Branch 4 80/10/09 4pp
- B0i0150017 Amended notice of deposition Deposition of D Horn will be taken on 801021.of T Cook on 801022 & of 0 Keeley on 801022 Cartificate of 8vc enci.
 PATON.W.D Hearing Branch 4 80/10/10 4pp
- 80:0150966 Amended notice of deposition Deposition of W Ferris will be taken on 80:1028;8 Afifi on 80:1027 & J Wanzeck on 80:1029 Certificate of Bvc enci PATON.W D. Hearing Branch 4 80/10/10 4pp
- 80:0160758 Response in apposition to 8 Stamiris 800723 amended petition to intervent Contention 4c Contention fails to satisfy specificity requirement Certificate of Svc encl FARNELL.A 8 Consumers Power Co FARNELL.A 8 Isham, Lincoln & Beale. 80/10/10 4pp
- 8010160997 Forwards D Hood & L Helier 801007-09 depositions W/o encl JUNES,B W Hearing Branch 2 80/10/14 ip.
- 8010160605 Response in support of B Stamiris 801010 amended petition to intervene & of B Stamiris 800924 Contention 4c re soil settlement remedial actions Certificate of Svc encl JCNES,B H. Hearing Branch 2 80/10/14 4pp.
- B010270503 Advises that applicant & NRC discovery will take innger than time stated at 800710 prehearing conference Status will be reported periodically.

 PATON, H D Hearing Branch 2. 80/10/24 1p.
- 8010280555 Order re 800910 prehoaring conference granting B Stamiris & SK Warren petitions & denying WH Marshail, PA Race, SD Reist et al petitions to intervene Consolidation of DL & license mod proceedings granted Waccepted contentions

 BECHHOEFER, C Atomic Bafety and Licensing Board Panel 80/10/24,
- 8010300038 Forwards exhibits of J Kane 801014,15 & 14 deposition H/o encl PATON, H D Hearing Branch 2 80/10/27 ip.
- B010300042 Forwards DB Hood B01007 deposition W/o encl PATON: W D Hearing Branch 2. B0/10/27 ip.
- B010300054 Forwards exhibits of D Horn B01021-22 deposition.T Cooke B01022 deposition & B Keeley 801023 deposition H/o encl JONES, B. W. Hearing Branch 2. 80/10/27 ip
- 8010300062 Advises that CPC reply to NRC 800827 requests re dewatering info.will be filed on 801031 in form of addition to CPC 800211 responses re plant fill. PATON.W D Hearing Branch 2 80/10/28 ip.
- 8010310376 Forwards updated & modified svc lists re facility proceedings & CP application Suggests that NRC keep svc lists up to date PRUNNER.E.J., Consumers Power Co. 80/10/28 17pp,

H Ceneral correspondence

- 8010170210 Forwards licensee 800714 ltr re correlation strength test templing frequency Reply is consistent w/NRC position SCHWENCER, A Licensing Branch 3 80/10/03 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010240204 Amend 83 to FSAR, Revision 30, Vol 1, revising & supplementing application for CP & OL Util position re NUREO-0667, NUREO-0694 & 106FR50 54(f), "Responses to Post-TMI-2 Issues & Events," encl CODK.J W Consumers Power Co 80/10/21 650pp
- --B010240214 Amend 83 to FSAR.Revision 30.Vol 2.revising & supplementing application for CP & OL. COOK.J U Consumers Power Co 80/10/21 600pp
- --B010240221 Amend 83 to FSAR.Revision 30.Vol 3.revising & supplementing application for CP & DL COOK, J. W. Consumers Power Co. 80/10/21 500pp
- --8010240230 Amend 83 to FSAR, Revision 30, Vol 4, revising & supplementing application for GP & DL Addendum, NRC open items encl COOK, J H Consumers Power Co 80/10/21, 400pp
- 8010310384 Forwards Certificate of Svc of Amend 83 consisting of Revision 30 to FSAR, to application for CP t OL BRUNNER, E J Consumers Power Co 80/10/27 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 80:01:60324 Forwards 1E Insp Repts 50-329/80-24 & 50-330/80-27 on 600801~31 No noncompliance noted. FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/09/10 2pp
- --Boioi60332 IE Insp Repts 50-329/80-26 & 50-330/80-27 on 800801-31
 No moncompliance noted Major areas inspected axamination of
 site conditions & detensioning of reactor vessel holddown
 bolts
 COBK, R. J., KNDP, R. C. Region 3, Chicago, Office of the Director
 BO/09/09, 5pp.
- 8010230574 Forwards IE Insp Repts 50-329/80-23 & 50-330/80-24 on 800819-22 No noncompliance noted FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/15. 2pp
- --B010230677 IE Insp Repts 50-329/80-23 & 50-330/80-24 on 800819-22 No noncompliance noted Major areas inspected const schedules, outstanding items of noncompliance, new util GA organization & examination of site const activity SUTPHIN,R N. KNDP,R C Region 3, Chicago, Office of the Director 80/09/15 3pp.
- B010240325 Forwards IR Insp Repts 50-329/80-25 & 50-330/80-26 on 800827-27 No noncompliance noted. FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/13. 2pp
- --8010240330 IE Insp Repts 50-329/80-25 & 50-330/80-26 on B00827-29 No noncompliance noted. Major areas inspected containment prestressing sys work activities, Hidland soil issues & quality records HAYES, D W. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch GALLAGHER, E J , LANDBHAN, R. B Region 3, Chicago, Office of the Director 80/09/12 5pp
- 8010080570 Responds to IE Bulletin 80-14, "Potential Misapplication of Rosemont, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or 0 Output Codes." Rosemont 1152 transmitters used in Class IE applications No safety violations noted COOK, J W. Consumers Power Co 80/09/22, ip
- 8010090175 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches," Specified switches are not used in currently designed safety-related applications COOK, U W Consumers Power Co 80/09/22, ip
- 8010160258 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " No written response required, KEPPLER.J O Region 3, Chicago, Office of the Director 80/09/30

- 8010280034 Forwards IE Circular B0-22, "Confirmation of Employee Qualifications " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/10/02 to
- 8010270021 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/10 ip
- R Periodic operating reports & related correspondence
- 8010030218 Forwards Quarterly Rept 31 re CPPR-81 & CPPR-83 activities for Oct-Dec 1980 CDGK.J W Consumers Power Co 80/09/03 38pp
- 8010290352 Forwards monthly rept for Sept 1980 per ALAB-106 & Amend 1 to CP CODA.J N Consumers Power Go 80/10/25 400pp
- S Reportable occurrences, LERs & related correspondence
- 8010100373 PNG-III-80-106 on 800530, Washington, DC news media reported problem winstaliation of some instrumentation sys Refers to drawing inconsistencies re-cross-referencing of instrumentation wiring Corrective actions being taken KNDP, RC , FIGRELLI, C Region 3, Chicago, Office of the Director 80/05/30 ip
- 8010020615 Part 21 rept re dampers shipped to facilities Dampers classified as nonsafety-related equipment & do not have potential to create substantial safety hazard Ref to 10GFR21 is retracted Affected customer & project list enci SLOAN,D E American Warming & Ventilating, Inc 80/09/18 App
- 8010020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DSRV 16 & DSRV 20 built before Feb 1980 MARTINI.D H Transamerica Delaval, Inc 80/09/19, 2pp
- 8010040240 Forwards monthly rept for Aug 1980, per ALAB-106 Bechtel nonconformance repts, log rept sheets, quality action requests, mpt corrective action repts & BMH noncomformity, audit finding & corrective action repts also and CDDX, J W Consumers Power Co 80/09/22 200pp
- 8010200332 Ack receipt of 800909 interim deficiency rept re containment internal structures coating deficiency Will review Pinal rept on matter upon receipt FIURELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/09/29 ip
- --8010200335 Interim deficiency rept re containment internal structures coating deficiency Progress made in isolating factors contributing to delamination condition & formulating corrective action program Next rept to be filed by 801103 COOK, J H Consumers Power Co 80/09/09 1p
- 8010170195 Ack receipt of 800919 interim deficiency rept re high energy line break analysis restraint design Final rept will be reviewed pending receipt FIURELLIO Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/09/30 ip
- 8010210072 Ack receipt of 800919 interim deficiency rept re component qualification test documentation review FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/30 ip
- --8010210077 Interim deficiency rept re component qualifications test documentation review. Util has developed program re qualification of safety-related electrical equipment. Next rept will be forwarded by 801205 COOK. J W Consumers Power Co 80/09/19 65pp
- 8010210009 Part 21 rept re pipe supports w/partially or totelly disengaged self-aligning rod and bushings furnished by ITT Grinell. Corner & Lada, Pacific Scientific-Kintoch Div & NPS Industries WAHL, H. W. Bechtel Power Corp (subs of Bachtel Corp.) 80/10/08 4ps.
- 8010200463 Interim rept re averstressed condition in letdown cooler supports. Analyses of letdown cooler supports based on nazzle loads are being conducted by manufacturer & BBH Interim or final rept will be sent on or before 801230 COOK, J W Consumers Power Co 80/10/10 ip

- 8010200501 Interim deficiency rept re potentially unsafe condition re tripping of reactor contant pumps during certain primary sys high void fraction conditions Plant design will be modified to incorporate safety grade automatic trip circuitry COUK.J U Consumers Power Co 80/10/10 2pp
- 8010270171 Part 21 rept re pipe supports w/partially or totally selfaligning rod end bushings Info submitted to other Bechtel Power Divs on 801008 for review Rept will be provided if defect applies to other Bechtel projects WAMIL.H U Bechtel Power Corp (subs of Bechtel Corp) 80/10/17 2pg

DOCKET 90-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans

- 8010160723 Forwards evaluation of util response to open issues in NRC 800604 fire protection safety evaluation Automatic Halon sys is not required due to alternate safe shutdown sys plans Review status encl IPPOLITO:TA Gperating Reactors Branch 2 80/09/30 5pp
- G Adjudicatory correspondence
- B010030240 Forwards 800919 order revising 800829 order for mod of OL, in entirety
 EISENHUT, D Q Division of Licensing 80/09/19 2pp
- --B010030250 Order revising B00B29 order for mod of CL DPR-49 published in B00912 FR, in entirety Response to IE Bulletin 79-018 shall be submitted by B0101 Request for hearing will not stay effectiveness of order UCB petitions discharged EIGENHUT. D & Division of Licensing 80/09/19 3pp
- 801003028 Forwards Director's decision under 10CFR2 206 & FR notice denying Citizens United for Responsible Energy 790717 petition for amound to OL reflecting NEDD-23631. "BWR Coolant Orygen Control." recommendations
 DENIGN.H R Diffice of Nuclear Reactor Regulation, Director 80/09/24 Rop
- -8010030032 Director's decision under 10CFR2 206 denying Citizens United for Responsible Energy 790717 petition request for amend to OL reflecting NEDO-23631, "BHR Coolant Oxygen Control," recommendations
 DENION: HR Office of Nuclear Reactor Regulation, Director 80/09/24 8pp
- --B010030040 Notice of issuance of Director's decision under 10CFR2 206.
 denying Citizens United for Responsible Energy 790717
 petition
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 B0707/24 2pp
- 8010270347 Advises that on 801014, Director's decision (DD-80-27) became final agency action for purposes of judicial review CHILK, S. J. Office of the Secretary of the Commission 80/10/27, to
 - Advisory Committee on Reactor Safeguards reports & correspondence
 - 10170319 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BWR Scram Bys " $$\rm HTMPELDS,J-ACRS-Advisory~Committee~on~Reactor~Safeguards~80/08/08-ip$
- -8010170333 Interim preliminary draft rept to ACRS, "Review of Recent Malfunctions of BMR Scram Sys " * ACRB - Advisory Committee on Reactor Safeguards 80/08/08
- Operating license stage documents & correspondence
- IDIO220079 Forwards erreta sheets amending 600705 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT. D O Division of Licensing 80/07/17 28pp
- 80(0030407 Forwards revised mod proposal to reactor protection sys motor generator sats, incorporating two protective circuitry packages in series between each motor generator sat & associated reactor protection sys bus Diagram enci ROOT, L. D. Jowa Electric Light & Power Co. 80/09/25. 3pp

- 8010150317 Application to amend License DPR-49 modifying Tech Specs to incorporate limiting condition of operations/surveillance requirements for control rod block scram discharge vol limit switches into Tables 3 2-C & 4 2-C Tables & amend fee encl RODT, L D lowa Electric Light & Power Co 80/10/09 4pp
- 8010240220 Application to amend License DPR-49, changing App A Tech Specs to provide for single recirculation loop operation ROOT, L D Towa Electric Light & Power Co 60/10/17 1p
- ~-8010240225 Proposed Change RTS 124 to App A Tech Specs.Sections 1 0 & 3 0.to provide for single recirculation loop operation # Iowa Electric Light & Power Co 80/10/17 36pp
- 8010300480 Responds to DO Eisenhut 801001 ltr re BWR scram sys Reassesament of scram sys shows no 100FR50 App A general design critoria deficiencies Will provide results of re-evaluation by 801215 RGOT, L D Iowa Electric Light & Power Co 80/10/23 1p
- @ Inspection reports, IE Bulletins & correspondence
- 8010150096 Forwards IE Insp Rept 50-331/80-12 on 800804-06 No noncompliance noted HEISHMAN,R F Region G. Chicago, Reactor Operations Nuclear Support Branch 80/09/18 200
- --8010150102 IE Insp Rept S0-331/80-12 on B00804-06 No noncompliance noted Major areas inspected control rod exercises & scram time reactivity anomaly determination & core power distribution limits
 STREETER.JF., CHOULES, N. C., HDPKINB, J. B. Region 3, Chicago, Office of the Director 80/08/15 4pp
- B010150106 Forwards IE Insp Rept 50-331/80-11 on 800701-31 No noncompliance noted, HEISHMAN.R.F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/08/19 App
- --8010150112 IE Insp Rept 50-331/80-11 on 800701-31 No noncompliance noted Major areas inspected operational safety verification, monthly surveillance & maint observation & IE bulletin & circular followup
 LITLE.W B. CHRISTIANSON.W. CLARDY.L S. Region 3. Chicago.
 Office of the Director BO/08/18 5pp
- 8010210013 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas.

 KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/03
- 8010200693 Forwards IE Insp Rept 50-331/80-14 on 800817-22 & 0904-05 Na noncompliance noted. FIORELLIO Region 3: Chicago: Reactor Construction & Engineering Bupport Branch 80/09/17 Zpp
- --80i0200685 IE Insp Rept 90-331/80-14 on 800819-22 & 0904-05 No noncompliance noted Major areas inspected licensee & contractor specs, procedures, work activities & GA documentation re torus support reinforcement installation KEY,N J , DANIELSON,D H Region 3, Chicago, Office of the Director 80/09/16 5pp
- 8010160295 Forwards Suppl 2 to IE Sulletin 79-018. "Environ Gualification of Class IE Equipment." No written response required
 KEPPLER, J.O. Region 3, Chicago, Office of the Director. 80/09/30 tp.
- 8010280639 Forwards IC Circular 80-22, "Confirmation of Employee Gualifications" No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director. 80/10/02 1p.
- 8010170549 Forwards IE Insp Rept 50-331/80-17 on 800708-12 & notice of violation Notice of violation withheld (ref 100FR2 790) HIND: J. A Region 9: Chicago: Safeguards Branch 80/10/03 2pp
- --8010170546 IE Insp Rept 50-331/80-17 on 800908-12 Noncompliance noted some watchman not adequately screened per security plan commitments Details withheld (ref 100FR2.790) CREED.J R., BELANGER, J.L. Region G. Chicago, Office of the Director HIND.J A Region G. Chicago, Bafeguards Branch. 80/09730 2pp

- 8010290027 Forwards IE Info Notice 80~34, "Failure of Steam Generator Support Bolting," No specific action or response requested XEPPLER.J G Region 3. Chicago, Office of the Director 80/10/10 19
- R Periodic operating reports & related correspondence
- 8010210404 Forwards monthly operating rapt for Sept 1980, MINECK,D.L. Iowa Electric Light & Power Co. 80/10/15 1
- --8010210408 Monthly operating rept for Sept 1780
 VAN SICKEL, J Iowa Electric Light & Power Co 80/10/15 7pp
- 8 Reportable occurrences, LERs & related correspondence
- B010090252 PND-III-80~134 on 800715, during testing & walkdown of control rod drive hydraulic sys.scream discharge vol drain valvs was determined to be installed backward Reverse installation does not have detrimental effect on scream CHRISTIAN40N, W. LITTLE, W.S., HEISHMAN, F. Region 3, Chicago. Office of the Director 80/07/16. App
- 8010150439 Forwards LER 80-045/03L-0 MINECK, D. L. lowa Electric Light & Power Co. 80/10/08 ip
- --B010150450 LER B0-045/03L-0 on B00708, during surveillance testing, condensate storage tank IT-5A low level switch LB-5218 was found inoperable Cause unknown Investigation continuing RAGER, M S lows Electric Light & Power Co B0/10/08 ip
- E010150475 Forwards LER 80-046/03L-0
 MINECK, D. L. lows Electric Light & Power Co. 80/10/08 ip.
- --B0101504B3 LER B0-046/03L-0 on B00909, during surveillance testing, reactor core isolation cooling turbine trip & sys isolation occurred. Caused by faulty torque switch in valve operator Buitch adjusted RAOER, M S. Iowa Electric Light & Power Co B0/10/08 1g
- 8010150421 Forwards LER 80-048/03L-0. MINECK,D L lowe Electric Light & Power Co 80/10/09 ip.
- B010150457 Forwards LER 80-049/03L-0 MINECK, D. L lows Electric Light & Power Co 80/10/09 1p
- --BOLO180447 LER 80-049/03L-0 on 800919, during surveillance testing, HPCI leak detection temp differential switch TDB 2260A was found failed downscale Caused by incoperable temp switch & temp element Both components replaced RAGER, M.S. Iowa Electric Light & Power Co. 80/10/09. 1p.
- SOI0150490 Farwards LER 80-047/03L-0 MINECK:D L lows Electric Light & Power Co. 80/10/09 1p
- --8010150499 LER 80-047/03L-0 on 800911.during surveillance testing, reactor water cleanup sys return line isolation valve MOV-2740 did not close within required time.Caused by loose set rod.Limit switch readjusted & set rod tightened RAOER.M.S. lowa Electric Light & Power Co. 80/10/09. ip
- S010230471 Forwards LER S0-050/03L-0
 MINECK,D L Iowa Electric Light & Power Co S0/10/16 ip.
- ---8010220472 LER 80-050/03L-0 on 800917, reactor core isolation cooling steam supply line isolation valve MOV-2401 would not open after being cycled closed during surveillance test Caused by faulty valve motor operator torque switch Switch replaced RAGER, M. S. lowe Electric Light & Power Co. 80/10/16. ip.
- DOCKET 50-332 BARNHELL REPROCESSING PLANT
- O Adjudicatory correspondence
- 8010010830 Comments on proposed rule RM 50-5:re NRC termination of efforts on GEBMO fuels NRC should resume GEBMO proceeding. Certificate of Bvc & svc list encl DECHER.U Affiliation Unknown. B0/09/03. 7pp.

- B010230281 Comments by TN Technological Univ on rulemaking 50-5 GESMO proceedings should be restarted immediately.

 DEMAS.N G Affiliation Unknown 80/07/11 1p
- 8010230349 Comments on rulemaking 50~5 supports reopening of GESMD proceedings LORFING, D Affiliation Unknown 80/09/11. 1p
- B010220540 Comments on rulemaking 50-5,NRC should not reopen OESMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to US nonproliferation policy HCLAUGHLIN.W Y Affiliation Unknown 80/09/12 1p
- B010230245 Comments on rulemaking 50~5 QEBMO proceedings should be resumed HACHNEY.C A Affiliation Unknown 80/09/12 1p
- 8010230341 Comments on rulemaking 50-5 CESMO proceedings should be reopened. LOPEZ/C R Affillation Unknown 80/07/12 ip
- B010020697 Recommends OEBMO proceedings be completed. Technically competent people available to complete GEBMO project Further delay in proceedings will increase energy costs OEBMO will provide basis for future decisions re spent nuclear fuel KURRAY: H Affillation Unknown. B0/09/13. 1p
- 8010230328 Comments on rulemaking 50-5 0ESMO hearings should not be reopened due to problems w/reprocessing Health hazards associated w/transport & reprocessing shown to be more serious than previous expectations
 CLEMENTS, T Affiliation Unknown. 80/09/13 ip
- 801022051B Comments on rulemaking 30~5 GESMO hearings should resume immediately BARRY.D Affiliation Unknown B0/09/14. 1p
- 8010230317 Comments on rulemaking 50-5 OESMO proceedings should not be reopense.
 TUCKER.C.A Affiliation Unknown 80/07/14 ip
- 8010230323 Comments on rulemaking 50-5 re resuming 9E8MD proceedings CHUBB.W Affiliation Unknown 80/09/14 3pp
- B010230231 Comments on rulemaking 50-5 OESHO proceedings should be resumed Delays will not serve nath security & will increase cost of energy GOURTNEY, J C Affiliation Unknown 80/09/15 te.
- 8010230247 Comments on rulemaking 50~5 Commission should reopen GESHQ processings BARRY.J E Affiliation Unknown 80/09/15 ip.
- BOIO230291 Comments on rulemaking 50-5-0EBMD hearings should be reopened
 JONES, W Affiliation Unknown 80/09/15 1p.
- 8010220527 Comments on rulemaking 50-5 supports resumption of GESMD proceedings CREIEZEMBKI,P Affiliation Unknown 80/07/16. 1p.
- 8010220663 Comments on rulemaking 50-5.088MO proceedings should be reopened Draft article encl which should have some input in forming policy on recycling Pu DEYA.R Citizens United for Responsible Energy. 80/09/17 9pp.
- 8010230304 Comments on rulemaking 50-5 GEBMO proceedings should be resumed UB should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent Puel PANZANI, F.A. Affiliation Unknown 80/09/17, ip.
- 8010020019 Comments an reopening of QESMO proceedings re Rulemaking 50-5; reopening & successful completion of hearing is lagical precedent to commercial reprocessing of spent nuclear fuel, QIBBB.D.C Affiliation Unknown. 80/09/23 Zpp.
- 8010020690 Recommends resumption of OESMO proceedings Persian Oulf area warfare necessitates technical development of spent reactor fivels to lessen dependence on imported oil MARWICK,E.F. Affiliation Unknown. 80/09/23, 1p.
- 8010020012 Comments by two citizens in support of respening of GESMO proceedings re Rulemaking 50-5 further consideration needed for energy development.

 BREITMAYER.F., KIRTLEY.J., Affiliation Unknown 80/09/24, 2pp

- 8010200501 Interim deficiency rept re potentially unsafe condition re tripping of reactor coolant pumps during certain primary sys high void fraction conditions Plant design will be modified to incorporate safety grade automatic trip circuitry COOK, J W Consumers Power Co 80/10/10 2pp
- B010270171 Part 21 rept re pipe supports u/partially or totally selfaligning rod and bushings info submitted to other Sechtel Power Divs on 801008 for review Rept will be provided if defect applies to other Bechtel projects WARLLH (I Bechtel Power Corp (subs of Bechtel Corp) 80/10/17 20p

DOCKET 50-001 DUANE ARNOLD ENERGY CENTER

- F Security, medical, emergency & fire protection plans
- 8010160723 Forwards evaluation of util response to open issues in NRC 800604 fire protection safety evaluation Automatic Halon sys is not required due to alternate safe shutdown sys plans Review status encl IPPOLITO, T.A. Operating Reactors Branch 2 80/09/30 5pp

O Adjudicatory correspondence

- 8010030240 Forwards 800919 order revising 800929 order for mod of GL.in entirety SISENHUTD O Division of Licensing 80/09/19 2pp
- --8010030250 Order revising B00827 order for mod of OL DPR-47 published in 800912 FR. in entirety Response to IE Bulletin 79-018 shall be submitted by 801101 Request for bearing will not stay effectiveness of order VCS petitions discharged EISENHUT. D O Division of Licensing 80/09/19. Spp
- 8010030028 Forwards Director's decision under 100FR2 206 & FR notice denying Citizens United for Responsible Energy 790717 petition for amend to QL reflecting NEDQ-23631, "BUR Coolant Oxygen Control," recommendations DENION, H R Office of Nuclear Reactor Regulation, Director. 80/09/24 2pp
- --801003022 Director's decision under 10CFR2 206 denying Citizens United for Responsible Energy 790717 petition request for amend to OL reflecting NEDO-23631, "BWR Coolant Orygen Control," recommendations DENTGI,H R Office of Nuclear Reactor Regulation, Director 80/09/24 Opp
- --9010030040 Notice of issuance of Director's decision under LOCFR2 206.
 donying Citizens United for Responsible Energy 790717
 potition
 DENTOH, H. R. Office of Nuclear Reactor Regulation, Director
 B0/09/24 2pp
- BO10290349 Advises that on BO1014, Director's decision (DD-80-29) became final agency action for purposes of judicial review CHILK, B. J. Office of the Secretary of the Commission BO/10/27, ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8010170319 Forwards interim preliminary draft rept "Review of Recent Malfunctions of BMR Scram Sqs " BTAMPELOS.J ACRS — Advisory Committee on Reactor Bafaguards 80/08/08 tp
- --8010170333 Interim preliminary draft rept to ACRS, "Review of Recent Malfunctions of BWR Scram Sys " * ACRS - Advisory Committee on Reactor Safeguards 80/08/08
- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENRUT. D O Division of Licensing 80/09/19 28pp
- 8010030407 Forwards revised mod proposal to reactor protection sys motor generator sets, incorporating two protective circuitry packages in series between each motor generator set & associated reactor protection sys bus Diagram encl ROOT, L D. Iowa Electric Light & Power Co 60/09/25 App

- 8010190317 Application to amend License DPR-49 modifying Tech Space to incorporate limiting condition of operations/survoillance requirements for control rod block scram discharge vol limit switches into Tables 3 2-C & 4-C Tables & amend fee encl ROGILD Jowa Electric Light & Power Co 80/10/09 App
- 8010240220 Application to amend License DPR-49, changing App A Tech Specs to provide for single recirculation loop operation ROOT, L.D. Jowa Electric Light & Power Co. 80/10/17 lp
- --8010240225 Proposed Change RT8 124 to App A foch Specs. Sections 1 0 to 3 0.to provide for single recirculation loop operation a lowa Electric Light & Power Co 80/10/17 36pp
- 8010300480 Responds to DG Eisenhut 801001 ltr re DWR scram sys Reassessment of scram sys shows no LOCERSO App A general design criteria deficiencies Will provide results of re-evaluation by 801215 RDOT.L.D. Yowa Electric Light & Power Co. 80/10/23 ip
- G Inspection reports: IE Bullstins & carrespondence
- 8010150096 Forwards IE Insp Rept 50-331/80-12 on 800804-06 No noncompliance noted HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Gupport Branch 80/08/18, 2pp
- --8010150102 IE Insp Rept 50-391/80-12 on 800804-06 No noncompliance noted Major areas inspected control rod exercises & scram time reactivity anomaly determination ? core power distribution limits STREETER.JF. CHOULES,N C. HOPKINB,J B Region 3, Chicago, Office of the Director 80/08/15 4pp
- B010150106 Forwards IE Insp Rept 90-331/80-11 on 800701-31 No noncompliance noted HEIBHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/19 2pp
- --8010150112 IE Insp Rept 50-331/80-11 on 800701-31 No noncompliance noted Major areas inspected operational safety verification, monthly surveillance & maint observation & IE builtin & circular follows LITLE-IN 8. CHRISTIANSON, W. CLARDY, L. S. Region 3. Chicago, Office of the Director 80/08/18 Spp
- 8010210013 Provides updated info re admittance of Region 3 personnel to facilities Forwards lists of personnel for whom permanent nonemployee badges are requested & personnel requiring badge for unescarted access in protected areas KEPPLER, J O Region 3, Chicago, Office of the Director (00/07/U) 400
- 8010200693 Forwards IE Insp Rept 50-331/80-14 on B00819-22 & Q904 05 ha honcompliance noted FIORELLI, G Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/09/17 2pp
- --8010200685 IE Insp Rept 50-331/80-14 on 800819-22 & 0904-05 No noncompliance noted Major areas inspected licenses & contractor specs, procedures, work activities & GA documentation re torus support reinforcement installation KEY.H J DANIELSON.D H Region 3, Chicago, Office of the Director 80/09/16 5pp
- 8010140295 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required. KEPPLER, J. O Region 3, Chicago, Office of the Director. 80/07/30
- 801028063B Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director BQ/10/C2 to
- 8010170543 Forwards IE Insp Rept 50-331/80-17 on 800908-12 & notice of violation. Notice of violation withheld (ref 100FR2, 770) HIND, J. A. Region 3, Chicago, Safeguards Branch 80/10/03 2pp
- --8010170546 IE Insp Rept 50-331/80-17 on 800908-12. Noncompliance hoted some watchmen not adequately screened per security plan commitments. Details withheld (ref 100FRZ 790).

 CREED, J. R. BELANGER, J. L. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Safeguards Branch 80/09/30 Zpp

- 8010290027 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J Q Region 3, Chicago, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010210404 Forwards monthly operating rept for Sept 1980 MINECK, B, L. Iowa Electric Light & Power Co. 80/10/15 ip
- ~~8010210408 Monthly operating rept for Sept 1980
 VAN BICKEL,J lows Electric Light & Power Co 80/10/15 7pp
- B Reportable occurrences: LERs & related correspondence
- 8010070232 PND-III-80-134 on 800715, during testing & walkdown of control rod drive hydraulic sys.scram discharge vol drain valve was determined to be installed backward Reverse installation does not have detrimental effect on scram CHRISTIANBON,W , LITTLE.W S , HEISHMAN.R F Region 3, Chicago. Office of the Director 80/07/16 App
- BO10150439 Forwards LER 80-049/03L-0 MINECK, D. L. Idwa Electric Light & Power Co. 80/10/08 1p
- ---B010130450 LER 80-045/03L-0, on 800708, during surveillance testing, condensate storage tank IT-5A low level switch L8-5219 was found inoperable. Cause unknown Investigation continuing RAOER, M. 8 I new Electric Light & Power Co 80/10/08 ip
- 8080150475 Forwards LER 80-046/03L-0 MINECK, D. L., Idwa Electric Light & Power Co. 80/10/08, ip
- --B010150483 LER 80-046/03L-0 on 800909, during surveillance testing, reactor core isolation cooling turbine trip & sys isolation occurred Caused by faulty torque switch in valve operator Ewitch adjusted, RAGER,M.S. Iowa Clectric Light & Power Co 80/10/08, 1p
- 8010150421 Forwards LER 80~048/03L~0 MINECK,D L. lows Electric Light & Power Co 80/10/09 ip
- --B010180431 LER B0-049/03L-0:on 900912, during operation w/reactor water cleanup sys out of svc.reactor recirculation sample inboard valve CV 4639 would not open Caused by personnel error in tagging out nitrogen supply to operator of valva CV 4639, RAGER, M. 8 Iowa Electric Light & Power Co 80/10/09 ip
- B010150457 Forwards LER 80-049/03L-0 HINECK, D. L. IDWA Electric Light & Power Co. 80/10/09 1p
- --BOID150467 LER 80-049/03L-0: on 800919, during surveillance testing, HPCI leak detection temp differential switch TDB 2260A was found failed downscale Caused by inoperable temp switch & temp element Both components replaced RAOER.M.S lows Electric Light & Power Co 80/10/09, ip
- BO10150490 Forwards LER 80-047/03L-0. MINECK,D L. Iowa Electric Light & Power Co. 80/10/09 1p
- --8050150499 LER 80-047/03L-0. on 800911, during surveillance testing, reactor water cleanup sys return line isolation valve MOV-2740 did not close within required time. Caused by loose set rod tightened.
 RAGER, M.B. I lowa Electric Light & Power Co. 80/10/09. ip
- BO10220471 Forwards LER 80-030/03L-0
 MINECK, D L Iowa Electric Light & Power Co B0/10/16 1p.
- --BO10220472 LER BO-050/03L-0. on B00917, reactor core isolation cooling steam supply line isolation valve MOV-2401 would not open after being cycled closed during surveillance test. Caused by faulty valve motor operator torque switch. Buttch replaced RAGER, M.S. Iowa Electric Light & Power Co B0/10/16. Ip.
- DOCKET 50-332 BARNHELL REPROCESSING PLANT
 Q Adjudicatory correspondence
- BOLOO10830 Comments on proposed rule RK 50-5; re NRC termination of afforts on OESMO fuels, NRC should resume OESMO proceeding. Certificate of Bvc & svc list enci.

 DECHER, U. Affiliation Unknown. BO/09/03 7pp.

- 8010230R81 Comments by TN Technological Univ on rulemaking 50-5 GESMO proceedings should be restarted immediately DEMAS.N O Affiliation Unknown 80/09/11 1p
- 8010230349 Comments on rulemaking 50-5 supports reopening of GEBMO proceedings
 LORFINO.D Affiliation Unknown 80/09/11 ip
- 8010220540 Comments on rulemaking 50-5 NRC should not reapen GESMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to U5 nonproliferation policy
 MCLAUGHLIN.W T. Affiliation Unknown 80/09/12 1p
- B010230265 Comments on rulamaking 50-5 GESMO proceedings should be resumed HACHEY, C.A. Affiliation Unknown B0/09/12 ip.
- 8010230341 Comments on rulemaking 50-5 GESMO proceedings should be respensed
 LOPEZ.C R Affiliation Unknown 80/09/12 in
- 8010020699 Recommends GESMO proceedings be completed Technically competent people available to complete OESMO project Further delay in proceedings will increase energy costs GESMO will provide basis for future decisons re spent nuclear fuel MURRAY.H Affiliation Unknown 80/09/13 1p
- 801023032B Comments on rulemaking 50-5 GEBKO hearings should not be reopened due to problems w/reprocessing Health hazards associated w/transport & reprocessing shown to be more serious than previous expectations CLEMENTB.T Affiliation Unknown 80/09/13 ip
- 8010220518 Comments on rulemaking 50-5 GESMO hearings should resume immediately.

 BARRY, D. Affiliation Unknown 80/09/14 lp
- BO10230317 Comments on rulemaking 50-5, GEBHO proceedings should not be reopened TUCKER, C.A. Affiliation Unknown BO/07/14 ip
- 8010230323 Comments on rulemaking 50-5 re resuming QESMO proceedings CHUBB,W Affiliation Unknown 80/09/14 3pp
- 8010230231 Comments on rulemaking 50-5 CESMO proceedings should be resumed. Delags will not serve nath security & will increase cost of energy COURTNEY. J C Affiliation Unknown 80/09/15 ip
- 8010230247 Comments on rulemaking 50-5 Commission should reopen GESHB proceedings
 BARRY, J E Affiliation Unknown 80/09/15 ip
- BO10230291 Comments on rulemaking SO-5 GESMD hearings should be racepened JONEG N Affiliation Unknown 80/09/15. ip
- B010220529 Comments on rulemaking S0-5 supports resumption of QESMO proceedings
 GREIBZEWSKI,P Affiliation Unknown 80/09/16. ip
- 8010220663 Comments on rulemaking 50-5-GEBMD proceedings should be reopened Draft article encl which should have some input in forming policy on recycling Pu DEYAR Citizens United for Responsible Energy 80/09/17 9pp.
- 8010230304 Comments on rulemaking 50-5.0E9MO proceedings should be resumed US should do everything to minimite use of foreign oil & extend U reserves by reprocessing of spent fuel, PANZANI.F A Affiliation Unknown. 80/09/17 ip
- 8010020019 Comments on reopening of GEBMO proceedings we Rulemaking 50-5 reopening & successful completion of hearing is logical precedent to commercial reprocessing of spent nuclear fuel. 01889.3. C. Affiliation Unknown. 80/09/23 2pp.
- 8010020690 Recommends resumption of QESMO proceedings Persian Gulf area warfare necessitates technical development of spent reactor fuels to lessen dependence on imported oil MARNICK, E. F. Affiliation Unknown 80/09/23 1p
- BO10020012 Comments by two citizens in support of reopening of GESKO proceedings ra Rulemaking 50-5 further consideration needed for energy development.

 BREITMAYER, F., KIRTLEY, J., Affiliation Unknown. B0/09/24. 2pp

- 8010020682 Forwards constituent commants on OESMO proceedings, Requests status of NRC intentions re-proceedings MOORE, N.H. House of Reg. Maus and Means. 80/09/24. 3pp.
- 8010020005 Comments on reopening of GESMO procedings re Rulemaking 50-5 continuation of review process needed to determine whether reprocessing & recycling is viable option DRAPER, E. L. Quif States Utilities Co. 80/09/25.
- 8010020081 Comments on respensing of GESMO proceedings we Rulemaking 50-5 hearing must be respensed promptly due to need for establishing legal & logical basis for evaluation of spent fuel reprocessing.

 BEHNKE, & B Commonwealth Edison Co 80/09/25 2pp.
- 8010020007 Comments on respening of GESMG proceedings as Rulemaking 50-5, no further action needed due to completion of avidance. THOMAS, R Environmentalists, Inc. 80/09/26, 1p
- 8010030484 Recommends reopening of GERMO proceedings. GHAMPAGNE, A. J. Affiliation Unknown. 80/07/26 1p.
- 80:00:0697 Order denying Allied General Nuclear Svcs 800926 request for 60-day extension to respond to Commission 800807 order. Untimely comments will be considered only to extent possible.
 CHILK, B. J. Office of the Secretary of the Commission. 80/09/29
- 8010020001 Forwards comments on reopening of QEBNO proceedings re Rulemaking 50-5, reinstitution of hearing reflects US interest in energy need & will establish framework for timely decisions on reprocessing & recycling. WALBKE, C Atomic Industrial Forum. 80/09/29. 3pp
- 8010020451 Comments on rulemaking 80-5 on behalf of 968M0 Util Group. OESMO proceeding should be reactivated IRWIN.D P Hunton & Williams 80/09/29. App
- 8010020663 Comments on rulemaking 50-5:0EBMO proceeding should be rescheduled.

 BURT-D M. Capital Legal Foundation. FIELD:M P. Affiliation Unknown. TODORDVICH.M.N. Scientists & Engineers for Secure Energy 80/09/29 2pp.
- 80:0020570 Forwards comments on behalf of NRDC on rulemaking 50~5:9E8MO proceedings should not be reopened MEIBB, E.R. Natural Resources Defense Council, HEIBB, E.R. Sheldon, Harmon & Meiss. 80/09/29 5pe
- B010030479 Views of Westinghouse on NRC 800807 order re resumption of QEBMO 4 other recycle-related licensing proceedings. Resumption recommended Certificate of Bvc encl. CDNANs B Z Westinghouse Electric Carp. 80/09/27. 13pp.
- B010020679 Recommends that NRG reopen CESMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced.

 OLBON.R.E. Affiliation Unknown. B0/09/30. 1p.
- 8010030471 Responds to Commission 800807 order requesting comments on reopening of GESMO & other recycle-related licensing proceedings proceedings whould be reactivated & consistent position on use of energy initiated KEARNEY, J. J. Edison Electric Institute, 80/09/30. Spp.
- B010160695 Supports resumption of GESMO proceeding as prelude to closure of nuclear fuel cycle. MODDY, J H Yankee Atomic Electric Co. 80/10/QB. 2pp.
- 80:0270306 Responds to 800924 ltr transmitting J Courtney request for NRC resumption of OESMO proceedings. J Courtney comments will be incorporated into public record to be considered by NRC. KAMMERER, C. Office of Congressional Affairs. 80/10/08. ip.
- 8010130364 Submits comments on resumption of OESMO rulemaking on behalf of AZ Public Syc CosCP&L. Con Ed & WI Electric Power Co.
 Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues.
 GALLO, J. Isham, Lincoln & Beale. 80/10/10. 3pp.
- 8010200395 Advises of address change from Columbia, BC to Washington, DC & requests records be changed.
 BELBER, T. M. Belser, Belser, & Haker. 80/10/13. 1p.
- 8010220494 Forwards JC Courtney 800916 ltr requesting that 988MQ hearings be resumed.
 LONO: R Senets, 80/10/13. 2pp.

- P Operating license stage documents & correspondence
- 8010070264 Comments on rulemaking 50-5 re reopening of GESMO & recycle related proceedings Reopening record will resolve economic, environ & resource questions re fuel reprocessing DISE,D P Niegera Mohawk Fower Corp 80/09/26 ip
- G. Inspection reports, IE Bulletins & correspondence
- 8010200652 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Bhipments of Radioactive Matis"

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/29 1p.
- 8010160146 Forwards Suppl 2 to IE Sulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/09/30 ip.
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 8010050951 Forwards comments re quard training & qualification plan Comments withheld (ref 100FR2 770) IPPOLITO,T.A Operating Reactors Branch 2 80/09/19 2pp
- 8010220528 Submits security plan info re termination of contract security force & implementation of Event 5. Info withheld (ref 100FR2 790).

 BAYNE, J. P Power Authority of the State of New York. 80/10/14
- B010220413 Provides updated status on implementation of mods & procedural changes required by BER supporting Amend 47 to license & requests extension for completion of specified mods
 WILVERDING, G. M. Power Authority of the State of New York, B0/10/17 900.
- 8010310386 Informs that certain math & installation delays occurred which have modified completion dates provided in OH Wilverding 801017 ltr re fire protection sys mod & extension of implementation deadlins.

 BAYNE, J. P. Power Authority of the State of New York 80/10/28
- O. Adjudicatory correspondence
- 8010030066 Forwards 800919 order revising 800829 order for mod of DL, in antirety.
 EISENAUT, D @ Division of Licensing. 80/09/19. 2pp.
- --8010030071 Order revising 800829 order for mod of GL DPR-59 published in 800912FR.in entirety. Response to IE Bulletin 79-018 must be submitted by 801101 Request for hearing will not stay effectiveness of onder UCS petitions for relief discharged. EISENHUT.D.O. Division of Licensing 80/09/19. Opp
- 8010160415 Forwards order confirming util commitments to implement action re LE Bulletin 80-17. "Failure of 76 of 185 Control Rode to Fully Insert During Screm at BMR" STELLOV. Office of Inspection & Enforcement, Office of the Director. 80/10/02. 2pp.
- --8010160421 Order confirming util commitments to implement action re-IE Bulletin 80-17. "Failure of 76 of 183 Control Rade to Fully Intert During Scram at BWR." BTELLO.V Office of Inspection & Enforcement, Office of the Director. 80/10/02. 7pp
- H General correspondence
- 8010280398 Requests corporate contact in NUREG-0020, "Operating Units Status Rept" (Grey Book) be changed from FW Lyon to JP Rayne.

 HILVERDING.O.M. Power Authority of the State of New York 80/10/23 ip.
- J. Insurance & indomnity information
- 8010280655 Requests Endorsements 32 & 33 to Policy HF-77 & Endorsements 38.39 to Policy NF-208.
 DINITI. I. Utility Finance Branch (formerly Antitrust & Indemnity), 80/09/24.

- P Operating license stage documents & correspondence
- 8010220099 Forwards errata sheets emending 800905 ltr which provided preliminary clarification of TMI action plan requirements.

 Corrected table of implementation schedule also encl
 EISENHUT.D O Division of Licensing 80/09/19 28pp.
- GO10080455 Requests add1 action re NRC 780807 Itr re deficiencies in Hatch-Unit 2 regulator sys design Mods should be performed to provide fully redundant Class IE protection at interface of Nonclass IE power supplies 8 reactor protection sys IPPOLITO.T A Operating Reactors Branch 2 80/09/24 3pp
- B010070524 Forwards pre-implementation review of TMI-2 action plan for Item 11 E 4 1 re dedicated penetrations PASTERNAK, R J Power Authority of the State of New York, 80/09/30
- 8010300186 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Bignals." Interim rept UDY.A.C E000 Idaho. Inc. FIN A-6256 8010300186, 80/07/30 Spp.
- 8010150286 Responds to NRC 800827 ltr re inservice insp & inservice test programs. Three items addressed per 801002 teicon. BAYNE, J P. Power Authority of the State of New York. 80/10/09
- BO10160489 Forwards application for amend of License DPR-59, per Lessons Learned Task Force Category A items & for amend of App A Tach Specs.Incorporating sys integrity measurements program & improved iodine measurements capability BAYNE, J.P. Pawar Authority of the State of New York. 80/10/10
- --B010160494 Application for amend of License DPR-59 per Lessons Learned Task Force Category A items & for amend of App A Tech Specs, incorporating sys integrity measurements program & improved inding measurements capability

 BAYNE, J P Power Authority of the State of New York, 80/10/10, 4pg
- --8010160500 Proposed changes to App A Tech Specs, Sections 3.2.4 2.6 2.6 3 % & 5, incorporating requirements for safety/relief valve position indication sys & adding shift technical advisor. Safety evaluation and the Pawer Authority of the State of New York 80/10/10. 12pp
- B010200441 Summarizes status of TMI-2 action plan Itams II E.4 1, II K.3,13a & II K 3 30a, in response to NRC B00705 ltr BAYNE, J P Power Authority of the State of New York B0/10/14 2pp
- BOLO 220413 Provides updated status on implementation of mode & procedural changes required by SER supporting Amend 47 to license & requests extension for completion of specified mode
 HILVERDING, 0 M Power Authority of the State of New York BO/10/17.
- 9010290350 Bubmits info re BWR scram sys, in response to NRC 901001 ltr.
 Ufil will submit re-evaluation of scram sys & schedule for implementation of mods by 801215 BAYNE, J P Power Authority of the State of New York 80/10/24
- 8010010386 Informs that certain math & installation delays occurred which have modified completion dates provided in QM Wilverding 801017 ltr re fire protection sys mod & extension of implementation deadline BAYNE, J. P. Power Authority of the State of New York 80/10/28
- G Inspection reports: IE Bulletins & correspondence
- 8010010396 Forwards IE Insp Rept 50-333/80-11 on 800623-27.No noncompliance noted CARLBON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/04. 2pp
- --8010010403 IE Insp Rept 80-333/80-11 on 800623-27 No noncompliance noted. Major areas inspected inservice inspectivities, walk through insp of torus & inspection of licensee response to IE Bulletin 80-13.

 MCBREARTY.R A Region 1, Philadelphia, Office of the Director. TRIPL.E. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/SD. App.

- BOIOOIOBIS Responds to IE Bulletin BO-17 re failure of control rods to insert during scram at BHR Discusses surveillance testing or tarety relief valve position Eurveillance will be conducted faily.

 PASTERNAX, R. J. Power Authority of the State of New York BO/OB/15-linp
- 8010220076 Forwards IE Insp Rept 50-333/80-06 on 800414-18 & 23-28 & notice of violation Notice of violation withheld (ref 10CFR2 790)

 ORIER B H Region i, Philadelphia, Office of the Director, 90000212 (2012)
- ~-8010220084 IE Insp Rept 50-333/80~06 on 800414-18 & 23-25 Noncompliance noted in areas of security plans, security organization, physical barriers, access control alarm stations accommunications. Details withheld (ref 10CFR2.790) DEVLIN, J H, BAILEY, R J, SMITH, O, Region 1, Philadelphia, Office of the Director 80/06/25 3pp
- 8010010644 Responds to IE Bulletin 80-17 refailure of control rods to insert during scram at BWR Actions required by bulletin have been completed Administrative controls implemented PASTERNAK, R. J. Power Authority of the State of New York 80/08/27 2pp.
- 8010010679 Responds to IE Bulletin 80-13 re cracking in core spray spangers. Video insp found no cracks in core spray sys PASTERNAK.R J Power Authority of the State of New York B0/08/27, 208
- 8010020308 Responds to IE Bulletin 80-14 re degradation of BWR scram discharge vol Records review did not reveal any instance of water hammer in scram discharge vol.
 PABTERNAK, R J Fower Authority of the State of New York. 80/08/27.
- 8010010740 Responds to IE Bullatin BO-15 re loss of emergency notification sys w/loss of offsite power. Emergency notification sys would be unaffected by loss of offsite power.
 PASTERNAN-R J Power Authority of the Btate of New York BO/09/05.
- 8010220273 Forwards nonproprietary response to NRC 800818 ltr reviolations noted in IE Insp Rept 50-333/80-05. Corrective actions include hiring security consultant Proprietary response withheld (ref 100FR2, 790).

 BERRY. 0 T. Power Authority of the State of New York. 80/09/12 30s
- 8010220027 Responds to Item B i of Bulletin 80-17. Buppl i, "Failure of 74 of 185 Control Rods to Fully Insert During Scram at BWR" Facility will complete inetallation of continuous monitoring sys before 801201 PABTERNAK.R J Power Authority of the State of New York, 80/09/16. Zpp.
- 8010220662 Ack receipt of 800904 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-333/80-09 BMITH, O. H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/097/22. ip.
- --8010220668 Responds to NRC 800814 ltr re violations noted in IE Insp Rept 50-333/80-09 Corrective actions: refuel floor & reactor bldg normal ventilation sys isolated to prevent release of I-131 through pathways PASTERNAK.R.J. Power Authority of the State of New York 80/09/04. 3pp
- --B010220571 Forwards IE Insp Rept 80-333/80-09 on 800514-16 & notice of violation SHITH-9.H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch, 80/08/14. 2pp
- --8010220673 Notice of violation from insp on 800514-16.

 * Region i, Philadelphia, Office of the Director. 80/08/12. ip
- --8010220476 IE Insp Rept 50-333/80-07 on 800514-16 Noncompliance noted: failure to adhere to Tech Specs re release rates.

 KNAPP.P.J. Region I, Philadelphia, Fuel Facility & Materials Safety Branch SERABIAN, J. A. BAER, R E. Region I, Philadelphia, Office of the Director 80/09/12. 4pp.
- 8010160415 Forwards order confirming util commitments to implement action re IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Screw at SHR."

 STELLO, V. Office of Inspection & Enforcement, Office of the Director. 80/10/02. 2pp.

- --B010160421 Order confirming util commitments to implement action re IE Bulletin 80-17. "Farlure of 76 of 185 Control Rods to Fully Insert During Scram at EMR" STELLO, V Office of Inspection & Enforcement, Office of the Director S0/10/02 7pp
- 8010240168 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/10/02 p
- 8010310017 Summarizes & updates status of programs re IE Bulletins 79-02,79-07 & 79-14 W/erception of two baseplate mods resulting from IE Bulletin 79-02 fileribility analysis, initial work for bulletins is complete PABTERNAK, R J Power Authority of the State of New York 80/10/07 Sam
- 8010150286 Responds to NRC 800827 ltr re inservice insp & inservice test programs Three items addressed.per 801002 telcon BAYNE.J P Power Authority of the State of New York 80/10/09 2nn
- 8010280214 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested ORIER-B H Region i, Philadelphia, Office of the Director 80/10/10 ip
- R Periodic operating reports & related correspondence
- 8010100270 Forwards monthly operating rept for Sept 1980
 PABTERNAK, R. J. Power Authority of the State of New York 80/10/03.
- --B010100271 Monthly operating rept for Sept 1980 ZUFELT.E L Power Authority of the State of New York 80/10/03 1399
 - Reportable occurrences, LERs & related correspondence
- iOi60680 PNO-II-80-131 State of SC suspended burial permit for licensee & is considering imposing \$1,000 civil penalty action is based upon improper shipment of radwaste "QTTER.J., STORR.J.P. Region 2, Atlanta, Défice of the Director 30/07/27
- 010060333 Forwards LER 80-074/03L-0
 PASTERNAK,R J Power Authority of the State of New York 80/10/01.
 1pp
- --8010060347 LER 80-074/03L-0 on 800903 during normal operations while conducting surveillance testing high drywell pressure switch O3-P5-12B was discovered set at 2 817 psig Caused by instrument drift Pressure switch recaller CHILDS, W V Power Authority of the State of New York 80/10/01
 -)2005B7 Forwards LER 80-075/03L-0 (STERNAX: R J Power Authority of the State of New York B0/10/10
 - 010200594 LER 80-075/03L-0 on 800913 during narmal operation, LPCI 8 inverter tripped Caused by failure of logic card A2 Logic card A2 replaced & testing restored inverter to operable status four days later

 * Power Authority of the State of New York 80/10/10. 1p.

 - 0210670 Forwards LER 80-076/04T-0 ASIERNAK.R J Power Authority of the State of New York 80/10/15
 - 3010210677 LER 80-076/04T-O on 801002 environ radiological monitoring revealed activity in periphyton organisms near site to be greater than twn times control sample for Co-60. Evaluation does not indicate significant anyion impact CHILDS: N V Power Authority of the State of New York 80/10/15
- 10280419 Forwards LER 80-036/01X-1
 PASTERNAK, R J Power Authority of the State of New York. 80/10/22, 1p
- 8010280429 LER 80-036/01X-I on 800417.during normal operation, everage power range monitor F found operating w/one level C low power range monitor input Caused by failure to declare monitor F inoperable after low power monitor F inoperable after low power monitor 800409 calibr * Power Authority of the State of New York 80/E0/22, 2pp

- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010070116 Notification of 800929 meeting w/util re implementation of criteria in NUREO-0696 ROSS, M. J. Operating Reactors Branch 1 80/09/29 2pp
- F Security, medical, emergency & fire protection plans
- 8010010545 Forwards revised training & qualification plan Plan withheld (ref LOUFR2 790)

 DUNN.C N Duquesne Light Co 80/09/26 1p
- 8010230269 Forwards mads required to resolve open items indicated in 790804 safety evaluation re fire protection WAROA.S A Operating Reactors Branch (80/10/01 3pp
- 8010100351 Forwards design description of emergency response facilities, including discussion of aneas differing from proposed NUREO-0694 Review & approval requested DURM: C (I Duquesne Light Co B0/10/02 14pp
- 8010170637 Responds to 800826 Itr re-workeble evacuation program for Hopewell Township, PA Future inquiries should be sent to FEMA or local nuclear plant licensee ORIMES, B K Emergency Proparedness Program Office 80/10/09
- P Operating license stage documents & correspondence
- 80:00:00:00 Ack response to NRC 79:109 itr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VAROA.B A Operating Reacture Branch 1 80:007/12 2pp
- B010140020 Forwards Amend 31 to License DPR-66 3 notice of issuence & availability VARGA-5 A Dperating Reactors Branch 1 80/07/12 3pp
- --B010140022 Amend 34 to License DPR-66 adding requirement to maintain safeguards contingency plan to be fully implemented within 30 days of Commission approval VARGA: A Operating Reactors Branch 1 80/09/12 4pp
- --8010140026 Notice of issuance & availability of Amend 31 to License DPR-66 VAROA, B A Operating Reactors Branch (BO/09/12 4pp.
- B010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TNI action plan requirements. Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing 80/09/19 28pp.
- 8010210125 Forwards Amend 32 to License DPR-66, safety evaluation & notice of issuance & evailability
 VAROA.8 A Operating Reactors Branch 1 80/09/27 3pp
- --B010210132 Amend 32 to License DPR-66, adding App A Tech Specs describing requirements for chlorine detection sys for plant control room VAROA.5 A Operating Reactors Branch 1 80/09/29 3pp
- ~~8010210141 Notice of issuance & availability of Amend 32 to License DPR-66 VARDALB.A Deparating Reactors Branch 1 80/09/27 2pp
- BO(10030393 Application for Amend 55 to DL revising response time for isolation of Control room ventilation sys & correcting typographical error DOWN.C N Duquesne Light Co 80/09/30 3pp
- --8010030395 Tech Spec changes to App A.Table 3 3-5.Pages 3/4 3-27 & 3/4 6-196 re initiating signal & function response time * Dequesne Light 00 80/09/30 2pp
- 8010050223 Forwards addl info on auxiliary feedwater sys, in response to NRC 800122 request DUNN, C N Duquesne Light Co 80/09/30 3pp.
- 8010310129 Forwards Amené 33 to License DPR-66, safety evaluation & notice of issuance & availability
 VARQA,S A Operating Reactors Branch 1 80/10/15 2pp.

- --B010310135 Amend 33 to License DPR-66, revising radiological Tech Specs re-response time required for isolation or control room ventilation sys & for isolation of certain containment penetrations VARCA, 8 A. Operating Reactors Branch 1 80/10/15 5pp
- ---8010310138 Safety evaluation supporting Amend 33 to License DPR-66
 * Office of Nuclear Reactor Regulation, Director 80/10/15 4p
- --8010310140 Notice of issuance & availability of Amend 22 to License DPR-66 VAROA.S A Operating Reactors Branch 1 80/10/15 2pp
- B010240432 Application for Amend 56 to Cicenso DPR-66, deleting hydraulic snubbers, either removed or thanged to mechanical snubbers, from App A Tech Spec Table 3 7-4 Fee encl DUNN.C (& Duquesne Light Co 80/10/17 3pp
- --8010240437 Proposed revised App A Tech Spec Yable 3 7-4, reflecting hydraulic snubbers removed or changed to mochanical snubbers
 - # Duquesne Light Co 80/10/17 3pp
- O Inspection reports. IE Bulletins & correspondence
- 8010060076 Requests add1 info re unresolved item contained in IE Insp Rept 50-334/78-29 re inservice insp of steam generator & pressurtier welds CARLED'N R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 90/06/02 2pp
- 8010080136 Forwards Mgt Meeting Rept 50-334/80-21 on 800718 BRUNNER: E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- --B010080163 Mgt Meeting Rept 50-334/80-21 on 800718 Buby discussed concerns re licensee implementation of administrative controls & action taken in response to incidents involving sutage recovery activities
 BECKMAN, D.A. Region 1, Philadelphia, Office of the Director MCCABE, F.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/08 5pp
- 8010010823 Responds to IE Bulletin 79-03A re longitudinal weld defects in 6A-312 Type 304 pipe Some pipe mat! has been used, however no application was found to exceed 65% of allowable stress
 DUNN, C N Duquesne Light Co 80/09/05 1p
- 8010010202 Ack receipt of 800902 ltr informing NRC of steps taken to correct iolations noted in 1E Insp Rept 50-334/80-15 SMITH.O H Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 80/09/10 1p
- --8010010210 Responds to NRC 800901 ltr reviolations noted in IE Insp Rept 50-334/80-15 Corrective actions loop calibr procedures to be revised to incorporate recentification requirements for resistance temp detectors DMM: C N Duquesne Light Co 80/09/02 3pp
- --8010010216 Forwards IE Insp Rept 50-334/80-15 on 800602-06 & notice of violation SMITM.0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/08/01 2pp
- --8010010220 Notice of violation from insp on 800602-06
 * Region 1: Philadelphia, Office of the Director 80/07/28 ip
- --8010010224 IE Insp Rept 50-334/80-15 on 800602-06 Noncompliance noted written procedures not prepared or implemented for calibr of discharge temp monitoring sys resistance temp detectors BORES,R J Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch JACKSON,T J Region 1, Philadelphia, Office of the Director 80/07/28 10pp
- B010010309 Ack receipt of 800903 ltr informing NRC of steps taken to correct violations noted in IE Tosp Rept 50-334/80-22 SMITH.0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/09/10 ip
- --8010010318 Forwards IE Insp Rept 50-334/80-22 on 800728-0801 & natice of violation SMITH.9 H Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/18 2pp
- --9010010322 Notice of violation from insp on 800728-0801.
 * Region i, Philadelphia, Office of the Director 80/08/15. ip

- --8010010329 IE Insp Rept 50-334/80-22 on 800728-0801 Noncompliance noted fallure to complete Form NRC-4 prior to exceeding 1 25 rem per quarter SERABIAN.J A Region 1. Philadelphia, Office of the Director KNAFP.P J Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/08/15 App
- B0100301iB Ac) receipt of B00B21 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/80-18 MARTIN,N Q Region 1, Philadelphia, Bafeguards Brench 80/09/10 lp
- --8010030121 Responds to NRC 800731 ltr re violations noted in IE Insp Rept 50-334/80-18 Corrective actions withheld (ref 10CFR2 790) DUNN,C 44 Doquesne Light Co 80/08/21 2pp
- --8010030124 Forwards IE. Insp. Rept 50-334/80-18 on 800731 & notice of violation Notice withheld (ref 10CFR2 790)
 GRIER, B. H. Region 1. Philadelphia, Office of the Director 80/07/31 2pp
- --8010030126 IE Insp Rept 50-334/80-18 on 800666-20 Noncompliance noted failure to notify commission prior to initiating changes that decrease effectiveness of security plan Detail withheld (ref 10CFR2 790)
 DEVL(N.J W Region I, Philadelphia, Safeguards Branch SMITH, O Region I, Philadelphia, Office of the Director 80/07/24 2pp
- 8010010777 Responds to IE Bulletin 80-15 re loss of emergency notification sys w/loss of offsite power Power is from Bell Telaphone Co central ofcs w/24 to 48-h battery as backup power DUNN, C N Duquesne Light Co 80/07/11 3pp
- E010010795 Ack receipt of 200306 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/80-09
 BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 20/09/11 ip
- --B010010B01 Responds to NRC B0070B itr re violations noted in IE Insp Rept 50-334/BD-09 Corrective actions interface between util depts clarified & dial indicators will not be used as quantitative measurements subj to procedural acceptance. DUNN.C II Duquesne Light Co 80/08/06 10pp
- --8010010805 Forwards IF Insp Rept 50-334/80-09 on 800308-0419 & notice of violation
 BRUNKER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/08 2pp
- -8010010809 Notice of violation from insp on 800308-0419

 * Region 1. Philadelphia, Office of the Director 80/06/30 4pp
- --BOIQOIOBIG IE Insp Rept 50-334/80-09 on 800308-0419 Noncompliance noted failure to callbr & control dial indicators, to implement & mainbain radiation monitor surveillance test & to implement document control measures MCCADE.E C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch HEGMER.T D . BECKMAN.D A Region 1. Philadelphia, Office of the Director BO/06/30 41pp
- 8010010829 Responds to IE Bulletin 79-14, "Beismic Analysis of As-Quilt. Safety Related Piping " Required mods will be accomplished prior to startug after next refueling outage DUNN.C N Duquesme Light Co 80/09/11 2pp
- 8010100077 Act receipt of 800819 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/78-02 CARLSON R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/18 ip
- 8010270440 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Comiant During Steam Generator Decontamination" No specific action or response requested ORIER, B H. Region 1. Philadelphia, Office of the Director 80/09/26 19
- 8010230396 Forwards response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Master list 5 proprietary qualifications work sheets encl Info withheld tref 100FR2 790 W/o nonproprietary encl DUNN.C N Duquesne Light Co 80/09/30 3pp
- 8010240135 Forwards IC Circular 80-22, "Confirmation of Employee Qualifications " No written response required GRIER.8 H Region I. Philadolphia, Office of the Director 80/10/02 ip

- 8010280239 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/10 ip
- 8010240498 Identifies status of activities re IE Builetin 79-14 All physical insp of piping & QC records completed All piping reanalyzed Mods to supports to be completed before startup Requests attension until 810331 for full completion DUNN.C N Duquesne Light Co 80/10/20 4pp
- R Periodic operating reports & related correspondence
- 8010020359 Forwards Aug 1980 NPDES monthly repts to PA Dept of Environ Resources. MODRE G W Duqueene Light Ca 80/09/29 14pp
- 8010020491 Forwards "Semiannual Efficient & Waste Disposal Rest, Jan-June 1980 " DUNN,C N Duquesne Light Co 80/09/29 ip
- --8010020492 "Semiannual Effluent & Waste Disposal Rept, Jan-June 1980 "

 → Duquesne Light Co 80/09/29 57pp
- 8 Reportable occurrences, LERs & related correspondence
- B010090548 PNS-I-79-001A on 791008.licensee & IBEH union committee reached tentative agreement on new contract Licensee believes new contract will be ratified thereby avoiding strike.

 BEVLIN.J W , ALLAN.J Region 1, Philadelphia, Office of the Director 79/10/09 ip
- 8010010534 RO 80-069/01P-0 on 800920, motor driven fire pump began smoking & leaking oil after surveillance test Investigation showed cooling water lost from upper bearing cooler Cause undetermined Temporary back-up pumps available WERLING. J A Duquesne Light Co 80/09/22 3pp
- 6010020466 Forward: LER 80-061/03L-0 WERLING, J.A. Duquesna Light Cq 80/09/26 2pp
- --8010020472 LER 60-061/O3L-0 on 800829.manual suction valve from boric acid tank A left shut.rendering flow path inoperable Caused by operator error due to procedural deficiency Operating order implemented to correct procedure error LACEY.H S Duquesne Light Co 80/09/26 Zpp
- B010070404 RD on B00725, dissel-driven fire pump auto started Caused by hole in section of pipe from back hoe operator digging up portion of fire main yard loop Leaf isolated & backup water made available Fipe section repaired WERLING, J. A. Duquesne Light Co. B0/07/26, 2pp
- 8010050222 RO 80-071/01P on 800926, during surveillance test to verify equipment operating times, control room isolation times determined not in accordance w/Tech Specs Caused by Tech Spec arror in specified response time WERLING, J. A. Duquesne Light Co. 80/09/29 2pp
- 8010070552 RO 80-071/01P-0 on 800925, furing surveillance test to verify equipment operating times, control room isolation times determined contrary to Tech Spec Caused by Tech Spec error in required time determination

 WERLING, J. A. Duquesne Light Co. 80/09/27 2pp
- 8010070069 Forwards LER 80-024/03L-0 WERLING, J. A. Duquesne Light Co. 80/09/30 2pp
- --8010070373 LER 80-024/03L-0 on 780428, audit revealed that weekly surveillance tests on boric acid pumps missed during wk of 780810 Caused by operator error due to confusion between modes Test scheduling mods have been made LACEY, W. S Duquesne Light Co 80/09/30 1p
- 8010070456 Forwards updated LER 80-017/01T-1 WERLING, J.A. Duquesne Light Co. 80/09/30 2pp
- --BD10070464 Updated LER BO-017/01T-1 on BD0326; reanalysis of piping & supports for main steam sys outside containment revealed design deficiencies if all five safety relief valves opened on any manifold Caused by load resulting from open valves. LACEY.N S Duquesne Light Co 80/09/30 2pp
- 8010070519 Forwards updated LER 80-044/01T-1, MERLING, J A Duquene Light Co. 80/09/30 2pp

- --8010070526 Updated LER 80-044/01T-1 on 800630, during recent review of original calculations for steam generators, lower snubber embedments conditions found inconsistent w/design specs Caused by loading deficiencies

 LACEY, N S Duquesne Light Co 80/09/30 2pp
- B010070521 Forwards LER 80-070/01T-0 WERLING, J.A. Duquesna Light Co. B0/09/30 2pp
- --Bolto70531 LER 80-070/01T-0 on 800922, unplanned dilution of RCS occurred Caused by boric acid blender procedure not accounting for manual emergency boration flow path being in svc Procedure has been changed LACEY.N 8 Duquesne Light Co 80/09/30 2pp
- 8010070850 Forwards updated LER 80-037/017-1 WERLING, J A Duquesne Light Co 80/09/30 2pp
- --B010070559 Updated LER B0-037/01T-1 on B00620, during investigation of Graver radiographs on containment liner seam welds, anomalies found including missing, duplicated & misinterpreted radiographs Cause not stated LACEY, NS Duquesne Light Co 80/09/30 1p
- 8010100307 Forwards LER 80-069/01T-0 WERLING, J.A. Duquesne Light Co. 80/10/03 2pp
- ---B010100310 LER 80-049/01T-0 on 800720.during surveillance test,motor-driven fire pump malfunctioned Caused by cooling loss to motor bearing, due to clogged water supply valve Isolation valve cleared 5 supply line checked LACEY.N S Duquesne Light Co 80/10/03 2pp
- B010140432 Discusses LER 80-073/01P on B01003 Potential exists for blowing more than one steam generator in event of single line break in RHR valve or in steam supply to turbine-driven auxiliary feedwater pump Engineering study is in progress MERLING, J A Duquesne Light Co 80/10/03 2pp
- B010240447 Forwards updated LER 80-036/03L-1 & LER 80-068/03L-0 WERLING, J A Duquesne Light Co 80/10/17 2pp
- --8010240454 Updated LER 80-036/03L-1 on 800514, boric acid buildup discovered around cracked soc-o-let weld on RHR pump vent valve Caused by pipe nipple length, vibration & valve weight Fitting rewelded LACEY, W.S. Duquesne Light Co. 80/10/17 ip
- --8010240461 LER 80-068/03L-0 on 800917, during testing of 1C high head charging pump, bearing temps began increasing & pump was shut doun Caused by personnel not installing valves properly Valves repositioned LACEY.N S Duquesne Light Co 80/10/17 2pp
- 8010200576 Ferwards LER 80-071/01T-0 WERLING, J. A. Duquesne Light Co. 80/10/13 2pp
- --B010200583 LER B0-071/01T-0 on 800726, during surveillance testing, control room isolation times determined to exceed Tech Spec required response time Caused by amission of diesel load sequencing time from original Tech Specs LACEY,N 8 Duquesne Light Co 80/10/13 2pp
- BO10270041 PND-I-BO-150 on BO1013, two individuals received detectable localized skin & hair contamination while disassembling ion exchanger Caused by leak when one gallon of water sprayed from fittings being loosened BECKMAN.D. MCCABE.E Region i. Philadelphia, Office of the Director. BRUNNER.E J Region i. Philadelphia, Reactor Operations Nuclear Support Branch 60/10/14 2p
- 8010240433 Forwards updated LER 80-031/01T-1 WERLING, J.A. Duquesne Light Co. 80/10/17 2pp
- --8010240441 Updated LER 80-031/01T-1 on B00521.total loss of residual heat removal occurred whom valves autoclosed Caused by false high pressure signal. Vent valve wold leak repaired LACEY,N B Duquesne Light Co 80/10/17. 2pp.
- 8010240468 Forwards LER 80-073/01T-0 WERLING, J A Duquesne Light Co 80/10/17 2pp.
- ---B010240473 LER 80-073/01T-0 on B01017.Westinghouse notification received re blowdown of all three generators & loss of heat sink during single steam-line break No corrective actions necessary

 LACEY.W B. Duquesne Light Co 80/10/17 2pp

- 8010280450 Forwards LER 80-075/01T-0 WERLING, J A Duquesne Light Co 80/10/22 2pp
- --8010280517 LER 80-075/01T-0 on 801008, determined that overstress condition exists on reactor coolant fill header from high head charging pumps Cause unknown Necessary mods made prior to start up LACEY-M S Duquesne Light Co 80/10/21 2pp

V Operator Examinations

- 8010280438 Forwards revised operator training program WERLING, J A Duquesne Light Co 80/09/02 1p
- --8010280443 "Training Manual." Revision 2 - Duquesne Light Co 80/08/11 60pp

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

- BO10240519 Ack receipt of 800813 ltr informing NRC of steps taken to correct violations noted in Health Physics Appraisal Rept 50-335/80-06 BTOHR.J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/10/08
- --B010240527 Responds to NRC 800624 ltr re violations noted in Health Physics Appraisal Rept 50-335/80-06 Corrective actions: plant breathing air supply was tested to ensure that breathing air meets specs
 UHRIG.R E Florida Power & Light Co B0/08/13 7pp
- --BD10240533 Forwards IE Health Physics Appraisal Rept 50-335/80-06, notice of violation & significant appraisal findings D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 App
- --B010240537 Notice of violation from health physics appraisal on B00310-21 * Region 2, Atlanta, Office of the Director B0/06/23 2pp
- --8010240537 Health Physica Appraisal Rept 50-335/80-06 Noncompliance noted contaminated tool control, lack of retraining program & failure to follow procedures & take adequate air samples ZAVADOSKI,R W. HOBEY,C M., LACEY,L R. Ragion 2, Atlanta, Office of the Director 80/06/23 ip
- B01021034(Forwards security plan/Revision 3 Revision withheld (ref 10CFR2.790) UHRIO, R E Florida Power & Light Co. 80/10/13 ip

Q Adjudicatory correspondence

- B0:10080352 Forwards order revising 800829 order for mod of CL.in entirety E15ENHUT.D 9 Division of Licensing, 80/09/19 2pp
- --8010080359 Order revising 800829 order for mod of OL published in 800911 FR.in entirety Response to IE Bulletin 79-018 must be submitted by 801101 Request for hearing shall not stay effectiveness of order UCS petitions for relief discharged. EISENHUT.D Q Division of Licensing 80/09/19 App

H General correspondence

- 8010080332 Advises of organizational changes in Advanced Bys & Technology & QA Depts Revision of topical QA rept will be transmitted upon completion UKRIG.R.E. Florida Power & Light Co. 80/10/03 ip
- 8010290271 Responds to 800902 ltr forwarding constituent concerns re evacuation plans for Port St Lucie & Ft Pierce areas of FL FEMA has lead responsibility for emergency preparedness of state & local governments DIRCKS, J Office of the Executive Director for Operations. 80/10/21 2pp.
- --80(0290275 Forwards constituent live re evacuation & emergency plans STONE.R. Senate 80/09/02. 7pp

J Insurance & indemnity information

- 8010150354 Forwards Endorsement 21 to NELIA Policy NF-227
 FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc.
 Div 80/10/10 5pp
- P Operating license stage documents & correspondence
- 8010060267 "Review of Temp Sensor Response Time Measurement Using Loop Current Step Response Technique " ACKERHANN N J Technology for Energy Corp 78/08/16 24pp
- 8010010715 Discusses review of util response to NRC 791109 ltr re ECCB evaluation models, dealing w/fuel cladding swelling & incidence of rupture, Response is acceptable No further action is necessary CLARK, R A Operating Reactors Branch 3 80/09/10 2pp
- B010050137 Forwards Amend 35 to Litense DPR-57 & notice of issuance & availability
 CLARK R A Operating Reactors Branch 3 80/09/18 3pp
- --8010060141 Amend 36 to License DPR-67, adding license condition to include implementation of safeguards contingency plan within 30 days of Commission approval CLARK.R A Operating Reactors Branch 3 80/09/18 2pp
- --8010060143 Notice of issuance & availability of Amend 36 to License DPR-67 CLARK,R A Operating Reactors Branch 3 80/09/18 2pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D. O Division of Licensing. 80/09/19 28pp
- 8010210413 Requests emend to App A of License DFR-67 to correct error in Tech Spec Section 3/4.9 14 re fuel pool cask drop analysis Proposed Tech Spec change encl
 UHRIG.R E Florida Power & Light Co 80/10/16 3pp
- ~~8010210416 Proposed change to Tech Spec Section 3/4 9 14 & bases, correcting error in fuel pool cask drop analysis, Safety evaluation enci + Florida Power & Light Co 80/10/16 Spp
- 8010220501 Forwards stress analysis of drain & fill method for cooling reactor & responses to NRC 800708 ltr re potential effects of rapid RCS depressurization No excessive stress levels occurred during normal cooldown UHRIG.R E Florida Power & Light Co 80/10/17 App.
- 8010280334 Notifies that installation of data display computer & equipment for technical support ctr will be completed by B10401. Caused by procurement delays UHRIO,R E Florida Power & Light Co. 80/10/23 ip.
- Q Inspection reports, IE Bulletins & correspondence
- 8010020732 Forwards IE Insp Rept 50-335/80-22 on 800708-17.No noncompliance noted LENIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/20 2pp
- --8010020737 IE Insp Rept 50-335/80-22 on 800708-17. No noncompliance noted Major areas inspected: plant operations; bulletin, circular; & info notice review: licensee actions w/respect to NRC correspondence.

 MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/20 6pp.
- 8010090D24 Forwards IE Insp Rept 50-335/80-20 on 800721-23.No noncompliance noted MURPHY/C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/25 2pp.
- --8010090031 IE Insp Rept 50-335/80-20 on 800721-23 No noncompliance noted Major areas inspected procedures governing various aspects re IE Bulletins 79-14 & 74-02 HERDTAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch. COMPTON,R M., MODENDB, L. Region 2. Atlanta. Office of the Director 80/08/22 Spp
- B010080051 Forwards IE Insp Rept 50-335/80-27 on 800723-31.No noncompliance noted. LEMIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/08/29. 2pp

DOCKETED ITEMS

- --8010080057 IE Insp Rept 50-335/80-27 on 800723-31 No noncompliance noted Major areas inspected plant operations, tour followup of IE Bulletin 79-15 & followup of headquarters concerns MESGITT.B R . MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/29 3pp
- 8010230089 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/29 1p
- B01003006B Ack receipt of 800827 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-21 MMRPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/09/17 ip
- --8010030081 Forwards response to NRC 800804 ltr re violations noted in IE Insp Rept 50-335/80-21 Corrective actions procedures will be changed to require QC concurrence when performing hot work in areas effecting safety-related equipment UHRIG.R E Florida Power & Light Co 80/08/27 3pp
- --8010030086 Forwards IE Insp Rept 50-335/80-21 on 800708-ii,notice of violation & notice of daviation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/04 2pp
- --8010030088 Natice of violation from insp on 800708-11 * Region 2. Atlanta. Office of the Director 80/08/01 ip
- --B010030092 Notice of deviation from insp on 800708-11 * Region 2, Atlanta, Office of the Director. 80/08/01 1p
- --8010030074 IE Insp Rept 50-335/80-21 on 800708-11 Nancompliance noted imadequate review & approval of fire protection base sys surveillance insp procedures MILLER.W H Region 2. Atlanta, Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/01 6pp
- 901030016B forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted 9TDR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/09/19 2gp
- --8010300179 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801
 No noncompliance noted Major areas inspected shipping paper,
 DOT placarding radiation levels, removable contamination &
 DOT marking & labeling requirements for packages
 MACARTHUR.T C., POTTER.J P. Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch 80/09/16 8pp
- 8010270239 Responds to IE Builetin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary 91de High Energy Line Rupture "Facility does not have centrifugal charging pumps UHRIO,R E. Florida Power & Light Co 80/09/22 ip
- Office Of the Director Region 2, Atlanta, Office of the Director 80/09/26
- >10150037 Ack receipt of 800917 ltv informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-25. LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/30. ip
- 8010150042 Responds to NRC E00825 ltr re violations noted in IE Insp Rept 50-335/80-25 Corrective actions control room reviewed for add1 outdated procedures Personnel instructed on proper verification procedures UHR10,R E Florida Power & Light Co 80/09/17 2pp
- 8010150047 Forwards IE Insp Rept 50-335/80-25 on 800424-0702 & notice of violation LEWIS:R C. Region 2. Atlanta: Reactor Operations Nuclear Support Branch. 80/08/25 2pp
- 80:0150050 Notice of violation from insp on 800624-0702 * Region 2: Atlanta: Office of the Director. 80/08/19. ip
- 8010150053 IE Insp Rept 50-335/80-25 on 800624-0702 Noncompliance noted.use of outdated & supersaded procedure re reactor anginering power ascension program.

 QUICK.D R. Region 2. Atlanta: Reactor Operations Nuclear Support Branch. BURNETT.P T Region 2. Atlanta. Office of the Director 80/08/19 6pp

- 8010160220 Forwards Suppl 2 to IE Bulistin 79-01B, "Environ Qualification of Class IE Equipment" No written response required O'REILLY.J P Region 3, Chicago, Office of the Director 80/09/30 in
- 8010270232 Advises that list of sys requested in IE Bulletin 80-11, "Masonry Hall Design," will be available by 801020 UHRIG.R E Florida Power & Light Co 80/10/01 1p
- 8010270552 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 ip
- 8010270049 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested D'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 801015033B Forwards monthly operating repts for Sept 1980 SCHMIDT.A D Florida Power & Light Co 80/10/04 1p
- --8010150341 Monthly operating repts for Sept 1980 CHILBON, V. T Fiorida Power & Light Co 80/10/04 13pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010070466 Forwards LER 80-044/03L-0 SCHMIDT, A D Florida Power & Light Co 80/09/18 ip
- --8010070474 LER 80-044/03L-0 on 800824 during normal operation, digital data processing sys failed due to computer haiting during calculational program No cause determined PACE.P L Florida Power & Light Co 80/09/18 ip
- 8010070431 Forwards LER 80-042/03L-0 8CHMIDT, A D Florida Power & Light Co 80/09/19 ip
- --8010070437 LER 80-042/03L-0 on 800821, during full power operation, control element assembly 53 dropped partially into core to height of 53 inches Caused by 15-volt power supply unit failure Installation of redundant power supplies underway PACE, P L Florida Power & Light Co 80/09/19 ap
- 8010070443 Forwards LER 80-054/03L-0 8CHMIDT.A.D Florida Power & Light Co. 80/07/22 1p.
- --8010070493 LER 80-054/03L-0 on 800822 during normal operation, leak test surveillance on containment personnel airlock inner door gasket interspace was missed during entry to investigate de-snergization of power source. Caused by personnel error PACE, P. L. Florida Power & Light Co. 80/09/22 ip
- 8010070420 Forwards LER 80-048/03L-0 SCHMIDT.A D Florida Fower & Light Co. 80/09/24 1p
- --8010070477 LER 80-048/03L-0 on 800826, during full power operation, control element assembly 51 dropped to full insertion Caused by failed power supply unit Power supply replaced & assembly aligned w/assembly group height Returned to svc PACE.P L Florida Power & Light Co 80/09/24 ip
- 8010080209 Forwards LER 80-047/03L-0 8CHMIDT, A D Florida Power & Light Co 80/07/24 1p
- ~~8010080217 LER 80~047/03L-0 on 800828, during full power operation, after 18 charging pump maint, seal water leak developed. Pump 14 was started but seal water pump mechanically seized Caused by 14 overheating 14 & 18 repaired & returned to svc PACE.P L Florida Power & Light Co. 80/09/24 1p.
- 8010080570 Ferwards LER 80-045/03L-0 8CHMIDT.A D. Florida Power & Light Co 80/09/24 1p
- --8010080473 LER 80-045/03L-0 on 800826, during full power operation, control element assembly (CEA) 24 dropped to full insertion, Caused by 15-volt power supply unit failure Installation of redundant gover supplies in progress PACE.P L Florida Power & Light Co 80/09/24 1p
- 8010100319 Forwards LER 80-053/03L-0. 8CHMIDT. A D Fiorida Power & Light Co 80/09/25, 1p

- --8010100323 LER 80-053/03L-0 on 800826, during full power operation, power supply to core protection calculator 1 failed Caused by bent fuse cilp to negative supply which did not allow sufficient contact. Power supply repaired & returned to svc PACE, P. L. Florida Power & Light Co. 80/07/25 ip
- 8010100326 Forwards LER 80-046/03L-0 SCHMIDT.A D Florida Power & Light Co 80/09/25 1p
- --8010100331 LER 80-046/03L-0 on 800827, during full power operation, control element assembly 33 dropped to full insertion Caused by failure in 15-volt power supply in coil power programmer Power supply replaced PACE,P L Florida Power & Light Co 80/09/25 1p
- 8010100329 Forwards LER 80-052/03L-0 SCHMIDT,A D Florida Power & Light Co 80/09/26 ip
- --8010100334 LER 80-032/03L-0 on 800904, at 70% while increasing power, control element assembly 1 dropped Cause not found Mods in progress to decrease malfunction, redundant power supplies & improve area ventilation & power supply mounting PACE.? L Florida Power & Light Co 80/09/26 ip
- BO10100316 Forwards LER 80-049/03L-0 SCHMIDT, A D Florida Power & Light Co 80/09/30 ip
- --B010100322 LER 80-049/O3L-0 on 800904, during full power operation, control element assembly 21 dropped to full insertion.

 Caused by faulty 15-volt power supply Power supply replaced & redundant supplies are being installed PACE, P. L. Florida Power & Light Co. 80/09/30 2pp
- BO10100313 Forwards LER BO-055/0GL-0 SCHMIDT, A D Florida Power & Light Co BO/10/02 ip
- --8010100317 LER 80-055/03L-0 on 800703, during normal operation, diesal generator A failed to pick up load during test & later overheated. Caused by operator error & leaking relief valve Operator reinstructed in procedure & valve replaced PACE, P L Florida Power & Light Co 80/10/02 ip
- 80101003i1 Forwards LER 80-050/03L-0 SCHMIDT, A D Florida Power & Light Co 80/10/03 1p
- --B010100314 LER 80-050/03L-0 on B00704, while power supplies for control element assemblies 42 & 44 were in parallel, both dropped. Probably caused by voltage spike PACE.P L Florida Power & Light Co 80/10/03 2pp
- 8010100339 Forwards LER 80-091/03L-0 SCHMIDT, A D Florida Power & Light Co 80/10/03 1p
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 Q Adjudicatory correspondence
- 8010160634 Forwards revised 800829 order, correcting refs Date for which hearing may be requested also revised. EISENHUT. D O Division of Licensing 80/09/19 ipp
- --8010160637 Order directing licensee to respond fully & completely to IE Bulletin 79-018; re environ qualification of Class IE equipment by 801101 EISENHUT: D 0 Division of Licensing 80/09/19 6pp
- P Operating license stage documents & correspondence
- B010040107 Informs that review of responses 771107 ltr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture has been completed. Response acceptable CLARK.R A Operating Reactors Branch 3 80/09/10 3pp
- 8010090488 Forwards responses to 800623 itr concerning proposed design of post-accident sampling & analysis sys for facilities Requirement for obtaining pressurized samples can be deleted GRUTCHFIELD, D. Operating Reactors Branch 5, 80/09/17, App

- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGENHUT. D O Division of Licensing 80/09/19 28pp
- 8010020504 Forwards 800702 NPDES renewal permit & Sections 316(a) & 316(b) approvals, issued 800611, to indicate util compliance w/state & federal statutes & regulations under Clean Hater Act of 1977 administered by CT Dept of Environ Protection COUNSIL. H Q. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 80/09/22 31pp
- 8010010569 Submits add1 info re fuel misload analysis performed in support of Cycle 4 reload Procedures utilized during fuel movement provide adequate assurance that probability of fuel misloading event is sufficiently low to practude analysis COUNSIL, H 0 , FEE, H F Northeast Utilities 80/09/26, 2pp
- B010050323 Application to amend License DPR-65 authorizing performance of tests at reduced RCS inlet temps in order to quantify secondary plant performance losses.
 COUNBIL,N O. FEELM.F. Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/30 4pp
- --8010060330 Proposed revision to Tech Specs 3/4 2-3 for Amend 55 to License DPR-65 Authorizes performance of tests at raduced RGS inlet temps in order to quantify secondary plant performance losses Low temp testing safety review encl a Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/30. Spp
- 8010070183 Bubmits addl info to support Cycle 4 safety evaluation in response to NRC 800512 request Includes containment electrical penetration replacement status & results of Cycle 4 reload outage steam generator insps CQUNSIL, N O , FEE, W F, Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/30 34pp
- 8010100324 Bubmits comments on TMI action plan requirements NRC should accept alternative means of training for mitigating core damage util will submit valve test data by BiO701 & plant specific analyses following completion of program COUNSIL,# 0 , FEE.W F Connecticut Yankee Atomic Power Co COUNSIL,# 0 , Northeast Nuclear Energy Go. (subs of Northeast Utilities) 80/10/01 &pp.
- 8010200325 Provides responses to add1 NRC questions re design & installation of RCS vent sys Includes description of const. location, size & power supply for vents Bolenaid valves & piping sys are capable of operating w/water or mixed gases COUNSIL, & G Northeast Nuclear Energy Co. (subs of Northeast Utilities). B0/10/03 3pp
- 8010240094 Forwards Amend &1 to License DPR-65, safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 80/10/06 6pp
- --8010240098 Amend 61 to License DPR-65 authorizing Cycle 4 operation at 2.700 KMt w/mixed core w/one-third Westinghouse fuel & two-thirds CE fuel & modified guide tubes for control element assemblies.
 CLARK.R A Operating Reactors Branch 3 80/10/06 55pp
- --8010240100 Safety evaluation supporting Amend 61 to License DPR-65 # Office of Nuclear Reactor Regulation, Director 80/10/06, 50pp
- --8010240102 Notice of issuance & availability of Amend 41 to License DPR-65. CLARK,R A Operating Reactors Branch 3 80/10/06. 2pp.
- 8010300361 Application to amend License DPR-65, incorporating changes in proposed Teck Specs re redundancy in decay heat removal capability in operating modes COUNSIL, HO Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/10/17 App
- --8010300365 Proposed revisions to Tech Specs 3/4.4 for RCS
 * Northeast Nuclear Energy Co. (subs of Northeast Utilities).
 80/10/17. 9pp
- G Inspection reports, IE Bulletins & correspondence
- 8010020786 Responds to IE Bulletin BO-15. Emergency notification sys powered by onsite PBX sys Bulletin investigation required 32 manhours COUNSIL,W G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) FEE,W F. Northeast Utilities 80/08/25. 3pp.

- 8010030128 Forwards IE Mgt Meeting Repts 50-245/80-14 & 50-335/80-15 on 800805 Immediate Action Ltr 80-28 issued,based on results of discussion
 GRIER.B H Region 1, Philadelphia, Office of the Director
 80/09/26 2pp
- -8010030132 IE Mgt Maeting Repts 50-245/80-14 & 50-336/80-15 on 800805. Details uithheld (ref 10CFRZ 790) MARTIK: W O . DEVLIN. J W . SHEPPARD. R E Region 1. Philadelphia. Bafeguards Branch 80/08/28 ip
- 8010230153 Forwards IE Insp Rept 50-336/80-10 on 800729-30 No noncompliance noted CARLSON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/26 2pp.
- --8010230157 IE insp Rept 50-336/80-10 on 900728-30 No noncompliance noted Major areas inspected qualification data for RGS electrical equipment inside containment & safety injection & containment spray sys EBNETER, B.D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch FINKEL, A E Region i, Philadelphia, Office of the Director, 80/08/25 9pp.
- 8010020760 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/80-06 & 50-336/80-04 BRUNNER;E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/27 1p.
- --B010020763 Responds to NRC B00626 itr re-violations noted in IE Insp. Repts 50-245/80-06 & 50-335/80-04 Corrective actions.hanger number 413082 hydraulic snubber will be replaced. Item C details withheld (ref 10CFR2, 790). COUNSIL.W O Northeast Nuclear Energy Co (subs. of Northeast Utilities). B0/07/22. 4pp
- --8010020765 Forwards IE lnsp Repts 50-245/80-06 k 50-336/80-04 on 800330-0503 k notice of violation, App A & B. App B details withheld (ref 100FR2, 790).
 BRUNNER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 80/06/26 2pp.
- --B010020767 Notice of violation.App A & B. from insp on B00330-0503 App B details withheld (ref 10CFR2 770), * Region i. Philadelphia, Office of the Director, B0/06/03. 2pp
- --9010020771 IE Insp Repts 50-245/80-05 & 50-336/80-04 on 800330-0503 Noncompliance noted failure to wear desimetry in accordance w/health physics procedures, to meet snubber surveillance w/health physics procedures, to meet snubber surveillance requirements & to comply w/security procedures KEIMIG.R R. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. EHEDLOSKY.J.T., ZIMMERMAN.R.P. Region i. Philadelphia, Office of the Director. 80/06/03 13pp.
- 010020175 Advises that actions outlined in util 800811 ltr are in accordance w/Licensee Meeting IAL-80-28. Documentation recontrol, accounting & security procedures exempt from disclosure (ref 10CFR2 790).

 QRIER, B. H. Region 1, Philadelphia, Office of the Director 80/08/29.
- 8010220021 Responds to IE Bulletin BO-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches" Spacified switches are used in containment air circulation fans: sty water pumps & charging pumps COUNBIL. M. G. FEE. M.F. Connecticut Yankee Atomic Power Co. COUNBIL. M. On Theast Nuclear Energy Co (subs of Northeast Utilities). 80/09/15 2pp
- 8010100032 Ack receipt of 800818 ltr informing NRC of steps taken to correct violations noted in IE Imag Rapt 50-336/80-08.
 ALLAN, J A Region 1, Philadelphia, Office of the Director.
 80/09/17 ip
- --8010100038 Responds to NRC 800724 itr re violations noted in IE Insp Rept 50-336/80-08 Corrective actions: instrument has been entered into station QA instrument program & periodic checks for calibr will be made FEE.M F., COUNSIL.M.Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/08/18 3pp.
- --8010100040 Forwards IE Insp Rept 30-336/80-09 on 800623-27 & notice of violation. BRUNNER,E.J. Region 1: Philadelphia: Reactor Operations Nuclear Support Branch. 90/07/24. 2pp.
- --8010100042 Notice of violation from insp on 800623-27.
 * Region i, Philadelphia, Office of the Director. 80/07/R3. ip.

- --8010100044 IE Inep Rept 50-336/80-08 on 800623-27 Noncompliance noted surveillance & inservice insplactivities performed ω/ο consistent use of procedure.

 CHUNO, J W , MCCANN, J Region 1, Philadelphia, Office of the Director GREENMAN, E Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 80/07/23 13pp
- 8010240195 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-245/80-09 & 50-335/80-05 MARTIN U O Region 1, Philadelphia, Bafeguards Branch 80/09/19
- --8010240202 Responds to NRC 800801 itr re violations noted in IE Insp. Repts 50-245/80-09 & 50-335/80-06, Corrective actions withheld (ref 10CFR2 790).
 COUNSIL-H.G. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 80/08/22 2pp
- --8010240205 Forwards IE Insp. Repts 50-245/80-09 & 50-336/80-06 & on 800623-27 & 30 & 0701-03 & notice of violation. Notice of violation withheld (ref 100FR2 790).
 MARTIN, M. C. Region i, Philadelphia, Bafeguards Branch. 80/08/01
- --8010240217 IE Thep Repts 50-245/80-09 & 50-336/80-06 on 800623-27 & 30 & 0701-03 Noncompliance noted: two doors found unsecured & two licenses vehicles found unlocked. Details withheld (ref 100FR2 790). SHEPPARD, R. E., MCKEOWN, L. M. Region 1, Philadelphia, Office of the Director. DEVLIN.J W. Region 1, Philadelphia, Bafeguards Branch 80/09/24 2pp
- 8010270242 Responds to IE Bulletin 80-18. "Maint of Adequate Min Flow Thru Centrifugel Charging Pumps Following Secondary Side High Energy Line Aupture." Hin flow requirements are met for high pressure safety injection pumps COVMBIL. W. O. Connecticut Yankes Atomic Power Co. CDUNSIL. W. O. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 80/09/22. 2pp.
- 8010270445 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." No specific action or response requested.

 ORIERS H Region 1: Philadelphia. Office of the Director 80/09/26. ip.
- 8010240128 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/10/02 ip
- 8010290173 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Solting." No specific action or response requested GRIER.B.H. Region 1, Philadelphia, Office of the Director. 80/10/10. 1p.
- R. Periodic operating reports & related correspondence
- 8010060270 Responds to NRC 800909 ltr requesting verfication of info on radioactive effluents. Forwards revised semiannual effluent & waste disposal repts for 1978. COUNSIGN On theset Nuclear Energy Co. (subs. of Northeast Utilities). B0/09/26. 1p
- --8010060278 Revised "Semiannual Effluent & Waste Disposal Rept for 80/09/30
- B010210432 Forwards monthly operating rept for Bept 1980. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/10/14. 1p.
- --B010210435 Monthly operating rept for Sept 1980.
 HOWLETT.O.H Northwast Nuclear Energy Co (subs. of Northwast Utilities). B0/10/04. Spp.
- S. Reportable occurrences, LERs & related correspondence
- 8010080450 PNO-I~80-112:on 800729; heavy rain & plugged yard drain caused flooding of auxiliary bldg Approx 2-3 ft of water is on -45 fb elevation KEIMIOR, R. Ragion 1. Philadelphia, Office of the Director, 80/07/30, 2pp.

- 8010090373 RO on 800812, third quarter sample of dusters from within 500 ft of discharge exceeded control station average activities by greater than factor of 10 Caused by ouster trays located in quarry boundaries w/o near-field dilution.
 MROCINALE, J. Northeast Utilities 80/10/03 3pp
- 8010090449 RO ETB-NR/50-245/50-336/80-1 on 800812, excessive levels of Co-58, Co-60 & Ag-110m were observed in third quarter sample of oysters Caused by increased plant liquid discharges Tech Specs will be revised.

 MRDCZKA, E, J Northeast Utilities 80/10/03 3pp
- 80102303B5 Forwards LER 80-032/03L-0 MROCZKA,E.J Northeast Nuclear Energy Go (subs. of Northeast Utilities) 80/10/16 1p
- --8010230390 LER 80-032/03L-O on 800917.during type C leak rate test during refueling, combined leakage rate exceeded Tech Specs Valve would not respond to remote actuator Caused by broken shear pin in mechanism attaching air actuator to valve stem ROTHGEB.R.W Northeast Nuclear Energy Co (subs. of Northeast Utilities) 80/10/16. 2pp
- 8010280537 Forwards update LER 78-033/03L-1. MRGCIKA: E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/10/22 ip
- --Bolo280541 Update LER 78-033/03L-1:on 781205, while operating dissel 12U for surveillance, low cooling water alarm received & confirmed Caused by flow restriction due to mussel debris in heat exchanger Byc water to dissel modified.

 CLEMENT, C. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/10/22 2pp
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- BOIO230343 Ack receipt of util BOO403 & 0718 ltrs transmitting security plan changes Changes are consistent w/code requirements & contain info that should be withheld from public (ref 100FR2 790).

 CLARK.R. A Operating Reactors Branch 3 80/09/25. 2pp.
- 80:10170044 Orants 800922 request for 30-day extension to emergency plan submittal date YOUNOBLODD: B J Licensing Branch 1. 80/10/01. 2pp.
- BO10210015 Notification of B01027 meeting w/util in BethesdarMD to discuss emergency response facilities ENOLE.L. Operating Reactors Branch 3. 80/10/01, 3pp.
- 8010270372 Clarifies aspect of 800725 commitment re installation of smote detection sys All 12 zones of smoke detectors for Unit 2 will be installed/operational during 801101 outage. All remaining zones will be operational at end of Unit 1 outage 8YLVIA.B.R Virginia Electric & Power Co. 80/10/22. Ip.
- O Adjudicatory correspondence
- 8010230121 Forwards order revising 800829 order for mod of OL dus to incorrect refs. Hearing date accordingly changed. EISENHUT, D 9 Division of Licensing 80/09/19. 2pp.
- --G010230125 Order for mod of License NPF-4, adding provision that requires response to IE Bulletin 79-018 by 801101. Revises 800829 order published in 800911 FR. Request for hearing shall not stay effectiveness of mod. UCS petition discharged, E18ENHUT, D. Q. Division of Licensing. 80/09/19. App.
- H General correspondence
- 8010230652 Responde to 800626 ltr to FERC inquiring when plants will be operational Provides schedule for projected plant restart. Gertificate of Evc encl. DERION,H.R. Office of Nuclear Reactor Regulation, Director, 60/09/05. Spp.
- 8010230714 Responds to 800724 ltr requesting info re plant operating saperience. Discusses LERs & radiation levels around facility. LERs do not directly affect safety of public due to multiple levels of protection.

 DIRGKS.W. J. Office of the Executive Director for Operations. 80709730. Spp.
- ---8010230713 Forwards AB Hepler 800784 1tr requesting info on facility. Requests response. RDSINSON.J.K. House of Rep. 80/08/01. 4pp.

- --8010230717 Requests info re operation of facility.comparison to other nuclear power plants & radiation reading around farm, HEPLER.A S Affiliation Unknown 80/07/24 1p.
- J Insurance & indemnity information
- 8010080349 Forwards Endorsement I to MAELU Binder XB-70. LOVING.L J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/10/02. 7pp
- P Operating license stage documents & correspondence
- 8010010721 Discusses review of util response to NRC 791109 ltr re ECCB swaluation models, dealing w/fuel cladding swelling & incidence of rupture Response is acceptable. No further action is necessary, CLARK, R.A. Operating Reactors Branch 3. 80/09/10, 20p.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D. O. Division of Licensing. 80/09/19. 28pp
- 8010010678 Forwards "Evaluation & Critique of NUREO/CR-1580 "
 Document foes not raflect importance in quality or
 applicability to nuclear power station control rooms.
 SYLVIA: B R. Virginia Electric & Power Co 80/09/26. ip
- --B010010488 "Evaluation & Critique of NUREO/CR-1580."

 * Virginia Electric & Powar Co 80/09/30, 100pp.
- 8010100252 Requests Units 3 & 4 settlement time records from 1980 to FSAR submittal date, YOUNGBLOOD, B. J. Licensing Branch 1. 80/09/29 2pp.
- 8010150143 Summary of 800828 & 29 meeting w/BNL re progress on physics technical assistance progress. Topic outline encl DUNENFELD; H. Core Performance Branch. 80/09/29, 8pp
- 8010070378 Responds to NRC 800705 request for info re TMI action plan requirement preliminary clarification Westinghouse owners group meeting w/NRC will determine addl effort required & re-evaluation will be submitted. Deadline unrealistic.

 BYLVIA, B, R, Virginia Electric & Power Go. 80/10/02. 2pp.
- 8010240282 Forwards Amend 20 to License NPF-4 & notice of issuance & availability.

 CLARK, R. A. Licensing Branch 3. 80/10/03. 3pp.
- --8010240292 Amend 20 to License NFF-4, revising license condition to maintain Commission approved safeguards contingency plan. CLARK.R.A. Licensing Branch 3. 80/10/03. 2pp.
- --B010240302 Notice of issuance & evailability of Amend 20 to License NPF-4. CLARKIR, A Licensing Branch S. 80/10/03. 2pp.
- 8010080436 Forwards response to NRC 800928 ltr re auxiliary feedwater sys design basis info & pump flow verification. Testing for motor driven Auxiliary Feedwater Pump 1-FN-P-3B is scheduled during upcoming fueling outage
 BYLVIA Virginia Electric & Power Co. 80/10/06. Spp
- BO10210545 Application to amend App B of Tech Spece to License NPF-4. Change will delete nonradiological ETS requirements which are outside NRC jurisdiction & authority, ETS encl. FEROUSON, J. H. Virginia Electric & Power Co. 60/10/15. Spp.
- --8010210348 Tech Spec changes to App B to License NPF-4. Changes will make ETS for Unit 1 identical in format & content to Unit 2 ETS.

 * Virginia Electric & Power Co. 80/10/15, 50pp.
- 8010280409 Forwards proposed Tech Spec changes, per NRC 800702, 0815 & 0611 ltrs to PMR licensees. FEROUSDN.J.H. Virginia Electric & Power Co. 80/10/15. Gpp.
- --8010280415 Proposed Tech Spec changes incorporating TMI-2 Lessons Learned Category A, revised maint requirements for min water levels above fuel assemblies. Provides for redundancy in decay heat removal capabilities.
 • Virginia Electric & Power Co. 80/10/15. 36pp.

DOCKETED ITEMS

- 8010240446 Provides current status & schedule for implementing in-house reload licensing, to facilitate orderly review of probable license amend proposals planned for third quarter 1981 & first quarter 1982 Requests interim meeting.

 TKOMAS,W N. Virginia Electric & Power Co 80/10/17 3pp
- B010240525 Notifies that surveying procedure for settlement monitoring was revised B01016 per ALAB-578 decision
 BYLVIA,B R Virginia Electric & Power Co B0/10/20 1p
- 8010240443 Responds to NRC 800924 request for add1 info re electrical distribution sys voltages Final analysis of terminal voltages on Class IS loads are not available for 801016 submittal Progress repts will be submitted SYLVIA, B R Virginia Electric & Power Co 80/10/22 1p
- 8010240451 Responds to NRC 800731 ltr re shift staffing requirements. Shift staffing determined in compliance w/criteria. SYLVIA.B R Virginia Electric & Power Co 80/10/22 1p
- 8010310468 Responds to NRC 801017 request for add1 info re multiple structure ARS evaluation being performed on facilities Forwards status of verious Category B items & integrated priority list of sys requiring further computer analysis BYLVIA, B R Virginia Electric & Power Co. 80/10/28. 21pp.

O Inspection reports. IE Bulletins & correspondence

- 8003240244 Forwards Waste Package Insp Rept 79-06A on 791126-28 No noncompliance moted SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/12/31 2pp
- --B003240287 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements. radiation levels, removable contamination & DOT marking POTTER. J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 79/12/12 7pp.
- 8004080145 Forwards Waste Packaging Insp Rept 80-02A on 800206-08 No noncompilance noted. STORR,J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/02/26 5pp
- --B0040B0147 Waste Packaging Insp Rept 80~02A on B00206-08 No noncompliance noted Major areas inspected DOT & NRC requirements including shipping paper. DDT placard radiation levels marking & labeling POTTER, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/02/20. 4pp.
- 8010230090 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 2an.
- 8010010238 Ack receipt of 800825 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26 STORR, J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/09/15 ip
- --8010010249 Responds to NRC 800624 & 800812 ltrs re violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26 Corrective actions procedure revised & sodium bisulfite now utilized in milk sample preservation technique.

 SYLVIA: 8 R Virginia Electric & Power Co. 80/08/25 3pp
- --8010010254 Ack receipt of 800818 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26.
 STOHR.J P Region 2. Atlanta, Office of the Director. 80/08/12
- --8010010263 Responds to NRC 800624 ltr re violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26, Corrective actions: investigation underway to analyze previous results. SYLVIA, B, R Virginia Electric & Power Co 80/07/18 2pp
- ---8010010271 Forwards IE Insp Repts 50-338/80-25 & 50-339/80-26 on 800319-23 & 0602 & notice of violation STOHR. J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/06/24 2pp.
 - B010G10274 Notice of violation from inep on B00519-23 & 0602 * Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 80/06/24. 3pp.

- --8010010283 IE Insp Repts 50-338/80-25 & 50-339/80-26 on 800519-23 & 0602 Noncompliance noted failure to have adequate procedure for preservation of milk samples for radioiodine analysis MONTQQMERY, D M Region 2. Atlanta. Office of the Director TROUP, C L Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/24 9pp
- 8010160079 Responds to IE Bulletin 80-18 To assure min flow from centrifupal charging pumps. Westinghouse will implement mods to boost pressure Response required 120 manhours SYLVIA.8 R Virginia Electric & Power Co 80/09/26 2pp
- B010270497 Forwards IE Info Notice B0-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/26
- 8010160130 Forwards Suppl 2 to IC Builetin 79-018, "Environ Gualification of Class IE Equipment " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30-18.
- B010290409 Informs of incorrect insp number contained in 800919 1tr IE Insp Rept 50-339/80-17 should read 50-338/80-32 BTOHR.J P Region 2, Atlanta: Fuel Facility & Materials Safety Branch B0/07/30 ip
- --8010290412 Forwards IE Insp Repts 50-338/80-17 & 50-339/80-30 on 800805-08 & 15-16. No noncompliance noted.
 BTOHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp
- --8010270416 IE Insp Repts 50-338/80-17 & 50-339/80-30 on 800805-08 & 15-18 No noncompliance noted Major areas inspected offsite support agencies, emergency facilities, equipment & procedures, emergency training, emergency tests & drills PERROTTI, D J. TAYLOR, P A. ANDREMS, D L. Region 2, Atlanta, Office of the Director 80/09/17 14pp
- 8010150550 Ack receipt of 800912 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-338/80-29 & 50-339/80-28 LEMIS-R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/10/01 ip
- --8010150555 Forward: IE Insp Repts 50-338/80-29 & 50-339/80-28 on 800402-11 & notice of violation LEUIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/20 2pp
- --8010150557 Notice of violation from insp on 800602-11
 * Region 2: Atlanta, Office of the Director, 80/08/20 2pp
- --B010150565 IE Insp Repts 50-338/80-29 & 50-339/80-28 on 800602-11
 Noncompliance noted failure to comply w/Tech Specs re
 channel inoperabliity & failure to establish pre-startup
 procedure
 WEBSTER.E H . TATERBALL.A P Region 2. Atlanta. Office of the
 Director KELLOOO,F J Region 2. Atlanta. Reactor Operations
 Nuclear Support Branch 80/08/20 Spp
- 8010270555 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02 is
- B010270060 Forwards IE Info Notice 80-36, "Failure of Bissm Generator Bupport Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/10/10 is
- B010240452 Clerifies position re util 800926 ltr providing info on installation of steam generator insp ports Need & benefits of installing ports will be re-evaluated if eddy current & hand hole insps indicate progressive denting is continuing. BYLVIA:B.R Virginia Electric & Power Co 80/10/20 ip.
- R Periodic operating reports & related correspondence
- 8010160560 Forwards replacement pages for "Radioactive Effluent Release Rept," for Jan-June 1980 SYLVIA,B.R. Virginia Electric & Power Co 80/10/09 ip
- --8010140564 Replacement pages for Section III, App B to "Radioactive Effluent Release Rept," for Jan-June 1980 * Virginia Electric & Power Co 80/10/09, 146pp.

A

- 8010160486 Forwards monthly operating repts for Sept 1980 SYLVIA.B R Virginia Electric & Power Co. 80/10/14 ip
- --8010160498 Monthly operating repts for Sept 1980
 WGDD8MALL.W A Virginia Electric & Power Co 80/10/02 8pp
- B Reportable occurrences, LERs & related correspondence
- B010160703 PNO-II-80-140 on 800816, facility will be focal point of joint emergency planning exercise involving util, Commonwealth of VA & adjoining counties PERROTTI, D J. JENKINB, G R. Region 2, Atlanta, Office of the Director 80/08/14 ip
- 6010070580 Forwards updated LER 80-042/01X-1 CARTWRIGHT,W R Virginia Electric & Power Co. 80/10/01 1p
- --B010070590 Updated LER 80-042/01X-1 on 800509. Westinghouse determined that following secondary side high energy line rupture: potential for damage to charging pump before safety injection, termination exists CARTWRIOHT, W R Virginia Electric & Power Co 80/10/01 3pp
- BOLO140415 Forwards LER BO-080/03L-O CARTHRIGHT,W R Virginia Electric & Power Co BO/10/07 ip
- --9010140423 LER 80-080/03L-0. on 800908, power to 120-volt ac vital bus i-IV was lost. Caused by supply break for inverter, which supplies power to vital bus i-IV, in open position Power restored via installed transformer CARTHRIGHT, W R Virginia Electric & Power Co 80/10/07. 2pp
- 8010140427 Forwards LER 80-078/03L-0. CARTWRIGHT,W R. Virginia Electric & Power Co. 80/10/07 ip
- --B010140436 LER B0-078/03L-0 on B0090B, w/unit in startup mode, governor value for steem driven auxiliary feedwater pump discovered in tripped position Cause of overspeed trip due to incorrect governor setting Covernor value reset CARTHRIOHT, W R Virginia Electric & Power Co 80/10/07 3pp
- 8010210686 Forwards LER 80-084/01T-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/10/16 ip
- --EI010210694 LER 80-084/01T-0 on 801002. Westinghouse notified util that high steam line flow setpoints specified in PLS document are less conservative than Tech Specs require. Caused by calculation assumptions not reflecting installation CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/10/16 3pp.
- BO10220477 Forwards LER 80-079/03L-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/10/16 1p
- --B010220478 LER B0-077/03L-0 on B00920, normalized axial power distribution exceeded limit by 0 BX Caused by rods driven 213 steps in preparation for flux mapping at 211 steps resulting in delta flux becoming negative Rods withdrawn CARTWRIGHT, W R Virginia Electric & Power Co. B0/10/16 2pp
- 8010220659 Forwards LER 80-082/03L-0.
 CARTWRIGHT: W R. Virginia Electric & Power Co 80/10/16. ip
- --B010220668 LER B0-082/03L-0 on 800925 tap settings for offsite ac power source transformers found not as assumed in voltage profile analyses. Caused by insufficient tap setting administrative control in 500 kV/34 5 kV & 34.5 kV/4160 volt transformers. CARTWRIGHT, W R. Virginia Electric & Power Co 80/10/16. 2pp
- 8010230414 Forwards LER 80-081/03L-0 CARTWRIOHT, M. R. Virginia Electric & Power Co. 80/10/17. ip.
- --B010230420 LER 80-0H1/O3L-0 on 800923, protection channel resistance temp detector discovered not calibr within required surveillance interval caused by improper specified test frequency. New test was written & performed satisfactorily CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/10/17. 2pp
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BO10220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of THI action plan requirements. Corrected table of implementation schedule also encl. EIBERHUT, D Q. Division of Licensing. 80/09/19, 28pp.

- F Security, medical, emergency & fire protection plans
- 8008260006 Discusses evaluation of emergency preparedness for facility Emergency preparedness program is acceptable, capable of being implemented & meets regulatory requirements ORIMES, B K Emergency Preparedness Program Office 80/08/19 is
- 6010230343 Ack receipt of util 800603 & 0718 ltrs transmitting security plan changes Changes are consistent w/code requirements & contain info that should be withheld from public (ref 10CFR2 790)
 CLARK-R A Operating Reactors Branch 3 80/09/25 2pp
- B010170044 Grants B00922 request for 30-day extension to emergency plan submittal date
 YUNNOBLOOD, B. J. Licensing Branch 1 B0/10/01 2pp
- 8010210015 Notification of 801027 meeting w/util in Bethesda: MD to discuss emergency response facilities ENGLE:L Operating Reactors Branch 3 80/10/01 3pp
- 8010270372 Clarifies aspect of 800725 commitment re installation of smake detection sys Ail i2 zones of smoke detectors for Unit 2 will be installed/operational during 801101 outage Ail remaining zones will be operational at snd of Unit 1 outage. SYLVIA.B R Virginie Electric & Power Co 80/10/22 ip

H General correspondence

- 8010230632 Responds to 800626 ltr to FERC inquiring when plants will be operational Provides schedule for projected plant restart Certificate of Svc encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/09/05
- 8010230714 Responds to 800724 ltr requesting info re plant operating experience Discusses LERs & radiation levels around facility LERs do not directly affect safety of public due to multiple levels of protection DIRCKS.W J Office of the Executive Director for Operations. 80/09/30 5pp
- --8010230713 Forwards AS Hapler 800724 ltr requesting info on facility. Requests response ROB INSON.J K House of Res. 80/08/01 4pp
- --8010230717 Requests info re operation of facility, comparison to other nuclear power plants & radiation reading around farm HEPLER.A 8 Affiliation Unknown 80/07/24 1p
- J Insurance & indemnity information
- 8010080549 Forwards Endorsement I to MAELU Binder XB-70 LOYINO, L J Harsh & McLennan, Inc., H & M Nuclear Consultants, Inc Div 80/10/02, 7pp.
- B010240251 Forwards payment of NRC B00924 Invoice 1176-80 Payment extends indomnity agreement for license to account for increase in power level for 800222-810221 BYLVIA, B R Virginia Electric & Power Co. B0/10/20 ip
- P Operating license stage documents & correspondence
- BO10010Bil Bubmits info re present status of facility. Facility operating at 50% power YOUNGBLOOD, B J Licensing Branch 1 BO/09/18 ip.
- 8010060110 Notification for 800922 meeting w/util & Stone & Webster in Soston: MA to discuss design of ABME code Class 2 & 3 piping sys.

 DROMERICK, A. W. Licensing Branch 1 80/09/19. 3pp.
- 8010030505 Notification of 800922 meeting w/util in Boston, MA to discuss design of ASME Class 2 & 3 piping sys DROMERICK, A. W. Licensing Branch 1, 80/09/25, 2pp.
- 8010010678 Forwards "Evaluation & Critique of NUREO/CR-1380 "
 Document does not reflect importance in quality or
 applicability to nuclear power station control rooms.
 BYLVIA, B.R. Virginia Electric & Power Co. B0/09/26 ip.
- --8010010688 "Evaluation & Critique of NUREO/CR-1580." * Virginia Electric & Power Co. 80/09/30 100pp

- 8010100232 Requests Units 3 & 4 settlement time records from 1980 to FSAR submittal date YOUNGSLOOD, B J Licensing Branch 1 80/09/29 2pp
- 8010200650 Summary of 800909 & 10 trip rept w/ID Natl Engineering Lab at North Anna 2 re inservice festing program for pumps &
 - CAPPUCCI, A. J. Mechanical Engineering Branch 80/09/29 4pp
- 8010070378 Responds to NRC 800905 request for info re THI action plan requirement preliminary clarification Westinghouse owners group meeting w/NRC will determine add1 effort required & re-evaluation will be submitted Deadline unrealistic BYLVIA.B R Virginia Electric & Power Co 80/10/02 2pp
- 8010230004 Requests review of possible deficiency in operability of low head safety injection pumps discussed in R Bosnak 800729 mano TEDESCO.R Assistant Director for Licensing 80/10/03 ip
- 8010190304 Submits primary & secondary electrical penetration protection for power control & instrumentation of electrical circuits, per NRC 790803 & 791130 ltrs. Bubmittal completes requirements of License NPF-7 issued 80092t BROWN.8 C Virginia Electric & Power Co B0/10/10 3pp
- B010160580 Forwards Revision 1, "Electrical Penetration Protection Instrument Circuits (Primary & Secondary)" & "Electrical Penetration Control Circuits (Primary & Becondary)" BROWN B C Virginia Electric & Power Co B0/10/10 App
- --8010160584 Revision 1. "Electrical Penetration Protection Instrument
 - Circuits " * Stone & Webster Engineering Corp 80/09/24 25pp
- -- 8010160590 "Electrical Penetration Protection Control Circuits (Primary
 - & Becandary) " 4 Stane & Webster Engineering Carp 80/10/10 25pp
- --B010160594 Revision 1, "Electrical Penetration Protection Power Circuits (Primary & Becondary)." * Stone & Webster Engineering Corp 80/09/22, 43pp
- 8010280409 Forwards proposed Tech Spec changes, per NRC 800702, 0815 & 0611 ltrs to PWR licensees, FERGUSON, J R Virginia Electric & Power Co. 80/10/13 3pp
- --8010280415 Proposed Tech Spec changes incorporating TMI-2 Lessons
 Learned Category A revised maint requirements for min water
 lavels above fuel assemblies Provides for redundancy in
 decay heat removal capabilities

 * Virginia Electric & Power Co 80/10/15 36pp
- 8010200446 Submits add1 info re low head safety injection pump operability per NRC request at 800922 meeting Operability will not be affected during postulated out of plumb periods associated w/post-accident containment response BYLVIA.B R Virginia Electric & Power Co 80/10/16. 2pg
- 8010240446 Provides current status & schedule for implementing in-house reload licensing, to facilitate orderly review of probable license amend proposals planned for third quarter 1981 & first quarter 1982 Requests inter
- B010240525 Notifies that surveying procedure for settlement monitoring was revised B01016 per ALAB-578 decision.
 BYLVIA:BR Virginia Electric & Power Co. B0/10/20. 1p
- 8010240451 Responds to NRC 800731 ltr re shift staffing requirements Shift staffing determined in compliance w/criteria. SYLVIA, BR Virginia Electric & Power Co. 80/10/22 ip
- 8010310468 Responds to NRC 801017 request for addl info re multiple structure ARS evaluation being performed on facilities. Forwards status of various Category B items & integrated priority list of sys requiring further computer analysis SYLVIA.8 R Virginia Electric & Power Co 80/10/28 2ipp.
- G Inspection reports, IE Bullstins & correspondence
- 8010230090 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matts "No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29

- 8010010238 Ack receipt of 800825 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26
 - 50-339780-20 STOHR,J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/15 ip
- --B010010249 Responds to NRC 800624 & 800812 ltrs re violation noted in IE Insp Repts 50-338/80-25 & 50-339/80-26 Corrective actions procedure revised & sodium bisulfite now utilized in milk semple preservation technique
 SYLVIA, B R Virginia Electric & Power Co 80/08/25 3pp
- --8010010254 Ack receipt of 800818 ltr informing NRC of steps taken to correct violation noted in TE Insp Repts 50-338/80-25 & 50-339/80-26 STOHR.J P Region 2, Atlanta, Office of the Director 80/08/12
- --8010010263 Responds to NRC 800624 itr re violation noted in IE Insp Rapts 50-338/80-25 & 50-339/80-26 Corrective actions investigation underway to analyze previous results BYLVIA.B R Virginia Electric & Power Co 80/07/18 2pp
- --8010010271 Forwards IE Insp Repts 50-338/80-25 & 50-339/80-26 on 800519-23 & 0602 & notice of violation STOHR.J.P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/24 2pp
- --8010010283 IE Insp Repts 50-339/80-25 & 50-339/80-26 on 800519-23 & 0602 Noncompliance noted failure to have adequate procedure for preservation of milk samples for radidiodine analysis MONTGOMERY.D M Region 2. Atlanta. Office of the Director TROUP.O L Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/06/24 9pp
- 8010160077 Responds to IE Bulletin 80-18 To assure min flow from centrifugal charging pumps. Westinghouse will implement mods to boost pressure. Response required 120 manhours SYLVIA:8 R Virginia Electric & Power Co 80/07/24 2pp
- 8010270497 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Conlant During Steam Generator Decontamination " No specific action or response requested O'REILLY, J. P. Region 2, Atlanta: Office of the Director, 80/09/26
- 8010160130 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No written response required.

 O'REILLY, J. P Region 2. Atlanta, Office of the Director 80/09/30
- B010290409 Informs of incorrect insp number contained in B00919 ltr IE Insp Rept 50-338/80-17 should read 50-338/80-32, STUHRJ P. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch, B0/09/30 ip
- --8010290412 Forwards IE Insp Repts 50-338/80-17 & 50-339/80-30 on 800805-08 & 15-18. No noncompliance noted 8TOHR. J P Region 2. Atlanta. Fuel Facility & Materiale Sefety Branch. 80/09719 2pp
- --8010290416 IE Insp Repts 50-338/80-17 & 50-339/80-30 on 800805-08 & 15-18 No noncompliance noted Major areas inspected, offsite support agencies, emergency facilities, equipment & procedures, emergency training, emergency tests & drills. PERROTTI.D J. TAYLOR.P A. ANDREWS.D L. Region 2, Atlanta, Office of the Director 80/09/17 14pp.
- B010150590 Ack receipt of B00912 ltr informing NRC of steps taken to corpect violation noted in IE Insp Repts 50-338/80-29 & 50-339/80-28 LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/10/01, ip
- --8010130555 Forwards IE Insp Repts 50-338/80-27 & 50-339/80-28 on 800602-11 & notice of violation.
 LEWIS,R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/20. 2pp
- --8010150559 Notice of violation from insp on 800602-11.
 ** Region 2, Atlanta, Office of the Director. 80/08/20 2pp.

- --8010150565 IE Insp Rapts 50-338/80-29 & 50-339/80-28 on 800602-11 Noncompliance noted fariure to comply w/Tech Specs re channel inoperability & failure to establish pre-startup procedure WEBSTER,E H , TATERSALL,A P Region 2, Atlanta, Office of the Director KELLOGG,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/20 Spp
- 80t0270555 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02
- 8010270040 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010160540 Forwards replacement pages for "Radioactive Effluent Release Rept." for Jan-June 1980. SYLVIA,B R Virginia Electric & Power Co 80/10/09 ip
- --8910160564 Replacement pages for Section III.App B to "Radioactive Effluent Release Rept," for Jan-June 1980 + Virginia Electric & Power Co 80/10/09 146pp
- 8010160956 Forwards monthly operating repts for Sept 1980 8YLVIA:B R Virginia Electric & Power Co 80/10/14
- --B010160459 Monthly operating repts for Sept 1980 HODDSHALL, W.A. Virginia Electric & Power Co 80/10/02 Bon
- S Reportable occurrences. LERs & related correspondence
- 8010080597 PNO-II-80~107 on 800612, unit achieved initial criticality Actual parameters were in close agreement w/predicted conditions. conditions. WEBSTER, E. H., KELLOGG, P.J. Region 2, Atlanta, Office of the 80/04/13
- 8010160703 PNO-II-80-140 on 800816, facility will be focal point of joint emergency planning exercise involving util, Commonwealth of V4 & adjoining counties PERROTTI.D J. JEMKINS, O R Region 2. Atlanta, Office of the Director 80/08/14 1p
- 80:0170280 Advises of possible deficiency in equipment operability of low head safety injection sus pumps. Suggests detailed investigation re possible deformation in shafts & bearings BOSNAK, R J Mechanical Engineering Branch 80/09/29 1p
- 80:0060221 Forwards LER 80-056/03L-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/10/01 ip.
- --8010060231 LER 80-056/OSL-0 on 800917.during routine containment exit, outer door on personnel hatch did not close properly Caused by misalignment Door adjusted & test performed to verify that air lock leakage rate was within acceptable limits CARTWRIGHT.W R Virginia Electric & Power Co 60/10/01 2pp
- EO10070301 Forwards LER 80-054/03L-1 CARTHRIGHT, W R Virginia Electric & Power Co 80/10/01 1p
- --8010070304 LER 80-054/03L-1 on 800817, when entering Mode 3 operation, buric acid transfer pump i-CH-P-28 placed in svc w/o performing periodic test PT-15, 2, Caused by personnel oversight Test performed w/satisfactory results CARTWRIOHT, W R Virginia Electric & Power Co 80/10/01 3pp.
- 8010070499 Forwards LER 80-050/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co. 80/10/01 1p
- --- B010070512 LER 80-050/03L-0 on B00902, during Mode 5, pressurizer pawerosuo/UD12 Ltk 80-050/O3L-0 on B00902, during Mode 5, pressuriter (
 operated relief valve was inoperable when nitrogen supply
 dropped, Caused by low nitrogen pressure, Pressure was
 restored in 12-h by renewing supply & pressuriting tanks
 CARTWRIGHT, W. R. Virginia Electric & Power Co. B0/10/01 2pp
- 8010070503 Forwards LER 80-061/03L-0
 CARTWRIGHT,W R Virginia Electric & Power Co. 80/10/01 ip

- --8010070513 LER 80-041/03L-0 on 800919. LHSI pump B relieve valve actuated at 190 pais rather than 220 psis Probably caused by upakened spring action allowing lower pressure to open valve apring tension reset & valve returned to svc CARTHRIGHT, W R Virginia Electric & Power Co 80/10/01 80/10/01 200
- 8010070515 Forwards LER 80-063/03L-0 CARTURIGHT.W R Virginia Electric & Power Co 80/10/01 ip
- --8010070525 LER 80-043/03L-0 on 800920, during performance of incore-accore detector calibr startup test, found zero point shift of DELTA T/T AVG Channel III summing amp Cause undetermined Channel placed in trip & new summing amp instelled CARTWRIGHT.W R Virginia Electric & Power Co. 80/10/01 2pp
- 8010070592 Forwards LER 80-060/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 80/10/01, 1p
- --8010070534 LER 80-060/03L-0 on 800913, in Mode 1, procedure 2-PT-62 4 revealed that leatage past outer seals on personnel air lock door exceeded Tech Bpecs Caused by misaligned personnel hatch on outer door. CARTURIGHT, W R Virginia Electric & Power Co 80/10/01 2pp
- 8010D70594 Forwards LER 80-057/03L-0. CARTHRIGHT.W R Virginia Electric & Power Co 80/10/01 1p
- --8010070596 LER 80-057/03L-0 on 800908, w/unit in Mode 3, individual rod position indication for Rod G-9 in shutdown bank B deviated from group demand position by greater than 12 steps Caused by instrument drift; Indicator recalibr CARTWRIGHT; WR Virginia Electric & Power Co. BO/10/C B0/10/01, 2pp.
- 8010070602 Forwards LER 80-055/03L-0 GARTWRIGHT,W R Virginia Electric & Power Co 80/10/01 1p
- --B010070607 LER B0-055/03L-0 on 800705, results of periodic valve inservice test revealed excessive laskage past 2-BI-70 Caused by corroded seating plug. Valve replaced & tested satisfactority.

 GARTWRIOHT.H R Virginia Electric & Power Co 80/10/01. 3p.
- 8010140397 Forwards LER BO-058/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/10/07 1p
- --B010140409 LER 80-058/03L-0 on 800909, steam flow indicator FI 2494 was reading high w/little or no flow Channel declared inoperable & placed in trip mode Cause not determined Instrument to be examined during next Mode 5 outage
 CARTHRIGHT, M. R. Virginia Electric & Power Co. B0/10/07, 2pp
- 8010150456 Forwards LER 80-059/03L-0, CARTWRIGHT: W R. Virginia Electric & Power Co. 80/10/08 ip.
- --8010150466 LER 80-059/O3L-O. on 800911.boron concentration of 2111 ppm in 81 accumulator 1A was discovered during sample analysis Caused by stratification of stagnant borated solution in accumulator CARTHRIGHT.N R Virginia Electric & Power Co 80/10/08 2pp
- 8010220479 Forwards LER 80-046/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/10/15, 1p.
- --8010220482 LER 80-076/03L-0 on 801003, while increasing power, neutron flux distribution deviated from axial flux difference target band Gaused by xenon accumulation in upper quadrants of core battypen time of rempodum & power ascension.

 CARTHRIGHT, W. R. Virginia Electric & Power Co. 80/10/15 2pp
- 8010220466 Forwards LER 80-062/03L-0.
 CARTHRIGHT, W R. Virginia Electric & Power Co. 80/10/16 1p
- --B010220470 LER 80-042/03L-0 on 800919,800918 RCB leak test not performed Cause6 by personnel oversight. Test subsequently performed satisfactorily, GARTMRTOHT. W R. Virginia Electric & Power Co. 80/10/14 2pp.
- 8010280547 Forwards LER 80-064/03L-0 GARTWRIGHT,W R. Virginia Electric & Power Co. 80/10/23 1p.

- DOCKET 50-340 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided greliminary clarification of TMI action plan requirements Corrected table of implementation schedule also esci EISEKHUT, D G Division of Licensing 80/09/19 28pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800705 itr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D G Division of Licensing 80/09/17 28pp
- B010220052 Notification of 801001 meeting w/util in Bethesda, MD to discuss applicant evaluation of high density fuel storage KINTER, L. Licensing Branch 2 80/09/24 3pp
- 8010270293 Advises that work is continuing to reduce design documents having unincorporated interim changes re unresolved Item 77-17-02 in IE Bulletin 79-17, Revision 2 HINES.E Detroit Edison Ca 80/09/24 1p
- 8010280643 Forwards requests for add1 info re FSAR Requests util amend FSAR to comply w/requirements listed in encl TEDESCO.R L. Assistant Director for Licensing 80/10/07 9pp
- B010210623 Forwards Certificate of Svc for Amend 30 to amended & substituted application for licenses
 MATERS.B R Detroit Edison Co 80/10/14 3pp
- F Security, medical, emergency & fire protection plans
- 8010160925 Forwards "Enrico Fermi Atomic Power Plant Unit 2 Evacuation Analysis Preliminary Estimate of Evacuation Times " Final rept will be submitted by mid-Dec 1980 TAUBER: H Detroit Edison Co 80/10/10 ip
- --8010160528 "Enrico Fermi Atomic Power Plant Unit 2 Evacuation Analysis Preliminary Estimate of Evacuation Times " # PRC Planning & Economics, Alan M Voorhees & Associates Div 80/10/31 29pp
- Q Inspection reports: IE Bulletins & correspondence
- 8010150230 Forwards IE Insp Rept 50-341/80-10 on 800605-0731 No noncompliance noted HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/21 2pp
- --8010150235 IE Insp Rept 50-341/80-10 on 800605-0731.No noncompliance noted Hajor areas inspected review of IE bulletin & circular followep.preoperationed GA program & licensee action on previous insp findings
 LITTLE,WS LITTLE,B H Region 3, Chicago. Office of the Director. 80/08/21 4pp
- 8010220059 Responds to IE Bulletin 80-19, Revision 1. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Mercury-wetted relays are not used at facility HINES.E Detroit Edison Co. 80/09/02 3pp
- B010070107 Responds to IE Bulletin B0-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Buitches "Westinghouse Type W-2 control switches not used at Facility HINES,E Detroit Edison Co B0/09/15 2pp
- 80:0200572 Forwards final response to Items 1-3 of IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-312, Type 304 Stainless Steel Pipe "No piping components use greater than 85%. allowable stress HINES,E Detroit Edison Co 80/09/15 2pp
- 8010270335 Forwards IE Mgt Meeting Rept 50-341/80-12 on 800812 & facility 800808 performance evaluation. No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/19 200

- --8010270338 IE High Meeting Rept 50-341/80-12 on 800812 No noncompliance noted Areas discussed regulatory performance of activities per systematic assessment of performance program Facility 800808 performance evaluation encil FIGRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/19 7pp
- 8010160295 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required KEPPLER, J. G Region 3, Chicago, Office of the Director 80/09/30 ip
- 80(0270187 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters w/Either A or D Gutput Codes "Requests Indefinite extension of 801001 rept date due to delay in 0E rept HINES.E Detroit Edison Co 80/09/30 2pp
- 8010280656 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/10/02
- 8010290018 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J. G. Ragion 3, Chicago, Office of the Director 80/10/10
- 8 Reportable occurrences, LERs & related correspondence
- 8010100393 PNG-III-80-107 in 800521 ltr.Detroit TV station WXYZ provided list of 31 aliegations re constipiping, nonconformance regiss & welding documentation Party making allegations will be contacted Addl investigation conducted PHILLIP, 9 DANIELSON, D. FIGRELLI, 9 Region 3. Chicago, Office of the Director 80/08/02 ip
- 8010170300 Ack receipt of 800703 deficiency rept re RHR heat exchanger relief valves FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/19 ip
- 801015053B Interim deficiency rept re nonseismic equipment installed over seismic Edison Engineering has identified affected equipment as nonseismic pieces of heating, ventilation & air conditioning duct Final rept will be provided by 810316 HINES,E Detroit Edison Co 80/09/30 2pp
- 8010240513 Bubmits final rept re problems in startup operations Startup operations suspended on 800328 due to deficiencies found w/procedures used by startup technicians Necessary corrective actions have been initiated HINES,E Detroit Edison Co 80/10/20 2pp
- DOCKET 30-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergency & fire protection plans
- 8010010547 Forwards comments on radiological emergency plan Addi info & commitments are required before program acceptable Plan should be revised according to criteria in NUREO-0654 & resubmitted within 60 days CLARK, R A Operating Reactors Branch 3 80/09/17 16pp
- B010070299 Forwards responses to unresolved issues identified in 800917 ltr re facility radiological emergency response plan Proposes revision to Page 2 6 4-5 re special telephone lists for schools & hosps & Table 2 4 re smergency action level WITHERS.B D Portland General Electric Co 80/10/02 32pp
- 8010280347 Provides initial notification & followup rept re inoperability of fire suppression sys Bys operability will not be met during planned maint overhaul of diesel-driven fire pump Bys will be inoperable 801020-1112
 YUNDT.C P Portland General Electric Co 80/10/16 ip.
- 8010280449 Forwards "Trojen Nuclear Plant Emergency Response Facilities," per NRC 800905 request Technical support ctr & amergency operations facility will be operational by 820401 & safety patrameter display sus by 820101 WITHERS, B. D. Portland General Electric Co. 80/10/21 1p
- --8010280452 "Trojan Nuclear Plant Emergency Response Facilities." * Portland General Electric Co 80/10/20, 32pp.
- 8010310390 Submits info re security plan Info withheld (ref 10CFR2 790). WITHERS,B D Portland General Electric Co 80/10/23 3pp

Q Adjudicatory correspondence

- B010230111 Forwards order revising 800829 order for mod of OL due to incorrect refs Hearing date accordingly changed.
 EISENHUT, D G Division of Licensing 80/09/25 2pp
- --B010230116 Order for mod of License NPF-1, adding provision that requires response to IE Bulletin 79-018 by 801101 Revises 800827 order published in 800911 FR Request for hearing shall not stay effectiveness of mod USC petition discharged PURPLE, R A Division of Licensing 80/09/25 App
- B010010364 Forwards util 800726 ltr containing evaluation of NCR 8022 re masonry wall connections Corrective actions are being performed to repair wall panels & are scheduled for completion by Nov 1980 JCHNSON, R W Fortland General Electric Co 80/07/26 3pp
- --B010010370 Forwards evaluation of nonconformance similar to LER 80-007.

 Suppl 1 Wall on column line 46 has capability to withstand im-plane & out-of-plane SSE loading conditions acceptably Centificate of Svc enc.;

 BROEHL, D J Portland General Electric Co 80/09/26, 7pp
- B010010703 Order granting extension until 801006 for Commission to review Director's decision under 10CFR2 206 CHILK.B. J. Office of the Secretary of the Commission 80/09/29 is.
- BO10200551 Notifies that Commission has decided not to review Director's decision denying intervenor request under 10CFR2 206. Commission ordered that further consideration be given to problems of evaluation during volcanic eruption CHILK, B J Office of the Secretary of the Commission 80/10/16.
- 8010300092 Brief in support of exceptions to ASLB 800711 initial decision & to ASLAB 800904 order Urges that decision be modified to include accelerated reporting conditions & that oral argument be held re exceptions W/Certificate of Svc OSTRANDER, F. H. Oregon, State of 80/10/22 19pp
- 8010300027 Forwards licensee response to IE Bulletin 80-ii re masonry well design which discusses criteria for seismic loads re AELB initial decision, Certificate of Svc encl JOHNBONN R.W Portland General Electric Co 80/10/23 3pp

H General correspondence

- 8010030460 Discusses resubmittal of petition by Physicians for Social Responsibility re withdrawal of util certificate due to volcanic activity of Ht St Helens Matter will be discussed at 800917 meeting Supporting documentation enci. DIXON.B. Energy, Dept of 80/09/15 13pp
- 801002059? Responds to 800727 telegram re Mount Bt Helens activity on facility. Concludes facility remains suitable from volcanic hazards viewpoint, based on assessment of effects of activity beginning 800320 Affidavit of RB McMullen re volcanism encl EIBENHUT, D. O. Division of Licensing 80/09/17. 4pp
- --8010020400 Requests immediate shutdown of facility due to volcanic activity of Hount Bt Helens
 PACKER:B Physicians for Bocial Responsibility. 80/07/27, 1p
- --8010020A04 Affidevit re assessments of landslides & volcanism on facility safety of operation Lendslides & volcanism do not pose potential threat to facility HCMULEN:R B Assistant Director for Environmental Technology 78/04/12 30pp
- E010080669 Responds to B0080B ltr re CA Bnow concerns about impact of Mount Bt Helens on facility Effects of volcanism at site have been minimal Probability of facility accident in combination w/road obstacles from volcanic ashfall is low. DIRCKS.M.J. Office of the Executive Director for Operations. 80/09/29. 3pp
- --8010080472 Requests response to encl CA Bnow concerns about impact of Mount St Helens on facility MAONUSON, W. Q. Senete, Appropriations 60/08/08. 2pp.
- GO100B0522 Advises that all future correspondence should be addressed to BD Withers, Vice President Nuclear, due to recent organizational changes, Copies of correspondence should be sent to JM Durham, Senior Vice President HITHERS, B. D. Portland General Electric Co. 80/10/02. is.

- P Operating license stage documents & correspondence
- B01007006B Notification of rescheduled 800930 meeting w/util & Westinghouse in Bethesda.MD to discuss lab examination results of steam generator Row 1 U-bend samples Heeting originally scheduled for 800925 TRAMMELL.C M Operating Reactors Branch 3 80/09/16 2pp
- 8010220099 Forwards errata shoots amending 800905 ltr which provided preliminary charification of THI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing 80/09/19 28pp
- 8010030055 Describes process that State of OR DOE proposes to use to fulfill personnel screening requirements of util security plan for dept resident inspector FRANK.L. Energy, Dept of 80/09/23 4pp
- B010090555 Advises that util commitments re NRC 791119 "Interim Position on Containment Purging Venting Pending Resolution of Isolation Valve Operability" are acceptable Bafety avaluation & Tech Spec changes will be provided, if required CLARK.R A Operating Reactors Branch 3 80/09/24 2pp
- 8010010559 Notifies of delay in implementation of TMI-2 Lessons Learned items scheduled for 610101 until resolution of matl delivery problems. Bummary of til commitments per NUREG-0578 & comments on NRC 800905 for to 11censees & applicants encl GOODWIN, C Portland General Electric Co 80/09/29 7pp
- 8010020341 Forwards application for Amend 46 to License NPF-1 Certificate of Svc encl WITHERS, B D Portland General Electric Co 80/09/30 2pp
- --8010020345 Application for Amend 66 of License NPF-1, changing Tech Specs 6 2-1,6 5 1 7,6 5.1 8,6.5 2 1-6 & 8-10.6.6-6 8, 5 0-4 & Table 5 1 showing organizational changes WITHERS, B D Portland General Electric Co. 80/09/30 5pp
- --8010020347 Proposed changes to Tech Specs & 2-1, & 5 1 7-8, & 5 2, 1-6 & 8-10, 6 6-6 8, 5 0-4 & Table 5 1 reflecting organizational changes * Portland General Electric Co 80/09/30 I3pp
- 8010D30432 Forwards application for proposed Change 65 to License NFF-1/deleting App B of security plan Fee & Certificate of Svc encl GCOUNTN/C Portland General Electric Co BO/09/30 3pp
- ~~8010030437 Application for proposed Change 65 to License NPF-1 re amend to security plan, reflecting encl util responses to NRC & DR DDE review comments Supporting data available in Central Files only M/Certificate of Svc 4 Portland General Electric Co 80/09/30 3pp.
- B010230314 Requests recalculation of boron dilution event under plant conditions not addressed in FBAR Licensee should provide commitment to revise procedures to insure maint of correct shutdown margin CLARK, R A Operating Reactors Branch 3 80/09/30 3pp
- 8010300225 "Adequacy of Station Electric Distribution Bys Voltages: Trojan Nuclear Power Station," interim rept. UDY, A C E080 Idaho, Inc FIN A-6236 8010300225 80/09/30 9pp
- B010080952 Forwards MCAP-9469, "Analysis of Capsule U From Portland General Electric Co Trojan Reactor Vessel Radiation Surveillance Program," Capsule U removed from reactor vessel for surveillance in Apr 1978 WITHERS, B. D. Portland General Electric Co B0/10/02 1p
- --8010080957 "Analysis of Capsule U From Portland General Electric Co Trojan Reactor Vessel Radiation Surveillance Program " DAVIDBON, J A., ANDERBON, B L. CHIRIGOS, J N., Westinghouse Electric Corp NGAP-7449. 79/05/31.
- 8010300460 Forwards request for add1 info re Mount St Helens volcanic activity effect on facility. Response requested within 45 days CLARK, R A. Operating Reactors Branch 3. 80/10/03. 4pp
- 8010230300 Forwards Amend 50 to License NPF-1, safety evaluation & notice of issuance & availability CLARK, R. A. Operating Reactors Branch 3 80/10/06 3pp
- ---8010230307 Amend 50 to License MPF-1.adding operability & surveillance requirements for new fire protection equipment.

 CLARK: A Operating Reactors Branch 3. 80/10/06. 17pp.

- ---8010230312 Safety evaluation supporting Amend 30 to License NFF-1 # Office of Nuclear Reactor Regulation, Director. 80/10/06 20:
- --8010230315 Rotice of Issuance & availability of Amend 50 to License NPF-1 CLARK, R. A. Operating Reactors Branch 3 80/10/06 2pp
- 8010300331 Forwards Amené 49 to License NPF-1 & notice of issuance & availability CLARK,R.A Operating Reactors Branch 3 80/10/06 3pp
- --B010309358 Amend 49 to License NPF-1, modifying license to require full implementation of safeguards contingency plan per 190FR73.40(b) within 30 days of approval CLARK.R.A Operating Reactors Branch 3 80/10/06 2pp
- --B010300367 Notice of issuence & availability of Amend 47 to License NPF-1 CLARK,R A. Operating Reactors Branch 3. 80/10/06. 2pp
- 8010210443 Submits info in response to NRC 800905 ltr.re small-break LOCA analysis:per NRC action plan requirements BROEKL.D.J. Portland General Ejectric Co. 80/10/16 2pp
- 8010220351 Forwards responses to Questions 361.4 through 361.6 revolcanic activity at Mount Bt Helens & relation to facility Largest magnitude earthquake on worldwide basis was 1764 supplied of Sheveluch on Kamchatka peninsula.

 BROEKL, D. J. Portland General Electric Co. 80/10/16. 899
- 8010300421 Forwards License Change Application 68 requesting emend to License NPF-1. Class III emend fee & Certificate of Svc enci WITHERS, B D Portland General Electric Co 60/10/24 2pp.
- --8010300424 License Change Application 60 requesting amend to License NPF-1 to incorporate changes in Tech Specs re refueling operations & redundancy in residual heat removal capabilities.
 WITHERS, B D. Portland Ceneral Electric Co. 80/10/24. 7pp
- --8010300425 Proposed changes to Tech Specs 3/4 4 through 3/4 9 13/ incorporating revisions ar refueling operations & redundancy in residual heat removal capabilities # Portland Gameral Electric Go. 80/10/24 14pp.
- G. Inspection reports: IE Bulletins & correspondence
- B010300678 Responds to IE Bulletin 80-19, "Failures of Hercury-Watted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E." Subj relays not used in logic matrix of sys at facility.

 9000WIN.C. Portland General Electric Co. 80/09/29. ip.
- 8010090377 Forwards IE Insp Rept 50-344/80-19 on 800721-25 No noncompliance noted CREWB, J L. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch B0/09/02. 2pp.
- --8010090379 IE Insp Rept 50-344/80-19 on 800721-25.No noncompliance noted Major areas inspected procurement; surveillance of pipe supports & constraints instrument calibr & responses to IE bulletins & circulars
 STERNBERG, D.M. Region 5. Ben Francisco, Reactor Descrations Nuclear Support Branch. JOHNSON, P.H.: CARLSON, J.D. Region 5. Ben Francisco. Office of the Director. 80/08/22. 7pp.
- 8010010285 Forwards IE Insp Rept 50-344/80-15 on 800714-17 & notice of violation, Encls withheld (ref 10CFR2, 790).
 NORDERHAUOLE R. Region 5, San Francisco, Safeguards Branch.
 80/09/08, 2pp.
- 8010090416 Forwards IE Insp Rept 50-344/80-18 on 800722-25. No honcompliance noted. CREMS.J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/08. 3pp.
- --B010070424 IE Insp Rept 50-344/80-18 on 800722-25. No noncompliance noted, Major areas inspected; program & documentation associated widcontrol of centrifugal charging/eafaty injection pumps.

 SHAFER, N. D., FOSTER, L. E. Region B. San Francisco, Office of the Director. 80/08/29. 9pp.
- 8010290400 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required.
 SNOELKEN.R.H. Region 5. Sen Francisco: Office of the Director.
 80/09/10. 1p.

- 8010080367 Responds to IE Bulletin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Raview revealed no Westinghouse type control switches used in safety-related applications at plant COCOWIN.C Portland General Electric Co 80/09/15 1p
- 8010230172 Forwards IE Insp Rept 50-344/80-21 on 800801-31 No noncompliance noted CREMS, J. Region 5, San Francisco, Reactor Operations Nuclear Bupport Branch 80/09/18 2pp
- --8010230180 IE Insp Rept 50-344/80-21 on 800801-31 No noncompliance noted Hajor areas inspected surveillance testing physical security plant mods & operations STERNBERO, D. M. Ragion 5, San Francisco, Reactor Operations Nuclear Support Branch. MaLhROS, M. H., JDHNGTON, Q. U. Region 5, San Francisco, Office of the Director. 80/09/17. App
- B010270367 Forwards response to IE Bulletin 80-18, "Maint of Adequate Min Flow thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Recommended Interim Mod II will be implemented BROEHL.D J Portland General Electric Co 80/09/24 10pp
- 8010080146 Ack receipt of 800912 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-344/80-20 CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/25 ip
- --B0100B01B1 Responds to NRC 800920 ltr re violations noted in IC Insp Rept 30-344/80-20 Corrective actions after verifying initial RCS boron concentration, boration of RCS commenced, GODDNIN, C Portland General Electric Co. 80/09/12 3pp.
- --8010080159 Forwards IE Insp Rept 50-344/80-20 on 800701-31 & notice of violation.
 CREWS, J. L. Ragion 5, Ban Francisco, Reactor Operations Nuclear Bupport Branch. 80/08/20. 2pp.
- --8010080144 Notice of violation from insp on 800701-31 * Region 5. San Francisco. Office of the Director 80/08/19 ip.
- --8010080170 IE Insp Rept 50-944/80-20 on 800701→31. Noncompliance noted failure to follow procedure re decontamination of steam generator channel heads MALMROB.K H . JOHNSTON.Q W Region 5, San Francisco, Office of the Director. STERNBERG.D H. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/19. Spp
- 9010270507 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested ENGELKEN.R.H Region 5. San Francisco. Office of the Director 80/09/26. Ip
- 80:016:0038 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required ENGELMEN.R H Region 3, San Francisco, Office of the Director. 80:09:29.
- 8010280023 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required. EMOELKENR H. Region 5, Ban Francisco, Office of the Director 80/10/02. Ip
- 8010280498 Forwards response to NRC 800703 request for additinfo re IE Bulletin 80-ii. "Masonry Wall Design " Evaluation criteria for single & double withe & composite masonry walls, info on tornade loads & basis for omitting testing program encl WITHERS, B. D. Portland General Electric Co. 80/10/23 53pp.
- Q010300027 Forwards licenses response to IE Bullatin 80-11 re masonry wall design which discusses criteria for seismic loads re ABLB initial decision. Certificate of 8vc encl. JOHNSON.R.W. Portland Ceneral Electric Co. 80/10/23. Spp
- R. Periodic operating reports & related correspondence
- BOIO150438 Forwards monthly operating rept for Bept 1980. YUNDT.C.P Portland General Electric Co. 80/10/06. 1p.
- "--B010150449 Monthly operating rept for Sept 1980.
 BAIR, Q. Q. Portland General Electric Co. 80/10/06. App.

- 8 Reportable occurrences, LERs & related correspondence
- E010090163 PND-V-80-062 on 800731,NRC resident inspector was notified that State of OR resident inspector assigned to plant will resign effective today lob dissatisfaction & financial hardship resulting from family relocation cited, CREHB.J L, STERNBERG.D M Region 5, San Francisco, Office of the Director 80/07/31 1p
- 8010010064 Forwards util 800926 itr containing evaluation of NCR 8022 re masonry wall connections Corrective actions are being performed to repair wall panels & are scheduled for completion by Nov 1980

 JOHNSDM.R W Portland General Electric Co 80/09/26 3pp
- --8010010370 Forwards evaluation of nonconformance similar to LER 80-007.

 Suppl 1 Wall on column line 46 has capability to withstand implane & out-of-plane 88E loading conditions acceptably. Centificate of Svc encl BROEHL, D J Portland General Electric Co 80/09/26 7pp
- BO10060274 Forwards evaluation of nonconformance re masonry walls which was similarly described in Suppl 1 to LER 80-07 Wall panels described satisfy SBE criteria Corrective action will be completed by early Nov 1980 BROE
- BO10090339 Forwards LER 80-018/03L-0 YUNDT, C.P. Portland General Electric Co. 80/10/02 2pp
- --8010070344 LER BO-018/03L-O, on BO0703, during periodic testing, disseldriven auxiliary feedwater pump failed to start in response to manual start signal Caused by starting battery failure. Battery replaced. PERRY.J C Portland General Electric Co 80/10/02, 1p.
- E010140474 Advises that subsequent review of 800925 rept on incorrectly set high steam flow bistable trip setpoints, determined that event was not reportable per IOCFR50 72 Written followup rept will not be submitted YUNDT,C P Portland General Electric Co 80/10/06 ip.
- 8010160587 Notifies that review of facility 800924 occurrence re incorrect setting of high steam/flow bistable trip setpoints does not meet immediate rept criteria Followup rept will not be submitted Bleam flow transmitter calibr. Bistables reset YUKOT, C.P. Portland General Electric Co 60/10/06. ip.
- BO101503B3 RO followup to B01007 rept re situation where low-low steam generator water level for both auxiliary feedwater pumps was inoperable Deficiency immediately corrected & tested satisfactorily LER on occurrence will be submitted, YUNDT, C P Portland General Electric Co. B0/10/08. 1p
- E010210700 Forwards LER 80-020/01T-0 YUNDT, C P Portland General Electric Co 80/10/14, 2pp
- --8010210707 LER 80-020/01T-0 on 801003, following reactor trip, both trains of auxiliary feedwater pumps failed to respond to automatic start signal. Pumps were manually started. Caused by incorrectly wired slave relay.

 PERRYJ C Portland General Electric Co 80/10/14. is
- E010210742 Forwards LER 80-019/03L-0.
 YUNDT, C P Portland Quarat Electric Co 80/10/14. 2pp.
- --B010210748 LER 80-019/03L-0.on 800924, during verification of calculations, discovered that reactor trip setpoints for high steam flow were set incorrectly Gaused by error in vendor manual Setpoints properly set, Manual wil be changed. PERRY, J C Portland General Electric Co. 80/10/14. 1p.
- 8010210385 RO during period 801020-1112; diesel-driven fire pump will be inoperable during planned maint overheul Local fire district will station pumper truck at site during outage Rept forwarded per limiting condition of operation in Tech Specs.
 YUNDT; C. P Portland General Electric Co. 80/10/16. ip.
- DOCKET 30-346 DAVIB-BERBE NUCLEAR POWER BTATION, UNIT 1
 F Security, medical, emergency & fire protection plane
- 8010080179 Notifies that fire protection mode should be completed at end of current refueling outage. Requests revision of fire protection Tech Specs within 60 days. Fire protection BTB encl.
 REID.R.W. Operating Reactors Branch 4. 80/09/23 2pp.

- --8010080182 STS Sections 3 3.4 3.3 7 & 4 7 re fire detection instrumentation ** Operation Reactors Branch 4 79/06/15 15pp
- 8010060359 Requests withdrawal of revision to License Condition 2 C 3h re-completion date for fire protection mods CROUSE,R P Toledo Edison Co 80/09/30 1pp
- Q Adjudicatory correspondence
- 8010270298 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing. 80/09/19 2pp
- --8010270304 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EIBERHUT.D.O Division of Licensing 80/09/19 App
- H General correspondence
- 8010100346 Provides address correction for QH Dept of Health QUILLIN:R M Qhio, State of 80/10/01 1p
- J. Insurance & indemnity information
- B0102B0244 Requests Indomnity Agreement B-79
 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indomnity).
 80/09/24. ip.
- P Operating license stage documents & correspondence
- 8010090195 Reaffirms NRC position re TMI Lessons Learned short-term requirement 2 1 3 b. "Instrumentation for Detection of Inadequate Core Cooling," Guidelines re vessel water level must be developed to provide operators w/max support. ROBS, D. F. Division of Systems Integration 80/09/09. 3pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of THI action plan requirements. Corrected table of implementation schedule also enci. EISENNUT, D. O. Division of Licensing 80/09/19 28pp
- B0100B0179 Notifies that fire protection mode should be completed at end of current refueling outage Requests revision of fire protection Tech Specs within 60 days Fire protection STS encl.

 REID, R W Operating Reactors Branch 4 80/09/23. 2pp
- ---8010080182 8T8 Sections 3 3.4.3.3.7 & 4 7 re fire detection instrumentation.
 4 Operating Reactors Branch 4 79/06/15 13pp.
- 8010230417 Forwards evaluation of 80090B response to Lessons Learned Task Force Requirement 2 i.S.b re instrumentation for detection of inadequate core cooling. Insufficient effort provided re advance warning of inadequate core cooling. EISENHUT, D 0 Division of Licensing 80/09/24. 7pp.
- 8010080233 Forwards "Primary Reactor Containment Integrated Leakage Rate Test Rept " Containment vessel has been assessed as fully capable of performing intended function in plant operation.

 CROUBE.R P Toledo Edison Co 80/07/29. ip.
- --8010080239 "Primary Reactor Containment Integrated Leakage Rate Test Rept." * Toledo Edison Co. 80/08/29 112pp.
- 8010230589 Summary of 800821 meeting w/BLW reactor owners group re abnormal transient operating guidelines program. VISBING, G. Operating Reactors Branch 4. 80/09/30 29pp.
- G010160745 Forwards Amend 32 to License NPF-3 & notice of issuance & availability.
 REID:R.N. Operating Reactors Branch 4 80/10/01. 3pp.
- --8010160751 Amend 32 to License NPF-3, adding requirement to maintain safeguards contingency plan to be fully implemented within 30 days.

 REID, R.W. Operating Reactors Branch 4, 80/10/01. 2pp.
- --8010160757 Notice of issuance & availability of Amend 32 to License NPF-3. REID,R.H. Operating Reactors Branch 4. BO/10/01. 2pp

- B010210087 Forwards Amend 33 to License NPF-3, safety evaluation & notice of issuance & availability
 REID.R W Operating Reactors Branch 4 80/10/01 2pp
- --8010210070 Amend 33 to License NPF-3 modifying Tech Specs to permit operation for second cycle & to reflect changes in RCS high pressure & power operated relief valve setpoints REID.R W Operating Reactors Branch 4 80/10/01 58pp
- ~~8010210093 Safety evaluation supporting Amend 33 to License NPF-3 + Operating Reactors Branch 4 80/10/01 33pp
- --8010210099 Notice of Issuance & availability of Amend 33 to License NPF-3 REID-R W Operating Reactors Branch 4 80/10/01 2pp
- 8010140247 Application for amend to License NPF-3, providing Tech Specs for fire detection sys per License Condition 2 c(4) ROWLES, N.C., CROUSE, R.P. Toledo Edison Co. 80/10/07 3pp
- --8010140249 Proposed Tech Specs 3 3 3 8 & 4 3 3.8 re fire detection instrumentation * Toledo Edison Co 80/10/07 5pp
- 8010290327 Requests submittal of fees for review of 800304.790328 & 0721/0804 applications for mod of license & Tech Specs MILLER.W C License Fee Management Branch 80/10/14 1p
- B010310311 Advises that Tast Case 12121 re monitoring bus voltages during reactor coolant pump motor start cannot be performed until 790323 request for undervoltage circuit bypass is approved CROUSE, R.P. Toledo Edison Co 90/10/27 19
- G Inspection reports. IE Bulletins & correspondence
- BOIO210019 Provides updated info re admittance of Region 3 personnel to facilities. Forwards lists of personnel for whom permanant nonemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/09/03 488
- 8010030288 Responds to IE Bulletin 60-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " No switches installed at facility CROUSE,R.P. Toledo Edison Go 80/09/12 2pp
- B010020070 Ack receipt of 800826 ltr informing NRC of steps taken to correct violations nated in IE Insp Rept 50-346/80-18
 KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/09/15.
 1p.
- --8010020075 Responds to NRC 800717 1tr re violations noted in IE Insp Rept 30-446/80-18 Corrective actions withheld (ref 10CFR2 790) CROUSE,R P Toledo Edison Co 80/08/26 1p
- B010100225 Ack receipt of B00902 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-346/80-19.
 HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/09/19 lp
- --8010100228 Responds to NRC 800812 ltr re violations noted in IE Insp Rept 90-345/80-19. Corrective actions personnel performing surveillance testing of fire extinguishers were reinstructed as to proper documentation methods CROUSE, R. P Toledo Edison Co 80/09/02 4pp.
- 8010150295 Forwards response to IE Bulletin 80-18 re maint of adequate min recirculation flow for HPIS pumps Concern identified not applicable as pumps used for HPIS are equipped w/min recirculation line, containing restriction orifice CROUSE, R P. Toledo Edison Co. 80/09/20 4pp
- 8010270463 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested KEPPLER.J g Region 3, Chicago, Office of the Director 80/09/25, is
- B010160254 Forwards Suppl 2 to IE Sullatin 79-018, "Environ Qualification of Class IE Equipment," No written response required
 KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/09/30

- 8010280084 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required KEPPLER.J 9. Region 3, Chicago Office of the Director 80/10/02 1s
- B010230049 Forwards IE Insp Rept 50-346/80-26 on B00909-i2 & notice of violation Notice of violation & details withheld (ref 10CFR2 790) HIND, J & Region G. Chicago, Safeguards Branch B0/10/09. 2pp
- --80(0230056 IE Insp Rept 50-346/80-26 on 800909-12. Noncompliance noted two vital areas unsecured 8 hand-carried package searches not performed Details withheld (ref 100FR2 790). HIND, J A Region 3, Chicago, Bafeguands Branch HADEDA, T. J. PIRTLE, G L. Region 3, Chicago, Office of the Director 80/10/06
- 8010290029 Forwards IE Info Notice 80-36, "Feilure of Steam Generator Support Bolting " No specific action or response requested. KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010150321 Forwards monthly operating rept for 8ept 1980 MURRAY, T. D. Toledo Edison Co. 80/10/08 1p
- --8010150323 Monthly operating rept for Sept 1980 SARSOUR, B Toledo Edison Co 80/10/08 13pp
- S Reportable occurrences, LERs & related correspondence
- 80070B0216 PNO-III-B0-137 on 900724.blown fuse caused Valve DH-12 on suction side of operating decay heat removal pump to close. Shutdown cooling flow to reactor lost Valves in bypass line around DH-12 opened, line vented & flow re-established. REYES, L., WARNICK, R., HEIBHMAN, R.F. Region G. Chicago, Office of the Director. EO/07/24 ip
- B0100B0347 PND-III-B0-142 on B00730, Dfc & Professional Employees will be honored by other craft unions including employees. Shift requirements for operations personnel heve been met REYEB, L. A. WARNICK, R. F. HEISHMAN, R. F. Region 3, Chicago, Office of the Director B0/07/31 2pp
- 8010020372 RC NP-09-80-01 on 800116 % 0210, discharge temp for liquid effluents exceeded 20 F above lake temp due to procedural deficiencies Cooling tower was operated in bypass mode causing temp to elevate above normal temp during startup. MURRAY, T D Toledo Edison Co 80/09/09 3pp
- B010010512 Forwards LER 80-067/03L-0 MURRAY, T D Toledo Edison Co 80/09/29 ip
- --8010010513 LER 80-067/03L-0 on 800829, while in Mode 5, main steam isolation bypacs valve MS101A failed Caused by failed solenoid valve operator SV101-1, Bolenoid replaced IBLEY, T Toledo Edison Co 80/09/26 2pp
- 8010010591 Forwards LER 80-066/03L-0 MURRAY.T D. Toledo Edison Co 80/09/29 ip
- --8010010597 LER 80-066/03L-0 on eight occasions between 800827 & 800920.
 doors were found open resulting in reduced capacity of
 emergency ventilation sys to meintein spent fuel pool area
 at required negative pressure Gaused by personnel error
 (MELSTAD.K. Toledo Edison Co. 80/09/26, 3pp
- 8010030445 Forwards LER 80-068/03L-0 MURRAY, T. D Toledo Edison Co 80/09/29 ip.
- --8010030451 LER 80-068/03L-0 on 800901, all indicators for meteorological instrumentation failed Caused by lightning striking tower, resulting in high voltage spike in wind direction sensor Repairs to tower sensors and Comstar computer completed ELDRED, D T. Toledo Edison Co. 80/09/29. 2pp
- H010070492 Forwards LER H0-069/03L-0 MURRAY, T. D. Teledo Edison Co. H0/10/02 1p.
- --9010070505 LER 80-069/03L-0 on 800902 during diesel generator 1-1 ofl change, bolt fragment discovered in crenkcase sump. Caused by loose bolts in idler gear to support spider of turbocharger spring drive assembly, Modified assembly installed, ADAMS, J. Toledo Edison Co. 80/10/02, 2pp.

- B010070451 Forwards LER 80-070/03L-0 MURRAY, T D Toledo Edison Co 80/10/03 1p
- --8010070458 LER 80-070/03L-0 on 800828, during weekly diesel fuel pump test ST 5016 01, diesel fuel pump failed to start at required 95 paig Caused by broken pressure switch Switch repaired & recalibrated FROHNE, R Toledo Edison Co 80/10/03 3pp
- 8010200436 Forwards LER 80-063/03L-1 MURRY, T D Toledo Edison Co 80/10/07 ip
- --B010200439 LER 80-063/03L-1 on B00B23.safety features actuation sys indication panel for damper HV3442 was inoperable Caused by blown fuse in control circuit Fuse replaced & sys returned to svc THMPBBON.T Toledo Edison Co B0/09/18 2pp
- 0010200444 Forwards revised LER 80-035/03L-1 MURRAY, T D Toledo Edison Co 80/10/07 1
- --B01020044B Revised LER 80-035/03L-1 on B00410, decay heat removal valve DH14A would not open beyond 20% Caused by radial arm of valve operator linkage moving slightly sideways & contacting bolt Radius arm readjusted HAKATURA;L Toledo Edison Co B0/05/07 2pp
- 8010270387 Forwards LER 80-071/03L-0 MURRAY.T D Toledo Edison Co 80/10/21 ip
- --B0102703BB LER 80-071/03L-0 on 800923, fire discovered in exhaust chamber of diesel generator 1-2 Caused by component failure resulting in turbocharger failing & releasing lubricating oil into exhaust chamber Turbocharger replaced SYSLO. J Toledo Edison Co 80/10/21 3pp
- 8010310460 Forwards revised LER 80-021/03L-1 MURRAY.T. D Toledo Edison Co 80/10/21 1
- --B0103:0466 Revised LRT 80-021/03L-1 on 800313.diesel fire protection pump could not be stopped at local control panel Cause undetermined Pump successfully restarted & stopped FROHNE, R Toledo Edison Co 80/04/10 2pp
- DOCKET 50-348 JOSEPH H FARLEY NUCLEAR PLANT, UNIT 1
- D NRC Braft/Final Environmental Statements, suppls & correspondence
- 8010160785 Addendum to FES for facility # Office of Nuclear Reactor Regulation, Director. NUREG-0727 ADD 80/09/30 54pp Available at NTIS \$3 50
- F Security, medical, emergency & fire protection plans
- BO10090460 Notification of BO0B19 meeting w/util & Dechtel in Bethesda. MD for working session on facility fire protection REEVES.E A Operating Reactors Branch i 80/0B/19 ip.
- 8010140351 Forwards status of fire protection program mods for review Discussion of second refueling outage schedule provided CLAYTON, F.L. Alabama Power Co., 80/10/07 3pp
- 8010280497 Notifies that proposed Mod Summary, Table 3 of Amend 11 to License NPF-2 has been incorporated into facility fire protection mod program Supersedes 770319 ltr. CLAYION:F. L. Alabama Power Co. 80/10/21 ip
- H. General correspondence
- BDIG210675 Responds to 800410 ltr re high costs & media access to onsite & offsite emergency operations facility. Access Elmited due to need for prompt reporting from technical personnel Public meeting re emergency facility planned. GRIMES.B.K. Emergency Preparedness Program Office. 80/07/29 2pp
- --8010210681 Comments on emergency planning costs & media access to obsite & offsite emergency facility.
 CHADWICK.J Affiliation Unknown. H0/04/10. 1p.
- J. Insurance & indemnity information
- 8010310567 Amend 7 to Indemnity Agreement R-Si.deleting Item 3 & aubstituting license numbers.

 8ALTZHAN.J Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/27 1p.

- P Operating license stage documents & correspondence
- 8010010188 Ack response to NRC 791107 1tr re ECCS evaluation models dealing u/fuel cladding swelling & incidence of rupture Response acceptable & no further action necessary VAROA-8 A Operating Reactors Branch i 80/09/12 2pp
- 8010220099 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENNUT,D G Division of Licensing 80/09/19 28pp
- B010060325 Forwards proprietary & nonproprietary versions of elevation dependent peaking factor vs core height graph, supporting B00815 Tech Spec change Application for withholding encl Proprietary version available in Central Files only CLAYTON.F.L. Alabama Power Co. 80/09/25 14pp
- 8010140467 Advises that Tech Spec Table 3 7-4 re safety-related snubbers will be revised as result of efforts to resolve concerns identified in IE Bulletins 79-02 & 79-14 Revised Tech Specs will be submitted by 801101 CLAYTON-F L Alabama Power Co 80/10/03 ip
- 8010300614 Forwards "Evaluation of Control Rod Guide Tube Thimble Wear in Facilities Designed by Westinghouse " Issue resolved for 17x17 fuel assemblies designed by Westinghouse for facility VARQA.8 A Operating Reactors Branch I 80/10/03 Jpp
- 8010140305 Forwards comments we TMI action plan requirements' preliminary clarification per addendum to NRC 800905 ltr & 800926 meeting Substantial change to requirement criteria would affect current implementation schedules W/o encl CLAYTON.F.L. Alabama Power Co 80/10/06 IV
- B010280487 Notifies that proposed Mod Bummary, Table 3 of Amend 11 to License NPF-2, has been incorporated into facility fire protection mod program Bugersedes 770317 ltr CLAYTON:F L Alabama Power Co 80/10/21 1p
- G Inspection reports, IE Bulletins & correspondence
- B010230072 Forwards IE Info Notice 80-32. "Charification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/29 2an
- B010240641 Forwards IE Insp Repts 50-348/80-23 & 50-364/80-30 on B00814-15 No nancompliance noted. MURPHY: C E Region 2: Atlanta: Reactor Construction & Engineering Bupport Branch B0/09/11 2pp
- --8010240463 IE Insp Repts SD-348/80-23 t SD-364/80-30 on 800814-15.

 No noncompliance noted Major areas inspected followup of noncompliances & inspector followup items re Part 21 evaluation & reporting matters 8RONNEE, V L. Region 2, Atlanta, Office of the Director CONLONIT E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/09 3pp
- 8010010438 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-14 & 50-364/80-16 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 80/09/12 Zpp
- --B010010676 Response to NRC 800808 ltr re violations noted in IE Insp Repts 50-348/80-14 & 50-345/80-16. Corrective actions, interim measures implemented until qualified storage space is found. OA sudit program revised for reaudit of corrective actions CLAYTON.F L. Alabama Power Co. 80/09/02 3pp
- 8010090287 Requests extension until 800924 to respond to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches." Extension is needed due to licensing & refueling activities.

 CLAYTON.F L. Alabama Power Co. 80/09/16, ip
- 8010060148 Ack receipt of 800911 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-348/80-21.

 KENNA, W. B. Region 2. Atlanta. Safeguards Branch 80/09/17 ip
- --8010060152 Forwards response to NRC 800818 itr re violations noted in IE Insp Rept 50-348/80-21 Corrective actions withheld (ref 10CFR2.790), CLAYTON.F L Alabama Power Co 80/09/11. ip.

- --B010060156 Forwards IE Insp Rept 50-348/80-21 on 800726-31 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA,W B Region 2. Atlanta, Safeguards Branch 80/08/18 2pp
- --8010040158 IE Insp Rept 90-348/80-21 on 600726-31 Nancompliance noted members of security force not properly qualified to perform security functions
 MODRE, D. E. HOWELL, J. C. Region 2, Atlanta, Office of the Director KCGUIRE, D. R. Region 2, Atlanta, Safeguards Branch 80/08/18
 1p
- 8010100126 Forwards response to IE Bulletin BO-18, "Maint of Adequate Min Flow Thru Centrifugal Charping Pumps Following Secondary Site High Energy Line Rupture." Min flowrate of 60 gpm required for pump operation could not be guaranteed CLAYTON:F L Alabama Power Co 80/09/23 Spp
- 8010100133 Forwards response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Normal Control Suitches " Total of 67 switches in Unit 1 & 49 switches in Unit 2 Identified in safety-related sys CLAYTON, F. L. Alabama Power Co. 80/09/24 15pp
- 8010270493 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested O'REILLY:J P Region 2. Atlanta. Office of the Director 80/09/26
- 8010160212 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30 ip
- 8010270578 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 to
- 8010240115 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-349/80-24 & 50-349/80-31 STGHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/06 ip
- --8010240134 Responds to NRC 800711 ltr re violations noted in IE Insp Repts 30-348/80-24 & 50-364/80-31 Corrective actions parsonnel in chemistry section have been reinstructed in requirement of AP-1 & AP-7 CLAYION.F L Atabama Power Co 80/09/26 2pp
- --8010240146 Forwards IE Insp Repts 50-348/80-24 & 50-364/80-31 on 800812-14 & notice of violation 8TOHR.J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/09/11 2pp.
- -8010240154 Notice of violation from Insp on 800812-14.
 * Region 2, Atlanta, Office of the Director 80/09/11 ip
- --8010240174 IE Insp Repts 50-348/80-24 & 50-364/80-3; on 800812-14 Noncompliance noted failure to review changes in Chemistry Procedure FNP-0-CPP-4.determination of fluoride ion in aqueous solutions HONTOOMERY.D.M. Region 2. Atlanta, Office of the Director STOHR.J P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/09/11. 8pp
- 8010270049 Forwards IE Info Notice 80-36, "Failure of Steam Generator Bupport Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/10
 - Periodic operating reports & related correspondence
- 010210402 Forwards monthly operating rept for Sept 1780 CLAYTON, F.L. Alabama Power Co. 80/10/15. 1p
- --8010210406 Monthly operating rept for Sept 1980. HAIRSTON W. G. Alabama Power Co. 80/10/01 7pp
- S. Reportable occurrences: LERs & related correspondence
- 8010140798 PNG-II-80-105:on 800611.steam penerator tube leak of 95 gallons per fay was identified in B steam generator. Upward leak rate trend existed for 30 days Licensee plans to shut down prior to reaching leak rate of 500 gailons per day.

 GUICK.D Region 2, Atlanta, Office of the Director 80/06/11

- B010080610 PND-fI-80-108 on 800614, plant was shut down due to steam generator tube leakage Unit presently in cold shutdown condition DDNAT,T J , MARTIN.R D Region 2, Atlanta, Office of the Director 80/06/16 Ip.
- 8010160530 PNO-II-80-132 on 800729, oil leak developed on turbine governor valve While ramping power down, main feedwater pump tripped & reactor tripped on low steam generator level ECCS dld not actuate & plant sys functioned as designed DDNAT,TJ . LEWIS.R C Region 2. Atlanta, Office of the Director 80/07/30 ip
- 8010070414 Forwards LER 80-053/03L-0 CLAYTON, F.L. Alabama Power Co. 80/09/29 1p
- --B010070621 LER 80-053/03L-0 on 800907, during serveillance testing, containment spray automatic actuation logic declared inoperable Caused by integrated circuit failure Circuit card replaced & logic returned to svc HAIRSTON, W Q Alabama Power Co 80/09/29 Ip
- 8010080452 Forwards LER 80-054/01T-0 CLAYTON, F. Alabama Power Co 80/10/03 1p
- --80j0080457 LER 80-054/017-0 on 800919, investigation revealed that during June 1979 containment equipment access hatch bolts had been evertorqued Caused by technical manual error Technical manual spees changed & bolts, nuts & pins replaced HAIRSTON, W O Alabama Power Co 80/10/03 2pp
- 8010210718 Forwards LERs 80-055/03L-0 & 80-056/03L-0 CLAYTON F, L Alabama Power Co 80/10/15 1p
- --8010210726 LER 80-055/03L-0 on 800910, during surveillance testing, 1A reactor coolant pump bus train B undervoltage relay was declared inoperable due to incorrect trip value Caused by as-left condition following previous surveillance HAIRSTON, W O Alabama Power Co 80/10/15 1p
- --8010210731 LER 80-056/03L-0 on 800911, svc water bldg A train battery sys was declared inoperable due to low battery cell specific gravity Caused by close terminal post proximity & poor terminal post seal design which caused acid leakage HAIRBTON, W. O Alabama Power Co 80/10/15 19
- 8010280462 Forwards LER 80-057/03L-0 CLAYTON, F. L. Alabama Power Co. 80/10/22 1p
- --B010280502 LER 60-057/03L-0 on 800922, during startup.RHR sys was removed from svc & isolated from RCS at 250 F Caused by operator error Tech Bpecs changed to clarify svc procedure HARRSTON.W O Alabama Power Co 8D/10/22 ip
- DOCKET 50-352 LINERICK GENERATING STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 7902090343 Forwards QE topical rept NEDD-24010-2, Suppl 2, "Bases for Criteria for Combination of Earthquake & Other Transient Responses by the Square-Root-Sum-Of-The-Squares Method "Rept is provided on behalf of Mark 2 owner's group SOBON.L. J. General Electric Co., Nuclear Energy Products Div 79/02/05 ip,
- --7902090367 Suppl 2 "Basis for Criteria for Combination of Earthquake & Other Transient Responses By the Square-Root-Sum of The Squares Method " Discusses method for combining multiple peak dynamic responses for blasts & earthquakes KENNEDY:R P . NEWMARK:N M . ENOLISH.W F General Electric Co NEDD-24010-2-01 78/12/31 30pp
- 80:0090475 Summary of 800805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads.
 Discussion topics, attendance & meeting handouts and!
 ANDERSON.C J Generic Issues Branch. 80/08/27 98pp
- 8010170247 Notification of 801002 meeting w/util in Bethesda,MD to discuss status of risk evaluation status, SELLS,D. Licensing Branch 2 80/09/09 2pp.
- 8010060102 Summary of 800704-05 meeting w/Mark II owners in Bethesda.MD re long-term program chugging & lateral loads.Attendance list & handouts encl ANDERSON.G.J Generic Issues Branch 80/09/12 65pp.

- 8010270238 Notification of 801008 meeting 4/representatives from Mark II owners group in Bethesda.MD to discuss Mark II plants chugging load spec ANDERSON.C. Generic Issues Brench 80/09/22 ip
- BO10070339 Responds to NRC request for info re implementation of TMI-2 action plan requirements initiation levels of HPCI & RCIC sys should be separated so that RCIC sys will initiate higher water level than HPCI sys QALLAQHER.J W Philadelphia Electric Co BO/10/02 6pp
- BO10090333 Forwards meteorological data tape used for probabalistic risk assessment for 1972-76, in response to NRC request at B01002 meeting re preliminary risk assessment W/o encl BOYGR.V B Philadelphia Electric Co B0/10/07 2pp
- \$010300443 Forwards NRC position re application of cladding swelling & rupture models for LOCA analysis Requests util provide supplemental calculations TEDESCO, R L Assistant Director for Licensing 80/10/07 3pp
- BO10150388 Responds to NRC 801002 request for outline of final rept re preliminary risk assessment Rept available by Apr 1981. Bupporting info used in analysis, including fault & event trees & QE & Bechtel plant drawings, available Nov 1980 BOYER, V 8 Philadelphia Electric Co 80/10/10, 4pp
- B010310521 Trip rept of B00513 visit to tour const site & containment & control room, Discussions hald re emergency planning & preparedness: Significant design difference included use of eight row of rebar SELLED Deprating Reactors Branch 2 80/10/20 4pp
- 8010310103 Notification of 801030 meeting w/0E in 8an Jose CA to discuss info requirements needed to conduct review of risk evaluation study BELLS:D Licensing Branch 2 80/10/22 3pp
- GO10280372 Forwards OE svaluation of proposed mod to HPCI & reactor core isolation cooling sys on behalf of BWR owners group Concurs w/owners group assessment that setpoint changes will gield minimal reduction in thermal cycle history OALLACHER, J. W Philadelphia Electric Co EO/10/24 7pp.
- F. Security, medical, emergency & fire protection plans
- B010160316 Requests encl facility emergency planning info be made available to public in LPDR room W/o encl BDUDER, J.L. Division of Rules and Records 80/10/02 1p
- H Quneral correspondence
- GO10220304 Responds to B00903 ltr re const of nuclear plant near populated areas. NRC decision to license facility will be based on environ review.emergency planning & lessons learned from TM1-2 accident INORAM F L. Office of Public Affairs 80/09/17 ip.
- --B010220309 Opposes issuance of CP to nuclear plants near populated areas. Expresses safety concerns to operation of facility & suggests alternative forms of energy BANIELB, J. A. Affiliation Unknown B0/09/03. ip.
- 8010280063 Responds to 800801 ltr re quarry blasting at site.NRC plans to investigate as-built structures to determine any detrimental effects Applicant will conduct survey to establish existence of excessive cracks.W/o relevant info. EISENHUT, D.Q. Division of Licensing, 80/10/09 2pp.
- --B010280070 Responds to NRC 791009 promise to forward info re effect of quarry blasting at site.NRC should not rely on util for info.Requests supportive info to determine if foundation under reactor bldg is adequate ROMANO.F.R. Air and Water Pollution Patrol 80/08/01 4pp
- Q Inspection reports: IE Bulletins & correspondence
- B010010625 Forwards IE Insp Repts 50-352/80-10 & 50-353/80-09 on 800317-20 No noncompliance noted.
 CARLSON:R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/28. 2pp.

- --8010010632 IE Insp Repts 50-352/80-10 t 50-353/80-09 on 800317-20
 No noncompliance noted Major areas inspected allegation
 that personnel were instructed to deviate from Bechtel
 procedures in primary containment
 MATTIA, J C , REMAKLUSt, Region 1, Philadelphia, Office of the
 Director MCGAUGHY, R W Region 1, Philadelphia, Reactor
 Construction & Engineering Support Branch 80/07/24 7pp
- 8010020239 Ack receipt of 800730 1tr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-352/79-12 & 50-353/79-11 GRIER.B H Region 1. Philadelphia, Office of the Director
- --B010020253 Responds to NRC 800628 ltr re violation noted in IE Insp Repts 50-352/79-12 & 30-353/79-11 Corrective actions future subcontractors will establish in writing OA program responsibility.effective BIO410 KEMPER.J S Philadelphia Electric Co B0/07/30 2pp
- B010100062 Forwards IE Insp Repts 50-352/80-15 & 50-353/80-13 on B00805 & 07-08 No noncompliance noted CARLEON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/08/21 2pp
- --B010100074 IE Insp Repts 50-352/80-15 & 50-333/80-13 on 800805 & 07-08
 No noncompliance noted Major areas inspected safety-related
 pipe welding in process, completed safety-related pipe
 welding & filter metal control sys.
 REYNOLDB, S D Region i, Philadelphia, Office of the Director
 TRIPP, L E Region i, Philadelphia, Reactor Construction &
 Engineering Support Branch 80/08/28 5pp
- 8010020117 Responds to IE Bulletin 80-19 Mercury-wetted relays are not used or planned for use in reactor protection sys KEMPER.J B Philadelphia Electric Co 80/08/26 ip
- 8010020197 Responds to IE Bultetin 80-to re Rosemount Models 1151 & 1152 pressure transmitters Transmitters have been installed in safety related applications Extension of time requested for complete response to bulletin KEUPER.J. 8 Philadelphia Electric Co 80/08/26 ip
- 8010010840 Responds to IE Bulletin 80-20 Na Westinghouse Type W-2 control switches are used or planned for use in safety-related applications KEMPER.J B Philadelphia Electric Co 80/09/10 ip
- 80:00:0848 Responds to IE Bulletin 80-16 re Rosemount Model 1:51 & 1:52 pressure transmitters Requests change for submittal of response to 80:001 KEMPER, J S Philadelphia Electric Co 80/09/10 ip
- BO10100024 Forwards Page 11 to IE Insp Repts 50-352/B0-12 & 30-353/B0-10 which may have been inadvertently emitted CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/09/15 2pp
- 80i0100092 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-352/80-04 & 50-353/80-04 CARLEGON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 1p
- --B010100094 Responds to NRC 800610 ltr re violations noted in IE Insp Repts 80-352/80-04 & 50-353/80-04 Util unable to submit amend to facility PSAR per 800710 commitment until 800924. REMPERIU B Philadelphia Electric Co 80/08/25. 19
- 8010140048 Ack receipt of B00826 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-08 & S0-353/80-07 GARLEON&R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --8010140054 Responds to NRC 800724 ltr re violations noted in IE Insp Repts 50-382/80-08 & 80-353/80-07 Corrective actions. training class was held 800612 for all discipline GC engineers stressing proper review of insp criteria KFMPER, J 8 Philadelphia Electric Co 80/08/26. 4pp
- --8010140056 Forwards IE Insp Repts 50-352/80-08 & 90-353/80-07 on 800501-30 & notice of violation CARLBOM,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/24 2pp
- --8010140099 Notice of violation from insp on 800501-30 * Region 1. Philadelphia, Office of the Director 80/07/18. 2pp.

- --8010140063 IE Insp Repts 50-352/80-03 & 50-353/80-07 on 800501-30 Noncompliance noted failure to perform insp of welds in process failure to provide document control & failure to inspect latest design documents

 MATTIA, J C Region 1, Philadelphia, Office of the Director KCOAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch BO/07/18 9pp
- 8010230710 Ack receipt of 800610 & 0703 ltrs informing NRC of steps taken to correct violations roted in IE Insp Repts 50-352/80-t2 & 50-353/80-t1 CARLS0/R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/26 1p
- --B0102307fi Responds to NRC 800312 ltr re violations noted in IE Insp Repts 50-352/B0-12 & 50-353/B0-11 Corrective actions memorandom issued directing that no matl substitutions be made to permanent plant hangers u/o prior approval KEMPER.J B Philadelphia Electric Co 80/07/03 lp
- --8010230713 Responds to NRC 800312 ltr re violations noted in IE Insp Repts 50-352/80-12 & 50-353/80-11 Corrective actions visual insp of installed pipe support pins will be extended to areas containing C-listed pipe supports KFMPER.J S Philadelphia Electric Co 80/06/10 4pp
- 8010230191 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosembunt.Inc Models 1151 & 1152 Pressure Transmitters w/
 Either A or D Output Godes " GE analysis will be delayed approx & wis Status rept will be sent by 810130
 KEMPER.J S Philadelphia Electric Ca 80/10/01 1p
- 8010240158 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER.8 H Region 1. Philadelphia. Office of the Director 80/10/02 | 1p
- 8010280168 Forwards [E Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested GRIER,8 H Region 1, Philadelphia, Office of the Director 80/10/10 1p
- S Reportable occurrences. LERs & related correspondence
- 8010010623 Interim rept for potential Bignificant Deficiency 16 re ASME bolts, nots & study obtained from unapproved sources Bolting mattle procured from manufacturers w/o Bechtel approved GA program Will swimit further rept KEMPER, J S Philadelphia Electric Co 80/09/25 2pp.
- U Congressional/Executive Correspondence
- 8010270141 Forwards USGS 800725 rept & util Jul 1980 rept re effects of quarry blasting on facility DIRCKS.N J Office of the Executive Director for Operations 80/10/21 2pp
- DOCKET 50-353 LIHERICK GENERATING STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 7902090343 Forwards OE topical rept NEDD-24010-2. Buppl 2, "Bases for Criteria for Combination of Earthquake & Other Transient Responses by the Square-Root-Sum-Of-The-Squares Method "Rept is provided on behalf of Mark 2 owner's group SORON, L J General Electric Co , Nuclear Energy Products Div 79/02/05 ip
- -7902090367 Suppl 2 "Basis for Criteria for Combination of Earthquake & Other Transient Responses By the Square-Root-Bum of The Squares Mathod "Discusses mathod for combining multiple peak dynamic responses for blasts & earthquakes. KENNEDY.R P. NEUMARK.N M. ENGLISH.W F General Electric Co. NEDD-24010-2-01 78/12/31. 30pp
- 010090475 Summary of 800805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads Discussion topics, attendance & meeting handouts encl ANOERBON, C J Generic Issues Branch 80/08/29 98pp
- 10170247 Notification of 801002 meeting w/util in Bethesda. MD to discuss status of risk evaluation status BELLS.D Licensing Branch 2 80/09/09 2pp.
- OOAO102 Summary of 800704-05 meeting w/Mark II owners in Bethesda. MD riong-term program chugging & lateral loads. Attendance st & handouts enci.

 'DERSON.C.J Generic Issues Branch 80/09/12 65pp

- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D 0 Division of Licensing 80/09/19 28pp
- B010270239 Notification of 801008 meeting w/representatives from Mark II owners group in Bethesda.MD to discuss Mark II plants chugging load spec ANDERBON.C Generic Issues Branch 80/09/22 ip
- B010070337 Responds to NRC request for info re implementation of TMI-2 action pian requirements Initiation levels of HPCI & RCIC should be separated so that RCIC sys will initiate higher water level than HPCI sys OAL! AC
- 8010090333 Forwards meteorological data tape used for probabalistic risk assessment for 1972-76, in response to NRC request at 801002 meeting re-preliminary risk assessment W/o encl 80YER, V 8 Philadelphia Electric Co 80/10/07 2pp
- 8010300443 Forwards NRC position re application of cladding swelling & rupture models for LOCA analysis Requests util provide supplemental calculations TEDESCO.R L. Assistant Director for Licensing 80/10/09 3pp
- 8010150388 Responds to NRC 801002 request for outline of final rept re preliminary risk assessment Rept available by Apr 1981 Supporting info used in analysis including fault & event trees & GE & Bechtel plant drawings available Nov 1980 BOYER, V S Philadelphia Electric Co 80/10/10 4pp
- 8010310521 Trip rept of 800513 visit to tour const site & containment & control room Discussions held re emergency planning & preparedness Significant design difference included use of eight row of rebar SELLS, D Operating Reactors Branch 2 80/10/20 4pp
- B010310103 Notification of 801030 meeting w/OE in Ban Jose,CA to discuss info requirements needed to conduct review of risk evaluation study SELLB,D Licensing Branch 2 80/10/22 3pp
- 8010280372 Forwards OE evaluation of proposed mod to HPCI b reactor core isolation cooling sys on behalf of BWR owners group Concurs w/owners group assessment that setpoint changes will yield minimal reduction in thermal cycle history OALLAGMER, J W Philadelphia Electric Co 80/10/24 7pp
- F Security, medical, emergency & fire protection plans
- 8010160316 Requests encl facility emergency planning info be made available to public in LPDR room W/o encl SDUDER, J L Division of Rules and Records 80/10/02 1p
- H General correspondence
- 8010220304 Responds to 800903 ltr re const of nuclear plant near populated areas NRC decision to license facility will be based on environ review emergency planning & lessons learned from TMT-2 accident INGRAM, F.L. Office of Public Affairs 80/09/17 lp
- --8010220307 Opposes issuance of CP to nuclear plants near populated areas Expresses safety concerns re operation of facility & suggests alternative forms of energy DANIELS.J A Affiliation Unknown 80/09/03 ip
- 8010280043 Responds to 800801 ltr re quarry blasting at site NRC plans to investigate as-built structures to determine any detrimantal effects. Applicant will conduct survey to establish existence of excessive cracks W/o relevant info EISEUMUT, D O Division of Licensing 80/10/09 2pp
- ~-8010280070 Responds to NRC 791009 promise to forward info re effect of quarry blasting at site NRC should not rely on util for info. Requests supportive info to determine if foundation under reactor bidg is adequate ROMANO, F. R Air and Water Pollution Patrol 80/08/01 4pp.
- @ Inspection reports. IE Sulletins & correspondence
- 8010010625 Forwards IE Insp Repts 50-352/80-10 & 50-353/80-09 on 800317-20 No noncompliance noted CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/28 2pp

- --B010010632 IE Insp Repts 50-352/80-10 & 50-353/80-09 on B00317-20 No noncompliance noted Major areas inspected allegation that personnel were instructed to deviate from Bechtel pracedures in primary containment MATTIA.J C., REMAKLUS.L. Region 1, Philadelphia. Office of the Birector MCGAUGHY, RV Region 1, Philadelphia. Reactor Construction & Enginee ing Support Branch 80/07/24 7pp
- 8010020737 Ack receipt of 800730 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-352/79-12 & 50-353/79-11 ORIER.9 H Region 1. Philadelphia, Office of the Director 80/08/21 ip
- --8010020253 Responds to NRC 800628 ltr re violation noted in IE Insp Repts 50-352/79-12 % 50-353/79-11 Corrective actions future subcontractors will establish in writing OA program responsibility effective 810410 KMMPER, J S Philadelphia Electric Co 80/07/30 2pp
- 8010100062 Forwards IE Insp Repts 50-352/80-15 & 50-353/80-13 on 80805 & 07-08 No noncompliance noted CARLSUN, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --B010100074 IE Insp Repts 50-392/80-15 & 50-393/80-13 on 800805 & 07-08.

 No noncompliance noted Major areas inspected safety-related pipe welding in process, completed safety-related pipe welding & filler metal control sys

 REYNOLDS, S D Region i, Philadelphia, Office of the Director TRIPP, L E Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/28 Spp
- B010020117 Responds to 1E Bulletin 80-19 Mercury-wetted relays are not used or planned for use in reactor protection sys
 KEMPER. J 8 Philadelphia Electric Co 80/08/26 ip
- 8010020197 Responds to IE Bulletin 80-16 re Rosemount Hodels 1151 & 1152 pressure transmitters Transmitters have been installed in safety related applications Extension of time requested for complete response to bulletin KEKPER, J. 8 Philadelphia Electric Co. 80/08/26 ip
- 8010010840 Responds to IE Bulletin 80-20 No Westinghouse Type W-2 control suitches are used or planned for use in safety-related applications KEMPER.J B Philadelphia Electric Co 80/09/10. 1p
- BO10010848 Responds to IF Bulletin 80-16 re Rosemount Model 1151 & 1152 pressure transmitters Requests change for submittal of response to BO1001 KEMPER, J. 8 Philadelphia Electric Co 80/09/10. ip
- 8010100024 Forwards Page 11 to IE Insp Repts 50-352/80-12 & 50-353/80-10 which may have been inadvertently omitted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 2pp
- 8010100092 Ack receipt of 800825 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-04 & 50-353/80-04 CARLSDIR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --8010100074 Responds to NRC 800610 ltr re violations noted in IE lnsp Repts 50-352/80-04 & 50-332/80-04 Util unable to submit amend to facility PSAR per 800710 commitment until 800724 KEMPER, J S Philadelphia Electric Co 80/08/25. ip
- 8010140048 Ack receipt of 800826 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-08 & 50-353/80-07 CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 lp
- --B010140054 Rasponds to NRG 800724 ltr re violations noted in 1E Insp Repts 50-352/80-08 & 50-353/80-07 Corrective actions. training class was held 800612 for all discipline GC engineers stressing proper review of insp critaria XEMPER.J 8 Philadelphia Electric Co 80/08/26. 4pp.
- --8010140056 Forwards IE Insp Repts 50-352/80-08 & 50-353/80-07 on 800501-30 & notice of violation CAPL80N:R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/24 2pp
- --80:0140059 Notice of violation from insp on 800501-30.

 **Region 1, Philadelphia, Office of the Director. 80/07/18 2pp.

- --8010140043 IE Insp Repts 50-352/80-08 & 50-353/80-07 on 800501-30 Noncompliance noted failure to perform insp of welds in process, failure to provide document control & failure to inspect latest design documents

 MATTIA. J C Region 1. Philadelphia. Office of the Director MGGAUGHY, R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/18 9pp
- 8010230710 Ack receipt of 800610 & 0903 itrs informing NRC of steps taken to correct violations noted in IE Insp Regts 50-352/80-12 & 50-352/80-11 & 50-352/80-11 & Foreign Region in Philadelphia, Reactor Construction & Engineering Support Branch 80/09/26 ip
- --8010230711 Responds to NRC 800312 itr re violations noted in IE Insp Repts 90-352/80-12 & 30-353/80-11 Corrective actions memorandum issued directing that no matl substitutions be made to permanent plant hangers w/o prior approval KEMPER. J 8 Philadelphia Electric Co 80/09/03 1p
- --8010230713 Responds to NRC 800312 ltr re violations noted in IE Insp Rapts 50-352/80-12 & 50-353/80-11 Corrective actions visual insp of installed pipe support pins will be extended to areas containing 0-listed pipe supports KEMPER.J 8 Philadelphia Elactric Co 80/06/10 4pp
- 8010230191 Responds to IE Buliwtin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Output Codes " GE analysis will be delayed approx 6 wks Status rept will be sent by 810130 KEMPER, J S Philadelphia Electric Co 80/10/01 ip
- 801024015B Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 ip
- 8010280168 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested ORIER, B. H. Region 1. Philadelphia. Office of the Director 80/10/10 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8010010623 Interim rept for potential Bignificant Deficiency 14 re ASME bolts, nuts & study obtained Prom unapproved sources Bolting matls procured from manufacturers w/o Bechtel approved GA program Will submit further rept KEMPER, J B Philadelphia Electric Co 80/09/25 2pp
- U Congressional/Exacutive Correspondence
- 8010290141 Forwards USOS 800725 rept & util Jul 1980 rept re effects of quarry blasting on facility DIRCKS.W J Office of the Executive Director for Operations 80/10/21. 2pp.
- DDCKET 50-354 HDPE CREEK NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUI.D 0 Division of Licensing. 80/09/19 28pp.
- O Adjudicatory correspondence
- 8010220541 Forwards radon info in response to request info should be made available to ASLAB & parties in radon proceedings ELLETT, N. H Environmental Protection Agency 80/10/10 150pp
- Q. Inspection reports, IE Bulletins & correspondence
- 8010020205 Act receipt of 800703 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-354/79-04 Util position re no addl nondestructive examination for buildups unacceptable CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 80/08/21 1p.
- --8010020207 Responds to NRC 771107 itr re violation noted in IE Insp Rept 50-054/79-04. Corrective actions: well buildup requiring nondestructive examination identified but projected date for action delayed until 800930 due to extended strike HARTIN.T J Public Service Electric & Gas Co. of New Jersey 80/07/03. 2pp.

- 8010060068 Forwards Mgt Meeting Repts 50-394/80-11 & 50-355/80-11 on 800805 in Newart: NU CARLSON:R T Region 1: Philadelphia: Reactor Construction & Engineering Support Branch 80/08/26 ip
- --8010060073 Mgt Hesting Repts 50-354/80-11 & 50-355/80-11 on 800805 Eubj discussed project & FSAR status, resident insp gragram & licensee performance BATEMAN, W H. MCOAUCHY, R H. Region 1, Philadelphia, Office of the Director CARLEON, R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/25 2pp
- 8010230073 Forwards IE Insp Repts 50-354/80-10 & 50-355/80-10 on 800530-0801 No noncompliance noted CARLSON, R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch. 80/08/27 2pp
- --8010230100 IE insp Repts 50-394/80-10 t 50-395/80-10 on 800630-0801 No noncompliance noted Major areas inspected:coring operations in safety-related walls & control rod drive housing restraint beam installation MCOAUOHY:R N . BATEMAN.W. H . WALTON, O A Region 1. Philadelphia. Office of the Director 80/08/26 12pp.
- 8010010819 Responds to IE Bulletin 80-20 rs Wastinghouse Type W-2 control switches Util is awaiting rept from Bechtel. Investigation to be completed by 801110 MARTIN T J Public Service Electric & Gas Co. of New Jersey 80/09/03 Ip
- B010010302 Ack receipt of 800814 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-07 & 50-355/80-07 CARLBOIN R Region f, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/09 1g.
- ~-80i001031i Responds to NRC 800702 ltr re violations noted in IE Inap Repts 50-354/80-07 & 50-355/80-07 Corrective actions:pump shaft free ends blocked & external mechine parts covered w/protective castings HARTIM.T.J Public Service Electric & Oas Co of New Jersey. 80/08/14 Spp
- ~~8010010314 Forwards IE Insp Repts 80-354/80-07 & 50-355/80-07 on 800505-30 & notice of violation CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/02 2pp
- --8010010316 Notice of violation from insp on 800505-30.

 * Region 1, Philadelphia, Office of the Director 80/07/01 2pp
- --8010010323 IE Insp Repts 50-354/80-07 & 50-355/80-07 on 800505-30 Noncompliance noted: failure to store RHR & core spray pumps per technical menual instructions & failure to make structural welds w/qualiffed weld procedures McGAUGHY, R. H. BATEMAN, H. H. Region I. Philadelphia, Office of the Director 80/07/01 12pp
- 8010270116 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Plants Designed by C-E." Subj relay not used in logic matrix of facilities reactor protective sys.

 MARTIN.T. J. Public Service Electric & Cas Co of New Jersey 80/09/17 [p
- 8010240162 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications," No written response required.
 ORIER, B.H. Region 1, Philadelphia, Office of the Director.
 80/10/02, 1p
- 8010280136 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested, ORIERS H Region 1, Philadelphia, Office of the Director. 80/10/10 1p
- S. Reportable occurrences, LERs & related correspondence
- B010020153 Ack receipt of B00820 interim rept re potential significant deficiency in containment relief valves. CARLBOILR.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. B0/09/12. is.
- ~~8010020158 Interim deficiency rept re primary containment relief valves supplied by GPE Controls Bechtel review showed calculation assumptions re seismic analysis require further vendor justification. Next rept by 801024.

 MARTIN.T.J. Fublic Service Electric & Oas Co. of New Jersey 80/08/20. ip.

- 8010130211 Ack receipt of 800702 interim rept re Con Chem spoxy surfacer sys potential significant deficiency Rept will be reviewed & evaluated CARLSON, R T Region 1, Philadelphia, Resctor Construction & Engineering Support Branch 80/09/15 1p
- --8010150215 Interim rept re Can Chem spaxy surfacer sys potential significant deficiency Duplicate reportability is satisfied by Bechtal Power Corp 800728 ltr to NRC Resolution & schedule will be submitted pending engineering evaluations MARTIN.T J. Public Service Electric & Oas Co of New Jersey 80704702 lp
- 8010210005 Part 21 rept re use of Con/Chem coating sys in safety related areas Provides clarified statement re Item 6 of previous itr JONES. O B Bechtel Power Corp (subs of Bechtel Corp) 80/10/06
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 9010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D 0. Division of Licensing, 80/09/19, 28pp.
- O Adjudicatory correspondence
- 80(022054) Forwards radon info in response to request Info should be made available to ASLAB & parties in radon proceedings ELLETT, N H Environmental Protection Agency 80/10/10. 150pp
- Q Inspection reports, IE Bulletins & correspondence
- B010060068 Forwards Mgt Meeting Repts 50-354/80-11 & 50-355/80-11 on 800805 in Newart.NJ CARLBON.R.T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/26 ip
- --B010060073 Mgt Meeting Repts 50-354/80-11 & 50-355/80-11 on 800805 Bubj discussed, project & FSAR status, resident insp program & licensee performance BATEMAN, W. H., MCGAUOHY, R. W. Region 1, Philadelphia, Office of the Director. CARLBON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/25 2pp.
- 8010230075 Forwards IE Insp Repts 50-354/80-10 & 50-355/80-10 on 800430-0801. No noncompliance noted CARLSON, R T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/27, 2pp.
- --8010230100 IE Insp Repts 50-354/80-10 & 50-355/80-10 on 800630-0801
 No noncompliance noted Major areas inspected coring operations in safety-related walls & control rod drive housing restraint beam installation.
 HCOAUGHY,R. W. BATEMAN.W. H., WALTON. G. A. Region 1, Philadelphia, Office of the Director. 80/08/26 12pp
- 8010010819 Responds to IE Bulletin 80-20 re Westinghouse Type W-2 control switches, Util is awaiting rept from Bechtel Investigation to be completed by 801110, MARTIN.T. J. Public Service Electric & Qas Co. of New Jersey 80/09/03 ip.
- 8010010302 Ack receipt of 800814 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-07 & 90-355/80-07 CARLSON, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/09. 1p.
- --8010010311 Responds to NRC 800702 ltr re violations noted in IE insp. Rapts 50-354/80-07 & 50-355/80-07 Corrective actions:pump shaft free ands blocked & external machine parts covered W/protective coatings MARTIN.T.J Public Service Electric & Oas Co. of New Jersey. 80/08/14. Spp.
- --8010010314 Forwards IE Insp Repts 50-354/80-07 & 50-355/80-07 on 800505-30 & notice of violation. CARLSON,R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch, 80/07/02 2pp.
- --8010010316 Notice of violation from insp on 800805-30
 4 Region 1: Philadelphia, Office of the Director. 80/07/01 2pp.

- --B010010323 IE Insp Repts 50-354/B0-07 & 50-355/B0-07 on 800505-30 Noncompliance noted failure to store RHR & core spray pumps per technical manual instructions & failure to make structural welds w/qualified weld procedures.

 MCGAUGHY,R W . BATEMAN.W H Region 1, Philadelphia, Office of the Director. B0/07/01 12pp
- B010270116 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Plants Designed by C-E " Subj relay not used in logic matrix of facilities reactor protective sys MARTIN, T J Public Bervice Electric & Oas Co of New Jersey, 80/09/17 ip
- BO10240162 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required QRIER.B.H Region 1, Philadelphia, Office of the Director 80/10/02 19
- 8050280136 Forwards IE Info Notice 80-36. "Failurs of Bteam Generator Support Bolting " No specific action or response requested QRIER.3 H Region i, Philadelphia, Office of the Director. 80/10/10 ip
- 8. Reportable occurrences. LERs & related correspondence
- E010020153 Ack receipt of B00820 interim rept re potential significant deficiency in containment relief valves CARLBON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/12, ip.
- --B010020188 Interim deficiency rept re primary containment relief valves supplied by OPE Controls. Bachtel review showed calculation assumptions re-seismic analysis require further vandor justification Next rept by B01024 MARTIN-T.J Public Service Electric & Oas Co. of New Jersey. 80/08/20 ip
- BD10210005 Part 21 rept re use of Con/Chem coating sys in safety related areas Provides clarified statement re Item 6 of previous ltr.

 JONES, G B. Bechtel Power Gorp (subs of Bechtel Corp.) 80/10/06.

 Zpp
- DOCKET 50-354 UNIV. OF ILLINOIS LOPRA RESEARCH REACTOR

 F Becurity, medical, emergency & fire protection plans
- B010080524 Bubmits items re-physical security plan requirements. Info withheld (ref 10CFR2, 790).

 BECK, Q.P. Illinois, Univ. of, Urbana-Champaign. 80/09/29, 1p
- O Inspection reports, IE Bulletins & correspondence
- 8010200099 Ack receipt of 800909 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-151/80-02 & 50-335/80-02.

 BAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/09/29.
- --B010200102 Informs of error noted in Item 15, independent measurements Reactor actually operating at 500 kW during survey.

 HECK.G.P Illinois. Univ. of, Urbana-Champaign. 80/07/07. ip.
- --8010200108 Responds to NRC 800902 ltr re violations noted in IE Insp Repts 50-151/80-02 & 50-354/80-02, Corrective actions:written confirmation will be obtained previous to shipping of Class A matis HILEY, Q. H. Illinois, Univ. of, Urbana-Champaign. 80/09/09 2pp.
- --B010200113 Forwards IE Insp Repts 50-151/80-02 & 50-356/80-02 on B00819-20 & notice of violation.
 DAVIS,A.B. Region 3. Chicago, Fuel Facility & Materials Bafety Scanch. B0/09/02. 2pp.
- --8010200117 Notice of violation from insp on 800819-20.
 Region 3, Chicago, Office of the Director. 80/08/28. 1p
- --8010200124 IE Insp Repts 50-151/80-02 & 50-356/80-02 on 800819-20 Noncompilance noted:failure to maintain certification & safety analysis required of all shippers of apec 7A packaging demonstrating that container meets spec 7A. PAULR A FISHER, W. L. Region 3, Chicago, Office of the Director. 80/08/28, 7pp.

- DDCXET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010090495 Summary of B00805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads
 Discussion topics, attendance & meeting handouts encl
 ANDERBON, C. J. Generic Issues Branch 80/08/29, 98pp
- 8010060102 Summary of 800704-05 meeting w/Mark II owners in Bethesda.MD re long-term program chupging & lateral loads. Attendance list & handouts encl.
 ANDERSON.C J Generic Issues Branch. 80/07/12, 65pp
- 8010220099 Forwards errats sheets amending 800905 itr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENMUT.D Q. Division of Licensing. 80/09/19, 28pp
- 8010270238 Notification of 801008 meeting w/representatives from Mark II owners group in Bethesda, MO to discuss Mark II plants chugging load spec. ANDERBUNG Generic Issues Branch 80/09/22. ip.
- 8010090007 Notification of 801015 meeting w/util in Bethesda, MD for briefing on plans for progress made towards resolving intake silting problem as followup to 800624 meeting. PELTIER:I.A Licensing Branch 2, 80/09/27 4pp
- 8010230075 Notification of cancellation of 801016 meeting w/util in Bethesda,MD to discuss plant staffing operations PELTIER,I.A Licensing Branch 2, 80/09/29, 1p.
- 8010220107 Forwards staff position on cladding swelling & rupture models for LOCA analyses. Requests util provide supplemental calculations TEDESCO.R L. Assistant Director for Licensing. 80/10/08 4pp
- 8010270314 Summary of 801015 meeting w/util in Bethesda:MD re potential silting problem at Zimmar Ohio River intake structure.

 Supporting documentation encl.
 PELTIER:I A. Licensing Branch 2. 80/10/17. Sápp
- F Security, medical, emergency & fire protection plans
- 8008200160 Forwards "Preliminary Evacuation Time Study of Plume Exposure Emergency Planning Zone Around WH Zimmer Nuclear Power Station Unit 1." in response to NRC 800702 request. FLYNN.J D. Cincinnati Oas & Electric Co. 80/08/18. 2pp.
- --8008200164 "Preliminary Evacuation Time Study of Plume Exposure Emergency Planning Zone Around HH Zimmer Nuclear Power Station, Unit 1." " Stone & Hebster Engineering Corp. 80/08/31. 31pp.
- 8010060070 Summary of 800828 meeting w/util re emergency response facilities
 PELTIERI, A. Licensing Branch 2 80/07/16 Spp.
- O Adjudicatory correspondence
- 8010160050 Interrogatories requesting info re "Preliminary Evacuation Time Study of Plume Exposure Emergency Planning Zone Around HH Zimmer Nuclear Power Station," Certificate of Svc encl BARTH-C.A. Hearing Branch 3, 80/10/10 4pp.
- 8010220329 Responds to ASLB 800917 memorandum & order Schedule for financial qualifications hearing cannot be provided due to grior commitments of financial analysts.

 BARTH-C.A. Hearing Branch 2 80/10/20. ip.
- H Oeneral correspondence
- 8010140065 FUIA request for documents re activities of various anti- & pro-nuclear organizations, NRC licensing hearings for facility & NRC &/or util legal & administrative strategies & policies.
 RIOBERO, B. Affiliation Unknown. 80/08/23. 2pp.
- 8010140060 Responds to FOIA request for documents re activities of various anti- & pro-nuclear organizations, NRC licensing hearings for facility & NRC &/or util legal & administrative strategies & policies. Forwards App A documents. W/o encis. FELTON, J. M. Division of Rules and Records. 80/10/03, 4pp.

Q Inspection reports. IE Bulletins & correspondence

- 8010160193 Forwards IE Insp Rept 50-358/80-17 on 800714-18,21-25,28 & 31 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/09/19. 2pp
- --8010160161 IE Insp Rept 50-358/80-17 on 800714-18,21-25,28 & 31 No noncompliance noted Major areas inspected unresolved items from previous insp. IE bulletin & circular followup & preoperational environ radiological monitoring program WARNICK,R F, DANIELS,F T., GWYNN,T.F Region 3, Chicago, Office of the Director 80/08/18, App
- 8010080212 Forwards IE Insp Rept 50-358/80-18 on 800805-08 No noncompliance noted DAVIS,A S. Region 3, Chicago, Fuel Farility & Materials Safety Branch 80/08/27 2pp.
- --8010080218 IE Insp Rept 50-358/80-18 on 800805-08 No noncompliance noted Major areas inspected environ protection & monitoring, GA & OC & emergency planning & preparedness PAPERIELLO.C J. PHILLIPS.N P. DESTMAN,M J. Region 3, Chicago. Office of the Director 80/08/27 12pp
- 8010090114 Responds to IE Bulletin 80-19 & Revision 1, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E" Mercury-wetted relays not utilized at facility BORGMANN.E A Gincinnati Gas & Electric Co 80/09/02 1p
- 8010200667 Forwards IE Insp Rept 50-358/80-20 on 800806-08 & notice of violation FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/02 2pp
- --8010200668 Notice of violation from insp on 800806-08, * Region 3, Chicago, Office of the Director 80/08/28 ip
- --8010200470 IE Insp Rept 50-358/80-20 on 800806-08 Noncompliance noted review of preservice insp & welding OA/QC procedures.work activities, nondestructive examination & welding, personnel certification & data
 WARD,K. B. Region 3, Chicago, Office of the Director
 DANIELSUN,D H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/28, opp.
- 8010290115 Forwards IE Insp Rept 50-358/80-16 on 800715-17 & 0814-15 & notice of violation. FIORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/03 2pp
- ---8010270118 Notice of violation from insp on 800715-17 & 0814-15 * Region 3: Chicago: Office of the Director. 80/08/27 ip
- ---8010270124 IE Insp Rept 50-358/80-16 on 800713-17 & 0814-15
 Noncompliance noted failure to document reorganization of
 site GA/OC operations
 DANIELEGN, D. H. Region 3. Chicago, Reactor Construction &
 Engineering Support Branch YIN, I. T. Region 3. Chicago, Office of
 the Director 80/08/27. Spp
- 8010270146 Forwards IE Insp Rept 50-358/80-19 on 800801,04-08,12-15, 18-21 & 25-29 & notice of violation KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/17, 2pp
- --8010270153 Notice of violation from insp on 800801.04-08,12-15,18-21 & 25-29.

 A Region 3. Chicago, Office of the Director. 80/09/18 3pg
- --8010270161 IE Insp Rept 50-358/80-19 on 800801.04-08.12-15.18-21 & 25-29 Noncompliance noted inadequate design control. inadequate measures to indicate status of components & repetitive failure of wald rod control DANIELS.F.T., MARNICK.R.F. Region 3. Chicago. Office of the Director 80/09/18. 11pp.
- 8010160279 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J G. Region 3. Chicago, Office of the Director. 80/09/30 lp.
- 9010280076 Forwards 1E Circular 80-22, "Confirmation of Employee Qualifications," No written response required.

 KEPPLER, J. Q Region 3, Chicago, Office of the Director 80/10/02.

- 8010240033 Ack receipt of 800819 & 0919 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/800-14 HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/10/08 1p
- --8010240035 Responds to NRC 800731 ltr re violations noted in IE Insp Rept 50-338/80-14 Corrective actions procedure being developed to provide listing of personnel authorized to sign various project documents BOROMANN,E A Cincinnati Oas & Electric Co 80/08/19 2pp
- 8010270024 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J O Region 3. Chicago, Office of the Director 80/10/10 19
- S Reportable occurrences, LERs & related correspondence
- 8010090265 PND-III-80-163 Region 3 is preparing to issue immediate action ltrs on 800903 confirming that utils will stop installation of lead elastomer 8 silicone gel penetration seals made by Tech-Bil Inc NEIBLER, J H. WILLIAMS, C C . FIORELLI, 9 Region 3, Chicago, Office of the Director 80/09/03 1p
- 8010200305 Ack receipt of 800711 interim deficiency rept re GE Type IAC induction disc relays w/petroleum jelly lubricated dials (fill review final rept on matter upon receipt FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/29 ip
- --8010200313 Interim deficiency rept re QE Type IAC induction disc relays w/petroleum selly lubricated time dials Investigation showed that 196 Type IAC relays & 9 type IJCV relays are on various sys Relays will be replaced & defective relays scrapped BURGMANN.E A Cincinnati Qas & Electric Co 80/09/11, 1p
- BOIO240349 Part 21 rept re actuator mounting Thirteen actuators lock nut mounted as opposed to seismically qualified bolt mounting on 5-inch bolt circle List of affected dampers encl
 BLOAN, D. E. American Warming & Ventilating, Inc. 80/10/14 Spp.
- DOCKET 50-361 BAN DNOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8010080310 Notification of contract execution "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station," awarded to K Aki
 LITLE: M Administrative Contracts Branch FIN 0-6878-0 80/08/22
- --8010080315 Contract "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station," awarded to K Aki
 AKI, K Massachusetts Institute of Technology PERLMAN, J.
 Administrative Contracts Branch FIN B-6898-0 80/08/22 5pp
- 8010020022 Notification of 800925-26 meeting w/Southern CA Edison Co in San Clemente.CA to observe & discuss resolution of open items. ROOD:H Licensing Branch 3 80/09/19 3pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D. O Division of Licensing 80/09/19 28pp
- 8010210294 Notification of 800930-1002 meeting w/util in 9an Clements. CA to review seismic qualifications of electrical & mechanical equipment R000.H Licensing Branch 3. 80/09/22, 3pp
- 8010070568 Forwards response to questions in NRC 800315 itr. Also forwards "Matertight Reliability of Condensate Storage Tank & Concrete Encl Walls Under OBE Tornado Events "BASKIN.K P. Bouthern California Edison Co 80/09/29. 8pp
- --8010070574 "Watertight Reliability of Condensate Storage Tank & Concrete Encl Walls Under OBE & Tornado Events,"

 * Southern California Edison Co 80/09/29 55pp.
- 8010080494 Forwards responses to NRC questions & revised FBAR sections re-preservice & inservice insp & testing BASKIN, K. P. Southern California Edison Co 80/10/06 100pp

- --B010080459 Preservice insp program plan KNOKE, J.R. Bouthern California Edison Co. 80/09/11 190pp
- --B010080462 Inservice testing program
 KNDKE, J.R. Southern California Edison Co. 80/09/11 140pp
- B010080526 Forwards info in response to NRC request made at 800923 meeting in Menlo Park, CA re Geosciences Branch review Response includes info on hypothesized offshore zone of deformation & assessment of landslide feature near Trail 5 BASKIN, K.P. Southern California Edison Co. 80/10/08 66pp
- 80:0210636 Forwards proposed App B to nonradiological ET8 per 10CFR90 36 & consistent w/proposed Change 94 to ET8 for License DPR-13 Requests ETB processing be coordinated w/review of proposed Change 94 to ET8
 BASKIN.K P Bouthern California Edison Co 80/10/18 3pp
- --8010210643 App 8.ET8 1 0-8 1 re limiting conditions for operation, environ monitoring. special studies & requirements, administrative controls & station reporting requirements a Southern California Edison Co. 80/10/15 3pp
- B010300151 Summary of 800723 meeting w/consultants.UB08.util & CA Div of Mines & Geology in Menlo Park.CA re plant seismology & geology. Attendee list-agenda & util conclusions encl ROOD. H Licensing Branch 3 80/10/16 11pp
- & Security, medical, emergency & fire protection plans
- BOOB130360 Forwards "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Plume Exposure Pathway Emergency Planning Zone"
 BASKIN, K.P. Southern California Edison Go 80/08/01. ip
- --8009150968 "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Plume Exposure Pathway Emergency Planning Zone " Builbur Smith & Associates 80/09/31 94pp
- 8010170145 Notification of 801020 meeting w/util & state & county representatives in El Segunda, CA to discuss completion dates & review matters for state & local emergency plans for facility & vicinity ROOD, H Licensing Branch 2, 80/10/08 App
- BO10210734 Notification of B01020 meeting w/util. Orange County, San Diego County & State of CA OES in El Segundo, CA to discuss completion detes & review matters for state & local emergency plans for facility & vicinity ROOD, H Licensing Branch 2 80/10/08 4pp
- G Adjudicatory correspondence
- B01001059B Forwards executed stipulation extending time for answering interrogatories CHANDLER.L J Office of the Executive Legal Director 80/09/29 ip.
- --8010010602 Stipulation extending time for answering Friends of the Earth, et al. interrogatories to 801017 CHANDLER, L. J. Office of the Executive Legal Director HHARTON, R. J. Wharton & Pagalies WHARTON, R. J. Friends of the Earth. 80/09/19 1p
- 8010030444 Executed & approved 800919 stipulation setting 801017 for NRC to respond to Friends of The Earth et al 800904 interrogatories CHANDLER.L J Hearing Branch 4 WHARTON.R, J Friends of the Earth 80/10/01 ip
- 8010030421 Memorandum & order correcting transcript of 800717 prehearing conference per LT Chandler 800927 encl ltr directed to ASLB SMITH I W Atomic Safety and Licensing Board Panel 80/10/02 ip
- --B010030426 Urges correction of 800717 prehearing conference transcript. Pages 239,240,241,266,267 & 268,Certain statements ascribed to LI Chandler were in fact made by RJ Wherton, counsel of Friends of The Earth, et al. CHANDLER.L. J Hearing Branch 4. 80/09/29. 1p
- 9010210286 Response to Priends of The Earth 800904 Interrogatories re subparallel branches of Cristianitos fault & seismic shaking of structures & ground surface Also addresses reactor operator performance in emergencies W/Certificate of Bvc. REITERIL: CARDONE: A T Assistant Director for Environmental Technology RODD: H. Licensing Branch 2 80/10/17. 46pp.

- H General correspondence
- B010140607 Forwards B Feldman 800903 ltr re insurance & liability from possible facility damage BADMAM.R E House of Rep. 80/09/29 2pp
- 8010270038 Responds to 800214 ltr to President Carter re ability of facilities to withstand earthquakes & effect of low level radiation ASLB plans to reopen San Onofre hearing record reseismic adequacy in first quarter of 1981 MIRAOLIA: FJ Licensing Branch 3 80/10/16 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B0102B0374 Forwards affidavit of svc affirming distribution of Amend 20 to FSAR per B00712 commitment BASKIN.K P Southern California Edison Co 80/10/20 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010090380 Forwards IE Insp Repts 50-361/80-10 & 50-362/80-07 on 800617-20 & 0714-18 No honoumpliance noted SPENCER.0 & Region 5, Ean Francisco. Reactor Construction & Engineering Support Branch. 80/08/22 2pp
- --8010090381 IE Insp Repts 50-361/80-10 & 50-362/80-07 on 800617-20 & 0714-18 No noncompliance noted Major areas inspected pipe support concrete expansion anchor boit installation & qualification of nondestructive examination personnel DUDDS: T Region 5. San Francisco. Reactor Construction & Engineering Support Branch. ECHARDT.J H, NARBUT.P P Region 5. San Francisco. Office of the Director 80/08/21 9pp
- B010240075 Responds to IE Bulletins B0-19 & 80-19 Revision 1. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Bubj relays not supplied for use at facilities.

 BASKIN.K P. Southern California Edison Co 80/08/25 1p.
- 8010200021 Forwards IE Insp Repts 50-361/80-14 & 50-362/80-09 on 800811-15 No noncompliance noted 800K.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 80/09/10 2pp
- --8010200034 IE Insp Repts 50-361/80-14 & 50-362/80-09 on 800811-15
 No noncompliance noted Mayor areas inspected radiation
 protection personnel, radiation safety procedures, radiation
 survey instrumentation & const environ monitoring program
 FISH:R F.: NENSLAMBRI:F A Region 5. San Francisco, Office of the
 Director. BODW, H.E. Region 5. San Francisco, Fuel Facility &
 Materials Safety Branch. 80/09/09 7pg
- B010290402 Forwards 1E Circular 80~21, "Regulation of Refueling Crews" No written response required. EMBELKBHR H Region 5, San Francisco, Office of the Director B0/09/10 1p.
- 8010080590 Responds to IE Bulletin 80-20, "Failures of Hestinghouse Type U-2 Spring Return to Neutral Control Suitches " Preliminary review from Bechtel & C-E reveals no final determination re equipment.

 BASKIN.K.P Bouthern California Edison Co. 80/09/11 2pp
- 8010020133 Discusses 800715 meeting w/util re NRC licenses performance systuation & forwards IE Insp Repts 50-361/80-13 & 50-362/80-08 & supporting data.
 ENGELKEN.R H Region 5, San Francisco, Office of the Director, 80/09/18 2pp
- --8010020137 IE Repts 50-361/80-13 & 50-362/80-08 on 800715, evaluating licensee performance from June 1977-June 1980 Installation of piping hangers & supports warrant increased insp frequency Related data enci ENOELKEN.R H . PATE.R J Region 5. San Francisco. Office of the Director SPENCER.O & Region 5. San Francisco. Reactor Genstruction & Engineering Support Branch 80/09/03. 16pp.
- 8010160270 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director 80/09/29, 10
- 8010310272 Forwards IE Insp Repts 30-361/80-15 & 50-362/80-10 on 800826-29 No noncompliance noted SPENCER, O. S. Region 5. San Francisco: Reactor Construction & Engineering Support Branch. 80/10/01 2pp.

- --8010310278 IE Insp Repts 50-361/80-15 & 50-362/80-10 on 800826-29 No noncompliance noted Major areas inspected installation of piging & component supports, electrical cable installation & internal wiring of transfer switch cubicle ECKMARDT, J H, NARBUT, P P Region 5, San Francisco, Office of the Director HAYNES, R C Region 5, 8an Francisco, Reactor Construction & Engineering Support Branch 80/09/30 7pp
- 8010280367 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required ENGELKEN,R M Region 5. San Francisco. Office of the Director BO/10/02 ip
- 8010080454 Forwards responses to NRC questions & revised FSAR sections re preservice & inservice insp & testing BASKIN, K.P. Southern California Edison Co. 80/10/06 100pp
- --B010080457 Preservice insp program plan KNOKE, J R Southern California Edison Co 80/07/11 190pp
- R Periodic operating reports & related correspondence
- 8010150407 Forwards magnetic tape of hourly meteorological data for period Jan 1976 to Dec 1979 per 800909 telcon NRC & station formats for meteorological data encl Tape available in Central Files only BASKIN.K P Southern California Edison Co 80/10/08 8pp
- S Reportable occurrences. LERs & related correspondence
- 8010100409 PNG-V-80-070 on 800917, marine diver died while working mear or around outfall structure for facility Cause of death unknown, but not believed to be associated w/operation of facility equipment FAULKENBERRY, B., CREWS, J. L., Region 5, Ban Francisco, Office of the Director 60/09/17 ip
- 8010020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DSRV 12. DSRV 16. 2. DSRV 15. DSRV 16. 2. DSRV 16. 2. DSRV 16. 2. DSRV 17. DSRV 17.
- O10240363 Part 21 rept re failure of motor operated valve stem during contracting testing Target Rock Model 74R-008 motor operated glove valve equipped w/Limitorque operator used in low pressure safety injection sys Gause under investigation PATTARINI Target Rock Corp 80/10/15 2pp.
- 3010240398 Clarifies 800715 final deficiency rept re lack of nondestructive examination of weld repair excavation cavities prior to rewelding in response to NRC 801007 request Examination of completed weld repairs performed NUNN. D E Bouthern California Edison Co 80/10/16 ip
- BOCKET 50-362 BAN GNOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8010080310 Notification of contract execution "Followon Simulation of Earthquake Ground Motions for San Unofre Nuclear Generating Station" swanded to K Aki LITTLE:K Administrative Contracts Branch, FIN B-6898-0 80/08/22
- -8010080315 Contract "Followon to Bimulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station," swarded to K Aki AKI.K Hassachusetts Institute of Tachnology. FIN 8-6898-0 80/08/22 5pp
- 010020022 Notification of 800923-26 meeting w/Southern CA Edison Co in San Clements.CA to observe & discuss resolution of open items ROOD-H Licensing Branch 3 80/09/19 3pp
- property presenting present a polyodyta app
- 0220097 Forwards errata sheets amending B00905 ltr which provided reliminary clarification of TMI action plan requirements. ornected table of implementation schedule also encl. ISENHUT.D 0. Division of Licensing 80/09/19, 28pp.
- 10294 Notification of 800930-1002 meeting w/util in San Clementa, o review setsmic qualifications of electrical & anical equipment

 . If Licensing Branch 3 80/09/22 3pp

- 8010070568 Forwards response to questions in NRC 800315 ltr Also forwards "Watertight Reliability of Condensate Storage Tank & Concrete Encl Walls Under OBE Tornado Events "BASKIN.K P. Southern California Edison Co 80/09/29 8pp
- --80:0070374 "Watertight Reliability of Condensate Storage Tank & Concrete Encl Walls Under DBE & Tornado Events "

 → Southern California Edison Co 80/09/29 56pp
- 8010080454 Forwards responses to NRC questions & revised FSAR sections re-preservice & inservice insp & testing
 BASKIN, K P Bouthern California Edison Co 80/10/06 100pp
- --8010080459 Preservice insp program plan KNOKE, J R Southern California Edison Co 80/09/11, 190pp.
- --8010080462 Inservice testing program KNOKE,J R Southern California Edison Co 80/09/11, 140pp
- 8010080526 Forwards info in response to NRC request made at B00923 meeting in Henlo Park.CA re Geosciences Branch review Response includes info on hypothesized offshore zone of deformation & assessment of landslide feature near Trail 5 BASKIM.K.P. Southern California Edison Co. 80/10/08 66pp
- 8010210636 Forwards proposed App B to nonradiological ETS per 10CFR50 36 & consistent w/proposed Change 94 to ETB for License DPR-13 Requests ETS processing be coordinated w/review of proposed Change 94 to ETB BASKIN: K P Southern California Edison Co 80/10/15 3pp
- --8010210643 App B.ETS 1 0-5 1 re limiting conditions for operation, environ monitoring, special studies & requirements, administrative controls & station reporting requirements & Southern California Edison Co 80/10/15 3pp
- 8010300151 Summary of 800923 meeting w/consultants.U808, util & CA Div of Mines & Deology in Menlo Perk, CA re plant seismology & geology Attendee list.agenda & util conclusions encl ROOD: H Licensing Branch 3 80/10/16 ilpp
- F Security, medical, emergency & fire protection plans
- BD08150360 Forwards "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Plume Exposure Pathway Emergency Planning Zone"

 BASKIN, K.P. Southern California Edison Co B0/08/01. Ip
- ~-8008150368 "Analysis of Time Required to Evacuate Transient & Permanent Population from Various Areas Within Pluma Exposure Pathway Emergency Planning Zone " « Wilbur Smith & Associates 80/08/31 94pp
- 8010170145 Notification of 801020 meeting w/util & state & county representatives in E1 Segunda, CA to discuss completion dates & revisu matters for state & local emergency plans for facility & vicinity.

 ROOD, H Licensing Branch 2 80/10/08 4pp
- 8010210734 Notification of 801020 meeting w/util,Orange County, San Diego County & State of CA OES in El Segundo,CA to discuss completion dates & review matters for state & local emergency plans for facility & vicinity ROOD,H Licensing Branch 2 80/10/08 4pp.
- G Adjudicatory correspondence
- 8010010598 Forwards executed stipulation extending time for answering interrogetories
 GHANDLER.L. J. Office of the Executive Legal Director 80/09/29
- ~-8010010602 Stipulation extending time for enswering Friends of the Earth.et al.interrogatories to 801017. CHANDLER.L J. Office of the Executive Legal Director WHARTON,R J. Wharton & Pogalies. WHARTON,R J. Friends of the Earth 80/07/19 1p.
- 8010030444 Executed & approved 800919 stipulation setting 801017 for NRC to respond to Friends of The Earth et al 800904 interrogatories.

 CHANDLER, L. J. Hearing Branch 4 NHARTON, R. J Friends of the Earth 80/10/01. ip
- 8010030421 Memorandum & order correcting transcript of 800717 prehearing conference per LT Chandler 800929 encl itr , directed to ASLB.

 BMITH, I. W. Abomic Sefety and Licensing Board Panel. 80/10/02 ip.

- --8010030426 Urges correction of 800717 prehearing conference transcript.
 Pages 239, 240, 241, 266, 267 & 268 Certain statements ascribed
 to LI Chandler were in fact made by RJ Wharton, counsel of
 Friends of The Earth, et al
 CHANDLER, L J Hearing Branch 4 80/09/29 ip
- 8010210286 Response to Friends of The Earth 800904 interrogatories re subparallel branches of Cristianitos fault & seismic shaking of structures & ground surface Also addresses reactor operator performance in emergencies W/Certificate of Svc REITER, L. CARDONE, A.T. Assistant Director for Environmental Tachnology ROUD, H. Licensing Branch 2 80/10/17 46pp

- BO10140607 Forwards B Feldman B00905 ltr re insurance & liability from cossible facility damage BADHAM,R E House of Rep B0/09/29 2pp
- 801027003B Responds to 800214 ltr to President Carter re ability of facilities to withstand earthquakes & effect of low level radiation ASLB plans to reopen San Onofre hearing record reseisnic adequacy in first quarter of 1981 MIRAGLIA: FJ Licensing Branch 3 80/10/16 3pp
- K Utility Final Safety Analysis Report (FSAR) & amonds
- BO10280374 Forwards affidavit of svc affirming distribution of Amend 20 to FBAR per BO0712 commitment BASKIN-K P Southern California Edison Co BO/10/20 3pp
- O Inspection reports, IE Bulletins & correspondence
- Egj0990380 Forwards IE Insp Repts 50-06i/80-i0 & 50-362/80-07 on 800617-20 & 0714-18 No noncompliance noted SPENCER, 0 S Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/08/22 2pp
- --B0100703Bi IE Insp Repts 50-361/80-10 & 50-362/80-07 on B00617-20 & 0714-18 No noncompliance noted Major areas inspected pipe support concrete expansion anchor bolt installation & qualification of nondestructive examination personnel DODDS: R T Region 5: Ban Francisco, Reactor Construction & Engineering Support Branch ECHARDT: J H: NARBUT, P.P. Region 5: Ban Francisco, Office of the Director B0/0B/21 7pp
- 80:0240075 Responds to It Gulletins 80-19 & 80-19 Revision i, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Buby relays not supplied for use at facilities BASKIN.K P Southern California Edison Co 80/08/25 ip
- @010200021 Forwards IE Insp Repts 50-36/1/80-14 & 50-362/80-09 on 800811-15 No noncompliance noted BOCK-H E Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch B0/09/10. 2pp
- --8010200034 IE Insp Repts 50-361/80-14 & 50-362/80-09 on 800811-15
 No noncompliance noted Major areas inspected radiation
 protection personnel radiation safety procedures radiation
 survey instrumentation & const environ monitoring program.
 FIBH.R F . WENBLAMBRILE A Region 5. Ban Francisco. Office of the
 Director BODK.H E. Region 5. San Francisco, Fuel Facility &
 Haterials Sefety Branch 80/09/09 7pp
- \$010290402 Forwards IE Circular 80-21. "Regulation of Refueling Creus" No written response required ENGELKEU, R H Region 5. San Francisco. Office of the Director B0/07/10 ip
- 8010080870 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Buitches "
 Preliminary review from Bechtel & C-E reveals no final determination re equipment BASKIN.*K P Southern California Edison Co. 80/09/11. 2pp
- BO10020133 Discusses B00715 meeting w/util re NRC licenses performance evaluation & forwards IC Insp Repts 50-361/80-13 & 50-362/80-08 & supporting data ERGELKED R Region 5, Ban Francisco, Office of the Director, B0/09/19 2pp.
- --B010020137 IE Repts 50-361/80-13 & 50-362/80-08 on 800715, evaluating licensee performance from June 1979-June 1980. Installation of piping hangers & supports warrant increased insp frequency, Related data encl ENOELKEN,R H. PATE,R J. Region 5, San Francisco, Office of the Director SPENCER, 0 & Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/09/03 16pp

- 8010160270 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required ENGELKEN:R H Region 5, San Francisco, Office of the Director 80/09/29 1p
- 8010310272 Forwards IE Insp Repts 50-361/80-15 & 50-362/80-10 on 800826-29 No noncompliance noted SPENCER.0 S. Region S. San Francisco. Reactor Construction & Engineering Support Branch 80/10/01 2pp
- --8010310278 IE Insp Repts 50-361/80-15 & 50-362/80-10 on 800826-29 No noncompliance noted Major areas inspected installation of piping & component supports, electrical cable installation & internal wiring of transfer switch cubicle ECKHARDT. J H. NARBUT.P P. Region 5, San Francisco, Office of the Director HAYNES.R C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/30 7pp
- 8010280667 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/10/02 ip
- 8010080454 Forwards responses to NRC questions & revised FSAR sections re-preservice & inservice insp & testing BASKIN.X P Southern California Edison Co 80/10/06 100pp
- --B010080459 Preservice insp program plan.
 KNOKE, J R Southern California Edison Co H0/09/ii 190pp
- R Periodic operating reports & related correspondence
- 8010150407 Forwards magnetic tape of hourly meteorological data for period Jan 1976 to Dec 1979 per 800909 telcon NRC & station formats for meteorological data encl Tape available in Central Files only BASKIN.K P Southern California Edison Co 80/10/08 8pp.
- 8 Reportable occurrences, LERs & related correspondence
- 8010100407 PNO-V-80-070 on 800917 marine diver died while working near or around outfall structure for facility Cause of death unknown but not believed to be associated w/operation of facility equipment FAULKENBERRY, B., CREWS, J.L. Region 5. Ban Francisco, Office of the Director 80/09/17 ip
- 8010240553 Part 21 rept re failure of motor operated valve stem during contracting testing Target Rock Model 74R-008 motor operated glove valve equipped w/Limitorque operator used in low pressure safety injection sys Cause under investigation PATTARINI Target Rock Corp 80/10/15 2pp
- 8010240378 Ciarifies 800715 final deficiency rept re lack of nondestructive examination of weld repair excavation cavities prior to rewelding in response to NRC 801007 request Examination of completed weld repairs performed NUNN, D E Southern California Edison Co 80/10/16. 1p
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT !

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGENHUT, D. O. Division of Licensing 80/09/19 28pp
- G Inspection reports, IE Bulletins & correspondence
- 8010240121 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 19
- 8010280229 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested GRIER, B H Region i, Philadelphia, Office of the Director 80/10/10 ip

- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- B010140070 Forwards status of facility completion IE believes projected fuel load date of 800928 is more realistic Region 2 will inspect security program implementation prior to licensing BRYAN.B E Division of Reactor Operations Inspections 80/08/27
- --8010140078 Forwards open items requiring resolution before facility may be endorsed for operation Evel loading data of 800928 is more realistic O'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/22 8pp
- 8010220274 Transcript of 800903 meeting re low power OL in Washington Pp 1-58
 Commissioners 80/09/03 40pp
- --8010220282 Draft Suppl 4 to SER, NUREO-75/034, for facility Draft DL ci D#fice of Nuclear Reactor Regulation, Director NUREG-0117 FT 80/08/28 177pp
- 8010030230 Forwards response to NUREO-0588, "Environ Qualification of Class IE Electrical Equipment " CLAYTON,F L. Alabama Power Co. 80/09/18 476pp
- 80:01:70149 Discusses status of facility licensing Estimated fuel load is 800929 All applicable comments were incorporated into fuel loading & low power testing license final comments on addendum to FEB & environ protection plan were obtained KININER, L. L. Licensing Branch 2 80/09/18 2pp
- 8010020303 Forwards request for addl info re QA program & oneite power Requests info by 800929 TEDESCO.R L. Assistant Director for Licensing 80/09/19 opp.
- 8010030304 Summary of 800B12 meeting w/util & local govt officials at plant site re review of OL application
 KININER.L L Licensing Branch 2 80/09/19 26pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENIUT. D O Division of Licensing, 80/09/19 28pp
- 8009240519 Forwards response to NRC 800825 & 0910 ltrs re TMI-related questions on RCB vents Response & oversize drawings available in Central Files only.

 CLAYTON.F L Alabama Power Co 80/09/22 2pp
- --8009240522 Response to NRC 600825 & 0910 ltrs re TMI-related questions on RCS vents Supporting oversize drawings encl.

 * Alabama Power Co. 80/09/22 185pp
- 8010220080 Notification of 800922 & 23 meeting w/util, Bechtel Corp & Hestinghouse at site to discuss review of ticense application & audit records on environ qualification of selected safety-related equipment KINTER.L. Licensing Branch 2 80/09/22 2pp
- 8010080546 Summary of 800905 meeting w/util & Hestinghouse re-encl Hestinghouse proposed responses to NAC questions on HCAP-9292 Responses will be submitted under NAC topical rept review program by 800915 KINTNER:L L Licensing Branch 2 80/09/24 70pp
- 8010090020 Summary of 800624 meeting w/util in Bethesda.MD re evaluation of organization & mgt improvements for review of DL application List of attenders agenda & meeting handout KINTNER.L.L Licensing Branch 2 80/09/24, 70pp
- 8010090217 Summary of 800716 meeting w/util in Bethesda, MD re applicant response to NRC positions on degraded grid voltage protection KINTER, L. Licensing Branch 2. 80/09/24 3pp
- 8010090226 Bummary of 800801 meeting w/util re open items in review of application for OL Applicant requested to provide response to dtd requirements listed in NUREO-0694 by 800804 List of attendees & agenda encl.

 KINTNER.L.L Licensing Branch 2 80/09/24, 6pp.

- B010:00063 Summary of B007:0 meeting w/util & Westinghause to discuss responses to NRC questions re-proposed exemptions to 10CFR30 Apps Q & H List of attendees & question/angwer responses and KINTRER.L L Licensing Branch 2 80/09/24 14pp
- 8010170304 Summary of B00709 meeting w/util re proposed radiological effluent Tec Specs List of attendees, agenda, applicant summary of meeting & marked-up Tech Specs for limiting combustiple gas concentrations in radwaste sys encl KINTNER, L. L. Licensing Branch 2 80/09/24 11pp
- 8010170310 Summary of H00715 meeting w/util in Bethesda.MD re NRC conclusions on improvements to control room design List of attendees & draft summary encl KININER.L L. Licensing Branch 2 80/09/24 9pp
- 80101/0312 Summary of 800703 meeting u/util in Bethesda,MD re preparation of rept on compliance u/NUREG-0589, "Interim Staff Position on Environ Gualification of Bafety-Related Electrical Equipment " Electrical Equipment "
 KINTNER, L. L. Licensing Branch 2 80/09/24 15pp
- 8010070545 Clarifies util 800612 % 0912 responses re engineered safety features bypass override & reset circuits in response to NRC 800929 telcon Mod to motor & turbine driven discharge valves will be made prior to operation above zero power CLAYTON.F. L. Alabama Power Co. 80/09/29 1p
- B010170011 Forwards Mechanical Engineering Branch position on facility leak testing program re RCS pressure isolation valves M/o enci BOSNAKIR J Mechanical Engineering Branch 80/09/29, 1p.
- 8010230086 Bummary of 800918 meeting w/util. Bechtel & Hestinghouse re review of full power OL application
 KINTNER, L. L. Licensing Branch 2 80/09/29 19pp
- 8010240163 Summarizes status of licensing procedure Fuel load & startup are rescheduled for S01015 & 801215, respectively Add1 time needed to complete pipe hanger mads KINTMER.L L Licensing Branch 2 80/09/29 2pp
- 8010070341 Forwards addl info re vehicle cask loading requirements & special procedures & precautions for radwaste & radioactive matl Provides assurance that process control program waste shipments comply w/burial ground requirements CLAYTON.F L. Alabama Power Co. 80/09/30 App
- --8010070343 Submits results of radioactive liner test for free liquid Tests demonstrate suitability of ures formaldehyde as acceptable solidification media MOTL: 0 P Chem-Nuclear Systems. Inc 79/08/16 3pp.
- 8010070395 Application to amend CPPR-86, authorizing use of mini purge sys during operation in Modes 1-4 for containment atmospheric & pressure control until first refueling outage Add1 into re-containment purge sys enc1 CLAYTON-F L. Alebama Power Co 80/09/30 9pp
- --8010070398 Proposed Tech Specs 3/4 & 1 5-3/4 & 1 7 re containment sys

 N Alabama Power Co 80/09/30 ip
- 8010070599 Corrects error in 780928 ltr re storage capacity for prinary spent resins Table 1: 5 i of FSAR states accurate value Storage capacity of 150 cubic ft could accommodate approx 1 5 months of discharge resins CLAYTON.F L. Alabama Power Co. 80/09/30 ip
- 8010080423 Forwards response to questions raised at 800918 meeting to fuse protection associated w/hot shutdown panel CLAYTON: F. L. Alabama Power Co. 80/09/30 4pp.
- 8010150638 Discusses licensing status re fuel loading date. Tech Space & environ protection plan Estimated fuel loading date is 801015.
 KINNER, L L. Licensing Branch 2 80/09/30 2pp.
- 8010140288 Forwards comparative analysis of natural circulation between Diable Canyon & Farley to justify 800922 assumption that results of prototype testing would be similar for both plants GLAYTON, F. L. Alabama Power Co. 80/10/06, 4pp
- 8010140305 Forwards comments re TMI action plan requirements' preliminary clarification per addendum to NRC 800905 ltr & 800926 meeting. Substantial change to requirement criteria would affect current implementation schedules. H/o encl. CLAYTON, F. L. Alabama Power Co 80/10/06, 1p

- BO10140346 Forwards additinfo requested by Seismic Qualification Review
 Team re emergency air compressors
 CLAYTON, F.L. Alabama Power Co. 80/10/06 Rpp
- 8010150387 Forwards addl info re G-list items in response to NRC BOO919 1tr CLAYTON,F L Alabama Power Co 80/10/08 47pp
- 8010210278 Forwards summary of 800630-0703 meeting w/util at site re DL application
 KINTNER, L Licensing Branch 1 80/10/08, ip
- --8010210281 Summary of 800630-0703 meating w/util at plant & corporate headquarters in Birmingham.AL to review util mgt & technical competence RIVENBARK,O W Assistant Director for Licensing 80/09/25 4pp
- 8010230187 Notification of 801016 meeting w/util in Dothan, AL to review OL application
 KINTNER, L Licensing Branch 1 80/10/08 3pp
- 8010280185 Summary of 800515-20 meetings w/util in Bethesda, MD re OL APPRICATION HINTNER, L.L. Licensing Branch 1 80/10/08 3pp
- BO10200495 Forwards add1 info re Class IE electrical equipment environ qualification, in response to NRC 800894 request CLAYTON, F.L. Alabama Power Co. 80/10/10 12pp
- 8010200590 Bubmits info re differences between Farley Nuclear Plant thet procedures & Bequoyah test procedures for natural circulation w/loss of power per 800714 request.
 CLAYTON, F. L. Alabama Power Co 80/10/13. 2pp
- BO10270297 Advises of licensing status for facility KINTNER, L. Licensing Branch 2 BO/10/15 2pp.
- BO10280424 Forwards facility max allowable leakage limits for sys gutside containment that may carry radioactive fluids following accident, per NUREO-0660 action plan requirements CLAYION, F L Alabama Power Co 80/10/20 2pp
- 8010280463 Notifies that complete re-evaluation of masonry walls has been postponed to 801208 to permit detailed engineering evaluation of as-built drawings CLAYTON, F. L. Alabama Power Co. 80/10/22 1p
- BO10300459 Forwards "Structural Integrity Test Rept Containment Structure" & "Primary Reactor Containment Integrated Leak Rate Test." Rate Test." CLAYTON:F L Alabama Power Co. 80/10/28 ip
- --8010300470 "Structural Integrity Test Rept.Containment Structure."

 Bechtel National: Inc 7597 80/07/31 115pp.
- --8010300473 "Primary Reactor Containment Integrated Leak Rate Test "
 # Bechtel Power Corp. (subs of Bechtel Corp.). 7397 80/10/28. 425pp.
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- BO10160785 Addendum to FES for facility.

 Office of Nuclear Reactor Regulation, Director NUREO-0727 ADD B0709730 54pp. Available at NTIS \$3.50
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 8010220274 Transcript of 800703 meeting re low power QL in Washington DC Pp 1-58 # Commissioners 80/09/03 60pp
- --B010220292 Draft Suppl 4 to SER, NUREO-75/034, for facility. Draft OL enci.

 Diffice of Nuclear Reactor Regulation, Director, NUREO-0117

 DRFT 80/08/28, 17799
- 8010080394 SER for facility. Suppl 4 to NUREO-75/034. ** Office of Nuclear Reactor Regulation, Director 80/09/30 180pp. Available at NTIS. \$5 80. NUREO-0117.
- BOIG140548 Forwards Buppl 4 to SER. NUREQ-75/034 BCHWENCER, A. Licensing Branch 2 80/09/30. ip

- F Security, medical, emergency & fire protection plans
- 8010280487 Notifies that proposed Mod Summary. Table 3 of Amend 11 to License NPF-2 has been incorporated into facility fire protection mod program Supersedes 790319 ltr CLAYTON:F L Alabama Power Co 80/10/21 lp
- J Insurance & indemnity information
- 6010310547 Amend 7 to Indemnity Agreement 8-81, deleting Item 3 & substituting license numbers.

 SALTZMAN.J Utility Finance Branch (formerly Antitrust & Indemnity)

 BO/09/27 ip.
- P Operating license stage documents & correspondence
- 8010070295 Forwards revised response re electrical separation of instruments required to bring plant to hot shutdown Fire barriers also discussed CLAYTON.F.L. Alabams Power Co 80/09/30 2pp
- B010070305 Forwards response to NRC B00919 questions re containment purge valve operability Operability confirmed from full-open position Requests that 50 degree restriction in Tech Specs be removed prior to exceeding 5% power CLAYTON:F.L. Alabama Power Co 80/09/30 3pp
- 8010280497 Notifies that proposed Mod Summary, Table 3 of Amend 11 to License NPF-2-has been incorporated into facility fire protection mod program Supersedes 790319 ltr CLAYTON F L Alabama Power Co 80/10/21 ip.
- 8010280444 Bubmits addi info re safety grade cold shutdown per 801022 request. Util will provide specific procedure for cooldown using natural circulation after completion of Diablo Canyon natural circulation tests & analyses
 CLAYTON: F. L. Alabama Power Co. 80/10/23 1p
- O Inspection reports, IE Bulletins & correspondence
- 8010020227 Forwards IE Insp Rept 50-364/80-28 on 800804-05 No noncompliance noted STOHR.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/08/21 2pp
- --8010020235 IE Insp Rept 50-364/80-28 on 800804-05 No nencompliance noted Hajor areas inspected preoperational testing health physics & chemistry procedures & startup testing procedures, TROUP.0 L Region 2. Atlanta: Office of the Director. 01880N.A Region 2. Atlanta: Fuel Facility & Materials Safety Branch 80/08/19. 3pp. CIRSON, A F
- 8010080220 Forwards IE Insp Rept 50-364/80-27 on 800624 & 0630-0702 No noncompliance noted
 LEHIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch 80/08/28 2pp
- ---8010080225 IE Insp Rept 50-364/80-27 on B00624 & 0630-0702.No noncompliance noted Major areas inspected shift technical advisor, shift supervisor duties & responsibilities & organization & mgt KELLOGG,P, BRADFORD,W Region 2, Atlanta, Office of the Director. MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/08/29 12pp
- 8010230072 Forwards 1E Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Bhipments of Radioactive Hatls" No written response required O'REILLY, J.P. Region 2 Atlanta. Office of the Director. 80/08/29.
- 8010240661 Forwards IE Insp Repts 50-348/80-23 & 50-364/80-30 on 800814-15 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/11. 2pp
- --8010240463 IE Insp Repts 50-348/80-20 & 50-344/80-30 on 800814-15
 No noncompliance noted Major areas inspected: followup of noncompliances & inspector followup items re Part 21
 evaluation & reporting matters.
 BROWLEE, V L. Region 2, Atlanta, Office of the Director,
 CONLOW, T.E. Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/09/09. Spp.
- 8010010438 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-14 & 50-364/80-16 LENIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Sranch 80/09/12 2pp.

- --8010010474 Responds to NRC 800808 ltr re violations noted in IE Insp. Repts 50-348/80-14 & 50-365/80-14 Corrective actions interin measures implemented until qualified storage space is found QA audit program revised for reaudit of corrective actions CLAYTON,F L Alabama Power Co 80/09/02 3pp
- 8010090287 Requests extension until 800924 to respond to IE Bulletin 80-20, "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Emitches "Extension is needed due to licensing & refueling activities.

 CLAYTON,F L Alabame Power Co. 80/09/16 is
- 8010100126 Forwards response to IE Bulletin 80-18. "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Site High Energy Line Rupture" Min flownate of 60 gpm required for pump operation could not be guaranteed. CLAYTON, F. L. Alabama Power Co. 80/09/23 Spp.
- 8010100133 Forwards response to IE Bulletin 80-20, "Failures of Westinghouse Type H-2 Spring Return to Normal Control Suitches," Total of 67 switches in Unit 1 & 49 switches in Unit 2 identified in sefety-related sys CLAYTON,F L. Alabama Power Co. 80/09/24. 15pp
- 8010230488 Responds to IE Bulletin 77-10, Item & re feedwater sys. pipe-to-nottle areas. & pipe supports. All areas within bulletin requirements CLAYTON.F.L. Alabama Power Co 80/09/26, 2pp.
- 8010160216 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Guslification of Class IE Equipment." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director S0/09/30.
- 8010270578 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required.

 D'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/10/02, 10
- 8010240115 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-349/80-24 & 50-364/80-31.
 STCHR.J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/10/06 1p.
- --8010240134 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 50-340/80-24 & 50-344/80-31 Corrective actions: personnel in chemistry section have been reinstructed in requirement of AP-1 & AP-7 CLAYTON,F L Alabama Power Co. 80/09/26 2pp.
- --B010240146 Forwards IE Insp Repts 30-348/80-24 & 50-344/80-31 on 800812-14 & notice of violation 870HR.J P Region 2. Atlanta, Fuel Facility & Haterials Bafaty Branch 80/09/11 2pp.
- --8010240154 Notice of violation from insp on 800812-14 * Region 2: Atlanta: Office of the Director. 80/07/11 is
- --8010240174 IE Insp Repts 50-348/80-24 & 50-364/80-31 on 800812-14 Noncompliance noted, failure to review changes in Chemistry Procedure FNP-0-CPP-A, determination of fluoride ion in aqueous solutions.

 HONTOOKERY.D.M. Region 2, Atlanta, Office of the Director.

 BTOHR.J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/09/11. 8pp.
- 8010240040 Responds to NRC 800917 ltr re IE Insp Rept 50-364/80-34. Info contained in insp rept not considered proprietary. CLAYTON: F L Alabama Power Co. 80/10/07. ip.
- ~-8010240041 Forwards IE Insp Rept 50-364/80-34 on 800820-22. No nencompliance noted MMPHY:C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/17. 2pp.
- --8010240042 IE Insp Rept 50-364/80-34 on 800820-22. No noncompliance noted Major areas inspected. Hicenee identified items, inspector followup items. IE bulletins & turnover of plant areas HUNT.M.D. Region 2. Atlanta, Office of the Director. BRYANT, J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/17. App.
- B010270043 Forwards IE Info Notice 80~36, "Failure of Steam Generator Support Bolting," No specific action or response requested O'REILLY, J. P. Region 2. Atlanta, Office of the Director, 80/10/10, 1s,

V Operator Examinations

B010080606 Summary of 800902-03 meeting w/util in Zion.IL re visit to Heatinghouse training ctr. KINTER.L.L Licensing Branch 2 WIOOINTON.D Licensing Branch 1. 80/09/18. 2pp

DOCKET 50-366 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8010210352 Forwards emend to security plan removing Nov 1977 revision of Chapter 10 & adding interim security measure Amend withheld iref 10CFR2. 790 HIDNER N A Georgia Power Co 80/10/03 1p.

O. Adjudicatory correspondence

- 8010270313 Forwards revised order for mod of license which requires submission of info to support environ qualification of safety-related electrical equipment EISELHUT.D 0. Division of Licensing 80/09/19 2pp
- --8010270317 Revised order for mod of license requiring timely submission of info previously requested re environ qualification of safety-related electrical equipment EIBENHUT:D O Division of Licensing 80/09/19 App

- 8010210778 Responds to Appling County Board of Commissioners 800825 ltr to fiscal impact studies of siting & decommissioning power plants & fiscal program adjustment NRC regulations require applicants to provide info on tax revenues & land use MULLER.D R Assistant Director for Environmental Technology 80/10/03. 2pp
- ---8010210781 Request, submitted by Appling County Board of Commissioners, for info re studies of fiscal impact of siting & decommissioning power plants on local juriedictions & NRC regulations affecting utils
 WINDHAM, J. R. Georgia, State of 80/08/25, 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010240213 Application to amend Licenses DPR-57 & NPF-5, changing FBAR. App A. Section 17.2 commitment to clarify intent to apply only to safety-related equipment Proposed fee determination, revised FBAR pages & Class I & II amend fees encl HIDNER. H. A Georgia Power Co 80/10/15 6pp
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8008130292 Notice of ACRS Subcommittee on Fluid Dynamics 800817-20 meeting in Inglewood.CA to review control rod drive insertion failures at Browns Ferry & scram discharge vol instrumentation failures at Brownswick & Hatch CHILK.S J Office of the Secretary of the Commission 80/07/30 200.
- P. Operating license stage documents & correspondence
- 80:0220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D 0. Division of Licensing, 80/09/19 28pp
- 8010210201 Forwards Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively, & notice of issuance & availability REID,R.W. Operating Reactors Branch 4 80/10/01, 3pp
- --8010210207 Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively, to include requirement to maintain sefeguards contingency plan to be implemented within 90 days REIO.R.W. Operating Reactors Branch 4 80/10/01. 4pp.
- --8010210212 Notice of issuance & availability of Amends 78 & 17 to Licenses DPR-57 & NPF-5, respectively.
 REID, R. W. Departing Reactors Branch 4 80/10/01, 2pp
- 80101303B1 Responds to request for add1 info re sys voltage study Add1 analysis results of steam voltage conditions encl. Util has modified voltage protection scheme for safety-related buses, WIDNERAW A. Georgia Power Co. 80/10/09 18pp.

DOCKETED ITEMS

- 8010190536 Forwards "Seismic Test of Diesel Generator Control Console KAL 71696 - SD 3025," in response to NRC 780522 request for addl info re seismic qualification of Fairbanks Morse static exciter cabinets Related itr encl HIDNER, W A Georgia Power Co 80/10/10 12pp
- --go10150540 "Beismic Test of Diesel Generator Control Console XAL 71676 - BD 3025" SINVELL, T , SUCEVIC, J M Westinghouse Electric Corp. EL, 486 75/04/30 11300
- B010210612 Responds to NRC 800707 itr requesting Tech Spec mods re scram discharge vol Present Tech Specs assume control drive sys operability & scram discharge vol piping is sized to assure complete scram Mods will not increase reliability WIDNER, W. A. Georgia Power Co. 80/10/10 ip
- E01023041B Application to amend Licenses DPR-57 & NPF-5, changing Tech Spacs re reactor protection sys electric power monitoring for Unit 1 & operability & surveillance of ac distribution sys Unit 2 Class III fee encl.
- --Boi0230491 Proposed Tech Specs 4 9,3 9 & 4 9 re reactor protection systematic power monitoring for Unit 1 & operability & surveillance of ac distribution sys for Unit 2 Proposed fee determination encl 4 Operation Power Co. Bo/10/15 Opp
- B010240213 Application to amend Licenses DPR-57 & NPF-5, changing FBAR.
 App A.Baction 17 2 commitment to clarify intent to apply
 only to safety-related equipment Proposed fee determination,
 revised FBAR pages & Class I & II amend fees encl
 WIDNER,W A Georgie Power Co 80/10/15 6pp
- B010270037 Responds to FOIA request for three categories of info re fees for withdrawn CP & OL applications Forwards App A documents SECY-364A & JF Absarne response sheet withheld (ref FOIA Exemptions 5) FELTON J M Division of Rules and Records 80/10/15. 2pp
- --8010270151 Notifies of completed assessment re review of costs for CP & OL actions Data sheets used to determine fee charges encl.

 BERKOH H N Office of Nuclear Reactor Regulation, Director, 79/10/30 4pp
- 8010230368 Application to amend NPF-5, changing Tech Specs re Cycle 2 operation w/Reload 1 fuel inserted Proposed fee determination & refs ent.

 HIDNER W.A. Georgia Power Co. 80/10/17 App.
- --8010230372 Proposed Tech Specs, Sections 2 O through 5 O, changing safety limits, reactor protection sys instrumentation setpoints, power distribution limits & design features re Cycle 2 operation w/Reload 1 fuel inserted.
 4 Georgia Power Co 80/10/17 lipp
- --8010230376 "Supplemental Reload Licensing Submittal for Hatch Nuclear Power Station Unit 2:Reload 1" ZANARDI.O", ENGEL:R E General Electric Co. Y1003J01A10. 80706/30 14pp
- B010310361 Responds to B01001 request re participation in development of scram sys design & performance criteria Not active member in subgroup considering criteria Plans to consolidate reviews of design rather than performing separate reviews WIDNER.H A Georgia Power Co. B0/10/24 app.
- @ Inspection reports: IC Bulletins & correspondence
- 8010170271 Forwards IE Insp Repts 50-321/80-33,50-344/80-33, 50-424/80-11 & 50-425/80-11 on 800730-31 & 0804. No nencempliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. 80/08/25 2pp.
- --8010170278 IE Insp Repts 50-321/80-33, 50-366/80-33, 50-424/80-11 & 50-428/80-11 on 800730-31 & 0804 No nancompliance noted.

 Major areas inspected followup on items relative to 100FR21.

 BROWNLEE, V L. Region 2, Atlanta, Office of the Director.

 CONLON.T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/08/21 3ep
- 8010200628 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls " D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/08/29

- 8010070273 Confirms schedule of masonry well evaluations, in response to IE Bulletin 80-11, "Masonry Wall Design " Change is necessitated by delay in receipt of computer code used for wall re-evaluations.

 WIDNER, W. A. Georgia Power Co. 80/09/16 ip
- 8010160041 Forwards order imposing civil monetary penalty per util 800714 response to 800619 notice of violation & notice of proposed imposition of civil penalty.

 DEYOUND, R C Office of Inspection & Enforcement, Office of the Director 80/09/24 3pp
- --8010160047 Order imposing civil monetary penalty in amount of \$4,000 for item of noncompliance noted in 800617 notice of violation re excessive radiation exposure rate inside cab of vehicle transporting waste DEYOUND,R C Office of inspection & Enforcement, Office of the Director 80/09/24 6pp
- 8010140003 Ack receipt of 800910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-31 k 30-366/80-31 LEWIG.R.C. Region 2. Atlanta, Reactor Operations Nuclear Susport Branch, 80/09/29
- --BolG140005 Responds to NRC 800815 ltr re violations noted in IE Insp Repts 50-321/80-31 & 50-366/80-31. Corrective actions proper valve lineup for major flow paths & min flows of all ECCB sys verified WIDMER.W A Georgia Power Co. 80/09/10. 2pp
- --8010140008 forwards IE Insp Repts 50-321/80-31 & 50-346/80-31 on 800610-0714 & notice of violation LEWIS,R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 80/08/15. 2pp
- --8010140010 Natice of violation from insp on 800610-0714 * Region 2, Atlanta, Office of the Director. 80/08/15 ip.
- --8010140013 IE Insp Repts 50-321/80-31 & 50-346/80-31 on 800610-0714. Noncompliance noted failure to properly align valves in safety sys & failure to correct seismic deficiencies in timely manner. RODERS:R F Region 2. Atlanta. Office of the Director. DANCE,H C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 80/08/15 7pp
- B010160157 Forwards Buppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. B0/09/30. ip
- 8010270549 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/02,
- 8010240903 Ack receipt of 800919 8 23 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-28 % 50-366/80-28 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/10/09.
- ---8010240005 Responds to NRC 800918 telcon re violations noted in IE Imap Repts 50-321/80-28 & 50-366/80-28, Corrective actions: preparation of document index to identify authorized drawings or manuals re safety-related glant procedures. MILLER.H J Georgia Power Co 80/09/23 5pp.
- --B010240007 Responds to NRC B00822 ltr re violations noted in IE Insp Repts 50-32:/80-29 % 50-356/80-28 Corrective actions:manager of GA will be provided closer access to company executives concerned w/activities re nuclear safety. MILLER, J. H. Georgia Power Co. 80/09/15 17pp.
- --8010240009 Forwards IE Insp Repts 50-321/80-28 & 50-366/80-28 on 800707-11,14-18 & 22-24 & notice of violation. O'REILLY, J P. Region 2, Atlanta, Office of the Director, 80/08/22, 2pp.
- --8010240010 Notice of violation from insp on 800707-11,14-18 & 22-24.

 * Region 2: Atlanta: Office of the Director. 80/08/22 7pp.
- --8010240012 IE Insp Repts 50-321/80-28 & 50-366/80-28 on 800707-11, 14-18 & 22-24, Noncompliance noted: failurs to executa/establish insp groppem, failure to resudit deficient areas & failure to respond to audit finding repts.

 BELISLE, Q.A., FREDRICKBON, P., PRICE, D.S., Region 2, Atlanta, Office of the Director, 80/08/22 47pp.

- 8010290047 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested D'REILLY, J P Region 2. Atlanta, Office of the Director 80/10/10 ip
- B010210303 Forwards payment of civil penalty per NRC 800924 order re excessive radiation exposure rate inside tractor cab of vehicls transporting waste to Barnwell.5C WIDNER:MA Decords Power Co 80/10/15 ip
- R Periodic operating reports & related correspondence
- B010170412 Forwards "Annual Environ Surveillance Rept. 1979 "
 HANRY, M Georgia Power Co 80/03/28 1p
- --8010170422 Forwards "Annual Environ Surveillance Rept.1979 " MANRY.H Georgia Power Co 80/03/28 1p
- --8010170431 "Annual Environ Surveillance Rept,1979 "
 4 Georgia Power Co 80/03/28 240pp
- 8010210410 Forwards monthly operating rept for Sept 1980 MANRY: M Georgia Power Co 80/10/10 1p
- --8010210414 Monthly operating rept for Sept 1980 UNDERHOOD, P R Georgia Power Co 80/10/10 7pp
- S Reportable occurrences, LERs & related correspondence
- 8010160642 PND-II-80-128 on 800726 unit was manually scrammed to test scram discharge vol Two of four scram level float switches failed to actuate All other sys performed normally during scram TAYLOR, P A , DANCE, H C Region 2, Atlanta, Office of the Director 80/07/28 1p
- E010040240 Forwards LER E0-127/03L-0 MANRY,M Gaorgia Power Co 80/09/23 1p
- --8010060245 LER 80-127/03L-0 on 800830.during normal operation, 2C diesel generator failed to start Cause not known Investigation initiated & generators tested every three days. Updated rept to be submitted pending results C000IN C L Georgia Power Co. 80/09/23 2pp.
- 8010170100 EN-80-023A on BD0924, order was issued imposing civil penalty of \$4,000 dased on item of nuncompliance re excessive radiation levels in transport vehicle BROCKETY, T. THOMPBON, D. Diffice of Inspection & Enforcement, Office of the Director B0/09/24 ip
- 8010070471 Advises that LER 80-128/03L-0 issued on 800923 should be disregarded 5 replaced w/LER issued on 800925 PALMER, C. Georgia Power Co 80/09/26 is
- 8010040242 Forwards LER 80-132/03L-0 MANRY.M Georgia Power Co 80/09/30 1p
- --8010060249 LER 80-132/03L-0 on 800910, pressure switch 2E21-N008B activated at 94 psig rather than 100 psig Gaused by setpoint drift Switch recalibr & trated successfully NIX,R T Georgia Power Co 80/09/30 2pp.
- 8010040254 Forwards LER 80-131/03L-0 MANRY:M Georgia Power Co 80/09/30 ip.
- --B010060259 LER 80-131/03L-O on 800907, reactor pressure switch 2831-Noi86 actuated at 162 psig rather than 135 psig. Caused by setpoint drift Switch recalibr & tested successfully NIX-R.Y Georgia Power Co 80/09/30. 2pp
- 010050357 Forwards LER 80-130/03L-0 MANRY: M Georgia Power Co 80/09/30 1p
- --8010060360 LER 8D-130/03L-0 on 800913, during steady state operation, 2P33-P001A, primary containment hydrogen & oxygen analyzer was discovered inoperable Cause not determined Analyzer was adjusted & currently operating progenty NIX.R T. Georgia Power Co. 80/09/30 2pp.
- 10080375 Forwards LER 80-129/032-0. MANRY:M Georgia Power Co 80/09/30 ip.

- --8010080382 LER 80-129/03L-0 on 800918 during surveillance on torus/ drywell vacuum breakers.2T48-F3230 valve failed to open upon test suitch actuation Cause not known as valve inaccessible valve will be inspected & repaired during cold shutdown NIX.R T Ocorgia Power Co 80/09/30 2pp
- 8010160472 Forwards LER 80-133/03L-0 MANNY,M Georgia Power Co 80/10/09 1p
- --8010160475 LER 80-133/03L-0 on 800923 reactor water lavel switches 1 & 2 tripped at 121 & 123 inches of water, respectively, contrary to Tech Spec max of 117 19 inches Caused by setpoint drift Switches recalibr & tested successfully NIX.R T Georgia Power Co 80/10/09 2pp
- 8010220493 Forwards LER 80-136/01T-0 MANRY, M Georgia Power Co 80/10/14 1p
- ---B01022049A LER B0-136/01T-0. on 800930. Bechtel notified util that PSW div I line was inadequately supported when subjected to OBE or DBE loads Caused by failure to install 3-directional support. Support Installed CQ00IN.C L. Georgia Power Co. B0/10/14 2pp
- 8010220488 Forward: LER 80-135/03L-0 MANRY, M Ocorgia Power Co 80/10/16 ip.
- --8010220489 LER 80-135/03L-0 on 800928, reactor conductivity increased & chlorides were found to exceed Tech Specs Caused by tube lask in D water box Tube repaired & reactor water cleaned ROCERS.U H Georgia Power Co 80/10/16 2pp
- 8010280213 RO on 801009, following reactor screm on low reactor water level due to loss of feedwater, HPCI tripped on high reactor water level Caused by HPCI auto initiating on low reactor water level & injecting into reactor HANRY.M Georgia Power Co 80/10/21 2pp
- 8010280375 Forwards LER 80-139/01T-0 MANRY, M Georgia Power Co 80/10/21 1p
- --8010280377 LER 80-139/01T-0 on 801008.AE notified of improper placement of anchor 2011-RAD-A91. resulting in seismic vulnerability of containment isolation valve 2011-F020 Caused by failure to follow original design. Order to close valve issued CD09IN, C L Georgia Power Co 80/10/21 2pp
- 8010280421 Forwards LER 80-134/03L-0 MANRY M Osorgia Power Co 80/10/21 ip
- --8010280425 LER 80-134/03L-0 on 800925 during HPN-2-3154 LPCI 2821-N031A reactor level switch: switches 3 & 4 tripped at 122 inches water autput Caused by component failure due to pointer binding Pointer straightened & instrument calibr NIX:R T Georgia Power Co 80/10/21 1p
- 8010280470 Forwards LER 80-137/03L-0 MANRY,M Georgia Power Co 80/10/21 ip
- --8010260476 LER 80-137/O3L-O on 800927, during plant shutdown, while performing HPCI turbine exhaust diaphragm functional test & calibr, pressure switch actuated contrary to Tech Spec. Caused by setpoint drift Switch recalibr & functionally tested NIX.R T Georgia Pawer Co 80/10/21, 2pp
- 8010310304 Forwards LER 80-140/03L-0 MANRY,M Georgia Power Co 80/10/23 1p
- --8010310410 LER 80-140/03L-0 on 801009, suppression chamber drywell vacuum breakers were not tested during safety relief valve G operation Caused by operator error Breakers were tested upon discovery of error BAXLEY, 8 X. Georgia Power Co 80/10/23 2pp.
- 8010310349 Forwards LER 80-034/03L-0 requested during 801021 telcon. BDYLE, E. Licensee Operators Evaluation Branch. 80/10/23. 19
- V Operator Examinations
- 8010280385 Forwards revised license requalification program in response to NRC 800329 request re operator training & licensing MANRY, M Georgia Power Co 80/09/12. 1p
- --8010280389 License requalification program,
 4 Gargia Power Co 80/09/12 8pp

- DOCKET 50-367 BAILLY GENERATING STATION
- A Application/construction stage documents & correspondence
- 8010020379 Discusses monitoring of ground water levels in vicinity of util & Cowles Bog Natl Landmark Map indicating location of old & new wells & water well records encl LAPHMIN W Interior. Dept of, Geological Survey 80/08/26 18pp
- 8010070475 Summary of 800805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads Discussion topics, attendence & meeting handouts encl ANDEREON.C J Generic Issues Branch 80/08/29 98pp
- B010060102 Summary of 800904-05 meeting w/Mark II owners in Bethesda.MD re long-term program chugging & lateral loads Attendance list & handouts encl ANDERSON.C J Generic Issues Branch 80/09/12 65pp
- 80:0220079 Forwards strata sheets amending 800905 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing 80/07/19 28pp
- 801027023B Notification of 80100B meeting w/representatives from Mark II owners group in Bethesda, MD to discuss Mark II plants chugging load spec ANDERBON.G Generic Issues Branch 80/09/22 ip
- BO10140327 Requests that NRC prepare supplemental E18 addressing impacts of const dewatering on Cowles Bog Natl Natural Landmark Decision to renew CP & const activities should be delayed until issuance

 ANORUS, C D Interior, Dept of 80/10/03 2pp.
- B010200445 Forwards open-file Rept B0-1105, "Reassessment of Effects of Const Dewatering on Ground-Water Levels in Cowles Unit, IN Dunes Nati Lakeshore, IN." suppl to water-resources Investigations 78-138 BTEWART, D K Interior, Dept of, Geological Burvey 80/10/03 1p
- --B010200447 Open-File Rept 80-1105, "Reassessment of Effects of Const Deuatering on Oround-Water Levels in Coules Unit, IN Dunes Natl Lakeshore, IN, " suppl to water resources Investigations 78-138 GILLIES, D. C., LAPHAN, W. W. Interior, Dept of, Geological Survey 80-1105 80/09/30 56pp
- BO102B0487 Forwards UBOB rept, "Reassessment of Effects of Const Dewatering on Ground-Hater Levels in Cowles Unit, IN Dunes Natl Lakeshore, IN " LYNCH, H D Licensing Branch i BO/10/08 2pp
- B010270359 Discusses Secretary of Interior B01003 ltr to NRC re impact of dewatering at facility Util is preparing detailed response to ltr & USGS repts Bummary of major points encl BHORBLE M Northern Indiana Public Service Co. 80/10/21 10pp.

Q Adjudicatory correspondence

- 8010020034 Advises of inability to attend oral argument Volen will read limited appearance statement on behalf of author SCHMIDT. 9 Affiliation Unknown 80/09/25 ip
- B010030510 Response in apposition to Porter County Chapter 800821 first request for production of documents Moves for protective order re Requests 2,8,9,12,13 & 24 & requests re consultants & contractors, W/Certificate of 89c Related correspondence EICHHORN, W H Northern Indiana Public Service Co EICHHORN, W H Eichhorn, Eichhorn & Link, * Lowenstein, Neuman, Reis, Axelrad & Toll 80/09/26. 5pp
- BO10020047 Motion for filing of encl reply brief re util contention that ABLB has erroneously found that City of Cary. IN. et al have standing for intervention Oranted on BO0930 COHN. D. B. SCHULTZ. W. B. Gary. IN. COHN. D. B. Cohn. D. B. 80/09/29
- --B010020055 Reply brief in form of pleading in opposition to util contention that ABLB has erroneously found that City of Qary, IN. et al have standing for intervention Certificate of Bvc encl COHN, D B / BCHULTZ, W B, Qary, IN, COHN, D B Cohn, D B, B0/09/29 100s

- 8010020743 Memorandum advising that G Sthultz brief statement may be read by RJ Vollen at 801002 oral argument Conference call not possible TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 80/09/29 200
- 8010060269 Requests that S Sekuler be substituted for D Hansell as counsel in Northern IN Public Byo Co case DUNTON, P Illinois, State of 80/09/29 ip
- 8010030435 Order denying intervenor Porter County Chapter motion re EIS.for reasons stated in ASLO 800926 order denying State of IL similar motion OROSSMAN, H. Atomic Safety and Licensing Board Panel 80/10/01 ip
- 8010070021 Order denying util.NRC.State of IL & Porter County Chapter objections to ASLB 800807 & 25 final orders ruling on intervention potitions Rulings unchanged GROSMAN, H Atomic Safety and Licensing Board Panel 80/10/02
- B010140498 Responds to Porter County Chapter 800917 request for designation of witnesses for deposition MD Lynch will be available for deposition on 801030 & 31 NRC has begun compilation of affected documents GODDARD, R J Hearing Branch 2 80/10/07 2pp
- 8010140006 Comments in opposition to Porter County Chapter & State of IL memoranda supporting admissibility of newly filed contentions Contentions not relevant to good cause criteria Cartificate of Svc enci.

 OGLOBERO, S C Hearing Branch 2 80/10/08 7pp
- 8010150455 Forwards comments on behalf of util re 800924 ltr from six organizations to NRC on ABLB proceeding about util application for extension to const completion date New info & allegations do not warrant suppl EIS W/Certificate of Evc. SHEALK H , LOWENSTEIN, R , NEWMAN, J R Lowenstein, Newman, Reis, Axeirad & Toll 80/10/10 lipp
- 8010160787 Response in opposition to util 800828 response to Porter County Chapter revised contentions Contentions raise issues re delay Contentions R-I 1 through R-I 9 & R-I 13 should be admitted. Certificate of Svc encl HICHER, J. M. VOLLEN, R. J. , OSANN, E. W. Izaak Walton League of America, Porter County Chapter 80/10/10 10pp
- B0102303B1 Requests info on selection process for accepting intervenors' petitions re NRC 800923 news release that intervenors were denied chance to petition Board on CP extension RONVIK:A Affiliation Unknown 80/10/13 ip
- 8010160538 Request for encl protective order re intervenor BPI 800821 request for production of certain contracts to supply NSBS & penerator for facility pending admission of contentions & examination of request Certificate of Svc encl
 EDOAR.Q L General Electric Co 80/10/14 12pp
- 8010200184 Reply in opposition to ERC & util 800822 & 28 responses; respectively, to State of IL newly filed contentions, Changes in regulations & ACRS consideration of safety questions form basis for admissibility, Certificate of 8vc encl BEKULER, 8 N . FAHNER, T C Illinois, State of 80/10/14 lipp
- 8010200589 Request for order to compel production of documents from util Util must produce documents over which util has control even if not in util possession Cause for protective order not shown H/Cerfificate of Svc Related correspondence VOLLEN,R J , WHICHER,J H , OSANN,E W Izaak Maiton League of America, Porter County Chapter. 80/10/14, 7pp
- 8010200669 Request for deferral of further response to Izaak Walton League. Porter County Chapter 800821 request for production of documents until AGLB rules on GE 801014 motion Certificate of Syc enci Related correspondence SHEA.K. H. Northern Indiana Public Service Co. SHEA.K. H. Lowenstein, Neuman, Reis, Axelrad & Toli 80/10/14. 4pp
- 8010210776 Motion orging issuance of order for D Lynch deposition in Chicago, IL No NRC witness appeared for 801015 deposition.

 Certificate of Svc encl Related correspondence.

 VOLLEN, 8 J . OSHAN, E W Izaak Walton League of America, Porter County Chapter VOLLEN, R. J Vollen, R J 80/10/17. 7pp.
- --8010210780 Notification of 780517 meeting w/util & const companies in Chicago, IL to discuss NRC questions & positions re util rept SL-3627 on present foundation proposal LYNCH,M C. Light Water Reactors Branch 4, 78/05/12 2pp

- B010240408 Forwards EW O'Rorke affidavit supplementing OE B01014 motion for protective order in matter of CP extension Notice of special appearance & Certificate of Svc encl FIRESTONE, E A General Electric Co 80/10/17 12pp
- 8010230696 Corrections to State of IL reply re NRC & util responses on neuly filed contentions SEKULER, S N Illinois, State of BO/10/22 ip
- 8010240492 Requests confirmation of delegation of authority to LS Rubenstein per notice of apportunity for hearing on application for CP extension Requests advice re source of delegation BISHOP.C.J Atomic Safety and Licensing Appeal Panel. 80/10/22
- 8010270508 Advises that most answers to 801013 ltr will be found in ASLB 800807 order available in LPDR Decision re Schultz & City of Oary, IN et al not yet issued BISHDP, C J Atomic Bafety and Licensing Appeal Panel 80/10/23
- 8010280615 Advises that NRC will take no position re applicant 800926 motion for protective order & Porter County Chapter 801014 motion to compel re intervenor discovery requests COLDBERG. S C Hearing Branch 2 80/10/29 ip
- B010290401 Response in apposition to Parter County Chapter 800918 second request for production of documents Moves for protective order re Requests 9.10 or 11 Certificate of Svc encl Related correspondence EICHHORN, W.H. Northern Indiana Public Service Co. EICHHORN, W.H. Eichhorn, Eichhorn & Link. 80/10/23 opp
- 8010300061 Partial response in opposition of GE motion for protective order Motion presumptuous due to GE status as non-party from whom discovery is not sought VOLLEN,R.J. trask Walton League of America, Porter County Chapter VOLLEN,R.J. Vollen, R.J. 80/10/24 Spp.
- --8010300069 Motion for extension until 10 days following completion of limited discovery Time necessary for response to issue raised by OE re contracts containing commercial info VOLLEN.R J 12a4k Malton League of America, Porter County Chapter VOLLEN.R J Vollen, R J 80/10/24 2pp
- --8010300079 Second motion for production of documents directed to util who failed to object or move for protective order Contracts w/GE re supply of nuclear steam sys must be inspected Util request for deferral must be denied VOLLEN.R J Izaak Walton League of America, Porter County Chapter VOLLEN.R J Vollen, R J 80/10/24 2pp.
- --8010300098 Notice of EM D'Rorke deposition on 801117 re D'Rorke 801017 Affidavit filed in proceeding Cartificate of 8vc encl VOLLENR J Izaak Malton League of America, Porter County Chapter VOLLENR J Vollen R J 80/10/24 4pp
- 8010300049 Discusses Director of Nuclear Reactor Regulation licensing authority, in response to 801022 ltr & forwards licensing project managers handbook & HR Denton 801016 memo redelegation of signature authority GOLDBERO
- --8010300048 Bubmits Ofc Ltr 26 re delegation of signature authority, Revision 4 Forwards 25 items superseding Dfc of Nuclear Reactor Regulation 800705 ltr.Revision 3 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/10/16 6pp
- 8010300040 Forwards specific sections of NRC Manual Chapter 0123 re 80 Goldberg 801027 ltr.Footnote 1 Sections revised on 800523 to reflect recent NRC reorganization OGLDBERG.S.C Hearing Branch 2 80/10/28 19
- 8010300055 Advises of NRC intention to take no position re discovery pleadings between Porter County Chapter & applicant QDLDBER0,8 C Hearing Branch 2 80/10/28 lp.
- 8010300587 Memorandum & order advising parties to comment upon NRC 801027 response re LS Rubenstein delegated authority, by 801105; if desired 818H0P.C J Atomic Bafety and Licensing Appeal Panel 80/10/28

- H General correspondence
- 8010210361 Responds to Mar 1980 comments made at White House issues briefing session AUREC-0623 is not intended to be sole basis for judging sites Evacuation plans considered in licensing actions leading to CP Foundation will be evaluated DENION-R R Office of Nuclear Reactor Regulation. Director 80/10/14 Spp
- 9 Inspection reports, IE Bulletins & correspondence
- 8010160272 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER.J.O Region 3. Chicago, Office of the Director B0/09/30 ip
- 8010280659 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/10/02
- B010270028 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER.J G Region 3. Chicago, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- 8010070475 Forwards well charts for 800917-24, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USOS wells for 800924 Gorrects water meter reading for 800917
 80HN,R J Northern Indiana Public Gervice Co 80/10/01 73pp
- B010150329 Forwards well charts for 800924-1001, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & US98 wells for 801001

 B01N, R J Northern Indiana Public Service Co 80/10/10
- B010210526 Forwards well charts for B01001-08. & Bailly wells w/o recorders.pond levels.pneumatic pressure transducers.water meter readings & UB08 wells for B01008 Info describing dewatering sys for ash pond sealing program encl B0HN.R J Northern Indiana Public Service Co B0/10/17 35pp
- T Hearing transcripts on non-antitrust matters
- 8010190177 Transcript of 801002 morning oral argument in Bethesda.MD re CP extension Pp 1-88 s Atomic Safety and Licensing Appeal Panel 80/10/02 87pp
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2
- A Application/construction stage documents & correspondence
- BO10240841 Application for Amend 50 to application for license, amending FSAR by correcting errors & omissions & updating shop tests & water chamistry sections
 CAVARAUGH, W. Arkansas Power & Light Co. 80/10/10 2pp
- --8010240542 Amend 50 to license application.consisting of Amend 50 to FSAR correcting errors & updating shop tests & water chemistry sections * Arkansas Power & Light Co 80/10/10 6pp
- F Security, medical, emergency & fire protection plans
- 8010070510 Requests extension until 801101 for implementation of fire protection safety evaluation Itoms 3 2.3 16,3 5,3 7,3 11, 3 12.3 14 & 3 18 will not be complete by 801001 TRIMBLE, D C Arkansas Power & Light Co 80/09/26. 3pp
- 8010070293 Notifies that security sys has been operable since 601001 TRIMBLE, D.C. Arkansas Power & Light Co. 80/10/01 1p
- O Adjudicatory correspondence
- B01016060B Forwards revised 800829 order, correcting refs Date for which hearing may be requested also revised EISENHUT, D 0 Division of Licensing 80/09/19 1p.

- --B010160617 Order directing licenses to respond fully & completely to IE Bulletin 79-018, re environ qualification of Class IE equipment by 801101 EISENHUT.D & Division of Licensing 80/09/19 App
- 8010280472 Requests 1-wk extension of time to request hearing on 800919 orders to respond to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Imminent issuance of Suppl 3 to subj bulletin may resolve util concerns REYNOLDS:N 8 Debevoise & Liberman 80/10/23 2pp
- 8010310432 Notifies of util withdrawal of 801023 request for extension to patition for hearing on orders for mod of facility licenses re environ qualification of Class IE equipment IE Bulletin 79-010.Suppl 3 revises requirements of orders REYNOLDS,N 8 Debavoise & Liberman 80/10/30 ip
- % Utility Final Safety Analysis Report (FSAR) & amends
- B010240541 Application for Amend 50 to application for license, amending FSAR by correcting errors & omissions & updating shop tests & water chemistry sections CAVANAUGH, W Arkansas Fower & Light Co 80/10/10 2pp
- ---8010240542 Amend 50 to license application, consisting of Amend 50 to FBAR correcting errors & updating shop tests & water chemistry sections Arkanses Power & Light Co 80/10/10 App
- B0102B0227 Forwards affidavit certifying that proper agencies & organizations have been served Amend 50 to FSAR TRIMBLE.D C. Arkansas Power & Light Co. 80/10/20 2pp
- P Operating license stage documents & correspondence
- B010010613 Submits info that demonstrates benefits of Core Performance Calculators/Control Element Assembly Calculators plant computer datalink Requests NRC concurrence to allow permanent operation of datalink
 TRIMBLE.D C Arkansas Power & Light Co 80/09/03 2pp
- 8010010535 Discusses review of util response to NRC 791109 ltr re ECC8 swaluation models dealing w/fuel cladding swelling & incidence of rupture Response is acceptable No further action is necessary CLARK.R A. Operating Reactors Branch 3 80/09/10 2pp
- B010070494 Application for amend of License NPF-5, changing Tech Specs 4 7 1.25 to hormal flow path of turbine-driven emergency feedwater sys train Class III fee enci CAVANAUGH. W. Arkansas Power & Light Co. 80/09/17 4pp
- --8010070498 Proposed Tech Specs 4 7 1 2b verifying normal flow path of turbine-drivan emergency faedwater sys train. * Arkansas Power & Light Co. 80/09/17 1p
- 8010070229 Confirms 800919 telefaxed authorization of Tech Bpec changes to Sections 3 6 2 3 % 4 6 2.3 re containment cooling group operability % svc water chlorination License amend & supporting matis will be sent upon completion NOVAK: T. M. Assistant Director for Operating Reactors 80/09/19.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMT action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O. Division of Licensing 80/09/19. 28pp
- 8010070280 Advises that plant procedures re waste gas sys hydrogen dioxide limits have been modified Waste gas sys will be returned to Region A within 24-h upon entry into Region B Modified Tech Specs will be submitted by 601031.

 TRIMBLE, D C Arkansas Power & Light Co 80/09/26. 3pp.
- 8010070308 Forwards request for Tech Spec change to reflect personnel reorganization Fee encl CAVANAUOH, W Arkansas Power & Light Co 80/09/29 2pp
- --8010070310 Proposed Tech Specs. Baction 6, reflecting personnel reorganization

 4 Arkansas Power & Light Co. 80/09/29 25pp.
- 8010070461 Forwards response to Item 3.0. Bubtopics a & b. of NRC 800805 ltm. Info addresses Drawings 234-803 & Drawings 234-804 TRIMBLE.D.C Arkensas Power & Light Co. 80/10/01 2pp.

- B010210434 Comments on new TMI action plan requirements Use of Reg Ouide 1 97.Revision 2.as basis of design requirements for instrumentation is inapprapriate TRIMBLE.D C Arkansas Power & Light Co B0/10/07. App
- 8010170512 Corrects util 800926 ltr re waste gas sys hydrogen/oxygen limits Corrected limits are 66 5% of relief valve setting for Units 1 & 2 TRIMBLE, D C Arkansos Power & Light Co 80/10/08 1p
- 8010170523 Notifies that util commitment has been fulfulled re environ monitoring program to rept large scale occurrences of bird impaction events on cooling tower structure Results submitted in 1978 & 79 annual environ operating repts TRIMBLE.D C Arkenses Power & Light Co 80/10/09 ip
- 8010270037 Responds to FOIA request for three categories of info refees for withdrawn CP & OL applications Forwards App A documents BECY-0344 & JF Ahearne response sheet withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 80/10/15. 2pp
- --801027015; Notifies of completed assessment re review of costs for CP & OL actions Data sheets used to determine fee charges and BERKON, H N Office of Nuclear Reactor Regulation, Director 79/10/30 4pp.
- 8010220499 Responds to NRC questions re util 800929 reorganization Tech Spac change request Functions of operations assessment superintendent: plant controller, special projects & health physics consultant outlined TRIMBLE, D.C. Arkansas Power & Light Co. 80/10/16 App
- 8010280331 Responds to NRC 801001 request for info re environ qualification testing of safety-related equipment for next 2 yrs Util review underway in response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment "TRIMBLE,D C Arkansas Power & Light Co 80/10/16 2pp.
- 8010310986 Responds to Tech Spec changes proposed by Revision 3 to NUREG-0103 & Revision 1 to NUREG-0202 re administrative controls Forwards proposed Tech Specs & Class III & I amend request per 10CFR170 22 CAVANAUGH, H Arkansas Power & Light Co 80/10/20. 4pp
- ~-8010310294 Proposed changes to Tech Bpecs & 11 1 & 6,11 2 for Unit 1 & 6 12 1 & 6 12 2 for Unit 2; implementing stricter administrative controls in high radiation areas 4 Arkansas Pawer & Light Co 80/10/20 2pp
- 8010310394 Responds to NRC info request on RCB pressure isolation theck valves Submits dates of last visual internal insp & individual hydrostatic test & next plant outage TRIMBLE.D C Arkansas Power & Light Co B0/10/24 2pp
- 8010310345 Informs of implementation plans re NUREG-0578 Category B requirements Unit 2 presently meets Category B requirements for Items 2 1,5,2 1 7 & 2 1 7 b Btatus of other items encl TRIMBLE.D C Arkanses Power & Light Co 80/10/27
- G Inspection reports, IE Bulletins & correspondence
- 8010160712 Responds to IE Bulletin 80-16 Transmitters installed at facility do not have output codes affected by bulletin. TRIMBLE.D C Arkansas Power & Light Co 80/07/31 3pp.
- 8010210246 Notifies that complete response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," wil be provided by 800818, upon receipt of hydramotor actuator info from ITT TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/31 ip
- 8010200621 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Bhipments of Radioactive Matls " BNIEZEK.J H Division of Fuel Facility & Materials Safety 80/08/29. ip
- 8010240024 Forwards IE Insp Repts 50-313/80-15 & 50-369/80-15 on B00722-0821 & notice of violation MADBEN.O L. Region 4. Dallas. Reactor Operations Nuclear Support Branch, B0/09/03 Zpp
- --8010240026 Notice of violation from insp on 800722-0821 * Region 4, Dallas, Office of the Director, 80/09/03

- --B010240028 IE Insp Repts 50-313/H0-15 & 50-368/H0-15 on 800722-0821
 Noncompliance noted anticontaminated clathing sampled found
 to have contamination levels exceeding established limit of
 Q i mean/hour
 JORNSON.W D . CALLAN.L J Region 4, Dallas, Office of the
 Director HUNICUTT,D M Region 4, Dallas, Reactor Operations
 Nuclear Support Branch 80/09/03 14pp
 - Nuclear Support Branch 80/09/03 14pp
- 8010240112 Responds to IE Bulletin 80-15. "Possible Loas of Emergency Notification Sys (ENS) w/Loss of Offsite Power " Insp conducted on 800627 to verify that ENS is powered unsite, TRIMBLE, D C Arkansas Power & Light Co 80/09/03 2pp
- B010210600 Forwards IE Mgt Meeting Repts 50-313/80-14 & 50-348/80-14 on 800820 No noncompliance noted Performance evaluation encl MADBEN.O L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/09/05 App
- --G010210405 IE Mgt Meeting Repts 50-313/60-14 & 50-369/60-14 on 600820 No noncompliance noted Major areas discussed activities at site from 790101 to 600819 CALLARIA J. J. GAGLIARDO J. E. HURNICUTT, D. M. Region 4, Dallas, Office of the Director 80/09/05 4pp
- 8010270333 Responds to IE Bulletin 80-22 No Westinghouse Type N-2 suitches are installed on any safety-related equipment at facilities ${\rm TRIMBLE,D,C} \quad {\rm Arkansas} \ {\rm Power} \ \& \ {\rm Light} \ {\rm Co} \quad 80/09/09 \quad {\rm 1p}$
- 8010300025 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
 No written response required
 SEYFRIT.K V Region 4, Dalias, Office of the Director 80/09/10
 ip
- 8010010021 Ack receipt of 800827 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-11 & 30-368/80-11 MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/09/12 Ip
- --8010010024 Responds to NRC 800808 ltr re violations noted in IE Insp. Repts 50-313/80-11 & 50-368/80-11 Corrective actions. Tech Specs change will be submitted allowing entry into Mode 3 w/one pressurizer safety valve inoperable TRIMBLE. D.C. Arkansas Power & Light Co. 80/08/27 Spp.
- B010240085 Updates B00703 response to IE Bullstin 80-11, "Masonry Hall Design" Schedule for completion of encl testing program to determine shear strength of monitor in collar joints has been delayed to B10316 GAVANAUOH, H. Arkansas Power & Light Co. 80/09/15 7pp
- B010230081 Forwards response to 800829 request to re-evaluate & describe actions to be taken re IE Info Notice 80-06. "Notification of Bignificant Events." Util notification requirement expanded TRIMBLE D C Ariansas Power & Light Co 80/09/18 Spp
- 80:0270424 Forwards IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination " No specific action or response requested BEFFRIT.K V Region 4, Dallas, Office of the Director 80/09/26
- 8010160095 Forwards Suppl 2 to 1E Bullstin 79-018. "Environ Qualification of Class IE Equipment " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/09/30 lp.
- 80(0270571 Discusses IE insp on 800617-20 & 0714-18 & forwards notice of violation & notice of proposed imposition of civil penalty BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/10/20 2pp
- --8010270574 Notice of violation from insp on 800617-20 & 0714-18 Noncompliance notes failure to conduct requalification lectures & to conduct performance evaluation a Office of Inspection & Enforcement, Office of the Director 80/10/20, [3pp]
- --8010270577 Notice of proposed imposition of civil penelty in amount of \$21,500 00 for item of noncompliance noted in IE image on 800617-20 & 0714-18

 + Office of Inspection & Enforcement, Office of the Director 80/10/20

- B010280472 Requests 1-wk extension of time to request hearing on B00919 orders to respond to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Imminent issuance of Suppl 3 to subj bulletin may resolve util concerns REYNOLDS, N 8 Debayoise & Liberman B0/10/23 2pp
- R Periodic operating reports & related correspondence
- B010070442 Advises that util B00915 ltr erroneously stated that ltr was forwarding Jul instead of Aug monthly operating rept
 TRIMBLE.D C Arkensas Power & Light Co 80/09/22 1p
- 8010210424 Forwards monthly operating rept for Sept 1980 TRIMBLE D C Arkansas Power & Light Co 80/10/15 1p
- --801021042B Monthly operating rept for Sept 1980 PENDERORAFT: R. Arkansas Power & Light Co 80/10/15 11pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010070150 PND-IV-RO-027; on 800821; all offsite talephone communication, including microwave sys; was lost for 3-h because of forest fire near plant site Caused by heat damage to aerisl telephone lines JOHNBOIM D; HUNNICUTT.D M; MADBEM, O L Region 4, Dallas, Office of the Director 80/08/22 2pp
- 8010070489 RO 80-072 on 800903, review of 800820 containment coolant surveillance test revealed inadequate svc water flows through containment cooling unit coolers Causad by severe plugging of svc water flow instrument sensing lines O'HANLON, J P Arkansas Power & Light Co 80/09/04 2pp
- B010060097 PND-IV-80-028A followup investigation into low svc water flow to containment cooling coils revealed partial to total flow blockage due to accumulation of clams, mud, silt & corrosion products Significant fouling identified HURNICUTT, D M , MADSEN, G L Region 4, Dallas, Office of the Director B0/09/18 ip
- B010D70563 Forwards updated LER 80-058/03X-1, TRIMBLE, D C Arkansas Power & Light Co 80/09/28 1p
- --8010070577 Updated LER 80-058/03X-1 on 800828.during Mode 1 operation. CEAC 2 failed on two separate occasions Cause undetermined CEAC 2 reinitialized per sys periodic test procedure All failure indications returned to normal PENOLRGRAFT.R Arkansas Power & Light Co 80/09/28 1p
- 8010070375 Forwards LER 80-045/04X-1 TRIMBLE.D C Arkansas Power & Light Co 80/09/29 1p
- --8010070384 LER 80-045/04X-1 on 800702, during Mode 3 & on 800803 furing Mode 1, condenser offgas radiation monitor 2RE-0649 found inoperable Caused by erratic radiation element background signal attributed to moisture buildup in plping SMIVELY.C.N Arkansas Power & Light Co 80/07/27 ip
- 8010070534 Forwards updated LER 79-056/03K-1. TRIMBLE.D C Arkansas Power & Light Co 80/09/29 1p
- --9010070543 Updated LER 79-056/03X-1 on 790713, review revealed that station battery surveillance inspless not performed on schedule Caused by oversight Supervisor reinstructed. Surveillance program administration centralized SHIVELY, C.N. Arkansas Power & Light Co. 80/09/29, 1p
- 8010070614 Forwards updated LER 80-050/03X-2 TRIMBLE: D C Arkansas Power & Light Co 80/09/29 1p.
- --8010070622 LER 80-050/03%-2 on 800717,0804 & 29,while tasting steam driven emergency feadwater pump 2P7A, turbina driver 2k3 tripped on overspeed Cause appears related to hydraulic control problem during initial start of 48-h idle turbina 6HIVELY,C N Arkansas Power & Light Co 80/09/29 ip
- 8010080477 Forwards LER 80-044/03X-1. TRIMBLE D C. Arkansas Power & Light Co. ,60/10/01 1p
- --8010080485 LER 80-044/03X-1 on 800701.0702 & 0902 safety injection tanks (8IT) were found w/boron concentrations below Tech Spec limit Caused by failure to flush fill line after shutdown cooling & before SIT makeup injection SKITH/N Arkansas Power & Light Co 80/10/01 4pp.

- 8010220218 PNS-IV-80-011 on 801001, bomb threat received by Russellville Police Dept, AR No evacuation planned Little Rock Air Force Base dispatched search team consisting of bomb disposal esperts
 KELLY, J Region 4. Dallas, Office of the Director 80/10/01 ip
- BO10080428 Forwards LER 80~069/03L-0
 TRIMBLE:D C Arkansas Power & Light Co 80/10/03 (p
- --8010080430 LER 80-069/03L-0 on 800903, sodium hydroxide addition tank concentration was less than 29% by weight of sodium hydroxide solution Caused by poorly seated reactor makeup water fill valve Valve torqued closed SHIVELY.C N Arkansas Power & Light Co 80/10/03 1p
- 8010200706 EN-80-049 on 801020, notice of violation & notice of proposed imposition of civil penalties of \$21,500 will be issued Action based on alleged noncompliance re continuing failure to effectively implement mot controls BROCKETT, T W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/10/16 ip
- DOCKET 50-369 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BO10220099 Forwards errata sheets amending BO0905 itr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EIGENHUT.D O Division of Licensing B0/09/19 28pp
- 8010070413 Confirms 800527 telcon re schedule & issuance of low power SER Schedule for fuel loading is 801202. SER should be issued by 801015.
 THIESLA C Dute Power Co 80/10/01 1p
- B010080548 Forwards draft emergency procedures re secondary line rupture 5 loss of feedwater for NRC review per Item I C 8 of NUREO-0694 PARKER, N.O. Duke Power Co. 80/10/02 74pp.
- B010070266 Forwards proprietary 1 nonproprietary responses to NRC questions on Barton transmitter qualification Responses specifically address Question 3 re Barton Lot 2 units Info withheld (ref 10CFR2 770)
 PARKER, H O Duke Power Co 80/10/03 2pp
- --8010070270 Authorizes use of encl affidavit in support of Duke Power Co application for withholding CAM-80-60 re qualification of safety-related instruments Util nonproprietary response to NRC questions re Barton transmitters encl WIESEMANN,R A Westinghouse Electric Corp 80/09/25 15ipp
- BO10150333 Forwards add1 info requested by NRC 800911 1tr on conformance of design to Reactor Sys Branch Technical Position 5-1 re RHR sys PARKER:N 0 Duke Power Co. 80/10/08 13pp
- 8010230241 Forwards request for info by 801015 re holddown assembly spring design unique to upper head injection plants. Cracked & broken springs have been detected in foreign plant w/ similar design TEDESCO.R L. Assistant Director for Licensing 80/10/08 3pp
- 8010270266 Notification of 801117 & 20 meeting w/util in Mecklenburg, NC to review NUREO-0588 & audit selected items of applicant submittal BIRKELIR A Licensing Branch 1 80/10/08, 3pp
- BO10270257 Notification of BO1107 meeting w/util in Hecklenburg,NC to observe & discuss safety features & operating procedures relevant to prospective issuance of OL BIRKEL,R.A Licensing Branch 1 BO/10/07 3pp
- BO10300472 Advises that util B00708 process control program is determined to contain proprietary into & will be withheld from public disclosure (ref 10CFR2 790)
 YOUNGBLOOD, B J Licensing Branch 1, 80/10/09 3pp
- BO10200358 Forwards draft of special low power testing procedures & wafety evaluation, in compliance w/NUREQ-0694 fuel loading requirement, PARKER.W.D. Duke Power Co 80/10/10. ip.
- --8010200565 Draft special low power testing procedure, TP/1/A/2190/20,
 "Natural Circulation Verification."

 4 Duke Power Co 80/10/10 17pp

- --8010200570 Draft special low power testing procedures, TP/1/A/2150/21, "Effect of Steam Generator Isolation on Natural Circulation"
 4 Duke Power Co 80/10/10 16pp
- --8010200577 Draft special low power testing procedures, TP/1/A/2150/23,
 "Natural Circulation w/Simulated Loss of Offsite Power"

 * Duke Power Co 80/10/10 itpp
- --8010200580 Draft special low power testing procedure TP/1/A/2150/26,
 "Simulated Loss of All Onsite & Offsite AC Power"

 -- Duke Power Co 60/10/10 10pp
- --B010200585 "Special Low Power Tests Safety Evaluation "

 Duke Power Co 80/10/10 47pp
- S01023040B Forwards updated responses for "Duke Power Co.McGuire Nuclear Station,Response to TMI Concerns " Unit 1 fuel loading is scheduled for Dec 1980 PARKER.N O Duke Power Co S0/10/10 32pp
- --8010230412 "Special Low Power Tests Safety Evaluation "

 * Doke Power Co 80/10/30 47pp
- 8010200430 Forwards evaluation results of util compliance w/NRC regulations contained in 10CFR20.50 & 100 Affidavit encl PARKER, U D Duke Power Co 80/10/13 34pp
- 8010170369 Forwards proprietary & nonproprietary info re environ qualification of Class IE equipment Application for withholding & affidavit encl Proprietary info withheld (ref 100FR2 790)
 PARKER, & O Duke Power Co 80/10/14 88pp
- 8010230459 Forwards response to NRC 800709 position re amergency safeguard features bypass, override & reset circuit potential design deficiencies
 PARKER, R O Duke Power Co 80/10/14 3pp
- 8010310096 Notification of 801103 meeting w/util in Mecklenburg County, NC to discuss emergency operating procedures BERKEL.R Licensing Branch 1 80/10/22 3pp
- 8010310438 Bubmits addl info re in-core thermocouples as discussed in util 800717 ltr Subcooling monitor uses thermocouples as inputs measured by operator aid computer PARKER, N O Dube Power Co 80/10/27 p
- F Security, medical, emergency & fire protection plans
- 801006009B Transmits emergency planning info for public availability at Charlotte.NC LPDR SOUDER.J L Division of Rules and Records 80/09/11 1p
- 8010160331 Notifies of NRC acceptance of revised training & qualification program Plan thall be followed 60 days after date of OL to qualify all security personnel within 2 yrs of YOUNGBLOOD, B. J. Licensing Branch 1 80/10/01 2pp
- 8010170039 Notifies that 800609 revised security training & qualification plan acceptable. YOUNGBLOOD, B J Licensing Branch 1 80/10/01 2pp
- O Adjudicatory correspondence
- 8010010546 Discusses NRC study re proposed interim hydrogen control requirements for small containment Requests NRC re-open licenting hearings Affiliation Unknown 80/09/29 1g
- B010020042 Motion for summary disposition of application for license, authorizing initial criticality & low-power operation Motion does not constitute admission that Carolina Environ Study Group has complied w/reopening stds MCOARRY.J.M., Debevoise & Liberman. B0/09/30 4pp
- --8010020050 Statement of metl facts on ebsence of genuine issue to be heard, in support of util motion for summary disposition of application re license for low power testing Issues refeed in OL application have no bearing on low power operation. MCGARRY, J. M. PORTER, W. L. Duke Power Co MCGARRY, J. M. Debeyoise & Liberman 80/09/30 Spp.

- --B010020054 Memorandum in support of util motion for summary disposition of application relicense for low power testing OL contested issues resolved in favor of full-term DL Excessive hydrogen generation very unlikely in low power mode MCOARRY, J. M., PORTER, W.L. Duke Power Co. MCOARRY, J. M. Debavoise & Liberman B0/09/29 15pp
- --R010020062 Affidavit stating that complete failure of ECCB is required for alleged excessive hydrogen generation Such failure is very unlikely in low power testing RABIN.II H Duke Power Co 80/09/30 4pp
- ---8010020068 Affidavit demonstrating that excessive hydrogen generation during fuel loading.initial criticality & low power appration will not occur due to design of ECCS. CANADY, K S Duke Power Co 80/09/30 3pp
- --8010020077 Affidavit demonstrating that util action affactively precludes excess hydrogen generation from TMI-type accident at facility Certificate of Bvc encl.
 GANADY.K B Dute Power Co 79/07/09 7pp
- 801008091& Requests reopening of hearings re facility evacuation plans Country roads surrounding plant have no warning sys WILBON'S Affiliation Unknown 80/09/30 Zpp
- 8010060022 Response in opposition to DR Belk 800927 late intervention.

 Limited appearance statement may be authorized Certificate
 of Bvc encl.

 MCOARRY, J M. PORTER, H.L. Duke Power Co. MCOARRY, J M. Debevoise &
 Liberman 80/10/02 4gp
- B010070555 Response in opposition to DM Wilson B00925 ltr seeking intervention if DL record response Petition deficient but limited appearance may be granted Certificate of Bvc encl. MCOARRY.J M. PORTER.W L. Duke Power Co MCOARRY.J M. Debevoise & Liberman B0/10/03 4pp
- B010140587 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in McOufre spent fuel pool, reported in encl Fower Reactor Events Certificate of Svc encl RILEY, J L Carolina Environmental Study Group 80/10/06. 12pp
- B010140507 Response in opposition to S Wilson B00930 ltr.if viewed as late petition to intervene. No objection to S Wilson public statement, if hearing reopened Certificate of Svc encl MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman, B0710708 4pp
- 8010150006 Response in opposition to P Edmonston 801002 request to make statement if viewed as petition to intervene No objection if viewed as request to make limited appearance statement if hearing held Certificate of Evc encl MCOARRY, J M Dute Power Co MCOARRY, J M Debevoise & Liberman. 80/10/09 49p
- E010200599 Requests that NRC reopen licensing hearings BOLLAO.L . BOLLAO.M. Affiliation Unknown BO/10/15 1p.
- 9010210772 Response in opposition to MR Johnson 800923 ltr reintervention if hearing reopened Limited appearance statement may be granted Certificate of Svc encl.
 MCGARRY, J M. PORTER, W L Duke Power Co. MCGARRY, J. M Debevoise & Liberman 80/10/17 App
- 8010210777 Response in opposition to L & M Bollas undated itr intervention if hearing reopened Limited appearance statement may be granted Certificate of Svc encl MCGARRY,J M. PORTER,W L. Duke Power Co MCGARRY,J.M Debevoise & Liberman. 80/10/17 Spg
- 8010230692 Stipulation for ASLE approval standing time to respond to applicant motion for summary disposition & request for expedited consideration until 801028 re low power operation. Oranted on 801021 Certificate of svc encl. MCGARRY.J M Consumers Power Co. CURTISS.J.R Regulations Division. RILEY.J L Carolina Environmental Study Group 80/10/21.
- B010240552 Response in apposition to Carolina Environ Study Oraup 801005 motion to reapen record to include Jul 1980 "Unplanned Boron Dilution," rept into evidence. No new info presented PORTER, W.L. Dute Power Co. B0/10/21 7pp.
- --8010240562 Affidavit addressing activities associated w/demineralizer operation & effect of boron decreased concentration Certificate of Svc encl ORTH.W.C Duke Power Co. 80/10/21 Spp

- 8010280582 Motion for extension until 801114 for NRC to develop adequate answer to Carolina Environ Study Group 801006 motion to reopen record re cask drop accidents Counsel engaged in other urgent duties Certificate of Svc snc1 CURTIES.J R Regulations Division 80/10/24 3pp
- H General correspondence
- B010020401 Expresses concern over lax attitude of employees at facility when answering questions during tour License proceedings should be reopened & discussions held on evacuation plans & problems of clams plugging outlet pipes
 WILEON, D. M. Affiliation Unknown B0/09/25 Spp
- 8010020554 Expresses concern over util failure to accept responsibility for faulty plant design & operating capacity Ice condenser & hydrogen recombiner sys cannot withstand rapid evolution event similar to THI NRC must reopen licensing hearings FENNELL. IC Sets Energy Alliance 80/09/26 ip
- 8010069277 Requests thhat licensing procedure be reopened for thorough examination of facility potential for TMI-type loss of containment Lake Norman area evacuation plans confusing & incomplete
 FRYBEROER,P Affiliation Unknown 80/09/27, ip.
- 8010100309 Requests that NRC recpen hearings & move to delay opening of facility pending resolution of problems re evacuation procedures EDKONDSON, P Affiliation Unknown 80/10/02 ip
- 80:0200622 Responds to 800829 ltr questioning containment adequacy Commission matl addressing concern encl Evidentiary hearing closed If hearing requested 10CFR2 714 requirements must be met 6/0 encl KETCHEN.E O Hearing Branch 4 80/10/15 3pp
- 8010280349 Urges that hearings for licensing facilities be reopened NELBON, K F Affiliation Unknown 80/10/21, ip
- J Insurance & indemnity information
- 8010280594 Requests endorsements & copy of Amend 2 to Policy B-83 DINITZ, I Utility Finance Branch (formerly Antitrust & Indomnity) 80/09/24 ip
- 9010270348 Forwards 800311 ltr transmitting Endorsements 55 & 57 to NELIA Policy NF-182 & 790607 ltr transmitting Amend 2 to Indemnity Agreement B-83 in response to NRC 800924 request, PARKER, N O Duke Power Co 80/10/21, ip
- @ Inspection reports, IE Bulletins & correspondence
- 8010230108 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 is
- 8010010014 Ack receipt of IE Insp Rept 80-369/80-22 on 800721-23 No proprietary info PARKER, W O Duke Power Co. 80/09/12 ip
- --8010010016 Forwards IE Insp Rept 50-369/80-22 on 800721-25 No noncompliance noted LEMIS, R.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/08/25 2pp
- --8010010018 IE Insp Rept 50-369/80-22 on 800721-25 No noncompliance noted Major areas inspected comparison of as-built plant safety sys w/FSAR drawings-hot functional preoperational tests to hot functional test progrem performance DUNAT.T J. FALCONER.D. Region 2, Atlanta, Office of the Director. MARTIN.R.D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/25, 4pp.
- 8010020782 Ack receipt of IE Insp Rept 50-369/80-20 on 800708-17. No proprietary info PARKER-N. O Duke Power Co. 80/09/15. ip
- --8010020784 Forwards IE Insp Rept 50-369/80-20 on 800708-17. No noncompliance noted LENIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/26. 2pp.

- --8010020787 IE Insp Rept 50~367/80-20 on 800708-17 No noncompliance noted Major areas inspected preoperational test witnessing, review of licensee response to circulars & follows on items from previous repts

 JOHNSON, A H. Region 2, Atlanta, Office of the Director UPRIGHT, C M. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/26 3pp
- B0100B0449 Forwards supplemental response to IE Bulletin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Ancho: Bolts " Util will account for base plate flexibility in calculation of expansion anchor bolt loads PARKER, W D Duke Power Co 60/09/16 6pp
- 8010080197 Ack receipt of IE Insp Rept 50-369/80-16 on 800625-27 No proprietary info PARKER, H. O Duke Power Ca 80/09/18 ip
- --B01008020D Forwards IE Insp Rept 50-369/80-14 on 800628-27 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/08/28 2pp
- --8010080205 IE Insp Rept 50-369/80-16 on 800625-27 No noncompliance noted Major areas inspected reviewing program for implementing recommendations it requirements of NUREG-0578 MELL006.P J. DCNAT.T J. Region 2. Atlanta. Office of the Director MARTIN.R D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/28 App
- 80(0)00217 Informs that response to IE Bulletin 80-18 will be submitted on 800927 PARKER, W D Duke Power Co 80/09/22 ip
- PARKER, W U DUKS FOWER CO 60704722 IP
- BO10030489 Ack receipt of B00905 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept B0-369/80-18 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/09/24 ip
- --B010030491 Responds to NRC 800/31 ltr re violations noted in IE Insp Rept 50-369/80-18 Corrective actions new procedures initiated for insp of pipe supports & rusty weld rods have been properly disposed PARKER, N O Duke Power Co 80/09/05 19pp
- --8010030476 Advises that response to IE Insp Rept 50-369/80-18 is being prepared Report contains no proprietary info. PARKER: W O Duke Power Co 80/08/26 ip
- --8010030500 Forwards IE Insp Rept 50-349/80-18 on 800630-0703 & notice of violation UREILLYJ P Region 2, Atlanta, Office of the Director.
- --B010030504 Notice of violation from insp on 800630-D703.
 ** Region 2, Atlanta, Office of the Director. 80/07/22 3pp.
- --B010030509 IE Insp Rept 50-369/80-18 on 800630-0703 Noncompliance noted failure to follow pipe support installation & insp requirements & failure to follow weld rod control requirements
 HERDY, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch ANG, N.P. Region 2, Atlanta, Office of the Director 80/07/22 App.
- 80:0150A5A Responds to IE Bulletin 80-18 Calculations indicate interim Hod II required to provide adequate miniflow for centrifugal charging pumps Response required 52 manhours PARKER,W G Duke Power Co 80/09/29 3pp.
- BOI0160138 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/09/30.
- 8010270415 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02. to.
- 8010240006 Requests addl info re inservice insp of pressure isolation valves Forwards position
 TEDESCO.R L Assistant Director for Licensing 80/10/06. 4pp
- 8010270181 Ack receipt of IE Insp Rept 50-369/80-23 on 800728-0801 No proprietary info PARKER, N O. Duke Power Co 80/10/06 ip.

- --B010270163 Forwards IE Insp Rept 50-369/80-23 on 800728-0801 No noncompliance noted LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch B0/09/17 2pp
- --8010270186 IE Insp Rept 50-369/80-23 on 800728-0801 No noncompliance noted Hajor areas inspected preoperational testing observation & review & follower on open items GRAHAM.ft J Region 2. Atlanta, Office of the Director MARTHUR D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 4pp
- B010290052 Forwards IE Info Notice B0-36, "Failure of Steam Camerator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/10/10 in
- 8010300380 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-367/80-08, 50-367/80-05, 50-49/80-06, 50-49/80-09, 50-414/80-07, 50-49/80-06 & 50-493/80-06 MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/10/16 2pp
- --8010300385 Respands to NRC 800718 ltr re violations noted in IE Insp Repts 50-369/80-08,50-370/80-05,50-413/80-09,30-414/80-09, 50-491/80-07,50-492/80-06 & 50-493/80-06 Corrective actions records storage facility constructed PARKER: H O Duke Power Co 80/08/15 7pp
- --8010300388 Forwards IE Insp Repts 50-369/80-08,80-370/80-05, 50-413/80-09,50-414/80-09,50-491/80-07,50-492/80-06 & 50-493/80-06 on 800519-23 & notice of violation NGRPN/C E Region 2. Atlanta. Resetor Construction & Engineering Support Branch 80/07/18 Zpp
- --8010300423 Notice of violation from insp on 800519-23
 4 Region 2, Atlanta, Office of the Director 80/07/18 4pp.
- --8010300428 IE Insp Repts 50-369/80-08.50-370/80-05.50-413/80-09.50-414/80-09.50-491/80-07.50-492/80-06 & 50-493/80-06 on 800519-23 Noncompliance noted in areas of temporary record storage facilities & fire protection BROMMLER.V L. HODENOS.L. BURDETTE.T.E Region 2. Atlanta. Office of the Director 80/07/18 23pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007300379 Forwards final rept re potential problem in safety-related overcurrent relays Problem was random in nature & not generic.
 BUVALL.D D Could-Brown Boveri 80/07/16 4pp
- B010030459 Deficiency rept re possible overvoltage during ground faults of potential transformers/cables connected to diesel generators Potential transformers will be replaced w/ phase-to-phase & open-delta connected transformers, PARKER: N O Duke Power Co 80/09/26 3pp.
- 8010240591 Part 21 rept re Brand Rex conductor. Absence of cured conductor results in unqualified Class IE equipment Vertification of all current & future components has been implemented ROBERTELL B Brand-Rex Co. 80/10/08 3pp.
- 8010200525 Deficiency Repts 8D 369/80-17 & 370/80-12 re improper operation of E-max Instruments. Inc Model 1750141 optical isolator when driving loads w/greater than 1 amp incush current Parts will be replaced w/Model 1750146. FARKER, W O Duke Power Co 80/10/10 2pp
- DOCKET 50-970 WILLIAM 8 MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also and EIEENHUT, D. G. pivision of Licensing. 80/09/19. 28pp.
- 8010070413 Confirms 800527 telcon re schedule & issuance of low power BER. Schedule for fuel loading is 801202. SER should be issued by 801015
 THIEB, A. G. Duke Power Co. 80/10/01. 1p.
- 8010080548 Forwards draft emergency procedures re secondary line rupture & loss of fagiwater for NRC review per Item I.C.S of NREG-0694. PARKER N D. Duke Power Co. 80/10/02. 74pp.

- 8010070266 Forwards proprietary & numproprietary responses to NRC questions on Barton transmitter qualification Responses specifically address Guestion 3 re Barton Lot 2 units Info withheld (ref 10CFR2 770)
 PARKER: N O Duke Power Co 80/10/03 2pp
- --8010070270 Authorizes use of encl affidavit in support of Duke Power Co application for withholding CAU-80-60 re qualification of safety-related instruments Util nonproprietary response to NRC questions re Barton transmitters encl WIESEMANN.R A Westinghouse Electric Corp 80/09/25 15ipp
- 8010150333 Forwards add! info requested by NRC 800711 ltr on conformance of design to Reactor Sys Branch Technical Position 5-1 re RHR sys PARKER.N O Duke Power Co 80/10/08 13pp
- 801023024! Forwards request for info by 801015 re holddown assembly spring design unique to upper head injection plants Cracked & broken springs have been detected in foreign plant w/ similar design TEDESCO.R L. Assistant Director for Licensing 80/10/08 3pp
- 8010270266 Notification of B01119 & 20 meeting w/wtil in Mecklenburg.NC fo review NUREG-0588 & audit selected items of applicant submittal BIRKEL,R A Licensing Branch 1 80/10/08 3pp
- 8010270257 Notification of 801107 meeting w/util in Mecklenburg, NC to observe & discuss safety features & operating procedures relevant to prospective issuance of OL BIRKEL, R A Licensing Branch i 80/10/09 3pp
- 8D10300472 Advises that util 8D0708 process control program is determined to contain proprietary info & uill be withheld from public disclosure (ref 10CFR2 790)
 YOUW08LCOD.8 J Licensing Branch 1 E0/10/09 3pp
- 8010200558 Forwards draft of special low power testing procedures & safety avaivation, in compliance w/NUREG-0694 fuel loading requirement PARKER, N O Duke Power Co 80/10/10 ip
- --8010200555 Draft special low power tasting procedure, TP/1/A/2150/20, "Natural Circulation Verification" * Duke Power Co 80/10/10 17pp
- --8010200570 Draft special low power testing procedures, TP/1/A/2150/21, "Effect of Steam Generator Isolation on Natural Circulation"
 - * Duke Power Co 80/10/10 16pp
- --B010200577 Draft special low power testing procedures TP/1/A/2150/23,
 "Natural Circulation w/Simulated Loss of Offsite Power"

 Duka Power Co B0/10/10 lipp
- --8010200580 Draft special low power testing procedure TP/1/A/2150/26, "Bimulated Loss of All Onsite & Offsite AC Power"

 Dute Power Co 80/10/10 10pp
- --8010200585 "Special Low Power Tests Safety Evaluation "
 * Duka Power Co 80/10/10 47pp
- 8010230408 Forwards updated responses for "Duke Power Co, McGuire Nuclear Station, Response to TMI Concerns " Unit 1 fuel loading is scheduled for Dec 1790 PARKER, N O Duke Power Co 80/10/10 32pp
- 8010230457 Forwards response to NRC 800707 position re emergency safeguard features bypass, override & reset circuit potential design deficiencies
 PARKER: N 0 Duke Fower Co 80/10/14 3pp.
- B010310096 Notification of B01103 meeting w/util in Mecklenburg County, NC to discuss emergency operating procedures BIRKEL.R Licensing Branch i B0/10/22 3pp
- 8010310438 Submits add1 info re in-rore thermocouples as discussed in util 800917 ltr Subcooling monitor uses thermocouples as inputs measured by operator aid computer. PARKER. W. O Duke Power Co 80/10/27 [p
- F. Security, modical, emergency & fire protection plans
- 8010060058 Transmits emergency planning info for public availability at Charlotte,NC LPDR SOUDER,J L. Division of Rules and Records 80/09/11. 1p.

- 8010140331 Notifies of NRC acceptance of revised training & qualification program Plan shall be followed 60 days after date of OL to qualify all security personnel within 2 yrs of that date
 YOUNODLOOD, D. J. Licensing Branch 1 80/10/01 2pp
- 8010170039 Notifies that 800609 revised security training & qualification plan acceptable
 YCUNGBLOOD:B J Licensing Branch 1 80/10/01 2pp
- @ Adjudicatory correspondence
- B010010546 Discusses NRC study re proposed interim hydrogen control requirements for small containment Requests NRC re-open licensing hearings
 BELK, D.R. Affiliation Unknown 80/09/27 ip
- 8010020042 Motion for summary disposition of application for license, authorizing initial criticality & low-power operation Motion does not constitute admission that Carolina Environ Study Oroup has complied w/reopening stds
 MCGARRY, J M . PORTER, W L Duke Power Co MCGARRY, J M Debavoise & Liberman 80/09/30 App
- --8010020050 Statement of matl facts on absence of genuine issue to be heard, in support of util motion for summany disposition of application re license for low power testing Issues raised in GL application have no bearing on low power operation MCOARRY, J M , PORTER, N L Duke Power Co MCOARRY, J M Debevoise & Liberran 80/09/30 Spp
- --8010020054 Memorandum in support of util motion for summary disposition of application re license for low power testing OL contested issues resolved in favor of full-term CL Excessive hydrogen generation very unlikely in low power mode MCGARRY, J M. PORTER, M. L. Duke Power Co. MCGARRY, J M. Debevoise & Liberman. 80/09/29 15pp
- ~~B010020062 Affidavit stating that complete failure of ECCS is required for alleged excessive hydrogen generation Such failure is very unlikely in low power testing RASIN-W H Duke Power Co B0/09/30 4pp
- --8010020028 Affidavit demnnstrating that excessive hydrogen generation during fuel loading initial criticality & low power operation will not occur due to design of ECCS CANADV.K S Duke Power Co 80/09/20 3pp
- --B010020077 Affidavit demonstrating that util action effectively precludes excess hydrogen generation from TMI-type accident at facility Certificate of Svc encl CAKADV.K S Duke Power Co 79/07/09 7pp
- 8010080516 Requests reopening of hearings re facility evacuation plans Country roads surrounding plant have no warning sys WILSON, S Affiliation Unknown 80/09/30 2pp
- 8010060602 Response in opposition to DR Belk 800927 late intervention Limited appearance statement may be authorized Certificate of Syc enci MCGARRY, J M. PORTER, W.L. Duke Power Co. MCGARRY, J M. Debevoise & Liberman 80/10/02 4pp
- 8010070555 Response in opposition to DM Wilson 800925 ltr seeking intervention if OL record reopened Petition deficient but limited appearance may be granted Certificate of Svc encl MCGARRY, J. M. PORTER, N. L. Duke Power Co MCGARRY, J M. Debevoise & Liberman 80/10/03 4pp
- 80i0i40587 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in HcOuire spent fuel pool reported in encl Power Reactor Events Certificate of Svc enc!

 RILEY.J L. Carolina Environmental Study Group. 80/10/06 12pp
- B010140507 Response in apposition to 8 Wilson B00930 ltr, if viewed as late petition to intervene No objection to 8 Wilson public statement; if hearing reopened, Certificate of 8vc encl MCGARRY, J. M Duke Power Co MCGARRY, J M Debevoise & Liberman, B0/10/08, 4pp.
- 8010130006 Response in opposition to P Edmonston 801002 request to make statement, if viewed as petition to intervene No objection if viewed as request to make limited appearance statement if hearing held Certificate of Svc encl.
 KCOARRY, J. M Duke Power Co. MCOARRY, J M Debevoise & Liberman 80/10/09 4pp
- 8010200599 Requests that NRC reopen licensing hearings BOLLAG.L., BOLLAG.M. Affiliation Unknown 80/10/15 ip.

- 8010210772 Response in opposition to MR Johnson 800923 ltr re intervention of hearing reopened Limited appearance statement may be granted Certificate of Svc encl MCOARRY, J M. PORTER, W. L. Duke Power Co. MCGARRY, J M. Debevoise & Liberman 80/10/17 4pp
- B010210777 Response in opposition to t.& M Boilag undated ltr intervention if hearing reopened Limited appearance statement may be granted Certificate of Svc encl MCOARRY, J M , PORTER. N L Duke Power Co MCOARRY, J M Debevoise & Liberman 80/10/17 5pp
- B010230692 Stipulation for ASLB approval extending time to respond to applicant motion for summary disposition & request for expedited consideration until B01028 re low power operation Oranted on B01021 Certificate of svc encl MCQARRY, J M Consumers Power to CURTISS, J R Regulations Division RILEY, J L Carolina Environmental Study Group 80/10/21
- 8010240552 Response in opposition to Carolina Environ Study Group 801006 motion to reopen record to include Jul 1980 "Unplanned Boron Dilution," rept into evidence No new info presented PORTERAGE L. Duke Power Co. 80/10/21 7pp
- --8010240562 Aftidavit addressing activities associated w/deminerallizer operation t effect of boron decreased concentration Certificate of Svc encl
 ORTH.W C Duke Power Co 80/10/21 8pp
- 8010280592 Motion for extension until 801114 for MRC to develop adequate answer to Carolina Environ Study Oroup 801006 motion to reopen record re cask drop accidents Counsel engaged in other urgent duties Certificate of Svc encl. CURTISS.J R Regulations Division 80/10/24 3pp

- GO10020401 Expresses concern over lax attitude of employees at facility when answering questions during tour License proceedings should be reopened & discussions held on evacuation plans & problems of clams plugging outlet pipes WILSON, D M Affiliation Unknown 60/09/25. 3pp
- 8010020554 Expresses concern over util failure to accept responsibility for faulty plant design & operating capacity Ice condenser & hydrogen recombiner sys cannot withstand rapid evolution event similar to TMI NRC must recopen licensing hearings.

 FENNELL.M Safe Energy Allience 80/09/26 ip
- 8318030430 Urges NRC to reopen hearings re licensing of plant Many people in area concerned that evacuation plans are inadequate STEPHENSON, J H Affiliation Unknown 80/09/26, 1p
- and the second s
- B010060277 Requests thhat licensing procedure be reopened for thorough examination of facility potential for TMI-type loss of containment Lake Norman area evacuation plans confusing & incomplete
 FRYBEROER.P Affiliation Unknown B0/09/29 is.
- BO10100309 Requests that NRC reopen hearings & move to delay opening of facility pending resolution of problems re evacuation procedures EDHGN8BGN.P Affiliation Unknown 80/10/02. 1p.
- 8010200622 Responds to 800829 [tr questioning containment adequacy Commission matl addressing concern encl Evidentiary hearing closed, if hearing requested, 100FR2 714 requirements must be
- met N/o encl
 KETCHEN.E 9 Hearing Branch 4 80/10/15 Spp
- 8010280349 Urges that hearings for licensing facilities be reopened NEC80N.K F Affiliation Unknown 80/10/21 1p
- J Insurance & indemnity information
- 8010280594 Requests endorsements & copy of Amend 2 to Policy B-83. DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 ip
- B010270348 Forwards 800311 ltr transmitting Endorsements 56 & 57 to NELIA Policy NF-182 & 790607 ltr transmitting Amend 2 to Indemnity Agreement B-83 in response to NRC 800924 request. PARKER N D. Duke Power Co 80/10/21 ip

- @ Inspection reports. IE Bulletins & correspondence
- 8010230108 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls." No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/08/29
- 80100B0449 Forwards supplemental response to IE Bulletin 79-02, Revision 2. "Pipe Support Sase Plate Designs Using Concrete Expansion Anchor Bolts "Util will account for base plate flexibility in calculation of expansion anchor bolt loads PARKER, N O Duke Power Co BO/09/16 App
- 8010100219 informs that response to IE Bulletin 80-18 will be submitted on 800929
 PARKER, W C Duke Power Co 80/09/22 ip
- 8010150654 Responds to IE Bulletin 80-18 Calculations indicate interim Mod II required to provide adequate miniflow for centrifugal charging pumps Response required 52 manhours PARKER, M O Duke Power Co 80/07/27 3pp
- 801014013B Forwards Suppl 2 to IE Sultetin 79-01B, "Environ Gualification of Class IE Equipment " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30 ip
- 8010270411 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02, ip
- B010240906 Requests add1 info re inservice insp of pressure isolation valves Forwards position TEDESCO.R L Assistant Director for Licensing 80/10/06 4pp
- 8010290052 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested D'REILLY, J P Region 2. Atlanta, Office of the Director BO/10/10. is.
- 8010280D50 Act receipt of 800730 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/80-13 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/10/16 ip
- --8010280057 Responds to NRC 800910 ltr re violations noted in IE Insp. Rept 50-370/80-13. Corrective actions tubing tray & supports removed crafts instructed in requirements for field routed installations
 PARMERN O Duke Power Co 80/09/30 2pp
- --8010280054 Forwards IE Insp Rept 50-370/80-13 on 800819-22 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/10, 2pp
- --8010280060 Notice of violation from insp on 800819-22 * Region 2. Atlanta, Office of the Director, 80/09/09, 1p
- --8010280064 IE Insp Rept 50-370/80-13 on 800819-22. Noncompliance noted: instrument tray & tray supports installed on safety-related motors w/o appropriate drawings.
 OIBBONS.T D Region 2. Atlanta, Office of the Director CONLON.T & Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/09 3pp
- 8010300380 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-414/80-09, 50-492/80-06 & 50-493/80-06 MURPHY-C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/10/16 2pp
- --8010300385 Responds to NRC 800718 ltr re violations noted in IE Insp Repts 50-369/80-08,50-370/80-05,50-413/80-09,50-414/80-09, 50-491/80-07,50-492/80-06 & 50-493/80-06 Corrective actions: records storage facility constructed. PARKER.H O Duke Power Co. 80/08/15 7pp
- ***0010300388 Forwards IE Insp Repts 50-369/80-08:50-370/80-05; 50-413/80-09:50-414/80-09:50-491/80-07:50-492/80-06 & 50-493/80-06 on 800319-23 & notice of violation HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/07/18 2pp.

- --8010300423 Notice of violation from insp on 800519-23

 * Region 2, Atlanta, Office of the Director 80/07/18 4pp
- --8010300428 IE Insp Repts 50-369/80-08,50-370/80-05,50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06 on 800519-23 Noncompliance noted in areas of temporary record storage facilities & fire protection BROWNEE, V L , MODENOS, L , 30RRETTE, T E Region 2, Atlanta, Office of the Director 80/07/18 25pp
- S Reportable occurrences, LERs & related correspondence
- 8010030459 Deficiency rept re possible overvoltage during ground faults of potential transformers/cables connected to diesel generators Potential transformers will be replaced w/ phase-to-phase & open-delta connected transformers PARKER, W. G. Duke Power Co. 80/09/26 3pp
- 8010240591 Part 21 rapt re Brand Rez conductor Absence of cured conductor results in unqualified Class IE equipment Verification of all current & future components has been implemented ROBERTS.L B Brand-Rez Co. 80/10/08 3pp
- B010200525 Deficiency Repts SD 369/80-17 & 370/80-12 re imprager operation of E-max Instruments. Inc Hodel 175C141 optical isolator when driving loads w/greater than I amp inrush current Parts will be replaced w/Model 175C146 PARKER, W O Duke Power Co. 80/10/10 200
- DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010070495 Summary of 800805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads. Discussion topics attendance & meeting handouts encl ANDERSON.C J. Generic Issues Branch 80/08/29 98pp.
- BO10060102 Summary of B00904-05 meeting w/Mark II owners in Bethesda.MD re long-term program chugging & lateral loads Attendance list & handouts encl.
 ANDERSON.C.J Generic Issues Branch B0/09/12 65pp
- 8010010025 Forwards request for add1 info re NUREG-0578 Dutstanding items include clarification of increased range monitors, integrity of radioactivity barriers in sys outside containment & post accident sampling commitments.
 TEDESCO,R.L. Assistant Director for Licensing 80/09/18, 4pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrocted table of implementation schedule also encl EISENHUT, D.O. Division of Licensing 80/09/19, 28pp
- 801027023B Notification of 80100B meeting w/representatives from Mark IJ owners group in Betheeda.MD to discuss Hark II plants chugging load spec ANDERSON.C. Generic Issues Branch 80/09/22. ip
- 8010100361 Submits list of current qualification programs for EPR1 util equipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC schedule

 LAMKEN, D.C. Commonwealth Edison Co. 80/09/24 2pp
- 8010020435 Forwards 800929 rept. "Preliminary Assessment Human Factors Review of Lasalle County Station Control Room." par NUREO-0694 requirements. Meeting tantatively scheduled 801015 to 416cuss NRC recommendations DELOEOROE, L. O. Commonwealth Edison Co. 80/09/29. 1p
- --8010020444 *Preliminary Assessment Human Factors Review of Lasalle County Station Control Room **
 ** Commonwealth Edison Co. 80/09/29 B3pp.
- 8010230010 Summary of 800924 meeting w/util & Sargent & Lundy in Bethesda.MD re applicant re-evaluation program relative to esismic qualification of equipment.Lists milestones established Attendes List encl
 8008NIA.A Licensing Branch i 80/10/01 Spp
- BOIGITOITE Bummary of BOOTOS meeting u/util in Bethesda.MD re-coil properties used in soil-structure interaction analyses.
 BOURNIA.A. Licensing Branch S BO/10/07. App.

- 8010230594 Notification of 801027 meating w/util in BethesdarMD re audit rept from site visit & schedule for implementing control room design changes BOURNIARA Licensing Branch 1 80/10/07 3pp
- 8010150474 Forwards "Equipment Requalification Program for Pool Dynamic Loads " Rept updates 900804 transmittal by inclusion of open items list for balance of plant & NSSS equipment currently being tested Rept available in Central Files only DELGEORGE, L. Q. Commonwealth Edison Co. 80/10/08 2pp
- 8010210538 Forwards response to NRC questions re floodplain mgt transmitted by RL Tedesco 800805 ltr to DL Peoples Facilities do not alter predicted flood levels associated u/1% flood Formal FSAR transmittal has not been developed DELOEDROGOLO Commonwealth Edison Co 80/10/16 14pp
- B010290417 Natification of B01029-31 meeting w/util at LaBalle site, 1L rs instrument & control drawing review DOURNIA, A Licensing Branch 1 B0/10/17 2pp
- --BO)0290418 Notification of 801029-31 site visit & meeting to discuss specific items & necessary rollowup actions THATCHER, D F Instrumentation & Control Systems Branch 80/10/17
- 8010240458 Forwards response to NUREO-0694 requirements Augments 800455 transmitted re commitments satisfying THI short-term Lessons Learned guidelines Info will be included in App L of FBAR DELEGORGE.L O Commonwealth Edison Co 80/10/20 100pp
- 8010280322 Forwards info re assumptions used in pool-temp analysis of stuck open relief valve, in response to NRC 800915 request.

 Justifications for manual scram occurring at 110 F pool temp to for use of main condenser as heat sink enc!

 DELGEOROE, L. O. Commonwealth Edison Co. 80/10/21 ip 16
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010020454 Forwards draft revision to FSAR re qualification of insp & testing personnel & mafety classification of reactor internals
 RAUSCHIT, J Commonwealth Edison Co 60/09/26 ip.
- ---B010020459 Draft Amends 41,44,49 & 50 to FSAR re qualification of insp & teeting personnel & safety classification of reactor internals * Componwealth Edison Co B0/09/26 lipp
- 8010280254 Forwards Amend 50 to FSAR, including new App N, revised responses to Reactor Sys Branch questions, one response to second-round question & updated oversize drawings in Section 1 7 of FSAR
 JANECEK, R, F. Communi
- --8010280257 Amend 50 to FSAR, * Commonwealth Edison Co 80/10/20 225pp
- --8010280260 Package of \$25 oversize electrical drawings submitted as part of Amend 50 to FSAR Drawings will be recalled at later date for microfilming & Commonwealth Edison Co 80/10/20 525pp
- P Operating license stage documents & correspondence
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implamented promptly REED. C Commonwealth Edison Co 80/10/01. Spp
- 8010210039 Notification that 801023 meeting w/util has been rescheduled to 801027 Meeting will be held in Bethesda. MD to discuss audit rept from site visit & to establish schedules implementing control room design changes 80URNIA: A Licensing Branch 1 80/10/07 3pp.
- Q Inspection reports, IE Bulletine & correspondence
- 8010160133 Forwards IE Insp Repts 50-373/80-30 & 50-374/80-19 on 800617-0725 & notice of violation. MEISHKAN,R F Regton 3, Chicago: Reactor Operations Nuclear Support Branch. 80708/21 2pp.
- --8010160137 Notice of violation from insp on 800617-0725

 * Region 3: Chicago: Office of the Director. 80/08/20 ip.

- --E010160145 IE Insp Repts 50-373/80-30 % 50-374/80-17 on 800617-0725 Noncompliance noted installed temporary power supply to battery charger not recorded in temporary feed log Condition * corrected 800707 SPESSARD,R. I. WALKER,R. D., SHEPLEY, S. E. Region 3, Chicago, Office of the Director 80/08/20 9pp
- PO10100009 Forwards IE Insp Repts 50-373/80-35 & 50-374/80-22 on B00919-20 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/09/04 2pp
- ---8010100012 IE Insp Repts 50-373/80-35 & 50-374/80-22 on 800819-20
 No noncompliance noted Major areas inspected instrumentation cable installation in Unit 2 & suppression pool mods in Units 1 & 2
 HILLIAMSIC C , NEISLER, J H , MATTEO, A J Region 3, Chicago, Office of the Director 80/09/02 4pp
- 8010100003 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/80-25
 HEISHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/09/18 2pp
- --B010100007 Responds to NRC B00724 ltr re violations noted in IE Insp Rept 50-373/B0-25 Corrective actions Startup Manual Procedure L6U 497-1 has been clarified & station surveillance procedures will be reviewed AGEL, J S Commonwealth Edison Ca B0/08/15 9pp
- B010070490 Forwards corrected Page 2 of 800703 cover ltr transmitting IE Insp Rept 50-373/80-33 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/07/26 2pp
- 8010150225 Responds to NRC 800814 & 27 ltrs re violations noted in IE Insp Repts 80-373/80-32 & 50-374/80-20 Corrective actions bore hanger insp will be conducted using procedure EC-7 ABELJ S Commonwealth Edison Co 80/09/26 9pp
- 8010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required KEFFLER, J G Region 3, Chicago, Office of the Director 80/09/30 1p
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director, 80/10/02 10
- E010290181 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropts 50-373/80-32 & 50-374/80-20 FIDRELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/09 ip
- --8010270172 Responds to NRC 800827 Itr re violations noted in IE Insp Repts 50-373/80-32 & 50-374/80-20 Corrective actions, contractor organization charts revised to delineate job classifications & util conducted audits ABEL.J 8 Commonwealth Edison Co 80/07/26 9pp.
- BO10270037 Forwards IE Info Notice 80-36. "Failure of Steam Cenerator Support Bolting " No specific action or response requested KEPPLER.J G Region 3. Chicago, Office of the Director 80/10/10
- S Reportable occurrences, LFRs & related correspondence
- 8010090265 PNG-III-80-165 Ragion 3 is preparing to issue immediate action ltrs on 800903 confirming that utils will stop installation of lead slastomer & silicone gel penetration seals made by Tech-Sil Inc.
 NEIBLER.J H. WILLIAMS.C C , FIORELLI.0 Region 3, Chicago, Office of the Director 80/09/03 ip
- 80:0160542 Final deficiency rept re small pipe hanger design deficiency Review program documented & audits of design control & review performed Surveillance program to monitor work instituted Periodic repts will be submitted after insp DELGEORGE.L O Commonwealth Edison Co 80/10/08. 2pp.
- 8010240546 Ack receipt of final rept re MSIV leakage control sys.Review to be completed during future insp FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/09 ip.

- --8010240551 Deficiency rept re MSIV leakage control sys Addl liquid bleodoff drainline installed downstream of heaters to prevent venting & back flow from sump DELGEORGE.L O Commonwealth Edison Co 80/09/19 2pp.
- B010290228 Ack receipt of B01008 final deficiency rept re small pipe hangers FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/10/21 ip
- DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B010070475 Summary of 800805 meeting w/Hark II owners to discuss lead plant interim condensation oscillation & chugging loads.
 Discussion topics, attendance & meeting handouts encl
 ANDERSON.C J Generic Issues Branch B0/08/27 98pp.
- 8010060102 Summary of 800704-05 meeting w/Mark II owners in Bethesda, MD re long-term program chugging & Eateral loads Attendance list & handouts encl
 ANDERSON.C J Generic Issues Branch 80/07/12 45pp.
- 8010010025 Forwards request for add1 info re NUREO-0578 Outstanding items include clarification of increased range monitors, integrity of radioactivity barriers in sys outside containment & post accident sampling commitments TEDEBCO.R L. Assistant Director for Licensing. 80/09/18. 4pp,
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl.
 EISENHUT.D O Division of Licensing 80/07/19, 28pp.
- 8010100341 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from 800917 meating Requests info re which program best fits NRC schedule

 LAMKEN-D.C. Commonwealth Edison Co. 80/09/24, 2pp
- 80:10020435 Forwards 800727 rept, "Preliminary Assessment Human Factors Review of Lasalle County Station Control Room," per NURG-0574 requirements Mosting tentatively scheduled 80:015 to discuss NRC recommendations DELOSORGE, L 0 Commonwealth Edison Co 80/07/27 1p
- --8010020444 "Preliminary Assessment Human Factors Review of Lasalle County Station Control Room "
 4 Commonwealth Edison Co. 80/09/29 83pp
- 8010230010 Summary of 800924 meeting w/util & Sargent & Lundy in Bethesda, MD re applicant rs-evaluation program relative to seismic qualification of equipment Lists milestones established Attendes list encl BOURNIA: A Licensing Branch 1 80/10/01 3pp.
- 8010170171 Summary of 800903 meeting w/util in Bethesda.MD re coil properties used in soil-structure interaction enalyses. BGURRIA.A Licensing Brench 3 80/10/07 4pp
- 8010230594 Notification of 801027 meeting w/util in Bethesda. ND re audit rept from site visit & schedule for implementing control room design changes BOURNIA: A Licensing Branch 1, 80/10/07 3pp
- 8010190474 Forwards "Equipment Requalification Program for Pool Dynamic Loads" Rept updates 800804 transmittal by inclusion of open items list for balance of plant & NSBS equipment currently being tested Rept awailable in Central Files only. DELGEORGE, L. O. Commonwealth Edison Co. 80/10/08, 2pp
- 8010210538 Forwards response to NRC questions re floofplain mgt transmitted by RL Tadesco 800805 ltr to DL Peoples. Facilities do not alter predicted flood levels associated w/1% flood formal FSAR transmittal has not been developed. DELGEORGE, L.O. Commonwealth Edison Co. 80/10/16 14pp.
- 8010290417 Notification of 801029-31 meeting w/util at LaSalle site, IL re instrument & control drawing review BOURNIA, A Licensing Branch 1, 80/10/17 2pp
- --8010270418 Notification of 801027-31 site visit & meeting to discuss specific items & necessary followup actions THATCHER, D.F. Instrumentation & Control Systems Branch. 80/10/17, App.

- BO1024043B Forwards response to NUREO-0694 requirements Augments 800415 transmittel re commitments satisfying TMI short-term Leasons Learned guidelines info will be included in App L. of FSAR DELOGRABLE Of Commonwealth Edison Co. 80/10/20 100pp
- 8010280322 Forwards info re assumptions used in pool-temp analysis of stuck open relief valve, in response to NRC 800915 request Justifications for manual stram occurring at 110 F pool temp & for use of main condensor as heat sink encl DELOEDRGE.L O Commonwealth Edison Co 80/10/21 ip 16
- K Utility Final Safety Analysis Report (FSAR) & amends
- B010020454 Forwards draft revision to FBAR re qualification of insp & testing personnel & safety classification of reactor internals RAUSCH,T J Commonwealth Edison Co. 80/09/26 ip.
- --8010020459 Draft Amends 41.46.49 & 50 to FBAR re qualification of insp & testing personnel & safety classification of reactor internals * Commonwealth Edison Co 80/09/26 11pp
- B010280254 Forwards Amend 50 to FSAR, including new App Mirevised responses to Reactor Bys Branch questions, one response to second-round question & updated oversize drawings in Section 1 7 of FSAR JANECEK, R F Commonwealth Edison Co 80/10/20, 1p
- --8010280257 Amend 50 to FBAR
 * Commonwealth Edison Co 80/10/20 225pp
- --Boi0280260 Package of 529 oversity electrical drawings submitted as part of Amend 50 to FSAR Drawings will be recalled at later date for microfilming
 4 Commonwealth Edison Co BO/10/20 525pp
- P Operating license stage documents & correspondence
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Pian Requirements" Urges NRC to consider usigning each proposed revision against benefit of having plant changes implemented promptly REED.C Commonwealth Edison Co 80/10/01 5pp.
- 8010210039 Notification that 801023 meeting w/util has been rescheduled to 801027. Meeting will be held in Bethesda. MD to discuss audit rept from site visit & to establish schedules implementing control room design changes
 BOURNIA, A Licensing Branch 1 80/10/07 3pp
- Q Inspection reports, IE Bullatins & correspondence
- 8010160133 Forwards IE Insp Repts 50-373/80-30 & 50-374/80-19 on 800617-0725 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/21 2pp
- --8010160137 Notice of violation from insp on 800617-0725, * Region 3. Chicago. Office of the Director 80/08/20 ip.
- --B010160145 IE Insp Repts 50-373/80-30 & 50-374/80-19 on 800617-0725 Noncompliance noted installed temporary power supply to battery charger not recorded in temporary feed log Condition corrected 800707 SPESSARD, R. L. WALKER, R. D., SHEPLEY, B. E. Region 3, Chicago, Office of the Director 80/08/20 9pp
- 8010100009 Forwards IE Insp Repts 50-373/80-35 & 50-374/80-22 on 800819-20 No noncompliance noted. FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/04 2pp.
- --8010100012 IE Insp Repts 50-373/80-35 & 50-374/80-22 on 800819-20, No noncompilance noted Major areas inspected instrumentation cable instellation in Unit 2 & suppression pool mods in Units 1 & 2.
 HILLIAMS, C C . NEISLER.J H . MATTEO.A J Region 3. Chicago, Office of the Director. 80/09/02 4pp
- 8010160330 Forwards IE Insp Rept 50-374/80-23 on 800826-27 No noncompliance noted FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/09/10 2pp

- --8010160336 IE Insp Rept 50-374/80-23 on 800826-27 No noncompliance noted Major areas inspected review of preservice insp procedures, work activities & review of nondestructive examinations data repts
 WARD, K D Region 3. Chicago, Office of the Director DANIELSON, D H Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 4pp
- 8010150225 Responds to NRC 800B14 & 27 ltrs re violations noted in [E Insp Repts 50-373/B0-32 & 50-374/B0-20 Corrective actions bore hanger insp will be conducted using procedure EC-7 ABEL. J 6 Commonwealth Edison Co 80/09/26 7pp
- B010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director B0/09/30
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director BO/10/02 to
- 8010290181 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/80-32 & 50-374/80-20 FIDRELI, & Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/10/09 Ip
- --8010270172 Responds to NRC 800827 ltr re violations noted in IE Insp Repts 50-373/80-32 & 50-374/80-20 Corrective actions, contractor organization charts revised to delineate job classifications & util conducted audits. ABEL.J B Commonwealth Edison Co 80/07/26 9pp
- 8010270037 Forwards IE info Notice 80-36. "Failure of Steam Cemerator Bupport Bulting " No specific action or response requested. KEPPLER, J. G. Region 3, Chicago: Office of the Director 80/10/10
- 8 Reportable occurrences, LERs & related correspondence
- 8010070265 PNO-III-80-165 Region 3 is preparing to issue immediate action ltrs on 800703 confirming that utils will stop installation of lead plastomer & silicons gel penetration seals made by Tech-Sil Inc.
 NEISLER, J H Region 3, Chicago, Office of the Director 80/09/03
- 8010240546 Ack receipt of final rept re MSIV leakage control sys Review to be completed during future insp. FIDRELLI, O Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/10/09 ip
- --8010240551 Deficiency rept re MBIV leakage control sys. Addl liquid bleedoff drainline installed downstream of heaters to prevent venting & back flow from sump DELOEOROE, L. D. Commonwealth Edison Co. 80/09/19. 2pp
- 8010270228 Act receipt of 801008 final deficiency rept re small pipe hangers. FIGRELLI, Q Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/10/21. Ip
- DOCKET 80-375 NUCLEAR EXAMINATION REACTOR
- J. Insurance & indomnity information
- 9010280285 Requests Endorsements 91.92 & 93 to Policy NF-12 & Endorsements 81 & 82 to Policy NF-93.
 DINITZ.I. Utility Finance Branch (formerly Antitrust & Indemnity) 80/99/24 ip.
- 8010230002 Unexecuted Amend 17 to Indemnity Agreement 8-13, changing Item 3 of attachment re license numbers SALTYMAN, J. Utility Finance Branch (formerly Antitrust & Indemnity), BO/09/27. ip.
- 8010280434 Forwards executed Amend 17 to Indemnity Agreement 8-13, deleting Item 3 re license number or numbers from agreement. BRINDLEY.J.H. Rockwell International Corp., Energy Systems Div. B0/10/23 2pp.

DOCKET 50-376 NORTH COABT NUC PLANT

- Q Adjudicatory correspondence
- 8010030116 Response in apposition to Citizens for Conservation of Natural Resources 800913 motion requesting deferral of ASLAB action on ALAB-605 until return of representative Commission decision does not affect intervenors W/Certificate of 8vc MCGURREN.H J Hearing Branch 3 80/09/30 App
- 8010080273 Response in opposition to Citizens for Conservation of Natural Resources motion for direct certification urging dismissel of application wyprejudice Future applications may not be barred unless public harmed Cartificate of Svc encl. AXELRAD, M Puerto Rico Electric Power Authority AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 80/10/03 10pp
- 8010140363 Response to intervenors' 800918 motion for stay of proceedings stating no position until ASLB has acted on request for direct certification Request should be dismissed w/o prejudice W/Certificate of Svc MCOURREN.H J Hearing Branch 1 80/10/08 App
- --80j0140571 Brief in opposition to intervenors' 800718 motion for direct certification to request application be dismissed w/o prejudice Motion is premature Denial will not cause irreparable harm Certificate of 8vc encl
 MCGURREN.H J. Hearing Branch i 80/10/08 21pp
- B010200598 Order granting intervenor 800913 request for stay of proceedings until 15 days after Commission ruling on intervenor 800918 motion for certification MCLEE.8 J. Atomic Safety and Licensing Board Panel. 80/10/16 ip
- 8010210819 Order declining to grant directed certification re 0 Fernos 800917 motion to dismiss CP application w/prejudice Transfers motion to ASLB for decision Appeal may be pursued following ASLB ruling.

 CHILK, B. J. Office of the Secretary of the Commission. 80/10/17 in.

DOCKET 50-978 CADRED NUCLEAR STATION

- A Application/construction stage documents & correspondence
- B01027023B Notification of B01008 meeting w/representatives from Mark II owners group in Bethesda, MD to discuss Mark II plants chugging load spec ANDERBON, C Generic Issues Branch 80/09/22. 1p

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 8010090230 Notification of change in location for 800730 meeting w/util in New York,NY to discuss status of Mechanical Engineering Branch open items W/o encl agenda.

 KANE,W Licensing Branch 2 80/09/18. 1p.
- B010230106 Notification of 800930 meeting w/util in NY to discuss status of Mechanical Engineering Branch open items MANE,H Licensing Branch 2 80/09/18 4pp
- BO10220097 Forwards errata sheets amending BO0905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D G Division of Licensing 80/09/19. 28pp
- B010090444 Notification of cancellation of 801010 meeting w/util in Taff.LA to review requirements for initial test program (FSAR Chapter 14).
 KANE.W. Operating Reactors Branch 2. 80/09/29 ip
- 8010160266 Notification of 801008 meeting w/util onsite to review initial test program requirements

 KANE.W Licensing Branch 2 80/09/29 5pp.
- BO10140302 Advises that methodology used in MBB-NA1-P. "Qualification of Reactor Physics Methods for Application to PMRs in Middle South Utils Bys." will be used to support facility supplemental safety evaluation MAURIN.L V. Louisiana Power & Light Co BO/10/08. 2pp

- B010270247 Provides background info on schedule & scope of facility OL stage environ review for initiating appropriate NEPA review & technical oversight functions Also provides lists of personnel assigned to OL review & tentative review goals BCHMENGER, A Licensing Branch 2 B0/10/08 4pp
- 8010310419 Forwards action items from 800930-1003 status rept meeting re facility & slides used in piping preoperational vibration test program & asymmetric loads presentations Util, Ebesco Svcs. Inc & C-E are proceedings w/resolution MAURIN, L V Louisiana Power & Light Co 80/10/24 18pp
- C Utility Environmental Report (ER), amends & correspondence
- 8010280440 Forwards Vol 4 of environ rept consisting of Amend 2 ASHELL: D L Louisiana Power & Light Co 80/10/23 3pp
- --8010280447 Val 2 of environ rept consisting of Amend 2 * Louisiana Power & Light Co 80/10/31 1000pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010010382 Forwards Amend 12 to application for CL, consisting of Amend 12 to FSAR
 ASWELL,D L. Louisiana Power & Light Co 80/09/26 19
- --8010010589 Amend 12 to application for OL.including responses to addl info requests from NRC Power Sys Branch, Reactor Sys Branch, Instrumentation & Control Sys Branch & miscellaneous internally generated changes ABMELL,D L Louisiana Power & Light Co 80/09/26 2pp
- --BO10010575 Amend 12 to FBAR, including responses to add1 info requests from NRC Power Bys Branch, Reactor Bys Branch, Instrumentation Control Bys Branch & miscellaneous internally generated changes,
 ASHELL, D. L. Louisiana Power & Light Co. B0/09/26 150pp
- --B010030376 Supporting documentation for Amend 12 to FSAR 4 Louisians Power & Light Co 80/07/26, 125pp
- --8010030380 Package of 141 plectrical drawings to be recalled at later date for microfilming.

 4 Louisiana Power & Light Co 80/09/25 141pp.
- 8010070025 Certifies syc of FBAR, Amend 12 on 801001 * Louisiana Power & Light Co 80/10/01 ip
- G Inspection reports, IE Bulletins & correspondence
- 8009300212 Submits response to IE Bulletin 80-09 ITT General Controls Beries AM-90 & NM-90 hydramotor actuators will be used in safety-related sys Problems are being investigated & corrective actions are being taken ABMELL, D. L. Louisiana Power & Light Co 80/08/29 2pp
- 8010270027 Forwards IE Insp Rept 50-982/80-20 on 800811-15 & notice of violation SEIDLE, M. C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/09/08 2pp
- --8010270028 Notice of violation from insp on 800811-15
 ** Region 4, Dallas, Office of the Director 80/08/29. 2pp
- ---8010270030 IE Insp Rept 50-382/80-20 on 800811-15 Noncompliance noted failure to follow procedural requirements for tension testing of installed expansion anchors NEACH.A.B., STEWART.R.C., CROSSMAN,W A Region 4, Dallas, Office of the Director 80/08/29. 7pp
- 8010270024 Forwards IE Insp Rept 50-382/80-21 on 800819-22 No noncompilance noted SEIDLE,W C. Region 4. Dellas. Reactor Construction & Engineering Support Brench. 80/09/10 2pp
- ---8010270026 IE Insp Rept 50-382/80-21 on 800819-22. No noncompliance noted, Major areas inspected const activities related to followup review of previously unresolved items STEMART,R.C. CROSSMAN.H A Region 4, Dallas, Office of the Director. 80/09/09 3pp
- 8010280279 Forwards IE Insp Rept 80-382/80-23 on 800714-0815 No noncompilance noted, MADBEN, Q.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 80/09/11 2pp.

- --8010280282 IE Insp Rept 50-382/80-23 on 800714-0815 No noncompliance noted Major areas inspected operational staffing & overall preoperational test program CONSTABLE, O. L. WESTERMAN, T. F. Region 4, Dallas, Office of the Director 80/09/10 2pp
- 8010160113 Forwards Suppl 2 to IE Builetin 79-018, "Environ Qualification of Class IE Equipment " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/09/30 to.
- 8010270525 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required EEYFRIT, K. V. Region 4, Dallas. Office of the Director. 80/10/02
- 8 Reportable occurrences, LERs & related correspondence
- 8009300942 Notifies that util response to Potential Const Deficiency 27 re ITT General Control actuators will be addressed in response to IE Bulletin BO-09. "Hydramotor Actuator Deficiencies" Response will be completed by 800829 AGMELL,D L. Louisians Power & Light Co 80/08/15 1p
- 8009050288 Deficiency rept re cracking problem in electrical wiring conduit Caused by overbending below original published min inside bend diameters. HIII replace conduits installed at bend diameters below min inside bend diameter CADV.N S . KNIGHT.K F Anaconda Co. Anaconda Matel Hose Div. 80/08/29 29p
- --8009050273 "Nuclear Wiring Conduit, Types NWC & NPH Flexible Liquidtight Hiring Conduits." Technical Data Rept 3727

 * Anaconda Co, Anaconda Metal Hose Div 79/05/11. 28pp
- --8009050296 "Liquidtight Flexible Steel Conduit" * Underwriters Laboratory UL 360. 80/08/29 30sp
- 8010060352 Rept on Bignificant Const Deficiency iB re flexible liquid tight wiring conduit covering failure (Amacanda) Deficiency under evaluation Rept will be submitted by 801017 ASHELL.D L. Louisians Power & Light Co. 80/10/01 ip.
- 8010210459 Final Rapt for Bignificant Const Deficiency iS re Anaconda flexible liquid tight wiring conduit covering failure Gaused by jackt failing & separating from metal. Installed conduits will be covered w/Okonite T-05 bage CRNICH.J., HILHIBER.R.J., ASHELL.D L. Louisiana Power & Light Co. 80/10/15 4pp
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

 A Application/construction stage documents & correspondence
- B010070675 Forwards summary of 800730 meeting w/util ra operations & insp program Subje discussed included GA & GC programs CARLSON,R T. Region i. Philadelphia. Reactor Construction & Engineering Support Branch 60/08/22 2pp
- 8010070495 Summary of 800805 meeting w/Mark II owners to discuss lead plant inter(m condensation oscillation & chapging loads. Discussion topics, attendance & meeting handouts encl ANDERSON, C J Generic Issues Branch 80/08/29 98pp
- B010060102 Summary of B00704-05 meeting w/Mark II owners in Bathesda, MD re long-term program chugging & lateral loads. Attendance list & handouts encl.
 ANDERSON.C J. Gameric Issues Branch. 80/09/12. 65pp.
- B010010032 Forwards request for addl info re containment sys, for NRC review of application for OLS Required info includes spaces re containment pressure, operator action & valve configuration
 TEDESCO, R L, Assistant Director for Licensing 80/09/17. Spp.
- 8010020119 Forwards request for add1 info on reactor sys for NRC review of application for DLs.
 TEDESCORR L. Assistant Director for Licensing. 80/09/19. 8pp.
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also enci. EISENHUT.D.Q Division of Licensing. 80/09/19. 28pp.

- 8010270238 Notification of 801008 meeting w/representatives from Harl II owners group in Bethosda.MD to discuss Mark II plants chugging load spac. ANDERGON.G Generic Issues Branch 80/09/22 ip
- 9010140271 Forwards Amend 24 to OL application, containing Revision 17 to FBAR GURTIS.N W Pennsylvenia Power & Light Co 80/09/30, 1p
- --8010140274 Application for Amend 24 to DL application.containing Revision 17 to FBAR CURIEN W Pennsylvania Power & Light Co 80/09/30 1p
- 8010210324 Confirms 801027-31 for NRC visit to prepare preliminary avaluation of control room w/regard to listed items. Requests that util perform preliminary human factors assessment of control room Assessment info encl
 8TARK.R M Licensing Branch 1 80/10/01 6pp
- 8010070585 Requests revisw of encl analysis of time required until 05 issuance. NRC review activities in next A months do not support util licensing & const schedule RAUFFMAN. J T Pennsylvania Power & Light Co 80/10/02 4pp
- B010220041 Forwards request for add1 info re core performance to complete OL application review Outstanding items include descriptions of racks & assumptions made in analysis re fuel reactivity, pool water temp & assembly placement TEDESCO.R L. Assistant Director for Licensing 80/10/02 3pp
- 8010210411 Forwards pressure curves for MSIV closure w/pressure scras, per 800821 request, CURTIB:N W. Pennsylvania Power & Light Co. 80/10/17 3pp
- 8010270180 Notification of 801105-06 meating w/util to discuss case load forecast & to visit site.
 STARK, R.M. Licensing Branch 1 80/10/21 6pp.
- F Security, medical, emergency & fire protection plans
- 8010280644 Responds to fire protection safety evaluation Item 3 2
 Proposed configuration of marinite board fire barriers to be
 installed in manholes encl Redundant syc water pump cables
 will be wrapped w/thermal barrier tape.
 TRIMBLE.D.C Arkansas Power & Light Co. 80/10/21 8pp
- ---8010280648 Revision A to "Electrical Wire & Cable Isolation Barrier Matls Test for Busquehanna Steam Electric Station, Units 1 & 2 for Sectel Power Corp "
 ALBA, A., BURROWS, A., SHIPWAY, O. Hyle Laboratories 80/07/28, 2000a
- 0. Adjudicatory correspondence
- GO10140502 Request for establishment of scheduls for completion of discovery re health & safety issues to avoid imposing multiple burdens on intervenors Certificate of Byc encl. Related correspondence SILBERG. J E Pennsylvania Power & Light Co SILDERG. J E. Shaw, Pittman. Potts & Trowbridge BO/10/07 7pp
- 8010140323 Requests to make limited appearance statement at licensing prehearing. Also requests that hearing be scheduled during evening hours &/or weekends.

 MUERTH. U. WUERTH. H. Affiliation Unknown. B0/10/10. 1p
- 8010210515 Response in opposition to applicant request reinterrogatories on safety issues Environ phase must take priority over safety-related discovery per ASLB 791030 order Certificate of Svc encl
 JDHNSRUD-J.H. Environmental Coalition on Nuclear Power 80/10/10
 3pp.
- B010270510 Notice of address changs. SCHULTZ, G. R. Susquehanne Environmental Advocates. 80/10/21 1p.
- 8010270457 Requests permission to make limited appearance statement at licensing proceedings.
 ELLIOTT, C W Thomas & Hair, 80/10/23, 1p.
- 8010300618 Affidavit in support of summary disposition of Contention 16 we cooling tower discharge. No radioactive water will be vanted from facility cooling towers Prof qualifications encl.
 RHOADES, H. J. Pennsylvania Power & Light Co. 80/10/24. 11pp

- 8010300561 Certifies svc of applicants' motion for summery disposition of Contention 16 w/supportive statement of matl facts & MJ Rhoades affidavit on 801027
 SILBERG, J E Ponnsylvania Power & Light Co SILBERG, J E Allegheny Electric Cooperative, Inc. 80/10/27 3pg
- 8010300606 Hotion for summary disposition of Contention 16 re cooling tower discharge supported by statement of matl facts reabsence of issues to be heard & My Rhoades affidavit Rusponses due in three wks per ASLB 790306 order SILBERG. J E . TRAVIESO-DIAZ Pennsylvanie Power & Light Co SILBERG. J E . Alleghang Electric Cooperative, Inc. 80/10/27, 2pp
- GO10300613 Statement of matl facts re absence of genuine issue to be heard, in support of summany disposition of Contention 16 on coaling tower discharge Sys designed to evaporate water daily from towers w/o radioactive releases
 SILBERO, J E , TRAVIESO-DIAZ Pennsylvania Power & Light Co
 SILBERO, J F , Allegheny Electric Cooperative. Inc 80/10/27 Spp.
- M Utility Final Bafety Analysis Report (FBAR) & amends
- 8010140271 Forwards Amend 24 to OL application, containing Revision 17 to FSAR CURTIS, N N Pennsylvania Power & Light Co 80/09/30. 1p
- --B010140274 Application for Amend 24 to CL application, containing Revision 17 to FBAR CURTION N Pennsylvania Power & Light Co B0/09/30 ip
- --8010140279 Revision 17 to FSAR * Pennsylvania Power & Light Co 80/09/30 725pp
- P Operating license stage documents & correspondence
- B010270200 Forwards request for add1 info re chemical angineering for review of application for OLs
 TEDESCO.R.L Assistant Director for Licensing G0/10/17 3pp
- @ Inspection reports, IE Bulletins & correspondence
- 8010230033 Forwards IE Insp Repts 50-387/80-16 & 50-388/80-12 on 800715-18 & 0727-0801 No noncompliance noted CARLSON.R.T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/25 Zpp
- --8010230043 IC Insp Repts 50-387/80-18 & 50-388/80-12 on 800715-18 & 0727-0801 No noncompliance noted Major areas inspected installation of safety-related instruments, review of responses to IE bulletins & discussions w/craft personnel, ESNETER: 8 D Region i, Philadelphia, Reactor Construction & Engineering Support Dranch PAOLINO, R. Region 1, Philadelphia, Office of the Director 80/08/22 9pp
- 8010020087 Responds to IT Bulletin 80-16 re Resemburt Models 1151 & 1152 pressure transmitters Transmitters in use & application evaluation underway Complete response will be provided by 800917.

 CURTIS.N.W Pennsylvania Power & Light Co. 80/08/27. 1p.
- 8010010684 Responds to IE Bulletin 80-19 & 80-19 Revision 1 Memcury-wested relays are not used in logic matrix of reactor protection sys. GURTIB:NW Pennsylvania Power & Light Co 80/09/02. 2pp
- 8010010833 Submits revised schedule for completion of Nuclear Class 1 stress repts for piping sys per IE Bulletin 79-14.

 GURTIS.N.W Pennsylvania Power & Light Co 80/09/11. Rpp.
- 8010140028 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-12 & 50-389/80-08. CARLSON.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/17. ip.
- --8010140031 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-387/80-12 & 50-388/80-08, Corrective actions, Nuclear Engineering Svcs committed to update certification documentation in more timely manner CURTIS.N W Pennsylvania Power & Light Co. 80/08/20, Spp.
- --8010140033 Forwards IE Insp Repts 50-387/80-12 & 80-388/80-08 on 800610-13 & 16 & notice of violation.
 CARLEGN.R.T Region 1: Philadelphia, Reactor Construction & Engineering Support Branch, 80/07/10. 2pp.
- --8010140038 Notice of violation from inep on 800410-13 & 16.

 # Region I, Philadelphia, Office of the Diractor. 80/07/08. 1p.

- --8010140043 IE Insp Repts 50-387/80-12 & 50-388/80-08 on 800610-13 & 16 Noncompliance noted failure to follow implementing nondestructive examination personnel certification procedure DURRY./P. HCBREARTY.R A. Region 1. Philadelphia, Office of the Director HCGAUGHY.R W. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/08 7pp
- 8010270194 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches. Eighty-eight switches are used at facilities Corrective actions will be submitted 801030 CURTIS.N W Pennsylvania Power & Light Co 80/09/23 2pp
- 8010240045 Submits partial response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc. Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Analyses of transmitter maloperation are in progress, CURTIS.N.W Pennsylvania Power & Light Co. 80/09/30. 2pp
- 8010240110 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. ORIER, B.H. Region I, Philadelphia, Office of the Director, 80/10/02.
- 8010280167 Forwards IE Info Notice 80-36, "Failure of Steam Centerator Support Buiting." No specific action or response requested ORIER.B.H Region i, Philadelphia, Office of the Director 80/10/10. ip.
- S. Reportable occurrences. LERs & related correspondence
- B010060247 Interim deficiency rept re defective Limitorque limit switch rotors Following engineering evaluation insp program will be implemented. Defective rotors will be replaced.

 CURTIB.H. W Pennsylvania Power & Light Co. 80/09/23, 2pp.
- 8010060284 Interim deficiency rept re application of Hilti shell anchors Final repts on Teledyne static & cyclic testing will not be available until Oct 1980 Final rept will be submitted by Dec 1980

 CURTIS.N # Pennsylvania Power & Light Co 80/09/25 ip
- 8010070086 Final deficiency rept re power generation control complex/ advanced control room cable connector. Insp program nearly complete All Unit 1 cable repairs will be completed prior to fuel load Unit 2 cables will be installed & repaired CURTIS:N W. Pennsylvania Power & Light Co. 80/09/29 Spp
- 8010070300 Final deficiency rapt re electrical cable damaged during pulling operations Serviceability of installed cables will be achieved by compliance w/Field Procedure FP-E-5 during const phases Supporting documentation encl CURTIS:N.W. Pennsylvania Power & Light Co. 80/09/29 18pp.
- 8010100337 Supplemental deficiency rept re Anchor Darling valve yokes. Condition continues to be tracked under MCAR 1-59. Final rept will be forwarded by Jan 1981, after completion of manufacturer testing CURTIS.N. U. Pennsylvania Power & Light Co 80/10/02 ip.
- 8010140331 Interim deficiency status update rept re Pacific check valves Bechtel investigation & rept re defective check valves will not be available until 801231 Will submit final rept by 810131.

 CURTIS-N. W Pennsylvania Power & Light Co. 80/10/06, ip.
- 8010240436 Interim deficiency rept re excessive voltage drops in ac motor operated valve controls circuits ER 100450 & ER 100508. Caused by sizeable resistence of small control cable long lengths. Alternatives being evaluated, CURTIS, N W Pennsylvania Power & Light Co. 80/10/20, 2pp.

V. Operator Examinations

- 8010220072 Notification of 801014 meeting w/util in Bethesda MD to discuss operator qualification requirements & util mgt organization. STARK/R.M. Licensing Branch 1. 80/09/22, 4pp.
- B010270415 Summary of S01014 meeting w/util in Bethesda, MD re operator qualification status & recent revision of mgt organization.
 STARK.R.M. Licensing Branch 1 80/10/20. 4pp.

- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B010070675 Forwards summary of B00730 meeting w/util re operations & insp program Subjs discussed included 9A & QC programs CARLSON,R T Region 1: Philadelphia, Reactor Construction & Engineering Support Branch B0/08/22 2pp
- B01009047B Summary of B00805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads Discussion topics.attendance & meeting handouts enci ANDERSON.C J. Generic Issues Branch B0/08/27 98pp
- 8010060102 Bummary of 800904-05 meeting w/Mark II comers in Bethesda. MD re long-term program chugging & lateral loads Attendance list & handouts encl
 ANDERSON.C J Ceneric Issues Branch 80/09/12 65pp
- 8010010032 Forwards request for add1 info re containment sys, for NRC review of application for GLs Required info includes spaces re containment pressure, operator action & valve configuration
 TEDESCO.R L Assistant Director for Licensing 80/09/17 5pp
- 8010020119 Forwards request for add1 info on reactor sys for NRC review of application for OLs
 TEDEBCO.R L Assistant Director for Licensing 80/09/19. Bpp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary ciarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D 0 Division of Licensing 80/09/19 28pp
- 8010270238 Notification of 801008 meeting w/rapresentatives from Mark II owners group in Bethesda,MD to discuss Mark II plants chugging load spec ANDERBON.C Generic Issues Branch. 80/07/22 ip
- 8010140271 Forwards Amend 24 to DL application, containing Revision 17 to FBAR. CURTIS N W Pennsylvania Power & Light Co 80/09/30 lp.
- --8010140274 Application for Amend 24 to QL application, containing Revision 17 to FBAR
 CURTIS:N H Pennsylvania Power & Light Co 80/09/30 ip
- 8010210324 Confirms 801027-31 for NRC visit to prepare preliminary evaluation of control room w/regard to listed items Requests that util perform preliminary human factors assessment of control room Assessment info encl
 STARKUR N Licensing Branch 1 80/10/01 6pp
- 8010070585 Requests review of encl analysis of time required until DL issuance NRC review activities in next 6 months do not support util licensing & const schedule KAUFFMAN.J.T Pennsylvania Power & Light Co 80/10/02 4pp.
- 8010220041 Forwards request for addl info re core performance to complete OL application review Outstanding items include descriptions of racks & assumptions made in analysis re fuel reactivity, pool uster temp & assembly placement TEDESCO, R L Assistant Director for Licensing 80/10/02 3pp
- H010210411 Forwards pressure curves for MSIV closure w/pressure scram, per 800821 request CURTIS-N W Pennsylvania Power & Light Co H0/10/17 3pp.
- B010290200 Forwards request for add1 info re chemical engineering for review of application for OLs TEDESCO.R L Assistant Director for Licensing 80/10/17 3pp
- 8010270180 Notification of 801105-06 meeting w/util to discuss case load forecast & to visit site STARKAR M Licensing Branch 1. 80/10/21. App
- F Security, medical, emergency & fire protection plans
- B010280644 Responds to fire protection safety evaluation Itam 3.2. Proposed configuration of marinite board fire barriers to be installed in manholes encl.Redundant syc water pump cables will be wrapped withermal barrier tape TRIMBLE, D.C. Arkansas Power & Light Co. B0/10/21. Bpp.

- --8010280648 Revision A to "Electrical Wire & Cable Isolation Barrier Matls Test for Busquehanna Steam Electric Station, Units i & 2 for Bechtel Power Corp " ALBA:A. BURROWS, A., SHIPWAY, O Wyle Laboratories, 80/07/28, 2000p.
- O Adjudicatory correspondence
- B010140302 Request for establishment of schedule for completion of discovery re health & safety issues to avoid imposing multiple burdens on intervenors Certificate of Bvc encl Related correspondence
 BILBERG.JE Pennsylvania Power & Light Co BILBERG.JE Bhaw, Pittman, Potts & Troubridge B0/10/07 7pp
- 8010140323 Requests to make limited appearance statement at licensing prehearing Also requests that hearing be scheduled during evening hours &/or weekends HUERTHHU. RECENTION Affiliation Unknown 80/10/10 ip
- 8010210515 Response in opposition to applicant request re interregatories on safety issues Environ phase must take priority over safety-related discovery per ABLB 791030 order.Certificate of Svc enci JOHNSRUD, J H Environmental Coalition on Nuclear Power, 80/10/10 3pp
- 8010270510 Notice of address change, SCHULTZ.9 R Susquehanna Environmental Advocates 80/10/21, 1p.
- 8010270457 Requests permission to make limited appearance statement at licensing proceedings ELLIOTT.C W Thomas & Hair 80/10/23 ip
- 80103006:8 Affidavit in support of summary disposition of Contention 16 re cooling tower discharge. No radioactive water will be vented from facility cooling towers Prof qualifications and RHOADES. W J. Pennsylvania Power & Light Co. 80/10/24. 11pp.
- 8010300361 Certifies svc of applicants' motion for summary disposition of Contention 16 w/supportive statement of matl facts & MJ Rhoades afficavit, on 801027 SILBERG, J E Pennsylvania Power & Light Co. SILBERG, J. E. Allegheny Electric Cooperative, Inc. 80/10/27 3pp
- 8010300606 Motion for summary disposition of Contention 16 re cooling tower discharge supported by statement of matl facts re absence of issues to be heard & MJ Rhoades affidevit Responses due in three was per ASLB 790306 order.
 SILBERG, J. E. TRAVIESO-DIAZ Pennsylvania Power & Light Co BILBERG, J E Alleghany Electric Cooperative, Inc. 80/10/27. 2pp.
- 8010300613 Btatement of math fects re absence of genuins issue to be heard, in support of summary disposition of Contention 16 on cooling tower discharge Bys designed to evaporate water daily from towers w/o radioactive releases
 SILDERGOJE: TRAVIESD-DIAZ Pennsylvania Power & Light Co.
 BILBERGOJE: Allegheny Electric Cooperative, Inc. 80/10/27 3pp
- K Utility Fine1 Safety Analysis Report (FSAR) & amends
- BOI0140271 Forwards Amend 24 to CL application containing Revision 17 to FBAR CURTIEN W Pennsylvania Power & Light Co 80/09/30 ip.
- --8010140274 Application for Amend 24 to DL application.containing Revision 17 to FSAR CURTIS.N.W. Pennsylvania Power & Light Co 80/09/30 ip.
- --8010140279 Revision 17 to FSAR + Pennsylvania Fower & Light Co. 80/09/30 725pp.
- Q Inspection reports, IE Bulletins & correspondence
- 8010230033 Forwards IE Insp Repts 50-387/80-18 & 50-388/80-12 on 809715-18 & 0729-0801 No noncompliance noted. CARLSON: R T Region is Philadelphia, Reactor Construction & Engineering Support Sranch 80/08/25. 2pp.
- ~~8010230043 IE Insp Repts 50-387/80-18 & 50-388/80-12 on 800715-18 & 0727-0801. No noncompliance noted Major areas inspected: installation of safety-related instruments, review of responses to IE builetins & discussions w/craft personnel. EBNETER-8. D. Region i, Philadelphia, Reactor Construction & Engineering Support Breanth, PADLINO.R. Region i, Philadelphia, Office of the Director 80/08/22, 9pp

- 8010020089 Responds to IE Bulletin 80-16 re Rosemount Models 1151 & 1152 pressure transmitters Transmitters in use & application evaluation underway Complete response will be provided by 800919
 - CURTIS, N H Pennsylvania Power & Light Co 80/08/27 1p
- B010010684 Responds to IE Bulletin 80-19 & 80-19. Revision 1 Mercury-wetted relays are not used in logic matrix of reactor protection sys CURTIB.N W Pennsylvania Power & Light Co 80/09/02 2pp
- 8010010833 Bubmits revised schedule for completion of Nuclear Class 1 stress repts for piping sys per IE Bulletin 79-14 CURTIS.N.N. Pennsglvania Power & Light Co 80/09/11 2pp
- B01014002B Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-387/80-12 & 50-388/80-08 CARLBONR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/17 Ip
- --B010140031 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 30-387/80-12 & 50-388/80-08 Corrective actions Nuclear Engineering Svcs committed to update certification documentation in more timely manner CURTIS.N W Pennsylvania Power & Light Co 80/08/20 3pp
- --B010140033 Forwards IE Insp Repts 50-387/80-12 & 80-388/80-08 on B00610-13 & 16 & notice of violation CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/10 2pp
- --8010140038 Notice of violation from insp on 800610-13 & 16
 * Region 1, Philadelphia, Office of the Director 80/07/08 1p
- -B010140043 IE Insp Repts 50-387/80-12 & 50-388/80-08 on 800610-13 & 16 Noncompliance noted failure to follow implementing nondestructive examination personnel certification procedure

 DURR, J P , MCBREARTY, R A Region 1, Philadelphia, Office of the Pirector MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/08, 7pp.
- 8010270194 Responds to IE Bulletin 80-20. "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches Eighty-eight switches are used at facilities Corrective actions will be submitted 801030 CURTIG.N W Pennsylvania Power & Light Co 80/09/23, 2pp.
- B010240045 Submits partial response to IE Bulletin B0-16, "Potential Misapplication of Rosemount, Inc. Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Analyses of transmitter maloperation are in progress CURTIS, N W Pennsylvania Power & Light Co 80/09/30 2pp
- 8010240110 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director. 80/10/02 ip
- 8010280167 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested requested
 ORIER.B H Region 1. Philadelphia, Office of the Director
 BO/10/10 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8010080380 PNO-I-80-123, on 800819, licensee reported chromate ion concentrations of 1 4 % 0 38 ppm in onsite settling basins.
 Source of contamination is sodium chromate used as corrosion inhibitor in RHR sys
 SLOBODIEN,M , BORES,R , SMITH,O Region 1, Philadelphia, Office of the Director 80/08/19 Ip.
- 80:0060247 Interim deficiency rept re defective Limitorque limit switch rators.Following engineering evaluation. Insp program will be implemented Defective rators will be replaced CURTIB:N W Pennsylvania Power & Light Co. 80/09/23. 2pp,
- 8010060284 Interim deficiency rept re application of Hilti shell anchors Final repts on Teledyne static & cyclic testing will not be available until Oct 1980 Final rept will be submitted by Dec 1980.

 CURTIS.N.W Pennsylvania Power & Light Go 80/09/25. 1p.

- 8010070086 Final deficiency maps are power generation control complex/advanced control room cable connector Inap program nearly complete All Unit 1 cable maps will be completed prior to fuel load Unit 2 cables will be installed & mapsimed CURTIS.N W Pennsylvania Power & Light Co 80/09/29 5pp
- 8010070300 Final deficiency rept re electrical cable damaged during pulling operations Serviceability of installed cables will be achieved by compliance w/Field Procedure FP-E-5 during const phases Supporting documentation encl CURTIS.N N Pennsylvania Power & Light Co 80/09/29 18pp
- 8010100337 Bupplemental deficiency rept re Anchor Darling valve yokes Condition continues to be tracked under MCAR 1-59 Final rept will be forwarded by Jan 1981, after completion of manufacturer testing

 CURTIS:N U Pennsylvania Power & Light Co 80/10/02 ip
- 8010140331 Interim deficiency status update rept re Pacific check valves Bechtel investigation & rept re defective check valves will not be available until 801231 Will submit final rept by 810131 CURTISIN W Pennsylvania Power & Light Co 80/10/06 1p Pennsylvania Power & Light Co 80/10/06
- 8010240456 Interim deficiency rept re excessive voltage drops in ac motor operated valve controls circuits ER 100450 & ER 100508 Causes by sizeable resistance of small control cable long lengths Alternatives being evaluated CURTIS,N W Pennsylvania Power & Light Co 80/10/20 2pp
- V Operator Examinations
- 8010220072 Notification of 801014 meeting w/util in Bethesda MD to discuss operator qualification requirements & util mgt STARK.R M Licensing Branch 1 80/09/22 App
- 8010270415 Summary of 801014 meeting w/util in Bethesda.MD re operator qualification status & recent revision of mgt organization STARK.R M Licensing Branch i 80/10/20 4pp
- DOCKET 80-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D 0 Division of Licensing 80/09/19 28pp
- 80100B0293 Summary of 800918 meeting w/util in Bethesda:MD re facility application schedule & NRC review BIRKEL:R A Licensing Branch i 80/09/22 37pp
- 8010060294 Advises that FBAR has been forwarded to EQ&O ID.Inc for acceptance review.per NRC request Util will amend FBAR to address TMI requirements by 810101 UHRIG.R E Florida Power & Light Co 80/09/23 ip
- B0100B0643 Notification of 801009 meeting w/util at site to discuss initial test program review BIRKEL,R A Licensing Branch 1 BO/09/26 3pp
- 8010080340 Forwards list of critical review areas & description of methods/options for accelerated review of OL application Draft SER w/open items list & NRC acceptance of Unit 2 as replicate of Unit 1 are among proposed methods. UHRIG.R E Florida Power & Light Co 80/10/03 9pp
- 8010140141 Notification of rescheduled 801023 meeting w/util on Hutchinson Island,FL to discuss initial test program review Heating originally scheduled for 801007 BIRKEL,R A Licensing Branch 1 80/10/03 3pp
- 8010170150 Summary of 800930-1002 meeting w/util & EHASCO at site re status of const & projected fuel load date for unit LICITRA, E A. Licensing Branch 3 80/10/08 App
- 8010240229 Ack receipt of NRC 800823 ltr re ATHS procedure. Formal emergancy operating procedure will be prepared after plant design is in final form Vendor guidelines on ATHS procedure encl. UHRIG:R E Florida Power & Light Co 80/10/20 12pp

9 Adjudicatory correspondence

8010100071 Order granting extension until 801014 for Commission to review ALAB-603 CHILK, B.J. Office of the Secretary of the Commission 80/10/06 in

H General correspondence

- 8010080332 Advises of organizational changes in Advanced Sys & Technology & OA Depts Revision of topical GA rept will be transmitted upon completion
 UHRIO,RE Florida Power & Light Co 80/10/03 ip
- 8010290271 Responds to 800902 Itr forwarding constituent concerns re evacuation plans for Port St Lucie & Ft Pierce areas of FL FEMA has lead responsibility for emergency preparedness of state & local governments DIRCKS:H J Office of the Executive Director for Operations 80/10/21 2pp
- --B010290275 Forwards constituent line re evacuation & emergency plans STONE, R Senate 80/09/02 7pp

I Financial information

- 8010150100 Forwards request for add1 info re application for transfer of ownership to City of Griando.FL & Orlando Utils Commission TEDESCO.R L. Assistant Director for Licensing 80/09/29 App
- B010290326 Forwards financial info requested by NRC B00729 ltr re transfer of ownership interest to City of Orlando & Orlando Utils Commission Cash flow statement & bond info encl UHRIO,R E Florida Power & Light Co 80/10/10 113pp.
- --8010290329 Annual Financial Rept for 1979 Comparative financial statement 8 participation agreement encl 9 Orlando Utilities Commission 79/12/07 274pp

M Antitrust correspondence

- 8010140261 Informs NRC that pending negotiations w/util & Fort Pierce Utils Authority, prefers not to comment about proposed conditions Certificate of Byc encl WILLIAMB. © L Brown & Williams WILLIAMB. © L Fort Pierce, Fl 80/10/07 3pp
- --8010140263 Confirms that 801007 ltr telecopied & forwarded by certified mail
 HILLIAMS.G L Brown & Williams WILLIAMS.G L Fort Pierce, Ft 80/10/09 lp
- 8010160589 Notifies that, pending negotiations w/FL Power & Light, util authority prefers not to comment on proposed license conditions & reserves right to seek different terms by negotiation or order after hearing HILLIAMS, O L Fort Pierce, Fl 80/10/07 ip
- 6010150392 Response in support of util/DOJ/NRC motion imposing license conditions & requesting written objections so long as terms of participation modified so as not to impede financing. Suggests prehearing conference JABLON.R A . ROTH.A J Florida Cities, 80/10/09. 21pp.
- --8010150397 Forwards settlement correspondence between FL Cities & util covering 791019-800307 FL Cities should be allowed to participate in NRC/DOJ/util negotiations

 JABLOM.R A Spiegel & McDiarmid 80/03/10 3pp
- --8010150408 Suppls 800325 conference request in behalf of FL Cities.
 Requests info re Ft Pierce withdraual from proceeding FL
 Cities should be allowed to participate in negotiations.EE
 Henge 800401 ltr to RJ Gardner & Certificate of Syc encl
 SPIEGEL, G Florida Cities 80/04/16 10pp.
- --801019041? Requests conference re FL Cities wish to participate in settlement negotiations among DOJ, NRC & util Author 800418 ltr to DOJ, util 760904 open ltr to Vero Beach residents, supporting documentation & Certif
- 8010170364 Request to file substitute answer to util/DDJ/NRC motion re proposed license conditions to correct typographical errors List of corrections, verification & Certificate of Svc encl JABLON R A Florida Cities, 80/10/15, 4pp

- 8010220534 Hemorandum & order advising NRC & util to respond to FL Citles 801009 joint motion by 801010 if so desired SMITH,I W Atomic Safety and Licensing Board Panel 80/10/20 ip
- 8010240063 Joint motion for opportunity to reply by 801114 to FL Cities 801009 pleading raising new matters re implementation of settlement agreement Certificate of Svc encl DEWEY, L S Antitrust Division URBAN, J R Justice, Dept of DYM, H Florida Power & Light Co 80/01/21 4pp
- 8010300623 Notice of reconstitution of ASLB by appointing MA Duggan as member instead of VB Deale LAZO,R K Atomic Safety and Licensing Board Panel 80/10/28 1p
- Q inspection reports, IE Bulletins & carrespondence
- B010020721 Forwards IE Insp Rept S0-389/80-10 on 800722-25 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/08/21 2pp
- --8010020725 IE Insp Rept 50-389/80-10 on 800722-25 No noncompliance noted Major areas inspected reactor vessel installation, licensee identified items & IE bulletin BRYANT, J C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND, C R. Region 2, Atlanta, Office of the Director 80/08/20 App
- B0102300B9 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matts" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/08/29 Ip
- 90:0270275 Responds to IC Bulletin 80-08, "Examination of Containment Liner Penetration Welds," Items 1-3 Backing bars are not utilized on butt welds Ali butt welds will be radiographed UHRIG.R E Florida Power & Light Co 80/09/29 15pp
- 8010160160 Forwards Suppl 2 to IE Builstin 79-018, "Environ Qualification of Class IE Equipment" No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30
- B010270552 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No writton response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/10/02
- 8010270047 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director. BO/10/10
- 8 Reportable occurrences. LERs & related correspondence
- 8010240363 Part 21 rept re failure of motor operated valve stem during contracting testing Target Rock Model 74R-008 motor operated glove valve equipped w/Limitorque operator used in low pressure safety injection sys Cause under investigation PATTARINI Target Rock Corp 80/10/15 2pp

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATMS issue Mods will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry, Sequoyah & Watts Bar & by fuel loading at Bellefonte, Hartsville & Phipps Bend MILLS.L M Tennessee Valley Authority 80/09/17 5pp
- 8010220099 Forwards errata sheets amending 800905 itr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D 9 Division of Licansing 80/09/19, 28pp.
- 8010180433 Notification of 801007 meeting w/util in Bethesda.MD to discuss proposed waste-heat utilization park KENYON.T.J Licensing Branch 2 80/10/02 3pp
- 8010200271 Safety evaluation re temp effect on main steam safety valve satpoint. Upgrade of exhaust fan & control sys to meet safety grade & Class IE electrical & instrumentation requirements is not necessary.

 * Office of Nuclear Reactor Regulation, Director 80/10/08, Spp.

- -- 8010200277 Submits addl info re mod to heating, ventilation & air conditioning sys by TVA to resolve main steam safety valve setpoint change BENNETT, A B Division of Reactor Construction Inspection BENNETT, A B 80/06/19 5рр
- 8010270135 Amend 2 to License SRM-1861, changing expiration date to 811231 or upon conversion of CPPR-91 to GL PAGE,R O Uranium Fuel Licensing Branch 80/10/08 ip
- J Insurance & indemnity information
- 8010280258 Requests Endorsement 40 to Policy NF-256 BINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 1p
- O Inspection reports, IE Bulletins & correspondence
- 8010200637 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Hatts" 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/29
- 8010080391 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches," Lists safety-related sys using Westinghouse-type switches Addi info to be reported by 801215 MILLB.1 M Tennessee Valley Authority 80/09/16 3pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-318/80-11, 50-519/80-11 & others HURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --8010170123 Responds to NRC 800806 ltr re violations noted in IE Insp. Repts 50-327/80-24,50-328/80-15 & others Corrective actions GA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLS,L M Tennessee Valley Authority 80/09/02 14pp
- B010160184 Forwards Buppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30
- 8010240101 Ack receipt of 800917 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-390/80-24 & 50-391/80-18 50-391/80-18 MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/01 ip.
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required C'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/02
- 8010290066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Solting " No specific action or response requested. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/10
- 8010280478 Responds to infractions noted in IE Insp Repts 50-390/80-25 & 50-391/80-19 Corrective actions:procedure rewritten to include additinsp items required by IE Bulletins 79-01 & 70-14 MILLG.L.M Tennessee Valley Authority 80/10/21 3pp.
- 8010280459 Provides ravised response to Deficiency 370/80-17-01.per 800925 meeting w/NRC re 800911 response NOT examiner reinstructed in proper acceptance criteria for liquid penetrant ineps Compilance achieved MILLS.L.M. Tennessee Valley Authority 80/10/23 2pp
- 8 Reportable occurrences, LERs & related correspondence
- B0091004j4 First interim deficiency rept re incorrect valve weights in auxiliary feedwater piping. Two types of water level control valves had discrepancy in valve weights compared to data used in piping analysis, Util reanalyzing piping sys MiLLB.L.M. Tennesses Valley Authority. 80/09/04. 2pp

- 8010080429 Third interim deficiency mept me breakdown in Dravo GA program Documentation me weld buildups to be reviewed & approved by authorized nuclear inspector All available radiographic film of shop welds raviewed & no defects found MILLS.L & Tennessee Valley Authority 80/09/30 ip
- 8010090407 Final deficiency rept re lack of fusion & poor weld quality as refueling water storage tank overflow line not fabricated in accordance w/ASNE Detailed review initiated & repairs scheduled for completion Nov 1980
 MILLE, L M Tennessee Valley Authority 80/10/02 2pp
- 8010150368 Final deficiency rept re incorrect installation of nitrogen battle bank supports Appropriate design drawings have been revised & all defective anchors have been replaced & tested Disciplinary action administered to responsible personnel MILLS.L M Tennessee Valley Authority 80/10/07 2pp
- 8010140523 Second interim deficiency rept re possible inadvertent boron dilution while on residual heat removal sys Westinghouse final evaluation & recommendations will be completed by Jan 1981 Next rept will be forwarded by 810206.
 MILLS.L M Tennessee Valley Authority 80/10/08 ip
- 8010210489 Interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment. Applicable QC procedures being written b/or revised, specifying proper insp & focumentation requirements
 MILLS, L M Tennessee Valley Authority 80/10/10 ip
- 8010210365 Final deficiency rept re usage of improper matls in auxiliary board room air conditioning sys. Improper copper tubing replaced w/type K tubing OA program revised to include mandatory matl verification prior to installation MILLG.L K Tennessee Vallay Authority 80/10/14. 2pp
- 80102B0427 Final deficiency rept re failure to use correct valve weights in piping analysis Caused by discrepancy between valve weights & input data used in piping analysis. Auxiliary feedwater piping reanalyzed Required mods will be made MILLS,L M Tennessee Valley Authority 80/10/22 2pp
- 8010280626 First interim deficiency rept re seismic qualification of remote control equipment installed in safety-related sys. Equipment must be retested due to upgrading of requirements since purchase Testing should be completed in Apr 1981 MIELS, L. M Tennessee Valley Authority 80/10/22 2pp.
- DOCKET 50-391 WATTB BAR NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATHS issue Mode will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry, Bequoyah & Watts Dar & by feel loading at Bellefonte, Hartsville & Phipps Bend MILLS:L.M Tennessee Valley Authority 80/09/17 Spp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGENAUT, D O Division of Licensing 80/09/19 28pp
- 8010150633 Notification of 801007 meeting w/util in Bethesda:MD to discuss proposed waste-heat utilization park KENYON:T J Licensing Branch 2 80/10/02 3pp.
- 8010200271 Bafety evaluation re temp effect on main steam safety valve satpoint. Upgrade of exhaust fen & control sys to mest safety grade & Class IE electrical & instrumentation requirements is not necessary.

 # Office of Nuclear Reactor Regulation, Director. 80/10/08 3pp
- --8010200277 Bubmits addl info rs mod to heating ventilation & air conditioning sys by TVA to resolve main steam safety valve setpoint change.

 BENNETTA B. Division of Reactor Construction Inspection Spp.
- G. Inspection reports. IE Bulletins & correspondence
- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls " O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29.

- 8010080391 Responds to IE Bulletin BO-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Lists safety-related sys using Westinghouse-type switches Addi info to be reported by 801215 MILLS/L M Tennessee Valley Authority 80/09/16 3pp
- B010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-518/80-11, 50-519/80-11 & others HURPHY, C E Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --8010170123 Responds to NRC 800806 ltr re violations noted in IE Insp Repts 80-327/80-24,50-328/80-15 & others Corrective actions CA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies HILLS:L K Tennessee Valley Authority 80/09/02 14pp
- 90:0160:184 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/09/30
- 3010240101 Ack receipt of 800917 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-390/80-24 & 50-391/80-18 MURPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/10/01 ip
- 3010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required Q'REILLY,J P Region 2, Atlanta, Office of the Director 80/10/02
- 1010290066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Bupport Bolting " No specific action or response requested D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/10
- 010280478 Responds to infractions noted in IE Insp Repts 50-390/80-25 & 50-391/80-19 Corrective actions:procedure rewritten to include additions items required by IE Bullatins 79-01 & MILLS:L N Tennessee Valley Authority 80/10/21, 3pp
- 010280459 Provides revised response to Deficiency 390/80-19-01.per 800925 meeting w/NRC re 800911 response NDT examiner reinstructed in proper acceptance criteria for liquid penetrant insps Compliance achieved MILLS:L K Tennessee Valley Authority 80/10/23 2pp
- Reportable occurrences, LERs & related correspondence
- 009100414 First interim deficiency rept re incorrect valve weights in auxiliary feedwater piping Two types of water level control valves had discrepancy in valve weights compared to data used in piping analysis Util reamalyzing piping sys.
 MILLS,L M Tennessee Valley Authority 80/09/04 2pp
- O10080429 Third interim deficiency rept re breakdown in Dravo QA program Documentation re weld buildups to be reviewed & approved by authorized nuclear inspector All available radiographic film of shop welds reviewed & no defects found MILLO,L M Tennessee Valley Authority. 80/09/30 ip.
- 010090407 Final deficiency rept re lack of fusion & poor weld quality as refueling water storage tank overflow line not fabricated in accordance w/ASME Datalled review initiated & repairs scheduled for completion Nov 1980.

 MILLS,L H Tennessee Valley Authority 80/10/02 2pp.
- 010150368 Final deficiency rept re incorrect installation of nitrogen bottle bank supports Appropriate design drawings have been revised & all defective anchors have been replaced & tested Disciplinary action administered to responsible personnel MILLB.L K Tennassee Valley Authority 80/10/07 2pp.
- 010160529 Becond interim deficiency rept re possible inadvertent boron dilution while on residual heat removal sys Westinghouse final evaluation & recommendations will be completed by Jan 1981. Next rept will be forwarded by 810206. MILLS.L M Tennessee Valley Authority 80/10/08 ip
- Di0210489 Interim deficiency rapt re inadequate documentation for miscellaneous mechanical equipment. Applicable GC procedures being written &/or revised, specifying proper insp & documentation requirements.

 MILLE, L N Tennessee Valley Authority 80/10/10, ip

- BO10210365 Final deficiency rept re usage of improper matts in auxiliary board room air conditioning sys Improper copper tubing replaced witype K tubing OA program revised to include mandatory matt verification prior to installation MILLB.L K Tennessee Valley Authority BO/10/14 2pp
- B0102B0427 Final deficiency rapt re failure to use correct valve weights in piping analysis Caused by discrepancy between valve weights & input data used in piping analysis Auxiliary feedwater piping reanalysed Required mods will be made MILLS.L R Tennessee Valley Authority 80/10/22 2pp
- 8010280626 First interim deficiency rept re seismic qualification of remote control equipment installed in safety-related sys Equipment must be retasted due to upgrading of requirements since purchase Testing should be completed in Apr 1981 MILLS.L. K. Tennessee Valley Authority 80/10/22 2pp
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010080642 Notification of 80i014-17 meeting w/util at site to discuss seismic qualification review team audit
 KANE,W Licensing Branch 2 80/09/18 5pp
- 8010220068 Notification of 800926 meeting w/util in Bethesda MD to review Tech Spec problem areas KANE,W. Licensing Branch 2 80/09/15 4pp
- 8010220099 Forwards errets sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIECHHUT.D 0 Division of Licensing 80/09/19 28pp
- B010010655 Documents delivery of radwasts solidification systematruction manual (process control manual) to B Kane of NRG Raquested offsite dose calculation manual should be completed in early Oct 1980
 NICHQLS:T C South Carolina Electric & Gas Co 80/09/25 ip
- 8010020333 Forwards Supplemental I&C info, referenced in util response to Guestion 31 76 in FSAR Amend 21 for issuance on 801003 Info withheld (ref 10CFR2 790)
 NICHOLS, T C South Carolina Electric & Gas Co 80/09/23 ip
- 8010160243 Notification of 801008 meeting w/util in Bethesda.MD to review & resolve open items in Reactor Sys Branch review of GL application KANE.N. Licensing Branch 2 80/09/25, 2pp
- B010070120 Notification of 801001 meeting w/util to review Unit 1 DL application schedule
 KANE, W Operating Reactors Branch 2 80/09/29, 2pp.
- 8010140145 Notification of 801009 meeting w/util in Bethesda.MD to discuss geology/seismology matters KANE.W. Licensing Branch 2 80/09/29 3pp
- 8010060225 Forwards response to Questions 362 15-362,49,which will be resubmitted as Amend 22 to FSAR,re effects of pumphouse settlement & svc water intake structure,per NRC 800702 request
 NICHOLS, T. C Bouth Carolina Electric & Oas Co 80/07/30 ip
- --B010040230 Responses to Questions 362 15 through 362.49 re pumphouse settlement & svc water intake structure.Responses will be resubmitted as Amend 22 to FBAR 8 Bouth Carolina Electric & Gas Co B0/11/30, 103pp
- 8010140109 Summary of B00730 meeting w/util re seismology matters. KANE:W. Licensing Branch 2 80/10/01 3pp.
- 8010230008 Notification of 901006 & 07 meeting w/util & Sandia Labs to review NRC comments on applicant reliability evaluation of emergency feedwater sys
 KANE,W Licensing Branch 2. 90/10/01, 2pp.
- 8010230576 Notification of 801009 meeting w/util in Bethesda. MD to reveiw administrative procedures & associated Tech Specs. KANE.W F. Licensing Branch 2 80/10/03 2pp.
- 8010170198 Notification of 801015-17 meetings w/util in Jenkinsville, 8C to review const progress to recommend order of priorities for scheduling manpower assignments. Agenda encl KANE, W Standardization & Special Projects Branch. 80/10/06. App

- 8010270219 Notification that 801015-17 meeting w/util in Jenkinsville, SC has been cancelled KANE. WF Licensing Branch 2 80/10/06 ip
- BOIO140272 Bubmits info to suppl responses to 800923 ltr re post-accident monitoring questions NICHOLB,T C South Carolina Electric & Gas Co 80/10/07 2pp
- 8010160512 Forwards response to NRC seismology Question 361 17 re comparison of earthquake time histories spectra to facility design response spectra Response completed to issues discussed at 800730 meeting w/NRC in Bethesda,MD NICHOLB,T C South Carolina Electric & Gas Co 80/10/08 43pp
- 8010280127 Summary of 800723-24 mastings w/util in Jenkinsville.SC reselected emergency operating procedures

 KANF-W F Standardization & Special Projects Branch 80/10/07
- B010270036 Notification of B01022 meeting w/util in Bethesda.MD to discuss plans for resolving items developed from Human Factors Engineering Branch review of control room KANE.W Licensing Branch 2 B0/10/13 3pp
- B010280201 Summary of B00726 meeting w/util in Bethesda.ND re changes which applicant proposed to Tech Speca KANE.N F Standardization & Special Projects Branch 80/10/15
- 8010300594 Summary of 801008 marting w/util & SC Public Svc Authority re Reactor Sys Branch review of DL application KANE, H F Licensing Branch 2 80/10/17 App
- BO10310569 Requests documentation of compliance w/NRC regulations by BO1114 per discussions during 800910 meeting TEDESCO.R L Assistant Director for Licensing 80/10/27, Zpp
- F Security, medical, emergency & fire protection plans
- 80:0070257 Forwards Revision 1 to "Safe Shutdown Analysis for Fires in Control Room, Relay Room or Cable Spreading Rooms," in response to Guestion 1 of NRC 800201 fire protection svaluation
 NICHOLS: T C South Carolina Electric 8 Gas Co 80/10/02 2pp,
- --B010070260 Revision 1 to "Safe Shutdown Analysis for Fires in Control Room, Ralay Room or Cable Spreading Rooms" # South Carolina Electric & Gas Co B0/09/27 35pp
- 8010200401 Notification of 801006-07 meeting w/util in Jenkinsville,80 to review security plan commitments
 KANE,W Licensing Branch 2 80/10/03 3pp
- B010240008 Forwards request for add1 info re fire protection training program & definition of "area of secondary attention."
 TEDESCO,R L Assistant Director for Licensing B0/10/07 Spp
- B010160553 Forwards Revision 2 of radiation emergency plan,Addl info re emergency operations facility & public warning sys will be provided NICHOLS:TC Bouth Carolina Electric & Oas Co. B0/10/13 ip
- --8010160558 Revision 2 of radiation emergency plan. * Bouth Carolina Electric & Oas Co 80/10/13 124pp
- 8010240442 Forwards Page 78A to radiation emergency plan, Revision 2 NICHOLS, T C South Carolina Electric & Gas Co 80/10/20 ip.
- --8010240445 Page 78A to radiation emergency plan. Revision 2.
- Q. Adjudicatory correspondence
- 8010140535 Notice of appearance in proceeding Certificate of Byc encl. MAHAN, R R South Carolina Electric & Oas Go. 80/10/06 2pp.
- B010140596 Forwards RR Mahan notice of appearance in proceeding Certificate of Svc encl.
 MAHAN,R R South Carolina Electric & Gas Co. B0/10/06 3pp.
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8010070189 Forwards Amend 2: to facility FSAR. Affidavit showing compliance w/100FR2.101(a) encl
 NICHOLB.T C. South Carolina Electric & Gas Co 80/10/03. 2pp.

- --8010070192 Amend 21 to facility FBAR

 * South Carolina Electric & Qas Co BO/10/03 500pp
- 8010160503 Forwards corrected pages to Chapter 17 of FBAR Changes will be incorporated in next amend to FSAR NICHOLB: T C South Carolina Electric & Gas Co 80/10/13 3pp.
- 8010230401 Forwards update to Amend 21 to FBAR, thanging Figure 17 1-1 NICHOLS, T C South Carolina Electric % Gas Co 80/10/15 2pp

M Antitrust correspondence

- B010130640 Response to CLI-80-2B issued 800630, stating that Commission should modify proposed significant changes criteria to aliminate conflict w/legislative intent Significant changes criterion should be viewed separately W/Certificate of 8vc KAPLAN, D. A., FABRIKANT, R., URBAN, J. R. Justice, Dept of 80/10/10
- G Inspection reports. IE Bulletins & correspondence
- 8010230064 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Hatls." No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/29 is.
- 8010230103 Forwards IE Insp Rept 50-395/80-18 on 800601-0703 & notice of violation
 LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/05, 2pp.
- --B010230109 Notice of violation from insp on B00601-0703, * Region 2, Atlanta, Office of the Director B0/07/24, 1p.
- --8010230343 IE Insp Rept 80-375/80-18 on 800601-0703 Noncompliance noted misleading alarm label on diesel generator panel remote-local-maint switch & start-up manual is draft copy rather than official copy KELLU00,F J , SKOLDS,J L Region 2, Atlanta, Office of the Director 80/07/24 7pp
- 8010240246 Forwards IE Insp Rept 50-395/80-23 on 800811-14 No noncompliance noted LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/09/05 2pp
- --8010240249 IE Insp Rept 50-395/80-23 on 800811-14 No noncompliance noted Major areas inspected preoperational test review & result evaluation GUICK, D R , FORD, E J. Region 2, Atlanta, Office of the Director 80/09/05 3pp
- 8010270190 Forwards IE Insp Rept 50-395/80-22 on 800806-08 No noncompliance noted LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 80/07/11 2pg
- --8010270193 IE Insp Rept 50-395/80-22 on 800806-08 No noncompliance noted. Major areas inspected program & procedure review for thermal expansion & vibration testing of safety-related piping sys in conjunction w/hot functional testing. WHITENER:H L. Region 2, Atlanta, Office of the Director OUICK D R Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 80/09/11, 5pp
- 8010160205 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No written response required.

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30 to
- 8010270560 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. O'REILLY, J. P Region 2. Atlanta, Office of the Director 80/10/02, ip
- 8010230080 Notification of 801009 meeting w/util in Bethesda, MD to raview concerns w/preservice insp program KANE-M. Licensing Branch 2 80/10/09 2pp.
- 8010270198 Responds to NRC 800911 ltr re violations noted in IE Insp Rept 50-395/80-21 Corrective actions work hold placed on GC work while procedures were amplified & clarified. NICHOLS:T.C. Bouth Carolina Electric & Gas Go. 80/10/03 2pp.

- --8010270202 Forwards IE Insp Rept 30-395/80-21 on 800812-15 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --8010290205 IE Insp Rept 50-395/80-21 on 800812-13 No noncompliance noted Major areas inspected: licensee identified items, inspector identified items & fire barrier installation
 - inspector identified items & fire carrier installation procedures & frawings.
 MALTER,D K., HERRIUEATHER,N. Region 2, Atlanta, Office of the Director CONLON,T.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/10 7pp
- 8010290042 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/10. ip.
- 8010310555 Forwards staff position re inservice insp of pressure isolation values. Requests list of pressure isolation values included in testing program & details on leak testing program by 801107 TEDESCO.R.L Assistant Director for Licensing 80/10/27 Spp.
- R. Periodic operating reports & related correspondence
- 8010300677 Submits weekly status rept for wk ending 801010 KANE.W Standardization & Special Projects Branch 80/10/16 2pp
- 8. Reportable accurrences, LERs & related correspondence
- 8010010435 Supplementary Part 21 Rept 1 re PC-2 installation electrical schematics & instruction books. No other installations have potential for nearly continuous operation of rocker arm prelude pump HORIARTY, JM Colt Industries, Inc. 80/09/12 ig
- 8010140343 Part 21 rept re Beloit Power Bys generator losing field Caused by lead between collector rings & field coils shorting to rotor & burning in two pieces at point of short linsp of another generator showed frayed insulation. HORIARTY, J. M. Colt Industries, Inc. 80/09/22 2pp.
- B010200457 Final deficiency rept re Class i gipe not having four-way ultrasonic examination, originally discussed in B00730 ltr Gaussd by personnel error Fiping supplier will perform proper examination onsite
 NICHOLS.T G Bouth Caroline Electric & Gas Go. 80/10/09, Spp
- V Operator Examinations
- B01024000B Forwards request for add1 info re fire protection training program & definition of "area of secondary attention." TEDEBCO.R.L. Assistant Director for Licensing. 80/10/07. 3pp.
- DOCKET 50-397 WPPBB NUCLEAR PROJECT, UNIT 2

 1. Application/construction stage documents & correspondence
- B010090495 Summary of B00805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads. Discussion topics; attendance & meeting handouts and!. ANDERSON.C.J Generic Issues Branch. B0/08/29 78pp.
- 8010060102 Summary of 800704-03 meeting w/Mark II owners in Bethesda.MD re long-term program chugging & lateral loads. Attendance list & handouts encl.
 ANDERSON.C.J Generic Issues Branch. 80/09/12, 65pp.
- 8010020397 Bummary of 800805 meeting w/HPP88 in Chicago, IL re BRV discharge load, improved definition & application mathod. Improved BRV discharge load definition is conservative & confirmed by in-plant BRV discharge tests.

 ELTAHILA: F. Containment Systems Branch. 80/09/18. Spp.
- 8010010726 Forwards request for addl info re proposed corrective weld at const joint in sacrificial shield wall. Info re tengential shear in ring channel above & below 541 ft const joint may already have been provided.

 TEDESCU.R.L. Assistant Director for Licensing. 80/09/19. App.
- B010220099 Forwards errata sheets amending 800903 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D. 0. Division of Licensing. 80/09/19, 20pp.

- 8010080425 Requests add1 NRC branch reviews required on util safety relief valve rept Potential need exists for review of refinements to generic Mark II condensation oscillation load or alternative load definition & methodology RENBERGER, D L Washington Public Power Supply System 80/10/01
- 8010090494 Forwards responses to Structural Engineering Branch Round 2. Set 1 questions re sacrificial shield wall RENBERGER.D.L. Washington Public Power Supply System. 80/10/03 22pp
- C Utility Environmental Report (ER), amends & correspondence
- BO10210379 Forwards Amend 4 to environ rept Amend supple ecological baseline data & updates description of environ monitoring programs.
 RENOEROER, D. L. Washington Public Power Supply System BO/10/07.
- --8010210383 Amend 4 to environ rept,

 * Washington Public Power Supply System 80/10/07 111pp.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010170120 Forwards Amend 11 to FSAR Affidavit will be provided within 10 days RENBERGER, D.L. Washington Public Power Supply System. 80/10/08. 2pp
- --B010170122 Amend ii to FSAR,
 # Washington Public Power Supply System. B0/09/30. B00pp.
- B010280510 Forwards 801022 transmittal 1tr & Certificate of Syc re Amend 11 to FSAR RENBERGER, D L. Weshington Public Power Supply System, 80/10/22, 3pp.
- A Inspection reports, IE Bulletins & correspondence
- 8010150027 Forwards IE Investigation Rept 50-397/80-02 on 791127-30, 1205-07 & 12-14,800109-11,22-25,29-0201,11-14 & 25-28, ENGELKEN,R H Region 5, San Francisco, Office of the Director. 80/06/17, 2pp.
- --B010150031 IE Investigation Rept 50-397/80-04 on 791127-30,1205-07 & 12-14.800109-11.22-25,29-0201.11-14 & 25-28 Noncompliance noted shield wall not eracted in accordance w/design requirements & failure to meintain instrument tubing. HAVNES,R C Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. BISHOPT W., HAIST,D P Region 5, San Francisco, Office of the Director. 80/04/02 27pp.
- 8010280610 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1351 & 1152 Pressure Transmitters W/Either A or D Output Codes " Transmitters will be converted to E output code models.
 RENGER
- 8010170361 Forwards IE Insp Rept 80-397/80-13 on 800811-14.No noncompliance noted, CREMB.U.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/08. 2pp.
- --8010170363 IE Insp Rept 50-397/80-13 on 800811-14. No noncompliance noted Major areas inspected operational QA program Implementation for preoperational testing flushing program & results of control red hydraulic sus flush.

 CARLSON. J D., WILLETT, D. J. Region 5, San Francisco, Office of the Director. STERNBERG) D. M. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 80/09/03. 4pp.
- 8010080576 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME 8A-012: Type 304 Stainless Steel Pips." Initial response of 800805 indicated review due by 800915 Due to delay in obtaining info, review will be completed 801103. RENBERGER, D. L. Washington Public Power Supply System. 80/09/09 ip.
- 8010290411 Forwards IE Circular 80-R1, "Regulation of Refueling Craus "
 No written response required.
 EK/GELKEN.R.H Region 5, San Francisco, Office of the Director.
 80/09/10, ip.
- B010310307 Forwards IE Insp Rept 50-397/80-10 on B00701-31. No noncompliance noted. BPENCER, G.S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. B0/09/12. 2pp.

- --8010310314 IE Insp Rept 50-397/80-10 on 800701-31 No noncompliance noted Major areas inspected pipe hanger design & matls.labor union training of GC inspectors & maint of installed equipment during labor dispute TOTELA D : MAIST.D Region 5. San Francisco, Office of the Director MAYNES,R C Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/09/10 3pp
- 8010080639 Responds to IE Builetin 79-15, "Deep Draft Pump Beficiencies " Initial response of 790918 indicated action would be taken, Responses received from suppliers indicate no operational problems experienced w/safety-related pumps RENBERGER, D. L. Washington Public Power Supply System 80/09/15
- 80100B0644 Responds to 1E Bulletin 90-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches." Facility does not use Westinghouse Type W-2 control switches in any safety sys design RENBERGER, D. L. Washington Public Power Supply System 80/09/15-16
- B0102202R7 Ack receipt of B00711,17 to OB12 ltrs informing NRC of steps taken to correct items of noncompliance in notice of violation. Info re plan & schedule for reviews of safety-related work has been reviewed & found acceptable.

 BTELLD, V Office of Inspection & Enforcement, Office of the Director. B0/09/17 Rpp
- 9010230079 Forwards IE Insp Rept 50-397/80-14 on 800825-28. No noncompliance noted SPENCER, 0.8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/09/18 2pp
- --B010230084 IE Insp Rept 50-397/80-14 on B00825-28. No noncompliance noted Hajor areas inspected preparations for regair of deficiencies in sacrificial shield wail & licensue allegations against prime electrical contractor HAYNES,R.C. Region 5, Ban Francisco, Resctor Construction & Englineering Support Branch HAIST,D.P. WANNER,W J. Region 5, Ban Francisco, Office of the Director B0/09/17 Bpp.
- 8010280039 Forwards IE Insp Rept 50-397/80-15 on 800801-31. No noncompliance noted SPENCER.0 S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 80/09/26 2pp
- ---8010280041 IE Insp Rept 80-397/80-15 on 800801-31 No noncompliance noted Major areas inspected licensee & contractor activities to re-evaluate & improve detailed work methods TOTH.A D. Region 5. Ban Francisco. Office of the Director HAYNES.R.C. Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch. 80/09/26. 9pp.
- 80:0160069 Ferwards Suppl 2 to IE Bulletin 79-018, "Environ dualification of Class IE Equipment," No written response required.
 ENGELKEN, R H Region 5, San Francisco, Office of the Director.
 80/09/29 ip.
- 8010280027 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required. ENGELKEN, R H Region S, San Francisco, Office of the Director. 80/10/02. ip
- 8010310049 Ack receipt of 800919 ltr informing NRC of steps taken to correct violetions noted in IE Insp Rept 50-397/80-08 BRENCER.0 8 Region 5, 8an Francisco, Reactor Construction & Engineering Support Branch. 80/10/24.
- --B010310050 Responds to NRC B00B15 ltr re violations noted in IE Insp Rept 50-397/80-08 Corrective actions:memo issued to clearly establish k reaffirm OA/GC independence from const. REMBERGER.D.L Heshington Public Power Supply System. B0/09/19.
- 8 Reportable occurrences, LERs & related correspondence
- B0102B04B6 Final deficiency rept re installation of missile producing equipment in Class IE erea. Protective barriers have been dasigned to prevent motor generator set flywheal failure from damaging adjacent Class IE equipment. RENBERGER, D. L. Washington Public Power Supply System. 80/10/21.

- DOCKET 50-400 SHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D.O. Division of Licensing 80/09/19 28pp
- 8010310393 Forwards "Shearon Harris Nuclear Power Plant, Nain Dam Spillumy Faults Ji & J2 " MCDUFFIE M A. Carolina Power & Light Co 80/10/27. 1p
- --8010310397 "Shearon Harris Nuclear Power Plant, Main Dam Spillway Faults J1 & J2 " + Carolina Power & Light Co. 80/10/27. 12pp
- @ Inspection reports, IE Bulletins & correspondence
- 8010200632 Forwards IE Info Notice 80-32, "Clarification of Gertain Requirements of Exclusive Use Bhipments of Radioactive Matla " G'REILLY, J. P Region 2. Atlanta, Office of the Director. 80/08/27 is.
- B010140035 Ack receipt of IE Insp Repts 50-400/80-19.50-401/80-17.50-402/80-17 & 50-403/80-17 on 80630-0703 & 0714-18 No progrietary info.

 HOWE, P. M. Carolina Power & Light Co. 80/09/15. 1p
- --8010140045 Forwards IE Insp Repts 80-400/80-19, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 800530-0703 & 0714-18.No noncompliance noted. MURHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/04. 2pp
- ---8010140053 IE Insp Repts 50-400/80-17, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompliance noted Major areas inspected safety-related concrete & soils work CONLON.T.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/07/03. App.
- 80:01:50:288 Submits add1 response to IE Bulletin 80-19 re use of mercury-wetted matrix relays Specified concerns do not apply as only application of relays in trip circuitry is in 7300 Process Control Sys & not used in scraw circuits.

 MCDUFFIE.M A. Garoline Power & Light Co. 80/09/17. 1p
- 8010080215 Ack receipt of IE Insp Repts 50-400/80-21,50-401/80-19, 50-402/80-19 & 50-403/80-19 on 800818-29. No proprietary info HOME, P W Carolina Power & Light Co 80/09/22. 1p
- --8010080221 Forwards IE Insp Repts 50-400/80-21:50-401/80-19: 50-402/80-19 & 50-403/80-19:on 800818-29. No noncompliance noted. MURPHY.G.E. Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/09/12. 2pp.
- --8010080226 IE Insp Repts 50-400/80-21,50-401/80-19,50-402/80-19 & 50-403/80-19, on 800818-29 No noncompliance noted Major areas inspected: handling & storage, soil compaction & testing & fire pravention & protection Maxwelling F. Region 2, Atlanta, Office of the Director. BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/12. 4pp.
- 8010140112 Forwards corrected summary page of IE Imap Repts 50~400/80-18.50-401/80-16.80-402/80-16 & 80-403/80-16 issued on 800826. MURPHY, C. E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/25. 2pp.
- --8010140121 Corrected summary page of IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 k 50-403/80-16, issued on 800826 ECONOMOSIN. Region 2. Atlanta: Office of the Director. HERDT.A R. Region 2. Atlanta: Reactor Construction & Engineering Support Branch. 80/09/24. 1p.
- ---8010140131 Responds to NRC 800826 ltr re violations noted in IE Insp. Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16. No proprietary info. HOKE, P.W. Carolina Power & Light Co. 80/09/03. ip.

- --8010140139 Forwards IE Insp Rapts 50-400/80-18.50-401/80-16.
 50-402/80-16 & 50-403/80-16 on 800707-11 & notice of violation
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/24 2pp
- --8010140144 Notice of violation from insp on 800707-11
 Region 2, Atlanta, Office of the Director 80/08/12 2pp
- --8010140155 IE insp Repts 50-400/80-18.50-401/80-16.50-402/80-16 & 50-403/80-16 on 800707-11 Noncompliance noted failure to follow procedures re housekeeping & document control & weld matl control ECONOMOS.N Region 2. Atlanta. Office of the Director HERDT.A Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/12 ipp
- 8010160298 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BD/09/30 1p.
- 8010270537 Forwards TE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02 to
- B010270058 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/10/10 to
- 8010310327 Ack receipt of 800919 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-18, 30-401/80-16, 50-402/80-16 & 50-403/80-16 MURPAYV.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/20 [p
- ---8010310341 Responds to NRC 800826 ltr re violations noted in IE Insp Repts 50-400/80-16,30-401/80-16,50-402/80-16 & 50-403/80-16 Corrective actions areas of housekeeping have been assigned to supervision. HONE,P W Carolina Power & Light Co 80/09/19. Spp
- R Periodic operating reports & related correspondence
- 9010270400 Forwards "Guarterly Data Rept Shearon Harris Nuclear Power Plant Seismic Monitoring Program. Jul-Bept 1980 " HCDUFFIE:M A Carolina Power & Light Co 80/10/22 1p.
- 1. Reportable occurrences, LERs & related correspondence
- Oi0080444 PNO-II-80-ii2 on 8006i8, util announced delay in scheduled commercial operating dates for plants by add1 i-3 yrs Reasons given were need to reduce capital expenditures & reduced area growth rate HUNT.M . RAUSCH.J.K Region 2. Atlanta. Office of the Director, 80/06/19 ip
- 8010230185 Part 21 rept re flexing of Unit 1 containment dome due to imposition of uneven loads during movement for final placement Evaluation re reportability per IOCFR50 55s not completed, Evaluation to be completed by 80115 CHIANGI,N J Caroline Power & Light Co. 80/09/23, 2pp
- DOCKET 50-401 SKEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 its which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D Q. Division of Licensing. 80/09/19, 28pp
- 8010310393 Forwards "Shearon Harris Nuclear Power Plant, Main Dam Spillway Faults J1 & J2 " MCDUFFIE, N A Carolina Power & Light Co. 80/10/27. ip.
- --8010310397 "Shearon Herris Nuclear Power Plant, Main Dam Spillway Faults U! & J2." * Caroline Power & Light Co 80/10/27 12pp.

- Q Inspection reports, IE Bullstins & correspondence
- 8010200632 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls" O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29
- 8010140035 Ack receipt of IE Insp Repts 50-400/80-19, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 80630-0703 & 0714-18 No proprietary info HOME, P W Carolina Power & Light Co 80/09/15 in
- --8010140045 Forwards IE Insp Repts 50-400/80-19, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No moncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 2pp
- --8010140053 IE Insp Repts 50-400/80-17,50-401/80-17,50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompliance noted Major areas inspected safety-related concrete & soils work CONLON,T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/03 4pp
- 8010190288 Submits addl response to IE Bulletin 80-19 re use of mercury-wetted matrix relays Specified concerns do not apply as only application of relays in trip circuitry is in 7300 Process Control 8ys & not used in scram circuits MCDUFFIE:M A Carolina Power & Light Co 80/09/17 1p
- 8010080215 Ack receipt of IE Insp Repts 50-400/80-21, 50-401/80-19, 50-402/80-19 & 50-403/80-19 on 800818-29, No proprietary info HOME.P W Carolina Power & Light Co 80/09/22 ip
- --801008022; Forwards IE Insp Repts 50-400/80-21,50-401/80-19, 50-402/80-19 & 50-403/80-19, on 800818-29 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 Zpp
- --8010080226 IE Insp Repts 50-400/80-21, 50-401/80-17, 50-402/80-17 & 50-403/80-19, on 800818-27 No noncompliance noted Major areas inspected handling & storage, soil compaction & testing & fire prevention & protection MAXHELL, 0 F Region 2, Atlanta, Office of the Director, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/12 4pp
- 8010140112 Forwards corrected summery page of IE Insp Repts 50-400/80-18.50-401/80-16.50-402/80-16 & 50-403/80-16 issued on 800826 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/25 2pp
- --8010140121 Corrected summary page of IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16, issued on 800826 ECONOMOS.N Region 2, Atlanta, Office of the Director HERDY, A Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/24 ip
- --8010140131 Responds to NRC 800826 ltr re violations noted in IE Insp Repts 50-400/80-16,50-401/80-16,50-402/80-16 & 50-403/80-16 No proprietary info. HUME.P.W. Carolina Power & Light Co. 80/09/03 ip
- --8010140139 Forwards IE Insp Repts 50-400/80-18,50-401/80-16, 50-402/80-16 & 50-403/80-16 on 800707-11 & notice of vicilation, MURPHY,C E Region 2, Atlants, Reactor Construction & Engineering Support Branch 80/08/26 2pp
- --B0i0i40i44 Notice of violation from insp on 800707-11 * Region 2, Atlanta, Office of the Director 80/08/12 2pp
- --8010140155 IE Insp Repts 50-400/80-18,50-401/80-15,50-402/80-16 & 50-403/80-16 on 800707-11. Noncompliance noted failure to follow procedures re housekeeping & document control & weld matcl control.

 ECONOMOS.N. Region 2. Atlanta, Office of the Director, HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/08/12 1pp
- 8010160278 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " No written response required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/09/30, ip

- 80:10270537 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 to
- 8010270098 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/10 ip
- 8010310329 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16 MMRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/20 ip
- --8010310341 Responds to NRC 800826 ltr re violations noted in IE Insp Repts 50-400/80-18,50-401/80-16,50-402/80-16 & 50-403/80-16 Corrective actions areas of housekeeping have been assigned to supervision HOME,P II Carolina Power & Light Co 80/09/19 5pp
- R Periodic operating reports & related correspondence
- BO10270400 Forwards "Quarterly Data Rept Shearon Harris Nuclear Fower Flant Saismic Monitoring Program, Jul-Sept 1980 " MCDUFFIE:M A Carolina Power & Light Co B0/10/22 ip
- --8010270402 "Quarterly Data Rept.Shearon Harris Nuclear Power Plant Beismic Monitoring Program Jul-Bapt 1980 " 4 Carolina Power & Light Co 80/10/22 Ip
- B Reportable occurrences, LERs & related correspondence
- 80:0080446 PNO-11-80-i12 on 800618.ut;1 announced delay in scheduled commercial operating dates for plants by addl 1-3 yrs
 Reasons given were need to reduce capital expenditures
 4. reduced area growth rate
 RWNT.M. RAUSCH.J K. Region 2. Atlanta. Office of the Director
 80/06/19 1p
- B010230185 Part 21 rept re flexing of Unit 1 containment dome due to imposition of uneven loads during movement for final placement Evaluation re reportability per 10CFR50.55e not completed Evaluation to be completed by 801115.

 CHIANGIN J Carolina Power & Light Co 80/09/20 2pp
- BOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMT action plan requirements Corrected table of implementation schedule also encl EISENHUT, D G Division of Licensing 80/09/19. 28pp
- 8010310393 Forwards "Sheaton Harris Nuclear Power Plant Main Dam Spillway Faults Ji & J2 " MCDUFFIE.N A Carolina Power & Light Co 80/10/27. 1p
- --8010310397 "Bhearon Harris Nuclear Power Plant, Main Dam Spillway Faults J1 & J2 " + Carolina Power & Light Co 80/10/27 12pp.
- G. Inspection reports, IE Bulletins & correspondence
- B010200632 Forwards IE Info Notice B0-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls"

 O'REILLY.J P Region 2. Atlanta, Office of the Director B0/08/29
- 8010140035 Ack receipt of IE Insp Repts 50-400/80-19,50-401/80-17, 50-402/80-17 & 50-403/80-17 on 80630-0703 & 0714-18. No proprietary info.

 HOWE, P W Carolina Power & Light Co. 80/09/15 ip
- --8010140045 Forwards IE Insp Repts 50-400/80-19,50-401/80-17, 50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompliance noted KWRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/09/04. 2pp.

- ~-8010140053 IE Insp Repts 50-400/80-17,50~401/80-17,50~402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompliance noted Major areas inspected safety-related concrete & soils work CONLON-TE Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/09/03 4pp
- 8010150288 Submits add) response to IE Bulletin 80-19 re use of mercury-wetted matrix relays Specified concerns do not apply as only application of relays in trip circuitry is in 7300 Process Control Sys & not used in scraw circuits.

 MCDUFFIE.H A Carolina Power & Light Co 80/09/17 ip
- 8010080215 Ack receipt of IE Insp Repts 50-400/80-21, 50-401/80-19, 50-402/80-19 % 50-403/80-19 on 800818-29 No proprietary info MOME, P N Carolina Power & Light Ca 80/09/22 ip
- --8010080221 Forwards IE Insp Repts 50-400/80-21.50-401/80-19, 50-402/80-19 & 50-403/80-19, on 800818-29 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/09/12 2pp
- --8010080226 IE Insp Repts 50-400/80-21,50-401/80-19,50-402/80-19 & 50-403/80-19, on 800818-29 No noncompliance noted Major areas inspected handling & storage, soil compaction & testing & fire prevention & protection MaxWELL,0 F Region 2, Atlanta. Office of the Director BRYANT,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 App
- 8010140112 Forwards corrected summary page of IE Insp Repts 50-400/80-16, 50-401/80-16, 50-402/80-14 \$ 50-403/80-16 issued on 800826 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/25 2pp
- --B010140121 Corrected summary page of IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16, issued on 800826 ECONOMOS, N. Region 2, Atlanta, Office of the Director HCRDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/24, 1p
- --8010140131 Responds to NRC 800826 ltr re violations nated in IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16 No proprietary info HOME: P (/ Carolina Power & Light Co 80/09/03 ip
- --8010140137 Forwards IE Insp Repts 50-400/80-18,50-401/80-16, 30-402/80-16 & 50-403/80-16 on 800707-11 & notice of violation WARPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/26 2pp
- --8010140144 Notice of violation from insp on 800707-11
 * Region 2. Atlanta, Office of the Director BO/OB/12, 2pp
- --8010140196 IE Insp Repts 50-400/80-18.50-401/80-16.50-402/80-16 & 50-403/80-16 on 800707-11 Noncompitance noted failure to follow procedures re housekeeping & document control & weld math control ECONDIOS, N Region 2. Atlanta. Office of the Director. HERDI.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/12 1pp.
- B010160298 Forwards Suppl 2 to TE Bulletin 79-018, "Environ Qualification of Class TE Equipment" No written response required,
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30
- 80:0270537 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/02 ip.
- 8010270058 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/10 ip
- 8010310329 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16 MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/10/20 1p.

- --8010310341 Responds to NRC 800826 itr re violations noted in IE Insp Repts 50-400/80-18,50-401/80-16,50-402/80-16 & 50-403/80-16 Corrective actions areas of housekeeping have been assigned to supervision HQUE,P W Carolina Power & Light Co. 80/09/19 Spp
- R. Periodic operating reports & related correspondence
- B010270400 Forwards "Quarterly Data Rept Shearon Harris Nuclear Power Plant Seismic Monitoring Program, Jul-Sept 1980 " KCDUFFIE,M A Carolina Power & Light Co 80/10/22 ip
- --B010270402 "Quarterly Data Rept. Shearon Harris Nuclear Power Plant Seismic Monitoring Program, Jul-Sept 1980 " * Carolina Power & Light Co 80/10/22 ip
- S Reportable occurrences, LERs & related correspondence
- 80:10080446 PND-11-80-112 on 800618.util announced delay in scheduled commercial operating dates for plants by add1 1-3 yrs
 Reasons given uere need to reduce capital expenditures
 t reduced area growth rate
 HUN), M Region 2. Atlanta, Office of the Director 80/06/19. 1p
- 8010230185 Part 21 rept re flexing of Unit 1 containment dome due to imposition of uneven loads during movement for final placement Evaluation re reportability per 10CFR50 55s not completed. Evaluation to be completed by 801115 CHIANGIN J Carolina Power & Light Co 80/09/23 2pp
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POHER PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of IMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D G Division of Licensing 80/09/19 28pp
- 8010310393 Forwards "Shearon Harris Nuclear Power Plant, Main Dam Spillway Faults J1 & J2 " MCDUFFIE,M A Carolina Power & Light Co 80/10/27 ip
- --8010310397 "Shearon Harris Nuclear Power Plant, Main Dam Spillway Faults J1 & J2" * Carolina Power & Light Co 80/10/27 12pp
- G Inspection reports. IE Bulletins & correspondence
- 8010200632 Forwards IE Info Notice 80-22. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls "
 - O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 tp
- 8010140035 Ack receipt of IE lnsp Repts 50-400/80-17, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 80630-0703 & 0714-18 No proprietery info HQWs,P W Carolina Power & Light Co 80/07/15 ip
- think it was a contribution of a contribution of
- --8010140045 Forwards IE Insp Repts 50-400/80-19, 50-401/80-17, 50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompliance noted MNRPHY, C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/04 2pp
- --8010140053 IE Insp Repts 50-400/80-19,50-401/80-17,50-402/80-17 & 50-403/80-17 on 800630-0703 & 0714-18 No noncompilance noted Major areas inspected safety-related concrete & soils work CONLON.T.E Region 2 Atlanta, Reactor Construction & Engineering Support Branch 80/09/03 4pp.
- 010150288 Submits add1 response to IE Bulletin 80-19 re use of mercury-wetted matrix relays Specified concerns do not apply as only application of relays in trip circuitry is in 7300 Process Control Sys & not used in scram circuits MCDUFFIE.H A Caralina Power & Light Co 80/09/17 ip
- 3010080215 Ack receipt of IE Insp Repts 50-400/80-21, 50-401/80-19, 50-402/80-19 & 50-403/80-19 on 800818-29 No proprietary Info HOUSE, P N Carolina Power & Light Co. 80/09/22, 1p,

- --8010080221 Forwards IE Insp Repts 50-400/80-21.50-401/80-19, 50-402/80-19 & 50-403/80-19, on 800818-29 No noncompliance nated MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/12 2pp
- ---8010080226 IE Insp Repts 50-400/80-21.50-401/80-19.50-402/80-19 & 50-403/80-19.on 800818-29 No noncompliance noted Major areas inspected handling & storage.toil compaction & testing & fire prevention & protection MAKKELL.OF Region 2. Atlanta, Office of the Director 80/09/12 4pp
- 8010140112 Forwards corrected summary page of IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16 issued on 800826 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/25 2pp
- --8010140121 Corrected summary page of IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16, issued on 800826 ECONDK05,N Region 2, Atlanta, Office of the Director 80/09/24
- --8010140131 Responds to NRC 800826 ltr re violations noted in IE lnsp Repts 50-400/80-18,50-401/80-16,50-402/80-16 & 50-403/80-16 No proprietary info HOME,P.W. Carolina Power & Light Co. 80/07/03 ip
- --8010140137 Forwards IE Insp Repts 50-400/80-18,50-401/80-16, 50-402/80-16 & 80-403/80-16 on 800707-11 & notice of violation MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/26 2pp
- ---8010140144 Notice of violation from inap on 800707-11 * Region 2, Atlanta, Office of the Director 80/08/12 2pp
- --8010140196 IE Insp Repts 50-400/80-18.50-401/80-16.50-402/80-16 & 30-403/80-16 on 800707-11 Noncompliance noted failure to follow procedures re housekeeping 5 document control & weld matl control COMMOS,N Region 2. Atlanta, Office of the Director 80/08/12 lps
- BO10160298 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/09/30
- B010270537 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/10/02.
- 801027005B Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/10/10, io
- B010310329 Ack receipt of B00919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16, MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/10/20 is
- --8010310341 Responds to NRC 800826 ltr re violations noted in IE Insp Repts 50-400/80-18, 50-401/80-16, 50-402/80-16 & 50-403/80-16 Corrective actions areas of housekeeping have been assigned to supervision HONE.P N Carolina Power & Light Co 80/09/19, 5pp
- R Periodic operating reports & related correspondence
- 8010270400 Forwards "Guarterly Data Rept Shearon Harris Nuclear Power Plant Seismic Monitoring Program.Jul-Sept 1980 " MCDUFFIE.M A Garolina Power & Light Co 80/10/22 1p

- S Reportable occurrences, LERs & related correspondence
- 8010080446 PNO-II-BO-112 on 800618, util announced delay in scheduled cornercial operating dates for plants by add1 1-3 yrs
 Reasons given were need to reduce capital expenditures
 & reduced area growth rate
 HUNF.II Region 2. Atlanta, Office or the Director 80/06/19 ip
- 8010230185 Part 21 rept re flexing of Unit 1 containment dome due to imposition of uneven loads during movement for final placement Evaluation re reportability per 100FR30 55e net completed Evaluation to be completed by 801115 CHIANGI,N J Carolina Power & Light Co 80/09/23 2pp
- DOCKET 50-404 NORTH ANNA POHER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8010100252 Requests Units 3 % 4 settlement time records from 1980 to FSAR subnittal date
 YOUNGBLOOD, B J Licensing Branch 1 80/09/29 2pp
- P Operating license stage documents & correspondence
- 8010010678 Forwards "Evaluation & Critique of NUREO/CR-1580 "
 Document does not reflect importance in quality or
 applicability to nuclear power station control rooms
 8VLVIA.3 R Virginia Electric & Power Co 80/09/26 ip
- --8010010688 "Evaluation & Critique of NUREO/CR-1980"

 # Viroinia Electric & Power Co 80/09/30 100pp
- **G** Inspection reports, If Bulletins & correspondence
- 8010230090 Forwards IC Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipmonts of Radioactive Matls "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 2ps
- 8010160293 Forwards Suppl 2 to IF Bulletin 79-018, "Environ Qualification of Class IE Equipment' No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/30 to
- 8010270555 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/10/02 ip
- 8010270060 Forwards IF Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/10/10 tp
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

 A Application/construction stage documents & correspondence
- 6010100252 Requests Units 3 % 4 settlement time records from 1980 to FB4R submittal date
 YOUN08L00D,B J Licensing Branch 1 80/09/29 2pp
- P Operating license stage documents & correspondence
- 80100(06/8 Forwards "Evaluation & Critique of NUREO/CR-1580." Document does not reflect importance in quality or applicability to nuclear power station control rooms BYLVIA.8 R Virginia Electric & Power Co 80/09/26 ip
- --8010010688 "Evaluation & Critique of NUREG/CR-1580"

 * Virginia Electric & Power Co 80/09/30 100pg
- Q Inspection reports, IF Bulletins & correspondence
- 8010230090 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matis" No written response required 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 20s

- 8010160293 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No written response required O'REILLY.JP Region 2, Atlanta, Office of the Director 80/09/3 ip
- 8010270555 Forwards IS Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02 in
- 8010270050 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/10/10
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

 F. Security, medical, emergency & fire protection plans
- 8010300517 Advises that revisions to LACBUR security plan are to be resubmitted per encl comments Final implementation schedule requested w/revisions in 30 days Encl withheld (ref 100FR2 790)
 CRUFCHFIELD, D Operating Reactors Branch 5 80/09/25 3pp
- O Adjudicatory correspondence
- 8010020656 Forwards order requiring submittal of info to support anyiron qualification of safety-related electrical equipment CRUICHFIELD, D. Operating Reactors Branch S. 80/08/29 2pp
- --8010020730 Order for mod of license to require timely submission of info previously requested re environ qualification of safety-telated electrical equipment EISENHUT.D 0 Division of Licensing 80/08/29 App.
- 8010230591 Informs of membership of ASLAB for facility show-cause proceeding ROSENTHAL:A S Atomic Safety and Licensing Appeal Panel SECY-A-80-142 80/07/22 1p
- 8010010696 Order granting Coulee Region Energy Coelition 800915 supported request for postponement of schedule until completion of order to show cause proceeding Deferral does not extend beyond issuance of initial decision BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/09/29
- 8010030470 Notice of hearing re NRC 800225 order to show cause on site dewatering sys ASLB consists of C Bechhoefer as chairman & QC Anderson & RS Decker members who will hold prehearing conferences to resolve controversy

 BECHHOEFER, C Atomic Safety and Licensing Board Panel 80/09/30
- 8010030517 Order re 800911 prehearing conference granting FM Oisen & Coulee Region Energy Coalition hearing requests re NRC 800225 order to show cause on liquefaction issue Certifies safe shutdown earthquate question to ASLAB BECHMEFER.C Atomic Safety and Licensing Board Panel. 80/09/30
- 8010030131 Order accepting certified question per ASLB 800930 prehearing conference order re ASLB authority to consider magnitude of safe shutdown earthquake Memoranda must be Filed by 801024 HAOINS. E Atomic Safety and Licensing Appeal Panel 80/10/01.
- 8010030514 Interrogatories directed to FM Olsen & Coulse Region Energy Coalition from which responses are required by 801020 Requests identification of witnesses re liquefaction issue W/Certificate of Svc Related correspondence. HIESTAND.0 8. GALLEN.K.P., OLAZER.B.A. Dairyland Power Cooperative 80/10/02 5pp
- 8010060018 Interrogatories directed to FM Olsen & Coules Region Energy Coalition to be answered by 801020 Requests identification of NRC 800829 safety evaluation statements w/which disagreement is made Certificate of Svc encl BURNS, S G Rulemaking & Enforcement Division, 80/10/02 4pp
- B010106054 First round interrogatories requesting info on seismic probability studies, Jul 1980 earthquake, Army Corps of Engineers MEB study & identity of NRC personnel instrumental in decision to restrain from request for dewatering sys. MORSE, A K Coulse Region Energy Coalition B0/10/02. 4pp.

- ---8010100056 First round interrogatories re soil liquefaction, consultant studies, SBE.pile driving & vater tables
 QUSEN.F M Affiliation Unknown 80/10/02 4pp
- B010070482 Ack receipt of ASLB B00929 order postponing full term DL schedule until completion of show cause proceeding obligations Inquires whether postponement applies to motions for discovery & summary disposition WOODHEAD, C P Hearing Branch I 89/10/96 1p
- BO1024005B Order granting addl wk for Coulee Region Energy Coalition to file discovery Answers to same must be filed by BO1112 & replies to summary disposition motions by B01201 Util & NRC must advise ASLB if filing of summary disposition is welved BECHHOEFER, C Atomic Safety and Licensing Board Panel B0/10/20
- 8010240046 Order granting extension until 801107 for Commission to elect whether to review ALAB-614 CHILK.S J. Office of the Secretary of the Commission 80/10/22
- 8010280598 Brief concluding that ASLAU is empowered to consider seismic issues re-site dewatering sys Absent such authority, lasue must be certified to Commission for permission to expand ASLAB power BURNS, S O , CYR, K D Rulemaking & Enforcement Division 80/10/24
- --8010280605 Cartifies syr of NRC brief on certified question on 801024 BURNS: 8 Rulemaking & Enforcement Division. 80/10/24 2pp
- B010290097 Response in opposition to certified question accepted by ASLAB on 801001 re magnitude of SSE ABLB inquiry must be restricted to order to show cause & Commission 800729 order Certificate of Svc enc!
 HIEBTAND.O S OALLEN,K P Dairyland Power Cooperative
 HIESTAND,O S Morgan, Lewis & Bockius 80/10/24 10pp
- 8010300044 Response opposing certain Coulee Region Energy Coalition & FM Olsen 801002 interrogatories Intervenors will be permitted to inspect & copy all repts & ltrs re liquefaction potential Waffidavite & Certificate of Svc HIESTAND, O S , OALLEN, K P Dairyland Power Cooperative HEISTAND, O S Horgan, Lewis & Bockius 80/10/27 14pp

- 010020501 Advises that E Gabelko can be removed from evt list for LACBWR Coulee Region Energy Coalition is doing an excellent Job on plant BABELKO.E Society Against Nuclear Energy 80/08/29 ip
 - Operating license stace documents & correspondence
- Oi0100277 Submits interim rept on problems in startup operations All testing equipment for OA Lovel 1 equipment sent for calibr Use of lab will be resumed when written procedures are implemented FAHRNER, N. J. Dairyland Power Cooperative 80/08/04 2pp
- 3010010773 Forwards REP evaluation of unsite emergency power sys diesel generator as input to integrated safety assessment Evaluation compares as-built facility design against NRC CRUTCHFIELD, D Operating Reactors Branch S 80/08/20
- --8010100144 "Onsite Emergency Power Sys Diesel Generator," BEP technical evaluation. Topic VIII-2 for LACBWR + Operating Reactors Branch 5 80/08/20 iipp
- 8010070548 Forwards Revision 1 to QA program Class II amend fee encl LINDER:F Dairyland Power Cooperative 80/08/28. 2pp.
- --B010070553 Revision 1 to QA Program
 LINDER, F Dairyland Power Cooperative 80/08/28. 45pp
- 801006005: Forwards safety evaluation re liquefaction potential at site per util 800225 response to order to show cause Detailed site dewatering proposal not required Plant should not be shut down DENIONAR Office of Nuclear Reactor Regulation, Director 80/08/29 2pp
- 80:0140223 Application for amend to License DPR-45 changing Tech Space 3 0,4,0 & 6 0 to clarify definition of "operable" as it applies to single-failure criterion for safety sys & adding requirements re Lessons Learned Category A items Fee encl LINOER, F. Dairyland Power Cooperative 80/09/12 App.

- --8010140229 Proposed changes to Tech Specs 3 0.4 0 & 6 0 to clarify definition of "operable" as it applies to single-failure criterion for safety sys & adding requirements re Lessons Learned Catagory A Items

 * Dairyland Power Cooperative 80/09/12 37pp
- 8010210594 Forwards response to NRC 780515 request re plant mod for ATMS per NUREG-0460, "ATMS for LWRs" Tech Specs changes encl No fee necessary LINDER,F Dairyland Power Cooperative 80/09/12 10pp
- --8010210598 Tech Specs 4 2 re nuclear instrument power range, safety channels & waste disposal during ATKS + Dairyland Power Cooperative 80/09/12 13pp
- 8010160507 Submits add1 info requested in NRC 800627 1tr re adequacy of facility electric distribution sys voltages LINDER:F Dairyland Power Cooperative 80/09/17 4pp
- 8010300134 Discusses issuance of Amend 17 to provisional DL for LACBHR Util 800117 analysis of safe shutdown capability not sufficient per encl BNL 800702 review Shutdown sys must comply w/10CFR50.App R. Section III.Paragraph L EISENHUT, D G Division of Licensing 80/09/18 5pp
- B010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENMUT.D G Division of Licensing 80/09/19 28pp
- 8010240192 Approves Nuclear Assurance Corp 800822 proposed spent fuel route change Forwards strip map indicating changes Map withheld (ref 10CFR2 790)
 MCCORKLE, W Physical Security Licensing Branch 80/09/22 ip
- 8010140335 Submits info requesting exemption from 10CFR50.App J. containment leakage testing re airlack doors of BWR containment bldg LINDER:F Dairyland Power Cooperative 80/09/26 4pp
- B010150476 Responds to DM Grutchfield B00701 ltr to F Linder re NRC evaluation of facility electrical penetrations Evaluation in error as epoxy seals are not required for penetration to function. Epoxy seals used to stop moisture entering cables LINDER:F Dairyland Power Cooperative B0/10/08 ip
- B010160478 Submits corrections to util 800409 response to NRC request for add1 info on TMI Short-Term Lessons Learned requirements (NUREO-0378) Items brought to J Shaa attention in 801006 telcon Facility will be shut down for refueling in Nov 1980 LINUER.F. Dairyland Power Cooperative 80/10/10 2pp
- 8010210308 Submits status rept re SEP Topics II-4 & III-6 re liquefaction potential 2 seismic analyses Orouting program scheduled for 801020 re turbine bldg floor Analysis has commenced re alternate core spray injection LINGER;F Dairyland Power Cooperative 80/10/14 ip
- 8010220538 Responds to NRC 800804 request for details re seismic syaluation program & justification for continued operation Low seismic risk assessments support continued operation. Related documentation and LINDER, F Dairyland Power Cooperative 80/10/14 17pp
- B010280353 Forwards Special Rept 80-02 covering results of sampling & analysis actions w/addl operational info for five occasions when reactor thermal power changed by more than 15% of rated thermal power within 1-h.

 LINDER, F Dairyland Power Cooperative 80/10/17 iipp.
- G Inspection reports, IE Bulletins & correspondence
- 8010010853 Forwards IE insp Rept 50-409/80-06 on 800701-31 & notice of violation HEIBHHAN,R F Region 3. Chicago, Reactor Operations Nuclear Bupport
- --- 8010010855 Natice of violation from insp on 800701-31
 * Region 3, Chicago, Office of the Director, 80/08/11 ip
- --8010010857 JE Insp Rept 50-409/80-06 on 800701-31, Noncompliance noted: failure to folious procedures for sys wiring mod as required re administrative control procedures ACP-04 1
 RIDOMAYK R . BAKER R R . BOYD.D C Region G. Chicago: Office of the Director. 80/08/11 9pp

- 8010160190 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) w/Loss Offsite Power " On 800902, test conducted on ENB extensions All extensions operated satisfactorily LINDER,F Dairyland Power Cooperative 80/09/02 2pp
- 8010160170 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) w/Loss Offsite Power " On 800902, test conducted on ENB extensions All extensions operated satisfactorily LINDER,F Affiliation Unknown 80/07/02 2pp
- BO10210063 Provides updated info re admittance of Region 3 personnel to facilities. Forwards lists of personnel for whom permanent momemployee badges are requested & personnel requiring badge for unescorted access in protected areas KEPPLER, J Q Region 3, Chicago, Office of the Director, BO/09/03
- BO10140088 Ack receipt of 800911 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-409/80-06 HEISHKAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/23 ip
- B010160171 Forwards IE Insp Rept 50-409/80-05 on 800707-11 & 0828-29 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30
- --8010160177 IE Insp Rept 50-409/80-05 on 800707-11 & 0828-29
 Noncompliance noted revision of security plan decreasing
 safeguards effectiveness made w/o prior approval Vital area
 not controlled Details withheld (ref 10CFR2.790)
 HIND, J A Region 3. Chicago. Bafeguards Branch CREED, J R,
 PIRTLE, O L Region 3. Chicago. Office of the Director 80/09/25
- 8010160306 Forwards Suppl 2 to IE Sulletin 79-018. "Environ Gualification of Class IE Equipment" No written response required. KEPPLER, J. Q. Region 3. Chicago, Diffice of the Director 80/09/30 to
- 8010280646 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required MEFPLER, J G Region 3, Chicago, Office of the Director 80/10/02
- 80:0270016 Forwards 1E Info Notice 80-36, "Failure of Steam Generator Support Solting " No specific action or response requested KEPPLER.J Q Region 3, Chicago, Office of the Director 80/10/10 1p.
- R Periodic operating reports & related correspondence
- 8010150371 Forwards monthly operating rept for Bept 1980 LINUER:F Dairyland Power Gooperative 80/10/07 ip
- --8010150373 Monthly operating rest for Sept 1980
 GOODMAN.L S Dairyland Power Cooperative 80/10/03. 14pp
- 8 Reportable occurrences, LERs & related correspondence
- 8010100389 PNO-II1-80-149; on 800809; unit was shut down to repair leakage through upper seal on control rod drive mechanism Outage is expected to last until 800816 BOYD, D.C., FORNEY, M.L., HEISHMAN, R.F. Region 3, Chicago, Office of the Director 80/08/12 Ip
- B010090234 PNO-III-80-158.on 800822.plant tripped from 55% power due to feedwater pump controller failure. All sys responded as required No radioactive releases
 B0YD.D.C. BRANCH.W. HEISHMAN.R F Region 3, Chicago, Office of the Director 80/08/25 2pp
- V. Operator Examinations
- 8010020306 Notifies that personnel in training for NRC license are enrolled in approved operator-senior operator requalification programs in response NRC 800829 telcon LINOER, F Dairyland Power Cooperative. 80/09/12, 1p

- DOCKET 50-410 NINE HILE POINT NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010090495 Summary of B00805 meeting w/Mark II owners to discuss lead plant interim condensation oscillation & chugging loads. Discussion topics attendance & meeting handouts encl ANDERSON. C.J. Generic Issues Branch B0/08/29 98pp
- 80:00:00:00:6 Forwards request for add1 into re DYWIDAO threadbar sys Draft questions served as agenda for NRC 80:08:14 meeting w/util in Bethesda,MD TEDESCO.R L. Assistant Director for Licensing 80:09:709, 4pp
- 8010060102 Summary of 800904-05 meeting w/Mark II owners in Bethesda.MD re long-term program chugging & lateral loads Attendance list & handouts encl
 ANDERSON.G J Oeneric Issues Branch 80/09/12 45pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EISENHUT.D O. Division of Licensing 80/09/19 28pp
- 801027023B Notification of B01008 meeting w/representatives from Mark II owners group in Bethesda, MD to discuss Mark II plants chugging load spec ANDERSON, C Generic Issues Branch 80/09/22 1p
- 8010070460 Forwards responses to Questions 0361,26-0361 35 contained in NRC 800708 ltr requesting add1 info re geologic invastigation RHODE.O.K Niagara Mohawk Power Corp 80/10/03 100pp
- G Inspection reports. IE Bulletins & correspondence
- 8010100087 Forwards IE Insp Rept 50-410/80-06 on 800714-18 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/20 2pp
- --8010100091 IE Insp Rept 50-410/80-06 on 800714-18 No mancompliance moted Major areas inspected activities associated w/reactor pressure vestel storage & placement review MCBREARTY.R A Region I. Philadelphia, Office of the Director. TRIPP.L E Region I. Philadelphia, Reactor Construction k Engineering Support Branch 80/08/19 7pp
- 8010100099 Forwards IE Insp Rept 50-410/80-07 on B00715-18 No noncompliance noted CARLSON:R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8010100103 IE Insp Rept 50-410/80-07 on 800715-18 No noncompliance noted Major areas inspected on-going & completed const activities & licensee procedures & records for processing of field changes
 VARELA:A A . CHAUDHARY. B K Region 1, Philadelphia, Office of the Director EBNETER:B D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/19. 8pp
- 8010230522 Forwards IE Insp Rept 50-410/80-08 on 800804-08 No noncompliance noted CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/29 2pp
- --8010230528 IE Insp Rept 50-410/80-08 on 800804-08, No noncompliance noted Major areas inspected offshift & onshift insp of util & contractor effort in setting of reactor vessel MCGREARTY, R. FEIL, R. Region 1. Philadelphia, Office of the Director MCGAUOHY, R. W. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/27 4pp
- 8010010794 Responds to IE Bulletin 80-16 re Rosemount Model 1151 & 1152 pressure transmitters Affected safety-related sys will be identified Corrective action proposed by 801031 RMODE. G K Niagara Mohawk Power Corp 80/09/02 ip.
- B010010B90 Responds to IE Bulletin 80~19.Revision 1 CP Clare Model H02X-1011 mercury-wetted relays are not used in reactor protection sys RHDDE.Q K Niagara Mohawk Power Corp 80/09/08 1p.
- 8010020317 Responds to 1E Bulletin 80-20 re Westinghouse Type W-2 control switches Response to info requested by bulletin will be completed by 801031 RHODE, G K Niagara Mohawk Power Corp. 80/09/11. 1p

- 8010200403 Submits add1 response to IE Bulletin 79-28, "Possible Malfunction of NAMCD Model EAIBO Limit Switches at Elevated Tamps "Util will exclude use of NAMCD EAIBO switches, date coded 02-79 through 08-79,-v/o new top cover gaskets RHDDE, Q K Niagara Mohawk Power Corp 80/09/17 ip
- 8010240113 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 ip
- B0102B0165 Forwards IE Info Notice 80-36, "Failure of Steam Ownerator Support Bolting " No specific action or response requested ORIER, B H. Region 1, Philadelphia. Office of the Director 80/10/10 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8010150027 Ack rateipt of 800801 final deficiency rept re biological shield wall linear indications CARLEGUAR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/12 ip
- --801013004i Final deficiency rept re biological shield wall linear indications All shop weld joints evaluated per AWB DI 1 % PBAR 1 were determined acceptable or repaired GA program modified to reduce possibility of weld-related problems.

 DISE.D P Niagara Mohawk Power Corp EO/OB/OI B3pp
- B010100249 Interim deficiency rept re failure of matl in spent fuel pool heat exchangers to meet impact testing spec requirements Caused by omission of test specimen parameter from impact test date Safety function may be jeepardized.

 RHODE, O K Niagara Mohawk Power Corp 80/10/02 3pp.
- 8010140492 Interim deficiency rept re reactor pedestal embedment PB-37. Halding procedure deviations found in eight sections of rebar which were field welded to shear bars. Procedures for welding not qualified Final rept to be submitted 801208. RHODE. O K Niagara Mohawk Power Corp 80/10/08 2pp.
- **OCKET 50-412 BEAVER VALLEY POHER BIATION, UNIT 2

 Application/construction stage documents & correspondence
- Ol0220097 Forwards errats sheets amending 800904 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing 80/09/19. 28pp.
- Becurity, medical, emergency & fire protection plans
- 010170637 Responds to 800826 itr re workable evacuation program for Hopewall Township.PA Future inquiries should be sent to FEMA or local nuclear plant licensee ORIMES.B K Emergency Preparedness Program Office. 80/10/03 1p.
 - Inspection reports. IE Bulletine & correspondence
- 10020213 Forwards IE Insp Rept 50-412/80-05 on 800604-06. No noncompliance noted SMITH.0 H Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/07/20 2pp
- 010020218 IE Insp Rept 50-412/80-05 on 800604-06. No noncompliance notef. Major areas inspected, solvinon conditions at const site & mot control program during site preparation JACKBEN.T J. Region 1, Philadelphia, Office of the Director, BORES,R J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/28 Spp.
- HO020138 Act receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/80-06.
 Awaits response re usiding electrode control.
 CARLBONER T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 80/08/22. 1p.
- --8010020144 Forwards IE Insp Rept 50-412/80-06 on 800602-06 & notice of violations. CARLSON.R.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/07/07. 2pp.
- --8010020147 Notice of violation from insp on 800602-06.
 * Region 1, Philadelphia, Office of the Director. 80/07/03. 2pp.

- --8010020151 IE Insp Rept 50-412/80-06 on 800602-06 Noncompliance noted, failure to return used or damaged welding electrodes to issue station & failure to provide adequate protection for equipment in temporary storage

 NARROW, L. PAOLIND.R. J. Region 1, Philadelphia, Office of the Director MCGAUGHY, N. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/03 11pp
- B010020110 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters have not been specified for any Class IE safety-related applications Any future orders will be of type which will not exhibit adverse characteristics WDDLEVER,E J Duquesne Light Co 80/08/27 1p
- 8010010690 Responds to IE Bulletin 80-19. Revision 1 Reactor protection sys does not use mercury-wested relays.

 MDDLEVER.E.J Duquesne Light Co. 80/08/29 ip
- 8010230706 Forwards IE Insp Rept 50-412/80-08 on 800811-15 No noncompliance noted. CARLEDNR T Region 1. Philadelphia, Reactor Construction & Engineering Bupport Branch 80/09/05. 2pp
- --8010230707 IE Insp Rept 50-412/80-08 on 800811-15 No noncompliance noted Major areas inspected containment liner dome, embedment records & pipe well thickness NARROW, L. MALTON, O. A., PAOLINO, R. J. Region 1, Philadelphia, Office of the Director 80/09/04 9pp
- 8010130182 Ack receipt of 800814 interim deficiency rept re linear indications in gib gusset welds in reactor vessel structural support Outstanding info includes determinations of extent of deficiencies in welds & determination of causes CARLEON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/18 2pp
- --B010180203 Interim deficiency rept re linear indications in gib gusset welds in reactor vessel structural support Pending outcome of metallographic analysis of weld sample, addl insps of gib gussets will be performed WDDLEVER.E J Duquesne Light Co B0/0B/14 4pp
- 8010200380 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches," Specified switches are not used at facility WODLEVER: E J Duquesna Light Co. 80/09/19, 1p.
- 8010240152 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required ORIER. B.H. Region i. Philadelphia, Office of the Director 80/10/02. ip.
- 8010280250 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested GRIER.B H Region i. Philadelphia, Office of the Director. 80/10/10, ip.
- B Reportable occurrences. LERs & related correspondence
- 8010130182 Ack receipt of 800814 interim deficiency rept re linear indications in gib gusset welds in reactor vessel structural support Outstanding info includes determinations of extent of deficiencies in welds & determination of causes CARLBOWN T Region 1, Philadelphia: Reactor Construction & Engineering Support Branch 80/09/18 2pp.
- --8010150203 Interim deficiency rept re linear indications in gib gusset welds in reactor vessel structural support Pending outcome of metallographic analysis of weld sample, addl inspe of gib gussets will be performed.

 WOOLEVER, E. J. Duquesna Light Co 80/09/14 4pp.
- 8010270100 Ack receipt of 800704 final deficiency rept re welding electrods control program.
 CARLBON.R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/09/23. 1p.
- ---B010270104 Final deficiency rept re welding electrode control program Investigation performed re extent of misapplication of welding electrode E309-16 assures that w/noted exceptions, proper control had been applied, HOCLEVER, E. J. Duquesne Light Co. B0/09/04, App.
- V. Operator Examinations
- 8010280438 Forwards revised operator training program WERLING, J. A. Duquesne Light Co 80/09/02 ip.

- Revision 2: 0010280443 "Training Manual," Revision 2 Duquesne Light Co
- DOCKET 90-413 CATAMBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800704 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISEKHUT, D O Division of Licensing 80/09/19 28pp.
- # General correspondence
- B010100358 Expresses concern re sale of facility Action will strengthen Duke Power Co monopoly EDDLEMAN,N Affiliation Unknown 80/10/04 4pp
- O Inspection reports. IE Bulletins & correspondence
- 8010230108 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive Use Bhipmants of Radioactive Hatls," No written response required.

 O'REILLY, J P Region 2: Atlanta: Office of the Director 80/08/29.
- 8010010186 Ack receipt of 800805 & 29 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-413/80-11 & 50-414/80-11 MURPHYC.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/11. ip
- --8010010177 Forwards supplemental response to NRC 800715 ltr re violations noted in IE Insp Repts 50-413/80-11 & 50-414/80-11. Corrective actions insp program for electrical cables revised. PARKER.H O Duke Power Co 80/08/27 2pp.
- --8010010206 Responds to NRC 800713 ltr re violations noted in IE Insp. Repts 50-413/80-11 & 50-414/80-11 Corrective actions insp. instructions revised to reflect insp. of all interconnecting wiring & cabling & const procedure implemented PARKER.W O Duke Power Co. 80/08/05 3pp
- --8010010214 Forwards IE Insp Repts 50-413/80-11 & 50-414/80-11 on 800327-29 & notice of violation. HURRHY,C E. Region 2, Atlants, Reactor Construction & Engineering Support Branch 80/07/15 2pp
- --8010010218 Notice of violation from insp on 800527-29.

 ** Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/15 2pp
- --8010010228 IE Insp Repts 50-413/80-11 & 50-414/80-11 on 800527-29.

 Noncompliance noted inadequate insp of safety-related electrical cables & failure to include circuit testing in const program

 OIBBONS T.D., MERRIKEATHER, N. Region 2, Atlanta, Office of the Director CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Dranch 80/07/15 4pp.
- 8010140023 Ack receipt of IC Insp Repts 50-413/80-18 & 50-414/80-18 on 800721-28 No proprietary info. PARKER, H. O Duke Power Co 80/09/22, 1p
- --8010140030 Forwards IE Insp Repts 50-413/80-18 & 50-414/80-18 on 800721-28 No noncompliance noted. MURPHY.C E. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/09/04 2pp.
- --BOIO140034 IE Insp. Repts NO-413/80-18 & 30-414/80-18 on BOO721-25, No noncompliance noted Major areas inspected; safety-related piping, math handling & storage & radiographic film.

 CELEY, J. L. Region 2, Atlanta, Office of the Director HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/03 6pp.
- 801014013B Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment." No written response required O'REILLY, J P Region 2: Atlanta. Office of the Director. 80/09/30. 1p
- 8010240156 Ack receipt of IE Insp Repts 50-419/80-19 & 50-414/80-19 on 800728-0801. No proprietary info PARKER, W.O. Duke Power Co. 80/09/30. ip.

- --8010240160 Forwards IE Insp Repts 50-413/80-17 & 50-414/80-17 on B00728-0801 & notice of violation MURPHy.C E Region 2. Atlants, Reactor Construction & Engineering Support Branch 80/09/10. 2pp
- --8010240166 Notice of violation from insp on 800728-0801, # Region 2. Atlants, Office of the Director 80/09/09, 1p.
- --9010240173 IE Insp Repts 50-413/80-19 & 50-414/80-19 on B00728-Q801. Noncompliance noted stainless steel piping found on ground & scaffolding found against piping & electrical cable found on floor BRYANTIJ C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. HUNT.M D. Region 2, Atlanta, Office of the Director BD/09/09 5pp.
- 8010240335 Ack receipt of IE Insp Repts 50-413/80-22 & 30-414/80-22 on 800317-22. No proprietary info PARKER, U. D. Duke Power Co. 80/09/30. ip
- --8010240339 Forwards IE Insp Repts 50-413/80-22 & 50-414/80-22 on 800819-22 No noncompliance noted MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --8010240346 IE Insp Repts 50-413/80-22 & 50-414/80-22 on B00819-22 No noncompliance noted Major areas inspected. OA procedures, responses to IE bulletins & previous insp items. BRYANT. J C Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch MCFARLAND. C R Region 2, Atlanta. Office of the Director 80/09/10 4ps.
- 8010240107 Ack receipt of IE Imsp Repts 50-413/80-21 & 50-414/80-21 on 800911-15 No proprietary info PARKER, N. D. Duke Power Co. 80/10/01 1p.
- --8010240111 Forwards IE Insp Repts 50-413/80-21 & 50-414/80-21 on 800811-15.No noncompliance noted MURPHY.G.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 60/09/11. 2pp.
- --8010240120 IE Insp Repts 50-413/80-21 & 50-414/80-21 on 900811-15.No noncompliance noted Kajor areas inspected; RCPB piping, containment structural steel & safety-related structural steel HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch. CROWLEY, B R Region 2, Atlanta, Office of the Director, 80/09/09 Spp
- 8010270411 Forwards IE Circular 80~22, "Confirmation of Employee Qualifications." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/02, 1p.
- 8010270419 Ack receipt of B01001 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-413/80-10 k 50-414/80-10 MVRPHY,G.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/10, 1p
- --8010270427 Responds to MRC 8D0819 ltr re violations noted in 18 Insp Repts 50-419/80-10 t 50-414/80-10. Corrective actions: reinspected all completed safety-related support welds, PARKER, H. O. Duke Pawer Co. 80/10/01 1p
- 8010270052 Forwards IE Info Notice 80-36, "Failure of Steem Generator Support Bolting," No specific action or response requested. O'REILLY-J.P. Region 2, Atlanta, Office of the Director 80/10/10. in
- 8010300380 Ack receipt of B00815 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 30-354780-08, 30-370/80-09, 50-413/80-09, 50-41/80-07, 50-491/80-07, 50-492/80-06 & 80-493/80-06 MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16 2pp
- --8010300385 Responds to NRC 800718 ltr re violations noted in IE Insp Repts 80-369/80-081,50-370/80-05,50-413/80-09,50-414/80-09, 50-491/80-07,50-492/80-06 & 50-493/80-06, Corrective actions: records storage facility constructed. PARKER: M. Q. Duke Power Co. 80/08/15, 7pp.
- --8010300388 Forwards IE Insp Repts 50-369/80-08,50-370/80-05, 50-413/80-09,50-414/80-09,50-491/80-07,50-492/80-06 & 50-493/80-06 on 800519-23 & notice of violation, MURPHY,C E. Region 2. Atlants, Reactor Construction & Engineering Buppert Branch 80/07/18 2pp.

- --B010390423 Notice of violation from inse on B00519-23
 ** Region 2, Atlanta, Office of the Director B0/07/18 4pp
- --8010300428 IE Insp Repts 50-367/80-08.50-370/80-05.50-413/80-09, 50-414/80-09, 50-491/80-07.50-491/80-06 & 50-493/80-06 on 800519-23 Noncompliance noted in areas of temporary record atorage facilities & fire protection BROWNEE, V L. MODENOS. L. BURDETTE, T E Region 2. Atlanta, Office of the Director 80/07/18 25pp
- 8010310022 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-413/80-14 & 50-414/80-14 MURPHY, CE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/10/17 ip
- --8010310025 Forwards response to NRC 800801 ltr re violations noted in IE Insp Repts 50-413/80-14 & 50-414/80-14 Corrective actions supplemental insp instructions issued to include checks for freedom of movement on applicable supports PARKER.N O Duke Power Co 80/08/25 2pp
- --8010310029 Forwards IE Insp Repts 50-413/80-14 & 50-414/80-14 on 800402-27 % notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/01 2pp.
- --8010310031 Notice of violation from insp on 800602-27

 * Region 2, Atlanta, Office of the Director 80/07/19 ip
- --8010310034 IE Insp Repts 50-413/80-14 & 50-414/80-14 on 800602-27 Noncompliance noted failure to install pipe strut in accordance w/drawings & procedures & failure to apply structural walds in accordance w/drawings MAXWELL.0 F Region 2. Atlanta, Diffice of the Director BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/18 7pp
- B010310035 Ack receipt of 800907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/10/17 ip
- --801031003B Forwards response to NRC 800815 ltm re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16 Corrective actions it explaining abbreviation & defining all ref documents will be sent to design engineering & const depts PARKER,N O Dute Power Co 80/09/09 3pp
- --2010310042 Forwards IE Insp Repts 50-413/80-16 & 50-414/80-16 on B00630-0718 & notice of violation. HURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch B0/08/15 2pp
- ~-8010310044 Notice of violation from insp on 800630-0718 * Region 2, Atlanta, Office of the Director. 80/08/01. ip.
- --8010310047 IE Insp Repts 50-413/80-16 & 50-414/80-16 on 800630-0718
 Noncompliance noted failure to correctly translate codes & spec drawings, procedures or instructions
 MAXMELL.0 F Region 2, Atlanta, Office of the Director
 BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/08/01 7pp
- R Periodic operating reports & related correspondence
- 8010210761 Forwards results of Jul 1979-June 1980 interim nonradiological monitoring No mods to study sampling or analytical techniques implemented from studies previously submitted No distinct changes in Late Wylie water quality. PARKER, N O Dute Power Co 80/10/15 ip
- --8010210566 "Interim Monitoring Study. Jul 1979-June 1980 "
 Duke Power Co 80/10/15 26pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007300377 Forwards final rept re-potential problem in safety-related overcurrent relays Problem was random in nature & not generic DUVALL.D D Gould-Brown Boveri. 80/07/16 4pp.
- 8010020603 Part 21 rept re potential defect in component of DBRV standby diesel generator concerning link rod assembly which could result in engine failure Defact limited to models DBRV 12: DBRV 16: DB

- 8010050281 Significant Deficiency Rept SD 413-414/80-13 re improper operation of Model 175C141 optical isolater, initially reported 800828 Isolators will be changed-out w/isolator of adequate current capacity Change to be completed by 820101 PARKER.W O Dute Power Co 80/09/26 2pp
- 8010230192 Part 21 rept providing update to 800703 deficiency rept ra 3-inch carbon steel elbows Chemical analysis of potentially defective fittings complete No defective fittings in use at any power facility HAYDEN.L E Chemtron Corp 80/10/01 4pp
- 8010240591 Part 21 rept re Brand Rex conductor Absence of cured conductor results in unqualified Class IE equipment Verification of all current & future components has been implemented RDERTEGL B Brand-Rex Co 80/10/0B 3pp
- DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D G Division of Licensing 80/09/19 28pp
- G Inspection reports. IE Bulletins & correspondence
- 8010230108 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls "No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29, in
- 8010010186 Ack receipt of 800805 & 29 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-419/80-11 & 50-414/80-11 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/11 ip
- ---B010010197 Forwards supplemental response to NRC 800715 ltr reviolations noted in IE Insp Repts 50-413/80-11 & 50-414/80-11 Corrective actions insp program for electrical cables revised PARKER, W O Duke Power Co 80/08/29 2pp
- --8010010206 Responds to NRC 800718 ltr re violations noted in IE Insp. Repts 50-413/80-11 & 50-414/80-11 Corrective actions insp. instructions revised to reflect insp. of all interconnecting wifing & cabling & const procedure implemented PARKER.H Q Duke Power Co. 80/08/05 3pp
- --B010010214 Forwards IE Insp Repts 50-413/80-11 & 50-414/80-11 on 800527-29 & notice of violation HURPHY,C.E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/07/15 2pp
- --8010010218 Notice of violation from insp on 800527-29.

 * Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/15 2pp
- --8010010228 IE Insp Repts 50-413/80-11 & 50-414/80-11 on 800527-29. Noncompliance noted inadequate insp of safety-related electrical cables & failure to include circuit testing in const program OIBBONS, T D , MERRIWEATHER.N Region 2, Atlanta, Office of the Director CONLON, T E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/15 4pp
- 8010140023 Ack receipt of IE Insp Repts 50-413/80-18 & 50-414/80-18 on 800721-25 No proprietary info PARKER, W.D. Duke Power Co 80/09/22 1p
- --801014003D Forwards IE Insp Repts 50-413/80-18 & 50-414/80-18 on 800721-25 No noncompliance noted MARPHY.C.E Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/09/04 2pp
- --B010140034 IE Insp Repts 50-413/80-18 & 50-414/80-18 on 800721-25 No noncompliance noted Major areas inspected safety-related piping, math handling & storage & rediographic film CELEY, J.L. Region 2, Atlanta, Office of the Director. HERDY, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/09/03, 6pp,

- 801016013B Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30 in
- B010240156 Ack recaipt of IE Insp Repts 50-413/80-19 & 50-414/80-19 on B00728-0801 No proprietary info PARKER.N O Duke Power Co 80/09/30 1p
- --8010240160 Forwards IE Insp Repts 50-413/80-19 & 50-414/80-19 on 800728-0801 & notice of violation MURPMY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 90/09/10 2pp
- --B010240166 Notice of violation from inep on 800728-0801 * Region 2, Atlanta: Office of the Director 80/09/09 ip
- --8010240173 IE Insp Repts 50-413/80-19 & 50-414/80-19 on 800728-0801
 Noncompliance noted stainless steel piping found on ground & scaffolding found against piping & electrical cable found on floor
 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch HUNT, M D Region 2. Atlanta, Office of the Director 80/09/09. Spp
- 8010240335 Ack receipt of IE Insp Repts 30-413/80-22 & 50-414/80-22 on 800817-22 Ne proprietary info PARKER, N O Duke Power Co 80/09/30 ip
- --B010240339 Forwards IE Insp Repts 50-413/80-22 & 50-414/80-22 on B00819-22 No noncompliance noted MURPHY.C. E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch B0/09/10 2pp
- --B010240346 IE Insp Repts 50-413/80-22 & 50-414/80-22 on 800819-22 No noncompilance noted Major areas inspected. OA procedures: responses to IE bulletins & previous insp items BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND. C. Region 2. Atlanta, Office of the Director 80/09/10 App
- 8010240107 Ack receipt of IE Insp Repts 50-413/80-21 & 50-414/80-21 on B00811-15 No proprietary info PARKER, W 0 Duke Power Co B0/10/01 ip.
- --B010240111 Forwards IE Insp Repts 50-413/80-21 & 50-414/80-21 on 800811-15.No noncompliance noted HURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/11 2pp
- --8010240120 IE Insp Repts 50-413/80-21 % 50-414/80-21 on 800Bii-15 No noncompliance noted Major areas inspected RCPB piping, containment structural steel & safety-related structural steel HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch CRCWLEY, B. R. Region 2. Atlanta. Office of the Director 80/09/09 Bpp
- 8050270411 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02
- 6010270419 Ack receipt of 801001 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-10 k 30-414/80-10 MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 60/10/10 ip
- --8010270427 Responds to NRC 800819 ltr re violations noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 Corrective actions reinspected all completed safety-related support welds. PARKER, M. O. Duke Pawer Co. 80/10/01 ip.
- 8010270032 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested 10'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/10/10
- 8010300380 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-412/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06.
 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16 2pp

- --8010390385 Responds to NRC B00718 ltr re violations noted in IE Insp Repts 50-349/80-08,50-370/80-05,50-413/80-09,50-414/80-09, 50-491/80-07,50-492/80-06 & 50-493/80-06 Corrective actions records storage facility constructed PARKER, H O Duke Power Co 80/08/15 7pp
- --8010300388 Forwards IE Insp Repts 50-349/80-08.50-370/80-05. 50-413/80-09.50-414/80-09.50-491/80-07.50-492/80-06 & 50-493/80-06 on 800519-23 & notice of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8010300423 Notice of viplation from inep on 800517-23
 * Region 2. Atlants, Office of the Director 80/07/18 4pp
- --8010300428 IE lnsp Repts 50-369/80-08.50-370/80-05.50-413/80-07.50-414/80-07.50-491/80-07.50-492/80-06 & 50-493/80-06 on 800519-23 Noncompliance noted in areas of temporary record storage facilities & fire protection BROWNLEE.V L . LENAMAN, J J . WALTERS, D K . Region 2. Atlanta, Office of the Director 80/07/18 25pp
- 8010310022 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-14 & 30-414/80-14 MRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/10/17 ip.
- --8010310025 Forwards response to NRC 800801 ltr re violations noted in IE Insp Repts 50-413/80-14 & 50-414/80-14 Corrective actions supplemental insp instructions issued to include checks for freedom of movement on applicable supports PARKER.#10 Duke Power Co 80/08/25, 2pp
- --8010310027 Forwards IE Insp Repts 50-413/80-14 & 50-414/80-14 on BO0602-27 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BO/08/01 2pp
- --8010310031 Notice of violation from insp on 800602-27,
 ** Region 2. Atlants, Office of the Director 80/07/18 1p
- --B010310034 IE Insp Repts 50-413/80-14 & 50-414/80-14 on 800602-27
 Noncompilance notes failure to install pipe strut in
 accordance w/drawings & procedures & failure to apply
 structural welds in accordance w/drawings.
 MAXHELL.0 F Region 2. Atlanta. Office of the Director
 BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering ,
 Bupport Branch 80/07/18 7pp
- B010310035 Ack recalpt of B00909 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repta 50-413/80-16 & 50-414/80-16 MRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/10/17 1p
- --8010310038 Forwards response to NRC 800815 ltr re violations noted in IE Insp Repts 50-413/80-16 & 50-414/80-16 Corrective actions ltr explaining abbreviation & defining all ref documents will be sent to design engineering & const depts PARKER, U O Duke Power Co 80/09/09. 3pp.
- --8010310042 Forwards IE Insp Repts 50-413/80-16 & 30-414/80-16 on 800630-0718 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/08/19 2pp
- --9010310044 Notice of violation from insp on 800630-0718
 * Region 2, Atlanta, Office of the Director 80/08/01 ip
- --8010310047 IE Insp Repts SD-413/80-16 & 50-414/80-16 on 800630-0718
 Noncompliance noted failure to correctly translate codes & spec drawings, procedures or instructions
 MAXHELL.0 F. Region 2. Atlanta, Office of the Director
 BRYANTJ.C Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/08/01. 7pp
- R. Periodic operating reports & related correspondence
- 8010210561 Forwards results of Jul 1979-June 1980 interim nonradiological monitoring No mods to study sampling or analytical techniques implemented from studies previously submitted No distinct changes in Lake Hylie water quality PARKER, H. O Duke Power Co. 80/10/15. ip
- --8010210566 "Interim Monitaring Study, Jul 1979-June 1980 " Duke Power Co. 60/10/15. 26pp

S Reportable occurrences, LERs & related correspondence

- 80100602B1 Significant Deficiency Rept SD 413-414/80-13 re improper operation of Model 175C141 optical isolater, initially reported 80082B Isolators will be changed-out w/isolator of adequate current capacity Change to be completed by 820101 PARKER, W G Duke Power Co 80/09/26 2pp
- 8010240591 Part 21 rept re Brand Rex conductor Absence of cured conductor results in unqualified Class IE equipment Verification of all current & future components has been implemented ROBERTS.L B Brand-Rex Co 80/10/08 3pp
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010010698 Forwards preliminary responses to Reactor Bys Branch questions to aid NRC in preparation of 800923-25 meeting Guestions 211 117,211.157 & 211 158 will be answered at later date Responses available in Central Files only DALE, L.F. Mississippi Power & Light Co. 80/09/16, 2pp
- 8010220077 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of THI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D 0 Division of Licensing 80/07/17 28pp
- 8010220235 Forwards request for add1 info re radiological controls Requests amend to FSAR to reflect responses to encl requests TEDESCO, R L Assistant Director for Licensing 80/07/22 25pp
- 8010010663 Requests that requirement to maintain sediment basins be deleted from environ protection program since MS River is protected by NPDES Permits MS0027031 & MS0029173 BALErL F Mississippi Power & Light Co 80/09/26 ip
- 8010070346 Forwards response to NRC 800421 request for info on Category 1 mesonry walls All mesonry walls in Category 1 bldgs are designed to requirements Oversize drawings available in Central Files only DALF.L. F. Mississippi Power & Light Co. 80/10/02 22pp
- 8010140239 Forwards description of preservice exam of ASME Class I & II components & application of exclusion criteria permitted by IMB-1220 & IMC-1220 One hundred oversized flow diagrams to be recalled for filming DALE:
- B01021032D Forwards request for add1 info consisting of Reactor Sys Branch & OA Branch questions from review of FSAR FSAR should be amended to reflect responses to requests TEDESCO,R L Assistant Director for Licensing B0/10/02, 4pp
- F Security, madical, emergency & fire protection plans
- 8010230331 Notification of 801021 meeting w/util, Pronto Power Corp & Science Applications. Inc in Bethesda. Md to discuss licensee approach to emergency planning requirements MARTORE, J. A. Licensing Branch 3 80/10/07 3pp.
- H General correspondence
- B01020033B Submits new address for receipt of future correspondence re facilities & addition of three names for distribution list DALE: L. F. Mississippi Power & Light Co. 80/10/13 2pp
- I Financial information
- B010200357 Forwards Federal Financing Bank & Rural Electrification Administration 801002 commitment notice in support of application to make South MS Electric Power Association part owner of facility BTAMPLEY.N L Mississippi Power & Light Co 80/10/16 34pp
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 8010010561 Forwards Amend 43 to application for OLs, submitted as Amend 43 to FBAR & consisting of responses to NRC questions & refinements of design info MCGAUGHY, J P Mississippi Pawer & Light Co 80/09/30 ip.

- --B010010566 Amend 43 to application for OLs, submitted as Amend 43 to FBAR & questions & refinements re FBAR MCQAUQHY,J P Mississippi Power & Light Co B0/09/30 2pp
- ---8010010575 Amend 43 to FBAR, consisting of responses to NRC questions & refinements of design info Mark III containment loads rept encl

 * Missission Power & Light Co 80/09/30 1200pp
- 8010160537 Forwards affidavit of svc for Amend 43 to FSAR per NRC 780527 ltr DALF,L F Mississippi Power & Light Co 80/10/10 2pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8010030490 Forwards IE Insp Rept 50-416/80-17 on 800722-0801 Nn noncompliance noted LEHIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/26 2pp
- --8010030492 IE Insp Rept 30-416/80-17 on 800722-0801 No noncompliance noted Major areas inspected preoperational test program administration & licensed operator training KELLOGO.P J Region 2, Atlanta. Reactor Operations Nuclear Support Branch MAGNER.A O Region 2, Atlanta, Office of the Director 80/08/26 App
- 8010230069 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Hatis " No written response required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/08/29 2pp
- 8010010031 Ack receipt of 800721 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416//80-12 & 50-417/80-00 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/05 ip
- ---B010010036 Responds to NRC 800624 ltr re violation noted in IE Insp Repts 50-416/80-12 & 50-417/80-08 Corrective actions appropriate documentation will be available for recording location of holes on cut reinforcing bars MCGAUGHY.J P Mississippi Pawer & Light Co 80/07/21 3pp
- --8010010044 Forwards IE Insp Repts 50-416/B0-12 & 50-417/B0-08 on 800527-30 & notice of violation MVRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. B0/06/24 2pp
- --8010010046 Notice of violation from insp on 800527-30
 * Region 2, Atlanta, Office of the Director 80/06/24 ip
- ---8010010057 IE insp Repts 50-416/80-12 & 50-417/80-08 on 800527-30
 Noncompliance moted unauthorized cutting of rebar
 RAUSCH.J K Region 2, Atlanta, Reactor Construction & Engineering
 Bupport Branch HUNT.M D Region 2, Atlanta, Office of the
 Director 80/06/24 5pp
- 8010080582 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 5A-312. Type 304 Stainless Steel Pipe " Review indicated that Type 300 series piping has not been used in specified applications at facility DALE.L. F Mississippi Power & Light Co 80/09/15 ip
- B010150328 Responds to IE Bulletin 80-17.Revision 1, re morcury-wetted matrix relays in reactor protective sys Specified concerns not applicable as relays are not used in protection sys Requests extension to complete NSBS portions
 DALE.L F Mississippi Power & Light Co 80/07/17 1p
- 8010150336 Responds to IE Bulletin 80-20 re W-2 spring return to neutral control switches Specified concerns not applicable as no switches are used in balance-of-plant safety-related sys.Requests extension to complete NBSB portion of bulletin DALE.L F Hississippi Power & Light Co 80/07/17 ip
- 80:0080384 Responds to IE Bulletin 77-24, "Frozen Lines " Heat tracing provided for lines to prevent freezing Completes previous response of 79:031

 DALE, L.F. Mississippi Power & Light Co 80/07/22 ip
- 8010160150 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment." No written response required.

 O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/09/30 to

- 8010270565 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 to
- 8010270041 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/10 10
- G010200487 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 50-416/80-19 & 50-417/80-19 Corrective actions GC instruction issued 800822 to control calibr certification of torque multipliers MCQAUGHY, J P Mississippi Power & Light Co 80/10/13 Zpp
- 8010210531 Requests relief from inservice insp of main steam piping encl in guard pipes. Relief request describing specific relief, info to support request & safety evaluation encl DALE, F Mississippi Power & Light CO 80/10/16 Spp
- S Reportable occurrences, LERs & related correspondence
- BO10210003 Part 21 rept re testing of 1-inch diameter Kwik-Bolt mechanical expansion anchors embedded 7 5 inches deep in 4000 psi design strength concrete blocks Results indicate average tensile value of 27,500 lbs HENKEL
- 8010200710 Part 21 rept re testing of 1-inch diameter Kwik-Bolt mechanical expansion anchors Corrects previously reported data & provides precise calculations on average ultimate tensile load, std deviation.working load & risk of failure HENKEL,H L. Hilti Fastening Systems 80/09/12 Spp
- 8010020569 Part 21 rept. supplementing 800911 & 12 ltrs re defective components. Investigation in progress to determine number & location of all such components in use Cause of defect still unknown FRIEDMAN.M Hilti Fastoning Systems 80/09/17 2pp
- BOIG020603 Part 21 rept re potential defect in component of DBRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DBRV 16 & DBRV 20 built before Feb 1980 MARTINI.D H Transamerica Delaval, Inc 80/09/19 2pp
- 8010030436 Interim deficiency rept per 10CFR30.55e & 10CFR21 re indications in six three-quarter inch couplings supplied by Guyan Alloqs, Inc. Investigation continuing Final rept will be provided by 801105. MCGAUCHY, J P Mississippi Power & Light Co 80/09/25 4pp
- 8010230138 Part 21 rept re failure of pillow block bearings in standby svc water basin fans Evaluation re reportability per 10CFR30, 53s not completed Evaluation to be completed by 810106 MCGAUGHY, J P Mississippi Power & Light Co 80/09/26 3pp
- 8010060254 Interim deficiency rept re oil level indicator lines outside missils barriers Constructor coordinating w/cooling tower supplier to identify & proceed w/corrective action Final rept by 810107 Ref 100FRS0 55s & Part 21 HCQAUGHY,J P Mississippi Power & Light Co 80/09/29. 2pp
- 8010080416 Fifth interim deficiency rept re inadequate crimps on connector pins for power generation control complex interconnecting cables All GE tests have been completed Util & constructor are reviewing test results MCGAUOHY.J P Mississippi Power & Light Co. 80/09/30 3pp
- 8010210007 Part 21 rept re Kiockner-Moeller 480-volt MCG starter relay. Investigation revealed matter not reportable per 10CFR30 55e or 10CFR21. MCGAUGHY, J P Mississippi Power & Light Co. 80/10/02. 3pp
- B010160504 Final deficiency rept re damage to intermediate metallic conduit. Caused by improper use & adjustment of threading dies Training conducted re proper threading techniques & 100X insp performed on threaded metallic conduit MCQAUGHY, J P Mississippi Power & Light Co. 80/10/06 3pp
- 8010160514 Interim deficiency rept re incomplete welds at member connection points on seismic HVAC hangers Caused by contractor failure to follow design drawings. Constructor to perform corrective action.

 MCOAUDHY. J. P. Mississippi Power & Light Co. 80/10/06. 2pp

- 8010210355 Final deficiency rept re incorrect pipe supplied by TX Pipe Bending Caused by failure to meet fesign requirements Analysis revealed that heavier pipe would not affect safety implications Supplier notified MCGAUGHY,J P Mississippi Power & Light Co 80/10/10 3pp
- 8010210630 Interim Deficiency Rept PRD-B0/53 certain power generation control complex cable assemblies supplied by QE were installed incorrectly Util is working w/constructor to evaluate cause of deficiency Final rept by 810120 MCGAUGHY.J P Mississippi Power & Light Co 80/10/13 2pp
- 8010300497 Part 21 rept re Reactor Controls, Inc pipe supports Tube steel substituted for angle Pipe clamps discovered broken away from supported pipe Evaluation underway. Final rept will be filed by 810121 MCGAUGHY, J P MississippI Power & Light Co 80/10/13 3pp
- 8010310511 Part 21 rept re incorrectly ordered throttling valve Valves for LPCS & RHR sys were incorrectly purchased as shutoff type Final rept will be filed by 810121 MCGAUGHY, J P Mississippi Power & Light Co 80/10/13 3pp
- 8010210478 Interim deficiency rept re rodent damage to cable insulation Residual heat removal sys loop B jocket pump & test return valve affected Safety evaluation completed insp of other sys & equipment in progress Final rept by 801218 MCGAUGHY, J. P Mississippi Power & Light Co 80/10/16 3pp
- B010240438 Second interim deficiency rept re debris that could accumulate & clog heat exchangers in safety related sys Util reviewing proposed design changes Final rept will be submitted on B10305 MCGAUGHY, J P Minnesota Power & Light Co 80/10/20 2pp.
- 8010310517 Part 21 rept re standby dissel generator instrument tubing failure Flat caused leaks to occur during routine pressure testing Util working w/contractor to resolve deficiency. Final rept will be filed by 810305 MCGAUGHY.J P Mississippi Power & Light Co 80/10/20 4pp
- 8010310523 Part 21 rept re noncompliance of NGSS radiographs to code requirements NSSS vendor conducting evaluation Final rept will be filed by 810507 MCGAUGHY.J.P Mississippi Power & Light Co 80/10/20. 3pp.
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8010010658 Forwards preliminary responses to Reactor Bys Branch questions to aid NRC in preparation of 800923-25 meeting duestions 21: 117, 21: 157 & 21: 158 will be answered at later date Responses available in Central Files only DALE, L.F. Mississippi Power & Light Co 80/09/16 2pp
- B010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMT action plan requirements Corrected table of implementation schedule also encl EISENHUT.D G Division of Licensing 80/09/19 28pp
- 8010220235 Forwards request for add1 info re radiological controls Requests amend to FSAR to reflect responses to encl requests
 TEDEBCO.R L. Assistant Director for Licensing 80/09/22 25pp.
- 8010010669 Requests that requirement to maintain sediment basins be daleted from environ protection program since MB River is protected by NPDES Permits MBD027031 & MB0029173 DALE, L.F. Mississipsi Power & Light Co. 80/09/24. 1p
- 8010070346 Forwards response to NRC B00421 request for info on Category i masonry walls. All masonry walls in Category i bldgs are designed to requirements Oversize drawings available in Central Files only DALE, L. F. Mississippi Power & Light Co 80/10/02 22pp.
- B010140239 Forwards description of preservice exam of ABME Class I & II components & application of exclusion criteria permitted by IMB-1220 & IMC-1220 One hundred oversized flow diagrams to be recalled for filming DALE, L.F. Mississippi Power & Light Co 80/10/02 110pp
- 8010210320 Forwards request for add) info consisting of Reactor Bys Branch & QA Branch questions from review of FBAR, FBAR should be amended to reflect responses to requests TEDEBCO.R L. Assistant Director for Licensing. 80/10/02 App.

- F Security, medical, emergency & five protection plans
- 8010230331 Notification of 601021 meeting w/util.Pronto Power Corp & Science Applications.Inc in Betheed4.Md to discuss licensee approach to emergency planning requirements MARTORE.J A Licensing Branch 3 60/10/07 3pp
- H General correspondance
- B01020033B Bubmits new address for receipt of future correspondence re facilities & addition of three names for distribution list DALE, L. F. Mississippi Power & Light Co. B0/10/13 2pp
- I Financial information
- 8010200357 Forwards Pederal Financing Bank & Rural Electrification Administration 801002 commitment notice in support of application to make South MB Electric Power Association part owner of facility STAMPLEY, N L. Mississippi Power & Light Co. 80/10/16 34pp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 9010010361 Forwards Amend 43 to application for OLs, submitted as Amend 43 to FSAR & consisting of responses to NRC questions & refinements of design info MCGAUGHY, J P Mississippi Power & Light Co 90/09/30 ip.
- --8010010366 Amend 43 to application for CLs, submitted as Amend 43 to FSAR & questions & refinements re FSAR MCOAUGHY, J.P. Mississippi Power & Light Co. 80/09/30 2pp
- --8010010373 Amend 43 to FSAR.consisting of responses to NRC questions & refinements of design info Mark III containment loads rept encl

 Mississippi Power & Light Co 80/09/30 1200pp
- 8010160537 Forwards affidavit of svc for Amend 43 to FBAR per NRC 780627 ltr DALE, L F. Mississippi Fower & Light Co 80/10/10 2pp
- Q Inspection reports, IE Bulletins & correspondence
- *Oi0230069 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29 2pp.
- 010010031 Ack receipt of 800721 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-415/80-12 & 50-417/80-08 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/05 ip.
- --8010010036 Responds to NRC 800624 itr re violation noted in IE Insp Repts 50-416/80-12 & 50-417/80-08. Corrective actions appropriate documentation will be available for recording location of holes on cut reinforcing bars MCGAUCHY, J.P. Mississippi Power & Light Co. 80/07/21 3pp
- -8010010044 Forwards IE Insp Repts 50-416/80-12 & 50-417/80-08 on 800527-30 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/24 2pp
- 8010010046 Notice of violation from insp on 800527-30

 * Region 2: Atlanta, Office of the Director 80/06/24, 1p.
- 3010010057 IE Insp Repts 50-416/80-12 & 50-417/80-08 on 800527-30 Noncompliance noted unauthorized cutting of rebar. RAUSCH, J K Region 2. Atlanta. Reactor Construction & Engineering Support Branch HUNT, M.D. Region 2. Atlanta. Office of the Director 80/06/24 5pp
- .0080592 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312.Type 304 Stainless Steel Pipe." Review indicated that Type 300 series piping has not been used in specified applications at facility lALE.L F. Mississippi Power & Light Co. 80/09/15. ip.
-)150328 Responds to LE Bulletin 80-19, Revision i, re mercury-watted itrix relays in reactor protective sys Specified concerns it applicable as relays are not used in protection sys Requests extension to complete NSSS partions DALE, L. F. Mississippi Power & Light Co. 80/09/17. 19.

- B010190336 Responds to IE Bulletin 80-20 re W-2 spring return to neutral control switches Specified concerns not applicable as no switches are used in balance-of-plant safety-related sys Requests extension to complete NSSS portion of bulletin DALE, L.F. Mississippi Power & Light Co. 80/09/17 ip
- 8010080384 Responds to IE Sulletin 79-24, "Frozen Lines" Heat tracing provided for lines to prevent freezing Completes previous response of 791031 DALE, L.F. Mississippi Power & Light Co 80/09/22 1p
- 8010160150 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30
- 8010270565 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02 is
- 8010270041 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2. Atlanta. Office of the Director 80/10/10 tp
- 8010200487 Responds to NRC 800911 ltr re violations noted in IE Insp Repts 30-416/80-19 % 50-417/80-19. Corrective actions OC instruction issued 800822 to control calibr certification of torque multipliers MCOAUGHY, U.P. Mississippi Power & Light Co. 80/10/13 2pp
- B010210531 Requests relief from inservice insp of main steam piping encl in guard pipes Relief request describing specific relief, info to support request & safety evaluation encl DALE, L. F. Mississippi Power & Light Co
- 8 Reportable occurrences, LERs & related correspondence
- B010030436 Interim deficiency rept per 10CFR30 55e & 10CFR21 re indications in six three-quarter inch couplings supplied by Guyon Alloys Inc Investigation continuing Final rept will be provided by B01105 MCGAUGHY.J P Mississippi Power & Light Co B0/09/25 4pp
- 8010230139 Part 21 rept re failure of pillow block bearings in standby svc water basin fans Evaluation re reportability per 10CFR90 55e not completed Evaluation to be completed by 8101006 MCGAUGHY, J P Mississippi Power & Light Co 80/07/26 3pp
- 8010060256 Interim deficiency rept re oil level indicator lines outside missile barriers Constructor coordinating w/cooling tower supplier to identify & proceed w/corrective action Final rept by 810107 Ref 10CFR50 55e & Part 21 MCGAUGHY, J P Mississippi Power & Light Co 80/09/27 2pp
- 8010080416 Fifth interim deficiency rept re inadequate crimps on connector pins for power generation control complex interconnecting cables Ali OE tests have been completed Util & constructor are reviewing test results MCOADOHY. J P Mississippi Power & Light Co. 80/09/30 3pp
- 8010210007 Part 21 rept re Klockner-Moeller 480-volt MCC starter relay investigation revealed matter not reportable per 10CFR30 55e or 10CFR21 MCOAUDHY, J. P. Mississippi Power & Light Co. 80/10/02 3pp.
- 8010160504 Final deficiency rept re damage to intermediate metallic conduit Caused by improper use 2 adjustment of threading dies. Training conducted re proper threading techniques & 100% insp performed on threaded metallic conduit MCGAUGHY, J P Mississippi Power & Light Co 80/10/06 3pp
- 8010160514 Interim deficiency rept re incomplete welds at member connection points on seismic HVAC hangers Caused by contractor failure to follow design drawings Constructor to perform corrective action.

 MCGAUGHY, J P Mississippi Power & Light Co 80/10/06. 2pp
- BO10210355 Final deficiency rept re incorrect pipe supplied by TX Pipe Bending Caused by failure to meet design requirements. Analysis revealed that heavier pipe would not affect safety implications Bupplier notified MCGAUGHY. J P Mississippi Power & Light Co 80/10/10 3pp

1

- B010300497 Part 21 rept re Reactor Controls, Inc pipe supports Tube steel substituted for angle Pipe clamps discovered broken away from supported pipe Evaluation underway Final rept will be filed by 810121 MCGAUGHY, J P Mississippi Power & Light Co B0/10/13 3pp
- B010310511 Part 21 rept re incorrectly ordered throttling valve Valves for LPCS & RHR sys were incorrectly purchased as shutoff type Final rept will be filed by B10121 MCGAUGHY, J P Mississippi Power & Light Co B0/10/13 3pp
- 8010210478 Interim deficiency rept re redent damage to cable insulation Residual heat removal sys loop B jocket pump & test return valve affected Bafety evaluation completed Insp of other sys & equipment in progress Final rept by 801218 MCGAUOHY.JP Mississippi Power & Light Co 80/10/16 3pp
- B010240438 Second interim deficiency rept re debris that could accumulate & clog heat exchangers in safety related sys Util reviewing proposed design changes Final rept will be submitted on 810306 MC9AUGHY, J.P. Minnesota Power & Light Co. 80/10/20 Rpp
- 8010310517 Part 21 rept re standby diesel generator instrument tubing failure. Flat caused leaks to occur during routine pressure testing Util working w/contractor to resolve deficiency Final rapt will be filed by 810305 MCGAUGHY, J P Mississippi Power & Light Co 80/10/20 4pp
- 8010310523 Part 21 rept re noncompliance of NSSB radiographs to code requirements NSSB vendor conducting evaluation Final rept uill be filed by 810507 MCGAUGHY, J P Mississippi Power & Light Co 80/10/20 3pp
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D G Division of Licensing 80/09/19 28pp.
- 8010020804 Forwards 800702 NPDES renewal permit & Sections 316(a) & 316(b) approvals, issued 8006(1), to indicate util compliance w/state & federal statutes & regulations under Clean Water Act of 1977 administered by CT Dept of Environ Protection COUNSIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 80/09/22 31pp
- Q Inspection reports. IE Bulletins & correspondence
- 8010010365 Forwards IE Insp Rept 50-423/80-05 on 800718,23 & 24 No noncompliance noted CARLSO'LR T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --8010010372 IE Insp Rept 50-423/80-05 on 800718,23 & 24 No noncompliance noted. Major stess inspected licensee action on previous insp findings, facility tours pipe welding & pole crane testing FEIL.R. REYNOLDS.S. Region I, Philadelphia, Office of the Director MCOAUGHY, R W Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/14 7pp
- BO10090161 Discusses amended NRC regulations requiring CP holders to provide free access to ofc space & facility for inspersonnel Resident inspector will assume duty station by B0117 W/o encl QRIER.D H Region i, Philadelphia, Diffice of the Director. B0/02/22 1p
- 8010010701 Responds to IE Buleltin 80~19 & 80-19, Revision 1. No mercury-metted relays are used in any matrix logic applications
 CDUNGIL.() O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/05 ip
- 8010020313 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters have not been used & are not planned for use in any equipment COUNSIL.11 O Northeast Nuclear Energy Co (subs of Northeast Utilities). 80/09/08. ip
- E010240242 Forwards IE Insp Rept 50-423/80-06 on 800820-21 No noncompliance noted CARLSGN:R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/12, 2pp

- --8010240248 IE Insp Rept 50-423/80-06 on B00820-21 No noncompliance noted Major areas inspected licensee action on previous insp findings.facility tour & reactor vessel installation records review
 FEIL.R Region 1. Philadelphia. Office of the Director MCOAUCHY.R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B0/09/10 3pp
- 8010220021 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches "
 Specified switches are used in containment air circulation fans, svc water pumps & charging pumps
 COUNSIL, U G Connecticut Yankee Atomic Power Co 80/09/15 2pp
- 801024012B Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required.
 ORIER, B H Region 1. Philadelphia. Office of the Director 80/10/02 lp
- 8010280173 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director, 80/10/10 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8010010419 Ack receipt of 800730 ltr re deficiencies in design & const CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80709703. 1p
- --B010010423 final deficiency rept re design & const problems in auxiliary syc & turbine bldgs Structural changes required are result of incomplete calculational methods & models originally used COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/30. 3pp
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 201000000
- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D Q Division of Licensing 80/09/19 28pp
- G Adjudicatory correspondence
- 8010310064 Ack receipt of 800725 petition on behalf of Oxorgians Against Nuclear Energy, requesting institution of proceeding to assess need for power from facility & for suppl EIB in light of new electricity demand forecasts DENTON. H R Office of Nuclear Reactor Regulation, Director, 80/10/21 2pp
- --8010310070 Notice of 800725 petition by 0 Flack, on behalf of Georgians Against Nuclear Energy, re request for proceeding to assess power need from facility & need for suppl EIS Petition is treated as request for action per 10CFR2, 206.

 CASE, E. 0 Office of Nuclear Reactor Regulation, Director, 80/10/21 1p
- --8010310075 Informs of providing assistance toward developing appropriate response to 800925 petition by G Flackson behalf of Georgians Against Nuclear Energy, re need for power from facility & need for suppl EIS Draft documents encl.

 MURRAY, J P Office of the Executive Legal Director 80/10/15
- O Inspection reports, IE Bulleting & correspondence
- --8010170278 IE Insp Repts 80-321/80-33, 50-366/80-33, 50-424/80-11 & 50-425/80-11 on 800730-31 & 0804 No noncompliance noted.

 Major areas inspected followup on items relative to 100FR21 BRDHNLEE,Vi. Region 2, Atlanta, Office of the Director CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/21 3pp

- 8010200628 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matis"

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/29, in
- 8009300110 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications
 DUTTON.D Georgia Power Co. 80/09/16 2pp
- BO10160154 Forwards Suppl 2 to 1E Bulletin 79-01B, "Environ Gualification of Class 1E Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30. in.
- 8010270549 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required Q'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 in.
- 8010300608 Updates util 800805 response to NRC 800404 ltr re IE Bulletin 77-03A. "Langitudinal Held Defects in ABME 8A-312. Type 304 Stainless Steel Pipe " No piping identified exceeding BSX allowable design pressure stresses DUTTON, D Georgia Power Co. DUTTON, D Southern Co. Services. Inc 80/10/06. 29p
- B010290047 Forwards IE Info Notice 80-36, "Failure of Steam Centrator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/10/10.
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- B010220079 Forwards errata sheets amending B00703 itr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing B0/07/17. 28pp.
- O Adjudicatory correspondence
- B010310064 Ack receipt of 800925 petition on behalf of Georgians Appinst Nuclear Energy, requesting institution of proceeding to assets need for power from facility & for suppl EIS in light of new electricity demand forecasts DENTON.H R Office of Nuclear Reactor Regulation, Director. B0/10/21 2pp
- --8010310070 Notice of 800925 petition by 0 Flact, on behalf of Georgians Against Nuclear Energy re request for proceeding to assess power need from facility & need for suppl EIS Petition is treated as request for action per 10CFR2 206 CASE/E 0 Office of Nuclear Reactor Regulation, Director 80/10/21 ip
- --8010310075 Informs of providing assistance toward developing appropriate response to 800925 petition by G Flack, on behalf of Georgians Against Nuclear Energy, re need for power from facility & need for suppl EIB Draft documents enci.

 HURRAY, J P Defice of the Executive Legal Director 80/10/15
 4pp.
- Q Inspection reports, IE Bulletins & correspondence
- 8010170271 Forwards IE Insp Repts 50-321/80-33, 50-366/80-33, 50-424/80-11 & 50-425/80-11 on 800730-31 & 0804 No noncompliance nated MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/25 2pp
- --8010170278 IE Insp Repts 50-321/80-33.50-366/80-33.50-424/80-11 & 50-425/80-11 on 800730-31 & 0804 No noncompliance noted. Major areas inspected:followsp on items relative to 10CFR21. BROKNLEE, V. L. Region 2. Atlanta. Office of the Director. 80/08/21 3pp
- 8010200628 Forwards IE Info Notice 80-32, "Glarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls."

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/08/29, is.

- 8010160154 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/30 is
- B010270549 Forwards IE Circular B0-22, "Confirmation of Employee Qualifications" No written response required.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director B0/10/02, in
- B01030060B Updates util 800805 response to NRC 800404 ltr re IE Bullatin 79-02A. "Longitudinal Weld Defects in ABME 8A-312. Type 304 Stainless Steel Pipe "No piping identified exceeding 85% allowable design pressure stresses DUTTON,D. Georgia Power Co DUTTON,D. Bouthern Co Bervices, Inc. B0/10/04 2pp.
- 8010270047 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting." No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/10.
- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- B010220099 Forwards errats sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIBENHUT, D O Division of Licensing B0/09/19. 28pp
- G. Adjudicatory correspondence
- 8010160029 Notice of appearance in proceeding. Certificate of Svc encl BCHERR, S, J Natural Resources Defense Council B0/10/10 4pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010200656 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactiva Matts " O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/29 io.
- 8010140180 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.

 O'REILLY, J P Region 2. Atlanta, Office of the Director. 80/09/30 ig
- 8010270579 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 ip
- 8010270072 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested O'REILLY, J. P. Region 2, Atlanta, Office of the Director. BO/10/10 is.
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATHB issue Mods will be evaluated & implemented to reduce risk Program can be inclemented by 1985 at Browns Ferry, Bequoyah & Matts Bar & by fuel loading at Bellefonte. Hartsville & Phipps Bend.
 MILLERL M Tennessee Valley Authority 80/09/17. Spp
- 8010010022 Forwards request for add1 info re structural engineering to assist NRC review of application for DL Revised numbering sys established to facilitate review New sequence cross-ref enci.

 TEDESCO.R.L. Assistant Director for Licensing. 80/09/18 16pp
- 8010220099 Forwards strate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also enci. EISERHUT, D. O Division of Licensing. 80/09/19. 28pp.
- BO10090479 Summary of B00623-24 meeting w/util.B&H, & ANL in Bethesda, HD re review of drawings to determine conformance w/ separation, redundancy & single failure criteria. BOURNIA,A Operating Reactors Branch 1 B0/09/30 App

- 8010220396 Bummary of 800723-24 meeting w/util.B&W & ANL in Bethesda,MD re review of electrical/instrumentation & control drawings to determine conformance w/separation, redundancy & single failure criteria
 BOURNIA.A. Operating Reactors Branch 1 80/09/30 6pp
- 8010310400 Responds to NRC 800827 ltr re development of emergency operating procedure for ATHS event Procedure to be submitted for review six months before expected fuel loading date MILLS, L. M. Tennessee Valley Authority 80/10/24 ip.
- F Security, medical, emergency & fire protection plans
- 8010160022 Disapproves of safeguards contingency plan, until info comparable to that found in PSS-BIL 19 O. Security Matrix, is provided Requests response within 30 days YOUNOBLOOD, B J Licensing Branch i 80/10/01 2pp
- J Insurance & indemnity information
- 8010240394 Forwards Endorsement 8 to NELIA Policy NF-258 RIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Dlv 80/10/14 23pp
- 4 Inspection reports: IE Bulletins & correspondence
- 8010020772 Forwards IE Insp Rept 50-438/80-15 & 50-439/80-15 on 800722-24 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --8010020776 Notice of violation from insp on 800722-24
 * Region 2. Atlanta, Office of the Director 80/08/15, 1p.
- ---B010020780 IE Insp Rept 50-409/80-15 & 50-439/80-15 on 800722-24.

 Noncompliance noted inadequate prestressing QA/QC
 procedures

 LENAHAN, J Region 2. Atlanta, Office of the Director
 COILLON, T E Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch B0/08/15 5pp
- 8010020244 Forwards IE Insp Repts 50-438/80-18 & 50-439/80-18 on 800729-0801 No noncompilance noted MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/20 2pp
- --8010020250 IE Insp Repts 50-438/80-18 & 50-439/80-18 on 800729-0801. No noncompliance noted Major areas inspected licensee action on previous insp findings.in-place storage of diesel generator 1A & review of OA implementing procedures WATERS.D K Region 2. Atlanta, Office of the Director. COM.ON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/20, 4pp.
- 8010020774 Forwards IE Insp Repts 50-438/80-16 & 50-439/80-16 on 800628-0726 & notice of violation MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/20. 2pp.
- --8010020777 Notice of violation from insp on 800628-0726 • Region 2. Atlanta, Office of the Director. 80/08/20 ip
- --8010020779 IE Insp Repts 50-438/80-16 & 50-439/80-16 on 800628-0726. Nancompliance noted failure to perform or witness pump sheft rotation & lubrication checks & application of concrete surfacer w/relative humidity in excess of limite CANTRELL.F.S. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. WILCOX.J D Region 2. Atlanta, Office of the Director. 80/08/20. 7pp
- B010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls."

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. B0/08/29.
- 8010080391 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Nautral Control Switches." Lists eafaty-related sys using Westinghouse-type switches Addl info to be reported by 801215.
 MILLS
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-439/80-11, 50-519/80-11 & others, HURFHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/09/26, 2pp.

- --8010170123 Responds to NRC 800806 ltr re violations noted in IE Insp Repts 50-327/80-24,50-328/80-15 & others Corrective actions GA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLS.L. M Tennesses Walley Authority. 80/09/02, 14pp
- 8010160184 Forwards Suppl 2 to IE Builetin 79-018, "Environ Qualification of Class IE Equipment" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/30 to
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/02 in
- 8010150430 Responds to IE Insp Repts 50-438/80-14 & 50-439/80-14 & Region 2 800912 itr re failure to provide prompt notification of const deficiency. Formal procedures issued stressing importance of prompt reporting of deficiencies HILLS.L M Tennessee Valley Authority 80/10/06 2pp
- 8010290066 Forwards 1E Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/10/10 is.
- 8 Reportable occurrences. LERs & related correspondence
- 8010020603 Part 21 rept re potential defect in component of DBRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DBRV 12. DBRV 16 & DBRV 20 built before Feb 1980.

 MARTINI.D.H Transamerica Deleval, Inc. 80/09/19, 2pp.
- 8010150358 First interim deficiency rept re discrepancies in weld designations in detail sheats for assembly of pipe hangers & supports supplied by ITT Orinnell Held translation is being developed, Review completion expected in Dec 1780. HILLS, L.M Tennessee Valley Authority. 80/10/03. 2pp.
- 8010160533 Fourth interim deficienty rept re makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring. Mestinghouse procedure for testing motors will be performed. Next rept will be forwarded by 810216.

 MILLS.L.M. Tennessee Valley Authority. 80/10/07. 2pp.
- 8010240419 Fourth interim deficiency rept re makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring Hestinghouse procedure for testing motors will be performed, Next rept will be forwarded by 810216.

 MILLS.L.M. Tenhessee Valley Authority 80/10/07. 2pp
- 8010160536 First interim deficiency rept re potential damage to air handling units in communication room due to movement of nonqualified equipment Util is investigating results of failure of air handling units to effect on plant operation.

 MILLB,L.M. Tennessee Vailey Authority. 80/10/09. 2pp.
- 8010160579 Interim deficiency rept re questionable heat traceability for enchorhead math used in prestressing sys for primary containment. Rock anchor tendon anchorheads are involved. Addi chemical testing of anchorheads will be done. MILLS.L.M. Tennessee Valley Authority. 80/10/09. 2pp.
- 8010240436 Fifth interim deficiency rept re possible nonconservative saismic response for primary branch lines. Official B&W submittel of Revision 3 to response spectra spec anticipated Next rept to be submitted by 810208.

 MILLS, L. M. Tennesses Valley Authority. 80/10/15. ip.
- 8010210578 Third interim deficiency rept re failurs of Auma Actuator. Inc motor-operated valve operators in essential raw cooling water sys. Auma Actuator. Inc representative examined valves & raquested that valves be ratured.

 MILLS.L.M Tennessee Valley Authority 80/10/16. 2pp.
- 8010280451 First interim deficiency rept re failure to establish verification & insp measures for safety-related welding. Util is evaluating issue & impact on GA program. Next rept will be forwarded by 810306.

 MILLE, L. M. Tennessee Valley Authority. 80/10/20. Spp.
- 8010280400 Final deficiency rapt re incorrect parameters contained in data tables for flange rapt.CES-ME:-77-5. Rapt will be revised & data table recomputed, based on 1977 ABME code, by 811201. All flanges will be requalified by revised rapt MILLS.L.M. Tennessee Valley Authority. 80/10/22. 3pp.

DOCKETED ITEMS

- 3010280517 Second interim defictency rept re incorrect syc factor on nameplate on Hestinghouse motors Specs require svc factor of 1 15 Vandor documentation certifies that motors have svc factor of 1 15 nameplates will be changed.

 MILLS,L M Tennessee Valley Authority 80/10/22 2pp
- 3010280371 Final deficiency rept re const GA audit deficiency Util has retrained welders & foremen & documented training Training completed 800819 NILLS, LM Tennessee Valley Authority 80/10/23 2pp
- 3010280373 First interim deficiency rept re buttonheads on rock anchor tendons Inap of 171 Unit 1 anchor tendons reveals 33 tendons w/one or more raised buttonheads Insp of Unit 2 tendons will be parformed concurrent wifinstallation of vertical tendons MILLS, L. M. Tennessee Valley Authority 80/10/23 2pp
- OCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- Application/construction stage documents & correspondence
- 0010020480 Forwards util program for resolving ATH8 issue Kods will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry, Bequoyah & Watts Bar & by fuel loading at Bellefonte, Hartsville & Phipps Bend MILLE.L M Tennessee Valley Authority &0/09/17 Spp
- 010010022 Forwards request for addl info re structural engineering to assist NRC review of application for OL Revised numbering sys established to facilitate review New sequence
- cross-ref encl
 TEDESCO.R L Assistant Director for Licensing 80/09/18 14pp
- 010220097 Forwards errata sheets amending 900905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGENHUT.D G Division of Lucensing 80/09/19 28pp
- 010090479 Summary of 800623-24 meeting w/util.8&H, & ANL in Dethesda, MD re ravisw of drawings to determine conformance w/ separation.redundency & single failure criteria 8000RNIA.A Operating Reactors Branch 1 80/09/30 6pp.
- 01022039& Summary of 800723-24 meeting w/util.B&W & ANL in Bethesda.MD re review of electrical instrumentation & control drawings to determine conformance w/separation.redundancy & single failure criteria BOURNIA, A. Operating Reactors Branch 1 80/09/30 App
- 010310400 Responds to NRC 800827 ltr re development of emergency operating procedure for ATMS event Procedure to be submitted for review six months before expected fuel loading date.
 MILLS.L.K Tennessee Vallsy Authority 80/80/24 Ip
- Security, medical, emergency & fire protection plans
- 010160022 Disapproves of safeguards contingency plan, until info comparable to that found in PSS-SIL 17 O, Security Matrix, is provided Requests response within 30 days YOUNOBLOOD, B J Licensing Branch i 80/10/01. 2pp
- Insurance & indemnity information
- 010240394 Forwards Endorsement 8 to NELIA Policy NF-258 RIELDER, J. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc Div 80/10/14 23pp
- Inspection reports, IE Bullatins & correspondence
- 010020772 Forwards IE Insp Rept 50-438/80-15 & 50-439/80-15 on 800722-24 & notice of violation HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/08/18 2pp
- 8010020774 Notice of violation from insp on 800722-24 * Region 2. Atlanta, Office of the Director 80/0 80/08/15 1p
- 8010020760 IE Insp Rept 50-438/80-15 & 50-439/80-15 on 800722-24 Noncompliance noted inadequate prestressing QA/QC
- procedures
 LENAHAN, J J Region 2, Atlanta, Office of the Director.
 CONLON, Y E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/08/15 5pp

- 8010020244 Forwards IE Insp Repts 50-438/80-18 & 50-439/80-18 on 809729-0801 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/20 2pp
- -8010020250 JE Insp Repts 50-438/80-18 & 50-439/80-18 on 800729-0801 No noncompliance noted Major areas inspected licensee action on previous insp findings, in-place storage of dissel generator lake review of GA implementing procedures WATENS.D K. Region 2. Atlanta, Office of the Director CONLON.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/08/20. 4pp
- 8010029774 Forwards IE Insp Repts 50-438/80~16 & 50-439/80-16 on 800628-0726 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/20 2pp
- --8010020777 Notice of violation from insp on 800628-0726
 Region 2. Atlanta, Office of the Director 80/08/ 80/08/20 1p
- --8010020779 IE Insp Repts 50-438/80-16 & 50-439/80-16 on 800628-0726
 Noncompliance noted failure to perform or witness pump shaft
 rotation & lubrication checks & application of concrete
 surfacer w/relative humidity in excess of limits
 CANTRELL, F B Region 2, Atlanta, Reactor Construction &
 Engineering Support Branch WILCOX, J D Region 2, Atlanta, Office
 of the Director 80/08/20 7pp
- B010200637 Forwards IE Info Notics 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls " O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29
- 80:0080391 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Lists safety-related sys using Westinghouse-type switches, Addi info to be reported by 80:1215
 MILLS,L M Tennessee Valley Authority 80/09/16, 3pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-24, 50-323/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-439/80-11, 50-519/80-11 & others.

 MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --8010170123 Responds to NRC 800806 ltr re violations noted in IE Insp Repts 50-327/80-24,50-328/80-15 & others Corrective actions GA audits have been reviewed to identify any conclusions & recommendations found to be de
- 8010160184 Forwards Suppl 2 to IE Builetin 79-018, "Environ Gualification of Class IE Equipment " No written response D'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/30
- 8010270530 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications" No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/10/02
- 8010190430 Responds to IE Insp Repts 50-438/80-14 & 50-439/80-14 & Region 2 800912 ltr re failure to provide prompt notification of const deficiency Formal procedures issued stressing importance of prompt reporting of deficiencies, MILLS.L M Tennessee Valley Authority 80/10/04 2pp.
- 8010270066 Forwards IE Info Notice 80-36. "Failure of Steam Generator Busport Bolting " No specific action or response requested D'REILLY.J.F Region 2. Atlanta, Office of the Director. 80/10/10
- S Reportable occurrences, LERs & related correspondence
- 801013035B First interim deficiency rept re discrepancies in weld designations in detail sheets for assembly of pipe hangers & supports supplied by ITT Grinnell Weld translation is being developed. Review completion expected in Dec 1980
 MILLS.L M Tennessee Valley Authority 80/10/03, 2pp.
- 8010160533 Fourth interim deficiency rept re makeup & purification & decay heat removal pump motors w/damaged thermocouple wiring Hestinghouse procedure for testing motors will be parformed Next rept will be forwarded by 810216 MILLS.L M Tennessee Vailey Authority 80/10/07 2pp

- 8010160536 First interim deficiency rept re-potential damage to air handling units in communication room due to movement of nonqualified equipment Util is investigating results of failure of air handling units & effect on plant operation MILLS.L M. Tennessee Valley Authority 80/10/09 2pp
- 8010160577 Interim deficiency rept re questionable heat traceability for anchorhead matl used in prestressing sys for primary containment Rock anchor tendon anchorheads are involved Addl chemical testing of anchorheads will be done MILLS.L M Tennessee Valley Authority 80/10/09 2pp
- 8010240436 Fifth interim deficiency rept re possible nonconservative seismic response for primary branch lines Official BtW submittel of Revision 3 to response spectra spec anticipated Next rept to be submitted by 810208 NILLS,L M Tennessee Valley Authority 80/10/15 ip
- 801021057B Third interim deficiency rept re failure of Auma Actuator, Inc motor-operated valve operators in essential raw cooling water sys Auma Actuator. Inc representative examined valves & requested that valves be returned MILLS,L M Tennessee Valley Authority 80/10/16 2pp
- 8010280451 First interim deficiency rept re failure to establish verification & insp measures for safety-related welding Util is evaluating issue & impact on GA program Next rept will be forwarded by 810306
 HILLS-L M Tennessee Valley Authority 80/10/20 2pp
- 8010280400 Final deficiency rept re incorrect parameters contained in data tables for flange rept.CEB-ME1-77-5 Rept will be revised & data table recomputed based on 1977 ASME code.by 811201 All flanges will be requalified by revised rept MILLS.L If Tennessee Valley Authority 80/10/22 3pp
- 8010280617 Second interim deficiency rept re incorrect syc factor on nameplate on Westinghouse motors Specs require syc factor of 1 15 Vendor documentation certifies that motors have syc factor of 1 15) nameplates will be changed MILLS.L M Tennessee Valley Authority 80/10/22 2pp
- S0102B0371 Final deficiency rept re const QA audit deficiency.Util has retrained welders & foremen & documented training Training completed B00815
 MILLS,L M Tennessee Valley Authority 80/10/23 2pp.
- 6010280373 First interim deficiency rept re buttonheads on rock anchor tendons. Insp of 171 Unit 1 anchor tendons reveals 33 tendons w/one or more raised buttonheads Insp of Unit 2 tendons will be performed concurrent w/installation of vertical tendons MILLS.L M Tennessee Valley Authority 80/10/23 2pp
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIGENHUT, D O Division of Licensing 80/09/19 28pp
- B010150116 Confirmation of 801001 meeting w/util in Cleveland.DH to discuss NRC evaluation of licensee performance for Jul 1979-June 1980 KEPPLER, J G Region 3, Chicago, Office of the Director. 80/09/24
- C Utility Environmental Report (ER), amends & correspondence
- 8010270331 Forwards OL stago environ rept for acceptance review scheduled to begin in Feb 1781 w/completion scheduled for Apr 1791 W/o encl HOUSTON, M D Licensing Branch 2 FIN A-2118 80/10/15 1p
- H. Utility Final Bafety Analysis Report (FBAR) & amends
- 8010100035 Forwards FBAR prepared by INEL for acceptance review Completion date tentatively scheduled for 801101. W/o encl HOUSTON, M D Licensing Branch 2 80/07/25 ip
- 8010200711 Ack receipt of util 800918 FBAR per licensing application requirement NRC review will be completed by 801201 HOUSTON: M D Licensing Branch 2 80/10/03 2pp

- @ Inspection reports, IE Bulletins & correspondence
- 8010010427 Forwards IE Insp Repts 50-440/80-11 & 50-441/80-10 on 800805-07 No nuntempliance mated FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/28 2pp
- --B010010432 IE Insp Repts 50-440/80-11 & 50-441/80-10 on 800805-07 No noncompliance noted Major areas inspected records associated w/installation & insp of selected IE cable trays & supports LEE.R L Region 3. Chicago, Reactor Construction & Engineering Support Branch, HAYES, D W Region 3. Chicago, Office of the Director SO/08/25 7pp
- 8010090115 Responds to 1E Bulletin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches "

 Specified switches are not utilized in safety-related
 circuit design in facilities

 DAVIDSON, D. R. Claveland Electric Illuminating Co. 80/09/04 ip
- B010090139 Clarifies B00804 response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe "Reactor vessel piping is fabricated from 8A-312 or A-312 matl Review will be completed by 800930 DAVIDSON, D R Cleveland Electric Illuminating Co 80/09/08. 80/09/08, 1p
- 8010030294 Responds to request for add1 info re IE Bulletin 80-07, "BWR Jet Pump Assembly Failure " Beam failures resulted from intergranular stress corrosion cracking OE recommends reduction in preload on jet pump beams & insp of beams DAVIDSON.D R Cleveland Electric Illuminating Co 80/09/25 2pp
- 8010240070 Bubmits addl info in response to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe." All piping in question is subj to stress levels less than 85% of code allowable DAVIDEON, D.R. Cleveland Electric Illuminating Co. 80/09/29. ip
- 80i0i60R82 Forwards Suppl 2 to IE Builetin 79-0iB, "Environ Gualification of Class IE Equipment." No written response KEPPLER, J @ Region 3, Chicago, Office of the Director 80/07/30
- 8010280650 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/10/02
- 8010270023 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested.

 KEPPLER.J G. Region 3, Chicago, Office of the Director 80/10/10.
- 8010280033 Forwards IE Insp Repts 50-440/80-21 & 50-441/80-19 on 800930-1002 No noncompliance noted. FIDRELLI, Q. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/10/15. 2pp
- --8010280058 IE Insp Repts 50-440/80-21 & 50-441/80-19 on 800930-1002
 No noncompliance noted Major areas inspected licenses action
 on previous item of noncompliance response to IE bulletins
 & circulars & ongoing site const activities
 KONKLIN.JE. HOUSTON.H D. WILLIAMS,C O. Region 3, Chicago,
 Office of the Director. 80/10/14 App
- B Reportable occurrences. LERs & related correspondence
- 8010020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in angine failure Defect limited to models DSRV 12.DSRV 16 & DSRV 20 built before Feb 1980 MARTINI.D H Transamerica Delaval, Inc. 80/09/19 2pp
- 8010030370 Final deficiency regt re Cutler-Hammer motor control ctrs Manufacturer will rewire motor control ctrs, replace improper saddle clamps & test & replace splice plate carriage bolts Estimated date of completion is 810227 DAVIDSON: D R Cleveland Electric Illuminating Co 80/09/29. 3pp
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800903 ltr which provided preliminary clarification of TME action plan requirements Corrected table of implementation schedule also encl. EISENHUT.D.O Division of Licensing. 80709/19 28pp.

- 8010130116 Confirmation of 801001 meeting u/util in Cleveland OH to discuss NRC evaluation of licensee performance for Jul 1979-June 1980
 - KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/26
- C Utility Environmental Report (ER), amends & correspondence
- 8010270331 Forwards DL stage environ rept for acceptance review scheduled to begin in Feb 1781 w/completion scheduled for Apr 1781 W/o encl HOUSTON.H D Licensing Branch 2 FIN A-2118 80/10/15 1p
- K Utility Final Safety Analysis Report (FEAR) & amends
- 8010100035 Forwards FBAR prepared by INEL for acceptance review Completion date tentatively scheduled for 801101 H/o encl HOUSTON-K D Licensing Branch 2 89/07/25 ip
- 8010200711 Ack receipt of util 800918 FBAR per licensing application requirement NRC review will be completed by 801201 HOUSTON-M D Licensing Branch 2 80/10/03 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8010010427 Forwards IE Insp Repts 50-440/80-11 & 50-441/80-10 on 800805-07 No noncompliance noted FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/28 2pp
- --8010010432 IE Insp Repts 50-440/80-11 & 50-441/80-10 on 800805-07 No noncompliance noted Major areas inspected records associated w/installation & insp of selected IE caple trays & supports LEE.R L Region 3. Chicago. Reactor Construction & Engineering Support Branch HAYES.D W Region 3. Chicago. Office of the Director 80/08/25 7pp
- 80i0090115 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Specified switches are not utilized in safety-related circuit design in facilities DAVIDSON D R Cleveland Electric Illuminating Co 80/09/04 ip
- 8010090139 Clarifies B00804 response to IE Bulletin 79-03A,
 "Longitudinal Weld Defects in ABKE SA-312, Type 304 Stainless
 85 eel Pipe " Reactor vessel piping is fabricated from SA-312
 or A-312 math Raview will be completed by 800930
 DAVIDSON, D.R. Cleveland Electric Illuminating Co 80/09/08 ip
- 8010030276 Responds to request for add1 info re IE Bulletin 80-07. "BWR Jet Pump Assembly Failure " Beam failures resulted from intergranular stress corrosion cracking OE recommends reduction in preload on jet pump beams & insp of beams.

 DAVIDSON.D.R Cleveland Electric Illuminating Co. 80/09/25 2pp.
- 8010240070 Submits add1 info in response to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Fipe "All piping in question is subj to stress levels less than 95% of code allowable BAVIDSON. D R Cleveland Electric Illuminating Co 80/09/29 ip
- B010160282 Forwards Suppl 2 to IE Bulletin 77-018, "Environ Qualification of Class IE Equipment" No written response required.

 KEPPLER, J 0 Region 3, Chicago, Office of the Director B0/09/30 ip.
- 8010280650 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/10/02 1p.
- 8010290023 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested. KEPPLER, J. O Region 3, Chicago, Office of the Director. 80/10/10, ip.
- 8010280053 Forwards IE Insp Repts 50-440/80-21 & 50-441/80-19 on B00930-1002 No noncompliance noted FIORELLI, Region 3, Chicago: Reactor Construction & Engineering Support Branch B0/10/15 Zpp
- --8010280058 IE Insp Repts 50-440/80-21 & 50-441/80-19 on 800930-1002. No noncompliance noted Major areas inspected licensee action on previous item of noncompliance response to IE bulletins & circulars & engoing site const activities. KONKLIN.J.E. HOUSTON.M.D., WILLIAMS.C G. Region 3, Chicago, Office of the Director 80/10/14. App.

- 8 Reportable occurrences, LERs & related correspondence
- 8010030370 Final deficiency rept re Cutier-Hammer motor control ctrs Manufacturer will rewire motor control ctrs replace improper saddle clamps & test & replace splice plate carriage bolts Estimated date of completion is 810227 DAVIDSON.D R Cleveland Electric Illuminating Co 80/09/29 3pp
- DOCKET 50-449 SEADROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010280481 Requests add1 fee remittance within 15 days of 1tr receipt re 790816 application for changes to CPPR-135 & CPPR-136 MILLER,W O License Fee Management Branch 80/10/09 1p
- G Adjudicatory correspondence
- 80:00:00:005 Order setting principle & initial procedure re remanded proceeding per Commission 80:07:25 order.CLI-80-33, acting upon New England Coalition on Nuclear Pollution petition for review Memoranda re evidence must be filed by 80:10:17 TGKPKINS.B A. Atomic Safety and Licensing Appeal Panel 80/09/27 3pp
- 8010080420 Requests that M Ferrar be reinstated as member of ASLAP WEI88.E.R Sheldon, Harmon & Weiss 80/10/03 1p
- 8010210471 Requests notification of NRC hearings re facility evacuation plans Requests opportunity to testify at hearing.
 8ANDERS,N L Sanders & McDermott 80/10/13 1p
- 8010170351 Informs of Commission 800725 reversal of ASLAB determination of seisalc issues in CP proceeding ASLAB must reopen record to take evidence re Chinnery methodology & consistency of NRC methodology Suspension of const not ordered SHAPAR.H K Office of the Executive Legal Director. 80/10/15 2pp
- 8010270433 Responds to ASLAB 800929 order re hearing reopening & Farrar resignation Requests Farrar be reinstated due to knowledge of issue, or entire panel be changed to experts in geology & seismology.

 WEINHDLD, E. H. Affiliation Unknown 80/10/15 2pp
- 8010220547 Memorandum in response to ASLAB 800929 order re anticipated evidence Will present expert witnesses re M Chinnery conclusion No direct case will be given re NRC methodology but reserves right to cross-examine W/Certificats of Svc DIONAN.T.O. GAD,R K Public Service Co of New Hampshire DIONAN.T O Ropes & Gray 80/10/16 4pp
- 8010210249 Memorandum in response to ASLAB 800929 order.identifying nature & scope of NRC testimony re seismic issues Advises of 810215 as estimated filing date Does not object to State of NH as location Myappearance & Certificate of 8vc LESBY, R P Hearing Branch 3 80/10/17. 6pp
- 8010210260 Memorandum on add1 seismic evidence, requesting that ACRB provide MD Trifunac as witness Urges certification to Commission if ABLAB rejects approach Certificate of Svc enci
- enci
 enci
 WEISS,E R , JORDAN, W.S New England Coalition on Nuclear Pollution,
 WEISS,E R Bheldon, Harmon & Weiss 80/10/17 7pp.
- B010220339 Order advising parties to respond to New England Coalition on Nuclear Pollution request to call MD Trifunac as ASLAB witness by 801024 if desired on remanded seismic issues. BISHOP.C J. Atomic Safety and Licensing Appeal Panel. 80/10/20 2pp
- 8010270513 Response in opposition to New England Coalition on Nuclear Power request to call MD Trifunac as ABLAB witness. Witness may be called if util rights of cross-examination are protected Certificate of Svc encl
 DIGNAN.T. Q. GAD.R K Public Bervice Co. of New Hampshire
 DIGNAN.T G Ropes & Gray 80/10/21 3pp
- 8010270452 Ack receipt of Pulley 801010 ltr in response to request for M Farrar resumed participation as ASLB member on remand of seismic issues for facility Reiterates request for M Farrar participation in proceedings
 WEISS, E.R. Bheldon, Harmon & Weiss 80/10/22, 1p.
- 8010280011 Response in support of New England Coalition on Nuclear Pollution request to call MD Trifunac as ASLAB witness Tastimony should be filed in advance Witness must be suby to cross-examination. Centificate of Svc

- BO10300581 Notice of reconstitution of ASLAB in CP proceeding AS Rosenthal, chairman & JH Buck & WR Johnson, members BISHOP, C J Atomic Safety and Licensing Board Panel 80/10/27 ip
- 8010300583 Ack receipt of 801022 ltr directed to AS Rosenthal Contents already discussed following 801003 ltr WR Johnson assigned as member in ASLAB instead of MC Farrar BISHUP,C J Atomic Safety and Licensing Appeal Panel 80/10/27

- BO10100100 Requests response to G Dow ltr re evacuation planning around facility
 MAYROULES, N House of Reg , Science & Technology 80/08/01
- --B010100102 Requests comment on encl 0 Dow concerns about evacuation planning around facility
 HAVROULES,N House of Rep , Science & Technology B0/07/14 4pp
- 8Diol00110 Responds to 800829 ltr re evacuation plans for areas surrounding facility Regulations on emergency planning have been expanded to include requirements for evacuation planning to distances of 10 miles before issuances of DL DENTON-H R Defice of Nuclear Reactor Regulation, Director planning to dis DENTON, H R DO
- -- 8010100113 Requests consideration of health concerns in formulating evacuation plans
 WilDE,FE Affiliation Unknown 80/08/29 2pp
- 8010070444 Responds to 80080! Itr re 0 Dow concerns about facility evacuation time estimates for installation of notification sys for public Licensee will be required to have evacuation time estimates reviewed by local officials DIRCKS.W J Office of the Executive Director for Operations 80/09/27 2pp
- ④ Inspection reports, IE Bulletins & correspondence
- 8010030014 Forwards IE Insp Repts 50-443/80-08 & 50-444/80-08 on BOO703 consisting of mpt meeting CARLSON,R Y Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/20 ip
- --8010030017 IE Insp Repts 50-449/80-09 \$ 50-444/80-09 an 800703 No Ologodolf IE insp Repts 50-443/80-08 to 50-444/80-08 on 800/03 No moncompliance noted Major areas inspected meeting re-const status; resident insp program,NRC independent measurements program, deficiency reporting & QA program deficiency reporting & QA program HCOAUQHY,R H, CERNE,A C Region 1, Philadelphia, Office of the Director CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/19, 2pp
- B010020082 Responds to IE Bulletin 80-16 No Rossmount Model 1151 or 1152 pressure transmitters in use in safety-related applications DEVINCENTIS, J Public Service Co of New Hampshire 80/08/21
- 8010030539 Responds to IE Bulletin 80-20 No Westinghouse Type W-2 control switches used in safety-related applications DEVINCENTIS, J Public Service Co of New Hampshire 80/08/22 ip
- 8010010497 Responds to IE Bulletin 80-19 & 80-19 Revision i
 Mercury-wetted relays are used in protection sys equipment
 Relays are hermetically sealed not used in matrix logic
 applications & not used in scram circuits.

 DEVINGENTIB, J Public Service Co. of New Hampshire 80/08/27 ip
- 8010300127 Forwards Suppl 2 to IE Bulletin 77-018. "Environ Qualification of Class IE Equipment." No written response required
 GRIER.B.H Region 1, Philadelphia, Office of the Director
 80/09/30, 1p
- 80/0240155 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director. 80/10/02 1p
- 8010280160 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested. GRIER.B H Region 1, Philadelphia, Office of the Director B0/10/10

- 8 Reportable occurrences, LERs & related correspondence
- B010200697 Ack receipt of 800821 interim deficiency rapt re rod drop CARLBON, R T Region 1, Philadelphia, Reactor Construction &
- ---B010200700 Interim deficiency rept on rod drop analysis advising that
 Hestinghouse topical rept will not be available until Sept
 1980 Util will submit final rept by Dec 1980
 DEVINCENTIS. J. Public Service Co. of New Hampshire 80/08/21
- 8010200703 Ack receipt of 800825 final deficiency rept to use of invalid seismic amplified response spectra GARLSON:R T Region L. Philadelphia, Reactor Construction & Engineering Support Branch 80/09/13 ip
- --8010200707 Final deficiency rept to use of invalid seismic amplified response data Corrective actions containment bldg annular steel frame redesigned to increase rigidity & long-term audit of all seismic Category I says will be conducted DEVINCENTIS. J Public Service Co of New Hampshire 80/08/28
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 801028048: Requests addl for remittance within 15 days of ltr receipt re 7903:6 application for changes to CPPR-135 & CPPR-136 MILLER.W O. License Fee Management Branch 80/10/09 ip
- O Adjudicatory correspondence
- 6010010005 Order setting principle & initial procedure re remended proceeding per Commission 800925 order:CLI-80-33, acting upon New England Coalition on Nuclear Pollution petition for review Memoranda re evidence must be filed by 601017 TOMPKINS:8 A Atomic Safety and Licensing Appeal Panel 80/09/29
- 80100B0420 Requests that M Farrar be reinstated as member of ASLAP WEISS, E R Sheldon, Harmon & Weiss 80/10/03, ip
- B01021049: Requests notification of NRC bearings re facility evacuation plans Requests opportunity to testify at hearing BANDERB, N L. Banders & McDermott B0/10/13 ip
- 8010170351 Informs of Commission B00928 reversal of ABLAB determination of seismic issues in CP proceeding ABLAB must reopen record to take evidence re Chinnery methodology & consistency of NRC methodology Suspension of const not ordered BHAPAR, H K Office of the Executive Legal Director 80/10/15, 2pp
- 8010270433 Responds to ASLAB 800929 order re hearing reopening & Farrar resignation Requests Farrar be reinstated due to knowledge of issue, or entire panel be changed to experts in geology & seismology WEINHOLD, E.H. Affiliation Unknown 80/10/15 2pp.
- B010220947 Hemorandum in response to ASLAB 800929 order re anticipated DIGMAN,T O Ropes & Gray BO/10/16 4pp
- 8010210249 Hemorandum in response to ABLAB 800929 order.identifying nature & scope of NRC testimony re seismic issues. Advises of 810215 as estimated filing date Does not object to State of NH as location W/eppearance & Certificate of Byc LESSY.R P Hearing Branch 3 80/10/17 6pp.
- B010210260 Memorandum on addl seismic evidence, requesting that ACRS provide MD Trifunac as witness Urges certification to Commission if ABLAB rejects approach Certificate of Svc WEIBS, E.R., JORDAN, W.S. New England Coalition on Nuclear Pollution. WEIBS, E.R., Sheldon, Harmon & Weist 80/10/17 7pp
- 8010220339 Order advising parties to respond to New England Coalition on Nuclear Pollution request to call MD Trifunac as ASLAB witness by 801024 if desired on remanded seismic issues BIBHOP:C J Atomic Barety and Licensing Appeal Panel. 80/10/20.

- 8010270513 Respanse in opposition to New England Coalition on Nuclear Power request to call MD Trifunac as ASLAB witness Witness may be called if util rights of cross-examination are protected Certificate of Svc encl
 DIGNAN.T O , QAD.R K Public Service Co of New Hampshire
 DIGNAN.T O Ropes & Gray 80/10/21 3pp
- 8010270452 Ack receipt of Pulley 801010 ltr in response to request for M Farrar resumed participation as ASLB member on remand of seismic issues for facility Reiterates request for M Farrar participation in proceedings WEI83,E R Sheldon, Harmon & Weies 80/10/22 lp
- 8010280011 Response in support of New England Coalition on Nuclear Polition request to call MD Trifunac as ASLAB witness. Testimony should be filed in advance Witness must be subj to cross-examination Certificate of Byc en
- 8010300581 Notice of reconstitution of ASLAB in CP proceeding: AB Rosenthal chairman & JH Buck & WR Johnson members BIGHOP, C J Atomic Safety and Licensing Board Panel 80/10/27 ip
- 8010300683 Ack receipt of 801022 itr directed to AB Rosenthal Contents already discussed following 801003 itr WR Johnson assigned as member in ASLAB instead of MC Farrar 816HOPrC J Atomic Safety and Licensing Appeal Panel 80/10/27

- BO1010010D Requests response to 0 Dow 1tr Te evacuation planning around MAVROULES, N House of Rep , Science & Technology, 80/08/01 1p
- --B010100102 Requests comment on encl 0 Dow concerns about evacuation planning around facility MAVRQULES,N House of Rep , Science & Technology 80/07/14 App.
- 8010100110 Responds to 800829 ltr re evacuation plans for areas surrounding facility Regulations on emergency planning have been expanded to include requirements for evacuation planning to distances of 10 miles before issuances of DL. DENION:H R Office of Nuclear Reactor Regulation, Director 80/09/24 200 299 80/09/26
- --B010100113 Requests consideration of health concerns in formulating evacuation plans WILDE,F E Affiliation Unknown 80/08/29 2pp
- B010070444 Responds to BCOBO1 itr re Q Dow concerns about facility evacuation time astimates for installation of notification sys for public Licensee will be required to have evacuation time estimates reviewed by local of time estima, DIRCKS-N J O
- G Inspection reports, IE Bulletins & correspondence
- 8010030016 Forwards IE Insp Repts 50-443/80-08 & S0-444/80-08 on 800703 consisting of mgt meeting CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/20 ip
- --B010030017 IE Insp Repts 50-443/80-08 & 50-444/80-08 on 800703.No noncompliance noted. Major areas inspected meeting re-const status, resident insp program, NRC independent measurements program, deficiency reporting & GA program MCOAUGHY, R W., CERNE, A C. Region i, Philadelphia, Office of the Director CARLSON, R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- 80:0020082 Responds to IE Sulletin 80-14 No Rosemount Model 1151 or 1152 pressure transmitters in use in safety-related applications
 DEVINGENTIS, J. Public Service Co. of New Hempshire 80/08/21 ip
- 8010030539 Responds to IE Bulletin 80-20 No Westinghouse Type W-2 control switches used in safety-related applications.

 DEVINCENTIS.J Public Service Co of New Hampshire. 80/08/22 lp
- 8010010697 Responds to IE Bulletin 80-19 & 80-19. Revision (Mercury-wetted relays are used in protection sys equipment Relays are hermetically sealed not used in matrix logic applications & not used in screm circuits. DEVINGENTIS, J Public Service Co of New Hampshire. 80/08/27 ip

- 8010300127 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/30
- 8010240155 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required ORIER, B. H. Region i, Philadelphia, Office of the Director 80/10/02 ip
- 8010280160 Forwards IE lnfo Notice 80-36. "Failure of Steam Ownerator Support Bolting " No specific action or response requested ORIER B H Region 1. Philadelphia, Office of the Director 80/10/10 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8010200697 Ack receipt of 800821 interim deficiency rept re rod drop analysis CARLEON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/15 1p
- --8010200700 Interim deficiency rept on rod drop analysis advising that Hestinghouse topical rept will not be available until Sept 1980 Util will submit final rept by Dec 1980 DEVINCENTIS, J Public Service Co of New Hampshire 80/08/21
- 8010200703 Ack receipt of 800828 final deficiency rept re use of invalid seismic amplified response spectra CARLEON,R T Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch 80/09/15 ip
- --B010200707 Final deficiency rept re use of invalid saismic amplified response data Corrective actions containment bldg annular steel frame redesigned to increase rigidity & long-term audit of all seismic Category I sys will be conducted DEVINCENTIS.J Public Service Co of New Hampshire B0/08/28 300
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 1 A Application/construction stage documents & correspondence
- 8010220099 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EIBENHUT, D 0 Division of Licensing 80/09/19 28pp
- 8010010554 Forwards HJ Oruy & Associates, Inc 800915 ltr w/info for update to FBAR Info includes well data on well within 5-mile radius of plants Supercedes rept submitted on 800523 Oversite drawing encl FEIST, C K Texas Utilities Co 80/09/22 iipp
- --- 8010010537 "Natural Gas & Dil Pipelines & Wells Within 5-Miles of Commenche Peak " # H J Gruy & Associates, Inc 80/09/22 ip
- 8010010556 Forwards comments & recommendations re draft NUREQ-0696 & proposed implementation schedule Encl comments reflect serious reservations re implementation schedule for emanyancy response facilities after final rept is issued SCHMIDT.H C Teyes Utilities Bervices. Inc 80/09/24 3pp.
- 8010150186 Notification of 801021-23 meeting w/util in Olen Rose, TX to assess const completion schedules, BURWELL, S.B. Licensing Branch 2 80/10/01 App
- 8010270025 Notification of 801015 meeting w/util in Bathesda, ND to discuss design changes being considered for facility in response to boron dilution transients
 BURWELL-8 B Licensing Branch 2 80/10/08 2pp
- 8010300440 Bummary of 800825 mgt level meating w/util in Bethesda: HD restatus & actions needed to complete TMI-2 requirements eafety review
 BURNELL-8.8 Licensing Branch 2, 80/10/08 5pp
- B010300558 Summary of B00826 meeting w/utils in Bethesda:MD re requirement for onsite technical support ctr. BURWELL:S.B Licensing Brench 2 80/10/17 6pp.

- C Utility Environmental Report (ER), amends & correspondence
- B010010532 Forwards Amend 1 to environ rept Amend includes responses to request for add1 info ½ anviron rept update requested by NRC 800827 Itr Affidavit enci OARY, R J Teras Utilities Generating Co 80/09/17. 2pp
- --B010010533 Amend i to environ rept

 4 Texas Utilities Generating Co 80/09/30 300pp
- BD10060264 Forwards affidavit of svc re Amend 1 to facility environ rept. CL stage BCCH1DT. H C Texas Utilities Generating Co 80/09/29 9pp
- B010080476 Forwards NOAA vecord of seismic activity, in response to NRC Question 79 re Amend 1 to environ rept WERNER, R Terms Utilities Bervices, Inc. 80/10/01. 12pp
- F Security, medical, emergency & fire protection plans
- 8010150391 Forwards presentation of assumptions, methodology & tabulation of BTP 95-1. App Accompliances currently being used to establish fire protection program FSAR will be arended to reflect updated fire hazards analysis GARY. R J Texas Utilities Generating Co 80/10/08 11pp
- O Adjudicatory correspondence
- BOOS140419 Forwards NRC mamorandum on ALAB-590 & applicability to admissibility of contentions Recommends mod of proposed GA/GC contention to fully address intervenors' concerns Centificate of Svc anci ROTHECHILD, M. U., TURK, S. E., Hearing Branch 1, 80/05/12, 3pp.
- --8005140440 Memorandum on ALAB-570 & applicability to admissibility of contentions ALAB-570 supports Citizens for Fair Util Regulation Contention 2 A & & Association of Community Organizations for Reform Now Contentions 4.7.15 & 20 ROTHBCHILD, M U Hearing Branch 1 80/05/12 Spp
- --8005140447 Discusses issuance of ASLAB 800422 decision re FH Potthoff appeal from denial of potition to intervene Decision reaffirms settled & sensible interpretation of section re basis for contentions Certificate of Svc encl ROBENTHALA, 8 Atomic Safety and Licensing Appeal Panel 80/05/02 4pp
- 8010020073 Forwards App A inadvertently smitted from TX Border Cooperative 800994 comments on proposed settlement O'NEIL.R.A Miller Balis & O'Heil 80/09/25. 9pp
- B010020727 Notion to compel Citizens for Fair Util Regulation to respond to applicants 800813 first set of interrogatories & request to produce documents Clarifies certain interrogatories Certificate of Svc encl REVNOLDB,NS, HORIN,NA Texas Utilities Generating Co 80/09/30
- 8010070562 Response supporting applicants' 800912 motion to compel if TX Association of Community Organizations for Reform Now reflyses to respond to interrogatories Urges reasonable extension until 801002 Certificate of 8 byc encl ROTHSCHILD,M U Hearing Branch 1 80/10/02 10pp
- B010140015 Response in opposition to applicant 800918 motion to compel. Facts do not support applicant re number of interrogatories objected to Requests protective order re answers to applicant first interrogatories W/Certificate of Svc ELLIB, J. Citizens Association for Sound Energy 80/10/02 12pp
- BO10090PA3 Response in opposition to Citizens for Fair Util Regulation B0091B motion for protective order re applicants' discovery requests Pending mod of ASLB 800616 order has no bearing on Contentions 2,5,7 & B N/Certificate of Bvc.
 REYNOLDS.N S., HORIN,M A Total Utilities Generating Co
 REYNOLDS.N S. Debevoise & Liberman 80/10/03 14pp.
- 8010140515 Response in support of applicant 800918 motion to compal Citizens Association for Sound Energy to respond to interrogatories, except those dealing w/extension of time. Certificate of Svc encl ROTHECHILD, M U Operations & Administrative Division. 80/10/08. 13pp
- 80(0150008 Response in opposition to Citizens for Fair Util Regulation 800918 motion for protection. No good cause established for relief sought Certificate of Svc encl ROIHECHILD: M U Operations & Administrative Division 80/10/09 120a.

- B010200690 Request for 10-day extension to suppl response to applicant 800918 motion to compel in order to allow intervenor access to ASLB & ASLAB 1978 & 1979 decisions Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 80/10/14. App
- 8010210503 Response in opposition to Citizens Association for Sound Energy 801002 motion for protective order re applicants' discovery Intervenor failed to identify interrogatories for which relief is sought Certificate of Svc encl REYNOLDB.N S , HORIN.W A Texas Utilities Generating Co REYNOLDS.N S Debavoise & Liberman 80/10/17 18pp
- B010220314 Response in support of applicants' 800930 motion to compel Citizens for Fair Util Regulation response to interrogatories. except Interrogatory & Seconds motion requiring suppl to prior response Certificate of Svc encl ROTKSCHILD. N. U. Hearing Branch 1 80/10/20 24pp
- 8010240059 Response in opposition in part to Citizens Association for Sound Energy 801002 motion to compel & mation for protective order Takes no position on roquest re alleged misstatements by applicants (sertificate of Svc enc) ROTHSCHILD.M U Hearing Branch 1 80/10/22 App
- 8010280678 Forwards NRC 801008 response to applicants' motion to compel served on all parties on B01008 W/o enci ROTHSCHILD, M U Hearing Branch 1 80/10/23 ip
- 8010310436 Response stating no objection to Citizens Association for Bound Energy 805014 motion for add1 time to suppl response re applicants' 800918 motion to comps! Does not oppose availability of NRC 1978-80 issuances H/Certificate of Svc. REYNOLDS:N S . HORIN,W A Texas Utilities Generating Co. REYNOLDS:N S . Pobevoise & Liberman 80/10/28 App
- H General correspondence
- 8010090532 FOIA request for all available info re Comenche Peat Life Force or any affiliate organizations Affidavit authorizing Center for Law in Public Interest to make request on behalf of Commanche Peak Life Force encl BELIN.A Center for Law in the Public Interest 80/09/16 3pp
- 8010090328 Responds to FOIA request for all available info re Comanche Peak Life Force or any offiliate organizations MRC has no files indexed or maintained under subj organization. W/o encl listing of TX PDRs FELTON, J N Division of Rules and Records 80/10/01 ip
- 8010300033 Advise; that 800430 prehearing conference transcript has been placed in mini-LPDR ROTHBCHILD; M U Hearing Branch i 80/t0/24, ip
- ---B010330036 Forwards 800430 prehearing conference transcript to be placed in LPDR for public insp W/o encl SDUDER.J L. Division of Rules and Records 80/10/20 ip.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010200343 Forwards Amend 12 to FSAR & emergency plan Affidavit encl OARY, R J Taxas Utilities Generating Co 80/10/08 2pp
- --B010200346 Amend 12 to FBAR
 * Texas Utilities Generating Co. B0/10/08 500pp
- ~-8010200347 Facility emergency plan a Taxas Utilities Generating Co 80/10/08 100pp
- M Antitrust correspondence
- 8007230171 Notification of centract execution. Med 4 to "Engineering Assistance Re Hearings for South TY Antitrust & Commanche Peak Antitrust Proceedings "
 HAIRSTON, C A Technical Assistance Contracts Branch FIN B-6523-80/08/20 1p
- --8009230181 Mod 4, changing scope of work, to "Engineering Assistance Re Hearings for Bouth TX Antitrust & Comanche Peak Antitrust Proceedings." * R II Beck & Associates GLAGDLA, A F Technical Assistance Contracts Branch FIN B-4523 80/08/20 ip

- 8010030125 Btatus rept by TX Border Comperatives opposing settlement negotiations Differences w/Central & South West Corp re do interconnection are not insurmountable, but accord not yet reached. H/supporting documentation & Certificate of Bvc O'NEIL, R A Southwest Texas Electric Cooperative O'NEIL, R A Killer, Balis & O'Neil 80/10/01 22pp
- B010060341 Forwards DGJ petition for leave to intervene & comments contesting applicant proposed offer of settlement MCMILLEN, N H Transportation, Dept of 80/10/01 1p
- --8010060349 Patition for leave to intervene.
 FAVRETTO:R J , KAPLAN.D A , FABRIKANT.R Justice.Dept of 80/09/17 3pp
- --8010060353 Comments contesting applicant proposed offer of settlement on grounds that proposal does not clearly meet requirements of Public Util Regulatory Policies Act. Certificate of Byc encl FAVRETTO,R J., KAPLAN, D.A., FABRIKANT,R. Justice, Dept of 80/09/29 13pp
- 8010070541 Motion for revision of procedural schedule Buggests 10-day extension after ASLB rules on proposed settlement for parties to file trial briefs & subsequent extension for other matters Urges conference cell Certificate of Svc encl. BPIEGEL, 0 Brounsville, TX SPIEGEL, Q Spiegel & McDiarmid BO/10/03 12pp
- 8010080289 Hotion to strike refs to Commanche Pack proceeding from Public Utils Board of City of Brownsville.TX 800925 motion to disapprove proposed license conditions. Refs were stricken from previous analogous pleadings. Certificate of 8vc encl. KKOTTS, J. B. , AMEARN, C D Texas Utilities Generating Co KNOTTS, Debevoise & Liberman 80/10/06 9pp E LIBTTONN
- 8010030319 Response in opposition to Public Utils Board of City of Brownsville, TX 800925 motion for disapproval of proposed license conditions ASLB should await Brownsville trial brief prior to deciding addi steps W/Certificate of Bvc KMOTTS, J B , AHCARN, C D Texas Utilities Generating Co KNOTTS, T B Debevoise & Liberman 80/10/06 8pp.
- B010140002 Response in opposition to City of Brownsville 801003 motion for revision of procedural schedule Motion is extraordinarily late & w/o merit Certificate of Syc ancl. MKOTTER, J B. AMBARN. C D Toras Utilities Generating Co KNOTTE, J D Bebevoise & Liberman 80/10/07 Spg
- 80:01:40:004 Response in opposition to Public Utils Board of City of Brownsville 80:003 motions for disapproval of negotiated license conditions & for delay of briefs Certificate of Svc encl OREER DO. Houston Lighting & Power Co 80/10/07, 27pp.
- B010140525 Response in apposition to City of Brownsville 801006 request for revision of procedural schedule Modest relaxation of procedural dates may be appropriate, but indefinite extension not warranted Certificate of Svc enci CHANANIA, FD Antitrust Division 80/10/07. Spp
- 8010140540 Response in opposition to City of Brownsville 801006 request for revision of procedural schedule Indefinite extension not warranted No opposition to modest extension. Settlement conditions need prompt consideration VCertificate of Svc FABRIKANT, R. Justice, Dept. of 80/10/08 8pp.
- 8010190024 Trial brief concluding that proposed license conditions are inadequate to cure situation inconsistent w/antitrust laws. Lists of witnesses, exhibits & bestimony & Certificate of Evranci. SPIEGEL, O . LANDSMAN, R M . POIRIER, M R Brownsville, TX 80/10/08.
- 8010170458 Advises that DDJ response to Brownsville.TX 801009 initial trial brief will also address engument 800928 motion for disapproval of sattlement license conditions FABRIHANT,R. Justice.Dept of 80/10/10. Ip.
- B010190476 Requests on behalf of util that Board hold conference call involving all parties to discuss & resolve serious questions re trial brief & related filings submitted by TX Util Constraing Co Cartificate of Sv centil.
 BOUKNIGHT, J. A. Lowenstein, Neuman, Reis, Azelred & Toll, 80/10/14.
- 8010160368 Reiterates position that City of Brownsville 800928 motion for disapproval of proposed license conditions was inappropriate Best method of response would be NRC raply brief if such action inappropriate, extension requested. CHANANIA:F.D. Antitrust Division. 80/10/14. 2pp.

- B010200602 Notice of B01023 special prehearing conference to consider pending motions & requests No further responsive pleadings required of parties until after matters ruled on by ABLB MILLER. HE Atomic Bafety and Licensing Board Panel B0/10/14
- 8010170305 Forwards original copy of Public Utils Board of Brownsville, TC initial trial brief W/o enci POTRICE, N R Spiegel & McDiarmid 80/10/15 1p
- G0102003B7 Requests that documents claimed by utils as confidential be made available to any requesting party on G01021 Reserves right to request showing of confidentiality per ASLG 791107 POIRIER, It R Spiegel & McDiarmid BO/10/15 tp
- B010720316 Forwards Public Utils Board of City of Brownsville, TX first suppl to B01008 initial trial brief, correcting liets of documents to be offered into evidence SPIEGEL.9 Spiegel & McDiarmid 80/10/16 1p
- --8010220320 First suppl to 801008 initial trial brief correcting lists of documents to be affered into evidence Certification of svc encl
 SPIEGEL, O Brownsville, TX SPIECEL, Q Spiegel & McDiarmid 80/10/16 53pp
- 8010270397 Responds to 801015 ltr re release of potential exhibits for which util has claimed confidential treatment Objects to release of matl per ASLB 790724 stipulation to protective order Lists documents which can be released w/o restriction WETTERHAHN.M J Conner, Moore & Corber BG/10/21 2pp
- 8010270439 Requests ASLB discuss at 801024 conference question of issuing subposhes for production of ultresses in lieu of formal filings of individual motions Cites Part IVO of initial trial brief
 SPIE06L.O. Spiegpl & McDiarmid 80/10/22 ip
- N Antitrust hearing transcripts
- 8010310591 Transcript of 801024 prehearing conference in Bethesda, MD Pp 1139-1266 * Atomic Safety and Licensing Board Panel. BO/10/24 127pp
- 8010310551 Transcript of 801024 prehearing conference in Bethesda, HD Pp 1139-1266
 * Atomic Bafety and Licensing Board Panel 80/10/24 127pp
- 9 Inspection reports, IE Bullsting & correspondence
- B010020181 Forwards IF losp Repts 30-445/80-16 & 90-446/80-16 on 8EIDLE.W C Region 4, Dellas, Reactor Construction & Engineering Support Branch 60/08/25 2pp
- --8010020183 IE Inap Repts 50-445/80-14 & 50-446/80-16 on 800701-31 No noncompliance noted Major areas inspected safety-related piping installation & welding electrical cable installation & protection of major components TAYLOR.R.O. CROSSMAN,W A Region 4. Dallas. Office of the Director 80/08/22 Bpp
- 8010020186 Forwards IC Insp Repts 50-445/80-19 & 80-446/80-19 on 800811-13 & 15 No noncompliance noted BEIDLE.N C Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/08/26 2pp
- --BO10020191 IE Insp Repts 50-445/80-19 & 50-446/80-19 on 800811-13 & 15 No noncompliance noted Major areas inspected const activities, observation of work & review of records for reactor pressure boundary piping OILBERT-L D . CROSSMAN.W A Region 4. Dallas, Office of the Director. HALL.R E Region 4. Dallas, Reactor Construction & Engineering Support Branch 90/08/23 App
- 8010310104 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Bys " Relays not used in safety not
- 8010090337 Ack receipt of 800B18 ltr informing NRC of steps taken to correct violations noted in IC Insp Rapts 50-445/80-15 & 50-446/80-15.

 BEIDLE-N.C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/12 ip

- --B010070341 Responds to NRC 800/23 ltr re violations noted in IE Insp Repts 50-445/80-15 & 50-446/80-15 Corrective actions: applicable fabrication & installation specifications includes provision for QA criteria for Class 5 hangers GARY, R. J. Teras Utilities Generating Co. 80/08/18 5pp
- 8010080202 Notifies that no proprietary info contained within IE Insp Repts 50-445/80-16,50-446/80-16,50-445/80-17 & 50-446/80-17 GARY,R J Teras Utilities Generating Co 80/09/17 1p
- 8010270373 Discusses assault of QC inspector described in 800910 daily rept Case does not warrant referral to DOJ nor further investigative effort MARD.M J Office of Inspection & Enforcement, Office of the Director 80/09/22 1p
- 8010170494 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-17 & 50-445/80-17 SETDLE.U C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/26 1p
- --B010170464 Responds to NRC 800731 ltr re violations noted in IE Insp Repts 50-445/80-17 & 30-446/80-17 Corrective actions. counterbore angles on Westinghouse Drawing 2716750, Revision 2, have been clarified OARY, R J Texas Utilities Generating Co 80/08/29 2pp.
- 8010970527 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications" No written response required SEYRIT, K V Region 4, Dallas, Office of the Director, 90/10/02, in
- S Reportable occurrences, LERs & related correspondence
- BO10020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DERV 12. DBRV 16 & DBRV 20 built before Feb 1980.
 MARTINI, D H Transamorica Delaval, Inc 80/09/19, 2pp.
- B010170502 Deficiency rept re Roto-lack insert locking tab installed at facility Problem should not be classified as potentially reportable deficiency Supporting documentation available at plant site GARYR J Texas Utilities Generating Co 80/10/10 1p
- 8010170479 Deficiency rept re Plascite 7122 coating Ongoing evaluation of lining problem will be completed & formal rept forwarded by 801114 GARY.R J Texas Utilities Generating Co 80/10/13. ip
- CARTINO TEXAS CELLETES GENERATING CO CONTONIA. IN
- 8010200416 Deficiency rept re thread engagement of sway struts Condition not reportable under 10CFR90 55e.as reported on BC0919 OARY R J Texas Utilities Generating Co BO/10/15 ip
- 8010280354 Interim deficiency rept re defects in installation of Hilti-Kwik concrete anchor bolts Identified anchor bolts have been removed Support will be reworked &/or relocated to meet required design criteria Follow
- 8010280398 Deficiency rept re diesel generator pipe supports. Deficiency is being evaluated to formulate corrective action Formal rept will be provided by 810116 GARY.R J Texas Utilities Generating Co. 80/10/21, ip.
- DOCKET 50-446 COMANCHE PEAK BTEAM ELECTRIC BTA., UNIT 2

 A Application/construction stage documents & correspondence
- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl ELBENHUT:D O Division of Licensing 80/09/19. 28pp.
- 80100i0554 Forwards HJ Gruy & Associates, Inc 800915 ltr w/info for update to F8AR info includes well data on well within 5-mile radius of plants Supercedes rept submitted on 800523. Oversize drawing encl FEIST, C X Texas Utilities Co. 80/09/22, 11pp.
- --80i00i0557 "Natural Gas & Oil Pipelines & Wells Within 5-Miles of Commenche Peak." 4 H J Gruy & Associates, Inc. 80/07/22, ip.

- 8010010556 Forwards comments & recommendations re draft NUREG-0696 & proposed implementation schedule. Encl comments reflect serious reservations re implementation schedule for semsogancy response facilities after final rept is issued. SCHMIDT.H C Texas Utilities Services. Inc 80/09/24 3pp
- BOI0150186 Notification of B01021-23 meeting w/util in Glan Rose, TX to assess const completion schedules
 BURWELL, S B Licensing Branch 2 B0/10/01 App.
- 8010270725 Notification of 801015 meeting w/util in Bethesda.MD to discuss design changes being considered for facility in response to boron dilution transients BURWELL.8 B Licensing Branch 2 80/10/08 2pp
- 8010300440 Summary of 800825 mgt level meeting w/util in Bethesda,MD restatus & actions needed to complete TMI-2 requirements safety review
 BURWELL,S.B. Licensing Branch 2 80/10/08 5pp
- 8010300558 Summery of 800826 meeting w/utils in Bethesda.MD re requirement for onsits technical support ctr BURWELL.8 B Licensing Branch 2 80/10/17 6pp
- C Utility Environmental Report (ER), amends & correspondence
- 8010010532 Forwards Amend 1 to environ rept Amend includes responses to request for additinfo & environ rept update requested by NRC 800827 itr Affidavit encl OARY, R J Texas Utilities Generating Co 80/09/17. 2pp
- ---8010010533 Amend 1 to environ rept. * Texas Utilities Generating Co 80/09/30 300pp
- 8010060264 Forwards affidavit of syc re Amend 1 to facility environ rept.OL stage BCHMIDT, H C Texas Utilities Generating Co 80/09/29 9pp
- 8010080476 Forwards NOAA record of seismic activity in response to NRC Question 79 re Amend 1 to environ rept.

 WERNER, R. Texas Utilities Services, Inc. 60/10/01 12pp
- F Becurity, medical, emergency & fire protection plans
- 8010150391 Forwards presentation of assumptions, methodology & tabulation of BTP 95-1, App A, compliances currently being used to setablish fire protection program, FBAR will be amended to reflect updated fire hazards analysis OARY, R, J Teras Utilities Generating Co 80/10/08 11pp
- Q Adjudicatory correspondence
- 8005140419 Forwards NRC memorandum on ALAB-590 & applicability to admissibility of contentions. Recommends mod of proposed GA/ GC contention to fully address intervenors' concerns Cartificate of Svc snc! ROTHSCHILD, M.U., TURK, S.E. Hearing Branch 1, 90/05/12 3pp
- --8005140440 Memorandum on ALAB--590 & applicability to admissibility of contentions ALAB--590 supports Citizens for Fair Util Regulation Contention 2 A 5 6 & Association of Community Organizations for Reform Now Contentions 4,7,15 & 20 ROTHSCHILD,M U Hearing Branch 1 80/05/12 Spp
- --8005140447 Discusses issuance of ASLAB 800422 decision re FH Potthoff appeal from denial of petition to intervene Decision reaffirms sattled & sensible interpretation of section rebasis for contentions Certificate of Svc enci ROSENTHAL.A. B. Atomic Safety and Licensing Appeal Panel. 80705702 4pp.
- 8010020073 Forwards App A inadvertently omitted from TX Border Cooperative 800724 comments on progoned settlement. O'NEILR.A MILTORIBLIS & O'Neil. 80/09/23. 9pp.
- 80:0020727 Notion to compel Citizens for Fair Util Regulation to respond to applicants 800813 first set of interrogatories & request to produce documents Clarifies certain interrogatories Certificate of Svc anci REYNOLDG, N. B., HORIN, WA Texas Utilities Generating Co 80/07/30, 2500
- B010070362 Response supporting applicants' B00912 motion to compel if TX Association of Community Organizations for Reform Now refuses to respond to interrogatories Urges reasonable attension until B01002. Centificate of 8 vc encl. R0THSCHILD.H.U Hearing Branch 1. B0/10/02. 10pp.

- 8010140015 Response in opposition to applicant 800718 motion to compel Facts do not support applicant re number of interrogatories objected to Requests protective order re answers to applicant first interrogatories W/Certificate of Svc ELLIS.J. Citizens Association for Sound Energy 80/10/02 12pp
- 8010080263 Response in opposition to Citizens for Fair Util Regulation 800918 motion for protective order re applicants' discovery requests. Pending mod of ABLB 800616 order has no bearing on Contentions 2.5.7 & B W/Certificate of 8vc
 REYNOLDS.N S . HORIN.N A Texas Utilities Generating Co
 REYNOLDS.N S . Debevoise & Liberman 80/10/03 14pp
- 8010140515 Response in support of applicant 800918 motion to compel Citizens Association for Sound Energy to respond to interrogatories, except those dealing w/extension of time Certificate of Svc encil ROTHSCHILD.M U Operations & Administrative Division 80/10/08
- 8010150008 Response in opposition to Citizens for Fair Util Regulation B00918 motion for protection No good cause established for relief sought Certificate of Svc encil ROTHSCHILDIM U Operations & Administrative Division 80/10/09
- 8010200690 Request for 10-day extension to suppl response to applicant 800918 motion to compel in order to allow intervenor access to ABLB & ABLAB 1978 t 1979 decisions Certificate of Byc ancl Related correspondence EELIS.J Citizens Association for Sound Energy 80/10/14. 4pp.
- B010210503 Response in apposition to Citizens Association for Sound Energy 801002 motion for protective order re applicants discovery Intervenor failed to identify interrogetories for which relief is sought Certificate of Svc encl REYNOLDS, N S. HORIN, N A. Texas Utilities Generating CorrEYNOLDS, N S. Debevoise & Liberman 80/10/17 18pp
- 8010220314 Response in support of applicants' 800930 motion to compet Citizens for Fair Util Regulation response to interrogatories except Interrogatory & Beconds motion requiring suppl to prior response Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/10/20 24pp
- 8010240059 Response in apposition in part to Citizens Association for Sound Energy B01002 motion to compel & motion for protective order Takes no position on request re alleged misstatements by applicants Certificate of Sov enci ROTHSCHILD,M U Hearing Branch 1 80/10/22 opp
- 8010280578 Forwards NRC 801008 response to applicants' motion to compel served on all parties on 801008 W/o encl ROTHSCHILD.M U Hearing Branch 1. 80/10/23 1p
- 8010310436 Response stating no objection to Citizens Association for Sound Energy 801014 motion for add1 time to suppl response re applicants' 800918 motion to compel Boss not oppose availability of NRC 1978-80 issuances W/Cortificate of Svc. REYNOLDS.N 5 HORIN,W A Teras Utilities Generating CoreyNOLDS.N 5 Debavoise & Liberman 80/10/28 App.

- 8010090532 FOIA request for all available info re Comanche Peak Life Force or any affiliate organizations Affidavit authorizing Center for Law in Public Interest to make request on behalf of Comanche Peak Life Force encl BELINA Center for Law in the Public Interest. 80/09/16 Spp
- 8010090828 Responds to FDIA request for all available info re Comanche Peak Life Force or any affiliate organizations RRC has no files indexed or maintained under subj organization H/o enci listing of TX PDRs
 FELTON, J M Division of Rules and Records 80/10/01 1p
- 8010300033 Advises that 800430 prehearing conference transcript has been placed in mini~LPDR ROTHSCHILD,M U Hearing Branch 1 80/10/24 ip
- ~-8010300036 Forwards 800420 prehearing conference transcript to be placed in LPDR for public insp W/o enci 80U0ER.J L. Division of Rules and Records 80/10/20 ip.
- M. Utility Final Bafety Analysis Report (FBAR) & amends
- 8010200343 Forwards Amend 12 to FBAR & emergency plan. Affidavit enci GARY: R. J Fexas Utilities Generating Co 80/10/08. 2pp.

- --8010200346 Amend 12 to FBAR
 * Texas Utilities Generating Co 80/10/08 500pp
- --8010200347 Facility emergency plan * Texas Utilities Generating Co 80/10/08 100pp
- M Antitrust correspondence
- 8009230171 Notification of contract execution, Mod 4 to "Engineering Assistance Re Hearings for South TX Antitrust & Comanche Peak Antitrust Proceedings "
 HAIRBTON.C A Technical Assistance Contracts Branch FIN 8-6523 80/08/20 1p
- --8009230181 Mod 4, changing scope of work, to "Engineering Assistants Re Hearings for South TX Antitrust & Comanche Peak Antitrust Proceedings " 4 R N Beck & Associates GLAGOLA, A F Technical Assistance Contracts Branch FIN B-4523 80/08/20 1p
- 8010030129 Status rept by TX Border Cooperatives opposing settlement negotiations Differences w/Central & South West Corp re dc interconnection are not insurmountable, but accord not yet reached W/supporting documentation & Certificate of 8vc O'MEIL.R A Southwest Texas Electric Cooperative O'MEIL.R A Miller, Balis & O'Neil 80/10/01 22pp
- 8010040341 Forwards DOJ petition for leave to intervene & comments contesting applicant proposed offer of settlement MCMILLEN, N H Transportation, Dept of 80/10/01 ip
- --8010060349 Petition for leave to intervene FAVRETTO:R J., KAPLAN.D A. FABRIKANT.R Justice, Dept of 80/09/17 3pp
- --8010060353 Comments contesting applicant proposed offer of settlement on grounds that proposal does not clearly meet requirements of Public Util Regulatory Policies Act Certificats of Svc ancl FAVRETIO, R J , KAPLAN, D A , FABRIKANT, R Justice, Dept of 80/09/27 1350
- BO10070341 Motion for revision of procedural schedule, Suggests 10-day extension after ASLB rules on proposed settlement for parties to file trial briefs & subsequent extension for other matters Urges conference call Certificate of Bvc encl, SFIEGEL.O. Brownsville.TX SPIEGEL.O Spiegel & McDiarmid BO/10/03 12pp
- 8010080289 Motion to strike refs to Commanche Peak proceeding from Public Utils Board of City of Brownsville, TX 800925 motion to disapprove proposed license conditions Refs were stricken from previous analogous pleadings Certificate of Svc encl. KNOTTS, J B , AMEARN, C D Taxes Utilities Generating Co. KNOTTB, J, 3. Debevoise & Liberman 80/10/06 9pp
- 80:0080319 Response in opposition to Public Utils Board of City of Brownsville.TX 800925 motion for disapproval of proposed license conditions ASLB should await Brownsville trial brief prior to deciding addl staps W/Certificate of Svc KNOTTS, J B , AKCARN.C D. Texas Utilities Generating Co KNOTTS, T.B. Debevoise & Liberman 80/10/06 Spp
- 8010140002 Response in opposition to City of Brownsville 801003 motion for revision of procedural schedule Motion is extraordinarily late & w/o mertt.Certificate of 8vc encl KKCITS.J S. AMEARN.C D. Texas Utilities Generating Co. KNOTTB.J S. Debavoise & Liberman 80/10/07 Spp.
- BOIO140004 Response in opposition to Public Utils Board of City of Brownsville BO1003 motions for disapproval of negotiated license conditions & for delay of briefs Certificate of Sycencl OREEN, D O Houston Lighting & Power Co. 80/10/07 27pp.
- 8010140525 Response in opposition to City of Brownsville 801006 request for revision of procedural schedule. Modest relaxation of procedural dates may be appropriate, but indefinite extension not warranted Certificate of Buc encl CHANANIA.F.D. Antitrust Division 80/10/07 8pp.
- BOI0140540 Response in opposition to City of Brownsville BOi006 request for revision of procedural schedule. Indefinite extension not warranted. No opposition to modest extension. Battlement conditions need prompt consideration W/Certificate of Byc. FABRIKANT.R Justice. Dept of BO/10/08 Bpp

- B010180024 Trial brief concluding that proposed license conditions are inadequate to cure situation inconsistent w/antitrust laws. Lists of witnesses, exhibits & testimony & Certificate of Svc encl SPIECEL, G., LANOSMAN, R.M., POIRIER, M.R. Brownsville, TX. 80/10/08 105pp
- B01017048B Advises that DDJ response to Brownsville, TX B01009 initial trial brief will also address argument B00925 motion for disapproval of settlement license conditions FAMRIKANTR Justice.Dept of B0/10/10 ip
- 8010150476 Requests on behalf of util that Board hold conference call involving all parties to discuss & resolve serious questions re trial brief & related filings submitted by TK Util Openerating Co Centificate of Svc encl 80V4NIOHT, J A Lowenstein, Newman, Reis, Assirad & Toll 80/10/14 9pp
- 801016056B Reiterates position that City of Brownsville 800925 motion for disapproval of proposed license conditions was inappropriate Best method of response would be NRC reply brief If such action inappropriates, extension requested, CHANANIA.F D Antitrust Division 80/10/14 2pp
- 8010200602 Notice of 801023 special prohearing conference to consider pending motions & requests No further responsive pleadings required of parties until after matters ruled on by ASLB MILLER, M.E. Atomic Bafety and Licensing Board Panel 80/10/14 2pp
- B0101703B5 Forwards original copy of Public Utils Board of Brownsvills, TX initial trial brief W/o encl. POIRIER, M R Spiegel & McDiarmid B0/10/15 ip
- 8010200397 Requests that documents claimed by utils as confidential be made available to any requesting party on 801021 Reserves right to request showing of confidentiality per ASLB 791107 order POIRIER, N. R. Spiegel & McDiarmid 80/10/15 1p
- 8010220314 Forwards Public Utils Board of City of Brownsville, TX first suppl to 801008 initial trial brief, correcting lists of documents to be offered into evidence SPIE0EL.O Spiegel & McDiarmid 80/10/16 ip
- --8010220320 First suppl to 801008 initial trial brief correcting lists of documents to be offered into evidence Certification of swc encl
 SPIECEL-0 Brownsville.TX SPIECEL.O Spiegel & McDiarmid.
 80/10/16 53pp
- 8010270357 Responds to 801015 ltr re release of potential exhibits for which util has claimed confidential treatment. Objects to release of mati per ABLB 770724 stipulation to protective order. Lists documents which can be released w/o restriction WETTERHAHN. M J Conner, Moore & Corber 80/10/21 2pp
- 8010270439 Requests ASLB discuss at 801024 conference question of issuing subpoenss for production of witnesses in lieu of formal filings of individual motions Cites Part IVO of initial trial brief SPIE0EL.0 Spiegei & McDiarmid 80/10/22 lp.
- N Antitrust hearing transcripts
- 8010310551 Transcript of 801024 prehearing conference in Sethesda.MD Pp 1139-1266 * Atomic Safety and Licensing Board Panel, 80/10/24 127pp
- O Inspection reports: IE Bulletins & correspondence
- 8010020181 Forwards IE Insp Repts 50-445/80-16 & 50-446/80-16 on 800701-31 No noncompliance noted SEIDLE, No Construction & Engineering Support Branch 80/08/23 2pp
- --8010020183 IE Insp Repts 80-448/80-16 & 80-446/80-16 on 800701-31 No noncompliance noted Major areas inspected:safaty-related piping installation 3 welding electrical cable installation & protection of major components
 TAYLOR, R G . CROSEMAN, W. A. Region 4, Dallae, Office of the Director 80/08/22, 8pp
- 8010020186 Forwards IE Insp Repts 50-445/80-19 & 50-446/80-19 on 800811-13 & 15 No noncompliance noted.

 SEIDLE, M.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/26. 2pp.

- --8010020191 IE Insp Repts 50-445/80-19 & 50-446/80-19 on 800811-13 & 15
 No noncompliance noted Major areas inspected const
 activities, observation of work & review of records for
 reactor pressurs boundary piping
 GILBERT, L D . CRUSSHAN, W A Region 4, Dallas, Office of the
 Director HALL.R E . Region 4, Dallas, Reactor Construction &
 Engineering Support Branch 80/08/25 4pp
- 8010310104 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " Relays not used in safety-related sys GARY,R J Texas Utilities Generating Co 80/09/08 ip
- B010090337 Ack receipt of B00818 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-15 & 50-446/80-15 BEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch B0/09/12 ip
- --8010090341 Responds to NRC 800723 ltr re violations noted in IE Insp Repts 50-445/80-15 & 50-446/80-15 Corrective actions applicable fabrication & installation specifications includes provision for 9A criteria for Class 5 hangers GARY-R J Texas Utilities Generating Co 80/08/18 5pp
- 8010080202 Notifies that no proprietary info contained within IE Insp Repts 50-445/80-16, 50-445/80-16, 50-445/80-19 \$\tilde{v}\$ 50-446/80-19 QARY, R J Texas Utilities Generating Co 80/09/17 1p
- 8010290373 Discusses assault of OC inspector described in 800910 daily rept Case does not warrant referral to DOJ nor further investigative effort MARD, W J Office of Inspection & Enforcement, Office of the Director 80/09/22 ip
- 8010170454 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-17 & 50-445/80-17 SEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Support Branch. 80/09/26 ip
- --8010170464 Responds to NRC 80073! Itr re violations noted in IE Insp Repts 50-445/80-17 & 50-446/80-17 Corrective actions counterbore angles on Westinghouse Drawing 2710950, Revision 2, have been clarified OARY:R J Texas Utilities Generating Co 80/08/29. 2pp
- 8010270327 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required SEYFRIT.K V Region 4. Dalias. Office of the Director 80/10/02
- 8 Reportable occurrences. LERs & related correspondence
- 8010020603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DSRV 12, DBRV 16 & DBRV 20 built before Feb 1780 MARTINI, D H Transamerica Delaval, Inc. 80/09/19 2pp.
- B010170502 Deficiency rept re Roto-lock insert locking tab installed at facility Problem should not be classified as potentially reportable deficiency Supporting documentation available at plant site QARY, R J Texas Utilities Generating Co B0/10/10 ip
- 8010170479 Deficiency rept re Plascite 7122 coating Ongoing evaluation of lining problem will be completed & formal rept forwarded by 801114
 ORRY.R J Texas Utilities Generating Co 80/f0/i3 ip
- 8010200416 Deficiency rept re thread engagement of sway struts Condition not reportable under 10CFR50 55e, as reported on 800919. GARY, R.J. Texas Utilities Generating Co. 80/10/15 ip
- 8010280354 Interim deficiency rept re defects in installation of Hilti-Kwik concrete anchor bolts Identified anchor bolts have been removed Bupport will be reworked 8/or relocated to meet required design criteria Followup rept provided by 810123 GARY,R J Texas Utilities Generating Co 80/10/21, 3pp
- 8010280358 Deficiency rept re diesel generator pipe supports Deficiency is being evaluated to formulate corrective action Formal rept will be provided by 810116 GARY.R.J Texas Utilities Generating Co 80/10/21 ip

DOCKET STN-50-447 GESSAR-238

A Application/construction stage documents & correspondence

8010090498 Summary of 800910 meeting w/GE re NRC & consultant questions from review of GE submittals on multiple safety/relief valve loads used for NSSS equipment evaluation Attendance list encl SU,T K Generic Issues Branch 80/09/29 4pp

DUCKET 50-452 GREENHOOD ENERGY CENTER: UNIT 2

A Application/construction stage documents & correspondence

BO10270273 Advises that work is continuing to reduce design documents having unincorporated interim changes re unresolved Item 79-17-02 in 1E Bulletin 79-17, Revision 2 HINEG.E Detroit Edison Co BO/09/24 ip

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A Application/construction stage documents & correspondence

8010270293 Advises that work is continuing to reduce design documents having unincorporated interim changes re unresolved Item 79-17-02 in IE Bulletin 79-17. Revision 2 HIMES.E Detroit Edison Co. 80/09/24 ip

DOCKET 50-494 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8010020643 Discusses interim actions for plant operation pending final resolution of ATMS Requests submission of ATMS emergency operating procedure TEDESCO, R. L. Assistant Director for Licensing 80/09/12 3pp Assistant Director for Licensing 80/09/12 3pp

8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Carrected table of implementation schedule also encl. EISERHUY, D 0 Division of Licensing 80/09/19, 28pp

B010020439 Forwards schematic drawings indicating circuits for each of 12 motor operated valves listed in response to FBAR Question 040 12.per NRC B00912 telcon request Oversize drawings encl NAUGHTON. H F Commonwealth Edison Co 80/09/24 ip.

--8010020448 "Key Diagram 480 Volts Auxiliary Bldg Engineered Safety Feature Motor Control Ctr 131X1 (1AP21E), Part 1 " • Sargent & Lundy, Inc 4391 80/07/28 ip.

-8010020455 "Key Diagram 480 Volts Auxiliary Bldg Engineered Safety Feature Motor Control Ctr (31X) & 131X(A (1API)1E & EA), Part 2 "

Sargent & Lundy, Inc 4391 80/07/28 10

8010020465 "Key Diagram 480 Volts Auxiliary Bldg Engineered Safety Feature Motor Control Ctr 191X2 (IAP25E) & I3IX2A (IAP25E-A)." + Sargent & Lundy, Inc. 4391 80/07/28 ip

-8010020507 "Key Diagram 480 Volts Autiliary Bldg Engineered Bafety Feature Motor Control Ctr 132X2 & A(1AP27E & A) " + Sargent & Lundy, Inc 4391 80/07/28 1p

-8010020509 "Mey Diagram 480 Volts Auxiliary Bldg Engineered Safety Feature Motor Control Ctr 132X4 91AP28E) & Motor Control Ctr 132X4A (1AP2EEA) " Bargent & Lundy, Inc 4371 80/07/28, 1p

--8010020510 "Schematic Diagram Bafety Injection Pumps Discharge Isolation Valves 1818802 A & B " 4 Sargent & Lundy, Inc. 4391 80/04/08 1p

--8010020911 "Schematic Diagram Safety Injection Pumps Suction From Radwaste Isolation Valve ISISBOA, RHR Heat Exchanger 1B to Safety Injection Pumps Isolation Valve 18188048,"

4 Sargent & Lundy, Inc. 4391 80/04/08 1p.

--8010020512 "Schematic Diagram Accumulators (A & 18 Discharge Isolation Valves 1918808A & B." Sargent & Lundy, Inc 4391 80/04/16. 1p

--8010020513 "Schematic Diagram Accumulators 1C & 1D Discharge Isolation Valves 1518808C & D " + Sargent & Lundy, Inc. 4391 80/04/14 ip

--8010020515 "Schematic Diagram RHR to RC Cold Legs 1A + 1D & 1B + 1C teolation Valves 1818809 A & B "
+ Sargent & Lundy, Inc 4391 80/04/16 1p

--8010020521 "Schematic Diagram Safety Injection Pumps & Pump 1A Miniflow Isolation Valves 1518813 & 1818814 " + Sargent & Lundy, Inc 4391 80/04/16 ip

--8010020526 "Achematic Diagram Safety Injection Pumps Discharge to Cold Legs Injection Valve 1818895.RHR to RC Hot Legs 1A & 1C Isolation Valve 1818840 " 4 Sargent & Lundy, Inc. 4391 80/05/09. Ip

--8010020539 "Schematic Diagram 480 Volts Feed to ECCS Water Supply Isolation Valves at Motor Control Ctr 131X1A & 131X2A " # Bargent & Lundy, Inc 4391 80/03/13 1p

--8010020533 "Schematic Diagram 480 Volts Feed to ECCS Water Supply Isolation Valves at flotor Control Ctr 132X2A & 132X4A " + Sargent & Lundy, Inc 4391 80/03/13 lp

8010100361 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC schedule LAMAKEN D.C. Commonwealth Edison Co. 80/09/24 2pp

B010070430 Comments on NRC B00905 ltr re "Preliminary Clarification of THI Action Plan Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED.C Communwealth Edison Co B0/10/01 5pp

B0101003BB Notification of B01015-17 meetings w/util in Byron & Braidwood, IL to conduct caseload forecast panel site visit to update NRC estimate of const completion date MOUN, C & Licensing Branch 1 B0/10/03 3pp

B010170164 Notification of cancellation of 801015-17 meetings w/util at sites to update NRC estimate of const date completion MODN,C W Licensing Branch i 80/10/08 3pp

G Adjudicatory correspondence

B010140011 Outlines schedule for issuance of NRC documents in proceeding DEB to be issued in Jan 1982,FE8 in Jul 1982 & SER in June 1982 KARMAN,M Hearing Branch 2 80/10/08 ip

80102703B4 Motion for ruling on pending contentions needed for OL avidentiary hearings Required negotiations & discussions took place Certificate of Buc end.

BIELAMSKI.A P. MILLER.M I., MURPHY.P M. Commonwealth Edison Co AP, MILLER,MI, MURPHY,PM Commonwealth Edison Co 80/10/24

O Inspection reports, IE Bullatins & correspondence

8010010606 Forwards IE Insp Repts 50-454/80-15 & 50-455/80-14 on 800805-07 & 12 & notice of violation No reply required due to immediate corrective action taken by util, FIQRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/28 2pp.

--8010010412 Notice of violation from insp on 800809-07 & 12 * Region 3, Chicago, Office of the Director 80/08/27

--8010010620 IE Insp Repts 50-454/80-15 & 50-455/80-14 on 800809-07 & 12 Noncompliance noted no measures established to specify acid resistant hardware or protect current carbon steel hardware against correction NAIDUAK R., BCHAPKER, J.F., HAYEG, D.W. Region 3, Chicago, Office of the Director. 80/08/27 9pp

8010010642 Forwards IE Insp Repts 50-454/80-16 & 50-455/80-15 on 800806-08. No noncompliance noted. FIORELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/28 2pp

--8010010449 IE Insp Repts 50-454/80-16 & 50-455/80-13 on 800806-08, No noncompliance noted Major areas inspected reactor cuclant pressure boundary & safety related piping work activities. LEE, E. W. K., DANIELSON, D H. Region 3, Chicago, Office of the Director 80/08/25 5pp.

- g010200672 Forwards IE Insp Repts 50-454/80-17 & 50-455/80-16 on 800820-21 No noncompliance noted FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/02 2pp
- --B010200674 IE Insp Repts 50-454/B0-17 & 50-455/B0-16 on B00B20-21 No noncompliance noted Major areas inspected ongoing site const activities repair of local instrument panels & warehouse storage of NSSS equipment KOMMLIN-JE, WILLIAMS-C C Region 3, Chicago, Office of the Director B0/08/28 5pp
- BOI0160314 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J 0 Region 3. Chicago. Office of the Director B0/09/30
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. O Region 3, Chicago, Office of the Director 80/10/02 is
- 8010270037 Forwards IE Info Notice 80-36, "Failure of Steam Cenerator Support Bolting " No specific action or response requested XEPPLER, J G Region 3, Chicago, Office of the Director 80/10/10, 16

DOCKET SO-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8010020643 Discusses interim actions for plant operation pending final resolution of ATMS Requests submission of ATMS emergency operating procedure TEDESCO,R L. Assistant Director for Licensing 80/09/12 3pp
- B010220099 Forwards errata sheets amending 800909 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISERMUY, D 9 Division of Licensing 80/09/19, 28pp
- B010020437 Forwards schematic drawings indicating circuits for each of 12 motor operated valves listed in response to FBAR Question 040 12.per NRC B00912 telcon request Oversize drawings encl. NAVOHTON.W F Commonwealth Edison Co B0/07/24 ip.
- BO10100341 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from B00917 meeting. Requests info re which program best fits NRC schedule, LAHKEN-D C Commonwealth Edison Co B0/09/24 2pp
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements " Urgos NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED,C Commonwealth Edison Co 80/10/01 Spp
- 801010038B Notification of 801015-17 meetings w/util in Byron & Braifwood. IL to conduct caseload forecast panel site visit to update NRC setimate of const completion date MODN.C W Licensing Branch 1. 80/10/03 Spp.
- 8010170164 Notification of cancellation of 801018-17 meetings w/util at sits to update NRC estimate of const date completion.

 MOON, C W Licensing Branch 1 80/10/08 3pp

O Adjudicatory correspondence

- B010140011 Dutlines schedule for issuance of NRC documents in proceeding, DEB to be issued in Jan 1982, FEB in Jul 1982 & BER in June 1982 KARKAN. M. Hearing Branch 2 80/10/08 lp
- 8010270384 Motion for ruling on pending contentions messed for OL swidentiery hearings. Required negotiations & discussions took place Cartificate of Svc encl BIECAMBRIA.P. : MILLER, M. I , MURPHY, P. M. Commonwealth Edison Co 80/10/24 5pp
- **G** Inspection reports, IE Bulletins & correspondence
- 8010010606 Forwards IE Insp Repts 50-454/80-15 & 50-455/80-14 on 800805-07 & 12 & notice of violation. No reply required due to immediate corrective action taken by util, FIORELLI, 0. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/28, 2pp

- --B010010612 Notice of violation from insp on B00805-07 & 12 * Region 3. Chicago. Office of the Director B0/08/27 ip
- --8010010620 IE Insp Repts 50-454/80-15 & 50-455/80-14 on 800805-07 & 12 Noncompliance noted no measures established to specify acid resistant hardware or protect current carbon steel hardware against corrosion NAIDU.K R. SCHAPKER, J F., HAYEB, D W. Region J, Chicago, Office of the Director 80/08/27 9pp
- 8010010642 Forwards IE Insp Repts 50-454/80-16 & 50-455/80-15 on 800806-08 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/08/28 2pp
- --8010010649 IE Insp Repts 30-454/80-16 & 50-455/80-15 on 800806-08 No noncompliance noted Major areas inspected reactor coolant pressure boundary & safety related piping work activities LEE.E W K. DANIELEON, D H Region 3, Chicago, Office of the Director 80/08/25 5pp
- 8010200672 Forwards IE Insp Repts 30-494/80-17 & 50-455/80-16 on 800920-21 No noncompliance noted FIGRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/02 2pp
- --8010200674 IE Insp Repts 50-454/80-17 % 50-455/80-16 on 800820-21 No noncompliance noted Major areas inspected ongoing site const activities repair of local instrument panels & warehouse storage of NSSS equipment KONKLIN.J E. WILLIAMS.C C Region 3. Chicago. Office of the Director 80/08/28 5pp
- B01016Q314 Forwards Suppl 2 to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director, 80/09/30
- B0102B0427 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/10/02
- 8010270037 Forwards IE Info Notice 80-36, "Failure of Steam Generator Bupport Bolting " No specific action or response requested KEPPLER.J G Region 3, Chicago, Office of the Director 80/10/10 1p
- S Reportable occurrences, LERs & related correspondence
- 8010100421 PNO-III-80-14B on BOOB11.contractor employee received critical internal injuries when caught between crane counterweight & engine housing Employee was taken to hosp & later died JONES,C.E., HILLIAMS,C.C., FIGRELLI,O. Region 3. Chicago, Office of the Director BO/08/11 1p
- DOCKET 50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010020643 Discusses interim actions for plant operation pending final resolution of ATMS Requests submission of ATMS emergency operating procedure TEDESCO, R. L. Assistant Director for Licensing 80/09/12 3pp
- 8010220099 Forwards erreta sheets amending 800905 itr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EIEENHUT. D 0 Division of Licensing 80/09/19 28pp
- 8010020439 Forwards schematic drawings indicating circuits for each of 12 motor operated valves listed in response to FBAR Gusstion 040 12-per NRC 800912 telcon request Oversize drawings encl NAUQHION.H.F. Commonwealth Edison Co. 80/09/24 ip
- --8010020448 "Key Diagram. 480 Volts Auxiliary Bldg Engineered Bafety Feature Motor Control Ctr 131X1 (1AP21E), Part 1 " * Bargent & Lundy, Inc 4391. 80/07/28 19,
- --8010020456 "Key Diagram 480 Volts Auxiliary Bldg Engineered Bafety Feature Motor Control Ctr ISIXI & ISIXIA (IAPIIE & EA). Part 2" 4 Bargent & Lundy, Inc. 4371 80/07/28 ip

- --8010020465 "Key Diagram 480 Volts Auxiliary Bldg Engineered Safety Feature Motor Control Ctr 131X2 (1AP25E) & 131X2A (1AP25E-A) "
 - Sargant & Lundy, Inc 4391 80/07/28
- --8010020507 "Key Diagram 480 Volts Auxiliary Bldg Engineered Bafety Feature Motor Control Ctr 132X2 & A(1AP27E & A)." 4 Bargent & Lundy, Inc 4391 80/07/28 ip
- ~-8010020509 "Key Biagram 480 Volts Auxiliary Bldg Engineered Bafety Feature Motor Control Ctr 132X4 91AP28E) & Motor Control Ctr 132X4A (1AP28EA) "
 - Sargent & Lundy, Inc. 4371 80/07/28 ip
- --B010020510 "Schematic Diagram Safety Injection Pumps Discharge Isolation Valves 1918802 A & B " + Sargent & Lundy, Inc. 4391 80/04/08 ip
- --8010020511 "Schematic Diagram Sefety Injection Pumps Suction From Radwaste Isolation Valve ISI8806.RHR Heat Exchanger 18 to Safety Injection Fumps Isolation Valve ISI88048 " + Sargent & Lundy, Inc 4391 80/04/08 1p
- -8010020512 "Schematic Diagram Accumulators 1A & 18 Discharge Isolation Valves 1818808A & B " + Sargent & Lundy. Inc. 4391 80/04/16 ip
- -8010020513 "Behematic Diagram Accumulators iC & 1D Discharge Isolation Valves 1818808C & D " 4 Sargent & Lundy, Inc. 4391 80/04/16 ip
- --8010020515 "Schematic Diagram RHR to RC Cold Legs iA + 1D & iB + iC Isolation Valves i5:8809 A & B "

 + Sargent & Lundy, Inc 4391 80/04/16 ip
- --8010020521 "Schematic Diagram Bafety Injection Fumps & Pump 1A Miniflew Isolation Valves 1818813 & 1818814 " Sargent & Lundy, Inc 4391 80/04/16 1p
- -8010020526 "Schematic Diagram Bafety Injection Pumpe Discharge to Cold Legs Injection Valve 1818805.RHR to RC Hot Legs 1A & 1C Isolation Valve 1818840 " + Sargent & Lundy, Inc 4391 80/05/09 Ip.
- -8010020539 "Behematic Diagram 480 Volts Feed to ECCS Hater Bupply Isolation Valves at Motor Control Ctr 131X1A & 131X2A " * Bargent & Lundy, Inc 4391 80/03/13 1p
- -8010020533 "Schematic Diagram 480 Volts Feed to ECCS Mater Bupply Isolation Valves at Motor Control Ctr 132X2A & 132X4A." * Sargent & Lundy, Inc 4391 80/03/13 Ip
- JOIO100361 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from BOO917 meeting Requests info re which program best fits NRC schedule LAMMEN.D C Commonwealth Edison Co 80/09/24 2pp
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED.C Commonwealth Edison Co. 80/10/Q1. 5pp.
- BOIO1003BB Notification of BO1015-17 meetings w/util in Byron & Braidwood, IL to conduct caseload forecast panel site visit to update NRC estimate of const completion date, MODN.C W Licensing Branch i BD/10/03, 3pp.
- 8010170164 Notification of cancellation of 801015-17 meetings w/util at sites to update NRC estimate of const date completion MGGN-C, W. Licensing Branch I. 80/10/08 3pp
- G. Adjudicatory correspondence
- B010140007 Outlines schedule for issuance of NRC documents in proceeding DEG to be issued by Jan 1984.FEB by Jul 1984 & SER by June 1982 KARMAN,M Hearing Branch 2 80/10/08, 1p
- Q Inspection reports: IE Bulletins & correspondence
- 8010150146 Forwards IE Insp Rept 50-436/80-08 on 800724 & 0814 & notice of violation
 FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering
 Support Branch. 80/08/28. 2pp.

- --8010150148 Notice of violation from insp on 800724 & 0814 # Region 3, Chicago, Office of the Director 80/08/26
- --8010150156 IE Insp Rept 50-456/80-08 on 800724 & 0814 Noncompliance noted welding math control inadequate as consumble inserts were not properly tagged & required documentation unavailable
 DANIELEON, D. H., LEE, E. W.K. Region 3, Chicago, Office of the 80/09/26
- 80:016:03:4 Forwards Suppl 2 to IE Bulletin 79-0:8, "Environ Gualification of Class IE Equipment" No written response KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30
- 8010210374 Ack receipt of 781127 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/78-06 & 50-457/78-07 NRC position re sieve qualification established FIGRELLI. © Region 3, Chicago, Reactor Conttruction & Engineering Support Branch 80/10/02 2pp
- B0102B0627 Forwards IE Circular B0-22, "Confirmation of Employee Gualifications" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/10/02
- 8010270037 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/10/10
- 8010290413 Ack receipt of 801001 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-456/80-08 FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/21 ip
- --B010270414 Responds to NRC 800828 ltr re violation noted in IE Insp. Rept 50-436/80-08 Corrective actions pracedures re control of weld mati re-examined, revised & instituted, ABEL.J S Commonwealth Edison Co B0/10/01 4pp.

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8010020549 Discusses interim actions for plant operation pending final resolution of ATMS Requests submission of ATMS emergency operating procedure. TEDESCO.R L Assist Assistant Director for Licensing. 80/09/12
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D G Division of Licensing 80/09/19. 28pp
- 8010020439 Forwards schematic drawings indicating circuits for each of 12 motor operated valves listed in response to FBAR Question 040 12-per NRC 800912 telcon request Oversize drawings encl NAUOHTOM W F. Commonwealth Edison Co 80/09/24, 1p
- 8010100361 Submits list of current qualification programs for EPRI util equipment qualification owners group resulting from 800917 meeting Requests info re which program best fits NRC schedule LAKKEN,DC Commonwealth Edison Co 80/09/24 2pp.
- B010070430 Comments on NRC B00905 ltr re "Preliminary Clarification of TMI Action Plan Requirements" Urgss NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly.

 REED.C. Commonweelth Edison Co B0/10/01 5pp.
- 8010100388 Notification of 801015-17 meetings w/util in Byron & Braidwood. It to conduct caseload forecast panel sits visit to update NRC estimate of const completion date MOON.C N. Licensing Branch 1 80/10/03, 3pp.
- 8010170164 Notification of cancellation of 801015-17 meetings w/util at sites to update NRC estimate of const date completion.

 MOGN.C W Licensing Branch 1. 80/10/08 3pp

DOCKETED ITEMS

@ Adjudicatory correspondence

8010140007 Dutlines schedule for issuance of NRC documents in proceeding DES to be issued by Jan 1984,FES by Jul 1984 & SER by June 1982 KARMAN,M Hearing Branch 2 80/10/08 1p

O Inspection reports, IE Bulletins & correspondence

- 8010160314 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/30
- 8010210394 Ack receipt of 781127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/78-06 & 50-457/8-07 NRC position re sieve qualification established B00903 FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/02 2pp
- 8010280627 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/02 1p
- 8010290039 Forwards IE Info Notice 80-36. "Failure of Steam Generator Bupport Bolting " No specific action or response requested KEPPLER, J O Region 3. Chicago, Office of the Director 80/10/10

POCKET 50-498 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

- 8010010013 Forwards description of stop work order resulting from recurring framework problems re placement of QA Category I concrete Corrective action intilated & order lifted DRAPER,E L Oulf States Utilities Co 80/08/06
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENMUF.D 9 Division of Licensing 80/09/19. 28pp.
- 8010220278 Forwards Amend 1 to CPPR-145, safety evaluation, negative declaration, EIA & FR notice.
 EISENHUT, D 0. Division of Licensing 80/10/03 4pp.
- --8010220280 Amend 1 to CPPR-149, adding Cajun Electric Power Cooperative, Inc as co-owner of facility EISENHUT, D Q Division of Licensing, 80/10/03 2pp.
- --8010220284 Safety evaluation supporting addition of Cajun Electric Power Gooperative Inc as co-owner of facility. KIRAGLIA.F J Licensing Branch 3 80/10/03 9pp
- --B01022020A Negative declaration re Amend 1 to CPPR-145 adding Cajun Electric Power Cooperative. Inc as co-owner of facility. HIRACLIA.F J Licensing Branch 3. B0710703 29
- --8010220289 EIA supporting Amend 1 to CPPR-148 re addition of Cajun Electric Power Cooperative Inc as co-owner of facility. + Licensing Branch 3 80/10/03 2pp
- --B010220292 FR notice re issuance of Amend 1 to GPPR-145, adding Cajun Electric Power Cooperative, Inc. as co-owner of facility MIRAOLIA: F. J. Licensing Branch 3 B0/10/03 2pp.
- 8010100353 Responds to 800905 ltr re halt of const at facility Forwards comments from concerned individual regarding suspension of const at facility.
 POLLARD, R D., WEISS, E R Union of Concerned Scientists 80/10/06.

G Adjudicatory correspondence

8010230513 Advises that on 801020.Director's decision under 10GFR. 206 became final agency action CHILK, S. J. Office of the Secretary of the Commission. 80/10/22. 1p

Q Inspection reports, IE Bulletins & correspondence

- 80100805&1 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" OE survey reveals that none of questionable hydramotor actuators were specified for plant DRAPER, E. L. Guif States Utilities Co. 80/08/28 ip
- B0100B0569 Responds to IE Bulletins 80-19 & 80-19, Revision i. "Failures of Marcury-Wetted Matrix Relags in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Review reveals that relays not specified for use in plant, DRAPER.E L Gulf States Utilities Co 60/08/28 ip
- B010310535 Forwards IE Insp Rept 50-458/80-09 on 800909-12 No noncompilance noted SEIDLE,W C Region 4, Dalles, Reactor Construction & Engineering Support Branch, B0/09/24 2pp
- --8010310534 IE Insp Rept 50-458/80-09 on 800909-12 No noncompliance noted Major areas inspected work & records for welding safety-related pipe GILBERT.L D. BEACH A B , CROSSMAN, W A Region 4. Dallas, Office of the Director 80/09/24 4pp
- 8010160101 Forwards Suppl 2 to IE Bullatin 79-01B, "Environ Qualification of Class IE Equipment" No written response required EEYFRIT,K V Region 4. Dallas, Office of the Director. 80/09/30.
- 8010170469 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-458/80-06 SEIDLE,W C. Region 4, Dallas, Reactor Construction & Engineering Bupport Branch 80/09/30 ip
- --8010170477 Responds to NRC 800728 ltr re violations noted in IE Insp. Rept 50-458/80-06 Corrective actions' computerized training record sign has been implemented & PSAR concrete oxygen content spaces clarified DRAPER.E L. Gulf States Utilities Co. 80/08/20. Spp.
- 8010270523 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required SEYFRIT,K V Region 4. Dallas, Office of the Director 80/10/02
- 8010300432 Ack receipt of 800910 ltr re two items of noncompliance & two deviations noted in IE Insp Rept 50-458/80-07. Addl info required re littering control in concrete placement areas & hot weather requirements per 800917 telcon BEIDLE, W. C. Region 4. Delias, Reactor Construction & Engineering Bupport Branch. 80/10/03 2pp.
- --8010300435 Forwards response to infractions noted in IE Insp Rept 50-458/80-07 Corrective actions continued emphasis to be placed on housetseping & field engineers will be responsible for completing concrete pour card checklist DRAPER.E.L. Guif States Utilities Co. 80/09/10. 7pp

8 Reportable occurrences, LERs & related correspondence

8010150204 Interim deficiency rept re incorrect input in calculations used to generate amplified response spectra of reactor bldg structures. Detailed review initiated & rept to be submitted pending review findings DRAPER, E L Gulf States Utilities Co 80/09/12 ip.

DOCKET 50-457 RIVER BEND STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 80(022009? Forwards errate elsets amending 800905 ltr which provided preliminary charification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT, D.G. Division of Licensing, 80/09/19, 28pp.
- 8010100353 Responds to 800905 ltr re halt of const at facility Forwards comments from concerned individual regarding suspension of const at facility.
 POLLARD, R. D., WEISS, E. R. Union of Concerned Scientists, 80/10/06.

O. Adjudicatory correspondence

8010230513 Advises that on 801020, Director's decision under 10GFR. 206 became final agency action CHILK, S. J. Office of the Secretary of the Commission 80/10/22.

- @ Inspection reports, IE Bulletins & correspondence
- B0100B0351 Responds to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies" QE survey reveals that none of questionable hydramotor actuators were specified for plant. DRAPER.E.L. Quit Btates Utilities Co B0/08/28, 1p
- 8010030367 Responds to IE Bulletins 80-19 & 80-19, Revision i. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Review reveals that relays not specified for use in plant. DRAPER, E.L. Guif States Utilities Co 80/08/28 1p
- 80i0160i01 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Glass IE Equipment." No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/09/30 ip.
- 8010270523 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications." No written response required. EEYFRIT.K.V Region 4, Dallas, Office of the Director. 80/10/02, 10

DOCKET 50-440 WPP8B NUCLEAR PROJECT, UNIT 1

- A. Application/construction stage documents & correspondence
- 8010220077 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of THI action plan requirements. Corrected table of implementation schedule also encl. EISENHUT, D.O Division of Licensing, 80/09/19, 28pp.
- 8010210314 Revised notification of 801007 meeting w/util in Seattle,WA to discuss RRC regional evaluation of licensee performance for May 1979-Jul 1980 for Units 1 & 4 k Aug 1979-Aug 1980 for Units 3 & 5, Meeting agenda enci.

 Region 5, San Francisco, Office of the Director. 80/09/30. 3pp
- 8010160321 Informs that commitment to perform scale model recirculation sump test in lieu of committed in-plant test may be waived after alternative scale model test program has been reviewed NRC will determine suitability of substitute. YOUNGRLOOD, B. J. Licensing Branch 1. 80/10/01. 2pp
 - '0210751 Responds to util 790315 & 0814 requests to perform scale indel recirculation sump test in lieu of in-plant test per SAR. Commitment may be relieved contingent on NRC approval if alternative program.
 'OUNGBLOOD, B. J. Licensing Branch 1. 80/10/01, 2pp.

Inspection reports. IE Bulletins & correspondence

- 0240579 Forwards IE Insp Repts 50-460/80-06 & 50-513/80-06 on 10429-0502 & notice of violation MCLKEN.R.H. Region 5. Sen Francisco, Office of the Director. 1/07/11. 2pp.
- 10240381 Notice of violation from inep on 800429-0502. * Region 5. San Francisco. Office of the Director. 80/07/09 Gpp.
- 10240587 IE Insp Repte 50-460/80-06 & 50-513/80-06 on 800429-0502. Noncompliance noted:failure to properly store & protect safety-related equipment & to install pipe hanger in accordance w/instructions.

 BISHOP-T.W., HERNANDEZ.O. Region 5, Ban Francisco, Office of the Director, DODDS.R.T. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. 80/07/09, 10pp.
- 90618 Responds to IE Bulletin 80-19, "Failures of Hercury-Wetted nix Relays in Reactor Protective Sys of Operating Nuclear or Plents Designed by C-E." Subj relays not in use in c matrix of sys at facilities. EROER, D. L. Washington Public Power Supply System, 80/09/05
 - 083 Responds to IE Bulletin 80-20, "Failures of Westinghouse -2 Spring Return to Neutral Control Buitches." Is do not use Westinghouse Type W-2 switches in related applications.

)ER.D.L. Washington Public Power Supply System. 80/09/08.
 - orwards IE Circular 80-21, "Regulation of Refueling Crews." response required.

 H. Region 5, San Francisco, Office of the Director.
 ip.

- 8010080373 Responds to IE Bullatin 79-24. "Frozen Lines " Adequate measures taken to preclude freezing of safety-related lines RENDERGER.D L Washington Public Power Supply System 80/09/13 200
- 8010160059 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/09/29 10
- 8010280027 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/10/02 1p
- 8. Reportable occurrences, LERs & related correspondence
- 8010020603 Part 21 rept re potential defect in component of DBRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DBRV 12 DBRV 16 & DBRV 20 built before Feb 1980.

 MARTINI, D H Transamerica Delaval, Inc. 80/09/19 2pp
- 8010300684 Interim deficiency rept re ASME III. Seiemic Category I pipe supports related to 1E Bulletin 79-02. Revision 2 Revises 800124 commitments & provides status w/revised completion dates. Related documentation enci RENBERGER, D. L. Weshington Public Power Supply Bystem 80/09/25 7pp.

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A. Application/construction stage documents & correspondence
- 8010220097 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of THI action plan requirements Corrected table of implementation schedule also encl. EISENHUT, D Q Division of Licensing 80/09/19 28pp
- 8010070246 Forwards FR notice of receipt of application for DLs, of availability of anyiron rept.of consideration of issuance of DLs & of opportunity for hearing, Also forwards notice of opportunity for public participation.
 BCHWENCER.A. Licensing Branch 3 80/09/23 ip.
- --B010070248 Notice of receipt of application for ULs. of availability of applicant environ rept. of consideration of issuance of OLe and of opportunity for hearing.

 BCHWENCER. A. Licensing Branch 3 80/09/23. 7pp
- --80i0070251 Notice of opportunity for public participation in proposed NRC licensing action on application by util for facilities.

 + Licensing Branch 3. 80/09/23 3pp
- 8010270015 Forwards "Quidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors," in response to 8000714 request M/o encl. BUCKLEY, B.C. Licensing Branch 3, 80/10/09, 2pp
- B010210375 Responds to NRC G00B29 ltr re acceptance review Util commits to providing responses on FSAR during Dac 1980 in form of emend to FSAR Addl info for environ rept will be provided during Jan 1981.

 WKLER, 0 E Illinois Power Co. 80/10/17. 10
- C Utility Environmental Report (ER), amends & correspondence
- 8010070246 Forwards FR notice of receipt of application for QLs.of availability of environ rept.of consideration of issuance of QLs & of opportunity for hearing. Also forwards notice of opportunity for public participation
 BCHMENGER.A Licensing Branch 3, 80/09/23, ip
- --8010070248 Notice of receipt of application for OLs.of availability of applicant environ rept of consideration of issuance of OLs and of opportunity for hearing.

 804MERGERIA. Licensing Branch 3. 80/09/23, 7pp.
- G. Adjudicatory correspondence
- 8010070246 Forwards FR notice of receipt of application for GLs: of availability of environ rept.of consideration of issuance of CLs k of opportunity for hearing. Also forwards notice of opportunity for public participation.

 8CHWENCER.A. Licensing Branch 9, 80/09/29, ip.

- --B010070248 Notice of receipt of application for OLs, of availability of applicant environ rept. of consideration of issuance of OLs and of opportunity for hearing BCMMENGER: A Licensing Branch 3 80/09/23 7pp
- --B010070251 Notice of opportunity for public participation in proposed NRC licensing action on application by util for facilities a Licensing Branch 3 80/09/23 3pp

- 8010080434 Requests that DH River Basin Commission be removed from mailing lists for facilities due to plant location. Buggests that MB River Basin Commission be added to mailing lists JOERINO.E A Ohio River Basin Commission 80/10/03 ip
- Q Inspection reports: IE Bulletins & correspondence
- 8010060103 Forwards IE Insp Rept 50-461/80-14 on 800805-08 & notice of violation FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/20 2pp
- --8010040106 Notice of violation from insp on 800805-08 * Region 3. Chicago. Reactor Construction & Engineering Support Brench. 80/08/19 ip
- --B010060108 IE Insp Rept 50-461/80-14 on 800805-08 Noncompliance noted failure to follow instructions

 MESCOTT, H.M., CORDERO, Z.C. Region 3, Chicago, Office of the Director KNOP, R.C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/19 8pp.
- B010060065 Submits response to IE Sulletin 80-19 Mercury-wetted switches are not used in safety-related sys.

 MULLER, G E Illinois Power Co 80/08/26 ip.
- B010140150 Forwards IE Insp Rept 50-461/80-16 on B00701-31 & notice of violation FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. B0/08/28 2pp.
- --B010140152 Notice of violation from insp on 800701-31.
 * Region 3. Chicago, Office of the Director. 80/08/26 2pp.
- --8010140155 IE Insp Rept 50-461/80-16 on 800701-31 Noncompliance noted: 250 containment rebar cadwelds installed out of normal position & w/o following installation instructions. KNOP.R C , LIVERMORE.H H Region 3, Chicago, Office of the Director. 80/08/26 13pp.
- 8010090098 Responds to IE Bulletin 80-20. "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Buitches. "Buitches are not used in safety-related applications, only for testing while breaker is in test position.

 WULLER, O. E. Illinois Power Co. 80/09/16. 1p.
- 8010290148 Forwards IE Insp Rept 50-441/80-18 on 800902-05. No noncompliance noted FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --B010290151 IE Insp Rept 50-461/80-18 on 800902-05. No nancompliance noted Major areas inspected records of installation & Glass IE cable trage & supports LEE,R L. Region G. Chicago, Office of the Director. HAYES,D.W. Region G. Chicago, Reactor Construction & Engineering Support Branch 80/09/25 4pp
- 8010170125 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-14. FIGRELIT, O Region G. Chicago, Reactor Construction & Engineering Support Branch 80/09/29 ip.
- --B010170131 Responds to NRC B00820 ltr re violations noted in IE Insp Rept 59-461/80-14 Corrective actions revision to process requirement sheet 5 individual performance records to be complisted by 801001. XOCH.L.U Illinois Power Co B0/09/19 2pp.
- 8010160268 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director. 80/09/30

- 8010170067 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-461/80-16. FIORELLI, 9 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/30. ip
- --8010170072 Responds to NRC 800828 ltr re violations noted in IE Insp Rept 50-461/80-16 Corrective actions: sys established to more adequately assure each design document used by company is properly reviewed. KUCH.L J Illinois Power Co. 80/09/17. 3pp
- 8010280452 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER.J C Region 3. Chicago. Office of the Director. 80/10/02 to
- 8010270026 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bulting " No specific action or response requested KEPPLER. J O. Region 3, Chicago, Office of the Director 80/10/10 lp.
- S Reportable occurrences. LERs & related correspondence
- 8010090204 PND-III-80-131 on 800711, stop work order will be placed on all electrical work because of had experience renoconformances & records. Evaluation is to be made of all electrical work for compliance w/requirements.

 VANDEL.T., FIORELLI, 0. Region 3. Chicago, Office of the Director 80/07/10 ip.
- 8010170185 Ack receipt of 800922 interim deficiency rept re failure of attachment welds of swing barriers dividing cabinets into bays during shipment FIDRELLIO Region 9. Chicago, Reactor Construction & Engineering Support Branch 80/09/30. ip.
- 8010280505 Interim deficiency rept re inadequate const controls & electrical raceway hanger installation Bixty-eight hangers found to deviate from design requirements. Bixteen deviations attributable to inadequate raceway installation procedures OERSTNER. W C Illinois Power Co 80/10/20 2pp.

U Congressional/Executive Correspondence

- 8010020561 Ack receipt of 800512 ltr expressing appreciation for NRC efforts to improve schedule re DL application. Case should be docketed in Sept. Every effort will be made to complete safety & environ review by const completion. DENTON.H.R. Office of Nuclear Reactor Regulation, Director 80/09/08. 2pp
- --8010020677 Expresses appreciation for efforts to improve schedule re OL application Imperative that Commission reach decision as soon as possible CRANE.D B. House of Rep. 80/05/12 ip.
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EIBENHUT, D. Ø Division of Licensing 80/07/19. 28pp.
- 8010070246 Forwards FR notice of receipt of application for CLs of availability of environ rept, of consideration of issuance of CLs to of apportunity for hearing, Also forwards notice of apportunity for public participation.

 SCHMENCER, A. Licensing Branch 3 80/09/23. ip.
- --801007024B Notice of receipt of application for DLs, of availability of applicant environ rept, of consideration of issuance of OLs and of opportunity for hearing Branch 3. 80/09/23 7pp.
- --8010070231 Notice of opportunity for public participation in proposed MRC licensing action on application by util for facilities + Licensing Branch 3, 80/09/23. Spp.
- 80(0270015 Forwards "Outdelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors." in response to 800714 request. W/o encl. BUCKLEY. B. C. Licensing Branch 3, 80/10/09, 2pp,

- 8010210375 Responds to NRC 800829 itr re acceptance review Util commits to providing responses on FSAR during Dec 1980 in form of amend to FSAR Addi info for environ rept will be provided during Jan 1981

 MULLER, 0 E Illinois Power Co 80/10/17 1p
- C Utility Environmental Report (ER), amends & correspondence
- 8010070246 Forwards FR notice of receipt of application for OLs. of availability of environ rept. of consideration of issuance of OLs & of opportunity for hearing Also forwards notice of opportunity for public participation
 SCHMENCER. A Licensing Branch 3 80/09/23 19
- --8010070248 Notice of recaipt of application for OLs. of availability of applicant environ rept. of consideration of issuance of OLs and of opportunity for hearing Branch 3 80/09/23 7pp
- Q Adjudicatory correspondence
- 8010070246 Forwards FR notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing Also forwards notice of opportunity for public participation
 SCHWENGER: A Licensing Branch 3 80/09/23 lp
- --80:007024B Notice of receipt of application for QLs, of availability of applicant environ rept, of consideration of issuance of QLs and of opportunity for hearing BCHHENCER. A Licensing Branch 3 80/09/23 7pp
- --8010070291 Notice of opportunity for public participation in proposed NAC licensing action on application by util for facilities

 * Licensing Branch 3 60/09/23 3pp
- H General correspondence
- B0100B0434 Requests that OH River Basin Commission be removed from mailing lists for facilities due to plant location Buggests that MS River Basin Commission be added to mailing lists JOERING, E A Ohio River Basin Commission B0/10/03 p
- O Inspection reports, IE Bulletins & correspondence
- B010060069 Bubmits response to IE Bulletin 80-19. Mercury-wetted suitches are not used in safety-related sys WULLER, O E Illinois Power Co 80/08/26 ip.
- 80:0090098 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Nautral Control Switches "Switches are not used in safety-related applications, only for testing while breater is in test position WULLER. G E Illinois Power Co 80/09/16 lp
- 801016026B Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Gualification of Class IE Equipment " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/30
- 8010280652 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/10/02
- 8010270026 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Boiting " No specific action or response requested MEPPLER. J G Region 3, Chicago, Office of the Director 80/10/10 is.
- S Reportable occurrences, LERs & related correspondence
- 9010090204 PNO-III-80-131 on 800711, stop work order will be placed on all electrical work because of bad experience renonconformances & rework. Evaluation is to be made of all electrical work for compliance w/requirements VANDEL, T., FIGRELLI, Q Region 3, Chicago, Office of the Director. 80/07/10, 19

- U Congressional/Executive Correspondence
- 8010020661 Ack receipt of 800512 itr expressing appreciation for APC efforts to improve schedule re OL application Case should be docketed in Sept Every effort will be made to complete safety & environ review by const completion DENION, H R Office of Nuclear Reactor Regulation, Director 80/09/08 2pp
- ~8010020677 Expresses appreciation for efforts to improve schedule re Q. application Imperative that Commission reach decision as soon as possible CRANE.D B House of Rep 80/05/12 ip
- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B010070339 Responds to NRC request for info re implementation of IH:-2 action plan requirements initiation levels of HPCI & RCIC should be separated so that RCIC sys will initiate higher water level than HPCI sys OALLAOHER, J. H. Philadelphia Electric Co. 60/10/02 App
- DOCKET 50-464 FULTON GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8010070337 Responds to NRC request for info re implementation of TMI-2 action plan requirements Initiation levels of HPC1 & RCIC should be separated so that RCIC sys will initiate higher water layer than HPC1 sys GALLAGHER. J. W Philadelphia Electric Co 80/10/02 6pp
- DOCKET SO-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

 G Adjudicatory correspondence
- 8010090074 First set of interrogatories & request for production of documents soliciting info re results of accident at site, emergency plan & demographics Certificate of Bvc encl Related correspondence BCHVEBBLER, W.J. Affiliation Unknown 80/09/05 6pp
- 8010140019 Comments on proposed rules 10CFR50 & 51 re withdrawal of proposed Annex to App D of 10CFR50 Commission has engaged in balancing amount of delay that would be involved in adding review against value to public safety
 DDHERTY, J F Affiliation Unknown 80/09/06 2pp
- B010010007 Notice of substitution of counsel S Plattman & D Preislar will appear in proceeding in lieu of R Lowerre Notices of appearances & Certificate of Svc enc!
 PREISTER, D , PLETTMAN. S Texas. State of 80/09/23 5pp
- 8010010219 Response to ASLB 800917 order for 801201 hearings Proposes trial of contentions in order listed by NRC in Exhibit A to NRC 800718 ltr Cm-line dates for facility are now projected for 1988 Certificate of Evc encl COPELAND, J. O., NEWMAN, J. R. Houston Lighting & Power Co COPELAND, J. O. Baker & Botts 80/09/25 5pp
- 8010020037 Advises that applicant brief in response to D Springer B00702 natice of appeal will be hand-delivered to ASLAB & sent by guaranteed mail to D Springer ASLB svc list was inadvertently used for 800722 svc Related correspondence MCGARRY.J M Debevoise & Liberman 80/09/25 lp
- 8010020724 Order correcting ASLB 800926 order First sentence should read Lemmer 5 contention in lieu of Lemmer 1 MQLFE.8 J. Atomic Safety and Licensing Board Panel 80/09/30 Lp
- 8010030448 Order granting extension until B01104 for I Doherty to reply to NRC L applicant motions for summary disposition TX PIRO shall file motions for summary disposition by 801008, 20 days after which applicant by NRC may respond WOLFE, B J. Atomic Safety and Licensing Board Panel 80/10/01 4pp
- B010050001 Certifies svc of 18 pleadings & related documents on B01002 BLACK-R L Hearing Branch 3 80/10/02. 3pp
- B010060006 Response in support of applicant B00804 motion for summer; disposition of Potthoff Contention 6 NEPA does not require consideration of remote & speculative alternatives beyond reasonable bounds.

 BLACK.R L Hearing Branch 3 80/10/02 Spp

- --B010040007 Statement of matl facts re absence of issues to be heard, in support of applicant mation for summary disposition of Potthorf Contention & Economic feasibility of marine biomass is uncertain & sys may produce serious environ consequences
 4 Hearing Branch 3 80/10/02 2pp
- --8010060009 Affidavit in support of applicant motion for summary disposition of Potthoff Contention 6 Marins biomass production is not viable alternative at present time Prof qualifications encl KARCIRUK,P Oak Ridge National Laboratory 80/09/25 15pp
- 8010060015 Partial response to UF Doherty 12th,13th & 14th sets of interrogatories Addresses Contentions 12,24 & 44 re occurrence of water hammer & generic review of reactor manual control sys design Affidavit encl HDDN:C N Assistant Director for Licensing 80/10/02 5pp
- 8010060301 Forwards transcript of 801001 taleon taken from tape recording made by applicant counsel at request of Chairman Molfe RASKIN,D B Lowenstein, Newman, Reis, Axelrad & Toll RASKIN, D B Houston Lighting & Power Co 80/10/02 Ip
- 8010070005 Response in opposition to intervenor Marrack 800912 motion for summary disposition of Contention 2(c) parallel to Contention 76 Denial would allow presentation of record & subsequent correction of deficiency in FEB & final suppl BLACK.R L Hearing Branch 3 80/10/02 6pp
- --8010070007 Statement of matl facts re presence of genuine issue to be heard, in opposition to summary disposition of Marrack Contention 2(c) Impacts of transmission lines on migratory waterfoul has been addressed in FSS & final suppl 4 Hearing Branch 3 80/10/02 ip
- --B010070009 Affigavit affirming NRC position that impacts of transmission pines on waterfowl will be minimized by applicant proposed routing which has no superfor alternative available Prof qualifications encl
 REED.R M Dak Ridge National Laboratory 80/10/02. App.
- 8010070029 Response in opposition to TX PIRO undated motion for summary disposition of Contention i Draft Suppl 2 to FES is in direct conflict w/intervenor conclusion re Bouth TX site environ preference as opposed to Allens Creek site BLACK:R L Hearing Branch 3 80/10/02 App
- --B010070033 Btatement of mati facts re presence of genuine issue to be heard, in opposition to summary disposition of TX PIRO Contention i Aliens Crock site preferable re aquatic ecology, water use & sociosconomic impacts
 BLACK, R. L. Hearing Branch 3 80/10/02 ip
- --B010070035 Affidavit in support of Allens Creek site preferential rates in comparison w/South TX project re terrestrial ecology bland use Prof qualifications & supporting documentation encl
 MODN.C W Division of Licensing 80/10/02 21pp
- B010070495 Response in opposition to TX PIRQ 800912 motion for summary disposition of Contention AC 8 Powerplant & Industrial Fuel Use Act of 1978 prohibitions & restrictions present factual & legal bar for natural gas alternative BLACK.R L. Hearing Branch 3 80/10/02 8pp
- --B010070508 Statement of mati facts re presence of genuine issue to be heard in opposition to TX PIRO motion for summary disposition of Contention AC 8 Natural gas generation does not constitute viable alternative + Hearing Branch 3 80/10/02 ip
- --8010070517 Affidavit attesting to uncertainty of future price & availability of natural gas generation Prof qualifications encl.
 DICK, J { } Dak Ridge Mational Laboratory 80/10/01 4pp
- --8010070523 Affidavit demonstrating that issue of nuclear vs natural gas costs weigh in favor of nuclear generation per NUREG-0480 of Dec 1978, "Coal & Nuclear Comparison of Gost Generating Baseload Electricity by Region " Prof qualifications encl. ROBERTS.J O Utility Finance Branch (formerly Antitrust & Inéamnity) MOON.C W Division of Licensing 80/10/02 8pp
- 8010070576 Response in opposition to TX PIRO 800806 motion for summary disposition & in support of applicant 800804 motion for summary disposition re TX PIRO addi Contention 30 BLAGK.R L. Hearing Branch 3 80/10/02 6pp

- ---8010070381 Statement of matl facts re absence of genuine issue to be heard Aircraft flying over or near facility will not suffer failure of guidance sys circuits due to airborne radiological emissions

 4 Hearing Branch 3 80/10/02 2pp
- --8010070588 Affidavit re TX PIRQ motion for summary disposition of Addl Contention 50 Dose rate & total dose of accidental airborne radioactivity are sufficient to cause electronic malfunction Prof qualifications encl SINTSOALLI.A A. FERRELL.C Siting Analysis Branch READ.J B J Accident Evaluation Branch 80/10/02 14pp
- 8010100066 Response in opposition to motions for summary disposition of airplane crash issue, Full-scale tests must be conducted to show effect of radiation on solid state electronics W/ Certificate of Svc encl

 8COTT, J M Texas Public Interest Research Group 80/10/02 7pp
- 8010100320 Provides status & history of CP proceeding,in response to 800917 request for early hearing date Licensing Board determined that hearing could not commence until mid-Jan 1981 due to conflict in hearing schedules.

 BICKWIT,L. Office of the General Counsel. 80/10/02 2pp
- ---8010100328 Order requesting to be advised on feasibility of CP hearing schedule & on past & current projected on-line dates for facility | MOLFE.B J Atomic Safety and Licensing Appeal Panel. 80/09/17
- 8010149743 Memorandum of law supporting applicant responses to TX PIRO 800806 & 0916 & D Marrack 800911 motions for summary disposition Intervenors' failure to establish all evidence leads to irrefutable conclusion Certificate of Svc encl COPELAND.J G , NEWMAN,J R Houston Lighting & Power Co COPELAND,J G Baier & Botts 80/10/02 13pp
- --8010140550 Response in opposition to TX PIRG motion for summary disposition of TX PIRQ Contention 1 re sits comparison. Failure to demonstrate significance of farmland pre-emption is fatal defect List of remaining issues in dispute encl COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co, COPELAND, J G Baker & Botts 80/10/02 18pp
- --8010140554 Affidavit re Ailens Creek vs Bouth TX Project sites Cost comparison tabulation uncl MCCUISTION.R M Houston Lighting & Power Co 80/09/30 12pp
- --8010140557 Affidavit re site evaluation.Util analysis looks only to cost, not to benefit Curriculum vitae encl HUSSEY, J R Dames & Moore 80/09/30 12pp
- --B010140366 Affidavit re sources of groundwater for facility Lakes Conroe, Houston & Livingston can supply surface water to meet city demands through yr 2000 Curriculum vitae, excerpts of C Johnson & Baxion depositions & Certificate of Svc encl VANSICKLE, D Turner, College & Braden, Inc B0/09/29 44pp
- --8010140573 Response in opposition to TX PIRO 800712 motion for summary disposition of TX PIRO addi Contention 8 re natural gas alternative As matter of law, util cannot construct new gas fired plants COPELAND, J O , NEWMAN, J R Houston Lighting & Power Co COPELAND, J O Bater & Botts 80/10/02 8pp
- --8010140578 Affidavit re natural gas plant alternative. Util not automatically entitled to FUA exemption because no nonattalinment areas exist in Houston. No environ exemptions available to util

 MCGUIRE.W F. Howston Lighting & Power Co 80/09/29 5pp
- --8010140582 Affidavit to economic comparison between competing generation alternatives Util does not qualify for any exemptions to Fusl Use Act which would allow unlimited use of gas for unlimited time W/Cartificate of Svc.
 BUY.J.D Houston Lighting & Power Co BO/09/30, 10pp.
- --B0101403B7 Response in opposition to TX PIRG motion for summary disposition of TX PIRO addl Contention 50 re letching. Applicant mati statement of undisputed facts remains unchanged CDPELAND. J G , NEWMAN, J R Houston Lighting & Power Co CDPELAND. J G , Sater & Botts B0/10/02 13pp
- --8010140574 Affidavit re latching. In order for radioactive emissions to effect electronics on aircraft, aircraft would have to park at site boundary for extended period. Certificate of Bvc encl
 SUKPTER, J. R. Houston Lighting & Power Co 80/09/11. 16pp.

- --B010140599 Response in opposition to D Marrick B00911 motion for summary disposition of Marrick Contention 2(c) Motion lacks statement of facts or admissible evidence & exceeds scope of contention Certificate of Svc encl
 COPELAND, J G , NEWMAN J R Houston Lighting & Power Co
 COPELAND, J G , Bater & Botts 80/10/02 14pp
- --8010140402 Affidavit re impact of plant on waterfowl & other environ effects Line no longer extends over lake & thus does not nead to be moved Prof qualifications encl SGRLICHT/F 0 Houston Lighting & Power Co 80/10/01 20pp
- 8010080247 Memorandum & order for 810112 commencement of environ evidentiary hearing Parties shall file testimony by 801218 Second prehearing conference will be held on 801202 LINENDERCER, 0. WOLFE, S. J. Atomic Safety and Licensing Board Panol 80/10/03 Epg
- 8010140009 Notice of withdrawal in proceeding Certificate of Svc encl 80NINXI,8 M Hearing Branch 3 80/10/07 3pp
- 8010160016 Motion for summary disposition of TX PIRO Contentions AC 1, AC 12.AC 31.2.4.5,7 & 8 re barge slip, cooling lake, atternative sources & technical qualifications Certificate of Svc encl Related correspondence 8COTT, J M Texas Public Interest Research Group 80/10/08 3pp
- 8010140518 Advises that NRC does not engage in exparte communications w/ABL9 mambers Misunderstanding based on ASLB 800717 order but clarified by ASLD 801003 order BLACK.R L Hearing Branch 1 50/10/09 2pp
- 8010150072 Response to first set of interrogatories. Either NRC has not performed analysis postulated in interrogatory or applicant has not yet provided info for NRC review Second suppl to FES schedulef for Oct 1980 publication W/Certificate of Syc MGON.C N Assistant Director for Licensing 80/10/09 lipp
- 8010160020 Response in opposition to Doherty 800930 motion to subpoena Sections 2,5-6.7,11.18.21 & 25 of Reed Rept Motion mooted by applicant agreement to provide info & improperly filed Cartificate of 8vc encl Related correspondence GULP:R H , COPELAND:J O Houston Lighting & Power Co CULP:R H Lowenstein, Newman, Reis, Axelrad & Toll 80/10/10 7pp
- 8010160784 Amended response to first set of interrogatories Info includes identity of individuals directing site selection Certificate of Svc encl Related correspondence RASKIN.D B. COPELAND.J G. Houston Lighting & Power Co. RASKIN.D E. Lowenstein, Newman, Reis, Azelrad & Toll. 80/10/14 4pp
- 8010200481 Clarifies 801003 memorandum 5 order Initial phase of 810112 hearing will be devoted exclusively to taking of evidence reenviron matters Intervenor direct testimong must be filed no later than 801218 Ltr sent to all parties 40LFE.S J Atomic Safety and Licensing Board Panel 80/10/15 ip
- 8010210272 Beeks clarification of ASLB 801003 memorandum & order scheduling 810112 environ hearing, re early completion of litigated issues & deferral of emergency planning BLACK-R L Hearing Branch 3 80/10/17 2pp
- B010220325 Response taking no position re JF Boherty 800930 motion to subpose a Sections 2,5,6,7,11,18,21 & 25 of GE Read Regt Motion most per Commission B01009 order re availability of rept per Black Fox decision Certificate of Svc encl. BLACK.R L Hearing Branch 3 80/10/20. 4pp
- 8010240570 Informal request for addl responses to first set of interrogatories & requests for production of documents, in lieu of motion to compel Includes second set of interrogatories directed to util Related correspondence SCHUESBLER, W.J. Affiliation Unknown 80/10/20 2pp
- 8010240033 Order clarifying 801003 memorandum & order If issues are settled sooner that contemplated subsequent issues will be moved up Emergency planning contention deleted from schedule Related testimony need not be filed by 801218 WOLFE,8 J. Atomic Safety and Licensing Board Panel 80/10/21 2pp
- 8010270522 First set of interrogatories & requests for production of documents directed to E Cumings.R Oriffith.L Johnston & R Lemmer re consolidated contention on effects of low-level radiation W/Certificate of Bvc Related correspondence COPELAND.J O. NEWMAN.J R Houston Lighting & Power Co COPELAND.J O. Baker & Botts. 80/10/22 7pp

- 8010280020 Response in opposition to TX PIRC motion for summary disposition served on 801007 instead of 801008 No good cause presented re late filling Motion fallacious & argument beyond admitted contentions W/Certificate of 8vc CDPELAND, J G , NEMMAN, J R Houston Lighting & Power Co CDPELAND, J G Baker & Dotts 80/10/22 10pp
- 8010270374 Response in opposition to JF Doherty 801013 motion to present direct testimony on TX PIRO contentions No good cause shoun for untimely filing Certificate of Svc and COPELAND, J Q , NEMMAN, J R Houston Lighting & Power Co COPELAND, J O Baker & Botts 80/10/24 11pp
- B010300060 Order scheduling 801202 second prehearing conference in Houston, TX re environ issues Public may attend w/o limited appearance statements Statements will be received at future evidentiary bearing WOLFE, S J Atomic Safety and Licensing Board Panel 80/10/27 2pp
- 8010310048 Response in opposition to JF Doberty untimely Contention 50 Intervenor failed to establish connection between design & alleged safety concern of coolent circulation degradation Certificate of Svc encl
 NEWHAN, J R . COPELANDI J G Houston Lighting & Power Go NEWHAN, J R
 Lowenstein Newman, Reis, Azelrad & Toll 80/10/27 Spp
- B010310051 Response in opposition to JF Doherty 801022 motion for addition to respond to motions for summary disposition No further extensions allowed per ABLE 801001 order Certificate of Svc enc!
 NENMAN.J R. CDPELAND.J Q. Houston Lighting & Power Co NEWMAN.J R Lowenstein, Newman. Reis, Areirad & Toll 80/10/27 4pp
- 8010300599 Response in opposition to JF Doherty motion to Join rejected Contention i w/contention admitted in ASLB 800926 order rehealth effects of low level radiation Contention challenges regulations & ASLB Feb 1979 order Certificate of Svc encl NEWMAN, J R , COPELAND, J O Houston Lighting & Power Co NEWMAN, J R , Lowenstein, Newman, Reis, Aselrad & Toll 80/10/28, 5pp
- 8010310446 Response stating no objection to JF Doherty 801022 motion for extension until 801115 to file remaining responses re motions for summary disposition Responses serve useful purpose re issues in controversy Certificate of Svc encl BLACK.R L Hearing Branch 3 80/10/29 4pp
- H General correspondence
- 8010030497 Requests notification of public hearing on facility ARONSON, W O Affiliation Unknown 80/09/25 ip
- 8010240404 Comments on new interim policy on Class 9 accidents & rulemaking on reactor siting criteria re facilities Commission should direct ASLB to include Class 9 accidents in suppl to EIB 8COTT.J. Affiliation Unknown 80/10/22 ip
- U Congressional/Executive Correspondence
- 8010080662 Provides history status & schedule for hearings in facility proceeding, in response to 800910 request DIRCKB,N J. Office of the Executive Director for Operations 80/09/26 2pp
- 8010080664 Provides history, status & schedule for hearings in facility proceeding, in response to 800912 request DIRCKS, H J Office of the Executive Director for Operations 80/09/26 2pp
- 8010100320 Provides status & history of CP proceeding, in response to 800917 request for early hearing date Licensing Board determined that hearing could not commence until mid-Jan 1981 due to conflict in hearing schedules.

 BICKWIT, L. Office of the General Counsel, 80/10/02 2pp.
- --8010100328 Order requesting to be advised on feasibility of CP hearing schedule & on past & current projected on-line dates for facility LHOLFE, B J Atomic Bafety and Licensing Appeal Panel 80/09/17. 200
- DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing. 80/09/19 28pp.

BO10240404 Comments on new interim policy on Class 9 accidents & rujemaking on reactor siting criteria re facilities
Commission should direct ASLB to include Class 9 accidents
in suppl to EIB
BCOTT, J Affiliation Unknown 80/10/22 ip

U Congressional/Executive Correspondence

- 6010080462 Provides history, status & schedule for hearings in facility proceeding, in response to 800910 request DIRCKS:H J Office of the Executive Director for Operations 80/09/26 2pp
- BO10080664 Provides history, status & schedule for hearings in facility proceeding in response to 800912 request DIRCKS.H J Office of the Executive Director for Operations 80/09/26 2pp
- DOCKET 90-471 PILORIM NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010080401 "NEPOOL Forecast for New England, 1980-1995 " BMITH, J.R. Boston Edison Co. 80/04/01 32pp
- 8010080406 "Long-Range Forecast of Electric Power Noeds & Requirements, Annual Suppl 1-D.1980-09," Vol 1 LYDON, J H , DESMOND, J J Boston Edison Co 80/05/01 170pp
- --8010080408 "Long-Range Forecast of Electric Fower Needs & Requirements, Annual Suppl 1-D.1780-87," Vol 2 DAKRELL, C B , DESMOND, J J Boston Edison Co 80/05/01 47pp
- 8010220099 Forwards errata sheets amending 800905 itr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D & Division of Licensing 80/09/19 28pp
- B Utility Preliminary Safety Analysis Report. amends
- 8010140392 Forwards Amend 40 to PSAR Amend incorporates revised Section 13 3, emergency planning, in response to final emergency planning rule HOWARD, J E Boston Edison Co BO/10/10 Spp
- --8010140386 Amend 40 to PSAR Amend incorporates revised Section 13 3.

 emergency planning in response to final emergency planning
 rule & provides info concerning evacuation time estimates,
 per (RRC 800702 ltr
 4 Boston Edison Co 80/10/10 246pp.

G Adjudicatory correspondence

8010070372 Order, admitting into need for power record, applicant Ethibits 2i A & B & 22, in response to State of MA mution, relong-range forecasts GOODHOPE, A. C Atomic Safety and Licensing Board Panel. 80/10/02 to

H General correspondence

- 80:00:00:00 Discusses emergency planning regulations, in response to 800:18 ltr re L Boyd concerns FEMA is responsible for adequacy of emergency preparedness in states & communities around nuclear plants DIRCKS: U J Office of the Executive Director for Operations 80:09/20 2pp
- ---8010100111 Requests response to encl L Boyd inquiry about emergency preparedness around facility
 HECKLERIM M House of Rep 80/04/18 2pp

DOCKET 50-472 PILGRIM NUCLEAR POWER STATION, UNIT 3

H General correspondence

BO10100106 Discusses emergency planning regulations, in response to BO0418 ltr re L Boyd concerns FEMA is responsible for adequacy of emergency preparedness in states & communities around nuclear plants
DIRCKB.I/J Office of the Executive Director for Operations BO/09/30 2pp

- --8010100111 Requests response to encl L Boyd inquiry about emergency preparedness around facility HECKLERN M House of Rep 80/04/18 2pp
- DOCKET STN-50-477 ATLANTIC GENERATING STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010270037 Responds to FDIA request for three categories of info re fees for withdrawn CP % OL applications Forwards App A documents SECY-364A & JF Ahearne response sheet withheld (ref FDIA Exemption 5) FELTON J % Division of Rules and Records 80/10/15 2pp
- --8010270073 Act receipt of 800108 ltr & 800123 Invoice 362-80 Declines payment of invoice No legal basis exists for NRC to seek payment when application was withdrawn prior to issuance of CP & bestowal of benefit to applicant PETERMAN, P C Public Service Electric & Gas Co of New Jersey 80/04/22 2pp
- --8010270151 Notifies of completed assessment re review of costs for CP & OL actions Data sheets used to determine fee charges enci BERKOW.H N Office of Nuclear Reactor Regulation, Director 79/10/30 4pp
- --8010270163 Provides estimated ACRS prof manpower expended for facility applications Most data has been reconstructed 8 was derived from many sources FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 79/03/28, 1p
- --8010270170 Responds to 790321 request for prof man-hours expended on sue sponte review of ASLB action re facilities No prof ran-hours were expended ROSENTHAL. A B Atomic Safety and Licensing Appeal Panel 79/03/21 1p
- --B010270180 Responds to request for actual mangower data re facilities ASLB considers proceeding contested case Maint of actual mangower records is not applicable to ASLB FITTI.C J Atomic Safety and Licensing Spard Panel 79/03/27
- DOCKET STN-50-478 ATLANTIC GENERATING STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010270037 Responds to FOIA request for three categories of info re fees for withdrawn CP & OL applications Forwards App A documents SECY-364A & JF Ahearne response sheet withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 80/10/15. Rpp
- --8010270093 Ack receipt of 800108 ltr & 800123 Invoice 362-80 Declines payment of invoice No legal basis exists for NRC to seek payment when application was withdrawn prior to issuance of CP & bestowal of benefit to applicant PETERMAN-P C. Public Service Electric & Cas Co of New Jersey 80/04/22 2pp
- --8010270151 Notifies of completed assessment re review of costs for CP & GL actions Data sheets used to determine fee charges encl
 BERKON, H N Office of Nuclear Reactor Regulation, Director 77/10/30 4pp
- --8010270163 Provides estimated ACRS prof manpower expended for facility applications Most data has been reconstructed & was derived from many sources.
 FRALEY.R.F ACRS Advisory Committee on Reactor Safaguards 79/03/28 ip
- --B010270170 Responds to 790321 request for prof man-hours expended on sua sponte review of ASLB action re facilities No prof man-hours were expended.
 ROSENTHAL. A B Atomic Safety and Licensing Appeal Panel 79/03/21 1p.
- --8010270180 Responds to request for actual manpower data re facilities ASLB considers proceeding contested case Maint of actual manpower records is not applicable to ASLB FITTI.C J Atomic Safety and Licensing Board Panel 79/03/27

- DOCKET STN-50-482 HOLF CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISE/HUT, D G Division of Licensing 80/09/19 28pp
- 8010070497 Requests that application fixed by util 791019 & notice published in FR on 800826 be amended to reflect fact that util is seeking issuance of CL only for Unit 1 Lists three items for correction in amended notice BRYAN.J K Union Electric Co 80/10/01 3pp
- --8010070505 Discusses planned review of GL applications for four BNUPPB duplicate plants; per util 780130 & 0530 ltrs & 780414 meeting Forwards NUREG-0272, we opportunities for improvement in nuclear power plant licensing, for comment W/o encl DEMTON, HR Office of Nuclear Reactor Regulation, Director 78/08/09 6pp
- 8010160346 Submits additinfore fuel load & commercial operating date, in response to NRC 800711 ltr Fuel loads rescheduled for Apr 1983 & commercial operation for Apr 1984 KOESTER.G L Kansas Gas & Electric Co 80/10/08 lp
- 8010160548 Forwards to WP Hasss, Revision I to GA program descriptions, incorporating agreements, commitments & clarifications re SHUPES OA programs as summarized in 800414,0527 & 0728 transmittals
 SETKEN.8 J Standardized Nuclear Unit Power Plant System 80/10/09
- K Utility Final Safety Analysis Report (FBAR) & amends
- 7910120238 Chapter I to SNUPPS FSAR, "Introduction "
 * Standardized Nuclear Unit Power Plant System 79/10/02 100pp
- 7910120265 Chapter 6 to SNUPPS FSAR, "Engineered Safety Features"
 * Standardized Nuclear Unit Power Plant System 79/10/02 400pp
- O Inspection reports, IE Bulletins & correspondence
- BO10210272 Bubmits add1 response to IE Bulletin 77-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe "Manufacturers have not furnished specified pipe matts for use in sys in which design hoop stresses exceed ASME Code. BEIKEN S J Standardized Nuclear Unit Power Plant System B0/08/20 2pp
- B010160024 Forwards IE Insp Rept 50-482/80-17 on 800Bit-14 No noncompliance noted BEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/25 2pp
- --8010160027 IE Insp Rept 50-482/80-17 on 800811-14 No noncompliance noted Major areas inspected const & work activities rereactor coolent piping CROSSMAN, N A. TOMLINSON, D P. Region 4. Dallas, Office of the Director HALL, R E. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/08/22 3pp
- 80:0020189 Responds to IE Bulletin 80-14.Rosemount Model 1:51 or 1:52 pressure transmitters are not used in any safety-related applications PETRICK,N A Standardized Nuclear Unit Power Plant System 80:08/26 ip
- 80:00:0835 Responds to 16 Bulletin BO-19 Hercury-wetted relays are not used in matrix logic in reactor trip circuitry Marcury-wetted relays are used in Westinghouse 7300 protection sys equipment & are hermatically sealed PETRICK, N A Standardized Nuclear Unit Power Plant System 80/08/29 is
- 8010270021 Forwards IE Insp Rept 50-482/80-13 on 800701-31, No noncompliance noted SEIDLE-W C Region 4. Dalkas, Reactor Construction & Engineering Support Branch 80/09/03 2pp
- --8010270D22 IE Insp Rept 50-482/80-13 on 800701-31 No noncompliance noted Major areas inspected; followup to previous insp findings, safety-related concrete placements & pipe welding & QC personnel qualifications

 DERGOC R , HUBACEK, M. O , CROSSMAN, W A Region 4, Dallas, Office of the Director 80/07/04, 14pp.

- BO10010B44 Responds to IC Bulletin BO-20 Westinghouse Type W-2 control switches are not used in safety-related applications PETRICK, N A Btanderdized Nuclear Unit Power Plant System BO/09709 ip
- B010080595 Responds to IE Bulletin 80-19. "Maint of Adequate Min Figure Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Discusses potential deficiency repostulated transient PETRICK, N A Standardized Nuclear Unit Power Plant System B0/09/15 2pp
- B010060146 Ack receipt of 800828,0908 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-482/80-08 50-482/80-19 BEIDLE:() C Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/09/18 1p
- --8010060149 Responds to NRC 800820 ltr re violations noted in IE Insp Rept 50-482/80-08 Comjective actions response to IE Insp Rept 50-482/80-15, dtd 800828, adequately addresses findings KGESTER: G L Kansas Cas & Electric Co 80/09/08 ip
- 8010160104 Forwards Ruppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required SEYPRIT, K V Region 4, Dallas, Office of the Director 80/09/30
- 8010270520 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/10/02
- S Reportable occurrences, LERs & related correspondence
- 8010080555 Responds to IE Builetin 80-18, "Maint of Adequate Min Flow Through Centrifugal Changing Pumps Following Becondary Bide High Energy Line Rupture " Discusses potential deficiency re postulated transient PETRICK, N A Standardized Nuclear Unit Power Plant System 80/09/15 2pp
- B010270199 Ack receipt of B00915 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture CARLBON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/09/24 ip
- --8010270208 Interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Design changes being evaluated Final rept will be provided in first quarter 1981 PETRICK,N A Standardized Nuclear Unit Power Plant System 80/09/15 2pp
- 8010220605 PNO-IV-80-035, on 801007, employee of subcontractor was seriously injured when crane boom fell on employee Employee suffered multiple fractures & contusions & was immediately taken to hosp VANDEL, TE; CROSSMAN, WA Region 4, Dallas, Office of the Director 80/10/09 19
- U Congressional/Executive Correspondence
- 8010020366 Provides status of licensing review in response to 800807 request FBAR acceptance review completed 800731 Acceptance review of environ rept underway & scheduled for completion late 8ept 1780 DERCKS.W.J. Office of the Executive Director for Operations 80/09/19 1p
- ---8010020374 Requests to be kept informed of developments described in each news clipping re-facility licensing review OLICKKAN, D. House of Rep., Science & Technology, 80/08/07 299
- DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 itr which provided pracliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISENHUT, D Q. Division of Licensing 80/09/19 28pp
- 8010020683 Act receipt of transcript on public hearing re proposed wastewater discharge permit for anytron rept review. DENION.H R Office of Nuclear Reactor Regulation, Director. 80/07/23 ip

- ~~B010020693 Forwards transcript of State of MO 800716 public hearing re proposed wastewater discharge permit for environ rept review TEASDALE, J P Missouri, State of 80/08/22 1p
- 8010070497 Requests that application filed by util 791019 & notice published in FR on 800826 be amended to reflect fact that util is seeking issuance of OL only for Unit 1 Lists three items for correction in amended notice BRYAN.J K Union Electric Co 80/10/01 3pp
- --8010070506 Discusses planned review of OL applications for four SNUPPS duplicate plants.per util 780130 & 0530 ltrs & 780414 meeting Forwards NUREG-0292.re opportunities for improvement in nuclear power plant licensing, for comment W/o encl DENTON, H R Office of Nuclear Reactor Regulation, Director 78/08/09 App
- 8010180548 Forwards to NP Haass, Revision 1 to QA program descriptions, incorporating agreements.commitments & clarifications re BNUPPS QA programs as summarized in 800414,0527 & 0728 transmittals BEIKEN,B.J Standardized Nuclear Unit Power Plant Bystem 80/10/09

O Adjudicatory correspondence

- B010070465 Requests correction of typographical errors re B00922 petition for leave to intervene REED.J G Affiliation Unknown 80/09/28 Ip
- 8010090048 Reply in opposition to applicant 800925 response to author 800910 petition to intervene Concedes original petition was inadequate but second petition timely filed Requests full party participation Certificate of 8vc encl RECO.J C. Affiliation Unknown 80/10/01 3pp.
- 8010070380 Notice of astablishment of ASLO to preside & ruls in QL proceeding if hearing ordered JP Glesson appointed chairman. Lists QC Bright & JR Kline as members. LAZO,R M Atomic Bafety and Licensing Board Panel. 80/10/02 2pp
- B010090045 Reply to NRC B00925 response to author B00910 petition to intervene Original petition inadequate Requests permission to renew & resubmit petition.Certificate of Svc encl REED.J G Affiliation Unknown 80/10/02 3pp
- BD10080251 Response in opposition to League of Women Voters B00918 & 19 requests for public hearing Requirements re standing & Interest not met Purely sconomic interest as taxpayers not sufficient per ALAB-470 Certificate of Svc encl BAXTER.T.A. CHARNOFF.0 Union Electric Co. BAXTER.T A Shaw, Pittman, Potts & Troubridge. 80/10/03 ópp
- BO10140541 Response in support of PBC of MO participation as interested state if hearing ordered No hearing required in absence of bona fide intervenor Certificate of Bvc and BAXTER, T A . CHARNOFF, O Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trombridge 80/10/07 4pp
- 80:01500B2 Response in opposition to MJ Reilly & League of Homen Voters of Mo 8009IB & 19 requests to intervene Neither party seeks intervention as fall party Hearing not required Limited appearance statements acceptable.
- 8010130401 Forwards 801001 ltr from util to HR Denton, requesting issuance of amend to NRC notice in proceeding.

 BAXTER, T. A. Shew, Pittman, Potts & Trombridge 80/10/10, 1p
- 8010160025 Response in opposition to Coalition for Environ. 8t Louis Region. Missourians for Bafe Energy. Craudad Alliance & K Drey 800925 Joint petition to intervene Neither standing nor interest shown. Certificate of Svc encl BAXTER. T. A. CHARNOFF. 9 Union Electric Co. BAXTER. T. A. Shew. Pittman. Potts & Troubridge 80/10/10 10pp.
- 8010160540 Response in support of PBC of MO B00922 petition to intervene as representative of state in event hearing is held. Certificate of Bvc encl MCGURREM.H J Hearing Branch (80/10/14 3pp
- 8010200665 Notices of appearance in proceeding Certificate of 8vc encl CHARNOFF.0 , BAXTER.T A , BERNSTEIN.D.L Union Electric Co 80/10/14 5pp.

- 8010200671 Response in opposition to JO Reed 800922 petition to intervene Requirements of 10CFR2 714 not met Certificate of Svc encl BAXTER, T A., CHARNOFF, O Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 80/10/14 4pp
- 8010170365 Response in support of K Drey 800925 petition to intervene interest & aspects requirements satisfied No position taken re aspects as contentions HJ McGurren notice of appearance & Certificate of Svc encl Hearing Branch 1 80/10/15 13pp
- 8010200166 Response in support of JG Reed petition to intervene, received 800910 Petitioner satisfied interest & aspects requirements No opinion expressed re contentions Cartificate of 8vc encl LESBY.R P Anti 80/10/16 10pp Antitrust Division MCOURREN, H J Hearing Branch 1
- 8010270387 Submittal of 801022 amended petition to intervene & request for hearing Requests free evc of future documents M/o encl REED, J O Affiliation Unknown 80/10/22 ip
- 8010290405 Amended petition to intervene & request for hearing questioning applicant financial capability to implement requirements Nineteen affidavits of interested citizans, supporting documents. Certificate of Svc & appearance encl REED, J O Affiliation Unknown 80/10/22 37pp
- 8010300072 Addendum to 800925 petition to intervene H/Certificate of Syc & affidavits of members of Coalition for Environ Crawdad Alliance & Missourians for Bafa Energy in support of intervention
 DREY, K Affiliation Unknown 80/10/25. App
- G Inspection reports, IE Bulletins & correspondence
- 8010010376 Forwards IE Insp Rept 50-483/80-20 on 800701-31 & notice of violation FIGRELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8010010379 Notice of violation from insp on B00701-31.

 * Region 3, Chicago, Office of the Director B0/08 BO/OB/13 1p
- --8010010383 IE Insp Rept 90-483/80-20 on 800701-31 Noncompliance noted tools used during fabrication of stainless steel piping sys not properly identified Failure to assure corrective action taken precludes repetition of adverse conditions.

 HANSEK, H A , KNOP R C Region 3, Chicago, Office of the Director BO/08/13 ip
- 8010060122 Forwards IE Insp Rept 50-483/80-19 on 800715-18 & notice of violation
 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/08/18 2pp
- --8010060126 Notice of violation from insp on 800715-18 # Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/08/18 2pp
- --B01004012B IE Insp Rept 50-4B3/80-19 on 800715-1B Noncompliance noted, failure to establish requirements for installation of battery racks & procurement of matl that did not conform to purchase space NESCOTT.H M , NAIDU.K R , KNOP.R C Region 3. Chicego, Office of the Director 80/08/18 15pp
- B010210292 Submits add1 response to IE Bulletin 79-03A, "Longitudinal Meld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe "ManuPacturers have not furnished specified pipe matle for use in sys in which design hoop stresses exceed ASME Code SEIKEN, S J Standardized Nuclear Unit Power Plant Egstem B0/08/2 BO/08/20.
- 8010060034 Requests that enci corrected page be substituted for incorrect page in NRC 800818 ltr re IE Insp Rept 50-483/80-19 on 800715-18 FIORELLIA Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/21 1p
- --8010060037 Corrected page to NRC 800818 ltr re IE Insp Rept 50-483/80-19 on 800715-18 FIORELLI.0 Region 3. Chicago. Office of the Director 80/08/21

- 8010020189 Responds to IE Bulletin 80-16.Resembnt Model 1151 or 1152 pressure transmitters are not used in any safety-related applications PETRICK, N A Standardized Nuclear Unit Power Plant System 80/09/204 to
- 80(0010835 Responds to IE Bulletin 80-19 Mercury-wetted relays are not used in matrix logic in reactor trip circuitry Mercury-wetted relays are used in Westinghouse 7300 protection sys equipment & are hermatically sealed PETRICK,N A Standardized Nuclear Unit Power Plant System 80/08/29. 1p
- B010D10B44 Responds to IE Bulletin B0-20 Westinghouse Type W-2 control switches are not used in safety-related applications PETRICK N A Standardized Nuclear Unit Power Plant System. B0/09/09 ip
- 8010160244 Forwards IE Insp Rept 50-403/80-21 on B00826-29 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/12 2pp.
- --B010160250 IE Insp Rept 50-483/80-21 on 800826-29. No nancompliance noted Major areas inspected: followup of 10CFR30 35e repts, fire prevention/protection.weld matl control & OA records. WESCOTT, H H , KNOP, R G Region S, Chicago, Diffice of the Director B0/09/12 6pp
 - 10080355 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Discusses potential deficiency repostulated transient PETRICKIN A Stanfardized Nuclear Unit Power Plant System. B0/09/15. 2pp
- :10010497 Ack receipt of 800731 itr informing NRC of steps taken to carrect violations noted in IE Insp Rept 50-483/80-17 DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/09716 ip
- --B010010503 Responds to NRC 800711 ltr re violations noted in IE Insp. Rept 50-483/80-17 Corrective actions: engineers informed that site burning of solid waste not permitted Required monitoring devices installed, celibr & placed into syc BRYAN, J K Union Electric Co 80/07/31 5p
- 0010290257 Forwards IE Insp Rept 50-493/80-23 on 800909-11.No noncompliance noted. **TORELLI,O. Region 3. Chicago, Reactor Construction & Engineering Jupport Branch. 80/09/26, 2pp
 - 3010270262 IE Insp Rept SO-483/80-23 on 800707-11 No noncompliance noted. Major areas inspected. RCPB, safety-related piping work & welding activities LEE, E. H. K. Region 3. Chicago, Office of the Director. DANIELSON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/23 5pp.
- 010100079 Ack receipt of 800916 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-20 FIDRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/30 ip
- -8010100082 Responds to NRC 800814 ltr re violations noted in IE Insp Rept 50-483/80-20.Corrective actions disposal of unused welding filler matl & stubs found lying loose, BRYAN.J K Union Electric Co 80/09/16 4pp.
- 3010160300 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Gualification of Class IE Equipment " No written response required.

 KEPPLER.J. O. Region 3. Chicago, Office of the Director. 80/09/30.
- 1010170055 Ack receipt of 800814 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-483/80-09. FIORELLI.O. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/09/30. ip
- -8010170061 Supple 800606 & 13 responses to NRC 800606 lit re violations noted in IE Insp Regt 50-483/80-09, Corrective actions: Daniel Intl Corp will further develop training program & recentify QA dispectors.

 BRYAN, J K Union Electric Co. 80/08/14 App
- 8010270553 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications," No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/10/02 to.

- 8010230702 Ack receipt of 800922 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-19 FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/10 2pp
- --8010230704 Responds to NRC 800818 ltr re violations noted in RE Insp. Rept 59-483/80-19 Corrective actions site constructor is being directed to paint battery racks w/acid resistant paint.

 BRYAN, J K Union Electric Co 80/09/22 Spp
- 8010270031 Forwards IE Info Notice 80-34. "Failure of Bteam Generator Support Bolting " No specific action or response requested KEPPLER, J Q Region 3. Chicago, Office of the Director 80/10/to
- 8010270384 Forwards IE Insp Rept 50-483/80-24 on 800902-26 No noncompliance noted, FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/15 2pp
- --8010270385 IE Insp Rept 50-483/80-24 on 800702-24 No noncompliance noted Major areas inspected safety-related const activities including protection of reactor vessel & other components of NRSS.

 HANSEN, U.A. KNOP, R.C. Region 3, Chicago, Office of the Director, 80/10/14. 9pp
- B Reportable occurrences, LERs & related correspondence
- 8010290242 Final deficiency rept re adequacy of application & insp of Albi-Duraspray fire proofing mtls applied to structural seed in safety-related bidgs Review of reinsp indicated deficiencies were minor Areas reworked.* BRYAN: J. K. Union Electric Co. 80/08/29 ip
- 8010140024 Ack receipt of 800710 final deficiency rept re Bergen-Paterson pipe support strut w/mechanical shock arrestor. Review will be completed during future insp 8RYAN, J K Region 3. Ohicago, Reactor Construction & Engineering Support Branch 80/09/19 1p
- ---B010140032 Final deficiency rept re potential bolt headpipe clamp interference which could hinder full function of Bergen-Paterson pipe support strut assemblies Bergen-Paterson advised that all assemblies corrected prior to shipment BRYAN, J. K. Union Electric Co. 80/09/10, 2pp
- 8010270197 Ack receipt of 800915 interim deficiency rept re contrifugal charging pump operation following secondary side high energy line rupture CARLEON R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/09/24 1p
- ---8D10270208 Interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture. Design changes being evaluated Final rept will be provided in first quarter 1981. PETRICK, N A Standardized Nuclear Unit Power Plant Bystem 80/09/15 2pp
- 8010170173 Ack receipt of 800826 final deficiency rept re nonconforming threads on 3 5-inch diameter stude & nuts for N888 steam generator lateral supports FIORELIA. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/09/29 1p.
- --B010170180 Final deficiency rept re nonconforming threads on 3 5-inch diameter atuds & nuts for MBBS steam generator lateral supports Encil Bechtel rept supple data transmitted in B00731 submittal BRYAN.J K Union Electric Co B0/08/26 14pp
- 8010150378 Interim deficiency rept re Bergen-Paterson pige support strut w/mechanical shock arrestor. Bechtel analyzed two pige supports Two supports placed on hold & will be dispositioned according to nonconformance control procedures 88YAN, J. K. Union Electric Co. 80/10/07 ip.
- 8010770246 Ack receipt of 801007 ltr informing NRC of steps taken to correct deficiency re-pipe support strut w/mechanical shock arrestor. FIGRELLIP.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/10/20. ip.
- --B010270251 Amended B00702 deficiency rept re pipe support strut by mechanical shock arrestor Supports pleced on hold & will be disposed of per nonconformence control procedures BRYARLJ, K Union Electric Co BD/10/07, ip

T Hearing transcripts on non-antitrust matters

- BO100206B3 Ack receipt of transcript on public hearing re proposed Mastewater discharge permit for environ rept review DENTON: H R Office of Nuclear Reactor Regulation, Director BO/09723 1p
- --8010020673 Forwards transcript of State of MO 800716 public hearing re proposed wastewater discharge permit for environ rept review TEABDALE, J.P. Missouri, State of 80/08/22 ip
- --8010020709 Transcript on 800716 public hearing before MD Dept of Natural Resources Commission Pp 1-92 Util comments, citizen Itr,Exhibits 1-5, written presentation by Governor & supplemental data re NPDES permit encl e Missouri, State of 80/07/16 140pp

DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1

- A Application/construction stage documents & correspondence
- B010070497 Requests that application filed by util 791019 & notice published in FR on B00826 be amended to reflect fact that util is seeking issuance of OL only for Unit 1 Lists three items for correction in amended notice BRYAN, J. K. Union Electric Co. B0/10/01 3pp
- --8010070506 Discusses planned review of OL applications for four SNUPPS duplicate plants.per util 780130 & 0530 ltrs & 780414 meeting Forwards NUREG-0292.re apportunities for improvement in nuclear power plant licensing.for comment.W/o enci DENTON.H R Office of Nuclear Reactor Regulation, Director. 78/08/09 6pp.

DOCKET BIN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT 1

- A Application/construction stage documents & correspondence
- O Inspection reports: IE Bulletins & correspondence
- B01030005B Forwards Suppl 2 to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." No written response required ORIER, B. H Region 1. Philadelphia. Office of the Director B0/09/30 19
- 8010240145 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required. GRIER, B. H. Region i, Philadelphia, Office of the Director 80/10/02 ip
- B010280162 Forwards IE Info Notice 80-36, "Failure of Steam Denerator Support Bolting " No specific action or response requested GRIER, B H Region i, Philadelphia, Office of the Director, 80/10/10 ip
- S Reportable occurrences, LERs & related correspondence
- 8010270199 Ack receipt of 800915 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture CARLSON.R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch, 80/09/24 ip
- --B010270208 Interim deficiency rept re centrifugel charging pump operation following secondary side high energy line rupture. Design changes being evaluated Final rept will be provided in first quarter 1981 PETRICK.N A. Standardized Nuclear Unit Power Plant System B0/09/15 2pp

- DOCKET STN-50-485 CALLGHAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also and EISENMUT, D 0 Division of Licensing 80/09/19 28pp
- B010020683 Act receipt of transcript on public hearing re-proposed wastewater discharge permit for environ rept review DENION.H R Office of Nuclear Reactor Regulation, Director B0/09/23 1p.
- --8010020693 Forwards transcript of State of MO 800716 public hearing re proposed wastewater discharge permit for environ rept review TEASDALE.JP Missouri, State of 80/08/22 is
- 8010070497 Requests that application filed by util 791019 & notice published in FR on 800826 be amended to reflect fact that util is seeking issuance of OL only for Unit i Lists three items for correction in amended notice BRYAN, J & Union Electric Co 80/10/01. 3pp
- --8010070506 Discusses planned review of OL applications for four BNUPPR duplicate plants, per util 780130 & 0530 Ltrs & 780414 meeting Forwards NNEG-0272, re opportunities for improvement in nuclear power plant licensing for comment 4/o encl DENTOU, H R Office of Nuclear Reactor Regulation, Director 78/08/09 6pp.
- 8010160548 Forwards to NP Heass, Revision 1 to QA program descriptions, incorporating agreements, commitments & clarifications re BNUPPS QA programs as summarized in 800414,0327 & 0728 transmittals SEIKEN,S J. Standardized Nuclear Unit Power Plant System. 80/10/09.
- O Adjudicatory correspondence
- B010070445 Requests correction of typographical errors re 800922 petition for leave to intervene REED, J 0 Affiliation Unitnown B0/09/28 1p
- B01009004B Reply in opposition to applicant B00925 response to author B00910 petition to intervene. Concedes original petition was inadequate but second petition timely filed. Requests full party participation. Certificate of Suc encl.

 REED. J O. Affiliation Unknown B0/10/01 Spp
- 8010070380 Notice of establishment of ABLE to preside & rule in OL proceeding if hearing ordered JP Gleason appointed chairman Lists GO Bright & JR Kline as members LAZO.R M Atomic Batety and Licensing Board Panel 80/10/02 2ps.
- 8010090045 Reply to NRC 800925 response to author 800910 setition to intervene. Driginal setition inadequate Requests permission to renew & resubmit setition Certificate of Syc encl. REEO, J O Affiliation Unknown 80/10/02 3pp.
- 8010080251 Response in opposition to League of Homen Voters 900918 & 19 requests for public hearing Requirements re standing & interest not mut Purely economic interest as taxpayers not sufficient per ALAB-470 Certificate of Svc encl.

 BAXTER.T.A. CHARNDER.O Union Electric Co. BAXTER.T.A Shaw. Pittman, Potts & Trowbridge 80/10/03 opp
- BOI014054: Response in support of PBC of MO participation as interested state if hearing ordered No hearing required in absence of bana fide intervenor Certificate of Bvc enci BAXTER.T A. CHARNOFF.Q Union Electric Co Pittman. Potts & Trowbridge 80/10/07 4pp
- B010150082 Response in opposition to MJ Reilly & League of Women Voters of No 800918 & 19 requests to intervene Neither party seeks intervention as fall party Hearing not required Limited appearance statements acceptable Certificate of Svc encl. LESBY, R.P. Antitrust Division 80/10/09. 5pp.
- 8010150401 Forwards 801001 ltr from util to HR Denton, requesting issuance of amend to NRC notice in proceeding BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge. 80/10/10 lp.

- 8010160025 Response in opposition to Coalition for Environ.St Louis Region.Missourians for Safe Energy.Crawdad Alliance & K Drey 800925 joint petition to intervene Neither standing nor interest shown Certificate of Evc encl BAXTER.T A . CHARNOFF.G Union Electric Co BAXTER.T A . Shaw, Pittman, Potts & Troubridge 80/10/10 10pp
- 8010160540 Response in support of PSC of MO 800922 petition to intervene as representative of state in event hearing is held Certificate of Svc encl MCGURREN,H J Hearing Branch i 80/10/14 3pp
- B010200665 Notices of appearance in proceeding Cartificate of Svc encl CHARMOFF, 0 , BAXTER, T A , BERNSTEIN, D L Union Electric Co 80/10/14 5pp
- B010200671 Response in opposition to J0 Reed B00922 petition to intervene Requirements of 10CFR2 714 not met Certificate of Svc encl
 BACTER.T A. CHARNOFF.Q Union Electric Co BAXTER.T A Bhaw, Pittman, Patts & Trowbridge 80/10/14 4pp
- B010170365 Response in support of K Drey B00925 petition to intervene Interest & aspects requirements satisfied No position taken re aspects as contentions HJ McGurren notice of appearance & Certificate of Svc encl
 MCGURREN.H J Hearing Branch 1 80/10/15 13pp
- 8010200166 Response in support of JG Read petition to intervene, received 800910 Petitioner satisfied interest & aspects requirements (%) opinion expressed re contentions Certificate of Svc encl
 LESSY.R P Antitrust Division MCGURREN.H J Hearing Branch 1 80/10/16 10pp
- 8010270389 Submittal of 801022 amended petition to intervene & request for hearing Requests free svc of future documents W/o encl REED, J O Affiliation Uningum B0/10/22 1p
- 8010270405 Amended petition to intervene & request for hearing questioning applicant financial capability to implement requirements Nineteen affidavits of interested citizens, supporting documents, Certificate of Bvc & appearance encl REED, J O Affiliation Unknown 80/10/22. 37pp
- 010300072 Addendum to 800925 petition to intervene H/Certificate of Svc & affidavits of members of Coalition for Environ.Crawdad Alliance & Missourians for Safe Energy in support of Intervention

 DREY.K Affiliation Unknown 80/10/25 App
- G Inspection reports. IE Builetins & correspondence
- B010210292 Submits add1 response to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 5A-312.Type 304 Stainless Steel Pipe "Manufacturers have not furnished specified pipe matls for use in sys in which design hoop stresses exceed ASME Code SEIKEN.S J Standardized Nuclear Unit Power Plant System 80/08/20.
- B010020189 Responds to IE Bulletin 80-16, Rosemount Hodel 1131 or 1152 pressure transmitters are not used in any safety-related applications
 PETRICA, N.A. Standardized Nuclear Unit Power Plant System
- 80:0010835 Responds to IE Bulletin 80-19 Mercury-wetted relays are not used in matrix logic in reactor trip circuitry Mercury-wetted relays are used in Mestinghouse 7300 protection sys equipment & are hermetically sealed. PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/29 19
- B010010B44 Responds to IE Bulletin B0-20 Westinghouse Type W-2 control suitches are not used in safety-related applications PETRICK.N A Standardized Nuclear Unit Power Plant System B0/09/09 ip
- 8010080555 Responds to IE Bulletin 80-10, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Becondary Side High Energy Line Rupture," Discusses potential deficiency repostulate transient PETRICK-N A Standardized Nuclear Unit Power Plant System, 80/09/15 208
- B010160300 Forwards Suppl 2 to IE Gulletin 79-018, "Environ Gualification of Class IE Equipment," No written response required. KEPFLER, J O Region 3, Chicago, Office of the Director B0/09/30 1s.

- 8010270553 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/10/02 ip
- 8010290031 Forwards IE Info Notice 80-35. "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER, J O Region 3, Chicago, Diffice of the Director BD/10/10
- S Reportable occurrences, LERs & related correspondence
- 8010270199 Ack receipt of 800915 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Bupport Branch 80/09/24 1p
- --8010270208 Interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Design changes being evaluated Final rept will be provided in first quarter 1981 PETRICK,N A Standardized Nuclear Unit Power Plant Bystem 80/09/15 2pa
- T Hearing transcripts on non-antitrust matters
- 8010020693 Ack receipt of transcript on public hearing re proposed wastewater discharge permit for environ rept review DENION.H R Office of Nuclear Reactor Regulation, Director 80/09/23 1p
- --8010020693 Forwards transcript of State of MO 800716 public hearing reproposed wastewater discharge permit for environ rept review.

 TEASDALE, J.P. Missouri, State of 80/08/22 1p
- --8010020709 Transcript on 800716 public hearing before MO Dept of Natural Resources Commission Pp 1-92 Util comments citizen ltr.Exhibits 1-5.uritten presentation by Governor & supplemental data re NPDES permit encl * Missouri, State of 80/07/16 140pp
- DOCKET STN-90-488 PERKINS NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISEMHUT. D.G. Division of Licensing 80/09/19 22pp
- 9 Adjudicatory correspondence
- 8010010479 Decision. ALAS-615. affirming ASLB 800814 order in which D Springer 800415 petition to intervene was denied. Untimely petition unjustified BISHOP.C J Atomic Safety and Licensing Appeal Panel. 80/07/27 Spe
- 8010220532 Order granting extension until 801031 for Commission to review ALAB~615 CHILM-8 J Commissioners 80/10/20 1p
- @ Inspection reports, TE Bulletins & correspondence
- 8010230074 Forwards 1E Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matis" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/29.
- 8010160275 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30 to.
- 8010270544 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY.J.P Region 2. Atlanta, Office of the Director 80/10/02 1p
- 8010270056 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Holting " No specific action or response requested. O'REJLLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/10 19

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- BO10220097 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also encl EISE(HUT, D G Division of Licensing 80/09/19 28pp.

G Adjudicatory correspondence

- B010010699 Decision.ALAB-615.affirming ABLB 800814 order in which D Springer 800415 petition to intervene was denied Untimely petition unjustified BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/29
- 8010220532 Order granting extension until 801031 for Commission to review ALAB-615 CHILM S J Commissioners 80/10/20 ip

Q Inspection reports. IE Bulletins € correspondence

- 8010230074 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29 200
- 8010160275 Forwards Suppl 2 to IE Builetin 79-01B, "Environ Qualification of Class IE Equipment" No written response required O'REILLY, J P. Region 2. Atlanta, Office of the Director 80/09/30
- 8010270544 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 to
- B010276086 Forwards IE Info Notice 80-36, "Failure of Bteam Generator Bupport Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/10/10

DOCKET BIN-50-490 PERKINS NUCLEAR BIATION, UNIT 3

G Adjudicatory correspondence

- 8010010699 Decision, ALAN-615, affirming ASLN 800814 order in which D Springer 800415 petition to intervene was denied Untimely petition unjustified BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/29
- 8010220332 Order granting extension until 801031 for Commission to review ALAB-615 CHILK:8 J Commissioners 80/10/20 ip

Q Inspection reports. IE Bulletins & correspondence

- 8010230074 Forwards IE Info Notice 80-32, "Clarification of Cartain Requirements for Exclusive Use Shipments of Radioactive Matls " No written response required, D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/27, 2pp
- 8010160275 Forwards Suppl 2 to 1E Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required D/REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/30
- B010270544 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02 in.
- 8010290056 Forwards IE Info Notice 80-36. "Failure of Bleam Generator Support Bolting " No specific action or response requested O'RETLLY, J.P. Ragion 2. Atlanta, Office of the Director. 80/10/10.

- DOCKET STN-50-491 CHERDKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of Till action plan requirements Corrected table of implementation schedule also encl EISENHUT, D O Division of Licensing 60/09/19 28pp
- G inspection reports, IE Bulletins & correspondence
- 8010230074 Forwards IF Info Notice 80-32. "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls "No written response required D'REILLY, J P Region 2. Atlanta, Diffice of the Director 80/08/29 200
- 8010140275 Forwards Suppl 2 to 1E Sulletin 79-01B. "Environ Qualification of Class IE Equipment " No written response required.

 O'REILLY: J.P. Region 2. Atlanta. Office of the Director 80/09/30
- 8010270544 Forwards IE Circular 80-22, "Confirmation of Employee Oualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02 ip
- B010290056 Forwards IE info Notice 80-26. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/10/10 to
- 8010300380 Ack receipt of 800815 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-08, 50-370/80-05, 50-413/80-07, 50-414/80-07, 50-492/80-06 \$ 50-493/80-06 MURPHY/C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/10/16 2pp
- --8010300385 Responds to NRC 803718 ltr re violations noted in IE Insp Repts 50-369/80-08.50-370/80-05.50-413/80-09.50-414/80-09. 50-491/80-07.50-492/80-06 & 50-493/80-06 Corrective actions records storage facility constructed PARKER:N 0 Duke Power Co 80/08/15 7pp
- --8010360388 Forwards LE Insp Repts 50-369/80-08.50-370/80-05, 50-413/80-09.50-414/80-09.50-491/80-07.50-492/80-06 & 50-493/80-06 on 800519-23 & notice of violation KURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8010330423 Notice of violation from insp on 800519-23
 * Region 2. Atlanta: Office of the Director 80/07/18 4pp
- --801030042B IE Insp Repts 50~369/80~08.50~370/80~05.50~413/80~07.50~414/80~07.50~412/80~06.50~473/80~06 on BOO519~23 Noncompliance noted in areas of temporary record storage facilities & fire protection BROWNLEE,V L., LENAHAN, J.J., WALTERS, D.K. Region 2, Atlanta, Office of the Director 80/07/18 25pp
- DOCKET SIN-50-492 CHEROXEE NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8D10220099 Forwards errata sheats amending 800905 ltr which provided preliminary clarification of Thi action plan requirements Corrected table of implementation schedule also encl ETERLAHUT.D G Division of Licensing 80/09/19 28pp
- Q Inspection reports, IF Bulletins & correspondence
- 8010230074 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29.
- 8010160275 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required.

 D'REILLY, J. P. Region 2- Atlanta. Office of the Director 80/09/30 to

- 8010270544 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/02
- B010290036 Forwards IF Info Notice 80-36. "Failure of Steam Gamerator Support Bolting " No specific action or response requested D'REILLY. J P Region 2. Atlanta. Office of the Director 80/10/10 ip
- 8010300380 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE (msp Repts 30-364/80-08, 50-39/80-05, 50-414/80-07, 50-414/80-07, 50-491/80-07, 50-492/80-06 & 50-493/80-06 & Region 2, Atlanta, Reactor Construction & Engineering Support Branch 83/10/16 2pp
- --8010300385 Responds to IRC 800718 ltr re violations noted in 1E Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06 Corrective actions, records storage racility constructed PARKER,N O Duke Fawer Co 80/08/15 7pp
- --8010300388 Forwards IE Insp Repts 50-369/80-08.50-370/80-05, 50-413/80-09.50-414/80-09.50-491/80-07.50-492/80-06 & 50-493/80-06 on 800517-23 t notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8010300423 Notice of violation from insp on 800519~23

 → Region 2, Atlanta, Office of the Director 80/07/18 4pp
- --8010300428 IE Insp Repts 50-359/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 30-493/80-06 on 800519-23 Noncompliance noted in areas of temporary record storage facilities & fire protection BROWNLES.V L. Region 2. Atlanta. Office of the Director CONKOUNT E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/18 25pp
- DOCKET BIN-50-493 CHERDAEE MUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 3010220097 Forwards errata sheats amending B00905 ltr which provided preliminary clarification of TMT action plan requirements. Corrected table of implementation schedule also encl EISENMUT, D 0 Division of Licensing 80/09/19 28pp.
- G Inspection reports, IE Bulletins & correspondence
- 8010230074 Forwards IR Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29 2pp
- B010160275 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required O'REILLY, J & Region 2. Atlanta, Office of the Director B0/09/30 ip
- 8010270544 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/10/02 ip
- 8010270096 Forwards IE info Notice 80-36. "Failure of Steam Generator Support Bolting," No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/10/10
- 8010300380 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06 MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/10/16 2pp
- --8010300385 Responds to NRC 800718 ltr re violations noted in IE Insp Repts 50-369/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06 Corrective actions records storage facility constructed PARKER, U O Dute Power Co 80/08/15 7pp.

- --8010300388 Forwards IE Insp Repts 50-349/80-08, 50-370/80-05, 50-413/80-09, 50-414/80-09, 50-491/80-07, 50-492/80-06 & 50-493/80-06 on 800519-23 & notice of violation huRPHY.C E Region 2 Atlanta, Reactor Construction & Engineering Support Branch 20/07/18 2pp
- --8010360423 Notice of violation from insp on 800519-23
 * Region 2. Atlanta, Office of the Director 80/07/18 4pp
- --8010300428 IE Insp Repts 50-369/80-08.50-370/80-05.50-413/80-09, 50-414/80-09, 50-491/80-07.50-492/80-06.50-493/80-06 on 800519-23 Noncompliance noted in areas at temporary record storage facilities & fire protection BRDMNLEE.V L. Region 2. Atlanta, Office of the Director COULDNLT E. Region 2 Atlanta. Reactor Construction 5 Engineering Support 3 ranch 80/07/18 25pp
- DOCKET STN-90-498 SOUTH TEXAS PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D Q Division of Licensing 80/09/19 28pp
- 8010010åå1 Submits criteria for establishing staffing levels, supporting AA program for facility per ARC 800819 request Graph & organizational chart encl GPREA.O U Houston Lighting & Power Co 80/09/24 4pp
- --8010010665 Man-loading curve graph & organizational chart supporting QA program
 4 Houston Lighting & Power Co 80/09/24 2pp
- 8010220216 Discusses required actions re QA program Forwards request for add1 info re QA program summarized in responses to 800728 show cause order TEDESCO.R L. Assistant Director for Licensing 80/09/24 7pp
- 8010220363 Forwards position on cladding & rupture models for LOCA analyses Response requested re supplemental calculations TEDESCO,R L Assistant Director for Licensing 80/10/07 3pp
- 8010210313 Submits info on GA program in response to NRC 800724 itr GA program & organizations described in 800523 & 0728 submittals will be filed w/NRC on 801031 GPREA: G W Houston Lighting & Power Co 80/10/15 Spp
- 8010240420 Forwards AWS safety-related welding 12-wk work plan for fourth quarter 1980, identifying add1 production welding & estimated completion time, in response to NRC 801003 ltr Category 1 structural steal welding began 801006 OPREA, C W Houston Lighting & Power Co 80/10/17 6pp
- C Utility Environmental Report (ER), amends & correspondence
- 8010160565 Forwards Amend 3 to environ rept includes updated info re revised project cost & schedule OPREA.G W. Houston Lighting & Power Co 80/10/06 ip
- --B010160969 Amend 3 to environ rept

 * Houston Lighting & Power Co B0/10/06 112pp
- 8010210537 Confirms that Amend 3 to environ rept.for OL stage transmitted to parties on 801014 MCGUIRE.W F Houston Lighting & Power Co 80/10/14 2pp
- 9 Adjudicatory correspondence
- B010020073 Forwards App A inadvertently omitted from TX Border Cooperative B00724 comments on proposed settlement O'NEIL.R A Hiller, Balis & O'Neil B0/09/25 7pp,
- B010140603 Responds to ASLB 800924 memorandum & order Hearings should commence as soon as possible Applicant will present testimony re technical qualifications reflected in ASLB 800924 order Certificate of Svc encl NEWMAN, J R Lowenstein, Newman, Reis, Aveirad & Toll 80/10/06 4pg
- 8010170343 Responds to ASLB 800924 memorandum & order inviting comments re further proceedings Applicant will file testimony & make evidentiary presentation on GA/OC matters first Applicant has burden of proof EJ Reis natice of appearance encl SLACK.R L Hearing Branch I 80/10/15 Spp

- 8010200544 Requests that encl unedited transcript of House Bubcommittee on Oversight & Investigations 800723 hearing on facility be served on ASLB & interested parties BICKMIT: L Office of the General Counsel 80/10/15 ip
- --8010200349 Forwards unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing on facility Requests review & correction Original copy should be returned within 1 wk of receipt PAINTER.X J House of Rep 80/09/23 1p
- --8010200557 Unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing on facility in Washington DC Pp 1-98
 - House of Rep 80/09/23 102pp
- 8010240427 Ack receipt of NRC 801015 ltr resteps to be taken in licensing proceeding Further clarification of issues is necessary Applicants restatement of issues included Certificate of Svc encl NEWMAN. J R , CULP R H , RASKIN. D B Lowenstein, Newman, Reis, Arelrad & Toll 80/10/22 8pp
- 8010309696 Request for evidential documents.x-rays & other matl re possible foreign objects in reactor containment bldg walls, pedestal or foundation MILLER.B Citizens Concerned About Nuclear Power, Inc. 80/10/23
- 8010280545 Act receipt of applicant 801022 ltr to C Beckhoefer re addl steps in proceeding Urges early prehearing confurence to finalize issues BORDENICK. B M Hearing Branch 3 80/10/27 to
- M Antitrust correspondence
- 8009230171 Notification of contract execution.Mod 4 to "Engineering Assistance Re Hearings for South TX Antitrust & Comenche Peak Antitrust Proceedings" HAIRSTON, C A Technical Assistance Contracts Branch FIN 8-6523 Peak Antivioring HAIRSTON, C A
- --8009230:81 Mod 4.changing scope of work, to "Engineering Assistance Re Hearings for South TX Antitrust & Communche Peak Antitrust Proceedings " R N Beck & Associates FIN 8-6523 80/08/20 1p
- 8010140497 Executed stipulation of DDJ, NRC, Central & Southwest Corp, Houston Lighting & Power, City of Austin & Public Svc Board of Ban Antonio incorporating attached license conditions W/a encl m/a enc: * Justice.Dept of CHANANIA,F D Antitrust Division * Houston Lighting & Power Co 80/09/12 4pp
- 8010030125 Status rept by TX Border Cooperatives opposing settlement negotiations Differences w/Central & Bouth Nest Corp re dc interconnection are not insurmountable, but accord not yet reached M/supporting documentation & Certificate of Bvc O'NFIL.R A Southwest Texas Electric Cooperative O'NEIL.R A Killer, Balis & O'NEIL BO/10/01 22pp
- 8010040341 Forwards DOJ potition for leave to intervene & comments contesting applicant proposed offer of settlement MCHILLEN,N H Transportation, Dept of 80/10/01 ip
- --B010040353 Gomments contesting applicant proposed offer of settlement on grounds that proposal does not clearly meet requirements or Public Util Regulatory Policies Act Certificate of Syc encl FAVRETTO, R J , KAPLAN, D A , FAGRIKANT, R Justice, Dept of 1500 80/09/29
- 8010070541 Hotion for revision of procedural schedule Suggests 10-day extension after ASLB rules on proposed settlement for parties to file trial briefs & subsequent extension for other matters Urges conference call Certificate of Svc ancl. SPIECEL. O Brownsville, TX SPIECEL. O Spiegel & McDiarmid 80/10/03 12pp
- B010080289 Motion to strike refs to Commanche Peak proceeding from Public Utils Board of City of Brownsville.TX 800925 motion to disapprove proposed license conditions Refs were stricken from previous analogous pleadings Certificate of Svc encl. KNOTTS. B., AHEARN.C.D Texas Utilities Generating Co KNOTTS. Bebavoise & Liberman B0/10/06. 9pp. KNOTTB, J. B.

- 8010080319 Response in opposition to Public Utils Board of City of Brownsville, TX 800925 motion for disapproval of proposed license conditions ASLB should await Brownsville trial brief prior to deciding addl steps W/Certificate of Svc KNOTTS, J B , AHEARN, C D Texas Utilities Generating Co KNOTTS, T B Debevoise & Liberman BO/10/06 Spp
- B010140D02 Response in opposition to City of Brownsville B01003 motion for revision of procedural schedule Motion is extraordinarily late & w/o merit Certificate of Svc encl KNOTTS, J B. AHEARN, C D. Teras Utilities Generating Co. KNDTTS, J B. Debevoise & Liberman. B0/10/07 Bpp
- 8010140C04 Response in opposition to Public Utils Board of City of Brownsville 801003 motions for disapproval of negotiated license conditions & for delay of briefs Certificate of Svc OREEN, D C Houston Lighting & Power Co 80/10/07 27pp
- 8010140525 Response in opposition to City of Brownsville 801006 request for revision of procedural achedule Modest relaxation of procedural dates may be appropriate, but indefinite extension not warranted Certificate of Syc encl
 CHANANIA.F D Antitrust Division 80/10/07 8pp
- 8010140540 Response in opposition to City of Brownsville 801006 request for revision of procedural schedula Indefinite extension not warranted No opposition to modest extension. Settlement conditions need prompt consideration WCertificate of Svc FABRIKANT, R Justice, Dept of 80/10/08 8pp
- 8010150024 Trial brief concluding that proposed license conditions are inadequate to cure situation inconsistent w/antitrust laws. Lists of witnesses, exhibits & testimony & Certificate of Svc SPIEGEL.0 , LANDSMAN.R K , POIRIER.M R Brownsville.TX 80/10/08 105pp
- 8010170498 Advises that DDJ response to Brownsville.TX 801009 initial trial brief will also address argument 800925 motion for disapprayal of settlement license conditions FABRIKANT.R Justice, Dept of 80/10/10 ip
- 8010150476 Requests on behalf of util that Board hold conference call involving all parties to discuss & resolve serious questions re trial brief & related filings submitted by TX Util Generating Co Certificate of Bvc encl BOXMITGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll BO/10/14
- 801016056B Reiterates position that City of Brownsville 800925 motion for disapproval of proposed license conditions was inappropriate Best method of response would be NRC reply brief If such action inappropriate, extension requested CHANANIA, F.D. Antitrust Division 80/10/14 2pp
- 8010200602 Notice of 801023 special prehearing conference to consider pending motions & requests No further responsive pleadings required of parties until after matters ruled on by ASLB MILLER, M.E. Atomic Safety and Licensing Board Panel 80/10/14.
- 8010170395 Forwards original copy of Public Utils Board of Brownsvills, TX initial trial brief N/o encl POIRIER.K R Spiegel & McDiarmid 80/10/15 1p
- 8010200397 Requests that documents claimed by utils as confidential be made available to any requesting party on 801021 Reserves right to request showing of confidentiality per ASLB 791107 POIRIER, HR Spiegel & McDiarmid BO/10/15
- 8010220316 Forwards Public Utils Board of City of Brownsville.TX first suppl to 801008 initial trial brief.correcting lists of documents to be offered into evidence SPIEOEL.0 Spiegel & McDiarmid 80/10/16 1p
- --8010220320 First suppl to 801008 initial trial brief correcting lists of documents to be offered into evidence Certification of svc enci SPIEGEL.0 Spiegel & McDiarmid 80/10/16 53pp.
- 8010270397 Responds to 801015 ltr re release of potential exhibits for which util has claimed confidential treatment Objects to release of mati per ASLB 790724 stipulation to protective order Lists documents which can be released w/o restriction. HETTERHAHN, M, J. Conner, Moore & Corber 80/10/21 2pp

- 8010270439 Requests ASLB discuss at 801024 conference question of issuing subposens for production of uitnesses in lieu of formal filings of individual motions Cites Part IVO of initial trial brief
 SPIEOEL.9 Spingel & McDiarmid 80/10/22, 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8010160107 Forwards Suppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No written response requires SEYFRIT.K V Region 4. Dallas. Office of the Director 80/09/30
- 8010270518 Forwards 1E Circular 80-22, "Confirmation of Employee Qualifications" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/10/02
- 8010230159 Ack receipt of 801002 ltr & confirms discussion re-actions taken to re-examine, repair & restart AMS welding Actions taken are acceptable Corrective actions re-ASME welding restart are not acceptable
 SEYFRIT, K V Region 4. Dallas, Office of the Director 80/10/03 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 8010010146 Second interim deficiency rept providing add1 info re stop work order on safety-rotated & code welding.Extensive investigation currently in progress covering welder qualification, production welding & inspection of the production welding & inspection of the production of
- 8010150208 Interim deficiency rept re incomplete visual insp of concrete embedments No indication of safety hazards
 Deficiency under further evaluation as precautionary measure
 & subsequent rept to be submitted pending survey results
 OPREA.0 W Houston Lighting & Power Co 80/08/28 3pp.
- 8010130199 Final deficiency rept re exhaust fan design for diesel generator fuel oil tank rooms Fan assemblies to be installed subj to replacement w/qualified motors & results of design verification program
 OPREA.O M Houston Lighting & Power Co 80/09/03 5pp
- 8010180188 Final deficiency rept re concrete placement GA program & revised procedurel requirements Inspector added to GC staff Personnel reinstructed in proper consolidation of placement Procedures rewritten winvolvement of supervisors OPREA.O W Howston Lighting & Power Co 80/09/04, 12pp.
- 8010130181 Second interim deficiency rept re-breakdown in program for procurement cycle of purchased matls & equipment. Procedures & schedule to be developed for verification program of vendor-related.safety-related matls.equipment & records OPREA.0 H Houston Lighting & Power Co 80/09/12 3pp
- 8010150193 Third interim deficiency rept re rejectable indications on radiographs of girth welds in essential cooling water syspipe Repair program & remexamination initiated for new accessible & inaccessible welds Update rept by 801215 GPREA.0 W Houston Lighting & Power Co. 80/09/12 4pp,
- 8010190162 Fourth interim deficiency rept re broken tie-down stude in containment bldg Unit i polar crain rail sys Caused by incomplete fusion of stud welds & deviations from design. Studs to be removed eliminated from design & replaced OPREA.O H Houston Lighting & Power Co 80/09/15, 6pp.
- 8010150169 Final deficiency rept re probable deficiency concerning measurement mathods used to determine verticality of spent fuel storage recks Not reportable under 10CFR50. 55e DPREA, O H Houston Lighting & Power Co 80/09/17 Spp.
- B010210452 Second interim deficiency rept re essential cooling water intake structure gentry crane seismic qualification Caused by 1.5 instead of 2 O factor in determining DBE values. Next rept will be submitted by 810122 OPREA. G. W Houston Lighting & Power Co. 80/10/01. 4pp
- _9010160794 PNO-IV-80-034 on 801002.util requested limited restart on safety-related welding & complex concrets placement, Based upon review of corrective action. AWB welding was allowed ABME welding t complex concrete pours were denied. HUBACEK, U.O., CROSSMAN, W.A. Ragion 4, Dallas, Office of the Director 80/10/03 1p

- E010210006 Part 21 rept re deficiencies noted in Class IE battery chargers supplied by Power Conversions Products Various electronic components supplied by foreign suppliers in violation of specs
 RICE.H M Brown & Root Corp (subs of Halliburton Corp)
 80/10/07 4pp
- 80:10160556 Second interim deficiency rept re-stud welds on concrete embedments Add1 data currently being collected for use in detailed evaluation of various aspects of deficiency Next rept will be submitted by 80:1217

 OPREA: Q W Houston Lighting & Power Ca 80/10/08 App
- 8010310528 Final Part 21 rept re breakdown in vendor surveillance program for Class IE electrical equipment Bafety-related equipment purchase orders identified in 800918 deficiency rept are part of 800413 generic deficiency OPREA.0 P Houston Lighting & Power Co 80/10/15 9pp
- BD10310295 Second interim deficiency rept re essential cooling water pump seat water design defect Preliminary design has been developed, however, detailed review & final approval pending Next rept will be submitted by 801221

 OPREA, O U Houston Lighting & Power Co 80/10/16, 4p
- B01030048B Part 21 rept re defect in Power Conversion Products part, Author will visit site on 801023 WEIL.E S Power Conversion Products, Inc 80/10/17 3pp
- 8010280540 First interim deficiency rept re apparent breakdown in quality program of Svc Level I paintings & concrete & steel surfaces inside reactor containment bldg Rejected coatings will be removed & reapplied OPREA, O U Houston Lighting & Power Co, 80/10/21 5pp
- 8010300566 PNO-IV-80-34A on 801017.util requested addl limited restart of AMS safety-related welding Request is for performing Category I structural steel welding embeds up to & including 1-1/2 inch thickness HUBACEK. 11.0 CROBBHAN. W.A. Region 4. Dallas. Office of the Director 80/10/23 1p
- B010280360 Interim deficiency rept re welding of main steam line pipe whip restraints Reinsp of welds will be performed by Brown & Root Units are being placed on hold until completion of insp Next rept will be submitted by B10116

 GPREA.Q W Howston Lighting & Power Co B0/10/24 Spp.
- U Congressional/Executive Correspondence
- 8010200544 Requests that encl unedited transcript of House Bubcommittee on Oversight & Investigations B00923 hearing on facility be served on ASLB & interested parties
 BICKNIT:L Office of the General Counsel 80/10/15 ip
- --8010200549 Forwards unedited transcript of House Subcommittee on Oversight & Envestigations 800923 hearing on facility Requests review & correction Original copy should be returned within 1 wk of receipt PAINIER, K J House of Rep 80/09/23 ip
- --8010200557 Unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing on facility in Washington, DC Pp 1-98
 - + House of Rep 80/09/23 102pp
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010220099 Forwards errota sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci EISENRUT, D Q Division of Licensing 80/09/17, 28pp.
- 80:001066: Submits criteria for establishing staffing levels, supporting GA program for facility per NRC 8008:19 request Graph & arganizational chart engl OPREA:0 W Houston Lighting & Power Co. 80/09/24 4pp
- --8010010465 Man-loading curve graph & organizational chart supporting GA program 4 Houston Lighting & Power Co 80/07/24, 2pp.
- 8010220216 Discusses required actions to QA program Forwards request for add1 info to QA program summarized in responses to 800728 show cause order TEDESCO.R L Assistant Director for Licensing 80/09/24 7pp

- 80:0220363 Forwards position on cladding & rupture models for LOCA analyses Response requested re supplemental calculations TEDESCO.R L Assistant Director for Licensing 80/10/07 3pp
- 8010210333 Submits info on QA program in response to NRC 800924 ltr QA program & organizations described in 800523 & 0728 submittals will be filed w/NRC on 801031 CPREA.Q W Houston Lighting & Power Co 80/10/15, 5pp
- 6010240420 Forwards AWS safety-related welding 12-wk work plan for fourth quarter 1980, identifying add1 production welding & estimated completion time, in response to NRC 801003 ltr Category 1 structural steel welding began 801006 DPREA. G W Houston Lighting & Power Co 80/10/17 6pp
- C Utility Environmental Report (ER), amends & correspondence
- 6010169565 Forwards Amend 3 to environ rept Includes updated info re revised project cost & schedule OPREA, G 13 Houston Lighting & Power Co 80/10/06 1p
- --8010160569 Amend 3 to environ rept
 * Houston Lighting & Power Co 80/10/06 112pp,
- BOIO210637 Confirms that Amend 3 to environ rept, for DL stage transmitted to parties on BO1014 MCQUIRE, W F Houston Lighting & Power Co BO/10/14 2pp
- G Adjudicatory correspondence
- B010020073 Forwards App A inadvertently omitted from TX Border Cooperative 800924 comments on proposed settlement. O'NEIL,R.A. Miller,Balis & O'Neil 80/09/25 9pp
- BO30140603 Responds to ASLB B00924 memorandum & order Hearings should commence as soon as possible Applicant will present testimony re technical qualifications reflected in ABLB B00924 order Certificate of Svc encl.

 NEUMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll B0/10/06 App
- 8010170343 Responds to ASLB 800924 memorandum & order inviting comments re further proceedings Applicant will file testimony & make evidentiary presentation on GA/GC matters first Applicant has burden of proof EJ Reis notice of appearance encl.

 BLACK:R L Hearing Branch 1 80/10/15 3pp
- 8010200544 Requests that encl unedited transcript of House Subcommittee on Oversight & Investigations 800928 hearing on facility be served on ASLB & interested parties
 BICKHITL Office of the General Counsel 80/10/15 ip
- -8010200549 Forwards unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing on facility Requests review & correction Original copy should be returned within 1 wk of receipt PAINTER.K J House of Rep 80/09/23 1p.
- --8010200557 Unedited transcript of House Subcommittee on Oversight & Investigations 800723 hearing on facility in Washingtons BC Pp 1-9B House of Rep 80/07/23 102pp
- 8010240427 Ack receipt of NRC 801015 ltr re steps to be taken in licensing proceeding Further clarification of issues is necessary Applicants restatement of issues included Cartificate of Bvc encl NEWMAN, J. R. CULP R H., RASKIN, D B. Lowenstein, Newman, Reis, Arelrad & Toll 80/10/22, 8pp
- 8010300886 Request for evidential documents,x-rays & other matl repossible foreign objects in reactor containment bldg walls, pedestal or foundation MILLER,B Citizens Concerned About Nuclear Power, Inc. 80/10/23
- 8010280545 Ack receipt of applicant 801022 ltr to C Beckhoefer re add1 steps in proceeding Urges early prehearing conference to finalize issues BDRDENICK.B M. Hearing Branch 3 80/10/27 1p.
- M Antitrust correspondence
- 8009230171 Notification of contract execution, Mod 4 to "Engineering Assistance Re Hearings for South TX Antitrust & Comanche Peak Antitrust Proceedings"
 HAIRSTON, C A Technical Assistance Contracts Branch. FIN 8-6523. HAIRSTON, C A 80/08/20. 1p

- --8009230181 Mod 4, changing scope of work, to "Engineering Assistance Re Hearings for South TX Antitrust & Comanche Peak Antitrust Proceedings "
 * R N Beck & Associates FIN B-6523 80/08/20
- 8010140497 Executed stipulation of DDJ.NRC.Central & Southwest Corp. Howston Lighting & Power, City of Austin & Public Svc Board of San Antonio incorporating attached license conditions W/o encl * Justice. Dept of CHANANIA, F D. Lighting & Power Co ED/09/12 4e Antitrust Division * Houston 4pp.
- 8010030125 Status rept by TX Border Cooperatives opposing settlement negotiations Differences w/Central & Bouth West Corp re do interconnection are not insurmountable, but accord not yet reached W/supporting documentation & Certificate of Svc O'NEIL,R A Southwest Texas Electric Cooperative B0/10/01. 22pp
- 8010060341 Forwards DDJ petition for leave to intervene & comments contesting applicant proposed offer of settlement MCHILLEN.N H Transportation.Dept of 80/10/01 1p
- --8010040349 Petition for leave to intervene FAVRETTO:R J Justice:Dept of 80/09/17 3pp
- ---8010060353 Comments contesting applicant proposed offer of settlement on grounds that proposal does not clearly meet requirements of Public Util Regulatory Policies Act Certificate of Byc encl FAVRETTO:R J Justice: Dept of 80/09/29
- 8010070541 Matian for revision of procedural schedule Suggests 10-day extension after ASLB rules on proposed settlement for parties to file trial briefs & subsequent extension for other matters Urges conference call Certificate of Svc encl BPIEOEL, 0 Brownsville, TX 80/10/03 12pp.
- BD100B0289 Motion to strike refs to Commanche Peak proceeding from Public Utils Board of City of Brownsville.TX B00929 motion to disapprove proposed license conditions Refs were stricken from previous analogous pleadings Certificate of Bvc encl KNOTTS, JB Teras Utilities Generating Co AHEARN.C D Debevoi Liberman BG/10/06 9pp Debevoise &
- BO100B0319 Response in opposition to Public Utils Board of Gity of Brownsville.TX 800925 motion for disapproval of proposed license conditions ASLB should await Brownsville trial brief prior to deciding addi steps M/Certi KNOTTS, JB Texas Ut Liberman 80/10/06. Врр
- B010140902 Response in opposition to City of Brownsville 801003 motion for revision of procedural schedule Motion is extraordinarily late & w/o merit Cartificate of Svc encl KNOTTS. J B Texas Utilities Generating Co AHEARN.C.D Debevoise & Liberman 80/10/07 Spp
- 8010140504 Response in opposition to Public Utils Baord of City of Brownsville 801003 motions for disapproval of negotiated license conditions & for delay of briefs Certificate of Svc GREEN, D.O. Houston Lighting & Power Co. 80/10/07 27pp.
- 8010140525 Response in opposition to City of Brownsville 801006 request for revision of procedural schedule Hodest relaxation of procedural dates may be appropriate, but indefinite extension not warranted Certificate of Svc encl CHANANIA,F D Antitrust Division 80/10/07 Spp
- BO10140540 Response in opposition to City of Brownsville 801006 request for revision of procedural schedule. Indefinite extension not warranted No opposition to modest extension Settlement conditions need grampt consideration W/Certificate of Svc FABRIKANT, R Justice, Dept of 80/10/08 Spp.
- B010190024 Trial brief concluding that proposed license conditions are inadequate to cure situation inconsistent w/antitrust laws Lists of witnesses.exhibits & testimony & Certificate of Syc GPIEGEL, 0 Brownsville, TX. SPIEGEL, Q, LANDSMAN, R, M Spiegel & McDiarmid 80/10/08 105pp
- BOI0170458 Advises that DOJ response to Brownsville, TX B0i009 initial trial brief will also address argument 800925 motion for disapproval of settlement license conditions. FABRIKANT, N Justice, Dept. of BO/10/10 10

- B010130476 Requests, on behalf of util, that Board hold conference call involving all parties to discuss & resolve serious questions re trial brief & related filings submitted by TX Util Generating Co Certificate of Box encl BOUXNIGHT, J A Lowenstein, Neuman, Reis, Azelrad & Toil, B0/10/14.
- 8010160368 Reiterates position that City of Brownsville 800923 motion for disapproval of proposed license conditions was inappropriate Best method of response would be NRC reply brief If such action inappropriate, extension requested CHANANIA: FD Antitrust Division 80/10/14 2pp
- 8010200602 Notice of 801023 special prehearing conference to consider pending motions & requests No further responsive pleadings required of perties until after matters ruled on by ASLS MILLER.M E Atomic Safety and Licensing Board Panel 80/10/14
- 80:0170385 Forwards original copy of Public Utils Board of Brownsville, TX initial trial brief 4/o encl POIRIER,M R Spiegel & McDiarmid 80/10/15 ip.
- B010200387 Requests that documents claimed by utils as confidential be made available to any requesting party on B01021 Reserves right to request showing of confidentiality per ASL8 791107 order PDIRIER: M R Spiegel & McDiarmid 80/10/15 ip.
- 8010220316 Forwards Public Utils Board of City of Brownsville, TX first suppl to 801008 initial tries brief, correcting lists of documents to be offered into evidence SPICOEL.0 Spiegel & McDiarmid. 80/10/14. 1p
- 8010270357 Responds to 801015 ltr re release of potential exhibits for which util has claimed confidential treatment Objects to release of matl per ABLE 790724 stipulation to protective order Lists documents which can be released w/o restriction WETTERHAHN, M. J. Conner, Moore & Corber. 80/10/21. 2pp
- 3010270439 Requests ASLB discuss at 801024 conference question of issuing subpoenss for production of witnesses in lieu of formal filings of individual motions. Cites Part 1VO of initial trial brief.

 SPIEOEL. G Spiegel & McDiarmid. 80/10/22, 1p.
- N Antitrust hearing transcripts
- 8010310551 Transcript of 801024 prehearing conference in Bethesda, MD. Pp 1139-1266 * Atomic Bafety and Licensing Board Panel. 80/10/24 127pp.
- G Inspection reports. IE Bulletins & correspondence
- 8010160107 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Oualification of Class IE Equipment " No written response required.

 SEYFRIT, K V Region 4, Dallas. Office of the Director. 80/09/30
- 8010270518 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required BEYFRIF.K V Region 4. Dellas, Office of the Director, 80/10/02 ip,
- 8010230159 Ack receipt of 801002 ltr & confirms discussion re actions taken to re-examine-repair & restart AMS welding Actions taken are acceptable. Corrective actions re ASME welding restart are not acceptable.

 BEYFRIT.K V Region 4. Dallas. Office of the Director. 80/10/03. 2pp.
- B Reportable occurrences, LERs & related correspondence
- 80:00:0146 Second interim deficiency rept providing additinfo re stop work order on safety-related & code welding Extensive investigation currently in progress covering welder qualification, production welding & insp.

 OPREA. 6 W. Houston Lighting & Power Co. 80/08/13 4pp.

- 8010130208 Interim deficiency rept re incomplete visual insp of concrete embedments. No indication of safety hazards Deficiency under further evaluation as precautionary measure & subsequent rept to be submitted pending survey results OPREA,0 # Houston Lighting & Power Co 80/08/28 3pp
- 8010150199 Final deficiency rept re exhaust fan design for diesel generator fuel oil tank rooms Fan assemblies to be installed subj to replacement o/qualified motors & results of design verification program
 OPREA.0 N Houston Lighting & Power Co 80/09/03 5pp
- 8010150188 Final deficiency rept re concrete placement GA program & revised procedural requirements Inspector added to GC staff Personnel reinstructed in proper consolidation of placement Procedures rewritten winvolvement of supervisors OPREA: G H Houston Lighting & Power Co 80/07/04, 12pp.
- 8010150181 Second interim deficiency rept re breakdown in program for procurement tycle of purchased meths & equipment Procedures & schedule to be developed for verification program of vendor-related, safety-related meths, equipment & racords OPREA,O W Houston Lighting & Power Co 80/09/12 3pp.
- 8010130193 Third interim deficiency rept re rejectable indications on radiographs of girth welds in essential cooling water sys pips. Repair program & re-examination initiated for new accessible & inaccessible welds Update rept by 801215 OPREA: O U. Houston Lighting & Power Co 80/09/12 4pp
- 8010130162 Fourth interim deficiency rept re broken tie-down stude in containment bldg Unit i poler crain rail eys Caused by incomplete fusion of stud welds & deviations from design Stude to be removed.eliminated from design & replaced.

 OPREA.O H. Houston Lighting & Power Co. 80/09/15 6pp
- BO101B0167 Final deficiency rapt re probable deficiency concarning measurement methods used to determine verticality of spent fuel storage racks Not reportable under 10CFR50 598 OPREA, G W. Houston Lighting & Power Ca 80/07/17 3pp
- B010210452 Becond interim deficiency rept re essential cooling water intake structure gantry crane seismic qualification. Caused by 1 5 instead of 2 0 factor in determining OBE values Next rept will be submitted by 810122

 OPREA. O. H. Houston Lighting & Power Co 80/10/01. App.
- B010160794 PNO-IV-80-034 on 801002, util requested limited restart on safety-related welding 8 complex concrete placement Based upon review of corrective action, ANS welding was allowed ABME welding & complex concrete pours were denied HUBACEK, H. Q., CROSSMAN, W A Region 4, Dallas, Diffice of the Director 80/10/03. 1p
- 8010210006 Part 21 rept re deficiencies noted in Class IE battery chargers supplied by Power Conversions Products Various electronic components supplied by foreign suppliers in violation of specs RICE.W M Brown & Root Corp (subs of Halliburton Corp). 80/10/07 4pp
- B010160556 Second interim deficiency rept re stud welds an concrete ambedments Addl data currently being collected for use in detailed evaluation of various aspects of deficiency Next rept will be submitted by B01217

 OPREA: O. H Hauston Lighting & Power Co. B0/10/08. 4pp.
- 8010310528 Final Part 21 rept re breakdown in vendor surveillance program for Class IE electrical equipment. Safety-related equipment purchase orders identified in 800918 deficiency rept are part of 800618 generic deficiency UPREA.O W Houston Lighting & Power Co 80/10/15 9pp
- 8010310295 Second interim deficiency rept re essential cooking water gump seal water design defect.Preliminary design has been daveloped, however, detailed review & final approval pending. Next rept will be submitted by 801221.

 OPREAG W. Houston Lighting & Power Co. 80/10/16. 4p.
- 8010300488 Part 21 rept re defect in Power Conversion Products part. Author will visit site on 801023 WEIL.E.S Power Conversion Products, Inc 80/10/17 3pp.
- 8010280540 First interim deficiency mept re apparent breakdown in quality program of Svc Level I paintings & concrete & etsel surfaces inside reactor containment bldg. Rejected coatings will be removed & reapplied OPREA.G.W. Houston Lighting & Power Co 80/10/21 5pp

0300566 PND-IV-80-34A on 801017.util requested addl limited restart f ANS safety-related welding Request is for performing stegory I structural steel welding embeds up to & including -1/2 inch thickness JRACEK.H G , CROSSMAN.W A Region 4: Dallas, Office of the Irector 80/10/23 ip

9289360 Interim deficiency rept re welding of main steam line pipe (ip restraints Reinsp of welds will be performed by Joun & Root Units are being placed on hold until completion I insp Next rept will be submitted by 810116. PREALQ W Houston Lighting & Power Co 80/10/24 Spp

ignoressional/Executive Correspondence

2200544 Requests that encl unedited transcript of House Bubcommittee 1 Oversight & Investigations 800923 hearing on facility be reved on ASLB & interested parties CKMIT.L Office of the General Counsel 80/10/15. Ip

N10200549 Forwards unedited transcript of House Bubcommittee on Oversight & Investigations 800923 hearing on facility Requests review & correction. Original copy should be returned within 1 wk of receipt PAINTER: K J House of Rep. 80/09/23, 1p

110200557 Unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing on facility in Washington.DC Pp 1-98 + House of Rep 80/09/23 102pp

ET 50-500 DAVIS-BESSE NUCLEAR PORER STATION, UNIT 2 ieneral correspondence

100346 Provides address correction for OH Dept of Health ILLIN.8 M Dhio, State of 80/10/01. 1p

ET 30-801 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3 eneral correspondence

100346 Provides address correction for OH Dept of Health ULLIN.R M Ohio, State of 80/10/01 ip

ET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3 pplication/construction stage documents & correspondence

220079 Forwards errata sheets amending 800905 itr which provided eliminary clarification of TMI action plan requirements resetted table of implementation schedule also enci 6ENHUT.D.O Division of Licensing, 80/09/19 28pp.

210314 Revised notification of 801009 meeting w/util in Seattle, HA discuss NRC regional evaluation of licensee performance r May 1979-Jul 1980 for Units 1 & 4 & Aug 1979-Aug 1980 r Units 3 & 5 Meeting agenda encl Region 5, San Francisco Office of the Director. 80/09/30 3pp

190380 Forwards info re Mount St Halens volcanism, in response to NBERGER, D.L. Washington Public Power Supply System. 80/10/04.

respection reports: IE Bulletins & correspondence

270035 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects ASRE 8A-312 Tope 304 Stainless Steel Pipe." Review of ping matl still in progress VBERGER, D. L. Washington Public Power Supply System 80/08/08.

290628 Responds to IE Bulletin 80-16, "Potential Misapplication of semount. Inc Models 1191 & 1192 Pressure Transmitters w/ ther A or D Output Codes." No subj transmitters installed planned for installation in safety-related sys. 48ERGER, D. L. Washington Public Power Supply System. 80/08/19.

100366 Forwards IE Insp Repts 30-308/80-07 & 50-509/80-07 on 3811-14, No moncompilance noted.

NOGR. 0.8 Region 5, Ben Francisco: Reactor Construction & pineering Support Branch 80/09/03. 2pp.

- --8010100349 IE Insp Repts 50-508/80-07 & 50-509/80-07 on 800811-14 JUNIOUSAY EE Insp. Repts 3D-300/80-07 & 30-309/80-07 on BOOBLI-14
 No noncompliance noted Major areas inspected containment
 steel welding activities as structural steel & concrete
 placement activities on safety-related structures
 DDDDD-R T Region 5, Ban Francisco, Reactor Construction &
 Engineering Support Brench HAIST.D P . HERNANDEZ.Q Region 5,
 Ban Francisco. Office of the Director 80/07/03 Spp
- 8010280618 Responds to IE Bulletin 80-19: "Failures of Mercury-Watted Hatrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Buby relays not in use in logic matrix of sys at facilities RENGERGER: D t. Washington Public Power Supply System 80/09/05.
- 8010270411 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required EMGELKENGR. H. Region 5, San Francisco, Office of the Director. 80/09/10. 1p
- 8010270374 Bubmits addl response to IE Bulletin 80-09, "Hydremotor Actuator Deficiencies." Vendors currently performing actuator testing to determine min capabilities RENSERGER.D L. Washington Public Power Bupply System 80/09/22
- 8010280634 Responds to IE Bulletin 79-24, "Frozen Lines " Thermal alarm tensors are located to monitor anticipated worst case condition & calibr to indicate within 2 F of actual fluid renberoer, D L Washington Public Pawer Supply System, 80/09/22
- 8010160069 Forwards Buppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required EMGELKEN'R H Region 8, San Francisco, Office of the Director. 80/07/29 ip.
- 8010310080 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type H-2 Spring Return to Neutral Control Switches " Nautral contacts are not connected to any circuitry Approx B manhours expended on actions required by bulletin. RENBERGER: D.L. Washington Public Power Supply Bystem 60/10/01
- B010280027 Forwards IE Circular 80-22. "Confirmation of Employee Qualifications " No written response required EMOELKEN R. H Region 5. San Francisco. Office of the Director 80/10/02 1p.
- 8010310007 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-308/80-06 k 50-309/80-06. Septime 10 Region 5, Sen Francisco, Reactor Construction & Engineering Support Branch 80/10/24 ip
- --B010310012 Responds to NRC B00904 ltr re violations noted in IE Insp Repts 30-308/80-06 & 30-309/80-06. Corrective actions: contractor OC directed to document rework in accordance w/applicable project procedures. REMBERGER.D.L. Washington Public Power Bupply Bystem 80/09/26.
- --B010310014 Forwards IE Insp Repts 50-508/80-04 & 50-509/80-05 on B00625-0718 & notice of violation EPENCER.O S. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. B0/07/04 2pp.
- ---8010310015 Notice of violation from insp on 800625-0718, * Region 5. San Francisco: Office of the Director. 80/08/28 2pp.
- --8010G10018 IE Insp Repts 50-508/80-06 & 50-509/80-06 on 800625-0718
 Noncompliance noted failure to establish measures to
 indicate imag status & failure to properly accomplish &
 inspect weiding.
 BISHOP-T M. Region 5, San Francisco, Office of the Director,
 HAYNES-R.C. Region 5, San Francisco, Reactor Construction &
 Engineering Support Branch 80/08/28, App.

DOCKET STN-50-509 RPPSB NUCLEAR PROJECT, UNIT 8 A Application/construction stage documents & correspondence

8010270099 Forwards errets sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl. EISENMUT, D. O. Division of Licensing. 80/09/19, 28pp.

- 8010210314 Revised notification of 801009 meeting w/util in Seattle,WA to discuss NRC regional evaluation of licensee performance for May 1979-Jul 1980 for Units 1 & 4 & Aug 1979-Aug 1980 for Units 3 & 5 Meeting agenda encl 4 Ragion 5. San Francisco, Office of the Director 80/09/30 3pp
- B010150380 Forwards info re Mount St Helens volcanism in response to NRC 800731 request RENBERGER, D L. Washington Public Power Supply System 80/10/06
- Q Inspection reports, IE Bulletins & correspondence
- 8010270035 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe." Review of piping matl still in progress RENBERGER.D L. Washington Public Power Supply System. 80/08/08
- BO10280625 Responds to IE Bulletin 80-16. "Potential Hisapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Butput Codes " No sub; transmitters installed or planned for installation in safety-related sys RENBERGER, D L Washington Public Power Supply System 80/08/19
- 8010100364 Forwards IE Insp Repts 50-508/80-07 & 50-509/80-07 on 800911-14 No noncompliance noted 8PENCER, 0 S. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/09/03 2pp
- --8010100347 IE Insp Repts 50-508/80-07 & 50-509/80-07 on 800811-14
 No noncompliance noted Major areas inspected containment
 steel weiding activities & structural steel & concrete
 glacement activities on safety-related structures.
 DODDB:R T Region 5, San Francisco, Reactor Construction &
 Engineering Support Branch HAIST, D P, HERNANDEZ, G
 San Francisco, Office of the Director 80/09/03 8pp
- 8010280618 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Sub, relays not in use in logic matrix of sys at facilities.

 RENBERGER, D L Washington Public Power Supply System 80/09/05 to.
- B010270411 Forwards IE Circular 80-21, "Regulation of Refueling Grews." No written response required ENGELKEUR H Region 5. San Francisco, Office of the Director 80/09/10 ip
- 9010270374 Submits addl response to IE Builetin 80-09, "Hydramotor Actuator Deficiencies" Vendors currently performing actuator testing to determine min capabilities.
 RENBERGER, D. L. Washington Public Power Supply System 80/09/22.
- B010280634 Responds to IE Bulletin 79-24, "Frozen Lines" Thermal alarm sensors are located to monitor anticipated worst case condition 3 calibr to indicate within 2 F of actual fluid temp.
 RENBERGER, D. L. Washington Public Power Supply System. 80/09/22
- 8010160069 Forwards Suppl 2 to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No written response required ENGELKEN, R. H Region 5, Ban Francisco, Office of the Director 80/09/29 Ip
- B010310080 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Emitches" Neutral contacts are not connected to any circuitry. Approx B manhours expended on actions required by bulletin. RENBERGER.D L. Washington Public Power Supply Bystem. B0/10/01
- 8010280027 Forwards IE Circular 80-22, "Confirmation of Employee Gwallfication: "No written response required. ENGELMENTR H Region 5, San Francisco, Office of the Director 80/10/02 1p
- 8010310007 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/80-06 & 50-509/80-06 SPENCER:0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/10/24. 1p

- --8010310012 Responds to NRC B00904 itr re violations noted in IE Insp. Rapts 50-508/80-06 & 50-509/80-06 Corrective actions contractor GC directed to document rework in accordance w/applicable project procedures
 RENBERGER, D. L. Washington Public Power Supply System 80/09/26
 400
- --8010310014 Forwards IE Insp Repts 50-508/80-06 & 50-509/80-06 on 800625-0718 & notice of violation SPENCER.0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/04 2pp
- --8010310015 Notice of violation from insp on 800625-0718 * Region 3. San Francisco. Office of the Director 80/08/28 2pp
- --8010310D1B IE Insp Repts 50-508/80-06 & 50-509/80-06 on 800625-0718
 Noncompliance noted failure to establish measures to
 indicate insp status & failure to properly accomplish &
 inspect welding
 BISHOP.T W Region 5. San Francisco. Office of the Director
 HAYNES.R C Region 5. San Francisco. Reactor Construction &
 Engineering Support Branch 80/08/28 App

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

- G Adjudicatory correspondence
- 6010170367 Response to ASLB 800909 order requesting add1 info re siting & emergency planning Blue Hills site within NUREG-0625 parameters Regulations requiring 10 & 50-mile emergency planning tones outside proceeding M/Certificate of Bvc 4000H6AB.C P Hearing Branch 3 80/10/15 17pp

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

- O Adjudicatory correspondence
- 8010170367 Response to ASLB 800909 order requesting add1 info re siting 3 smergency planning. Blue Hills site within NUREG-0625 parameters. Regulations requiring 10 & 50-mile emergency planning zones outside proceeding W/Certificate of Svc WOODHEAD, C P Hearing Branch 3 80/10/15 17pp

DOCKET 50-513 WPPBS NUCLEAR PROJECT. UNIT 4

- A Application/construction stage documents & correspondence
- B010220077 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D.0 Division of Licensing 80/09/19 28pp
- 8010210314 Revised notification of 801007 meeting w/util in Seattle, HA to discuss NRC regional evaluation of licensee performance for May 1979-Jul 1980 for Units 1 & 4 & Aug 1979-Aug 1980 for Units 3 & 5 Meeting agenda
- 8010160321 Informs that commitment to perform scale model recirculation surp test in lieu of committed in-plant test may be waived after alternative scale model test program has been reviewed NRC will determine suitability of substitute, YOUNOBLOOD, B J Licensing Branch 1 80/10/01 2pp.
- BO10210751 Responds to util 790515 & 0814 requests to perform scale model recirculation sump test in lieu of in-plant test per PBAR Commitment may be relieved contingent on NRC approval of alternative program YOUNOBLOUD.B J Licensing Branch 1, 80/10/01 2pp
- G. Inspection reports. IE Bulletins & correspondence
- 8010240579 Forwards IE Insp Repts 30-460/80-06 & 50-513/80-06 on 800429-0502 & notice of violation ENGELSEN.R H Region 3. San Francisco, Office of the Director 80/07/11 2pp
- --B0102405B1 Notice of violation from insp on B00429-0502 # Region 5, San Francisco, Office of the Director B0/07/09 3pp

- --8010240587 IE Insp Repts 50-460/80-06 % 50-513/80-06 on 800429-0502
 Noncompliance noted failure to properly store & protect
 safety-related equipment & to install pips hanger in
 accordance w/instructions
 BISHOP,T W. HERNANDEZ,Q Region 5, San Francisco, Office of the
 Director DODDS, R Y Region 5, San Francisco, Reactor
 Construction & Engineering Support Branch 80/07/09 10pp
- 8010280618 Responds to IE Bullatin 80~17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Sub; relays not in use in logic matrix of sys at facilities RENGERGER.D L Washington Public Power Supply System 80/07/05 to
- 8010090083 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches "
 Projects do not use Westinghouse Type W-2 switches in safety-related applications
 RENBEROER.D L Washington Public Power Supply System. 80/09/08
- 6010290411 Forwards IE Circular 80-21, "Regulation of Refueling Craws" No written response required ENCELMEN.R H Region 5, San Francisco, Office of the Director, 80/09/10 10
- 8010080573 Responds to IE Bulletin 79-24. "Frozen Lines " Adequate measures taken to preclude freezing of safety-related lines RENBERGER, D. L. Washington Public Power Supply System 80/09/15
- B010160069 Forwards Buppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required. ENGELKEN.R H Region 5, San Francisco, Office of the Director B0/09/29 1p
- 8010280027 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required ENGELKEN.R. H Region 5. San Francisco, Office of the Director 80/10/02. 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8010020603 Part 21 rept re potential defect in component of DRRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DRRV 16.4 DRRV 20 built before Feb 1930 MARTINI.D H Transamerica Delaval, Inc. 80/09/19 2pp
- B010300484 Interim deficiency rept re ASME III, Seismic Catagory I pipe supports related to IE Bulletin 79-02, Revision 2 Revises B0012A commitments & provides status w/revised completion dates, Related documentation encl
 RENBERGER, D L. Washington Public Power Supply System 80/09/25
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8060220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISERNUT.D O. Division of Licensing. 80/09/19 28pp.
- BO10270280 Expresses desire to proceed w/const licensing of facility NRC has not committed resources to complete application reenviron & site suitability issues Certificate of Bvc encl LINOBLAD, W J Portland General Electric Co 80/09/30. 4pp.
- G Adjudicatory correspondence
- GO10010010 Becond status rept re environ site suitability record.per ASLB 790721 order Requests approval of schedule agreed upon by parties for proposed findings. Further status rept will be filed by BO117 Certificate of Svc encl BURDENICK, B. M Hearing Branch 4 89/09/30, 5pp.
- BOL003043B Order re-schedule for site suitability filings Approves BOL015 for applicant.BOL125 for NRC.BIOL15 for State of OR & BIO206 for intervenors BOWERSE S. Atomic Sefety and Licensing Board Panel. BO/10/01. Ip.
- 8010210365 Forwards 801015 motion requesting extension until 801022 for filing of applicant proposed findings of fact HASTINGS.U. Portland General Electric Co 80/10/15. 1p.

- --B010210571 Requests order extending time to file proposed findings of fact from B01015 to B01022 Certificate of Svc encl HASTIROS.W Portland General Electric Co 80/10/15 3pp
- 8010270378 Forwards proposed findings of fact & conclusions of law in form of partial initial decision re environ & site suitability Table of contents encl HASTINOS.W Portland General Electric Co 80/10/22 2pp
- --8010290382 Proposed findings of fact & conclusions of law in form of partial initial decision re environ & site suitability Argues adequacy of location from radiological effects standpoint Certificate of Svc encl
 Portland General Electric Co 80/10/22 75pp
- 8010270499 Order granting extension until 801022 for util to fils findings of fact Other parties have addl seven days from filing time stated in ASLB 801001 order BONERS.E B Atomic Gafety and Licensing Board Panel 80/10/23
- DUCKET 50-515 PEDBLE SPRINGS NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TM1 action plan requirements Corrected table of implementation schedule also encl EISENHUT.D O Division of Licensing 80/09/19 28pp
- 8010270280 Expresses desire to proceed w/const licensing of facility NRC has not committed resources to complete application reenviron & site suitability issues Certificate of Svc encl LINDBLAD.U J Portland General Electric Co 80/09/30 4pp
- O Adjudicatory correspondence
- 8010010010 Second status rept re environ site suitability record, per ASLB 790721 order Requests approval of schedule agreed upon by parties for proposed findings Further status rept will be filed by 801117 Certificate of 8vc encl BORDENICK.B H Hearing Dranch 4 80/09/30 5pp
- 8010030438 Order re schedule for site suitability filings Approves
 801015 for applicant:801125 for NRC.810115 for State of OR &
 810206 for intervenors
 80MERS.E 8 Atomic Safety and Licensing Board Panel 80/10/01. ip
- 8010210755 Forwards 801015 motion requesting extension until 801022 for filing of applicant proposed findings of fact HABTINOS.W Portland General Electric Co 80/10/15 ip
- --8010210571 Requests order extending time to file proposed findings of fact from 801015 to 801022 Certificate of Svc encl HASTINOS,W Portland General Electric Co 80/10/15. 3pp
- 8010270378 Forwards proposed findings of fact & conclusions of law in form of partial initial decision re environ & site suitability Table of contents encl. HASTINOS.H Portland General Electric Co 80/10/22 2pp
- ---8010270382 Proposed findings of fact & conclusions of law in form of partial initial decision re environ & site suitability
 Argues adequacy of location from radiological effects
 standpoint Certificate of Syc encl
 Portland General Electric Co 80/10/22 75pp.
- 8010270497 Order granting extension until 801022 for util to file findings of fact Other parties have addl seven days from filing time stated in ASLB 801001 order BONERS.E 8 Atomic Safety and Licensing Board Panel, 80/10/23 Ip
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

 O Adjudicatory correspondence
- B010160522 Forwards petition for rehearing in Case B0003 re application for certificate of environ compatibility & public need.

 Certificate of Bvc encl
 FUTTER, J L Long Taland Lighting Co 80/10/08 17pp
- 8010160754 Status Rept 5 in siting board proceeding Applicant 801008 patition for rehearing in Case 80003 encl. Paper re impact of siting board developments on appeal & CPs will soon be filed, Certificate of 8vc encl.

 REVELEY: H T Long Island Lighting Co REVELEY: W. T. Hunton & Williams 80/10/13 4pp

- --8010160762 Petation for rehearing of Case 80003 before NY State Board on Electric Generation Siting & Environ Opinion & order 800708 deadlines should be extended one yr Proceedings must be coordinated w/EPA review Certificate of 8vc encl BARRETT-E M , WALSH, E J , FUTTER, J i. Long Island Lighting Co 80/10/08 13pp
- H General correspondence
- 8010030378 Informs that correspondence for nuclear responsibilities should be addressed to MS Pollock HGFFORD:A W Long Esland Lighting Co 80/09/30 1p
- 8010200421 Notifies that future NRC correspondence re facilities should be addressed to CJ Davis WOFFORD.A W Long Island Lighting Co 80/10/10 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8010030534 Responds to IE Bulletin 80-16 Plant design does not include Rosenount Model 1151 & 1152 pressure transmitters PLASKON, R E Long Island Lighting Co 80/08/20 1p.
- 8010200695 Responds to IE Bulletin 80-20, "Failure of Hestinghouse Type H-2 Spring Return to Neutral Control Switches" Hestinghouse has not fabricated any control cabinets for safety-related equipment using specified switches PLASKON, R E Long Island Lighting Co 80/09/16 ip.
- 8010240147 Forwards IE Circular 80-22, "Confirmation of Employee Gualifications " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/10/02 19
- 8010280248 Forwards IE Info Notice 90-36. "Failure of Steam Generator Support Bolting " No specific action or response requested. GRIER, B H Region 5. Philadelphia. Office of the Director 80/10/10 19
- DOCKET 8TN-50-517 JAHESPORT NUCLEAR STATION, UNIT 2 9 Adjudicatory correspondence
- B010160522 Forwards petition for rehearing in Case B0003 re application for certificate of environ compatibility & public need Certificate of Bvc encl FUTTER, J L. Long Island Lighting Co. B0/10/0B. 17pp
- B010160754 Status Rept 5 in siting board proceeding Applicant B01008 petition for rehearing in Case B0003 encl Paper re impact of siting board developments on appeal & CPs will soon be filed. Certificate of Svc encl REVELEY, W T Long Island Lighting Co. REVELEY, W T Hunton & Williams B0/10/13 4pp
- --8010160762 Petition for rehearing of Case 80003 before NY Blate Board on Electric Generation Siting & Environ Opinion & order 800708 deadlines should be extended one or Proceedings must be coordinated w/EPA review Certificate of Svc encl BARRETT, EM, WALSH, EJ, FUTTER, JL Long Island Lighting Co. 80/10/08, 15pp
- H. General correspondence
- 8010030378 Informs that correspondence for nuclear responsibilities should be addressed to M8 Pollock WOFFORD: A W Long Island Lighting Co 80/09/30. 1p.
- 8010200421 Notifies that future NRC correspondence re facilities should be addressed to CJ Davis WQFFORD:A W. Long Island Lighting Co 60/10/10 ip
- G. Inspection reports, IE Bulletins & correspondence
- 8010030534 Responds to IE Bulletin 80-16.Plant design does not include Rosemount Model 1151 & 1152 pressure transmitters PLASKON, R.E. Long Island Lighting Co. 80/08/20. ip.
- 8010200695 Responds to IE Bulletin 80-20, "Failure of Hestinghouse Type M-2 Spring Return to Neutrel Control Buitches." Hestinghouse has not fabricated any control cabinets for safety-related equipment using specified switches PLABKON: R. E. Long Island Lighting Co. 80/09/16, 1p.

- 8010240147 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/10/02 ip
- B01028024B Forwards IE Info Notice 80-35. "Failure of Steam Generator Support Bolting " No specific action or response requested GRIER, B H Region 1. Philadelphia, Office of the Director 80/10/10 1p
- DUCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATWB issue Mods will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry, Bequoyah & Natts Bar & by fuel loading at Beliefonte. Harts-ville & Phipps Bend MILLS, L M Tennessee Valley Authority 80/09/17 Spp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT.D G Division of Licensing 80/09/19 28pp
- G Inspection reports, IF Bulletins & correspondence
- 7809180180 IE Inspec Rept #50-518/78-07.50-519/78-07.50-520/78-07 t 50-521/78-07.CPPR-150.CPPR-151.CPPR-152.CPPR-153ion 780619-22 during which no items of nancompliance were identified in reactor vessel presve inspec [Enc] to 78091801661 CROMLEY.B R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 78/08/08 7pp
- 7807180180 IE Insp Rept 50-518/78-07.519/78-07.50-520/78-07 & 50-521/78-07(CPPR-15).CPPR-151.CPPR-152.CPPR-153) on 780619-22 furing which no items of noncompliance were identified in reactor vessel preservice insp (Encl to 7809180166) CROWLEY. B R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 78/08/08 7pp
- E010090236 Forwards IE Insp Repts 50-518/80-15, 50-519/80-15, 50-520/80-15 & 50-521/80-15 on 800630-0731 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/28 2pp
- --8010070244 IC Insp Repts 50-518/80-15,50-519/80-15,50-520/80-15 & 50-521/80-15 No noncompliance noted Major areas inspected match compaction & structural concrete for spray ponds & structural steel in A-1 fuel bldg
 EMANAW B Region 2, Atlanta, Office of the Director CANTRELL.F & Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/27 7pp
- BD10200637 Forwards IE Info Notice BO-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matis"

 O'REILLY, J P Region 2, Atlanta, Office of the Director, 10
- 8010270055 Forwards IE Insp Repts 50-518/80-16.50-519/80-16 & 50-520/80-16 on 800804-08 No noncompliance noted MURPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --8010270060 JE Insp Repts 50-518/80-16,50-519/80-16 & 50-520/80-16 on 800804-08 No moncompliance noted Major areas inspected welding mati control steel structures & supports & welding activities within containment.

 GIRARD, E. H. Region 2. Atlanta, Office of the Director, HERDY, A.R. Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch. 80/09/05 7pp
- B010090102 Forwards response to IE Bulletin 80-20, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches," None of sub; switches found in safety-related applications to date Investigation continuing MILLS: L. M. Tennessee Valley Authority 80/09/12, 10pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in 16 insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-318/80-11, 50-519/80-11 & others MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 28p

- --8010170123 Responds to NRC 800806 itr re violations noted in IE Insp Repts 50-327/80-24,50-328/80-15 & others Corrective actions QA audits have been reviewed to identify any conclusions & recommendations found to be deficienties MILLS.L K Tennessee Valley Authority 80/09/02 14pp
- 8010160184 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" No written response required O'REILLY: J P Region 2, Atlanta, Office of the Director 80/09/30 to
- 8010270530 Forwards IF Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/10/02
- 8010290066 Forwards LE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- BO10090497 Forwards "Hartsville Nuclear Plant Primary Water Quality Monitoring Rept" EL-ASHRY.M T Tennessee Valley Authority 80/10/01 ip
- --8010080506 "Nartsville Nuclear Plant Primary Water Quality Monitoring Rapt " MENERT.D L Tennessee Valley Authority WR(70)-50-10-80 1 90/09/30 272ep
- S Reportable occurrences, LERs & related correspondence
- 8010010861 Part 21 third interim rept re defects in Resemount trip/calibr units & pressure transmitters supplied by GE Rosemount & GE will replace defective switches in Model StODU trip units Transmitters will be corrected MILLS.C. M. Tennessee Valley Authority 80/09/17 Spp.
- 8010320603 Part 21 rept re potential defect in component of DSRV standby diesel generator concerning link rod assembly which could result in engine failure Defect limited to models DSRV 12.0 BSRV 15.0 SRV 18.0 DSRV 15.0 SRV 18.0 DSRV 18
- 6010070342 Third interim deficiency rept re cracks in reactor pressure vessel wall Licensee will repair cracks in wall Awaiting GE approval of recommended disposition & repair procedures Will submit final rept by 810101

 MILLGIL M Tennessee Valley Authority 80/10/03 ip.
- DOCKET 9TH-50-919 HARTSVILLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B010020480 Forwards util program for resolving ATMS issue Mods will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry Sequoyah & Hatts Bar & by fuel loading at Bellefonte. Hartsvélle & Phipps Bend MILLS, L M Tennessee Valley Authority 80/09/17 Spp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENNUT.D O Division of Licensing 80/09/19 28pp
- Q Inspection reports, IE Bulletins & correspondence
- B010070236 Forwards IE Insp Repts 50-518/80-15, 50-519/80-15, 50-529/80-15 / 50-521/80-15 on 800630-0731. No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp
- --B010090244 IE Insp Repts 50-518/80-15, 50-519/80-15, 50-520/80-15 & 50-521/80-15 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray ponds & structural steel in A-1 fuel bldg
 BMAN.W.B Region 2, Atlanta, Office of the Director.
 CANTRELL.F & Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/27, 7pp.

- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Regulfrements of Exclusive Use Shipments of Radioactive Matls "O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29
 - 1p Region 2, Actanta, Director 80/08/29
- 8010270055 Forwards IE Insp Repts 50-518/80-16.50-519/80-16 & 50-520/80-16 on 800804-08 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/10 2pp
- ~-8010270060 IE Insp Repts 50-518/80-16,50-519/80-16 & 50-520/80-16 on 800804-08 No noncompliance noted Hajor areas inspected welding math control, steal agructures & supports & welding activities within containment GIRARD,E H Region 2. Atlants, Office of the Director HERDT,A R Region 2. Atlants Reactor Construction & Engineering Bupport Branch 80/09/03 7pp
- 8010090102 Forwards response to IE Bulletin 80-20, "Failures of Mestinghouse Type M-2 Spring Return to Neutral Control Switches " None of sub) switches found in safety-related applications to date Investigation continuing MILLS.L M Tennessee Valley Authority 80/09/12 10pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE 1819 Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 80-391/80-14, 50-439/80-13, 50-396/80-11, 50-519/80-11 & others HURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- ---8010170123 Responds to NRC 800804 lir re violations nated in IE Insp Repts 50-327/80-24,50-328/80-15 & others Corrective actions OA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLS.L M Tennesses Vallay Authority 80/09/02 14pp
- 8010160184 Forwards Suppl 2 to IE Bulletin 79-018, "Environ dualification of Class IE Equipment" No written response required O'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/09/30, to
- 8010270330 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02
- 8010270066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested C'REFLLY, J.P. Region 2. Atlanta, Office of the Director 80/10/10
- R Periodic operating reports & related correspondence
- BO100B0497 Forwards "Hartsville Nuclear Plant Primary Water Guality Monitoring Rept" EL-ASHRY, N Tennassee Valley Authority 80/10/01. 1p
- --B010080506 "Hartsville Nuclear Plant Primary Water Guality Monitoring Rept,"

 METUERT: D L Tennessee Valley Authority WR(70)-50-10-80 1, 80/09/30 272pp
- S Reportable occurrences, LFRs & related correspondence
- 8010010851 Part 21 third interim mept rm defects in Rosemount trip/calibr units & pressure transmitters supplied by CE. Rosemount & GE will replace defective switches in Model 5100U trip units Transmitters will be corrected MILLS.L N Tennessee Valley Authority 80/09/17 3pp
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

 A Application/construction stage documents & correspondence
- B0100204B0 Forwards util program for resolving ATMB issue Mods will be evaluated & implemented to reduce risk Program can be implemented by 1988 at Browns Ferry, Bequoyah & Watts Bar & by fuel loading at Bellefonte. Hartsville & Phipps Bend, MiLLS.L M Tennessee Valley Authority 80/09717 5pp
- 80:0220099 Forwards errats sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected bable of implementation schedule also encl.
 EISENMUT.D 0. Division of Licensing, 80/09/19. 28pp.

- O Inspection reports, IE Bulletins & correspondence
- 8010090236 Forwards IE Insp Repts 50-518/80-15, 50-519/80-15, 50-529/80-15 & 50-521/80-15 on 800630-0731 No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp
- --8010070244 IE Insp Repts 50-519/80-15, 50-519/80-15, 50-520/80-15 & 50-521/80-15 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray ponds & structural steel in A-1 fuel bldg

 BNAM.W B Region 2, Atlanta, Office of the Director CAKIRELL.f B Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/27 7pp
- 8010200637 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls " O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/29
- 8010270055 Forwards IE Insp Repts 50-519/80-14,50-519/80-14 & 50-520/80-14 on 800804-08 No noncompliance notes MURPHY.C E Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --8010270060 IE Insp Repts 50-518/80-16,50-519/80-16 & 50-520/80-16 on 800804-08 No noncompliance noted Hajor areas inspected, welding math controlisteel structures & supports & welding activities within containment GIRARD, E. H. Region 2. Atlanta, Office of the Director. HERDY, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/05 7pp
- 8010070102 Forwards response to IE Bulletin 80-20. "Failures of Westinghouse Type N-2 Spring Return to Neutral Control Buitches" None of subj switches found in safety-related applications to date Investigation continuing MILLS, L ff Tonnessee Valley Authority 80/07/12 10pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rapts 50-327/80-24, 50-328/80-15.50-399/80-20.50-391/80-14.50-438/80-13.50-518/80-11.50-519/80-11 & others MURPHY,C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
 - 10170123 Responds to NRC 800806 ltr re violations noted in IE Insp Repts 50-327/80-24.50-328/80-15 & others Corrective actions: GA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies HILLS.L M Tennessee Valley Authority 80/09/02 14pp.
- /10160184 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Gualification of Class JE Equipment " No written response required.

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30 lp.
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02
- B010290066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting." No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/t0/10 to
- R Periodic operating reports & related correspondence
- B010080497 Forwards "Hartsvills Nuclear Plant Primary Mater Quality Monitoring Rept " EL-ASHRY, M T Tennessee Valley Authority 80/10/01. 1p
- --8010080506 "Hartsville Nuclear Plant Primary Water Quality Monitoring Rept." HEINERT.D.L Tennessee Valley Authority WR(70)-50-10-80 1 80/09/30 272pp
- 8. Reportable occurrences, LERs & related correspondence
- BOIODIOBAI Part 2: third interim rept re defects in Rosemount trip/calibr units & pressure transmitters supplied by OE. Rosemount & OE will replace defective switches in Model 510DU trip units Transmitters will be corrected MILLS, L. M. Tennessee Valley Authority BO/09/17 3pp.

- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATWS issue Hods will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Browns Ferry, Sequoyah & Watts Bar & by fyel loading at Bellefonte. Hartsville & Phipps Bend MILLS, L. K Tennessee Valley Authority 80/09/17 5pp
- B010220097 Forwards errata sheets amending B00905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl. EIBENNUT, D G Division of Licensing B0/09/19 2gpp
- Q Inspection reports, IE Bulletins & correspondence
- 7809180180 IE Inspec Rept #50-518/78-07.50-519/78-07.50-520/78-07 & 50-521/78-07 (CPPR-150. CPPR-151. CPPR-152. CPPR-153) on 780619-22 during which no items of noncompliance were identified in reactor vessel presvc inspec [Encl to 7809180164] CROMLEY. B R. Region 2. Atlanta: Reactor Construction & Engineering Support Branch 78/08/08 7pp.
- 8010090236 Forwards IE Insp Repts 50-518/80-15.50-519/80-15. 50-529/80-15 & 50-521/80-15 on 800630-0731 No noncompliance noted. HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/28 2pp
- --8010090244 IE Insp Repts 50-518/80-15,50-519/80-15,50-520/80-15 to 50-521/80-15 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray ponds & structural steel in A-1 fuel blidg

 BHAN,N B Region 2, Atlanta, Office of the Director 80/08/27
- 8010200637 Forwards IE Info Notice 80-32. "Clarification of Certain Raquirements of Exclusive Use Shipments of Radioactive Hatls." O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/29
- 8010070102 Forwards response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Ewitches "None of subj switches found in safety-related applications to date Investigation continuing.

 MILLS,L M Tennesses Valley Authority 80/07/12 10pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-24, 90-328/80-15, 50-390/80-20, 50-391/80-14, 50-439/80-13, 50-518/80-11, 50-519/80-11 & others MUR
- --8010170123 Responds to NRC 800806 itr re violations noted in IE Insp Repts 50-327/80-24,50-328/80-15 & others Corrective actions QA addits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLS.L M Tennessee Velley Authority. 80/09/02 14pp
- 80i0160184 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No written response required.
 O'REILLY, J. P Region 2, Atlanta, Office of the Director. E0/09/30 ip
- 8D10270530 Forwards IE Gircular 80-22, "Confirmation of Employee Qualifications" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02
- 8010270056 Forwards IE info Notice 80-35, "Failure of Steam Cenerator Support Bolting." No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/10/10
- R Periodic operating reports & related correspondence
- 8010080497 Forwards "Hartsville Nuclear Plant Primary Water Quality Monitoring Rept " EL-ASHRY: T Tennessee Valley Authority 80/10/01, 1p
- --B010080506 "Hartsville Nuclear Plant Primary Water Quality Monitoring Rept " MEINERT, D. L. Tennessee Vailey Authority WR(70)-50-10-80 1 B0/09/30 272pp.

- B Reportable occurrences, LERs & related correspondence
- B010010B61 Part 21 third interim rept re defects in Rosemount trip/celibr units & pressure transmitters supplied by GE Assemount & OE will replace defective switches in Model 5100U trip units Transmitters will be corrected HILLBL M Tennessee Valley Authority 80/09/17 3pp
- DOCKET STN-90-822 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EIBERHUT.D O Division of Licensing 80709719 28pp
- B010020337 Forwards Amend 5 to application for OL & Annual Financial Repts for 1979
 HYERS.R V Puget Sound Power & Light Co B0/09/26 2pp
- --8010020343 Amend 5 to application for OL Amend revises application to reflect relocation of project to Hanford Reservation & updates Exhibits B.C.D.E. & O Exhibits A & H are deleted HYERS.R V Puget Sound Power & Light Co 80/09/26 34pp
- ---8010020349 Annual Financial Rept 1977

 * Puget Sound Power % Light Co 80/09/24 33pp,
- ---8010020355 Annual Financial Rept 1979
 4 Pacific Power & Light Co 80/03/31 37pp
- --8010020361 Annual Financial Rept 1979

 * Washington Water Power Co 80/09/26 37pp
- --E010020378 Annual Financial Rept 1979
 * Portland Cameral Electric Co 60/03/31 42pp.
- 8010200437 Forwards original affadivits of svc dtd 800930 ra Amend 5 to application (general info vol) per 10CFR2 101 & Commission instruction for distributing amend applications
 THOMBEN,F T Perkins, Cole, Stone, Olsen & Williams 80/10/09
- O Adjudicatory correspondence
- 8010070313 Advises that Amend 5 to application has been filed, changing site to Hanford Reservation, per ASLB 800827 order Present schedule is to file amends to environ rept & PBAR reflecting change by 800930
 THOMSEN, F T Perkins, Coje, Stone, Disen & Williams 80/09/30
- I Financial information
- B010020337 Forwards Amend 5 to application for GL & Annual Financial Repts for 1979. HYERS.R V Puget Sound Power & Light Co B0/09/26 2pp.
- ---8010020355 Annual Financial Rept 1979
 * Pacific Power & Light Co 80/03/31 37pp
- --8010020361 Annual Financial Rept 1979.

 # Washington Water Power Co 80/09/26 37pp.
- --8010020378 Annuel Financial Rept 1979
 Portland General Electric Co 80/03/31 42pp
- POCKET BIN-50-523 EXAGIT NUCLEAR POWER PROJECT. UNIT 2

 A Application/construction stage documents & correspondence
- 80i0220099 Porwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISE/HWI7.D 0. Division of Licensing. 80/09/19. 28pp
- 8010020337 Forwards Amend 5 to application for OL & Annual Financial Repts for 1979.

 MYERS, R. V. Puget Sound Power & Light Co. 80/09/26 2pp.

- --B010020343 Amend 5 to application for CL Amend revises application to reflect relocation of project to Hamford Reservation & updates Exhibits B.C.D.E. & O Exhibits A & H are deleted MYCRS.R.V Puget Sound Power & Light Co 80/09/26 34pp
- --8010020349 Annual Financial Rept 1979 * Puget Sound Power & Light Co 80/09/26 53pp
- --8010020355 Annual Financial Rept 1979 * Pacific Power & Light Co 80/03/31 37pp
- --B010020361 Annuel Financial Rept 1979 ⇒ Nashington Water Power Co 80/09/26 37pp
- 8010200437 Forwards original affadivits of svc dtd 800930 re Amend 5 to application (general info vol) per 10CFR2 101 & Commission instruction for distributing amend applications
 THOMSEN.F T Perkins, Cole. Stone, Olsen & Williams 60/10/09
- Q Adjudicatory correspondence
- 8010070313 Advises that Amend 3 to application has been filed changing site to Hanford Reservation, per ABLB 800027 order Present schedule is to file amends to environ rept & PSAR reflecting change by 800930.
 THOMBEN, FT Perkins, Coie, Btone, Olsen & Williams 80/09/30
- I Financial information
- 8010020337 Forwards Amend 5 to application for OL & Annual Financial Repts for 1979 MYERB,R V Puget Sound Power & Light Co 80/09/26 2pp
- --8010020349 Annual Financial Rept 1979
 * Puget Sound Power & Light Co B0/09/26, 53pp.
- --8010020355 Annual Financial Rept 1979

 * Pacific Power & Light Co. 80/03/31 37pp
- --8010020361 Annual Financial Rept 1979
 4 Washington Water Power Co 80/09/26 37pp
- --8010020378 Annual Financial Rept 1779 * Portland General Electric Co 80/03/31 42pa
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010220079 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also encl EIBENHUT.D G. Division of Licensing 80/09/19 28pp
- 8010210417 Advises that Bechtel responses to outstanding items of PVN98 Class IE dc power sys review have been reviewed & found to sufficiently address concerns.

 VAN BRUNT: E. Arizona Public Service Co B0/10/14 2pp.
- 8010280417 Discusses sys reviews for various facility sys Requests NRC scheduls sys reviews supporting licensing schedule, Also requests meeting in Bethesda. MD to resolve facility & CESBAR-F sys review issues
 VAN BRUNT, E. Arizona Public Bervice Co. 80/10/21 2pp
- C. Utility Environmental Report (ER), amends & correspondence
- 8010280392 Comments by Water & Power Resources Svc on Suppl 1 to environ rept for facility, Proposal has no identifiable effect on DDI programs TROMPETER: K M Interior, Dept of. 80/10/23 ip.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8010100306 Forwards Proof of Syc for Amend 2 to facility FBAR per DO Elsenhut 800618 itr & 100FR2 101. VAN BRUNT,E E Aritona Public Service Co 80/10/02 3pp

Q Inspection reports. IE Bulletine & correspondence

- 8010170417 Forwards IE Inep Repts 50-528/80-12:50-529/80-12 & 50-530/80-12 on 800728-0801 No noncompliance noted SPENCER:0 B Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/09/03 2pp
- --B010170428 IE Insp Repts 50-528/80-12.50-529/80-12 & 50-530/80-12 on B00788-9801 No noncompliance noted Major areas inspected. reactor coolent pressure boundary welding done liner plate installation electrical cables & general const ECMMARDIJH, WAONER, W. J. Region 5. San Francisco, Office of the Director DODDS: R. T. Region 5. San Francisco, Cestor Construction & Engineering Support Branch B0/09/03 7pp
- B010170644 Forwards IE Insp Repts 50-528/80-13,50-529/80-13 & 50-530/80-13 on B00714-29 No noncompliance noted BPENCER,0.8. Region 5, San Francisco. Reactor Construction & Engineering Bupport Branch B0/09/10 2pp.
- --B010170662 IE Insp Repts 50-528/80-13, 50-529/80-13 & 50-339/80-13 on 800714-25. No noncompliance noted Major areas inspected closure of Unit i containment bldg const opening & reinforcing steel amission from containment bldg walls, VORDERBRUEGOEN Region 5, San Francisco, Office of the Director DUBDS:R T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 60/09/09. 3pp
- 8010290404 Forwards IE Circular 80-21, "Regulation of Refueling Crews," No written response required.
 EMBELKEN,R.H Region 5, San Francisco, Office of the Director, 80/09/10 ip
- B010300145 Responds to IE Bulletin B0-20, "Failures of Westinghouse Tupe W-2 Spring Return to Neutral Control Switches" Designated switches not used at facility. Total of 71 manhours used to complete review VAN BRUNT, E.E. Arizona Public Service Co. 80/09/15. 1p
- 8010160086 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required.

 ENVELMENT H Region 5, San Francisco, Office of the Director, 80/09/29, ip.
- 80:03:0089 Responds to IE Bulletin in 79-03A. "Longitudinal Held Defects in ABME SA-312, Type 304 Brainless Steel Pipe " Based on min difference between actual ratio of design & allowable stress (0.86 vs 0.85). examination not necessary VAN BRUNT, E E. Arizona Public Service Co 90/10/01 3pp
- B010280021 Forwards IE Circular B0-22, "Confirmation of Employee Qualifications" No written response required. ENOELKEN.R H Region 5, San Francisco, Office of the Director B0/10/02 ip
- 8. Reportable occurrences, LERs & related correspondence
- 8010020446 Interim deficiency rept to loose bushings on Corner & Lada sway struts. Sizes i-3 Struts are being located & identified by Bechtel Const Deficient struts will atther be repaired or replaced Finel rept will be submitted by 801121 VAN BRUNT, E. Arizona Public Service Co 80/09/24, 3pp
- 8010060253 Interim deficiency rept re excessive shear stresses in concrete slabs supporting safety injection tenks 10,2A & 2B. Beismic loads on safety injection tenk supports will be re-evaluated by C-E. Final rept to be submitted by 801231 VAN BRURT, E. Arizona Public Service Co. 80/09/26. App.
- BOIO160839 Interim deficiency rept re inadequate concrete atrength achieved u/pneumatically placed morter repairs Evaluation of all repairs will be completed BOI201, Final rept will be submitted by 801215
 VAN BRUNT.E.F Arizona Public Service Co. 80/10/07 7pp.
- BO1029037: Interim deficiency rept re groove weld deficiencies on main control panels. Comeip & Bechtel will perform analysis by BO110: Repairs conducted when nonconformance & weld repair procedures established. Final rept to be submitted by B01115 VAN BRUNT, E. Arizona Public Bervice Co. 80/10/15. 3pp.
- 8010290324 Final interim deficiency rept re potential failure of temp detection controllers used on CTI-Nuclear air handling & filtration equipment. McOraw Edison issued recall notice to return controllers for repair or replacement VAN BRUNT, E. E. Arizona Public Service Co. 80/10/23, 3pp.

- DOCKET BIN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISE(HVI).D.O Division of Licensing 80/09/19 28pp
- EISENHUT, D. O Division of Licensing 80/09/19 28pp

 8010210417 Advises that Bachtel responses to outstanding items of
- 8010210417 Advises that Bachtel responses to outstanding items of PUNOS Class IE dc power sys review have been reviewed & found to sufficiently address concerns VAN BRUNTLE E Arizona Public Service Co 80/10/14 2pp.
- 8010280417 Discusses sys reviews for various facility sys Requests NRC schedule sys reviews supporting licensing schedule Also requests meeting in Bethesda-MD to resolve facility & CEBAR-F sys review issues

 VAN BRUNTLE E Arizona Public Service Co. 80/10/21. 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 8010280392 Comments by Water & Power Resources Svc on Suppl i to environ rept for facility Proposal has no identifiable effect on DDI programs TRCMPETER.K M interior Dept of 80/10/23, 1p
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8010100306 Forwards Proof of Svc for Amend 2 to facility FSAR per DO Eisenhut 800618 ltr & 10CFR2 101 VAN BRUNT, E E Arizona Public Service Co 80/10/02 3pp
- O Inspection reports: IE Bulletins & correspondence
- 8010170419 Forwards IE Insp Repts 50-528/80-12,50-529/80-12 & 50-530/80-12 on 800728-0801 No noncompliance noted BPENCFR: 0 B Region 5, San Francisco, Reactor Construction & Engineering Support Brench 80/09/03 2pp
- --8010170428 IE Insp Repts 50-528/80-12.50-529/80-12 & 50-530/80-12 on 800728-0801. No noncompliance noted Hajor areas inspected reactor coolant pressure boundary welding, dome liner place installation, electrical cables & general const. ECKHARDT. H., WAONER. W. J. Region 5, Ban Francisco. Office of the Director DODDGR T. Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/09/03 7pp
- 8010170544 Forwards IE Insp Repts 50-528/80-13,80-529/80-13 & 90-530/80-13 on 800714-25 No noncompliance noted BPENCER,0 8 Region 5, Ben Francisco, Reactor Construction & Engineering Support Branch 80/09/10 2pp
- --B010170662 IE Insp Repts 50-528/80-13,50-529/80-13 & 50-530/80-13 on 800714-25. No noncompliance noted Major areas inspected closure of Unit 1 containment bldg const opening & reinforcing steel omission from containment bldg walls. VURDERRAUEGGEN Region 5, San Francisco, Office of the Director DODDS.R.Y. Region 5, San Francisco, Reactor Construction & Engineering Support Branch, B0/09/09 5pp.
- 8010290404 Forwards IE Circular 80-21. "Regulation of Refueling Crews "
 No written response required
 ENGELKEN.R.H Region 5. Sen Francisco. Office of the Director
 80/09/10. ip
- 8010300145 Responds to IE Bulletin 80-20, "Failures of Hestinghouse Type N-2 Spring Return to Neutral Control Switches." Designated switches not used at facility Total of 71 manhours used to complete review VAN SRUNT, E. E. Arizona Public Service Co. 80/09/15 1p
- 8010160086 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Qualification of Class IE Equipment," No written response required.
 ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/09/29 in
- 8010310089 Responds to IE Bulletin in 79-03A, "Longitudinel Weld Defects in ASME BA-312. Type 304 Stainless Steel Pipe." Based on min difference between actual ratio of design & allowable stress (0.86 vs 0.85). examination not necessary.

 VAN BRUNT, E. E. Arizona Public Service Co. 80/10/01. 3pp
- 9010280021 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required.
 ENGELKEN.R.H Region 5. San Francisco. Office of the Director 80/10/02. 1p.

- 8 Reportable occurrences, LERs & related correspondence
- 8010020446 Interim deficiency rept re loose bushings on Corner & Lada thay struts, Bires 1-3 Struts are being located & identified by Bechtel Const Deficient struts will either be repaired or replaced Final rept will be submitted by 801121 VAN BRUNT.E E Arizona Public Service Co 80/09/24 3pp
- 8010060253 Interim deficiency rept re excessive shear stresses in concrete slabs supporting safety injection tanks 18,2A & 28, Sejamic loads on safety injection tank supports will be rep-evaluated by C-E Finel rept to be submitted by 801231 VAN SRUNT, E E Arizona Public Service Co 80/09/26 App.
- 8010160539 Interim deficiency rept re inadequate concrete strength achteved u/pneumatically placed morter repairs Evaluation of all repairs will be completed 801201 Final rept will be submitted by 801215 VAN BRUNTLE E Arizona Public Service Co 80/10/07 7pp
- 8010290371 Interim deficiency rept re groove weld deficiencies on main control panels Comeip & Bechtel will perform analysis by B01101 Repairs conducted when nonconformance & weld repair procedures astablished Final rept to be submitted by 801115 VAN ERUNT, E E Arizona Public Service Co. B0/10/15, 3pp
- 8010290324 Final interim deficiency rept re potential failure of temp detection controllers used on CTI-Nuclear air handling & filtration equipment McGraw Edison Issued recall notice to raturn controllers for repair or replacement.

 VAN BRUNT,E E Arizona Public Service Co 80/10/23 3pp
- DOCKET STM-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D. G Division of Licensing 80/09/19 28pp.
- 8010210417 Advises that Bechtel responses to outstanding items of PUNOB Class IE dc power sys review have been reviewed & found to sufficiently address concerns VAN BRUNTLE E Arizona Public Bervice Co 80/10/14 2pp
- B010280417 Discusses sys reviews for various facility sys Requests NRC schedule sys reviews supporting licensing schedule. Also requests meeting in Bethesda: 40 to resolve facility & CESBAP-F sys review issues VAN BRUNT.E E Arizona Public Bervice Co. 80/10/21. 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 8010280392 Comments by Water & Power Resources Evc on Suppl 1 to environ rept for facility Proposal has no identifiable effect on DOI programs TROMPETER,K M Interior, Dept of, 80/10/23 1p.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8010100306 Forwards Proof of Svc for Amend 2 to facility FSAR per DO Eisenhut 800618 itr & 10CFR2.101. VAN BRUNT.E E Arizona Public Service Co. 80/10/02, 3pp.
- Q Inspection reports. IE Bulletins & correspondence
- BO10170417 Forwards IE Insp Repts 80-828/80-12,50-529/80-12 & 50-539/80-12 on 800728-0801 No noncompliance noted BPENCER,0 & Region 5, Ham Francisco, Reactor Construction & Engineering Bupport Branch 80/09/03 2pp
- --8010170428 IE Insp Repts 50-528/80-12,50-529/80-12 & 50-530/80-12 on 800725-0801 No noncompliance noted Major areas inspected reactor coolant pressure boundary welding dome liner plate installation, electrical cables & general const. ECMHARDT, J. H., WAONER, W.J. Region 5, San Francisco, Office of the Director DODB, R. T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/03. 7pp.
- 8010170644 Forwards IE Insp Repts 50-228/80-13,50-329/80-13 & 50-330/80-13 on 800714-25. No noncompliance noted. SPENCER, 0.8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 80/07/10 2pp.

- --8010170662 IE Insp Repts 50-528/80-13.50-529/80-13 & 50-530/80-13 on 800714-25 No noncompliance noted. Hajor areas inspected closure of Unit 1 containment bldg const opening & reinforcing steel omission from containment bldg walls VORDERBRUEOGEN Region 5. San Francisco. Office of the Director DODDs.R T. Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 80/09/09 Spp
- 8010290404 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required ENGELKEN.R H Region B. Ban Francisco. Office of the Director 80/09/10 ip
- 8010300145 Responds to IE Bulletin 80-20. "Failures of Hestinghouse Type N-2 Spring Return to Neutral Control Switches" Designated suitches not used at facility. Total of 71 manhours used to complete review VAN BRUNT, EE Arizona Public Service Co 80/09/15 ig
- 8010160086 Forwards Buppl 2 to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No written response required ENGELKENR H Region 5. Sen Francisco. Office of the Director 80/09/29 is.
- 8010310089 Responds to IE Bulletin in 79-03A. "Longitudinal Held Defects in ASKE BA-312. Type 304 Stainless Steel Pipe." Besed on min difference between actual ratio of design & allowable stress (0.86 vs. 0.85), szeminetion not necessary VAN BRUNT. E. Arizona Public Service Co. 60/10/01 3ps.
- 8010280021 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications." No written response required ENGELKEN.R H Region 5, Ban Francisco, Office of the Director. 80/10/02. 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8010020446 Interim deficiency rept re loose bushings on Corner & Lada sway strute, Sizes 1-3 Strute ere being located & identified by Bechtel Const, Deficient strute will either be repaired or replaced Final rept will be submitted by 801121.

 VAN BRUNT, E. & Arizone Public Service Co. 80/09/24. Spp
- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

 A Application/construction stage documents & correspondence
- 8010210584 Notifies that Amend 56 to PSAR is acceptable MEBB.T M. Tennessee, State of 80/10/09 ip.
- DOCKET 50-838 MEMPHI8 STATE UNIV. RESEARCH REACTOR
 J Insurance & indomnity information
- 8010280309 Requests endorsements & copy of Amend 2 to Policy E-59 DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24. ip.
- DOCKET STN-50-546 MARBLE HILL NUCLEAR SYATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8010060192 Notifies that AL Parme & Hamm Engineers. Inc have been spletted re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors STELLO.V. Office of Inspection & Enforcement, Office of the Director 80/08/06. Ip
- B010090113 Notifies that AL Parms & Hamm Engineers, Inc have been selected as consultants re concrete const problems at facilities. Consultants selected after input from & discussions Wintervenors.

 BYELLO, V. Office of Inspection & Enforcement, Office of the Director 80/08/05. 1p
- B010070137 Notifies that AL Parms & Hamm Engineers, Inc have been selected as consultants re concrete const problems at facilities. Consultants selected after input from & discussions w/intervenors BTELLO, V. Office of inspection & Enforcement, Office of the Director. B0/08/04. 1p

- B010070144 Notifies that AL Parme & Hamm Engineers. Inc have been selected as consultants re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors STELLO, V Office of Inspection & Enforcement, Office of the Director 80/08/06 ip
- 8010090156 Notifies that AL Parme & Hamm Engineers, Inc have been selected as consultants re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors of Inspection & Enforcement, Office of the STELLO, V Office of Director 80/08/04 10
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT, D 0 Division of Licensing 80/09/19 28pp
- 8010150276 Comments on "Ltr to All Licensers of Operating Plants & Applicants for QLs & Holders of CPs " Recommends re-sramination of implementation schedules for plants approaching QL or in operation SHIELDS, B W Public Service Co of Indiana. Inc 80/10/06 Spp

G Adjudicatory correspondence

- 8010100124 Order granting extension until 801014 for Commission to review Director's decision under 10CFR2 206
 CHILK,S J Office of the Secretary of the Commission 80/10/04.
- 80(0230508 Advises that on 80(016, Director's decision (DD-80-27) became final agency action for purposes of judicial review CHILK, S. J. Office of the Secretary of the Commission 80/10/22
- Q Inspection reports, IE Bulletins & correspondence
- 8010200688 Forwards IE Insp Repts 50-546/80-20 & 50-547/80-20 on 800701-31 & motice of violation FIGRELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 2pp
- --B010200489 Notice of violation from insp on 800701-31.
 ** Region 3. Chicago, Office of the Director 80/08/03 is
- -8010200691 IE Insp Repts 50-546/80-28 & 50-547/80-28 on 800701-31 Noncompliance noted purge gauges not calibr HARRISON: J. WILLIAMS.C. Region 3: Chicago. Office of the Director BO/08/03 7pp
- 010290128 Forwards IE Insp Repts 50-546/80-30 & 50-547/80-30 on 800729-0801 & 26-29 No noncompliance noted.
 FIDRELLIA Region 3. Chicago, Reactor Construction & Engineering
 Support Branch 80/09/12 2pp
- --8010290133 IE Insp Repts 50-546/BO-30 & 50-547/BO-30 on 800729-0801 & 26-29. No noncompliance noted Major areas inspected PSI concrete evaluation program const verification grogram & machanical caduald splice tensile testing.

 HAYES.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch HAHKINS,F C. WILLIAMS,C.C. Region 3. Chicago. Office of the Director 80/09/12 9pp
- B010090107 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Buitches." Indicating lights on switches will be rewired as interim solution. List identifying switches enc! SHIELDS.S. H Public Service Co. of Indiana, Inc. 80/09/15 2pp
- 8010270102 Forwards IE Insp Repts 50-546/80-26 & 50-547/80-26 on 800722-25 & 0818-21 No noncompliance noted FIGRELLI, O Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/09/15 2pp
- --8010270110 IE Insp Repts 50-546/80-26 & 50-547/80-26 on 800722-25 & 0818-21. No noncompliance noted, Major areas inspected: essential svc piping installation & verification program being conducted at Chicago Bridge & Iron.
 DANIELEDND H Region 3, Chicago, Reactor Construction & Engineering Support Branch. CORDERO, Z. C., ERB. C. M. Region 3, Chicago, Office of the Director. 80/07/12 5pp.
- 8010200676 Forwards IE Insp Repts 50-546/80-31 & 50-547/80-31 on 800801-31. No noncompliance noted. FIORELI.G. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 80/09/19 2pp

- --8010200678 IE Insp Repts 50-546/80-31 & 50-547/80-31 on 800801-31.Na noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg.Unit 1 & 2 containments w/miscellaneous areas to verify activities complied w/stop work order HARRISON.J J , WILLIAMS,C C Region 3, Chicago, Office of the Director 80/09/18 Spp
- 8010160305 Forwards Suppl 2 to IE Bulletin 79-019, "Environ Bualification of Class IE Equipment " No written response raquired
 KEPPLER.J O Region 3, Chicago, Office of the Director 80/09/30
- B010280120 Ferwards IE Circular 80-22, "Confirmation of Employee Qualifications " No written response required KEPPLER.J © Region 3. Chicago, Office of the Director, 80/10/02
- 8010230680 Ack receipt of 800924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-546/80-28 & 90-547/80-28 FIGRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/10/10 ip.
- ---8010230683 Responds to NRC 800708 ltr re violations noted in [E Insp. Repts 50-846/80-28 & 50-947/80-28 Corrective actions, storage & maint instructions have been revised to require calibrated gauges Implementation scheduled for 801031 SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/09/24, 3,3
- B010290032 Forwards IE Info Notice B0-36. "Failure of Steam Generator Support Bolting " No specific action or response requested KEPPLER.J G Ragion 3, Chicago, Office of the Director. B0/10/10
- 8 Reportable occurrences, LERs & related correspondence
- 8010100414 PNO-III-80-ii3 person making allegations re testing of concrete at const site has agreed to be interviewed by NRC on 800617 Director 80/06/16 1p
- 8008060283 PNG-III-80-125 on 800702, util notified NRC of convening of Orand Jury in connection w/alleged concrete honegcomb coverup issues at site Sessions scheduled for 800721-23 NRC involvement uncertain SCHREIBINZ.B R , WILLIAMS.C C , FIORELLI.O. Region 3, Chicago, Office of the Director 80/07/02
- B0100B0553 PNO-III-80-138 on B00724. Indianapolis Star printed statements attributed to Region 3 inspector indicating that DDJ investigation resulted from political pressure & Congressional influence BTRASHAR, J. HAYEB, D.W. Region 3. Chicago, Office of the Director BD/07/24 2pp
- 8010090314 PNO-III-80-163 on 860903, two FRI agents plan site visit regrand jury probe of improper reporting & repair of concrete imperfections Region 3 resident inspector will accompany agents during visit
 HAWKINS:F. HAYES.D. WILLIAMS.C. Region 3, Chicago, Diffice of the Director 80/09/02 ip
- 80:015:007: Ack receipt of 80:07:1 interim deficiency rept re deficiencies in auxiliary steel used to support pipe hangers FIORELLI.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/18 ip
- --8010150097 Interim deficiency rept re defect in auxiliary steek used is support pipe hangers Util presently evaluating deficiencies to determine effect on safe operation of plant. Final rept will be submitted by 801215.

 SHIELDS. 8 W Public Service Co. of Indiana. Inc 80/09/11 by
- 8010290207 Final deficiency rept we accessible mechanical splices (cadwelds) not meeting visual insp requirements.

 Nonconformances thoroughly evaluated using tensile testing & radiography Deficiency not reportable per 100FR50, 85(a) SHIELD8/S W Public Service Co of Indiana, Inc. 80/09/18
- 8010010691 Ark receipt of 800911 final deficiency rept re reinforcing steel NRC will complete review during future insp. FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/09/19 1p.
- 8010060224 Interim deficiency rept re unverified sampling & testing frequencies of cadueld splices Reinspaction & evaluation showed strength requirements met Item not reportable.

 SHIELDS.S.W. Public Service Co. of Indiana. Inc. 80/09/29.

- 8010060288 Interim deficiency rept re code requirements for certified matl test repts ASME confirmed that only certificate of compliance required for well filler matl used on spool pleces Addl surveillance results available by 801215
 SHEELDS,S W Public Service Co of Indiana, Inc. 80/09/29 1p
- 8010170199 Ack receipt of 800918 interim deficiency rept re-mechanical splices not meeting visual insp requirements NRC review will be completed during future insp FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/30 ip
- --8010170204 Interim deficiency rept re mechanical splices not meeting visual insp requirements Nonconformances were evaluated & mechanical splices modified to meet strength requirements SHIELDS.8 W Public Service Co of Indiana, Inc. 80/09/18 ip
- E010300464 Ack receipt of 800929 final deficiency rept re sampling & testing of mechanical cadweld splices
 FIGRELLI, Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/10/08 ip
- E010300457 Ack receipt of 800929 interim deficiency rept re questionable weld filler matl in Category I piping FIDRELLI.O Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/10/08 ip
- 8010300484 Part 21 final rept re intermittent contact operation occurring in Type N-2 switch when set in neutral position.
 Util will implement Westinghouse interim rewiring solution
 SHIELDS.B W Public Service Co of Indiana
- B010240402 Final deficiency rept re nonconformances in Hestinghouse quality verification packages Acceptable dispositions obtained in all previously identified nonconformances Item is not reportable under 10CFR50 55e
 BHIELDB, S. W. Public Service Co. of Indiana, Inc. 80/10/17 2pp.
- 8010240409 Final deficiency rept re installation of nonsafety-related anchors in safety-related bldg w/o approved procedures Engineer evaluation determined that installation does not impair bldg safety ltem is not reportable under 10CFR50 55e BHIELDS, B W Public Service Co of Indiana. Inc 80/10/17 2pp
- 8010240457 Final deficiency rept re potential defect in applied Carbo-Zinc 11 primer on containment bldg polar cranes Polar cranes will be blasted to remove present prime coat & then reprimed after resumption of safety-related work BHIELDS.8 W Public Service Co of Indiana, Inc 80/10/17 2pp
- BO10240414 Interim deficiency rept re failure of steam generator embedment radiographs to meet density requirements Add1 embedments & pipe restraints determined unacceptable Components will be returned to supplier for re-
- E010290365 Interim deficiency rept re substitution of mat1 allowed by stainless steel liner work spec Thorough investigation through AE & contractor underway Final rept available by B01121
 BHIELDS, S W Public Service Co of Indiana, Inc. 80/10/23 2pp
- 8010290367 Interim deficiency rapt re cable tray hanger welds. Welds evaluated & reinspected Some welds require rework Evaluation of addl welds planned Final rept to be submitted by 801205 EHIELDS, 8 & Public Bervice Co of Indiana, Inc 80/10/24, 2pp

U Congressional/Executive Correspondence

- BD10020403 Responds to 800729 ltr re available NRC expertise to assess adequacy of safety-related const at facility NRC has adequate in-house expertise to competently carry out effective insp program at facility AHEARKE, J F Commissioners 80/09/02, 2pp.
- --8010020413 Requests demanstration of availability of NRC in-house expertise to assess facility const safety.NRC should allow independent examination of const activities to ensure against const error.
 FORD.W Senete 80/07/29 ip

- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8010040192 Notifies that AL Parme & Hamm Engineers. Inc have been selected re concrete const problems at facilities. Consultants salected after input from & discussions w/ intervenors

 STELLO.V Office of Inspection & Enforcement. Office of the Director 80/08/06 to
- BD10090113 Notifies that AL Parme & Hamm Engineers, Inc have been salected as consultants re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors
 BTELLO.V Office of Inspection & Enforcement, Office of the Director BD/08/06 ip
- B010090137 Notifies that AL Parms & Hamm Engineers. Inc have been selected as consultants re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors
 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/06 ip
- 8010090144 Notifies that AL Parms & Hamm Engineers. Inc have been selected as consultants re-concrete const problems at facilities Consultants selected after input from & discussions w/intervenors
 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/06 ip
- 8010090196 Notifies that AL Parme & Hamm Engineers. Inc have been selected as consultants re concrete const problems at facilities Consultants selected after input from & discussions w/intervenors
 SYELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/06 ip
- 8010220099 Forwards errata sheets amending 800909 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISE/MHUT, D O Division of Licensing 80/09/19 28pp
- 8010150276 Comments on "Ltr to All Licensees of Operating Plants & Applicants for OLs & Holders of CPs " Recommends re-examination of implementation schedules for plants approaching OL or in operation SHIELDS:8 W Public Service Co of Indiana, Inc. 90/10/06 3pg

9 Adjudicatory correspondence

- 80:00:00:24 Order greating extension until 80:00:4 for Commission to review Director's decision under iOCFR2 206 CHILK, B.J. Office of the Secretary of the Commission 80/10/06
- 8010230508 Advises that on 801016. Director's decision (DD-80-27) became final agency action for purposes of judicial review CHILK/S J Office of the Secretary of the Commission 80/10/22
- 9 Inspection reports, IE Bulletins & correspondence
- 8010200698 Forwards IE insp Repts 50-546/80-28 & 50-547/80-28 on 800701-31 & notice of visitation FIORELLI, O Ragion 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 2pp
- --8010200689 Notice of violation from insp on 800701-31 * Region 3, Chicago, Office of the Director 80/08/03 ip
- --8010200691 IE Insp Repts 50-546/80-28 & 50-547/80-28 on 800701-31 Nuncompliance noted purgs gauges not calibr. HARRISON.J J. WILLIAMS.C C Region 3, Chicago, Office of the Director 80/08/03 7pp
- 8010290128 Forwards IE Insp Repts 50-546/80-30 & 50-547/80-30 on 800729-0801 & 26-29 No noncompliance noted FIORELLIO Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/09/12 Zpp
- --8010270133 IE Insp Repts 50-546/80-30 & 50-547/80-30 on 800727-0801 & 26-27 No noncompliance noted Major areas inspected PBI concrate evaluation program.const verification program & machanical cadweld splice tensile testing HAYES,D W Regian 3, Chicago, Reactor Construction & Engineering Support Branch HAMINNS,F C WILLIAMS,C C Region 3, Chicago, Office of the Director BO/09/12 7pp

- 8010070107 Responds to IE Bulletin BO-20, "Failures of Hastinghouse Type N-2 Spring Return to Neutral Control Switches" Indicating lights on switches will be rewired as interim solution List identifying switches encl
 SHIELDS.S N Public Service Co of Indiana, Inc 80/09/15 2pp
- 8010290102 Forwards IE Insp Repts 50-546/80~26 & 50-547/80-26 on B00722-25 & GB18-21 No noncompliance noted FIGRELLING Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/15 2ap
- --8010270110 IE Insp Repts 50-546/80-26 & 50-547/80-26 on 800722-25 & 0818-21 No noncompliance noted Major areas inspected essential svc piping installation & verification program being conducted at Chicago Bridge & Iron DANIELSON, D H. Region 3, Chicago, Reactor Construction & Engineering Support Branch CORDERO, Z C , ERB, C M Region 3, Chicago, Office of the Director BO/09/12 5pp
- 8010200676 Forwards IE Insp Repts 50-546/80-31 & 50-547/80-31 on B00801-31 No noncompliance nated FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/09/19 2pp
- --8010200578 IE Insp Repts 50-546/80-31 & 50-547/80-31 on 800801-31 No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg. Unit I & 2 containments w/miscellaneous areas to verify activities complied w/stop work order HARRISON, J J, MILLIAMS.C C Region J. Chicago, Office of the Director 80/09/18 5pp
- 8010160305 Forwards Suppl 2 to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" No written response required. KEPPLER, J.O. Region 3. Chicago. Office of the Director 80/09/30 ib
- 8010280120 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director. 80/10/02 to
- 8010230680 Act receipt of 800924 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-546/80-28 & 50-547/80-28 FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/10/10 tp
- --8010230683 Responds to NRC 800908 ltr re violations noted in IE Insp Repts 80-546/80-28 & 50-547/80-28 Corrective actions storage & maint instructions have been revised to require calibrated gauges. Implementation scheduled for 801031 SHIELDS.8 W Public Service Co of Indiana. Inc 80/09/24 3pp
- 8010290032 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested KEPFLER.J 0 Region 3, Chicago, Office of the Director 80/10/10
- 8 Reportable occurrences, LERs & related correspondence
- 8010100414 PNG-III-80-113 person making allegations re testing of concrete at const site has agreed to be interviewed by NRC on 800617 PHILLIP:0 A . NORELIUS:C E Region 3. Chicago. Office of the Director 80/06/16 to
- 8008060283 PND-III-80-125 on B00702, util notified NRC of convening of Grand Juny in connection w/allaged concrete homeycomb coverup issues at site Sessions scheduled for 800721-23. NRC involvement uncertain SCHMEISHIZ-B R. WILLIAMS.C C. FIORELLI.0 Region 3, Chicago. Diffice of the Director 80/07/02 ip
- 8010080553 PNO-III-80-i38 on 800724. Indianapolis Btar printed statements attributed to Region 3 inspector indicating that DOJ investigation resulted from political pressure & Congressional influence STRASMAR J. HAYES, D. W. Region 3. Chicago, Office of the Director 80/07/24 2pp.
- 8010090314 PND-III-80-163 on 800903, two FBI agents plan site visit re grand jury probe of improper reporting & repair of concrete imperfections Region 3 resident inspector will accompany agents during visit HAHKINS.F., HAYES.D., HILLIAMS.C. Region 3, Chicago. Office of the Director, 80/09/02 lp

- B010150091 Ack receipt of 800911 interim deficiency rept re deficiencies in auxiliary steel used to support pipe hangers FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/09/18 ip
- --8010150099 Interim deficiency rept re defect in auxiliary steel used to support pipe hangers Util presently evaluating deficiencies to determine effect on safe operation of plant Final rept will be submitted by 801215 SHIELDB, S.W. Public Service Co. of Indiana. Inc. 80/09/11 lp.
- 8010270207 Final deficiency meptine accessible mechanical splices (cadualds) not meeting visual inspirequirements. Nonconformances thoroughly evaluated using tensile testing & radiography Deficiency not reportable per IOCFR50 55(s). BRIELDS:S & Public Service Co. of Indiana, Inc. 80/09/18 1p.
- 8010010691 Ack receipt of 800911 final deficiency rept re reinforcing steel NRC will complete review during future insp FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/09/19 ip
- B010060224 Interim deficiency rept to unverified sampling & testing frequencies of caduald splices Reinspection & evaluation showed strength requirements met Item not reportable SHIELDS.B W Public Service Co of Indiana, Inc 80/09/29 2pp.
- 801006028B Interim deficiency rept re code requirements for certified math test repts ASME confirmed that only certificate of compliance required for weld filler math used on spool piecos Addi surveillance results available by 801215
 SHIELDS.8 W Public Service Co of Indiana, Inc. 80/09/29 1p
- 8010170199 Ack receipt of 800918 interim deficiency rept re mechanical splices not meeting visual insp requirements NRC review will be completed during future insp ffORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/30 ip
- --8010170206 Interim deficiency rept to mechanical splices not meeting visual insp requirements Nonconformances were evaluated & mechanical splices modified to meet strength requirements SHIELDS.S W Public Service Co of Indiana. Inc 80/09/19 Ip.
- 80:0300464 Ack receipt of 800929 final deficiency ropt re sampling & testing of mechanical cadweld splices FIGRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch BO/10/08 ip
- 8010300447 Ack receipt of 800929 interim deficiency rept re questionable weld filler matt in Category I piping FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch BO/10/08 ip
- 8010300484 Part 21 final rept re internittent contact operation occurring in Type M-2 switch when set in neutral position Util will implement Westinghouse interim rewiring solution SHIELDS.8.W Public Service Co of Indiana, Inc. 80/10/14 Spp
- 8010240402 Final deficiency rept re nonconformances in Hestinghouse quality verification packages Acceptable dispositions obtained in all previously identified nonconformances Item is not reportable under 100FRF0 55e SMIELDS.8 W Public Service Co of Indiana, Inc. 80/10/17 200
- 8010240407 Final deficiency rept re installation of nonsafety-related anchors in safety-related bidg ω/ο approved procedures.
 Engineer svaluation determined that installation does not impair bldg safety litem is not reportable under 10CFR50 55e SHIELDS, S W Public Service Co of Indiana, Inc 80/10/17 25p
- 8010240457 Final deficiency rept re potential defect in applied Carbo-Zinc 11 primer on containment bidg polar cranes Polar cranes will be blasted to remove present prime coat & then reprimed after resumption of safety-related work SHIELDS.S W Public Service Co of Indiana, Inc 80/10/17 2pp
- B010240414 Interim deficiency rept re failure of steam generator embedment radiographs to meet density requirements Addi embedments & pipe restraints determined unacceptable Components will be returned to supplier for re-examination SHIELDS, 8 W Public Service Co of Indiana, Inc. 80/10/20 23p
- 8010290365 Interim deficiency rept re substitution of math allowed by stainless steel liner work spec Thorough investigation through AE & contractor underway Final rept available by 801121 SHIELDS: 8.W Public Service Co of Indiana, Inc. 80/10/23 2pp

- 8010290367 Interim deficiency rept re cable tray hanger wolds Helds evaluated & reinspected Same welds require rework Evaluation of addl welds planned Final rept to be submitted by 801205 EHIELDS, B.W. Public Service Co. of Indiana, Inc. 80/10/24 2pp
- U Congressional/Executive Correspondence
- BO10020403 Responds to 800729 ltr re available NRC expertise to assess adequacy of safety-related const at facility NRC has adequate in-house expertise to compatently carry out effective insp program at facility AHEARNE, J. F. Commissioners BO/09/02 2pp
- --8010020413 Requests demonstration of availability of NRC in-house expertise to assess facility const safety NRC showld allow independent examination of const activities to ensure against const error FORD, N Senate 80/07/29 Ip

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

- O Adjudicatory correspondence
- 8010230688 Notice of withdrawal of 750725 CP application Certificate of Svc encl BERRY, G T Power Authority of the State of New York 80/10/20
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATKS issue Mods will be evaluated & implemented to reduce ris? Program can be implemented by 1985 at Browns Ferry, Bequoyah & Watts Bar & by feel loading at Bellefonto. Hartsville & Phipps Bend HILLS.L ii Tennessee Valley Authority 80/09/17 5pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISENHUT. D O Division of Licensing 80/09/19 28pp
- 8009300400 Forwards technical questions re implementation of interim policy on 100FR50 & 51 MILLB.L M Tennessee Valley Authority 80/09/23 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8010200697 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matls" G'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/29
- 8010090602 Forwards response to IE Bulletin 80-20. "Failures of Mestinghouse Type W-2 Spring Return to Neutral Control Switches "None of subj switches found in safety-related applications to date Investigation continuing MILLS.L M Tennasses Vailey Authority 80/09/12 10pp
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-24. 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-439/80-13, 50-439/80-13, 50-519/80-11, 50-519/80-11 & othere MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/24 2pp
- --B010170123 Responds to NRC 800806 ltr re violations noted in 1E Insp Repts 30-327/80-24,50-328/80-15 & others Corrective actions: OA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies. MILLG.L M Tennessee Valley Authority 80/09/02. 14pp
- 80:01:60:184 Forwards Suppl 2 to 1E Bulletin 79-0:18, "Environ Qualification of Class IE Equipment " No written response required.

 D'REILLY, J.P. Region P. Atlanta, Office of the Director 80/09/30 ip
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/10/02, 1p.

- 8010270066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/10/10 to
- 8 Reportable occurrences, LERs & related correspondence
- 8010160353 PNO-II-80-106 on 800612, util reported fire an barge transporting reactor vessel & shroud head Plywood container enciosing shroub head caught fire Util is investigating cause of fire Damage.if eny.is unknoun (RIGHT, R W. & CANTRELL,F S Region 2, Atlanta, Office of the Director 80/06/12 ip
- 8010010861 Part 21 third interim rept re defects in Rosemount trip/calibr units & pressure transmitters supplied by OE Rosemount & GE will replace defective switches in Model 510DU trip units Transmitters will be corrected MILLS.Ł K Tennessee Valley Authority 80/09/17 3pp
- B0100B0B19 Final deficiency ropt re HPCS diesel generator switchgear wiring discrepancies Ail wiring discrepancies have been identified Hardware corrections will be completed by B10130 Software changes will be completed by 810430 MILLS.L K Tennossee Valley Authority 80/09/30 3pp
- DOCKET STN-50-554 PHIPPS BEND RUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATNS issue Mode will be evaluated & implemented to reduce risk Program can be implemented by 1985 at Drowns Ferry, Sequoyah & Matts Bar & by fuel loading at Bellefonte Harts/
- 8010220099 Forwards errate sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also encl EISE(NUT, D O Division of Licensing 80/09/19, 28pp
- B009300400 Forwards technical questions re implementation of interim policy on 10CFR90 & 51 MILLS.L H Tennessee Valley Authority B0/09/23 3pp
- O Inspection reports. IE Bulletins & correspondence
- B01020D637 Forwards iE Info Notice 80-32. "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matis"

 D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/0B/29 ip
- 8010070102 Forwards response to IE Bulletin 80-20, "Failures of Wastinghouse Type W-2 Spring Return to Neutral Control Switches," None of subj switches found in safety-related applications to date Investigation continuing MILLS, L M Tennessee Valley Authority 80/09/12 10pp
- 8010170107 Ack receipt of 800902 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-24, 50-329/80-13, 50-390/80-20, 50-37/20-14, 50-438/80-13, 50-318/80-11, 50-519/80-11 & others HURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/26 2pp
- --8010170123 Responds to NRC 800806 itm re violations noted in IE Inso Repts 50-327/80-24.50-328/80-15 & others. Corrective actions OA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILL8.L M Tennessee Valley Authority 80/09/02 14pp
- G010160184 Forwards Suppl 2 to IE Bulletin 79-018, "Environ Qualirication of Class IE Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/09/30, is
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Ouglifications," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/02 is
- 8010290066 Forwards IE Info Notice 80-36. "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/10/10

S Reportable occurrences, LERs & related correspondence

- 80:0010861 Part 21 third interim rept to defects in Rosemount trip/calibr units & pressure transmitters supplied by GE Rosemount & GE will replace derective suitches in Hodel 5100U trip units Transmitters will be corrected MILLS:4. M Tennessee Valley Authority 80/09/17 3pp
- B0100B0317 Final deficiency rept re HACS diesel generator switchgear wiring discrepancies have been identified Hardware corrections will be completed by B10130 Software changes will be completed by B10430 MILLB.L M Tennessee Valley Authority 80/09/30 3pp

DOCKET STN-50-556 BLACK FOY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Corrected table of implementation schedule also enci £ISECHUT. D O Division of Licensing 80/09/19 28pp

G Adjudicatory correspondence

- BO10140029 Informs Commission of Justice Dept position on whether Reed Rept should be considered agency record for purposes of access under FOIA Commission should deny FOIA appeals based upon Exemption 4
 BICKNIT-L Office of the General Counsel BECY-80-079F B0/09/09
- --8010140042 Re-emphasizes ASLBP concerns re handling of FDIA requests for GE Reed Rept DOJ cited Ezemption 4 of FDIA as basis for confident; ality Draft responses to FDIA requests & draft menorandum order encil YORE, J R Atomic Safety and Licensing Board Panel 79/03/20 155a.
- 8010150004 Order directing ASLB to transmit Reed rept to Ofc of Secretary & vacating ASLB protective order Matter remanded to ASLB when rept made public HOYLE, J.C. Office of the Secretary of the Commission 80/10/09 pp

Oi60377 Responds to appeal to denial of FOIA request for OE nuclear eactor study & related sub-task force repts known as Reed ept Orants appeal. Rept will be available in PDR within 20 ays Forwards order to availability of Reed Rept HILK. BJ Office of the Secretary of the Commission 80/10/09.

1016-0148 Responds to appeal re denial of FOIA request for GE nuclear reactor study & related sub-task force repts known as Reed tept Orants appeal Rept will be available in FDR within 20 days Forwards order re availability of Reed Rept CHILK.S. J. Office of the Secretary of the Commission 80/10/09 in.

80i0160i66 Memorandum & order on certified question return of 0£ nuclear reactor study Since majority of Commission did not vote to withhold rept must be released MOYLE, J. C. Office of the Secretary of the Commission 80/10/09 500

10150365 Demands on behalf of OE, that NRC return OE Reed Rept immediately due to NRC denial of request that rept be withheld from disclosure under 10CFR2 770 Rept must not be blaced in PDR EDDAR of Morgan, Lewis & Bockius 80/10/10 4pp

3200609 Order directing Reed Rept & transcripts of in camera essions re reptibe made publically available.
(DLFE:8 J. Atomic Safety and Licensing Board Panel 80/10/15 2pp

General correspondence

0270245 Forwards NRC 800623 ltr to K Malone,re facility emergency lanks in response to 800804 request GOHERCERA. Liesnsing Branch 2. 80/08/26 ip.

DUCKET STN-50-557 BLACK FOX STATION, UNIT 2

- A Application/construction stage documents & correspondence
- B010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TML action plan requirements Corrected table of implementation schedule also encl EISENHUT.D C Division of Licensing 80/09/19 28pp

G Adjudicatory correspondence

- 8010140029 Informs Commission of Justice Dept position on whether Reed Rept should be considered agency record for purposes of access under FOIA Commission should deny FOIA appeals based upon Exemption 4 BICKNIT, L. Office of the General Counsel SECY-80-079F 80/09/09
- --B010140042 Re-suphasizes ASLBP concerns re handling of FOIA requesta for GE Reed Rept DDJ cited Exemption 4 of FOIA as basis for confidentiality Draft responses to FOIA requests & draft memorandum order enci YORE, J R Atomic Safety and Licensing Board Panel 79/03/20, 1500
- 8010150004 Order directing ASLB to transmit Reed rept to Ofc of Secretary 2 vecating ASLB protective order Matter remanded to ASLB when rept made public HOYLE. J C Office of the Secretary of the Commission BO/10/09
- 80i0iá0i48 Responds to appeal re denial of FOIA request for GE nuclear reactor study & related sub-task force rapts known as Reed Rept Orants appeal Rept will be available in PDR within 20 days Forwards order re availability of Reed Rept CHILK.S J Office of the Secretary of the Commission. B0/10/09
- --8010160166 Memorandum & order on certified question return of GE nuclear reactor study Bince majority of Commission did not vote to withhold rept must be released HDYLE. J C Office of the Secretary of the Commission 80/10/09 Spo
- 80:0150365 Demands on behalf of GE, that NRC return GE Reed Rept immediately due to NRC denial of request that rept be withheld from disclosure under 10CFR2 790 Rept must not be placed in PDR EDGAR.O I Morgan, Lewis & Buckius 80/10/10 4pp
- 8010200609 Order directing Read Rept & transcripts of in camera sessions re rept.be made publically available WOLFE.6 J Atomic Safety and Licensing Board Panel 80/10/15 2pp

H Genaral correspondence

8010270245 Forwards NRC 800623 ltr to K Majone,re facility emergency plans,in response to 800804 request BCHWENGER,A Licensing Branch 2 80/08/26 ip

DOCKET 50-564 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

- A Application/construction stage documents & correspondence
- 8010960115 Forwards FR notice re proposed amend to regulations dealing w/determination of no significant hazards consideration, resulting from petition for rulemaking 50-17 ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/02 208

O Adjudicatory correspondence

- 8010010830 Comments on proposed rule RM 50-5.re NRC termination of efforts on GESMO fuels NRC should resume GESMO proceeding. Certificate of Svc & svc list encl
 DECHER.U Affiliation Unknown 80/09/03 7pp
- 8010230281 Comments by TN Technological Univ on rulemaking 50-5 GESHO proceedings should be restarted immediately DEMAS, N. & Affiliation Unknown 80/09/11 1p
- 8010230349 Comments on rulemaking 50-5 supports reopening of GESMO proceedings LORFING D Affiliation Unknown 80/09/11, 1p.

- 8010220540 Comments on rulemaking 50-5 NRC should not reopen GEBMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to US nonproliferation policy MCLAUGHLIN, W.T. Affiliation Unknown 80/09/12 ip
- B010230265 Comments on rulemaking 50-5 GESMO proceedings should be resumed HACHIEV,C A Affiliation Unknown B0/09/12 ip
- 8010230341 Comments on rulemaking 50-5 OFSMD proceedings should be reapened LCPE7.C R Affiliation Unknown 80/09/12 ip
- BOLOO20597 Recommends GESMO proceedings be completed Technically competent people available to complete GESMO project Further dalay in proceedings will increase energy costs GESMO will provide basis for future decisons re
- 8010230328 Comments on rulemaking 50~5 GESMO hearings should not be reopened due to problems w/reprocessing Health hazards associated w/transport 3 reprocessing shown to be more serious than previous expectations CLEMENTS. T. Affiliation Unknown 80/09/13 ip
- 8010220518 Comments on rulemaking 50~5 GESMO hearings should resume irradiately EARRY,D Affiliation Unknown 80/09/14 ip
- B010230317 Comments on rulemaking 50-5 GESMO proceedings should not be reopened TUCKER, C A Affiliation Unknown 80/09/14 lp
- B010230323 Comments on relemaking 90-5 re resuming GESMD proceedings CHUBB.N Affiliation Unknown 80/09/14 3pp
- 8009220237 Comments on rulemaking 50-5 GEEMO proceedings should be resumed & completed Reprocessing & recycle of LWR fuel should be considered
 TEOU.FANIDIS.N Affiliation Unknown 80/09/15 ip
- 80:022023: Comments on rulemaking 50~5 QEBMO proceedings should be resumed Delays will not sorve natl security & will increase cost of energy COURTMEY, J.C. Affiliation Unknown 80/09/15 1p
- B010239247 Commonts on rulemaking 50-5 Commission should reopen GESMG proceedings
 BARRY, J E Affiliation Unknown G0/07/15 ip
- 8010230271 Comments on rulemaking 50-5 GESMO hearings should be reopened
 JONES: N Affiliation Unknown 80/07/15 ip
- JO≒ES,N Affiliation Unknown 80/09/15 1p
- GO10320529 Comments on rulemaking 50-5 supports resumption of GESMO proceedings CRELESCHEMILP Affiliation Unknown GO/09/16 Lp
- 8010220653 Comments on rulemaking 50-5 GEBMO proceedings should be reopened Draft article encl which should have some input in farming policy on recycling Pu DEYA,R Citizens United for Responsible Energy 80/09/17 9pp
- B010230304 Comments on rulemaking 50-5 GEBMO proceedings should be resumed VB should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent fuel. PANZANI,F A Affiliation Unknown B0/09/17 ip.
- 8010020019 Comments on reopening of GEBMO proceedings re Rulemaking 90-5 reopening & successful completion of hearing is logical precedent to commercial reprocessing of spent nuclear fuel GIORS D.C. Affiliation Unknown 80/07/23 2pp
- B010020590 Recommends resumption of QEBMO proceedings Persian Oulf area warfare necessitates technical development of spent reactor fuels to lessen dependence on imported oil MARWICK, EF Affiliation Unknown B0/09/23 ip
- B01002G012 Comments by two citizens in support of reopening of OEBHO proceedings re Rulemaking 50~5 further consideration needed for energy development BREITHMYER,F Affiliation Unknown 80/09/24 2pp
- B010020192 Forwards constituent comments on GESMO proceedings. Requests status of NRC intentions re-proceedings
 MCWREW H House of Rep , Ways and Means. B0/09/24 3pp

- 8010020005 Comments on reopening of GESMO procedings re Rulemaking 30-5 continuation of review process needed to determine whether reprocessing & recycling is viable option DRAPER.E L. Gulf States Utilities Co 80/09/25 2pp
- 8010020081 Comments on reopening of GESMO proceedings re Rulemaking 50-5 hearing must be reopened promptly due to need for establishing legal & logical basis for evaluation of spent fuel reprocessing BEHNKE.W B Commonwealth Edison Co 80/09/25 2pp
- 8010020007 Comments on reopening of GESHD proceedings to Rulemaking 50-5 no further action needed due to completion of evidence TROMAS.R Environmentalists, Inc. 80/09/26 ip
- 8010030484 Recommends responing of OESMO proceedings CHAMPAONE, A J Affiliation Unknown 80/09/26 1
- 8010010687 Order denying Allied General Nuclear Svcs 800926 request for 60-day extension to respond to Commission 800807 order Untimely comments will be considered only to extent possible CHILK.8 J Diffice of the Secretary of the Commission 80/09/29 in
- 8010020001 Forwards comments on reopening of GEBMO proceedings re Rulamating 50-5 reinstitution of hearing reflects US interest in energy need % will establish framework for timely decisions on reprocessing & recycling WALSKE,C Atomic Industrial Forum BO/09/29 3pp.
- 8010020651 Comments on rulemaking 50-5 on behalf of CESMO Util Group GESMO proceeding should be reactivated IRWIN:DP Hunton & Williams 80/09/29 4pp
- 8010020663 Comments on rulemaking 50-5:0ESMD proceeding should be rescheduled BURT.D II Capital Legal Foundation 80/09/29 2pp
- 8010020670 Forwards comments on behalf of NRDC on rulemaking 50-5 GESMO proceedings should not be respensed
 WE188.E R Natural Resources Defense Council 80/09/29 5pp
- 8010030479 Views of Westinghouse on NRC 800807 order re resumption of 088MD & other recycle-related licensing proceedings Resumption recommended Certificate of Svc encl COMAN. 8 Z , KENRICK, J R , CAMPSELL, V W Hestinghouse Electric Corp. 80/09/29 13pp
- 8010020675 Recommends that NRC reopen OESMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced OLSDN R E Affiliation Unknown 80/09/30 1p.
- 8010030471 Responds to Commission 800807 order requesting comments on reopening of GESMO & other recycle-related licensing proceedings Proceedings should be reactivated & consistent position on use of energy initiated.

 KEARNEY, J J Edison Electric Institute 80/09/30, 3pp.
- 8010160695 Supports resumption of GESMO proceeding as prelude to closure of nuclear fuel cycle MOGDY.J H Yankee Atomic Electric Co 90/10/08 2pp
- 8010270506 Responds to 800924 ltr transmitting J Courtney request for NRC resumption of OESMO proceedings J Courtney comments will be incorporated into public record to be considered by NRC KAMMERER, C Office of Congressional Affairs 80/10/08 ip
- 8010150364 Submits comments on resumption of GEBMO rulemaking on behalf of AZ Public Syc Co.CP&L.Com Ed & UI Electric Power Co Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues OALLO.J Isham. Lincoln & Seale BO/10/10 3pp
- 8010700375 Advises of address change from Columbia, SC to Washington, DC & requests records be changed
 HELSER, T M Belser, Belser, & Baker SD/10/13. ip
- 8010220494 Forwards JC Courtney 800916 ltr requesting that GESMO hearings be resumed LONG.R Benate. 80/10/13 2pp

- P Operating license stage documents & correspondence
- 80:0070264 Comments on rulemaking 50-5 re reopening of GEBMO & recycle related proceedings Reopening record will resolve economic-environ & resource questions re fuel reprocessing DISE.D P Niegare Mohawk Power Corp 80/09/26 ip
- DOCKET STN-50-566 YFLLOW CREEK HUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8010020480 Forwards util program for resolving ATMS issue. Mods will be evaluated & implemented to reduce risi, Program can be implemented by 1783 at Browns Ferry, Bequoyab & Hatts Bar & by fuel loading at Beliefonte, Hartsville & Phipps Bend, MILLS, L K Tennessee Valley Authority 80/09/17, 5pp
- 8010220099 Forwards errata sheets amending 800705 ltr which provided preliminary clarification of TMI action plan requirements. Corrected table of implementation schedule also encl EISELHAUT.D 9 Division of Licensing 80/09/19. 28pp
- 8009300400 Forwards technical questions re implementation of interim policy on iOCFR30 & 51
 MILLS:L M Tennessee Valley Authority 80/09/23. 3pp
- 8010310338 Requests expedited review of Newport News Industrial Corp draft topical rept re vol reduction sys Util plans to utilize sys at Units 1 & 2 MILLS,L.M Tennessee Valley Authority 80/10/24. 1p.
- Q Inspection reports. IE Bulletins & correspondence
- 8010200637 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Hatls "
 D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/29 is.
- 8010230254 Forwards IE Insp Repts 50-564/80-13 & 50-567/80-13 on 800803-08 No noncompliance noted. MURPHY.C.E Region 2: Atlants, Reactor Construction & Engineering Support Branch 80/09/04 2pp
- --B010230262 IE Insp Regts 50-566/80-13 & 50-567/80-13 on 800805-08. No noncompliance noted Major areas inspected.steel structures & supports, welding activities within containment & containment radiographic film COLEY, J L Region 2, Atlanta, Defice of the Director HERDT, A.R Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/07/04. App
- 8010090391 Responds to IE Builetin 80-20, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches " Lists safety-related sys Using Westinghouse-type switches. Additing to be reported by 801215 MILLS.L. M Tennessee Valley Authority 80/09/16. 3pp.
 - 10170107 Ack receipt of 800902 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11 & others.

 MURPHY, G. E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/24 2pp
- -8010170123 Responds to NRC 800806 ltr re violations noted in IE Insp Repts 50-327/80-24,50-328/80-15 & others. Corrective actions: QA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies. MILLE, L M Tennessee Valley Authority. 80/09/02 14pp.
-)10160:84 Forwards Buppl 2 to IE Bulletin 79-019, "Environ dualification of Class IE Equipment," No written response required.

 6'REILLY, J P Region 2: Atlanta: Office of the Director 80/09/30.
- 010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" No written response required.

 O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/10/02.

 ip.
- 8010290319 Submits second revised response to infraction nated in IE Insp Repts 50-564/80-03 & 50-567/80-03. Corrective actions: radiographs made before 800207 re-examined for deficiencies. Film processing & shim placement guidalines established. MILLS, L. M. Tennessee Valley Authority. 80/10/03. 3pp.

- 8010290066 Forwards IE Info Notice 80-36, "Failure of Steam Generator Support Bolting " No specific action or response requested O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 80/10/10
- 8010280611 Forwards response to NRC 800926 Ir re violation noted in IE Insp Repts 50-566/80-14 & 50-567/80-14 Corrective actions review of concrets test dispositioned in GCIR 51057 showed design strength should be realized at later than design age, MILLS, L M Tennessee Valley Authority 80/10/21 2pp.
- 8 Reportable occurrences, LERs & related correspondence
- 8010070321 PNO-II-80-ii4 on 800623, stop work order was issued for earthfill placement around emergency raw cooling water spray pond Order was issued because of Region 2 concerns reperformance of GC program, Immediate action 1tr to be issued. WRIDHT,R, GANTRELL,F Region 2, Atlanta, Office of the Director 80/06/24 1p
- 8010160695 PNU-II-80-143 on 800827. Region 2 issued confirmation of action ltr to util which confirmed those actions to be completed prior to placing addl Class I concrete in control bldg
 THOMAS.M., CANTRELL, F.S. Region 2. Atlanta, Office of the Director 80/08/27
- 8010210397 Final deficiency rept re improper documentation & utilization of computer program INERTIA Study initiated of methods used to calculate shoar-related properties used in seismic analysis Check made of all other plants MILLS.L M Tennesses Valley Authority. 80/10/14 Spp.
- 8010280595 Fourth interim rept re Const QA.Audit Significant Deficiency: YC-C-80-03 Evaluation of Item 2 complete; U results are being documented Next rept will be submitted by 801201.

 MILLSIL M Tennessee Valley Authority 80/10/21 ip.
- BO10280445 First interim deficiency rept re QA Audit MBO-7.Deficiencies 2.3 & 5 Deficiencies under evaluation Next rept will be submitted by B01125
 MILLS.L H Tennessee Valley Authority 80/10/23, 2pp
- DOCKET STH-50-967 YELLOW CREEK NUCLEAR PLANT, UNIT 2

 A Application/construction shage documents & correspondence
- 8010020480 Forwards util program for resolving ATWS issue Mode will be evaluated & implemented to reduce risk. Program can be implemented by 1785 at Browns Ferry, Sequoyah & Matts Ber & by fuel loading at Bellefonte. Hartsville & Phipps Bend MILLS.L.M Tennessee Valley Authority 80/07/17, 5pp
- 8010220099 Forwards errata sheets amending 800905 ltr which provided preliminary clarification of TMI action plan requirements Garrected table of implementation schedule also encl. EISENMUT, D Q. Division of Licensing 80/09/19. 28pp
- 8009300400 Forwards technical questions re implementation of interimpolicy on 100FR90 & 51.
 MILLS,L II Tennessee Valley Authority 80/09/23, 3pp
- 8010310338 Requests expedited review of Newport News Industrial Corp draft topical rept re vol reduction sys Util plans to utilize sys at Units 1 & 2 MILLS, L. R. Tennessee Velley Authority 80/10/24, ip.
- G Inspection reports, IE Bulletins & correspondence
- 8010200697 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements of Exclusive Use Shipments of Radioactive Matla," O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/29, ip.
- 8010230254 Forwards IE Insp Repts 50-56/80-13 & 50-567/80-13 on 800805-08 No noncompliance noted HURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/09/04 2pp.
- --8010230262 [E Inep Repts 50-366/80-13 % 50-367/80-13 on 800805-08 No noncompliance noted Major areas inspected: steel structures & supports, welding activities within containment & containment radiographic film.

 COLEY, J.L. Region 2, Atlantar, Pactor Construction & Engineering Support Branch, 60/09/04. 6pp

- B0100B0391 Responds to IE Bulletin B0-20. "Failures of Hestinghouse Tupe U-2 Spring Return to Neutral Control Switches " Lists safety-related sys using Hestinghouse-type switches Addi info to be reported by B01215 MILLE, L M Tennessee Valley Authority B0/09/16. 3pp.
- 8010170107 Ack receipt of 800902 ltr informing NRC of steps taken to carrect violations noted in IE lnsp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-519/80-11 & others MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/09/26 2pp
- --Boioi70123 Responds to NRC B00806 ltr re violations noted in IE Insp Repts 50-327/B0-24,50-328/B0-15 & others. Corrective actions: QA audits have been reviewed to identify any conclusions & recommendations found to be deficiencies MILLS.L.M. Tennesses Valley Authority B0/09/02, 14pp.
- 8010160184 Forwards Suppl 2 to IE Sulletin 79-018, "Environ Gualification of Class IE Equipment " No written response required.
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/30.
- 8010270530 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications," No written response required.
 D'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/10/02 to.
- 8010270317 Submits second revised response to infraction noted in IE insp Repts 50-566/80-03 & 50-567/80-03 Corrective actions radiographs made before 800207 re-examined for deficiencies Film processing & shim placement guidelines established MILLS.L M. Tennessee Vallsy Authority 80/10/03, 3pp
- 8010290066 Forwards IE Info Notice 80-36, "Feilure of Steam Generator Bupport Bolting " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/10/10 1p
- 8010280611 Forwards response to NRC 800926 in re violation noted in IE Insp Repts 50-564/80-14 & 50-567/80-14 Corrective actions review of concrets test dispositioned in GCIR 51057 showed design strength should be realized at later than design age MILLS, L. M. Tennessee Valley Authority 80/10/21 2pp
- B Reportable occurrences, LERs & related correspondence
- 8010210397 Final deficiency rept re improper documentation & utilization of computer program INERTIA. Brudy initiated of methods used to calculate shear-related properties used in seismic analysis Check made of all other plants.

 MILLB.L M Tennessee Valley Authority 80/10/14. 3pp.
- 80(0280596 Fourth interim rept re Const QA Audit Bignificant Deficiency, YC-C-80-03 Evaluation of Item 2 complete; U results are being documented Next rept will be submitted by 801201 HILLS, L. M. Tennessee Valley Authority 80/10/21 Ip.
- 8010280445 First interim deficiency rept re GA Audit M80-7, Deficiencies 2.3 & 5 Deficiencies under evaluation Next rept will be submitted by 801125, MILLS.L. H. Tennessee Velley Authority 60/10/23 2pp
- DOCKET STN-50-368 NEP NUCLEAR, UNIT 1
- A Application/construction stage documents & correspondence
- 8010270037 Responds to FOIA request for three categories of info re fees for withdrawn CP & QL applications Forwards App A documents. SECY-364A & JF Ahearne response sheet withheld (ref FOIA Exemption 5) FELTONJ M. Division of Rules and Records. 80/10/15. 2pp.
- --B010270064 Bubmits background info re CP application for facilities.

 Util filed motion to withdraw application on 791217 & was notified by NRC on B00324 re costs incurred for review of application. Licensee has failed to pay required fee.

 KILLER: N.O Licensee Fee Management Branch. B0/06/20. ip.
- --8010270102 Summerizes decisions reached re issues involved in implementation of 780323 revised license fee schedule. Time actually spent in traveling will be excluded from fee consideration. Lists guidelines for withdrawing application. KILLER, W. G. License Fee Management Branch. 79/02/01. 4pp

- --8010270105 Confirms 800208 telcon re request to allocate ACRS review effort per 800201 memo Amount of time spent should be allocated equally between units HILLER.W O License Fee Management Branch. 80/03/04 ip
- --8010270110 Submits mangower data re CP raview for facilities in response to 800122 request. FRALEY,R.F. ACRS - Advisory Committee on Reactor Safeguards 80/02/01, 1p
- --8010270117 Notifies that RM Laza 800127 rept was correct.ASLB accepted applicant motion to withdraw application.All time was spent as contested case.
 FITT1.C J. Atomic Bafety and Licensing Board Panel 80/03/11.
- ---8010270126 Responds to B00123 request for actual manpower data refacilities ABLB has not recorded prof man-hours expended in proceeding due to determination as contested proceeding LAZD-R.H. Atomic Bafety and Licensing Board Panal 80/01/29 ip
- --8010270142 Responds to 800120 request for actual manpower data spent re review of CP application for facilities. ASLAB spent no prof ran-hours in sua sponte review of Board action concerning CP proceeding. ROSCATMALA B Atomic Bafety and Licensing Appeal Panel 80/01/23, ip.
- DOCKET BTH-50-969 NEP NUCLEAR, UNIT 2
- A Application/construction stage documents & correspondence
- 8010270037 Responds to FOIA request for three categories of info re fees for withdrawn CP & OL applications. Forwards App A documents. SECY-364A & JF Ahearne response sheet withheld (ref FOIA Exemption 5) FELTON, J, H Division of Rules and Records 80/10/15, 2pp
- --B010270064 Submits background info re CP application for facilities.

 Util filed motion to withdraw application on 791217 & was notified by NRC on 800324 re costs incurred for review of application Licensee has failed to pay required fea.

 MILLER.H O License Fee Management Branch. 80/06/20 ip
- --B010270102 Summarizes decisions reached re issues involved in implementation of 780323 revised license fee schedule Time actually spent in traveling will be excluded from fee consideration. Lists guidelines for withdrawing application MILLER: N. Q. License Fee Management Branch. 79/02/01 App
- --8010270104 Confirms 800208 telcon re request to allocate ACRB review effort per 800201 memo. Amount of time spent should be allocated equally between units HILLER, M.O. License Fee Hanagement Branch. 80/03/04 1p.
- --8010270110 Submits menpower data re GP review for facilities in response to 800122 request FRALEY,R F. ACRS - Advisory Committee on Reactor Bafaguards. 80/02/01 1p.
- --8010270317 Notifies that RM Lero 800127 rept was correct. ASLB accepted applicant motion to withdraw application, All time was spent as contested case FITTLC J Atomic Bafety and Licensing Board Panel. 80/03/i1.
- --8010270126 Responds to 800123 request for actual manpower data refacilities ABLB has not recorded prof man-hours expended in proceeding due to determination as contested proceeding. LAZD/R H Atomic Bafety and Licensing Board Panel. 80/01/29, ip.
- --8010270142 Responds to 800120 request for actual manpower data spent re review of CP application for facilities. ASLAB spent no prof man-hours in sua sponte review of Board action concerning CP proceeding. ROBENTHALIA 8 Atomic Safety and Licensing Appeal Penel 80/01/23. 1p.
- DOCKET 50-382 BUNDESERT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8010100389 Submits info re past alteration & present condition of site, in response to NRC inquiry concerning util motion for termination of focket proceeding.

 COTTON. O.D. Ban Diego Gas & Electric Co. 80/10/06. 1p.

O. Adjudicatory correspondence

- 8010010003 Request for extension until 801017 to respond to applicant 800911 notion for withdrawal of application & termination of proceeding Info re payment of fees & redress of proposed site needed prior to response. Certificate of Svc encl. 8000ENICK. B M Rearing Branch 4 80/09/30 3pp
- 8010020719 Order grenting extension until 801017 for NRC to respond to applicant 800911 motion for termination of proceeding LAZO.R M Atomic Safety and Licensing Board Panel. 80/09/30 ip
- 80:0160770 Response to applicant 800911 withdrawal of application & motion to terminate proceedings No objection since no significant radress required, based on activities at site Certificate of Svc encl BORDENICK, B M Hearing Branch 4 80/10/15 3pp

DOCKET 50-583 SUNDESERT, UNIT 2

- A Application/construction stage documents & correspondence
- BOIO100357 Submits info re past alteration & present condition of site, in response to NRC inquiry concerning util motion for termination of docket proceeding COTTON-0 D San Diego Gas & Electric Co. BO/10/06 ip

O Adjudicatory correspondence

- B010010003 Request for extension until 801017 to respond to applicant B00911 motion for withdrawal of application & termination of proceeding info re payment of fees & redress of proposed site needed prior to response Certificate of Syc encl BORDENICK, B M Hearing Branch 4, 80/09/30 Spp.
- 8010020719 Order granting extension until 801017 for NRC to respond to applicant 800911 motion for termination of proceeding LAZO,R M. Atomic Safety and Licensing Board Panel. 80/09/30. 1p.
- 8010160770 Response to applicant 800911 withdrawal of application & motion to terminate proceedings No objection since no significant redress required, based on activities at site. Certificate of Svc encl BORDENICK, B H. Hearing Branch 4. 80/10/15. 3pp.

DOCKET STN-50-596 NEW HAVEN, UNIT 1

- Q Adjudicatory correspondence
- 8010220383 Forwards util withdrawal of application. SPINDEL, N.W. Huber, Hagill, Lawrence & Farrell. 80/10/16 1p
- --8010220371 Withdraws 781107 CP application Cites State of NY Siting Board 800523 denial of motion for rehearing of 791012 order, dismissing case in which applicant sought Certificate of Environ Compatibility & Public Need, as prime motivator KINTIGH.A E New York State Electric & Oas Corp. 80/10/14 2pp
- 8010240076 Motion to terminate proceeding due to dismissal of Case 80008 by NY State Board on Electric Generation Biting reserviron compatibility Attempts to license nuclear-fueled plants at New Haven or Stuyvesant sites abandoned.

 BPINDELIN W New York State Electric & Oas Corp PUTTER, J. L. Long Island Lighting Co SPINDEL, N. W. Huber, Magill, Lawrence & Farrell. 80/10/16 2pp
- --8010240082 Hithdrawal of 78110P application to license nuclear-fueled generation station at New Haven or Stuyvesant sites, due to dismissal of Case 80008 by NY State Board on Electric Generation Siting re environ compatibility XINTIOH.A E New York State Electric & Gas Corp. * Long Island Lighting Co. 80/10/16 2pg
- 8010240087 Hithdrawal of 781109 application to license nuclear-fueled generation station at New Haven or Stuyvesant sites, due to dismissal of Case 80008 by NY State Board on Electric Generation Siting

 * New York State Electric & Oas Corp * Long Island Lighting Co. 80/10/16. 1p.

DCKET STN-50-597 NEW HAVEN, UNIT 2

Adjudicatory correspondence

)220383 Forwards util withdrawal of application. 'INDEL:XLW Huber, Magill, Lawrence & Farrall 80/10/16 ip

- --8010220391 Withdraws 781109 CP application Cites State of NY Siting Board B00523 denial of motion for rehearing of 791012 order, dismissing case in which applicant sought Certificate of Environ Compatibility & Public Need, as prime motivator KINTIGH, A E New York State Electric & Oas Corp. 80/10/16 2pp
- 8010240076 Motion to terminate proceeding due to dismissal of Case 80008 by NY State Board on Electric Generation Siting reenviron compatibility Attempts to license nuclear-fueled plants at New Haven or Stuyvesant sites abandoned SPINDEL.N W New York State Electric & Oas Corp FUTTER.J L Long Island Lighting Co SPINDEL.N W Huber, Magill, Lawrence & Farrell 80/10/16 2pp
- --B0102400B2 Withdrawal of 781109 application to license nuclear-fueled generation station at New Haven or Stuyvesant sites, due to dismissal of Case 8000B by NY State Board on Electric Generation Siting re environ compatibility
 KINTIGHAE New York State Electric & Gas Corp * Long Island Lighting Co 80/10/16 2pp
- 80:0240087 Withdrawal of 78:109 application to license nuclear-fueled generation station at New Haven or Stuyvesant sites, due to dismissal of Case 80008 by NY State Board on Electric Generation Siting

 * New York State Electric & Gas Corp * Long Island Lighting Co 80:710716 | 10

DOCKET 50-599 CARROLL FACILITY I

A Application/construction stage documents & correspondence

- BOJOO70430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action flan Requirements" Urges NRC to consider weighing each proposed revision against benefit of having plant changes implemented promptly REED.C Commonwealth Edison GO 80/10/01 5pp
- Adjudicatory correspondence
- 8010100131 Order granting extension until 801020 for Commission to elect to review ALAB-601 CHILK. B J Office of the Secretary of the Commission 80/10/03 ip.
- 8010220942 Order granting extension until 801027 for Commission to review ALAB-601 CHILK.8 J Commissioners 80/10/20 1p
- G010300867 Order granting extension until B01103 for Commission to review ALAB-601 CHILK.S J Office of the Secretary of the Commission B0/10/27

DOCKET 50-600 CARROLL FACILITY II

- A Application/construction stage documents & correspondence
- 8010070430 Comments on NRC 800905 ltr re "Preliminary Clarification of TMI Action Plan Requirements " Urges NRC to consider wrighing each proposed revision against benefit of having plant changes implemented promptly REEO, C. Commonwealth Edison Co 80/10/01 Spp.
- O Adjudicatory correspondence
- 8010100131 Order granting extension until 801020 for Commission to elect to review ALAB-601 CHILK, 8 J Office of the Secretary of the Commission 80/10/03 to.
- 8010220542 Order granting extension until 801027 for Commission to review ALAB-601 CHILK.S.J. Commissioners 80/10/20 ip
- 8010300567 Order granting extension until 801103 for Commission to review ALAB-601.

 CHILK: B J Office of the Secretary of the Commission. 80/10/27

MESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

ET 70-0008 BATTELLE COLUMBUS LABORATORIES

0220360 Approves proposed route for transport of spent reactor fuel, a response to 800812 request Encl arrangements & approved bute withheld (ref 100FR2 790) CORKLE,O W Physical Security Licensing Branch 80/10/06 2pp

ET 70-0025 ROCKWELL INTERNATIONAL CORP

0220212 Requests 30-day extension of 600822 submission date for evised physical security plan for SNM TRILEY,M E Rockwell International Corp , Energy Systems Div 0/07/14 ip

Di022022O Forwards administrative fee in response to NRC 800805 ltr request for amend to license in connection w/30-day extension of submission date for revised physical security plan REMLEY,IX E Rockwell International Corp , Energy Bystems Div BO/39/14 ip

0150558 Forwards revisions to E80-80-17, "Physical Security Plan for rotection of Moderate Strategic Quantities of ENMs at Hot abs of Energy Sys Group of Rockwell Intl," per 800716 equest for addl info Encl withheld (ref 10CFR2 790) EMEEVING THE Rockwell International Corp , Energy Systems Div 0708/20

0150080 Approves 800714 request for deferral until 800921 for ubmittal of revised fixed site safeguards physical rotection plan URNETTR F Division of Bafeguards 80/08/26 1p

0070513 Requests facility tour for SL Davis for completion of NRC ontracted research rept. "Behavioral Observation Program to soure Continued Reliability for Employees"
CCDRKLE, GW Physical Security Licensing Branch B0/09/04 Ip

0240545 Forwards increment to analysis entitled "Effect of Natural henomena on Existing Pu Fabrication Facilities,Response of tructures to Wind Hazard at Atomics Intl Nuclear Matls evelopment Facility,Santa Susana.CA: "Vol I DUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/09/12

010240553 Recommends endorsement of "Effect of Natural Phenomena on Existing Pu Fabrication Facilities, Response of Structures to Wind Hezerd at Atomics Intl Nuclear Matls Development Facility, Santa Susana-CA, "Vol I AYER.J E., DURKHARDT, W. Advanced Fuel & Spent Fuel Licensing Branch 80/09/12 ip

010240558 "Effect of Natural Phenomena on Existing Pu Fabrication Facilities:Response of Structures to Wind Hazard at Atomics Intl Nuclear Matls Development Facility, Santa Busana, CA." Vol I

MCDONALD, J R , ALIKHANLOU, F 4 Argonne National Laboratory Texas Tech Univ 80/08/31 40pp

KET 70-0027 BABCOCK & WILCOX CO

0060021 Requests that attached 800605 ltr replace 791120 ltr Ltr odifies original request for specific exemptions of easurement control program & limit of error calculations. ORDANI.R A Babrock & Wilcox Co , Naval Nuclear Fuel Div 0/06/05 Ip

010060023 Application to amend License SNM-42, requesting exemption from 10CFR70 58(f) measurements control plan requirements for airborne U released to environ W/o encl amend fee CORDANIR A Babcock & Wilcox Co , Naval Nuclear Fuel Div 80/05/05 2pp

0070483 Requests amend to License BNM-42, exempting (OCFR70 \$7(b)(10) equirements re calculating uncertainty due to calibr of scondary weighing stds Administrative amend fee encl ORDANI, R Babcock & Wilcox Co , Naval Nuclear Fuel Div 0/04/09.

8060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800515 16 No noncompliance noted, TOHR, J P Region 2, Atlanta, Fuel Facility & Materials Sefety ranch 80/06/23 2pp.

- --B008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance noted Major areas inspected/compliance w/NRC & DOT regulations TROUP.0 L Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/06/23 6pp
- 8010150532 Forwards revised chapters of B&W, NNFD, "Fundamental Nuclear Matl Control (FNMC) Plan " Revisions made per Ounderson 800721-23 visit CORDANI,R A Babcock & Wilcox Co , Nuclear Material Div 80/08/13
- BO10100272 Approves B00725 request for 7-day delay in start of Jul-Aug 1980 physical inventory Submits revised Safeguards Amend HPP-1.adding new license condition PARTLOWJ 0 Material Control Licensing Branch B0/08/15 ip
- 8010210759 Application for amend to License SNK-42, replacing physical security plan Fee encl W/o encl revised physical security plan CORDANI,R A Babcock & Wilcox Co , Naval Nuclear Fuel Div BO/08/22 2pp
- 8010190087 Advises of NRC plans for review of revised fixed site physical protection submittal MCCGRKLE.G W Physical Security Licensing Branch 80/09/02 ip
- 8010190635 Forwards JA Lynott & RA Jolliff 800618 certificates for FY79 & FY80, providing financial assurance for payment for decommissioning costs
 JORDAN:L V Babcock & Wilcox Co 80/09/02 4pp
- 8010210R83 Forwards certificates of assurance attesting that company has met all restrictive covenants contained in promissory note agreements re decommissioning activities & can meet financial obligations

 JORDAN, L. V. Babcock & Wilcox Co. 80/09/02 4pp
- B010200240 Forwards 800904 NNFD. "Fundamental Nuclear Matle Control Plan." Revision 4 Chapter i revision corrects matl control & accountability statistician reporting status Only FNMC plan schedule encl
 CORDANIAR A Datcock & Wilcox Co. Nuclear Material Div 80/09/05
- 8010200233 Requests that all correspondence be directed to RA Cordani to effectively continue coordinated action/response w/NRC MCCLANAHAN, H H Bebcock & Wilcox Co , Nuclear Material Div. 80/09/08.
- 8010230487 Requests amend to License BNM-42 to include provisions for accepting & recording shipper values for one scrap fuel assembly from United Nuclear Corp.
 CORDANIS A Babcock & Hilcox Co . Naval Nuclear Fuel Div.
 80/09/08 ip
- B0100B01i9 Forwards Amend MPP-i to License BNM-42, incorporating new & revised license conditions & withdrawing obsolete conditions Fundamental nuclear matl control plan submitted earlier should be withheld (ref 100FR2 790) PARTLOMIJ 0 Material Control Licensing Branch B0/09/16 1p
- --8010080124 Revised Amend MPP-1 to License SNM-42, incorporating new & revised license conditions & withdrawing obsolete conditions to fundamental nuclear matl control # Material Control Licensing Branch. 80/09/16 4pp.
- 8010020238 Ack receipt of 800911 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 70-0027/80-13 KENNA, W B Region 2, Atlanta, Safeguards Branch 80/09/17 ip
- --80(0020265 Responds to NRC 800819 ltr re violations noted in IE Insp Rapt 70-0027/80-13 Corrective actions withheld (ref 100FR2 790). ECKERTJ P. Babcock & Wilcox Co , Naval Nuclear Fuel Div. 80/09/11 lp
- --B0100R0270 Forwards IE Insp Rept 70-0027/80-13 on 800729-31 Details withheld (ref 10CFR2 790)
 KENNA,W B Region 2: Atlanta, Safeguards Branch 80/09/19 2pp
- --8010020275 IE Insp Rept 70-0027/80-13 on 800729-31 Details withheld (ref 10CFR2 790). TQBIN.II J , MCGUIRE,D R Region 2, Atlanta, Office of the Director 80/08/18 ip
- 8010290406 Forwards Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted STDHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp

- --8010290410 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801 No noncompliance noted Major areas inspected shipping paper.DOT placarding radiation levels removable contamination & prohibited articles or contents MACARTHURLT C . POTTER.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/09/16 8pp
- 80:0160000 Requests add1 info re physical protection plan Specific details will be discussed at 80:002-03 meeting in Silver Spring, MD MCCORKLE, O W Physical Security Licensing Branch 80:009/24 ip.
- --8010160012 Discusses forthcoming meeting w/B&H
 SMITH.O F Physical Security Licensing Branch 80/09/23 ip
- BO10160719 Forwards IE Insp Rept 70-0027/80-14 on 800902-04 No noncompliance noted Details withheld (ref 10CFR2 770) KENNA, H B Region 2, Atlanta, Safeguards Branch 80/09/26 ip
- --8010160724 IE Insp Rept 70-0027/80-14 on 800902-04 No noncompliance noted Major areas inspected shipping & receiving Details withheld (ref 10CFR2 790)
 JONES,D W Region 2. Atlanta, Office of the Director KAHLE, J B Region 2. Atlanta, Safeguards Branch 80/09/26 ip

DOCKET 70-0033 TEXAS INSTRUMENTS. INC

- 8010230120 Forwards IE Insp Rept 70-0033/80-08 on 800728-31 No noncompliance noted Details withheld (ref 100FR2 790) MARTIN W O Region 1, Philadelphia, Safeguards Branch 80/08/25 200.
- --8010230124 IE Insp Rept 70-0033/80-08 on 800728-31 No noncompliance noted Major areas inspected security plan, physical barriers, access controls & detection aids Details withheld (ref 10CFR2 790) DEVLIN.J W. MCKEOWN,L M. Region 1, Philadelphia, Safeguards Branch 80/08/22 ip
- 8010280055 Responds to 800716 ltr requesting Amend 13 to License 8NM-23 & discontinuation of 790215 application for license renewal Original license is extended to 820630 Renewal fee will be refunded MILLER.W O License Fee Management Branch 80/10/08 ip.
- 8010210567 Forwards "SNM Monthly Rept of Matl Discards (MD) & Inventory Difference" & Form NRC/ERDA 742 w/supporting subschedule in response to NRC 800430 request H/o encls SCHWENSFEIR:R Texas Instruments, Inc. 80/10/13 ip
- BO102i04BD Forwards updated Sections 10 5 10 1.1-1.Revision A & 10 5 10 1.1-2.Revision B of HFIR Project emergency plan per BO0430 request BCHMENBFEIR.R Texas Instruments. Inc BO/10/15 4pp
- BO10280524 Responds to NRC BO0430 request for updated sections of High-Flux Isotope Reactor Project emergency plan Sections & forwarding itrs encl. W/o encl BCHMENSFEIR:R Texas Instruments, Inc BO/10/22 ip
- --8010280932 Forwards updated sections of High-Flux Isotope Reactor Project emergency plan & forwarding ltrs Changes submitted for info purposes only. BCHWENSFEIRR Texas Instruments, Inc 80/10/22 8pp

DOCKET 70-0036 COMBUSTION ENGINEERING, INC.

- B010150098 Approves GNM security plan submitted on B00513, amending License SNM-33, Amend MPP-3 by adding encl Section 12 MCCORKLE, Q, W Physical Security Licensing Branch B0/09/28 2pp
- 8010080118 Forwards IE Insp Rept 70-0034/80-04 on 800812-13 No compliance noted DAVIS-A.B. Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/09/04 2pp
- --8010080136 IE Insp Rept 70-0036/80-04, on 800812-15 No noncompliance noted Major areas inspected organization facility changes, internal/external exposure control/liquid/gaseous effluents & training PECK.C.C. FISHER.H.L. Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/09/02 App

DOCKET 70-0048 WESTINGHOUSE ELECTRIC CORP

- 8010010294 Forwards IE Insp Repts 70-0048/80-01 & 70-1503/80-01 on 800404 No noncompliance noted KINNEMAN,J D Region i. Philadelphia. Office of the Director 80/08/01 2pp
- --8010010298 IE Insp Repts 70-0048/80-01 & 70-1503/80-01 on 800604 No moncompliance noted Major areas inspected personnal monitoring-radiation safety committee, hot coil entry controls & airborne releases to unrestricted areas KINNEMAN, J. COSTELLO, F. Region 1, Philadelphia, Office of the Director 80/07/31 App

DOCKET 70-0082 NUCLEAR METALS, INC

8010220567 PND-I-B0-114 on 800730.mixture of depleted U tetrafluoride & magnesium overheated & exploded Licensee is making surveys to determine extent of contamination Bloassays are planned for personnel in facility at time of event KINNEMARC, J D. SKITH.O H Region 1, Philadelphia, Office of the Director 80/07/31 2pp

DOCKET 70-0134 WISCONSIN, UNIV OF, MADISON

- 80100399315 Forwards IE Insp Repts 50-156/80-04 & 70-0134/80-02 on 800811-12 No noncompliance noted DAVIS-A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/08/28 2pp
- --8010030519 IE Insp Repts 50-154/80-04 & 70-0134/80-02 on 800811-12 No noncompliance noted Major areas inspected radiation protection training, radwaste mgt program, effluent controls & transportation activities FIGHER.

DOCKET 70-0135 BABCOCK & WILCOX CO

- 8010070150 Confirms 800820 telcon in response to NRC 800703 ltr re corrective actions to be taken against spread of contamination in laundry GRIER.B H Region 1. Philadelphia, Office of the Director. 80/08/21 2p
- 8010010406 Forwards IE Insp Repts 70-0135/80-20 & 70-0364/80-16 on 800714-18 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/08/08
- --8010010417 IE Insp Repts 70-0135/80-20 t 70-0364/80-16 on 800714-18.86 noncompliance noted Major areas inspected, measurement to statistical controls of liquid effluent waste treatment sys in low enriched U plants
 ZIBULBKY, H Region I, Philadelphia, Office of the Director, JOYNER, J H Region I, Philadelphia, Safeguards Branch 80/08/05
- 8010200133 Forwards comments in response to 800318 submittel of revised fundamental nuclear matl control plan for low enriched U operations 8ome comments require response to meet current regulatory position. Encl withheld (ref 10CFR2, 790) PARTLON. J. G. Material Control Licensing Branch. 80/08/22 ip
- 8010020494 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/80-18 MARTIN.W G Region 1. Philadelphia. Safeguards Branch 80/08/27 in.
- --9010020691 Responds to NRC 800715 ltr re violations noted in IE Insp Rept 70-0135/80-18 Corrective actions withheld (ref 10CFR2 790) AUSTIN, H A Babcock & Wilcox Co 80/08/06 Ip.
- --B010020697 Forwards IE Insp Rept 70-0135/80-18 on 800623-27, Details withheld (ref 10CFR2, 790)
 MARTIN, N O. Region 1, Philadelphia, Bafeguards Branch. B0/07/15
 220
- --8010020702 IE Inep Rept 70-0135/80-18 on 800623-27. Noncompliance notes. licensee failed to discard used tamper seals. Details withheld (ref 10CFR2 790).

 JOYNER, J. H. Region I. Philadelphia: Bafeguards Branch.
 BIGSETT, P. H., SUMMERS, R. J. Region I. Philadelphia: Office of the Director. 80/07/07 ip.

- BO10240108 Forwards IE Insp Repts 70-0135/80-23 & 70-0364/80-19 on 800804-08 No noncompliance noted.
 MARTIN N O Region 1. Philadelphia, Safeguards Branch 80/08/29
- ~~8010240114 IE Insp Repts 70-0135/80~23 & 70-0364/80-19 on 800804-08
 No noncompliance noted Major areas inspected measurement & statistical controls. ID & associated LEID Details withheld (ref 10CFR2 790)

 JOYNER, J H Region i. Philadelphia. Safeguards Branch
 HHLDBY, D J Region i, Philadelphia. Office of the Director 80/08/27 | 1p
- 80:0150635 Forwards JA Lynott & RA Jolliff 800618 certificates for FY79 & FY80.providing financial assurance for payment for decommissioning costs
 JORDANI, L V Babcock & Wilcox Co 80/09/02 App
- BO10210283 Forwards certificates of assurance attesting that company has met all restrictive covenants contained in promissory note agreements re decommissioning activities & can meet financial obligations

 JORDAN.L V Babcock & Wilcox Co 80/09/02 4pp
- 8010210240 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/80-12 GRIER.B H Region 1, Philadelphia, Office of the Director 80/09717 lp
- --B010210247 Responds to NRC 800703 ltr re violations noted in IE Insp Rept 70-0135/80-12 Corrective actions metls from two containers were promptly removed to permit proper storage in covered metal containers AUSTIN: A Babcock & Wilcox Co., Nuclear Material Div 80/08/06
- --8010210251 Forwards LE Insp Rept 70-0135/80-12 on 800428-0502 & 14-15 & notice of violation SMITH, 9 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/03 2pp
- ~-8010210256 Notice of violation from insp on 800428-0502 & 14-15 * Region 1, Philadelphia: Office of the Director 80/07/02 2pp
- ~-8010210264 IE insp Rept 70-0135/80-12 on 800428-0502 & 14-15
 Nancompliance noted failure to follow nuclear safety posting
 requirements & failure to store combustible waste matl in
 covered metal containers
 ROTH, J. Region 1, Philadelphia, Office of the Director
 CROCKER, H W. Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch 80/07/02 19pp
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC
- 8010060087 PNO-II-80-130 on 800728, fire distovered in small room where process tubes are cleaned Samples of air exhausted during fire showed no redioactivity above normal levels. Licenses estimates two to three g U may have been in room KAHLE.J B . KENNA W B Region 2. Atlanta, Office of the Director 80/07/28 1p
- BO10090172 Forwards Nuclear Fuel Svcs, Inc 800730 physical protection plan. Revision 18 Rept withheld (ref 10CFR2 790) MICHEL, C J Nuclear Fuel Services, Inc (subs. of Oetty Oil Co.). BO/07730 ip
- 8010210764 Forwards final status rept for completing installation on add1 liquid storage capacity in waste water treatment facility
 MICHEL,C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co)
 80/08/12 2pp
- BO10140153 Matl/Byproduct License SNM-124 is amended per S00725 application Amend B authorizes soil decontamination as described in application RAGE.R G Uranium Fuel Licensing Branch BO/OB/15 2pp.
- BO10240288 Forwards proprietary physical safeguards plan. Plan is complete revision of physical protection plan & upgrades sys performance capabilities Plan withheld (ref 10CFR2 790) MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Cq) BO/08/19 ip
- 80:0150608 Forwards bimonthly status rept outlining status of committed improvements & evaluations as of 800815 Encl withheld (ref 100FR2.790)
 TAYLOR, C W Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.).
 80/08/25, ip

- 8010020200 FDIA request for IE Insp Rept 70-0143/79-40 & all other documents re environ monitoring & control at facility WEISS.E R Sheldon, Harmon & Weiss 80/08/26 ip
- 8010150612 Requests amend to License SNM-124.subj to administrative fee Amend outline withheld (ref 10CFR2 790)
 MENSLEY.K D Nuclear Fuel Services, Inc. (subs. of Qetty 0:1 Co.)
 80/08/28 1p
- B010090517 Advises that RR Rentschler has been assigned project officer for review of revised fixed site physical protection plan MCCORKLE,0 W Physical Security Licensing Branch 80/09/02 ip
- 8010200348 Forwards minor & major safeguards amend fees re 800730 & 0819 requests, respectively, in response to NRC 800807 ltr MICHEL-C J Indiana & Michigan Electric Co 80/09/03 ip
- --B010200332 Requests minor safeguards amend fee re B00730 request for revision of physical security plan WEISS, D License Fre Management Branch 80/08/07 ip
- 8010090177 Bubmits proposed schedule for submitting physical safeguards plan
 MICHEL.C J Nuclear Fuel Bervices, Inc. (subs. of Getty Oil Co.)
 80/09/04 2ap
- B010150657 Requests release of const area adjacent to railroad for addition of fill MICHEL.C J Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.) 80/09/09 5pp
- 8010030137 Submits NRC criteria per Condition A-2 of Amend 8 to SNM-124 Licensee shall collect representative surface samples of each grid of affected area & dry soil sample shall be analyzed for total alpha activity PAGE,R 0 Uranium Fuel Licensing Branch 80/09/15 1p
- BO10100014 Advises that Attachment A to IE Insp Rept 70-143/80-01 does not contain proprietary info & will be distributed in accordance w/normal procedures
 KENNA, W B Region 2. Atlanta, Safeguards Branch 80/09/16 ip
- --8010100017 Forwards 1E Insp Rept 70-143/80-01 on 800109-10 & 0519-23 KENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/06 2pp
- --8010160020 IE Insp Rept 70-143/80-01 on 800109-10 t 0519-23 No noncompliance noted Major areas inspected U effluent scrubber sys.stack sampling sys.safety committees t operations review KAHLE.J B. DAVIS.J H. Region 2, Atlanta, Office of the Director KENNAIN B. Region 2, Atlanta, Safeguards Branch 80/06/06 Gpp
- --8010100023 "Analysis of Ventilation Scrubbers & Qaseous Effluent Measurement Sys at NFB Plant, Erwin, TN " BEVERLY, C R , KOBINSKI, F E Union Carbide Corp FIN A-9069 KY/L-1050 80/05/05 37pp
- B0:0010055 Advises that no add1 fee required re 780427 & 800709 applications for minor safety amond to License SNM-124 MILLER,N O License Fee Management Branch 80/09/17 ip
- 8010150132 Responds to 800909 request for release of decontaminated land Land adjacent to main track of Clinchfield Railroad is released for unrestricted use Addl decontamination efforts required to release remaining land, PAGE.R 0 Uranium Fuel Licensing Branch. 80/09/18 2pp
- 8010030329 Ack receipt of 800905 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-46.
 KENNA, W.B. Region 2, Atlanta, Safeguards Branch 80/09/19 lp
- 80:0020:35 Add1 response to FOIA request for 11 documents refacility Forwards affidavit of KJ Dircks Info partially withheld (ref FOIA Exemption i) FELTON, J M Division of Rules and Records 80/09/24 ip
- --8010020145 Unclassified affidavit of WJ Dircks re facility inventory difference. Info partially withheld (ref FQIA Exemption 1). DIRCKS.W J Office of Nuclear Material Bafety & Bafeguards 80/02/19 4pp
- B010020176 Responds to FOIA request for IE Insp Rept 70-0143/79-40 & all other documents re environ monitoring & control at facility IE insp rept is available in PDR Remaining documents are undergoing review FELTON, J. M. Division of Rules and Records. 80/09/24 ip

- B010020370 Forwards response to IE Insp Rept 70-0143/B0-24 Response withheld (ref 10CFR2 790) MANSER, W C Nuclear Fuel Services, Inc (subs of Qetty Dil Co) 80/09/26 ip
- 8010010630 Responds to 800916 ltr re NRDC matter Commission 800922 order denies NRBC motion along w/Oil Chemical & Atomic Workers Intl Union rights to submit written statements of position & present oral anguments Detailed order pending NORDLIKOER,M S Office of the General Counsel 80/09/29 1p
- 8010270285 Ack receipt of NRC 800915 ltr transmitting [E Insp Rept 70 0143/80-18 Rept contains no proprietary info MANSER, N C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/09/30 1p
- --8010270289 Foruards IE Insp Rept 70-0143/80-10 on 800604-06 & 0714-17 No noncompliance noted STCHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/09/15 ip
- --8010270295 IE Insp Rept 70-0143/80-18 on 800604-06 & 0714-17 No noncompliance noted Major areas inspected environ program mg6. implementation of monitoring programs. GC of analytical measurements & nonradioactive releases GIDEON, GT Region 2. Atlanta, Office of the Director JENKINS, GR Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/09/11 12pp
- 80:0060079 Add1 response to FQIA request for IE Insp Rept 70-0143/79-40 & all other documents re environ monitoring & control at facility Documents are avaliable in Hashington. DC PDR FELTON. J H Division of Rules and Records 80/10/01 ip
- 8010070386 Requests access authorizations for individuals who will have access to classified info at or in conjunction u/facility Required info & signed security acknowledgement encl List of info/viduals not encl individua... MANSER, W.C. A Nuclear Fuel Services, Inc (subs of Cetty Oil Co)
- 8010070424 Requests NRC security facility approval for handling of NRC classified info Forwards classified security plan Plan withheld (ref 10CFR2 770) MANSERN C Nuclear Fuel Services. Inc (subs of Oetty Oil Co) 80/10/01 ip
- B010270007 Confirms B00926 agreement that vendor will include discussion of issues in addendum to B00919 rept, to be submitted by B01008 List of issues withheld (ref 100FR2 790) O'REILLY. J P Region 2, Atlanta, Office of the Director. 80/10/02
 - 10070283 Forwards proposed security procedures & controls for protection of natl security info Info withheld (ref 100FR2 770) CLARK,JR Nutlear Fuel Services. Inc. (subs of Getty Dil Co) 80/10/03 ip
- 3010230250 Amend MPP-i to License SNM-i24 adding condition 6 5 1 to authorize use of shipper's tare weight values & impurity analyses for U fluoride receipts.
 PARTLOW 0 Material Control Licensing Branch 80/10/03 ip
- 3010230423 Forwards request for add1 info re revised Bection 3 0 of 800618 fundamental nuclear mat1 control plan Encl to 800618 ltr detarmined to contain proprietary info (ref 10CFR2 790) PARTLUM, J 9 Material Control Licensing Branch 80/10/06 ip
- 0010240178 Ack receipt of 800926 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-26
 KENNA,W B Region 2, Atlanta: Safeguards Branch 80/10/06 1p
- 8010240185 Responds to NRC 800903 ltr re violations noted in 1E Inap Rept 70-0143/80-26 Corrective actions withheld (ref 10CFR2 790) MANSER, H C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/09/26 ip.
- 3010240191 Forwards IE Insp Rept 70-0143/80-26 on 800728-31 Details withheld (ref 10CFR2 790) KENMA, W. B Region 2, Atlanta, Safeguards Branch 80/09/03 2pp
- 10150417 Submits munthly rept re status of investigative & corrective actions taken on main process stack of Bidg 302/303 & apdate of daily air concentrations Evaluation of scrubber efficiency will be available by 801031 MANBER, M.C. Nuclear Fuel Services, Inc. (subs. of Gatty Dil Co.) 80/10/08 50a

- 8010160493 Responds to NRC 800929 request for review of 800323 rept "Technical Assessment of Inventory Differences at NFS," Jan 1978-Mar 1980 No proprietary info found MAMSER.W C Nuclear Fuel Services. Inc (subs of Getty 011 Co) 10 80/10/10
- 8010210485 Forwards request for amend to License BNM-124.Amend MPP-1. Section 5 5 Request withheld (ref 100FR2 790) Fee enci HENSLEY.X D Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 80/10/13 1p
- 8010210325 Responds to NRC 800922 ltr re violations noted in IE Insp Rept 70-143/80-24 Corrective actions request for amend to License SNN-124 to be submitted re exemption to requirement for fire hydrant fire prevention program audited MANSER,N C Nuclear Fuel Services, Inc (subs of Getty Dil Co) BO/10/15 8pp
- B010310300 Forwards classified discussion re status of commitments made & potential effect on each subj area on inventory difference as requested by Region 2 801002 ltr Encl withheld per 10CFR2 770 10CFR2 790 HENSLEY, X D Nuclear Fuel Services, Inc (subs of Getty Dil Co) BO/10/24 ip

DOCKET 70-0157 TEXAS, UNIV OF

8010230118 Forwards request for add1 info re safety program to complete license renewal review Outstanding items include description of radiation safety officer educational qualifications, experience & duties STEVENSON, R L Uranium Fuel Licensing Branch 80/09/23 2pp

DOCKET 70-0162 LUCIUS PITKIN, INC

- 8010210164 Trip rept re 900911 visit to Region I ofc & 800912 visit to facility re application for renewal of License SNM-137, Company considering listed three options in plenning nuclear activities
 SDONO, A L. Uranium Fuel Licensing Branch 80/09/11 2pp
- --8010210169 Forwards comments on content & insp of 751126 application for renewal of License SNM-137 to be discussed during AL Soons 800811 visit ROTH. J Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/29 3pp
- BO10210112 Requests NRC approval to change License BNN-137 permitted U-235 possession limit from 500 g to less than 350 g, subj to NY State licensing jurisdiction RISINO.B A Lucius Pitkin. Inc 80/09/05 ip

DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO

- 801006002B Forwards request for reduction in number of nondestructive assay stds per 800626 telcon between EL Bellisario & O Ounderson Request withhheld (ref 100FR2 790) AUSTINAM A Babcock & Wilcox Co , Nuclear Material Div 80/06/26
- 8008210613 Application for renewal of Certificate of Compliance 6400 for super Tiger Shipping package Requested info re leakage test requirements 5 seal replacement schedules is presented in App C of encl mat!

 DIPHAZZA,R Westinghouse Electric Corp 80/07/28 61pp
- --BOOB210614 Application for certificate of compliance to deliver Super Tiger, DDT SP 6400, to carrier, as fissile Class i shipment lpment ITLER, E K I 100/17 2pp Babcock & Wilcox Co , Nuclear Material Div
- ---BCOS210615 Responds to quastions re loading of Buper Tiger w/waste drums.raised in AEC 71118 ltr Crates inherently safe from criticality since no more than 5 g fissile fuel contained per cubic ft of crates Two illegible drawings encl. REITLER, E & Babcock & Wilcox Co , Nuclear Material Div. 72/01/06 6pp
- 8010010406 Forwards IE Insp Repts 70-0135/80-20 & 70-0364/80-16 an 800714-18 No noncompliance noted MARTIN.W. O Region 1: Philadelphia, Safeguards Branch 80/08/08

- --B010010417 IE Insp Repts 70-0135/80-20 & 70-0364/80-16 on 800714-18 No noncompliance noted Major areas inspected measurement & statistical controls of liquid effluent waste treatment sys in low enriched U plants
 ZIBULBXY, H Region 1. Philadelphia, Office of the Director
 JOWER, J H Region 1. Philadelphia, Safeguards Branch 80/08/05
- BOIO100256 Approves BOOBO1 request for exemption from requirement to submit Category 1 physical security plan
 BURNETT,R F Division of Safeguards 80/08/21 ip
- 8010150543 Forwards fundamental nuclear matl control plan for Pu decommissioning activities Nuclear Matls & MFg Div will request license conditions to cover processing to decommissioning transition Encls withheld (ref 10CFR2 790) AUBTIN,M A Babtock & Wilcox Go , Nuclear Material Div 80/08 B0/08/29
- B01024010B Forwards IE Insp Repts 70-0135/80-23 & 70-0364/80-19 on B00B04-0B No noncompliance noted MARTIN, 0 Region i. Philadelphia, Bafeguards Branch B0/08/29
- --B010240114 IE Into Repts 70-0139/80-23 & 70-0364/80-17 on B00804-08 No noncompliance noted Major areas inspected measurement & statistical controls. ID & associated LEID Details withheld (ref 10CFR2 790) JOYNER, J. H. Region i, Philadelphia, Bafeguards Branch HOLODY, D. J. Region i, Philadelphia, Office of the Director 80/08/27 ip
- 8010130635 Forwards JA Lynott & RA Jolliff 800618 certificates for FY79 & FY80, providing financial assurance for payment for decommissioning costs JORDAN, L.V. Bebcock & Wilcox Co. 80/09/02 4pp
- 8010210283 Forwards certificates of assurance attesting that company has met all restrictive covenants contained in promissory note agreements re decommissioning activities & can meet financial obligations.

 JORDAN, L. V. Babcock & Wilcox Co. 80/09/02 4pp.
- 89:10070144 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power " Phone line insp performed by maint personnel w/telephone representative 4 administrative directive issued AUBTIN,K A Bebcock & Wilcox Co 80/09/08 1p.
- 9010020193 Ack receipt of 800905 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/80-15 SMITH O.H. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 80/09/10 ip
- --8010020202 Responds to NRC 800811 ltr re violations noted in IE lnsp Rept 70-0364/80-15 Corrective actions existing Class II & IV OA audit schedules reviewed to ensure inclusion of all current activities. Babcock & Wilcox Co , Nuclear Material Div 80/09/05 AUSTIN, M A
- --8010020206 Forwards IE Insp Rept 70-0364/80-15 on 800424-27 & notice of violation BMITH.9 H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/11 209
- --8010020217 Notice of violation from insp on 800624-27 * Region 1, Philadelphia. Office of the Director 80/08/08 1p
- --8010020223 IE Insp Rept 70-0364/80-15 on 800624-27, Noncompliance noted failure to conduct audits of GA program & failure to maintain records of receipt insp of equipment in Pu facility Fab I ventilation sys CROCKER:H W. ROTH.J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/08 17pp.
- B010300188 Corrects errors in IE Insp Rept 70-0364/80-20 MARTIN:N 0 Region 1. Philadelphia. Bafeguards Branch 80/09/25. MARTININ O
- --8010300193 Forwards IE Insp Rept 70-0364/80-20 on 800812-15 No noncompliance noted MARTIN,W O Region 1. Philadelphia, Safeguards Branch 80/09/12
- --8010300178 IE Insp Rept 70-0364/80-20 on 800812-15. No noncompliance noted Details withheld (ref 100FR2 770)
 DEVLIN,J W, BAILEY,R J Region 1, Philadelphia, Safeguards Branch. 80/09/05. 1p

- 8010100302 Forwards Endorsements 1.2,4,7,11-14,14-18 to MAELU Policy MF-84 & Endorsements 2-7,9-23,25-28,31-34,37-40,42,44-49, 55,57-60,62,65,66,68,70,74,75 & 79 to MELIA Policy NF-83 BOTHMAN.J J Ray McDermott & Co 80/10/06 B3pp
- 8010240370 PNO-I-80-148 on 801009, plywood cover on decommissioned hood in Fab 5 chemistry lab discovered smoldering Cause of fire speculated to be from ceiling tiles igniting during hood welding operation ROTH.J. CRCCKER.H W Region 1, Philadelphia, Office of the Director SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/10/10 2pp

DOCKET 70-0371 UNITED NUCLEAR CORP

- S010090482 Forwards revised frawing of proposed protected area 2 matl access area entry/exit control points All hand cerried packages from Didg C will be searched Hard copy of drawing in Central Files only United Nuclear Corp Naval Products Div 80/06/16 DUSTAFRON, R B
- 8010070487 Responds to NRC 800608 ltr re potential adverse effect of safeguards program due to decision to terminate recovery of high enriched U Recovery contract expected to be negotiated w/B&N Navy Nuclear Fuel Division in Sept 1780
 OANLEY, D E United Nuclear Corp , Navai Products Div 80/06/25
- 8010010334 Forwards IE Insp Rept 70-0371/80-11 on 800714-17 No noncompliance noted
 MARTIN.II O Region 1. Philadelphia. Bafeguards Branch BO/08/07
- --8010010341 IE Insp Rept 70-0371/80-11 on 800714-17 No noncompliance noted Major areas inspected mgt of nuclear matl control, shipping & receiving WOLTNER, E. Region 1, Philadelphia, Office of the Director, JOYNER, J. Region 1, Philadelphia, Bafeguards Branch, 80/07/31
- 8010090476 Requests 30-day extension for submitting safeguards physical protection plan for upgrade rule Plan will be submitted prior to 800922 Fee encl
 KIRK,W F United Nuclear Corp ,Navel Products Div 80/08/07. ip
- 80:01:50083 Approves util 800807 request for deferral until 800921 for submittal of revised fixed site safeguards physical protection plan BURKETTIR F Division of Safeguards 80/08/20 ip
- 8010200247 Forwards United Nuclear Corp Naval Products Div physical protection plan per NRC 791128 amends to 100FR73 physical protection rule Plan withheld (ref 100FR2 790) KIRK, W.F. United Nuclear Corp., Naval Products Div. 80/09/12, 19
- B010010477 Forwards explanation of why responses to questions contained in NRC 800415 ltr re units of nonspherical geometry & tiered arrays were found unsatisfactory Review will continue upon receipt of add1 info
 BTEVENBON.R L Uranium Fuel Licensing Branch 80/09/17 App
- 8010080132 Forwards Amend MPP-1 to Litense SNM-368 incorporating new & revised license conditions Fundamental nuclear ma control plan submitted earlier should be withheld (ref 100FR2 790) PARTLOWJ O Material Control Licensing Branch Material Control Licensing Branch 80/09/17 1p
- --8010080143 Revised Amend MPP-1 to License BNM-368/incorporating new & revised license conditions to fundamental nuclear control + Material Control Licensing Branch 80/09/17 7pp
- B010200522 Responds to 1E Bulletin B0-19, "Possible Loss of Emergancy Notification Sys (ENS) w/Loss of Offsite Power * Actual power failure required to actuate transfer switch k power sys at facility Emergency diesel generator tested weekly GAN EY, D E United Nuclear Corp , Navel Products Div. 80/09/17 200
- 801014019B Responds to 800723 ltr re Sr-90 contamination at facility. 8r-90 came from processing U from nuclear excursion & low power experiments in conjunction w/navel reactor program Facility will be required to decontaminate to KRC criteria CRCH. H T Uranium Fuel Licensing Branch 80/09/19 2pp
- --8010140233 Discusses reorganization of Naval Products Div & Commercial Products Div activities under Licenses SNM-368 & SNM-777 Revised sections of each license enci, LINDSERO.J A. United Nuclear Corp 68/06/10, 3pp.

- B010230093 Forwards IF Insp Rept 70-0371/80-14 on 800825-29 No noncompliance noted Details withheld (ref 10CFR2 790) MARTININ O Region I, Philadelphia, Safeguards Branch. B0/09/23.
- --8010230099 IE Inep Rept 70-0371/80-14 on B00825-28.No noncompliance noted Major areas inspected storage & internal controls & measurements & statistical controls Datails withheld (ref 10CFR2,790)
 J0YMER.J H Region 1, Philadelphia, Bafeguarda Branch, H0LODY,D J BISSETT,P H, Region 1, Philadelphia, Office of the Director, B0/09/19 ip
- 8010160004 Notifies that WC Floyd has been appointed project officer for review of revised fixed site physical security plan.

 MCCORKLE, O. H. Physical Security Licensing Branch 60/09/24. ip.
- 8010270228 Forwards request for add1 info re 800919 classified application re changes in storage criteria, GTEVENBON,R.L. Uranium Fuel Licensing Branch, 80/10/05 23pp.

DUCKET 70-0487 UNION CARBIDE CORP

- 9010230716 Ack receipt of 791205 ltr informing NRC of steps taken to correct violations noted in IE losp Repts 50-054/79-04 & 70-0687/79-04 MARTIN N Q Region 1, Philadelphia, Bafeguards Branch. 80/02/20.
- --B010230718 Forwards IE insp Repts 50-054/79-04 & 70-0687/79-04 on 790921-24 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 MARTIN.W G Region 1, Philadelphia, Bafeguards Branch. 79/11/02
- --8010230719 IE Insp Repts 50-054/79-04 \$ 70-0687/79-04 on 790821-24 Noncompliance noted alarm sys, hot cell manipulators & unlocked doors Details withheld (ref 100FR2,790).
 BAILEY,R J Region 1, Philadelphia, Office of the Director.
 DEVLIN,J W Region 1, Philadelphia, Safeguards Branch 79/10/23
- B010200638 Forwards encl to B00817 ltr. "Union Carbide Medical Products Div Request for Exemption Per 100FR73,800718." Encl withheld (ref 100FR2 790) VOTH-M H Union Carbide Corp 80/08/15 ig
- 8010020170 Nobifies that no add1 fee is required for 80080A revision to Amend MPP-3 to License SNK-639. MILLER.W O License Fee Management Branch 80/09/15 ip

HOCKET 70-0698 WALTZ MILL SITE, WESTINGHOUSE ELECTRIC CORP.

- 0100103B9 Forwards IE Insp Rept 70-0698/80-01 on 800602 & 05. No noncompliance noted KINNEMAN, J D Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/01 2pp
- --8010010395 IE Insp Rept 70-0698/80-01 on 800602 & 05, No noncompliance noted Major areas inspected scope of activities, decommissioning activities, liquid effluents, hot lab activities & waste handling COBTELLO,F. Region 1, Philadelphia, Office of the Director KINNEHAN, J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/31 3pp
- 8010010471 Forwards draft of NRC interim guidelines for preparing environ info for nuclear facilities, to assist licenses in preparing info necessary for renewal of license, Requests date by which necessary info will be transmitted.

 CROW, W. T. Uranium Fuel Licensing Branch 80/09/18, App

DOCKFT 70-0734 GENERAL ATOMIC CO

- 8010200269 Discusses omission to NRC 800717 summary of 800715 meeting re upgrade rule implementation. Security plan covering Category I facility will be submitted Aug 1980. Alternative plan re decommissioning will be developed WELLHOUSER: H. N. General Atomic Co. (subs. of Guif Cil Co.). 80/08/01 2pp
- 8010070627 Responds to 800801 itr re upgrade rule. Application of measures to meet rule intent must meet level of protection required by programmed implementation dates. Rule should be met by 810320 or 90 days after security plan approval. SURNETER.F. Office of Nuclear Material Bafety & Safeguards, 80/08/20 Rpp.

- 8010060094 PNO-V-80-064A on 800809, container of UC-ThC exploded Miss wipes of four employees in vicinity indicated some internal deposition may have occurred Lung counts indicated no thornum lung deposition THOMAB.R.D., CQQLEY.W J Region 5, San Francisco, Office of the Director 80/08/22 2pp.
- 8010180089 Advises of NRC plans for raview of revised fixed sits physical protection submittal HCCORKLE, G. W. Physical Security Licensing Branch 80/09/02 Is
- B010090524 Requests facility tour for BL Davis for completion of the contracted research rept, "Behavioral Observation Program to Assura Continued Reliability for Employees" MCGORKLE, O W Physical Security Licensing Branch 80/09/04 is
- 8010200096 Notifies that OA Co will continue security upgrade rule implementation plan development & discontinue decommissioning plans PSC of CU approved reload segment 10 mfg continuation HELLHOUSER: H N General Atomic Ca (subs of Gulf Dil Co) 80/09/05. 19
- 8010130086 Requests revisions to 800821 physical protection program C s to broad scope, ofc was unable to conduct meaningful review Major areas require extensive revision Blueprints must be provided re capital improvements. DURNETT, R F Division of Sefeguards 80/09/19 2pp
- 8010140078 Forwards IE Insp Rept 70-0734/80-07 on 800908-12 No noncompliance noted Major areas inspected program for controlling & accounting for SNM Encl withheld (ref 10CRR2 770)
 NORDERHAUO.L R Region S. San Francisco, Safeguards Branch-80/10/02 16
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 8010Zi0174 Submits semiannual effluents release monitoring results for License SNM-960 from Jan-June 1920 Rept includes activities conducted under state buproduct source matl license GEST/R E. Oeneral Electric Co. 80/08/19, ip
- 8010270371 Forwards IE Insp Rept 70-0754/80-04 on 800707-10 No noncompliance noted 800K/H E Region 5, San Francisco, Fuel Facility & Moterials Safety Branch 80/08/26 2pp
- --8010270373 IE Insp Rept 70-0754/80-04 on 800707-10 No noncompliants noted Major areas inspected, organization mode to facilities & sys, internal review & audit, employee training & environ programs.

 COOLEY, N. J., THOMAB, R. D., BODK, H. E., Region 5, San Francisco, Fuel Facility & Materials Safety Branch, 80/08/25, 10pp.
- 8010090521 Requests facility tour for BL Davis for completion of)다. contracted research rept. "Behavioral Observation Program to Assure Continued Reliability for Employees " MCCOPKLE, O W Physical Security Licensing Branch 80/09/04 1;

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8010230194 Summary of 800529 meeting w/United Nuclear Corp Recovery Bys Div in Silver Spring MD re decommissioning program EMEIOH.C. IJ Material Control Licensing Branch 80/06/13 9ps
- 8010010611 Forwards IE Insp Rept 70-0820/80-09 on 800625-26 No noncompliance noted 8MITH.Q H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/29 2pp
- --80:001:0617 IE Insp Rept 70-0820/80-09 on 800628-26 No noncompliance noted Major areas inspected startup of new lagoon waste disposal process
 KINNEY, W N Ragion 1, Philadelphia, Office of the Director, STEVENSON, R. L., CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/28 4pp.
- 8010010388 Forwards IE Insp Rept 70-0820/80-10 on 800728-31. No noncompliance noted.
 MARTIN.W. G. Region 1, Philadelphia, Bafeguards Branch BO/08/13

- --8010010390 IE Insp Rept 70-0820/80-10 on 800728-31 No noncompliance noted Major areas inspected access control, detection aids, response controls, communication eys, testing & maint & BNM protection SMITH, 9 Region 1, Philadelphia, Office of the Director. DEVLIN, J W Region 1, Philadelphia, Safeguards Branch, 80/08/14, 1p
- 8010100274 Approves of 800624 request for exemption from requirement to submit revised Category I security plan Consideration based on reduced strategic SNM inventory rationals provided in request & adequacy of security plan protective measures BURNETT, R F Division of Bafeguards 80/08/21 2pp
- 8010230141 Forwards IE Insp Rept 70-0820/80-11 on 800707-08 & 0801 No noncompliance noted SMITH:0 H Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/23 2pp
- --8010230148 IE Insp Rept 70-0820/80-11 on 800707-08 & 0801 No noncompliance noted Major areas inspected water & solids samples from selected monitoring walls & all operating lagons CROCKER, HW Region i, Philadelphia. Fuel Facility & Materials Safety Branch ROTHJ Region i, Philadelphia, Office of the Director 80/08/22 5pp
- 8010010330 Ack receipt of 800728 itr informing NRC of steps taken to correct violations noted in IE Inep Rept 70-0820/80-08, EMITH: 0 H Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/08/27, 2pp
- --8010010336 Responds to NRC 800701 itr re violations noted in IE Insp Rept 70-0820/80-08. Corrective actions. Authorization RO 277, posted identifying safety limit for storage of fissile matl. BOMERS, C.E. United Nuclear Corp. 80/07/28. 2pp
- --B010010340 Forwards IE Insp Rept 70-0820/80-08 on 800602-05 & notice of violation SMITH, O. H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 80/07/01 2pp
- --8010010342 Notice of violation from insp on 800602-95.

 * Region i, Philadelphia, Office of the Director. 80/06/30 ip
- --8010010347 IE Insp Rept 70-0820/80-08 on 800402-05, Noncompliance noted failure to post proper nuclear criticality safety limit in warehouse for storage of fissile matl in inner containers from UNG-2000 containers
 KINNEY, II W Region I, Philadelphia, Diffice of the Director, CROCKER, H W Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/06/30 lipp
- 8010060165 PND-1-80-124, samples from test wells in close proximity to effluent waste lagoons have shown presence of byproduct math radionuclides Average concentrations are less than 10% 10CFR20 limits except for 8r-90 which is 40% KINNEY,W W. CRUCKER.H.W. SMITH.O.H. Region 1, Philadelphia, Office of the Director 80/08/28 2pp
- 6010150548 Forwards partial modified fundamental nuclear math control plans applicable to decommissioning efforts Bubmittal will be completed wk of 800901 License fee not required because nuclear math control program effectiveness not decreased GREGO.R J United Nuclear Corp , UNC Recovery Systems Div 80/08/29.
- 8010240277 Forwards IE Insp Rept 70-0820/80-12 on 800812-15. No noncompliance noted.

 MARTIN, W O Region 1. Philadelphia, Bafeguards Branch 60/09/08 2pp
- --8010240284 IE insp Rept 70-0820/80-12 on 800812-15. No noncompliance noted Major areas inspected measurements of BNM in waste discards & facility holdup of BNM Details withheld (ref 10CFR2 790)

 JOYNER, J H Region 1, Philadelphia, Bafeguards Branch CDHEM, I , ZIBULBKY, H Region 1, Philadelphia, Defice of the Director 80/09/05 1p
- B010150114 Forwards FR notice re establishment of LPDR for proposed decommissioning of facility FELTON, J M Division of Rules and Records. 80/09/16 ip
- --BOi0180119 Notice of establishment of LPDR for proposed decommissioning of facility FELTON.J M Division of Rules and Records. BO/09/16 2pp

- 8010020046 Forwards revision of Sections 1 0-8 0 of Amend MPP-2 to License SNM-7/7/modifying mati control & accounting program PARTLOW, J. 0 Material Control & Accountability Development Branch 80/09/19 1p
- --B010020053 Revised Sections i O-B O of Amend MPP-2 to License-777, modifying math control & accounting program

 4 Material Control & Accountability Dayslopment Branch 80/09/19.
- 801014019B Responds to 800723 ltr re 8r-90 contamination at facility. 8r-90 came from processing U from nuclear excursion & low power experiments in conjunction w/naval reactor program. Facility will be required to decontaminate to NRC criteria CRDW.W.T Uranium Fuel Licensing Branch 80/09/19, 2pp
- --B010140202 Matl/Byproduct License BNM-777, Amend 19, allowing recovery of BNM from space reactor components, as described in 660329 application
 MCBRIDE, J A Atomic Energy Commission. 66/05/05 19
- --B010140208 Requests temporary approval for recovery of SNM from spare reactor components. Flow diagram deemed proprietary & is withheld (ref 100FR2 790) CRONIN.D F. United Nuclear Corp. 66/03/29, 2pp
- --8010140213 Submits info requested in NRC 660411 telegram re recovery of SNM from spare reactor components CRONIN,D F. United Nuclear Corp. 66/04/13. 1p.
- --B010140221 Amend 33 to Matl/Byproduct License ENM-777.authorizing processing of enriched U.described in 670529 application MGBRIDE, J.A. Atomic Energy Commission. 67/06/15, 1p
- --8010140224 Requests ARC concurrence that Amend 19 to License SNM-777 would parmit processing of similar math utilizing same health & safety considerations CRONIN.D F. United Nuclear Corp 67/05/29. 1p.
- --8010140228 Amend 43 to License SNM-777 & Amend 77 to License SNM-368, authorizing possession & use of SNM in specified areas NUSBBAUMER.D A Atomic Energy Commission 80/06/17. 3pp
- --8010140233 Discusses reorganization of Neval Products Div & Commercial Products Div activities under Licenses SNM-368 & BNM-777. Revised sections of each license encl LINDFERG. J A United Nuclear Corp 68/06/10. 3pp
- 8010210795 Notifies that physical protection plan will remain in effect until enriched U holdings are confirmed by IE Matls must consist of resins k residues awaiting shipment or unpackaged waste in lagoons Revised security sys must be maintained.
 BURNETT,R F Division of Safeguards. 80/09/23, 2pp
- 8010220206 PND-I-B0-1398:on 801003; re-shipment of low level waste w/ leaking drum Leaking drum & box repackaged for shipment to licensee. State of RI has requested NRC to increase insp of licensee activities KINNEY.W W , CROCKER.H.W . BMITH.Q.H. Region 1; Philadelphia, Office of the Director. B0/10/03 2pp
- DOCKET 70-0824 BABCOCK & WILCOX CD
- 80:10090527 Forwards Revision 1 to Page 7.1 of 800320 security planspermitting 30 days for submission of NRC/DQE-741 form to shipper.U/o encl.

 OLSEANA F Babcock & Wilcox Co. 80/08/08. ip.
- 80:015063B Forwards JA Lynott & RA Jolliff 800618 certificates for FY79 b FY80-providing financial assurance for payment for decomissioning costs JORDAN: L V Babcock & Wilcox Co. 80/09/02. 4pp.
- 8010200253 Forwards replacement pages to Bidg C security plan per NRC 800811 recommended changes, Encl withheld (ref 10CFR2, 790) OLSEN: A F. Babcock & Wilcox Co. 80/09/02, ip.
- 8010210R83 Forwards certificates of assurance attesting that company has met all restrictive covenants contained in promissory note agreements re decommissioning activities & can meet financial obligations

 JDRDAN.L.V. Babcock & Wilcox Co. 80/09/02 4pp.
- 8010090509 Forwards revision to License SNM-778.Amend MPP-1.adding Bection 12.physical protection requirements for SNM of low strategic significance MCGORKLE.O W Physical Security Licensing Branch. 80/09/17. 2pp

- g010020372 Requests that listed endorsements & signed indemnity agreemants or amends to indemnity Agreement Q-i be provided DINITZ.I Utility Finance Branch (formerly Antitrust & Indemnity) 80/09/24 | Ip
- 8010140142 Notifies that Endorsements 3.4.6-13, 16.18, 20-26, 28-40, 43-48, 50-32, 55-62, 65.66, 68, 70-74 & 79 to Policy NF-11 & all endorsements to Policy NF-85 have not been received DINITY. I Utility Finance Branch (formerly Antitrust & Indemnity) BO/09/24 1p

DOCKET 70-0882 COLUMBIA UNIV

- B010170095 Application for renaval of License 5NM-870 Supporting documentation each LORIG.P.M Columbia Univ B0/08/25 14pp
- DOCKET 70-0925 CIMARRON FACILITY, MERR-HOBEE CORP.
- 8010020219 Responds to IE Bulletin 80-15 re loss of emergency notification sys w/loss of offsite power. Emergency notification sys is powered by onsite power Util expended 14 membours on bulletin SHELLEY.N J Kerr-McGee Nuclear Corp 80/09/15 4pp
- 8010210620 Forwards Table I. "Radioactivity in Cassous Effluent." re release of SNN in effluents to unrestricted area during first half of 1980 per App B of Reg Guide 1 21 & 10CFR70 59
 SHELLEY.U J. Kerr-McGee Nuclear Corp. 80/09/26 3pp

DOCKET 70-1048 FLORIDA, UNIV OF

B010090490 Requests amend to License SNM-1050, extending expiration date to 851221 & authorizing storage of SPERT fuel in concrete bldg adjacent to facility rather than metal Quonset hut DIAZ,N J, CARROL,E E Florida, Univ of, Gainesville 80/07/15

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

- 80100104)6 Forwards outline of planned actions re insp findings Encl withheld (ref 10CFR2 790) ORIER,B H Region 1. Philadelphia. Office of the Director. 80/08/25 1p.
 - 10200359 Forwards IE Insp Rept 70-1100/60-08 on 800821 re meeting to discuss nuclear mat1 control & accountability program at facility Details withheld (ref 10CFRZ 790) ORIER,8 H Region 1. Philadelphia. Office of the Director 80/09/12 ip
- --B010200361 IE Insp Rept 70-1100/80-08 on 800821 re mpt meeting to discuss corrective actions concerning imbalance between book records & physical inventory records re item control areas. Details withheld (ref 10CRR2 790).

 CDHEN-I Region 1: Philadelphia: Office of the Director.
 JOYNER-J H Region 1: Philadelphia: Safeguards Branch 80/09/11
- IOIO210203 Summary of 600925 meeting w/C-E in Silver Spring,MD reproposed request for amond to License GNM-1067 for possession 5 packaging of U.S. thorium waste discovered in wooded area on C-E site in Windsor.CT
 KETZLACH.N: Uranium Fuel Licensing Branch. 80/10/01 2pp

DOCKET 70-1113 GENERAL ELECTRIC CO

- 8010060027 Forwards physical security plan for License SNM-1097.Plan withheld fref 10CFR2 790)
 KAPLAN, A L. General Electric Co., Nuclear Energy Products Div B0/05/16 ip
- 8010150580 Responds to GE 800611 ltr re-application for Amend A-8 for warehouse bldg const Fundamental nuclear math control plan must be modified prior to SNM storage PARTLON-J Q Material Control & Accountability Development Branch 80/08/12 ip
- 3010200258 Discusses minutes of 800811 meeting w/GE,NRC & Science Applications, Inc in Wilmington, NC re GE fuels plant mods preliminary questions & supporting info to License SNM-1097 amends DONELSON, S E, Science Applications, Inc. 80/08/20 3pp

- 8010220456 PNO-II-80-142 on 800822, truck loaded w/five full OR-308 y haxafluoride cylinders was forced off I-85 near Oreensborg, NC Truck did not everturn No damage to cylinders & no personnel injuries CORYELL, O P., KENNA, W.B. Region 2, Atlanta, Office of the Director 80/08/22 1p
- 80i0i50ii5 Forwards semiannual effluent rept for Jen-June 1980 KAPLAN, A. General Electric Co., Nuclear Energy Products Div 80/08/29 2pp
- B010090278 Trip rept for 800811 visit to facility w/Science Applications Inc re environ review of licensing amends on installation & use of incinerator & major plant expansion SHUM.E Y Uranium Fuel Licensing Branch B0/09/03 ip
- 8010090157 Submits revisions to fundamental nuclear matl control plan for fuel fabrication facility in Wilmington,NC Info should be withheld (ref 10CFR2 790) # Owneral Electric Co , Nuclear Energy Products Div 80/09/09 ip.
- B010020606 Amend 15 to License BNM-1097, adding new storage bldg Safety evaluation encl PAGE, R G Uranium Fuel Licensing Branch 80/09/11 1p
- --8010020612 Safety evaluation supporting Amend 15 to License BNM-1097, adding new storage bldg Proposed storage can be used w/o undue risk to health 8 safety STEVENBON.R L , CROW.W T Uranium Fuel Licensing Branch BD/09/11 2nd
- BO10230131 Forwards IE Insp Rept 70-1113/80-16 on B00908-12 No noncompliance noted Details withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta, Safeguards Brench 80/10/03 2pp
- ---8010230137 IE Insp Rept 70-1113/80-16 on 800908-12.No noncompliance noted Details withheld (ref 10CFR2 790) KAHLE, J B., HODDES, J. W. Region 2, Atlanta, Bafeguards Branch 80/10/03 1p
- B010310307 Notifies that Waste Package Insp Rept 15000037/80-12 does not contain proprietary info KAPLAN.A L. General Electric Co., Nuclear Energy Products Div B0/10/07. ip

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 8010240095 Forwards IE Insp Rept 70-1143/80-12 on 800812-14 No noncompliance noted MARTIN.U G Region 1, Philadelphia, Safeguards Branch 80/08/29, 200.
- --8010240104 IE Insp Rept 70-1143/80-12 on 800812-14. No noncompliance noted Major areas inspected security organization, physical barriers, response controls & central alarm & communication sys. Details withheld (ref 100FR2 790)
 DEVLIN, J W. Region 1, Philadelphia, Bareguards Branch LADUN, R Region 1, Philadelphia, Defice of the Director 80/08/28, 1p
- 8010140068 Ack receipt of 800229 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1143/79-06 MARTIN, W. G. Region 1. Philadelphia, Bafeguards Branch 80/09/15
- --8010140072 Responds to NRC 800206 ltr re violation noted in TE Insp Rept 70-1142/79-06 Corrective actions withheld (Ref 10GFR2 770) HODRE J B Westinghouse Electric Corp 80/02/29 ip
- ---B010140084 Forwards IE Insp Rept 70-1143/79-06 on 791011 & 25 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 MARTIN.W 9 Region 1, Philadelphia, Safeguards Branch B0/02/06
 20n
- --8010140090 IE Insp Rept 70-1143/79-06 on 791011 & 25 Noncompliance noted: in shipment of Pu oxide to DDE plant on 791010, one container was understated by approx 100 g Pu. WUBINER. H L. Region i. Philadelphia, Office of the Director JDYNER. J H Region i, Philadelphia, Safeguards Branch 80/01/30 to.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

9005120223 Forwards Waste Packaging Inep 80-03 on 800227-29 No noncompliance noted. STORN,J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/20 2pp

- --B005120230 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected placarding requirements, radiation levels, marking & labeling requirements for packages
 POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/03/17 7pp
- 8008060175 Forwards Waste Packaging Insp Rept 15000039/80-07 on 800315 & 16 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/06/23 2pp
- --8008060179 Waste Packaging Insp Rept 15000039/80-07 on 800515 & 16 No noncompliance noted Major areas inspected/compliance w/NRC & BOT regulations TROUP.0 L. Region 2. Atlanta, Fuel Facility & Naterials Rafety Branch 80/06/23 6pp
- B010070164 Requests NRC approval for Hestinghouse to amend License SNM-1107 per 10CFR70 14 granting relief from 10CFR78(1) provisions & permitting contaminated low enriched scrap accumulation for period not exceeding Aug 1981 FQSTER, H Westinghouse Electric Corp , FWR Systems Div 80/07/21 in
- 8010060082 PNO-II-80-133 on 800731, conversion area of plant evacuated when minor U hexafluoride leak accurred No personnel exposed to excessive concentrations of airborne U & no radioactive mat1 released to environ KAHLE, J B , KENNA, W B Region 2, Atlanta, Office of the Director 80/07/31 1p
- 8010060157 PNO-II-80-195 on 800801, small U hexafluoride release occurred during line venting operation About 50 personnel evacuated that area of plant No radioactive matl released to environ CORVELL, GP, KENNA, W. B Region 2, Atlanta, Office of the Director 80/08/04. 1p
- 8010200287 Submits effluent monitoring results for Jan-June 1980 ODDHIM N L Westinghouse Electric Corp., PWR Bystems Div 80/08/07 2pp
- BOIG160424 Forwards annual review update to emergency plan FIGHER, R E Westinghouse Electric Corp. 80/08/14 1p
- --8010140427 Revision i to emergency plan

 # Westinghouse Electric Corp 80/04/30 17ap
- 8010090221 Forwards IE Insp Rept 70-1151/80-22 on 800729-0801 No nuncompliance noted KENNA-W B Region 2, Atlanta, Safeguards Branch, 80/08/20 ij
- --8010090227 IE Insp Rept 70-1151/80-22 on 800729-0801. No noncompliance noted Major areas inspected operations, facility changes & mods, safety committees, training & review of nonroutine events
 CORYELL, O P , TILLMAN, A Region 2, Atlanta, Office of the Director KAHLE, J B Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/08/19. 4pp
- --8010070235 Forwards survey results of scrap molybdenum at Westinghouse Nuclear Fuel Division plant prior to release for unrestricted use STOMR.J P Region 2. Atlanta. Fuel Facility & Materials Bafety Branch 80/07/29 3pp
- 8010150221 Revises Amend MPP-1 to License 8NM-1107.adding Section 12. "Physical Protection Requirements for BNN of Low Strategic Significance" Implementation requested by 800921 MCCORKLE.Q.W Physical Security Licensing Branch 80/08/25 2pp
- 8010200197 Forwards Columbia Fuel Fabrication Facility 800515 manual, "Bite Physical Security Plan," Revision 1, including 8NM shipment handling measures & radiation monitoring Manual withheld (ref 100FR2 790)
 DIPIAZZAR P Westinghouse Electric Corp., PWR Bystems Div 80/09702 ip
- 8010310055 Forwards Waste Packaging Insp Rept 15000039/80~15 on 800727-0801. No noncompliance noted. STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/09/19 2pp
- --8010310068 Waste Packaging Insp Rept 15000039/80-15 on 800727-0801. No noncompliance noted Major areas inspected; shipping paper, DQT placarding, radiation levels, removable contamination & prohibited articles or contents MACARTHUR, T.C., POTTER: J P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/09/16 Bpp.

- 8010220034 Forwards proprietary IE Insp Rept 70-1151/80-25.un 800902-04 & nonproprietary insp summary No noncompliance noted Rept withheld (ref tOCFR2 790)
 KENNA:W B Region 2. Atlanta: Safaguards Branch 80/09/29 ip
- --8010220038 Nonproprietary insp summary IE Insp Rept 70-i151/80-25 No noncompliance noted Major areas inspected measurement program including solid measured discards & replicate measurements Details withheld (ref iOCFR2 790) BATESIJW, KAHLEJJ B Region 2. Atlanta, Safequards Branch 80/07/26 ip
- 8010310313 Ack receipt of 800918 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/80-20 KENNA:W B Region 2. Atlanta. Safeguards Branch 80/10/21 lp
- --B010310319 Responds to NRC B00829 ltr re violations noted in IE Insp Rept 70-1151/B0-20 Corrective actions withheld (ref 106782 790) G0DBHIN.W.L. D'AMDRE,M. Westinghouse Electric Corp. 80/09/18
- --8010310322 Forwards IE Insp Rept 70-1151/80-20 on 800721-25 & notice of violation Natice of violation withheld (ref 100FR2 790), KENNA, W B Region 2, Atlanta, Safeguards Branch 80/08/29 2pp
- --B010310340 IE Insp Rept 70-1191/80-20 on B00721-25 Noncompliance noted failure to establish, maintain & follow sys for measurement of all SMM Details withheld (ref 10CFR2 770) BATES, J W. Region 2. Atlanta, Office of the Director GILLEBPIE, F P. Region 2, Atlanta, Safeguards Branch B0/08/29 ip
- DOCKET 70-1192 KERR-MCGEE NUCLEAR CORP
- BO10210620 Forwards Table 1, "Radioactivity in Cassous Effluent." re release of SNH in effluents to unrestricted area during first half of 1980 per App B of Reg Quide 1 21 & 10CFR70 59

 SHELLEY.W J Kerr-McQue Nuclear Corp 80/09/26, 3pp.
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE GORP.
- 8010090531 Advises that present security plan complies w/Upgrade Rule requirements
 8H6LLEYW J Kerr-McGee Nuclear Corp 80/08/11 1p
- 8010100265 Approves 800811 request for exemption from requirement to submit revised physical security plan BURNETT-R F Division of Safeguards 80/08/21, 1p
- 8010020219 Responds to IE Bulletin 80-15 re loss of emergency notification sys w/loss of offsite power. Emergency notification sys is powered by onsite power Util expended 14 manhours on bulletin SHELLEY. IJ Kerr-McGee Nuclear Corp 80/09/15 4pp
- 8010100025 Forwards new license conditions for License SNK~1174, Amend MPP-3, re termination plans Accountability program needs to be strengthened Termination plans in 800108 ltr will be withheld (ref 10CFR2 790) MARTLOH, J O Material Control Licensing Branch 80/09/22 5pp
- DOCKET 70-1201 UF & CONVERSION FACILITY. BABCOCK & WILCOX CO
- 8010060029 Advises that no addi fee required for Amend 13 to License 8NM-1168 issued on 800701 MILLER, W O License Fee Management Branch, 80/08/05, lp.
- 8010170059 Forwards effluent monitoring results from Jan-June 1980 ZEFF, D W Babcock & Wilcox Co 80/08/20 2pp.
- 8010150695 Forwards JA Lynott & RA Jolliff 800618 certificates for FY79 & FY80: providing financial assurance for payment for decomplisioning costs
 JORDAN: L V Babcock & Wilcox Co 80/09/02 4pp
- 80:02:10:283 Forwards certificates of assurance attesting that company has met all restrictive covenents contained in promissory note agreements re decommissioning activities & can meet financial obligations

 JORDAN-L V. Babcock & Wilcox Co. 80/09/02 4pp

- 8010030145 Forwards IE Insp Rept 70-1201/80-01 on 800819-21 No noncompliance noted KENNAN B Region 2, Atlanta, Safaguards Branch 80/09/16 2pp
- --B010030151 IE Insp Rept 70-1201/80-10 on 800819-21 No noncompliance noted Major areas inspected-measurement control program & independent insp effort Details withheld (ref 10CFR2 790) BATES, J W Region 2, Atlanta, Office of the Director KAMLE, J B Region 2, Atlanta, Safeguards Branch 80/09/15 ip
- DOCKET 70-1257 MIXED DXIDE FABRICATION PLANT, EXYON NUCLEAR CO , INC
- 8010090508 Forwards plan for physical protection of ENN of low strategic significance H/G encl HANBENLE Erxon Nuclear Co , Inc (subs of Exxon Corp) 80/05/16 ip
- 8010070635 Confirms 800807 meeting results re licensee actions to opgrade physical protection program Submission date extension to 801231 granted Pu disposition contingency plan should be developed BURNETTR F Office of Nuclear Material Safety & Safeguards 80/08/18 2pp
- 8010080266 Forwards NUREO-0722, "Effects of Natural Phenomena on Exxon Nuclear Co Mixed Dride Fabrication Plant at Richland.WA" APR.JE, BURKHART, W. Advanced Fuel & Spent Fuel Licensing Branch 80/07/12 ip
- --B010080272 Forwards NUREC-0722, "Effects of Natural Phenomena on Exxon Nuclear Co Mized Oxide Fabrication Plant at Richland, WA" ROUSE, L. C Advanced Fuel & Spent Fuel Licensing Branch 80/09/12
- --8010080276 "Effects of Natural Phenomena on Exxon Nuclear Co Hixed Oride Fabrication Plant at Richland WA " « Office of Nuclear Material Safety & Safeguards NUREG-0722 80/09/30 55pg Available at NTIE
- 8010150620 Forwards increment of analysis of effects of natural phenomena entitled "Environ Consequences of Postulated Pu Releases from Erzon Nuclear Mixed Orice Fabrication Plant, Richiand, MA, as Result of Severe Natural Phenomena "ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/09/12
- --BoloiSOA26 Forwards "Environ Consequences of Postulated Pu Releases from Erron Nuclear Mixed Oxide Fabrication Plant.Richland, MA: as Result of Severe Natural Phenomena "Recommends endorsement of rept as staff position AVER.J E , BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch E0/09/12 1p
- --8010150528 "Environ Consequences of Postulated Pu Releases from Exxon Nuclear Mised Oxide Fabrication Plant.Richland.WA.as Result of Savers Natural Phenomena " JAMISON.J D. WATSON.E C. Battelle Memorial Institute, Pacífic Northwest Laboratory FNL-3315 80/02/28 70pp
- 801015004B Forwards corrected Page 1 for "Risk Analysis of Postulated Fu Releases from Erxon Nuclear Mixed Oxide Fuel Plant as Result of High Wind & Earthquakes." in response to Vendor 800709 observation Dose calculation is still valid AYER.J E Advanced Fuel & Spent Fuel Licensing Branch 80/09/23 is
- --8010150078 Revised Page 1 to "Risk Analysis of Postulated Pu Releases from Exxon Nuclear Mixed Gride Fuel Plant as Result of High Wind & Carthquakes " * Battelle Memorial Institute, Pacific Northwest Laboratory 60/09/23
- 8010140061 Forwards IE Insp Rept 70-1237/80-06 on 800819-20 No noncompliance noted Major areas inspected examination of activities re physical protection against industrial sabotage & theft of SNM Encl withheld (ref 10GFR2 790) NORDERHAUO, L. R. Region 5, Ban Francisco, Safeguards Branch 80/10/01 2pp
- 8010230134 Trip rept re 800922 visit to Region 5 ofc & 800923 visit to facility re environ review on current license renewal action SHUM: Y Uranium Fuel Licensing Branch. 80/10/01 ip
- 8010270224 Forwards comments & questions re environ info submitted in connection w/license renewal application. Requests responses by 801115
 SHUM.E Y Uranium Fuel Licensing Branch 80/10/08 6pp.

- 8010300546 Forwards comments & questions re environ info submitted in support of renewal of License SNM-1227 SHUM, E.Y. Uranium Fuel Licensing Branch 80/10/08 App
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- 8010100093 Informs of no change in status of fuel stored at facility in May 8 June Current status table encl DAMBON.D M General Electric Co 80/07/02 2pp
- B010190572 Forwards specific exemptions for matls & plant protection Amend MPP-3, dtd 791106. & administrative action fee for Amend request W/o encl DANSON.D M General Electric Co , Nuclear Energy Product* Div B0/08/05 1p
- 8010140158 Summary of 800731 site visit to observe facility changes
 Cask receiving area has been enci-pump room addition was
 under constructive & support sys has been installed &
 fluorine bidg equipment has been removed Svc list encl
 CLARK.A T Advanced Fuel & Spent Fuel Licensing Branch
 400
- BD1017004B Forwards revised description of compressed air sys at facility Distribution list encl
 DANSON, D K General Electric Co 80/08/25 3pp
- 8010070533 Notion for order setting aside summary disposition schedule outlined in ASL8 600909 order Intervenors may review contentions following NRC safety evaluation rept Certificate of Svc encl
 BACHTANN.R 0 Hearing Branch 1 80/10/03 4pp
- BO10130990 Request for order dismissing intervenors Rorem et al from proceeding due to failure to comply w/discovery Intervenor failed to answer 800719 interrogatories per ASLB-800909 order Certificate of Svc encl Related correspondence SWAJKOWSKI,R W . RUDNEY,M A General Electric Co 80/10/09 5pp
- 8010170357 Requests that Contentions 1 through 5 be dismissed due to State of IL failure to respond to discovery requests, despite ASLB orders Certificate of Svc enr! SZHAJMONEKI.R, ROGNEY, MA General Electric Co SZHAJKONEKI.R Mayer. Brown & Platt 80/10/13 4pp
- 8010210279 Petition for institution of hearing re license amend & consolidation w/pending hearing re license renewal States right of intervention b urges that parties in renewal proceeding be allowed to intervene Certificate of Svc encl SEKULER. S N , FAHNER. T C lilinois, State of 80/10/15 7pp
- 80(0210282 Motion to stay renewal of license proceeding until 30 days past effective date of promulgated iOCFR72 Parties are to familiarize themselves w/rule when published in Oct Certificate of Svc encil SEKULER,S N . FAKNER,T C Illinois, State of 80/10/15 App.
- 8010210592 Responds to NRC 801003 motion to set aside schedule for surmary disposition OE will respond within three wks after receipt of new 10CF772 regulations Certificate of Syc encl Related correspondence RODNEY. HA Mayer, Brown & Platt 80/10/15 2pp
- B010240073 Order granting NRC motion to postpone schedule for summary disposition.
 GDDDHGPE.A C Atomic Safety and Licensing Board Panel 80/10/21
- B010270371 Response in opposition to GE motion for sanctions Ruling on motion must be stayed for reasons stated in State of IL 801015 motion to stay proceedings or, alternatively, denied Certificate of Svc encil FAHNER, T C , VRANKEN, J V Illinois, State of 80/10/24 App
- 8010300084 Response in opposition to GE motion to dismiss intervenor as party due to failure to respond to interrogatories. Intervenors do not possess necessary skills & matls to work apace Wother parties Certificate of Syc encl.
 ROREM.B L Affiliation Unknown 80/10/24 Spp

8010300066 Forwards advance copy of new 10CFR72, anticipated for publication in Nav 1980 Licensing renewal proceeding is to continue in accordance w/new Part 72
BACHMANN, R O Hearing Branch 1 80/10/28 1p

- 8010310487 Response in support of State of IL 801015 motion to stay proceedings until 30 days after effective date of 10CFR72 Opposes 0E motions for sanctions against intervenors Rorem et al Certificate of 8vc encl ROTHSCHILD.M U Hearing Branch 1 80/10/29 13pp
- DOCKET 70-1327 UF & CONVERSION FACILITY, ALLIED GENERAL NUCLEAR
- 8010010830 Comments on proposed rule RK 50-5 re NRC termination of efforts on GESMO fuels NRC should resume GESMO proceeding Certificate of Svc & svc list encl
 DECHER, U Affiliation Unknown 80/09/03 7pp
- 8010230281 Comments by TN Technological Univ on rulemaking 50-5 QESMO proceedings should be restarted immediately DEMAS,N O Affiliation Unknown 80/09/11 ip
- 8010230349 Camments on rulemaking 50-5 supports respening of GEBMD proceedings
 LORFING.D Affiliation Unknown 80/09/11 1p
- 8010220540 Comments on rulemaking 50-5 NRC should not reopen GESMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to US nonproliferation policy
 MCLAUGHLIN.W T Affiliation Unknown 80/09/12 ip
- 8010230265 Comments on rulemaking 80-5 GESMO proceedings should be resumed
 HACKNEY, C A Affiliation Unknown 80/07/12 ip
- 8010230341 Comments on rulemaking 50-5 GESMO proceedings should be reopened LOPEZ.C R Affiliation Unknown 80/09/12 1p
- 8010020699 Recommends GEBMO proceedings be completed Technically competent people evailable to complete GEBMO project Further delay in proceedings will increase energy costs GEBMO will provide basis for future decisions re spent nuclear fuel MURRAY, H Affiliation Unknown 80/09/13 ig.
- 8010230328 Comments on rulemaking 50-5 GEBMO hearings should not be reopened due to problems w/reprocessing Health hazards associated w/transport & reprocessing shown to be more serious than previous expectations

 CLEMENTB.T Affiliation Unknown 80/09/13 ip
- 8010220518 Comments on rulemaking 50-5 GESMO hearings should resume immediately BARRY.D Affiliation Unknown 80/07/14, 1p
- 8010230317 Comments on rulemaking 50-5 GEBMD proceedings should not be respense
 TUCKER.C A Affiliation Unknown 80/07/14 ip
- 8010230323 Comments on rulemaking 80-5 re resuming CESMO proceedings CMUSB,W Affiliation Unknown 80/09/14 3pp
- 8009220237 Comments on rulemaking 50-5:0ESMO proceedings should be resumed & completed Reprocessing & recycle of LUR fuel should be considered TSOULFAMIDIS.N Affiliation Unknown 80/09/15 ip
- 8010230231 Comments on rulemaking 50-5 GEBMO proceedings should be resumed Delays will not serve nath security & will increase cost of energy COURTNEY.J C Application Unknown 80/09/15 1p
- BO10230247 Comments on rulemaking 50-5 Commission should reopen GESMO proceedings
 BARRY, J E Affiliation Unknown BO/07/15 ip
- B010230291 Comments on rulemaking 50-5 GEBMO hearings should be reopened JONES, W. Affiliation Unknown B0/09/15 1p
- B010220529 Comments on rulemaking 50-5 supports resumption of GEGMO proceedings CREIBZENSKI,P Affiliation Unknown 80/09/16 ip.
- BO10220663 Comments on rulemaking 50-5 GEBHO proceedings should be respended Draft article encl which should have some input in forming policy on recycling Pu.

 DEYAR. Citizens United for Responsible Energy. 80/09/17 9pp.

- 8010230304 Comments on rulemaking 50-9 GESMO proceedings should be resumed US should do everything to minimize use of foreign oil C. satend U reserves by reprocessing of spent fuel PANZANTIF A Affiliation Unknown 80/09/17 Ip
- 8010020019 Comments on reopening of GESMO proceedings re Rulemaking 50-5 reopening b successful completion of hearing is logical precedent to commercial reprocessing of spent nuclear fuel GIBBS, D C Affiliation Unknown 80/07/23 2pp
- 8010020690 Recommends resumption of QESMO proceedings Persian Gulf area warfare necessitates tochnical development of spent reactor fuels to lessen dependence on imported oil tARMICK.E.F. Affiliation Unknown 80/09/23 ip
- 8010020012 Comments by two citirens in support of reopening of GESMO proceedings re Rulemaking 50-5 further consideration needed for energy development BREITMAYER, F Affiliation Unknown 80/09/24 2pp
- 80100206B2 Forwards constituent comments on GEBMO proceedings Requests status of NRC intentions re-proceedings MODRE, W.H. House of Rep., Hays and Means 80/09/24 3pp
- 8010020005 Comments on reopening of GESMO proceedings re Rulemaking 50-5 continuation of review process needed to determine whether reprocessing & recycling is viable option DRAPER.E L. Guif States Utilities Co. 80/09/25
- B0100200B1 Comments on reopening of GEBHD proceedings re Rulemaking 30-5 hearing must be reopened promptly due to need for establishing legal & logical basis for evaluation of spent fuel reprocessing BEHNKE, W B Commonwealth Edison Co 80/09/25 2pp
- 8010020007 Comments on reopening of GESMO proceedings re Rulemaking 50-5 no further action needed due to completion of evidence THOMAS.R Environmentalists, Inc. 80/07/26 ip
- 8010070264 Comments on rulemaking 50-5 re reopening of OESMO & recycle related proceedings Reopening record will resolve economic, environ & resource questions re fuel reprocessing DISE, D P Niagara Mohawk Power Corp 80/09/26 lp
- 8010010687 Order denying Allied Deneral Nuclear Sycs 800926 request for 60-day extension to respond to Commission 808807 order Untimely comments will be considered only to extent possible CHILK, 8 J. Office of the Secretary of the Commission 80/09/29
- 80100R0001 Forwards comments on reopening of CESMO proceedings re Rulemaking 50-5 reinstitution of hearing reflects UB interest in energy need & will establish framework for timely decisions on reprocessing & recycling HALSKE.C Atomic Industrial Forum 80/09/27 3pp
- 801002065: Comments on rulemaking 50-5 on behalf of 9E6MO Util Group GE6MO proceeding should be reactivated IRWIN, D.P. Hunton & Williams 80/09/29 App
- BO10020663 Comments on rulemaking 50~5.0ESMO proceeding should be rescheduled BURY, D M Capital Legal Foundation BO/09/29 2pp
- 8010020670 Forwards comments on behalf of NRDC on rulemaking 80-5 066MD proceedings should not be reopened WEI89,ER Natural Resources Defense Council 80/09/29 5pp
- B010030479 Views of Westinghouse on NRC 800B07 order re resumption of QEBMD & other recycle-related licensing proceedings Resumption recommended Certificate of Svc encl.

 COMAN, B Z Westinghouse Electric Corp B0/09/29 13pp
- 8010020479 Recommends that NRC reopen QESMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced QLSQN.R E Affiliation Unknown 80/09/30 1p
- 8010030471 Responds to Commission B00807 order requesting comments on reopening of GESMO & other recycle-related licensing proceedings. Proceedings should be reactivated & consistent position on use of energy initiated KEARNEY, J J Edison Electric Institute, 80/09/30 3pp
- 8010160675 Supports resumption of GESMO proceeding as prelude to closure of nuclear fuel cycle.
 MODDY, JH Yankee Atomic Electric Co 89/10/08 2pp

- B010270506 Responds to B00924 ltr transmitting J Courtney request for NRC resumption of GESMD proceedings J Courtney comments will be incorporated into public record to be considered by NRC KAMMERER.C Office of Congressional Affairs B0/10/08 ip
- BOIO150364 Bubmits comments on resumption of GESKO rulemaking on behalf of AZ Public S.c Co.CPLL.Con Ed & WI Electric Power Co Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues QALLO.J Isham. Lancoln & Beale BO/10/10 Spp
- B010200395 Advises of address change from Columbia.SC to Washington.DC & requests records be changed BELSER.T M Belser, Belser, & Baker 80/10/13 ip
- 8010220494 Forwards JC Courtney 800916 ltr requesting that OESMD hearings be resumed LDNO, R Senate 80/10/13 2pp
- 8010030484 Recommends responding of OESMO proceedings CHAMPAGNE, A J Affiliation Unknown 80/09/26 ip

DOCKET 70-1363 AIR FORCE, DEFT OF

8009100371 Forwards IE Circular 80-19, "Noncompliante W/License Requirements for Medical Licensees" No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/26

DOCKET 70-1374 IDAHD STATE UNIV

- 8010270234 Forwards request for add1 info re review of 780423 application for renewal of License SHM-1373. Info needed reseafety program STEVENBON, R.L. Uranium Fuel Licensing Branch 80/10/24 2pp
- DOCKET 70-1406 VET ADMIN HOSP NEW ORLEANS. LA
- 8009100373 Forwards IE Circular 80-19. "Noncompliance W/License Requirements for Medical Licensess " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director. 80/08/26
- POCKET 70-1432 RECYCLE FUELS PLANT, HESTINGHOUSE ELECTRIC CORP
- 1010010830 Comments on proposed rule RM 50-5 re NRC termination of afforts on GESMO fuels NRC should resume GESMO proceeding Certificate of Svc & svc list encl DECMER.U Affiliation Unknown 80/09/03 7pp
- 8010230281 Comments by TN Technological Univ on rulemaking 50-5 GESMO proceedings should be restarted immediately DEMAB.N.O. Affiliation Unknown, 80/09/11 1p
- 8010230349 Comments on rulemaking 50-5. supports reogening of 0EBMO proceedings LORFITUO.D Affiliation Unknown 80/09/11 ip
- B010220540 Comments on rulemaking 50~5 NRC should not reopen 0EBMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to US nonproliferation policy MCLAUGHLIN.W T Affiliation Unknown 80/09/12 1p
- 8010230265 Commants on rulemaking 50~5 GESMO proceedings should be resumed HACHNEY: C.A. Affiliation Unknown 80/09/12 19
- 8010230341 Comments on rulemaking 50-5 GESMO proceedings should be reopened LOPEZ-C R Affiliation Unknown 80/09/12 ip
- B010020399 Recommends OESMO proceedings be completed. Technically competent people available to complete GESMO project Further delay in proceedings will increase energy casts OESMO will provide basis for future decisons re spent nuclear fuel, MURRAY. M Affiliation Unknown B0/09/13 1p.

- B010230328 Comments on rulemaking 50-5 GESMO hearings should not be reopened due to problems w/reprocessing Health hazards associated w/transport & reprocessing shown to be more serious than previous expectations CLEMENTS. T Affiliation Unknown 80/09/13 ip
- 8010220518 Comments on rulemaking 50-5 OESMO hearings should resume immediately BARRY, D. Affiliation Unknown 80/09/14 1p
- 8010230317 Comments on rulemaking 50-5 GESMO proceedings should not be reopened TUCKER.C A Affiliation Unknown 80/09/14 ip
- 8010230323 Communts on rulemaking 50-5 re resuming GESMO proceedings CHUBB,W Affiliation Unknown 80/09/14 3pp
- 8009220207 Comments on rulemaking 50-3 GESMO proceedings should be resumed & completed Reprocessing & recycle of LWR fuel should be considered TBOULFAKIDIS.N Affiliation Unknown 80/09/15 1p
- 8010230231 Comments on rulemaking 50-5 GESMO proceedings should be resumed Delays will not serve natl security & will increase cost of emergy COURTNEY, J C Affiliation Unknown 80/09/15 1p
- B010230247 Comments on rulemaking 50-5 Commission should reopen QEBHOproceedings BARRY, J E Affiliation Unknown B0/09/15 1p
- 8010230291 Comments on rulemaking 50-5 GEBMO hearings should be reopened JDNEs, M Affiliation Unknown 80/09/15 ip
- 8010220529 Comments on rulemaking 50-5 supports resumption of GEEMO proceedings CREISIZENSXLP Affiliation Unknown 80/09/16 lp
- 8010220663 Comments on rulemaking 50-5 GESMO proceedings should be rappened Draft article encl which should have some input in forming policy on recycling Pu
 DEYAR Citizens United for Responsible Energy 80/09/17 9pp
- 8010230304 Comments on rulemaking 50-5 GESMO proceedings should be resumed US should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent fuel PANZANI,F A Affiliation Unknown 80/09/17 ip
- 8010020019 Comments on reopening of OESMO proceedings re Rulemaking 50-5 reopening & successful completion of hearing is logical precedent to communical reprocessing of spent nuclear fuel. 01888.0 C Affiliation Unknown 80/09/23 2pp
- 8010020690 Recommends resumption of GEBMO proceedings Persian Gulf area warfare necessitates technical development of spent reactor fuels to lessen dependence on imported oil MARHICK.E.F. Affiliation Unknown 80/09/23 ip
- BOIOO20012 Comments by two citizens in support of respening of GEBMO proceedings re Rulemaking 50-5 further consideration needed for energy development BREITMAYER:F Affiliation Unknown BO/09/24 2pp
- 8010020692 Forwards constituent comments on QEBMO proceedings Requests status of NRC intentions re-proceedings MOORE.W H House of Rep . Ways and Means 80/09/24 3pp
- 8010020005 Comments on reopening of OESMO procedings re Rulemaking 50-5 continuation of review process needed to determine whether reprocessing & recycling is viable option DRAPER.E. Culf States Utilities Co 80/07/25 2pp
- 8010020081 Comments on reopening of OESMO proceedings re Rulemaking 50-5.hearing must be reopened promptly due to need for establishing legal & logical basis for evaluation of spent fuel reprocessing BEHNKE, W B Commonwealth Edison Co 80/09/25 2pp
- 8010020007 Comments on reopening of QESMO proceedings re Rulemaking 50-5 no further action needed due to completion of evidence. THOMAS.R Environmentalists, Inc 80/09/26 ip.
- 8010030484 Recommends reopening of GERMO proceedings CHAMPAGNE.A.J Affiliation Unknown 80/09/26. ip

- 8010070264 Comments on rulemaking 50-5 re reopening of GESMD & recycle related proceedings Reopening record will resolve economic. environ & resource questions re fuel reprocessing DISE.D P Niagara Mohauk Power Corp 80/09/26 ip
- 8010010697 Order denying Allied General Nuclear Svcs 800926 request for 60-day extension to respond to Commission 800807 order Untimely comments will be considered only to extent possible CHILK.S J. Office of the Secretary of the Commission 80/09/29
 - CHILK, S J Office of the Secretary of the Commission 80/09/29
- 8010020001 Forwards comments on reopening of GESHO proceedings re Rulemaking 90-5 reinstitution of hearing reflects U8 interest in energy need & will establish framework for timely decisions on reprocessing & recycling WALSKE.C Atomic Industrial Forum 80/09/29 3pp
- B010020651 Comments on rulemaking 50-5 on behalf of 0ESHO Util Group OESHO proceeding should be reactivated IRWIN.D P Hunton & Williams 80/09/29 4pp
- BOIQO2O663 Comments on rulemaking 50-5 GESMO proceeding should be rescheduled BURT, D M Capital Legal Foundation 80/09/29 2pp
- 6010020670 Forwards comments on behalf of NRDC on rulemaking 50-5 GEGMO proceedings should not be reopened MEISG.E R Natural Resources Defense Council 80/07/29 5pp
- 8010030479 Views of Westinghouse on NRC 800807 order re resumption of GEBMO 8 other recycle-related licensing proceedings Resumption recommended Certificate of Svc encil COWAN, B Z Westinghouse Electric Corp 80/09/29 13pp
- 8010020675 Recommends that NRC reopen GESMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced OLSON, R E Affiliation Unknown 80/09/30 1p
- 8010030471 Responds to Commission 800807 order requesting comments on reopening of OSSMO & other recycle-related licensing proceedings Proceedings should be reactivated & consistent position on use of energy initiated KEARNEY, J J Edison Electric Institute 80/09/30 3pp
- 8010160675 Supports resumption of GESMO proceeding as prelude to closure of nuclear fuel cycle MOCDY.JH Yankee Atomic Electric Co 80/10/08 2pp
- 8010270506 Responds to 800924 ltr transmitting J Courtney request for NRC resumption of GEBMO proceedings J Courtney comments will be incorporated into public record to be considered by NRC KAMMERER. C Office of Congressional Affairs 80/10/08 ip
- BO1015036A Bubmits comments on resumption of GEBMO rulemaking on behalf of AZ Public Svc Co.CPSL.Con Ed & WI Electric Power Co Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues OALLO, J Isham, Lincoln & Beale 80/10/10 3pp
- 8010200395 Advises of address change from Columbia, SC to Washington, DC & requests records be changed BELSER.T N Belser, Bolser, & Baker 80/10/13 lp
- 8010220494 Forwards JC Courtney 800916 ltr requesting that GESMG hearings be resumed LONG, R Benate 80/10/19 2pp
- DOCKET 70-1447 LANCASTER GENERAL HOSP LANCASTER PA
- 8010140172 Ack receipt of 800814 ltr informing NRC of steps taken to correct violations noted in LE Insp Repts 30-03151/80-01, 30-00493/80-01 & 70-1447/80-01 [KINNEMAN.J D. Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/09/11 [p
- --B01014017B Responds to NRC 80071B ltr re violations noted in IE Insp Repts 30-03151/80-01.30-00493/80-01 & 70-1447/80-01 Corrective actions radiation safety committee membership will be revised & personnel advised of procedures WEDEL.P O Lancaster General Hosp. Lancaster.PA 80/08/14 2pp
- --8010140184 Forwards notice of violation identified in IE Insp Repts 30-03151/80-01.30-00493/80-01 & 70-1447/80-01 on 800707. KINNEMAN.J.D Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/07/18 2pp.

- --B010140170 Notice of violation from insp on 800707 Noncompliance noted failure to make whole body surveys

 * Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch
 B0/07/18 1p
- DOCKET 70-1503 WESTINGHOUSE ROD CENTER, WESTINGHOUSE ELECTRIC CORP
- B010010294 Forwards IE Insp Repts 70-0048/80-01 & 70-1503/80-01 on B00504 No noncompliance noted KIPNEMAILJ D Region 1. Philadelphia. Office of the Director B0/08/01 2pp
- --B010010258 IE Insp Repts 70-904B/80-01 \$ 70-1503/80-01 on 800404 No noncompliance noted Major areas inspected personnel monitoring, radiation safety committee, hot cell entry controls & airborne releases to unrestricted areas KINNEMAN, J. COSTELLO, F. Region & Philadelphia, Office of the Diractor B0/07/31 4pp

DOCKET 70-1703 EASTHAN KODAK CD

- 8010100068 Ack receipt of 800804 ltr informing NRC of actions taken in response to IE Insp Rept 70-1703/80-01 KINNEMAN.J D Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 80/09/05 ip
- --8010100072 IE Insp Rept 70-1703/80-01 on 800801 Areas covered expiration of license & application for new license Application has been filed No further action planned KINNEMAN. J D Region I. Philadelphia. Fuel Facility & Materials Safety Branch ROME. CA Region i. Philadelphia. Office of the Director 80/07/04 2pp
- --Bold100076 Forwards renewal request for License BNM-1513.per 800801 telcon request HARTER.E S Eastman Kodak Co 80/08/04 ip
- --8010100078 Requests renewal of License 8NM-1513 MARTER:E 8 Eastman Kodak Co 80/06/16 ip
- DOCKET 70-1821 PLUT PROD FACIL . ALLIED GENERAL NUCLEAR SERVICES CORP
- 8010010830 Comments on proposed rule RM 50-5 re NRC termination of efforts on GESMO fuels NRC should resume GESMO proceeding Certificate of 84c & svc list encl
 DECHER, U Affiliation Unknown 80/09/03 7pp
- 8010230281 Comments by TN Technological Univ on rulemaking 50-5 GESMO proceedings should be restarted immediately DEMAS,N O Affiliation Unknown 80/09/11 lp
- 8010230349 Comments on rulemaking 50-5 supports reopening of GESMO proceedings LCRFING.D Affiliation Unknown 80/09/11 1p
- 8010220540 Comments on rulemaking 50-5 NRC should not reopen GESMO or other nuclear recycle-related licensing proceedings. Opposes action which would be contrary to US nonproliferation policy MCLAUOHLIN.W T Affiliation Unknown 80/09/12 1p
- 8010230265 Comments on rulemaking 80-5 GESMO proceedings should be resumed HACHNEY.C A Affiliation Unknown 80/09/12 1p.
- 8010230341 Comments on rulemaking 50-5 GEBMO proceedings should be reopened LOPEZ, C R Affiliation Unknown 80/09/12 1p
- 8010020699 Recommends GESMO proceedings be completed Technically compatent people available to complete GESMO project Further delay in proceedings will increase energy costs GESMO will provide basis for future decisions re spent nuclear fuel MURRAY.H Affiliation Unknown 80/09/13 1p
- 8010230328 Comments on rulemaking 50-5:GEBMO hearings should not be reopered due to problems w/reprocessing Health hazards associated w/transport & reprocessing shown to be more serious then previous expectations.

 CLEMENTS.T. Affiliation Unknown 80/09/13 ip
- 8010220518 Comments on rulemaking 50-5 GESMO hearings should resume firmediately BARRY.D Affiliation Unknown. 80/09/14 ip

- B010230317 Comments on rulemaking 50-5.9EBMO proceedings should not be responed TUCKER, C A Affiliation Unknown 80/09/14. 1p
- 8010230323 Comments on rulemaking 50-5 re resuming GEBMO proceedings. CHUBB, W Affiliation Unknown 80/09/14. 3pp
- 8009220237 Comments on rulemating 50-5 GESMG proceedings should be resumed & completed Reprocessing & racycle of LWR fuel should be considered TEQUIFANIDIS.N Affiliation Unknown 80/09/15 Ip.
- 8010230231 Comments on rulemaking 50-5 QESMO proceedings should be resumed Delays will not serve natl security & will increase cost of energy COURTNEY.J C Affiliation Unknown. 80/09/15 ip.
- 8010230247 Comments on rulemaking 50-5 Commission should reopen GESMO proceedings.

 BARRY, J.E. Affiliation Unknown, 80/09/15, 19
- BOIOR30291 Comments on rulemaking 50-5.0ESMO hearings should be reopened JONES.N Affiliation Unknown 80/09/15. ip.
- BO10220529 Comments on rulemaking 50-3, supports resumption of QESHO proceedings CREISZENSXI.P Affiliation Unknown B0/09/14 lp.
- 8010220663 Comments on rulemaking 50-5 GESMO proceedings should be reopened Draft article encl which should have some input in forming policy on recycling Pu DEYA:R Citizens United for Responsible Energy 80/09/17 9pp.
- 8010230304 Comments on rulemaking 50-5 GESMD proceedings should be resumed UB should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent fuel PANZANIF A Affiliation Unknown 80/09/17 ip
- 8010020019 Comments on reopening of GESMO proceedings re Rulemaking 50-5 reopening & successful completion of hearing is logical precedent to commercial reprocessing of spent nuclear fuel. 01885.D C Affillation Unknown 80/09/23 2pp
- 8010020690 Recommends resumption of GESMO proceedings Persian Gulf area warfare necessitates technical development of spent reactor fuels to lessen dependence on imported oil MARMICK.E F Affiliation Unknown 80/09/23. 1p
- 310020012 Comments by two citizens in support of reopening of GESMO proceedings re Rulemating 50-5 further consideration needed for energy development BREITMAYER; F Affiliation Unknown. 80/07/24. 2pp.
- 8010020005 Comments on reopening of SESMO procedings re-Rulemaking 80-3.continuation of review process needed to determine whether reprocessing & recycling is viable option DRAPER.E L Ouif States Utilities Co 80/09/23 2pp.
- 8010020081 Comments on reopening of GESMO proceedings re Rulemaking 30-5 hearing must be reopened promptly due to need for establishing legal & logical basis for evaluation of spent fuel reprocessing BEHNXE, N B Commonwealth Edison Co 80/09/25. 2pp
- 8010020607 Comments on reopening of QESMO proceedings re Rulemaking 50-5:no further action needed due to completion of evidence THOMAB:R Environmentalists, Inc 80/09/26 ip
- 010030484 Recommends reopening of GESMO proceedings. CHAMPAGNE.A J Affillation Unknown B0/09/26 ip
-):0070264 Comments on relemaking 30~5 re reopening of GESMO & recycle related proceedings. Reopening record will resolve economic, environ & resource questions re fuel reprocessing.
 DISE, D P Niegara Hohawk Power Corp 60/09/26 ip.
- >10010687 Order denying Allied Ceneral Nuclear Sycs 800924 request for 60-day extension to respond to Commission 800807 order. Untimally comments will be considered only to extent possible. CHILK, B. J. Office of the Secretary of the Commission, 80/09/27. ip

- 8010020001 Forwards comments on reopening of OEBMO proceedings re Rulemaking 50-5 reinstitution of hearing reflects US interact in energy need & will establish framework for timely decisions on reprocessing & recycling WALBKE, C Atomic Industrial Forum 80/09/29, 3pp
- 8010020651 Comments on rulemaking 50-5 on behalf of GESMO Util Group OEBMO proceeding should be reactivated IRWIN,D P Hunton & Williams 80/09/29 4pp
- 80:0020663 Comments on rulemaking 50-5 GESMO proceeding should be rescheduled BURT, D M Capital Lagal Foundation 80/09/29 2pp
- 8010020670 Forwards comments on behalf of NRDC on rulemaking 50-5.058MO proceedings should not be reopened WEISB-E R Natural Resources Defense Council 80/07/29 3pp
- 8010030479 Views of Westinghouse on NRC 800807 order re resumption of OBSMD & other recycle-related licensing proceedings Resumption recommended Certificate of Svc encl CDNAN.8 Z Westinghouse Electric Corp 80/09/29 13pp.
- 8010020675 Recommends that NRC reopen OESMO hearings in order that spent reactor fuel can be utilized & dependence on foreign oil can be reduced OLSON, R E Affiliation Unknown 80/09/30 ip
- 8010030471 Responds to Commission 800807 order requesting comments on reopening of 088M0 & other recycle-related licensing proceedings Proceedings should be reactivated & consistent position on use of energy initiated KEARNEY, J J Edison Electric Institute, 80/09/30 3pp
- 8010160695 Bupports resumption of GESMO proceeding as prelude to closure of nuclear fuel cycle MODDY,J H Yankee Atomic Electric Co 80/10/08 2pg
- 8010270506 Responds to 800924 itr transmitting J Courtney request for NRC resumption of QEBMO proceedings J Courtney comments will be incorporated into public record to be considered by NRC KAMMERER, C Office of Congressional Affairs 80/10/08 ip
- 8010190364 Submits comments on resumption of OESMO rulemaking on behalf of AZ Public Svc Co.CP&L.Con Ed & UI Electric Power Co Proceeding would provide factual basis on which NRC could render independent judgment on urgently needed issues QALLO.J Isham, Lincoln & Beale 80/10/10 3pp
- 8010200395 Advises of address change from Columbia, BC to Washington, DC & requests records be changed
 BELSER, T N 9elser, Belser, & Baker 80/10/13 ip
- 8010220494 Forwards JC Courtney 800916 ltr requesting that QESMO hearings be resumed LCNO.R Senate 80/10/13, 2pp.

DOCKET 70-2185 HILLGREST MEDICAL CENTER TULBA, OK

- 8009100370 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensess" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/26
- DOCKET 70-2313 NUCLEAR FUEL SERVICES
- 8010220162 Notifies of NRC review & approval of Bill 8, 2443, authorising Secretary of Energy to carry out high level liquid nuclear waste mpt demonstration program at Western NY Svc Ctr in Hest Valley, NY, AHEARNE, J.F. Commissioners 80/09/24 5pp
- DOCKET 70-2317 TELEDYNE CAST PRODUCTS
- 8010210765 Responds to 800108 request to terminate License SNM-1677. Forwards "Guldalines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct Bource or BNM "GROW, W.Y. Uranium Fuel Licensing Branch 80/09/18. 1p

DOCKET 70-2478 TRANSNUCLEAR, INC.

B010150623 Requests approved route change bypassing Fayetteville,NC urban area. & that context of ltr be withheld (ref 10CFR2 790)
MANOUSI.J Transnuclear, Inc. B0/08/20 ip

801020013B Responds to 800820 request for route change. Route previously approved remains contingent in meeting requirements of 10CFR73 37 relative to heavily populated areas Proposed alternate change approved per mod MCCGRKLE. O W Physical Security Development Branch 80/09/22 1p.

DOCKET 70-2479 TRANSNUCLEAR, INC.

8010150623 Requests approved route change, bypassing Fayetteville, NC urban area, & that context of itr be withheld (ref 10CFR2 790)
MANJOUSI, J Transnuclear, Inc. 80/08/20 ip

8010200138 Responds to 800820 request for route change Route previously approved ramains contingent in meeting requirements of 10CFR/3 37 relative to heavily populated areas Proposed alternate change approved per mod MCCORKLE.0 W Physical Security Development Branch, 80/09/22 1p

DOCKET 70-2560 DKLAHOMA OSTEOPATHIC HOSP TULSA, OK

8009100379 Forwards IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensees " No written response required
SEYFRIT.K V Region 4. Dallas. Office of the Director 80/08/26.

DOCKET 70-2609 COMMONWEALTH EDISON CO

SOI0:50093 Approves SNM security plan submitted on 800722, amending Licenses SNM-1892 & BNM-1833 Addi license conditions encl. MCCCRKEE, 6, W Physical Security Licensing Branch. 80/08/28 2pp.

8010220094 Amend 3 to License SNM-1802, changing Item 8A to 6,000 kg of U-235 at max enrichment of 3 1% PAGE,R O Uranium Fuel Licensing Branch 80/09/23 1p.

--B010220108 Bafety evaluation re B00711 amend application for Licenses SNM-1802 & BNM-1833, raising possession limit to 6,000 kg U-235 Change in allowed inventories will not affect nuclear, environ or safety Issuance of amend recommended STEVENSON, R. L., GROWN, W.T. Uranium Fuel Licensing Branch B0/09/23

DOCKET 70-2623 MCGUIRE SPENT FUEL POOL, DUKE POWER CO

8010270580 Application for amend to License GNM-1773 for receipt, use & storage of single fuel assembly into different locations of core for indexing purposes
PARKER-U 0 Duke Power Co 80/08/12 ip

8010140597 Requests to reopen record based on safety-related matter bearing on conclusion as to whether criticality incident may occur in McGuire spent fual pool, reported in encl Power Resctor Events Certificate or Buc encl RILEY. J L Carolina Environmental Study Group 80/10/06 12pp.

8010240552 Response in apposition to Carolina Environ Study Group 801005 motion to reasen record to include Jul 1980 "Unplanned Boron Dilution," rept into evidence No new info presented
PORTER-W. L. Duke Power Co GO/10/21 7pp.

 8010240562 Affidavit addressing activities associated w/demineralizer operation & effect of boron decreased concentration. Certificate of Byc encl Duke Power Co 80/10/21 8pp

DOCKET 70-2889 COMMONWEALTH EDISON

8010150093 Approves SNM security plan submitted on 800728, amending Licenses SNM-1802 & SNM-1833 Addi license conditions encl. MCCORKLE, O W Physical Security Licensing Branch. 80/08/28. 2pp.

8010220094 Amend 3 to License SNM-1802, changing Item 8A to 6,000 kg of U-235 at max enrichment of 3 1% PAGE,R 0 Uranium Fuel Licensing Branch 80/09/23 ip

-8010220108 Safety evaluation to 800711 amend application for Licenses 8NM-1802 & SNM-1833, raising possession limit to 6,000 kg U-235 Change in allowed inventories will not affect nuclear, environ or safety issuance of amend recommended. BTEVERBON.R L , CROWN, W T Uranium, Fuel Licensing Branch, 80/29/29 10 ĺρ

DOCKET 70-2896 MCKAY-DEE HOSP CENTER OQDEN, UT

8009100369 Forwards IE Circular 80-19. "Noncompliance W/License Requirements for Medical Licensess" No written response required BEYFRIT,K V Region 4. Dallas, Office of the Director 80/08/26

8010240350 IE Insp Findings & Licenses Ack 844 801006 of License BNM-1847 Insp findings no items of noncompliance noted CAIN.C L Region 4, Dallas, Office of the Director 80/10/06 BO/10/06 1p

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

8010080280 Memorandum in support of add1 late contentions Access to voluminous matis very limited Certificate of Byc encl. ALLRED, D.L. Affiliation Unknown 80/10/01 5pp

--8010080285 Add1 proposed contentions alleging failure of Westinghouse to provide sufficient info for NRC to adequately usigh environ.technical & economic issues Certificate of Bvc encl ALLRED,D L Affiliation Unknown 80/10/01 27pp

8010090071 Second set of proposed valid contentions re atomic explosion risk, authority to possess & process SNM, Agreement State status, spant fuel Pu risk, ALARA program, Mobile Bay estuary, new EPA stds & breathing masks Certificate of Svc encl.
MCPHILLIPS, J Safe Energy Alliance 80/10/01, 24pp.

8010140016 Memorandum in support of second set of contentions Motion filed on 800420 for extension of time in which to file contentions Contentions based on licensee application not found by petitioner until 20082 Certificate of 8vc encl MCPHILLIPS. J Bafe Energy Alliance 80/10/01 4pp

8010210269 Responds to JF Holf request re 801016 telcon w/ABLB, Hestinghouse, DL Allred & NRC Parties will hold 801106-07 meeting re stipulation of contentions Extension until 801215 granted for State of AL to file Issues TURK, B E. Hearing Brench 1 80/10/17 2pp.

8010310430 Statement expressing strong opposition to licensing facility Summarizes Safe Energy Alliance of Central AL 801027 town meeting t NRC 801027 public hearing. WILLIAMS,L O Affiliation Uninown 80/10/29 2pp

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

8010270135 Amend 2 to License SNM-1841, changing expiration date to 811231 or upon conversion of CPPR-91 to OL PACE,R Q Uranium Fuel Licensing Branch. 80/10/08, 1p

DOCKET 70-2913 TENNESSEE VALLEY AUTHORITY

8010300495 Amend 1 to License 8NM~1863 changing expiration date to 810331 or upon conversion of CPPR-73 to OL, PAGE R. 9 Uranium Fuel Licensing Branch 80/10/08 ip.

DOCKET 70-2926 DETROIT EDISON CO.

8010150104 Requests submittal of security plan for 800304 application MCCORKLE, O W Physical Security Licensing Branch BO/09/20 ip.

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO.

8010270528 Requests date for receiving SNM in response to 800710 request for authorization to possess same. KETZLACH.N. Uranium Fuel Licensing Branch, 80/10/10, 1p

DOCKET 70-2033 EASTMAN KODAK CO

8010230543 Informs of forthcoming check for renewal of License 8NM-1513 HARTER,E S Eastman Kodak Co 80/08/04 1p

--8010230647 Ack receipt of 800616 ltr requesting License 8NM-1313 renewal Application will be processed upon receipt of fee JACK50N.G License Fee Management Branch 80/07/24 ip

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

8010310115 Forwards QA program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/10/23 1p

~~8010310120 QA program approval for radioactive matl package 0018, Revision 0 MACDDNALD,C E Transportation Branch 80/10/23 1p.

DOCKET 71-0046 TELEDYNE ENERGY SYSTEMS

8010240187 Advises that OA plans re sentinel & protective packaging have been cancelled Caused by failure to assign new docket number liew docket number should be assigned to sentinel plan
MCGREW.J W Teledyne Energy Systems 80/10/01 1p

DOCKET 71-0102 SOURCE PROD & EQUIP CD . INC

8010240034 Forwards GA program for shipping packages & radioactive matl
DICHARRY,R F Source Production & Equipment Co ,Inc. 80/09/29 1p

--9010240036 QA program for shipping packages & radioactive met!

* Source Production & Equipment Co . Inc 80/09/25 lipp

DOCKET 71-0371 MODEL NNFD-10, UNIFIED NUCLEAR CORP

B010200532 Forwards QA program for Naval Electronic Bys Engineering Ctr.San Diego.CA SMITH.R H Navy.Dept of 80/09/16 1p

--8010200539 Forwards GA program
DE GUZMAN.A S Navy.Dept of.Electronics Systems Engineering
Center.BC 80/08/18 1p

--8010700547 QA program

4 Navy. Dept of Electronics Systems Engineering Center, 80 80/08/18 2pp

8010310190 Forwards 0A program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/10/21 lp

---B010310155 QA program approval for radigactive matl package 0371, Revision O MACDUNALD,C E Transportation Branch 80/10/21 ip

DOCKET 71-0385 NAVY, DEPT OF, NAVAL NUCLEAR POWER UNIT PORT HUENEME, CA

8010100145 Ack receipt of 800812 ltr forwarding Change Transmittal 1 to Instruction 9090 1 Changes are acceptable Description of OA program should be resubmitted. w/o use of pen & ink changes
MACDONALD.C E Transportation Granch 80/09/11. 1p

DOCKET 71-0395 NAVY, DEPT OF, NAVAL FACILITIES ENG COMMAND

8010010777 Forwards request for addl info re QA program Application for approval should be from Naval Energy & Environ Support Activity, rather than from another organization w/concurrence
MACDDNALD/C E Transportation Stanch 80/09/19. 2pp.

DUCKET 71-0396 ATOUR WASHINGTON, INC.

8010080995 Forwards OA program approval for radioactive mati package MACDDNALD, C E Transportation Branch 80/09/26 ip

---8010080301 0A program approval for radioactive matl package 03%, Revision 0 M4CDCHALD:C E Transportation Branch 80/09/26 1p

DOCKET 71-5026 MODEL BC-48-220, AFCOR, INC

BO10200180 Requests registration as user Model CN8-14-190 BENNERT.K New England Nuclear Corp 80/09/22 1p

BO10240C02 Requests registration as user of Model BC-48-220 PASTERMAK.R J Power Authority of the State of New York 80/10/01 10

DOCKET 71-5959 MODEL URARY NIT-TNK, NUCLEAR FUEL SERVICES, INC.

8010280032 Natifies that Certificate of Compliance 5059 for Model Uranyl NIT-TMK expires on 801231 Continued use of package is contingent on consolidated application for renewal MACDONALD, C.E. Transportation Branch 80/10/08 ip

9010200420 Requests renewal of Certificates of Compliance 3442.50% L 6273 Fee enci MICHEL, C J Nuclear Fuel Services, Inc. (subs. of Gatty Gi) Co 3 80/10/14 1p

DOCKET 71-5088 MODEL D34710-1, U.S. NUCLEAR, INC.

8010070277 Responds to NRC 800616 ltr re Certificate of Compliance 5038 used by DDE & requests copy of renoval FITZSIMMONS,T Fnergy, Dept of 80/06/20 ip

8010020074 Forwards application for renewal of Certificate of Compliance 5088 for Models 034710-1 & D34710-2 & lead test rept Fee encl REPLEV.II E Rockwell International Corp 80/09/08 ip

--8010020080 "Testing of Radioactive Matl Shipping Container to Requirements of AFC Regulation 10CFR71" • Missouri, Univ. of, Rolla 66/09/29 31pp

--B010020085 Application for renewal of Certificate of Compliance SSG for Models B04710-7 & B04710-7 & Roctwell International Corp 80/07/08 14pp

9010310246 Forwards Revision 2 to Certificate of Compliance 9090 for Models D34710-1 & D34710-2 Supersedes 770304 Certificate of Compliance 9052 MACDDMALD.C E Transportation Branch 80/10/17, 2pp

--8010310250 Certificate of Compliance 5088, Revision 2, for Hodgis D34710-1 & D34710-2 MCDCNALD, C E Transportation Branch 80/10/17 4pp

DOCKET 71-5274 MODEL UNC-1634, UNITED NUCLEAR CORP

BO10220635 Notifies that Certificate of Compliance 5274 for Hodel UNC-1634 expires on B01130 Consolidated application for renewal is required for continued use of package MACDONALD.C E Transportation Branch B0/10/07 ip

DOCKET 71-5442 MODEL LA-36, BABCOCK & WILCOX CO

8010200420 Requests renewal of Certificates of Compliance 5442,5059 to 6273.Fee encl
MICHEL, C. J. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.)
80/10/14 1p

DOCKET 71-5450 MODEL RCC-1,-2,-3, NESTINGHOUSE ELECTRIC CORP

B010270072 Forwards Revision 10 to Certificate of Compliance 5450 fpt
Models RCC.RCC-1.RCC-2.RCC-3 & RCC-4
MACDUNALD.C E Transportation Branch 80/10/14 2pp,

. !

- --B010270075 Certificate of Compliance 5450 Revision 10, for Models RCC, RCC-1.RCC-2.RCC 3 / RcC-4 MACDONALD.C E Transportation Branch 80/10/14 Spp
- DOCKET 71-5641 MODEL UNC-2500
- 8010280037 Notifies that Certificate of Compliance 5641 for Model UKC-2500 expires 810131 Continued use of package is contingent on consolidated application for renewal MACDOWALD.C E. Transportition franch 80/10/08 ip
- DOCKET 71-5796 HODEL 181361, PICKER CORPORATION
- 9010220491 Notifies that Certificate of Compliance 9796 for Models 191375 2 191361 expires 801231 Continued use of package is contingent on request for renewal MACDOMALD.C E Transportation Branch 80/10/07 1p
- DOCKET 71-5805 MODEL ATCOR VNDB CASK, ATCOR, INC
- BOID270427 Notiries that Cortificate of Compliance 5805 for Model Atcor VABB expires 801931 Continued use or package is contingent on consolidated application for renewal MACDGMALD.C E Transportation Branch 80/10/08 ip
- DOCKET 71-5908 MODEL DOT-GM TYPE B. BABCOCK & WILCOX CO
- 8010100261 Approves request for registration as user of Model DOT-6M-B in response to request MACDB/ALD, C.E. Transportation Branch 80/09/29 ip
- DOCKET 71-5926 MODEL 100: GENERAL ELECTRIC CO
- 8010190613 Forwards Revision 6 to Certificate of Compliance 5926 for Model GE-100 MACDBNALD, C. E. Transportation Branch 80/09/25 2pg
- --8010130614 Certificate of Compliance 5926 Revision 6 for Hodel OE-100. MACDONALD, C E Transportation Branch 80/09/25. 3pp
- DOCKET 71-5939 MODEL OF-1500, GENERAL ELECTRIC CO
- 8010270365 Application for 6-month renewal of Certificate of Compliance , 5937 for Hodel 1500 for enci CU*NINGHAM.G E General Electric Co 80/09/26 1p
- BO10270169 Requesty registration as user of Model 1500 to ship Co-60 to Saudi Arabia
 PARKER, J. G. International Nutronics, Inc. 80/09/27 ip
- DOCKET 71-9957 MODLE BHI-1. ENERGY, DEPT OF
- BO10020122 Forwards revised Drawing 43-6704-0001.Revision B for substitution of Revision A drawings re BAR for Model BMI-1 shipping cask, in response to R Odegaardon B00711 ltr BURIAN.R J Battelle Memorial Institute. Columbus Laboratories BO/07/27 2pp
- BO10010645 Application for amend of Cartificate of Compliance 3957 for Model BMI-1 Change addresses use of Union Carbide Corp process U cride container & special form capsule as containment vessel BUNIAM.R. J Battelle Memorial Institute, Columbus Laboratories. BO/08/25, 2pp
- ---8010010653 "BAR for Model BMI-1 Shipping Cask," Revision B.

 * Battelle Memorial Institute, Columbus Laboratories, BO/08/01
 8769.
- DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO
- 801002007A Requests registration as user of Madel 9E-200 EMBWILER: T R Battelle Hamorial Institute, Columbus Laboratories 80/09/04 ip

- 8010100027 Approves request for registration as user of Model GE-200, in response to request MACDONALD, C.E. Transportation Branch 80/09/29 ip
- 8010150109 Approves request for registration as user of Model GE-200 MACDONALD.C E Transportation Branch 80/09/29 ig
- 8010210025 Forwards Revision 3 to Certificate of Compliance 5971 for Model 0E-260 MACDONALD, C.E. Transportation Branch 80/09/30 2pp
- --8010210027 Certificate of Compliance 5971 Revision 3.for Model GE-200 MACDONALD.C E Transportation Branch 80/09/30 3pp
- DOCKET 71-5998 MODEL 0E-400, GENERAL ELECTRIC CO
- 8010220687 Forwards Revision 3 to Certificate of Compliance 5998 for Model CE-400 MACDONALD, C.E. Transportation Branch 80/10/07 1p
- --8010220690 Certificate of Compliance 5998. Revision 3. for Model GE-400 MACDONALD.C E Transportation Branch 80/10/07 3pp
- DOCKET 71-6098 KODEL 83-1, NUCLEAR ENGINEERING CO
- 8010280671 Responds to 800530 itr re Model 8-3 shipping package Pravious package approval permitted equivalent to DOT Spec 17H steel drums which received variety of interpretations & disagreements Equivalent was deleted to eliminate problems MACDONALD, C.E. Transportation Granch 80/10/14 ip
- DOCKET 71-6089 MODEL 33-FE-100, GENERAL ATOMIC CO
- 8010270105 Application for reneval of Certificate of Compliance 4089 for two yes w/o issuance of consulidated safety analysis MOKRY, W R General Atomic Co (subs of Oulf Oil Co.) 80/09/22 in
- 8010220646 Notifies that Certificate of Compliance 6089 for Model 33-FE-100 expires on 801031 Vendor may submit consolidated application for renewal MACDDMALD.C E Transportation Branch 80/10/07 1p
- DOCKET 71-6244 MODEL 6244. CHEM-NUCLEAR SYSTEMS, INC
- 8010730516 Requests registration as user of Model CNSI-4-85 PABTERNAM,R J Power Authority of the State of New York 80/09/24 to
- DOCKET 71-6273 MODEL 48X, F. A. Y. ALLIED-CENERAL NUCLEAR BERVICES
- 8010220450 Notifies that Certificate of Compliance 6273 for Models 48A, 48Y, 48F & 48Y expires on 801031 Continued use of package is contingent upon request for renewal MAGDENALD.C E Transportation Branch 80/10/07 ip
- BO1020D420 Requests renewal of Certificates of Compliance 5442,5059 & 6273 Fee and MICHEL, C.J. Nuclear Fuel Services. Inc. (subs. of Getty Gil Co. 1 BO/10/14 ip
- DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC
- 8010230177 Requests registration as user of Model UNC-2701 transportation package Check encl KAPLANIA L General Electric Co . Nuclear Energy Products Div 80/08/22 ip
- --8010230203 Returns check encl w/800822 ltr requesting registration as user of Model UNG-2901 transportation package Fee not required NEISB, D License Fee Management Branch 80/08/27 ip

DOCKETED ITEMS

- DECKET 71-6346 MODEL FSV-1, GENERAL ATOMIC CO
- 8010030189 Application for renswal of Certificate of Compliance 6346. updating drawing refs for Model FSV-1 MDMNY. W R Deneral Atomic Co (subs of Gulf Dil Co) 80/08/28
- --8010030197 Addendum 1.Revision 1. "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask " MODRE.R L General Atomic Co (subs of Gulf Gil Co) GADR-55 ADD 1 R1 80/08/31 123pp
- ---8010030200 Revision 2, "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask " MGDRE.R L. General Atomic Co (subs. of Gulf Gil Co.) GADR-55 R2 80/08/31 75pp
- 8010150607 Forwards Revision 4 to Certificate of Compliance 6346 for Model FSV-1 MACDONALD, C E Transportation Branch 80/09/25 ip
- --8010150410 Certificate of Compliance 6346, Revision 4 for Model F8V-1 MACDONALD, C E Transportation Branch 80/09/25 3pp
- DOCKET 71-6947 MODEL F6V-9, GENERAL ATOMIC CO
- BO10220449 Notifies that Certificate of Compliance 6347 for Hodel FBV-3 expires on BO1031 Applicant may submit consolidated application for renewal MAGDONALD.C E Transportation Branch BO/10/07 1p
- DOCKET 71-6375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC
- 8010100424 Forwards summary of mods to renewal application package, in response to NRC 800623 ltr request for addl info Mods will bring package to reg guide stds Changes assure safe reliable package for transport of Type B matts
 COMBETT, J S Chem-Nuclear Systems, Inc 80/09/08 19
- DOCKET 71-4400 MODEL, SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8008210513 Application for renewal of Certificate of Compliance 5400 for super Tiger Shipping package Requested info re leakage test requirements & seal replacement schedules is presented in App C of encl mat!

 DIPLAZZA, R Westinghouse Electric Corp 80/07/28 51pp
- ---800B210614 Application for certificate of compliance to deliver Super Tiger, DOT 69 6400.to carrier, as fissile Class 1 shipment REITLER,E K Babcock & Wilcox Co , Nuclear Material Div 71/09/17 2pp
- --8008210615 Responds to questions ralloading of Super Tiger w/waste drums raised in AEC 711118 ltr Crates inherently safe from criticality since no more than 5 g fissile fuel contained per cubic ft of crates Two illegible drawings enci REITLER, E. K. Babcoct & Wilcox Co., Nuclear Material Div 72/01/06 App
- 8009250450 Forwards revised drawing in Encl II of 800815 ltr re Model 6400 packaging AUBTIN,M A Babcock & Wilcox Co , Nuclear Material Div 80/09/04
- ---8009250454 "Bupertiger, Model 6400 " # Baboock & Wilcox Co , Nuclear Material Div 80/08/13 ip.
- DOCKET 71-6489 MODEL OB-09998, GENERAL ATOMIC CO
- B010230224 Advises of intent not to renew license authorizing domestic shipment of radioactive matl in Model GR-09978 MORRY, W R General Atomic Co (subs of Gulf Oil Co.) 80/09/22, in

- DOCKET 71-4581 MODEL 51032-1 & IA, EYKON NUCLEAR CO , INC
- 8010010358 Forwards Revision 13 to Certificate of Compliance 458% for Models 51032-1 % 51032-1a MACDONALD.C E Transportation Branch 80/09/22 1p.
- ---BO;0010362 Certificate of Compliance 6581 Revision 13, for Models 51032-1 & 51032-1a MACDOMALD, C Fransportation Branch 80/09/22 4pp
- DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC
- 8010090112 Requests registration as user of Model LL-50-100 FITZSIM(D,45,T Energy, Dept of 80/08/21 ip
- 8010100258 Approves request for registration as user of Model LL-50-100, in response to request MACDONALD C E Transportation Branch 80/09/26 1p
- DOCKET 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 80:0090:188 Application for Revision 12 of Certificate at Compliance 6698 to provide statistical & direct comparison analyses of cavity dimensional measurements Fee encl
 JCHNECH, C R Nuclear Assurance Corp 80/09/12 2pp
- --B010090192 "Cavity Measurements of NAC-1D Spent Fuel Shipping Cast" CARLBOILR W Nuclear Assurance Corp NAC-E-803 80/09/30 7969
- DOCKET 71-6717 HODEL 6717 B
- 8010220283 Advises of registration as user of Model 6717-B MACDONALD, C.E. Transportation Branch 80/09/24 1p
- 8010090075 Notification of registration as user of Models 6717-B k C-1 MACDONALD, C E Transportation Branch 80/09/29 1p.
- DOCKET 71-6722 HODEL DS-33-180, TENNESSEE VALLEY AUTHORITY
- 8010220374 Notifies that Certificate of Compliance 6722 for Model BS-33-180 expires on 801130 Continued use of package is contingent upon request for renewal MACDONALD, C E Transportation Branch 80/10/07 ip
- DUCKET 71-6744 MODEL POLY TIGER, NUCLEAR ENGINEERING CO.
- 8010149176 Forwards Drawing 32216.Revision J. re shield transportation cast.in response to 800702 ltr MCOREW, J W Teledyne Energy Systems 80/09/22 lp
- --8010140181 "Shield Transportation Cask " Sheet 1 of 2. * Teledyne Energy Bystems 73/10/08 1p
- --8010140265 "Shield Transportation Cask " Shest 2 of 2 * Teledyne Energy Systems 73/10/08 ip
- 8010290388 Forwards addl info required for review of application to amend Model Poly Tiger packaging Info should be submitted as revised pages to original SAR MACDONALD, C E Transportation Branch 80/09/25. 2pp
- DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO
- 8010220589 Forwards GA Program Insp Meeting Repts 99900382/80-01 k 71-9001/80-02 on 800729 No noncompliance noted POTATOVS,U Region 4, Dallas, Vendor Inspection Branch 80/08/01
- --8010220592 QA Program Insp Meeting Repts 99900382/80-02 & 71-9001/80-02 on 800729 No noncompliance noted Major areas discussed. corrective & preventive actions in response to previous rept MCNEILL, W. M. WHITESELL, D. E. Region 4, Dallas, Vendor Inspection Branch, 80/07/31 2pp

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

8010020127 Application for Amend T-18 to Certificate of Compliance 9009 re eishption from annual loak test requirement of Section 12 for inner containers of FL 10-1 package used for shipments of unnul hit ate solutions Two revisions encl KAPLAN, A L. Transportation Branch 80/08/27 4pp

DOCKET 71-9010 MODEL NC1-1/2, NL INDUSTRIES, INC

8010230187 Requests registration as user Model NLI-1/2 /UNDT.C P Portland General Electric Co 80/09/16 ip

B01010023B Approves request for registration as user of Model NLI-1/2, in response to request MACDUMALD,C E Transportation Branch 80/09/24 1p

8010160684 Ack receipt of 800929 ltr & remittance for amend to Certificate of Compliance 9010 Addl payment necessary WE188.D License Fee Management Branch 80/10/08 ip

DOCKET 71-9011 MODEL E-MEH-00-00004, TRANSPORTATION, DEPT OF

BO10280007 Notifies that Certificate of Compliante 9011 for Model E-NeH-00-00004 expires on 801231 Continued use of package is contingent on request for renewal MACDMALD.C E Transportation Branch 80/10/08 1p

DOCKET 71-9016 MODEL TN-9 , TRANSNUCLEAR, INC

8010210237 Ack receipt of 800904 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Repts 99900092/80-01 t 71-9016/80-01 FOTAPDVS.V Region 4. Dallas. Vendor Inspection Branch 80/09/18

--8010210248 Forwards GA Program Insp Repts 99700092/80-01 & 71-9016/80-01 on 800707-11 ? notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/08/01 2en

--8010210253 Notice of deviation from insp on 800707-11
* Region 4. Dallas, Office of the Director 80/07/20 ip

--B010210258 QA Program Insp Repts 99900092/80-01 & 71-9016/80-01 on B00707-11 Noncompliance noted testing of completed products documents did not address specs required by QA manual & App E MCNEILL, W M, WHITEBCLL.D E Region 4. Dallas, Vender Inspection Branch B0/07/30 Spp

DOCKET 71-9018 MODEL BU-4, GENERAL ELECTRIC CO

BO10150076 Approves request for registration as user of Model BU-6 MACDDMALD.C E Transportation Branch 80/09/29 1p

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

B010270137 Forwards Revision & to Certificate of Compliance 9019 for Model BU-7 MACDONALD,C E Transportation Branch 80/10/15 2pp

--8010270141 Certificate of Compliance 9019 Revision & for Model BU-7. MACDONALD, C E Transportation Branch 80/19/15 3pp

SOCKET 71-9022 MODEL CE-250-2, COMBUSTION ENGINEERING CD., INC.

8010270118 Forwards Revision 5 to Certificate of Compliance 7022 for Model CE-250-2 MACDONALD, C.E. Transportation Branch 80/10/14 2pp.

--8010270122 Certificate of Compliance 9022.Revision 5.for Model CE-250-2 MACDDMALD.C E Transportation Branch 80/10/14 3pp

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC.

8010100234 Approves request for registration as user of Model 660, in response to request.

MACDONALD,C E Transportation Branch 80/09/24 ip

DOCKET 71-9034 MODEL TRIGA-1, GENERAL ATOMIC CO

B009170190 Application for amend to Certificate of Compliance 9034 substituting revised drawing & allowing use of packages fabricated w/current DOT-required labeling Amend fee encl MORRY, W R General Atomic Co (subs of Gulf Oil Co) 80/08/28 to

--8009170193 "Fuel Shipping Container TRIQA I " Sheet 1 of i 4 Denaral Atomic Co (subs of Gulf Dil Co) 80/08/04 ip

DOCKET 71-9036 MODEL. C-1, SOURCE PRODUCTION EQUIPMENT CO

8010090075 Notification of registration as user of Models 6717-8 & C-1 MACDONALD,C E Transportation Branch 80/09/29 ip

DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO.

8007170197 Application for amend to Certificate of Compliance 9037 substituting revised drawing & allowing use of packages fabricated w/current DOT-required labeling Amend fee encl MOMRY, W R General Atomic Co (subs of Oulf Oil Co) 80/08/28

---8009170203 "Fuel Shipping Container.TRIGA II " Sheet 1 of 1 4 General Atomic Co (subs of Gulf Gil Co) 80/08/04 is

DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.

B010270423 Ack receipt of Certificate of Compliance 9039. Revision 5 for Model 715 Future correspondence should be forwarded to Wilmington, NC 9188018 D.L. Babcock & Wilcox Co. 80/10/01 ip.

DOCKET 71-9044 HODEL GE-1600, GENERAL ELECTRIC GO

8010100028 Approves request for registration as user of Model QE-1600in response to request MACDONALD.C E Transportation Branch 80/09/27 1p

8010220682 Forwards Revision 5 to Certificate of Compliance 9044 for Model GE-1600 MACDDNALD.C E Transportation Branch 80/10/08 3pp

--8010220684 Certificate of Compliance 9044, Revision 4. for Hodel 0E-1600 HACDONALD, C E Transportation Branch 80/10/08 4pp

DOCKET 71-9049 MODEL GE-500. GENERAL ELECTRIC CO.

8010270128 Forwards Revision 3 to Certificate of Compliance 9049 for Model 0E-500 MACDDNALD.C.E. Transportation Branch, 80/10/14 ip.

--B010270131 Certificate of Compliance 9049, Revision 3, for Model GE-500 MACDONALD, C'E Transportation Branch 80/10/14. 3pp

DOCKET 71-9087 MODEL FPD 100, GENERAL ATOMIC CO

8010300674 Application for renewal of Certificate of Compliance 9057 for Model FPD-100 Fee enc1 MURRY, N R General Atomic Co (subt of Ouif Dil Co) 80/09/30

DOCKETED ITEMS

8010220437 Notifies that Certificate of Compliance 9057 for Model FPD-100 expines on 801031 Continued use of package is contingent on request for renewal MACDDMALD.C E Transportation Stanch 80/10/07 ip

DOCKET 71-9074 MODEL AP-160, ANEFCO, INC

8010150074 Approves request for registration as user of Model AP-100. MACDONALD.C E Transportation Branch 80/09/29 Ip

DOCKET 71-9090 MODEL 480M. ALLIED CHEMICAL CORP

8010030180 Informs of failure to receive NRC reply to 800328 ltr requesting registration as user of Hodel 30 A SINKE,0 J Kerr-McGee Nuclear Corp 80/09/04 1p

DOCKET 71-9094 MODEL CHSI-21-300, CHEM-NUCLEAR SYSTEMS, INC

8010230518 Approves registration as user of Model CNB-21-300, in response to request MACDONALD, C E Transportation Branch 80/09/24 ip

DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC.

8010270253 Advises that proposed Revision 4 of SAR for Model T-3 should be issued in name of DDE, Richland, NA PETERSON, J M Energy, Dept of 80/09/26 ip

DOCKET 71-9136 MODEL OF 9136, GENERAL ELECTRIC CO

B010010034 Application to amend Certificate off Compliance 9136, modifying approved Model GE-9136 as identified in encl drawings Fee encl GUNNIKOHAM.O E General Electric Co 80/08/15 3pp

--8010010037 "GE Packaging Model 9136" Sheet Number 908E615 MUNIS,J General Electric Co BO/08/19 ip

--8010010039 "GE Packaging Model 9136" Sheet Number 908E627

--8010010042 "GE Packaging Model 9136" Sheet Number 9086620 MUDIS, J General Electric Co 80/08/19 1p

DOCKET 71-9853 MODEL ORNL - BNL - NBS UN FUEL CONTAINER, ENERGY,

8010100253 Approves request for registration as user of Model DRML-UNIR-CONT, in response to request MACDONALD, C.E. Transportation Branch 80/09/24 ip

1

Ì

NONDOCKETED ITEMS

	1
LOCFR	COMMISSION MEETING RECORDS
8010020072 discuss C 1-28 Commis	Transcript of 600919 public meeting in Washington.DC to ommission program to review OL applications Pp sioners 80/09/19 30pp
BO10020092 to discus teams Pp statement # Commis	
BO10060177 proposed * Commis	Transcript of 800919 public meeting in Washington,DC re amend to 10CFRSO concerning ATWS Pp 1-81 sioners 80/09/19 84pp
8010070171 Washingto # Commis	Transcript of 800919 Affirmation Session 80-41 in n.DC Pp 1-8 sioners 80/09/19 11pp
Washingto	Transcript of 801016 Affirmative Session 80-45 in n.DC to discuss'SECY-A-80-108 Pp 1-5. sioners 80/10/16 Spp
SEC Y-80-3	Franscript of NRC 801016 meeting in Washington,DC to discuss 25 re unresolved safety issues sioners 80/10/16 59pp
& yote on	Transcript of NRC 801016 mweting in Washington DC to discuss fire protection program Pp 1-84.Viewgraphs encl sioners 80/10/16 93pp
briefing Pp 1-34 S	Transcript of NRC 801015 public maeting in Weshington,DC re on NRC equal employment apportunity program upporting info encl sioners 80/10/15 137pp
NRC 79080	Forwards Commission determination releasing transcript of 3 budget markup morning session Office of the Becretary of the Commission 80/10/14
Washing transcr	2 Transcript of NRC 790808 budget markup morning session in ton.DC Pp 1-115 Commission determination releasing ipt encl. issioners 79/08/08 117pp
8010270269 800818 me # Adviso	Transcript of Advisory Committee on Medical Uses of Isotopes eting in Bathesda MD Pp 1-151 ry Committee on Medical Uses of Isotopes BO/0B/iB i5ipp
of Isat	9 Forwards transcript of Advisory Committee on Medical Uses opes 800818 meeting V.L. Licensing Management Branch 80/10/10 20p
Cormissio	Forwards Commission determination releasing transcript of n 790808 meeting.afternoon session.re FY81 budget . Office of the Becretary of the Commission. 80/10/14
790808	6 Commission determination releasing transcript of Commission meating, afternoon session, in Washington, DC Pp 1-35 issioners 80/10/14 36pp

B010300511 Forwards Commission determination releasing transcript of Commission 790809 meeting re FYB1 budget.

MOYLE, J. C Office of the Secretary of the Commission. 80/10/14.

```
--80103005i9 Commission determination releasing transcript of Commission 790809 meeting in Washington DC Pp 1-7 4 Commissioners 80/10/14 8pp
B010300518 Forwards Commission determination releasing transcript of
Commission 770807 meeting, morning session, re FY81 budget
HDYLE, J C Office of the Secretary of the Commission 80/10/14
---B010300517 Commission determination releasing transcript of Commission 790B07 neeting.morning session, in Washington, BC Pp 1-113 + Commissioners 80/10/14 114pp
8010300325 Forwards Commission determination releasing transcript of Commission 790806 meeting re FYB1 budget HQYLE.J C Office of the Secretary of the Commission 80/10/14
--8010300528 Commssion determination releasing transcript of Commssion
790806 meeting in Hashington DC Pp 1-86
+ Commissioners 80/10/14 87pp
                                ADVISORY COMMITTEE ON REACTOR BAFEGUARDS
ACRS
8010080147 Summary of ACRS Reactor Operations Subcommittes 800804 meetings re Omeha Public Power District application for power level increase & role of NRC resident inspector in increase in direct inspector & increase in direct inspector & ACPS - Advisory Committee on Reactor Safeguards 80/08/21 13pp
B010080154 Summary of Regulatory Activities Subcommittee 800805 meeting re review of revisions to 100FR50 & reg guides # ACR8 - Advisory Committee on Reactor Safeguards 80/07/04 11pp
8010080165 Summary of Safety Philosophy Criteria Subcommittee 800806 meeting re-progress on development of requirements & presentation on proposed Ofc of Policy Evaluation plan for
       developing safety goals.
4 ACRS - Advisory Committee on Reactor Safeguards 80/09/06 Spp
8010080176 Summary of ACRS Metal Components Subcommittee 800617-18 meeting re review of math metallurgy & mechanical angineering portions of NRC research budget & status rept on Hestinghouse I ow pressure turbine disc cracks & failures ACRS - Advisory Committee on Reactor Safeguards 80/07/21
8010080616 Summary of ACRS Reactor Safety Research Subcommittee 800708 meeting re review of pertinent portions of NRC reactor safety research program & draft ACRS rept to NRC **

** ACRS - Advisory Committee on Reactor Safeguards 80/08/12 8pp
8010090100 Summary of ACRS Reactor Operations Subcommittee 800520 meeting re review of programs & FYS2 budget of Research Support Branch of Ofc of Nuclear Regulatory Research per ACRS rept to NSC & Congress.

ACRS - Advisory Committee on Reactor Safeguards 80/06/16 18pp
B010090103 Bunmary of ACRS Subcommittee on Class ? Accidents 800509 meeting in Chicago.IL re-status of rulemating on degraded core cooling & Class ? accident safety research program # ACRS - Advisory Committee on Reactor Safeguards 80/07/11
8010090106 Summary of ACRS Waste Mgt Subcommittee & Fuel Cycle
Subcommittee 800626 & 27 joint meeting re review of proposed
1982 safety research budget
# ACRS - Advisory Committee on Reactor Safeguards 80/07/14
BO100901A9 Minutes of ACRS Subcommittee on Extreme External Phenomena
B00804 meeting in Washington.DC re-selsmic design of
nuclear power reactors.Task Action Plan 40 & funding for
research.W/supporting documentation.
* ACRS - Advisory Committee on Reactor Safeguards B0/09/06 13pp
```

304		
8011	8010090173 Hinutes of ACRS Subcommittee on OETR 800516-17 meeting in SumpliCA re geology, seismology & structure; smalneering	
FI	aspects of facility * ACRB - Advisory Committee on Reactor Hafequards - 80/08/08	
Mi	lippp,	
DDCI	8010090178 Minutes of ACRS Subcommittee on Advanced Reactors 791129 masting in Albuquerque, NM re HRC appropried research on	
DDC1	safety of advanced reactors W/supporting documentation	
	* ACRS - Advisory Committee on Reactor Bafeguards 80/03/25 71	DD.
8014		
Ma	8010090180 Minutes of ACRB Reactor Fuel Subcommittes 800429 meeting	
	Washington, DC rs NRC research program concerning fuel	ın
	behavior H/supporting documentation.	
DOCI	* ACRB - Advisory Committee on Reactor Safeguards 80/06/27 51;	р
8010	9010090463 Submits schedule & discussion outline for 242nd ACRB	
P4	meeting on 600405-07 in Weshington, DC.	
ន	* ACRB - Advisory Committee on Reactor Safeguards 80/05/21 4pg	,
	8010090466 Submits tentative schedule for ACRS subcommittee 800617-18	ì
DOCI	maeting on matal components in Washington, DC EPRI safety	
	relief valve test program questions encl * ACRB - Advisory Committee on Reactor Bafequards 80/06/12 4ss	
8011	* ACRB - Advisory Committee on Reactor Bafeguarés 80/06/12 App	
r.		
Mi	8010070493 Forwards comments on draft reg guide RS 705-4. "Lightning	
	Protection for Nuclear Power Plants " New distribution	
	frequency curve based on strate data to stricken heights no	
DOCI	greater than 60 maters has been developed. JOHNSDN:IB Affiliation Unknown 80/04/10 98pm	
POC!	JOHNSON-I B Affiliation Unknown 80/04/10 98pp	
801:	SOLOTEOLOGY Transcript of ASS Cuberralation of Hoste Mat Solden	
b.	6010150180 Transcript of ACRS Subcommittee on Waste High 801003 mornin meeting in Washington, DC re proposed NRC rule on technical	9
Ρί	criteria for regulating geological disposal of high lavel	
	radwaste & waste confidence rulemaking. Pp 1-234	
	# ACRB - Advisory Committee on Reactor Safeguards 80/10/03	
	6010150642 Suggeste revisions to Reg Guide 1 97 re defining	
	instrumentation requirements for varied emergency resonner	
	functions & integration of various made	
	CATTON I ACRS - Advisory Committee on Reactor Safeguards	
	60/08/15 2pp	

- 8010150644 Discusses 800819-20 meeting or BMR scram sys & suggests safety sys be evaluated for possible interfacing w/nonsafety sys to eliminate problems resulting in scram sys failures CATTOM! ACRS Advisory Committee on Reactor Bafeguards 80/09/15. 2pp
- 8010160114 Discusses ORNL blow down heat transfer program & suggests procedural & developmental review of radiation contribution re heat transfer CATTON I. ACRS - Advisory Committee on Reactor Safeguards. 80/09/04 App
- G010160576 Summerizes 246th ACRS meeting on G01009-11 re SECY-80-438A, proposed rule on fire protection. Extremely prescriptive requirement of Branch Technical Position 9 5-1 does not provide best means to assure safety PLESSET.N. S ACRS Advisory Committee on Reactor Safeguards R0/10/14 20.0 B0/10/14 200
- 8010160604 Transcript of Bubcommittee on External Phenomena 801008 hearing in Hashington, DC Pp 1-104 e ACRS Advisory Committee on Reactor Bafeguards 80/10/08, 104pp.
- 8010160610 Transcript of Bubcommittee on Safety Philosophy, Technology & Criteria 801008 hearing in Washington, DC, Pp i-185.

 * ACRS Advisory Committee on Reactor Safeguards. 60/10/08,
- 8010160615 Transcript of Subcommittee on Reactor Operations 801007 seating in Weshington, DC. Pp 1-128 + ACRS Advisory Committee on Reactor Safeguards. 80/10/07 138pp.
- 80101606R3 Transcript of 246th general mesting of advisory committee on 801009 in Washington, DC re nuclear data link, Pp 1-76. a ACRB Advisory Committee on Reactor Safeguards. 80/10/09, 76pp.
- 8010140627 Transcript of Subcommittee on Advanced Reactors 801008 meeting in Washington, DC. Pp 1-30.

 * ACRS Advisory Committee on Reactor Safeguards. 80/10/08. SOpp.

- 6010170015 Responds to 800812 ltr to WJ Dircks as need for islate evaluations due to cascading failures in nuclear plants. Bys Integration Branch will take lead role in developing criteria & methods for subsequent sys interaction review DENTON.H R Office of Nuclear Reactor Regulation, Director 80/09/27
- --8010170024 Requests NRC advice re approach to examining causely-failures in nuclear plants PLESSET, M B ACRS Advisory Committee on Reactor Safeg. 1111 89/08/12 2pp
- B010170064 Notice of ACRS 800807-09 meeting in Washington CC HOYLE, J C Office of the Sacretary of the Commission 80.
- 8010170074 Schedule & outline for discussion at 243rd ACRJ appli pa 800710-12 in Washington.DC. * ACRS Advisory Committee on Reactor Safeguards 80/07/02 14
- 8010170299 Draft revised notice of ACRS 800710-12 meeting Past's revised to permit discussion of recent operating experience at nuclear facilities which represent substantive safety issues possibly impacting public hoalth & safety HDYLE, J C. Office of the Secretary of the Commission, B9709-13
- B010170467 Draft notice of ACRS 7B1107-11 meeting w/West Garact Fig. 5
 Bafety Committee in Washington. DC to discuss reactor safety policy & practice in US & West Germany HDYLC. J C Office of the Secretary of the Commission 801.4.2
- B010200014 Submits comments on ACRS Fluid Dynamics Bubcceelited B00819-20 meeting ACOSTA:A J California Institute of Technology B0/00/21 5;;
- 8010200192 Minutes of ACRS Subcommittee on Fire Protection spelling to discuss proposed 100FR50 rule on fire protection Rule will be discussed at 249rd ACRS meeting # ACRS Advisory Committee on Reactor Safeguards 83/07/31
- --8010200200 Forwards util 800630 comments on proposed firs prelicks rule, II/o encl.
 PARKER, H O Duke Power Co. 80/07/03, 1p
- 8D10210031 Summary of ACRS Subcommittee on Reactor Safety Rassact meeting in Washington, DC re review of proposed FVS2 budget for NRC safety research programs & other related masters # ACRS Advisory Committee on Reactor Safeguards 63/07/11
- 8010210161 Urges that hearing for rulemaking on probabilistic siels for safety assessment be initiated as soon as possible More effort needs to be spent on increasing public confidence in method CATTON, I ACRB - Advisory Committee on Reactor Bafesvires 80/07/09 2pp.
- 8010210512 Requests NRC view on whether BWR 5/6 sqs has addition regiability for source of high pressure unter necessary under ATMB conditions ACRS 800416 ltr did not imply that BMR 5/6 sys had problems similar to early BMRs. FRALEY.R.F. ACRS - Advisory Committee on Reactor Bafejvards 80/10/14 1p
- 8010210389 Comments on NRC preliminary plans for addressing Seldins; of FY80 NRC authorization bill requirements. Endorses AMC intent to implement tight mpt controls to limit effort to areas of potential safety payoff. Refs ACRS 801009 assing FRALEY, R.F ACRS Advisory Committee on Reactor Safeguards 80/10/14, ip
- 8010220117 Transcript of 246th ACRS meeting on 801010 in Washington N Pp 77-277 Viewgraphs, responses to questions to fire protection rule, SECY-80-438A & draft FR notice encl. M: ACRS Advisory Committee on Reactor Bafeguards 60/10/12 400pp
- 8010220161 Discusses methods & results of seismic evaluation of size facilities, per ACRS 800604 subcommittee meeting on setvice external phenomena ESE in new const w/floor of 0.2 g should be adopted w/o being rigidly retroactive.

 THOMPSON. O. A. Affiliation Unknown 80/06/10 ip
- B010220165 Discusses application of probabilistic methods gracewind at ACRG B00604 meeting on extreme external phenomena. Adoption of stronger min SBE should not warrant waiver of meticulous investigation of any site.

 PAGE, B. M. Stanford Univ. B0/06/10 2pp

- 8010220172 Submits add1 comments on draft reg guide RS 705-4, "Lightening Protection of Nuclear Power Plants " Submits corrections to 800410 ltr & typed Pages 31-38 in substitution of Pages 31-40 of encl rept My encl JUHNSQN, I B Affiliation Unknown 80/04/18 tp
- 8010220178 Forwards comments on draft reg guide R8 705-4, "Lightening Protection for Nuclear Power Plants," supplementing 800410 & 18 ltrs Also includes ref page covering Refs 26-40
 JOHNSON, I 8 Affiliation Unknown 80/05/23 46pp
- BO10220182 Change notice of agenda for ACRS BO0904-06 meeting Portions of sessions discussing budgetary info may be closed to public attendance HOYLE, J C Office of the Secretary of the Commission SHIELDS, W M Office of the General Counsel B0/08/27 2pp
- B010220189 Notice of ACRS Ad Hoc Subcommittee B00919-20 meeting w/West Oerman Reactor Bafety Committee in Washington, DC to discuss B&W NSSS, proposed changes in NRC siting criteria & consideration of Class 9 accidents in emergency planning HOYLE-J C Office of the Secretary of the Commission 80/09/03 200
- 8010220240 Submits comments on Class 9 Subcommittee 800702 meeting in Los Angeles.CA Greater priority should be placed on developing capability to monitor & contain severe accidents LEE.JC Michigan. Univ of 80/07/31 3pp
- 8010230123 Summary of 244th ACRS 800807-09 meeting in Washington,DC to discuss unresolved safety issues & Reg Guide 1 87 PLESEST,N 8 ACRS Advisory Committee on Reactor Safeguards 80/08/18 2pp
- 8010230142 Behedule & outline of discussion for 244th ACR8 800807-09 meeting in Washington DC 4 ACRS Advisory Committee on Reactor Safeguards 80/07/28 3pp.
- 8010230146 Revised schedule & outline of discussion for 245th ACRB 800704-06 meeting in Washington, DC + ACRB Advisory Committee on Reactor Befeguards 80/09/02 3pp
- 8010240234 Forwards comments on draft Reg Ouide RB 705-4 re lightning protection for nuclear power plants
 JOHNSON, I B Affiliation Unknown BO/08/10 Spp.
- 8010240294 Comments on Reg Quide 1 97.Revision 2, "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident," LIPINSKI,N C Argonne National Laboratory, 80/08/13 3pp.
- B010240298 Provides brief resume of B00619 discussions w/NRC in Mashington DC Bilver Spring & Bethesda MD re status of work on combination of dynamic loads under various NRC programs Agenda encl QALL: W R Affiliation Unknown 80/07/29 5pp
- 8010280367 Responds to 800812 ltr recommending addition of three unresolved safety issues Single failure criterion is too broad to be designated as separate issue Dr Power supply reliability & control says reliability are acceptable.

 DENION.H R Office of Nuclear Reactor Regulation. Director. 80/10/09 3pp
- 8010280495 Suggests change in format of ACRS findings re review of license applications OILINGKY, V. Commissioners 80/10/02 ip.
- 8010310002 Transcript of ACRB Subcommittee on ECCB 801023 meeting in ID Falls, ID re semiscale & LOFT programs, Pp 280-475. Viewpraphs encl & ACRB Advisory Committee on Reactor Safeguards. 80/10/23.
- 8010310013 Transcript of ACRR Subcommittee on ECCS 801022 meating in ID Faile: ID re semiscale & LOFT programs Pp 1-279.

 ** ACRB Advisory Committee on Reactor Safeguards. 80/10/22.
- 8010310325 Submits observations & recommendations re seismic qualification of auxiliary feedwater sys. Efforts should be made to better qualify risk on plant specific basis in next few months PLESSET.M.S ACRS - Advisory Committee on Reactor Gafeguards. 80/10/15, 2pp

- COMMISSION NRC COMMISSIONERS
- B010020384 Declines 800910 invitation to meet & discuss TMI & other topics re nuclear energy due to extensive business trips Other Commissioners may be contacted HENDRIE.J H Commissioners 80/09/16 ip
- --8010020387 Requests meeting w/JM Hendrie to discuss THI & other topics rs nuclear energy Related documentation encl AXELROD.D M Affiliation Unknown 80/09/10 18pp
- 8010060005 Expresses compratulations for receiving Presidential Rank Award HENDRIE, J M Commissioners 80/09/13 1p
- 8010060008 Congratulates Director as distinguished recipient of Presidential Rank Award HENORIE, J.M. Commissioners. 80/09/13 ip
- 8010060033 Responds to 800714 itr expressing concerns re Model ALARA program for medical facilities Model ALARA program does not involve any changes in tRC regulations or policy Purpose is to improve NRC procedures to assure application of ALARA AHEARNE, J. F. Commissioners 80/09/09 2pp
- --8010060040 Expresses concern re model ALARA program for medical facilities. Recommends that NRC 800616 ltr be rescinded by Commissioners ALARA approach should be published in FR for comment & apply to all licensees HOLEMANU O R. American Association of Physicists in Hedicine COLEMANU O R. HOLEMAN, O R. /
- --B010060045 Ltr to all medical licensees forwarding revised ALARA program to be implemented by B00B15 Revised program reduces administrative burden on licensee & provides mgt tool for maintaining occupational exposures ALARA DIRCKB.W J. Office of Nuclear Material Bafety & Bafeguards. B0/06/13. 9pp
- 8010060080 Weekly info rept for wk ending 800917 REHM,T A Office of the Executive Director for Operations 80/09/24. 27pp.
- 8010070631 Provides Subcommittee on Energy Nuclear Proliferation & Federal Sycs w/answers to Senator Mathias questions re NRC B00418 appearance before committee. Approx 38% of Commissioner time spent on nuclear export matters AHEARNE.J F, Commissioners. 80/09/11, 25pp rt matters 25pp
- --B010070648 Requests answers to encl questions re NRC 800419 appearance before committee QLENN.J. Benate, Governmental Affairs 80/05/06 2pp
- 8010080192 Provides Subcommittee on Federal Spending Practices & Open Govt w/data re meetings under Sunshine Act, Jan-June 1980 Includes total number of open meetings, closed meetings & partially closed meetings, AHEARNE.J.F Commissioners 80/09/16 1p
- --B0100B0198 Requests info re meetings conducted under Sunshine Act. Jan-June 1980 CHILES.L Senster Governmental Affairs 80/08/25 1p
- BOIO100081 Provides Subcommittee on Energy, Research & Production w/ responses to BOO724 questions on high level waste mgt DAVIS, J. O. Office of Nuclear Material Bafety & Bafeguards BO/09708. 15pp
- --- 8010100095 Requests response to encl addl questions on high level waste mgv. MCCORMACK, M. House of Rep., Brience & Technology, 80/07/24 3pp
- 8010100128 Forwards twentieth rept on AOs at licensed nuclear facilities for first calendar querter 1980, W/o encl AHEARNE, J. F. Commissioners, 80/09/23, 1p.
- --B010100130 Forwards twentieth rept on AUs at licensed nuclear facilities for first calendar quarter 1780 AHEARNE, J. F. Commissioners. B0/09/23, 1p.
- 8010140114 Ack receipt of 800705 ltr invitation to speak at dinner in NY City, Invitation is accepted for after first of yr. HENORIE, J. M. Commissioners 80/09/10. ip
- --8010140117 Invites JM Hendrie to address NY business community either in Nov 1980 or during beginning of yr COULT.C.M. Touche Ross & Co. 80/09/05, ip

- 8010130217 Weekly info rept for wk ending 800926 REHM.T A Office of the Executive Director for Operations 80/10/02 28pp
- 8010160001 Ack receipt of 800827 ltr invitation to nuclear power forum invitation is accepted, schedule permitting HENDRIE, J M Commissioners 80/09/09 lp
- --8010160002 Invites JM Hendrie to participate in forum on safety of nuclear energy HILLIAMS E. AUSTIN COLLEGE SHERMAN, TX 80/08/27 1p
- 8010200003 Expresses appreciation for visit & tour of San Jose facilities
 HENDRIEJ M Commissioners 80/09/19 ip
- 8010200004 Expresses appreciation re invitation to attend BWR training conference dinner
 MENORIE.J M Commissioners 80/09/19 1p
- 8010210786 Discusses enci direct mail advertisement bearing Hendrie quote against First Amendment protection of freedom of press Forwards 790430 ltr to American Newspaper Publishers Association explaining remark as wry joke HENDRIE, J M Commissioners 80/09/15 2pp
- 8010220115 Forwards 800917 memo re delegations of authority Requests comment
 AMEARIC, J F Commissioners 80/09/17 ip
- --8010220120 Submits President's Reorganization Plan Number I for 1980 re delegation of authority for Executive Director of Operations, effective 801001 AHEARNE, J F Commissioners 80/07/17 2pp
- 8010230082 SECY-80-439
 Westly into rept for wk ending 800912
 REHH,T A Office of the Executive Director for Operations
 60/09/19 30pp
- 8010230274 Weekly info rept for Wi ending 801003 REHM.T A Office of the Executive Director for Operations 80/10/08 28pp
- B010270548 Forwards NUREG-0728,-0729 & -0730 re actions taken or being taken to improve NRC response to nuclear plant incidents or emergencies Submittal satisfies requirements in P L 90-295 W/o sncl AHEARNELJ F Commissioners B0/L0/03 4pp
- --8010270557 Forwards NUREG-0728.-0729 L -0730 re actions taken or being taken to improve NRC response to nuclear plant incidents or emergencies Submittal satisfies requirements in P L 90-295 AHEARKE, J. F. Commissioners
- --8010270364 NUREG-0728
 "Rept to Compress NRC Incident Response Plan " Oversize charts encl
 + Office of Inspection & Enforcement, Office of the Director 80/09/30 27pp
- --8010270566 NUREG-0729
 "Rept to Congress on NRC Emergency Communications "
 * Office of Inspection & Enforcement, Office of the Director 80/09/30 30pp
- --B010270570 NUREO-0730
 "Rept to Congress on Acquisition of Reactor Data for NRC Operations Ctr"
 "Office of Inspection & Enforcement, Office of the Director B0/07/30 26pp
- 8010280049 Weekly info rept for wk ending 801010 REHM.T A Office of the Executive Director for Operations 80/10/15 56pp
- 8010280085 Responds to 800730 request for info re disposal of nuclear waste off CA coast AEC authorized low level waste disposal sites in Pacific Ocean prior to 1972 EPA now has responsibility for ocean disposal Wisopporting info AHEARNE.JF Commissioners 80/10/01 19pp.
- --B010280092 Requests info re alleged nuclear wasta repository off Mendocino coast in northern CA CLAUSEN, D H. House of Rep. 80/07/30, 2pp.

- 8010280495 Suggests change in format of ACRS findings re ravity at license applications GLLINSKY-V Commissioners 80/10/02 ip
- 8010290280 Provides Subcommittee on Environ Energy & Natural Regarded w/response to 800828 request for info re present & future use of ocean for radwaste disposal No regulatory development planned for high or low level waste ocean disposal AHEARNE, J F Commissioners 80/10/01 4pp
- --8010290281 Provides Subcommittee on Environ, Energy & Natural Refer a
 w/response to 800828 request for info re present & future
 use of ocean for raduaste disposal No regulatory development
 planned for high or low level waste ocean disposal
 AMEARNE, J.F. Commissioners 80/10/01 4pp
- --B010290284 Responds to 800828 request for info re present & fus.re
 use of ocean for radwaste disposal No regulatory development
 planned for high or low level waste ocean disposal
 AMEARNE, J F Commissioners 80/10/01 App
- --8010290288 Responds to 800828 request for info re present L fujurations of ocean for raduaste disopsal No regulatory development planned for high or low level waste ocean disposal. Related info encl

 AHEARNE. J F Commissioners 80/10/01 26pp.
- --8010290295 Requests info re ocean disposal of radwasts NRC possition of ocean disposal also requested, HOFFETT.T , MCCLOSKEY.P N House of Rep , Government Operations BURTOII.J L House of Rep , Sp
- 8010300132 Forwards memo re new safety concepts for future conit Requests comment & suggested improvements AHEARNE.J F. Commissioners 80/09/11 1p
- --B010300138 Requests response to question re NRC effort toward developing new safety concepts for possible future const of nuclear power plants Requests views as to proper level of effort AMEARIKE, J.F. Commissioners 80/09/11 1p
- 8010300275 Weekly info rept for Wk ending 801017 REHM.T A Office of the Executive Director for Operation; 80/10/22 26pp
- B010300547 Bubmits comments on proposed H R 7506. "Limitations on Call Recordkeeping Requirements & Actions of 1980" NRC should be exempted from limitations on enforcement period such as H R 7506 would impose AHEARNE.J F. Commissioners 80/10/14 2pp
- --8010300552 Forwards proposed H R 7506, "Limitations on 9evt Recordkesping & Actions of 1980 " Comment requested, BROOKS.J House of Rep., Government Operations 80/06/12 413
- CONTRACT NEC CONTRACTS AND MODIFICATIONS
- 8010010107 Notification of contract execution, Mod 8 to "Svcs of MR Johnson on ABLAP" Contractor Univ of VA CDLEMAN, R Administrative Contracts Branch NRC-10-75-140, 8D/09/18 1p
- --8010010113 Mod 8,providing correct total NRC obligations.to 'Syst +F WR Johnson on ASLAP " → Virginia, Univ of MATTIA,M J Administrative Contracts Branch NRC-10-75-140 80/09/18 ip
- B010010229 Notification of contract execution,Mod 2 to "Review i Evaluation of Ocologic & Science Features of Nuclear Power Sites " Contractor DDI HAIRSTON,C Technical Assistance Contracts Branch, FIN 8-6879 NRC-03-80-113, 80/09/16 1p
- --8010010232 Mod 2, increasing funds to "Review & Evaluation of Casiffit & Salamic Features of Nuclear Power Sites" * Interior, Dept of DDUOMERTY, D J Technical Assistance Contracts Branch. FIN B-6837 NRC-03-80-113 80/07/16 1)
- 8010010247 Notification of contract execution, Mod 7 to "Btudy #1 N4# England Belsmicity H/Emphasis on MA & NH * Contractor: MII. BROMBERO, B Research Contracts Branch. FIN A-4058 NRC-04-74-757 8D/09/12 [p

- --B010010253 Mod 7.extending period of performance & increasing funds to.
 "Study of New Seismicity W/Emphasis on MA & NH "
 DUMMER.O Massachusetta Institute of Technology MORTON, K V
 Research Contracts Branch FIN A-4058 NRC 04-76-209 80/09/12
 400
- BO10010252 Natification of contract execution, Mad 1 to "Conversion, Programming, Implementation & Documentation of NRC Automated Personnel Sys " Contractor Rehab Group, Inc HEGOINS, E J Administrative Contracts Branch NRC-10-80-390 B0/09/22 1p
- --B010010262 Mod i.increasing estimated cost & fixed fee & providing furnishing of space.to "Conversion. Programming. Implementation & Documentation of NRC Automated Personnel Sys "

 * Rehab Group, Inc. MATTIA Administrative Contracts Branch COLLINS,F M Bail Business Administration NRC-10-80-390 B9/09/22 3pp
- 8010010255 Notification of contract execution.Mod 1 to "Emergency Procedures Criteria for Nuclear Power Plant Operations " Contractor XYZYX Info Corp MAIRETON.C Technical Assistance Contracts Branch FIN 8-6872 NRC-03-80-118 80/09/05 ip
- --8010010261 Mod 1.modifying statement of work & revising period of performance & effective date for govt-furnished matl to "Emergency Procedures Criteria for Nuclear Power Plant Operations"

 *** XYZYX Information Corp DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6872 NRC-03-80-118 80/09/05 4pp
- B010010260 Notification of contract execution, Mod 2 to "Stony Brook Seismic Network on Long Island, NY Operation & Maint " Contractor Research Foundation of State Univ of NY HAGEY, SI Research Contracts Branch FIN B-6616 NRC-04-79-208 80/09/12 1p
- --B01001026B Mod 2, extending period of performance & increasing funds, to "Stony Brook Seismic Network on Long Island, NV Operation & Maint"
 PARR.R G New York, State Univ of, Stony Brook MORTON, K V
 Research Contracts Branch FIN B-6616 NRC-04-79-208 B0/09/12
 4pp
- 8010010269 Notification of contract execution Mod 11 to "Consulting Bycs (A-E) Related to Evaluation of Facility Concepts, Cost Estimates & Schedules for Experimental Facilities " Contractor Burns & Roseinc MORTON: K V Research Contracts Branch FIN B-6220 NRC-04-77-097 80/09/17 1p.
- --BOLOGIO279 Mod ii, increasing funds to "Consulting Svc (A-E) Related to Evaluation of Facility Concepts.Cast Estimates & Schedules for Experimental Facilities "PUCILLO, A C Burns & Roe Co MORTON, K V Research Contracts Branch FIN B-6220 NRC-94-77-097 E0/09/17 ip
- 8010010272 Notification of contract specution, Mod 4 to "Carser Counseling " Contractor Binder, Elster, Mandelson & Wheeler, Inc.
 MIGOINS, E. J. Administrative Contracts Branch NRC-10-79-387.
- --8010010278 Mod 4, revising Item 4 of Mod 3 requiring contractor to furnish of c space for counseling sassions from 600917-810916 to "Career Counseling" a Binder, Elster, Mendelson & Wheeler, Inc. MATTIA, M. J. Administrative Contracts Branch NRC-10-79-387 80/09/17, 18
- 8010010273 Notification of contract exacution Mod 2 to "State Transportation Surveillance Program." Contractor: SC Dept of Health & Environ Control FLYNN.M Administrative Contracts Branch FIN 8-1612 NRC-06-78-357, 80/09/18
- --8010010282 Mod 2.extending period of performance for addityr & increasing total amount of contract by \$15,000 to "State Transportation Surveillance Program"

 DANTZLER.M.U Bouth Carolina. State of MATTIA.M J

 Administrative Contracts Branch BANTMAN.L.D

 Transportation.Dept of FIN 8-1612 NRC-06-78-357 80/09/18.
- 8010010276 Notification of contract execution.Mod B to "Central VA Regional Beismic Natuork " Contractor Polytechnic Inst & State Univ.
 JACOBS.A Research Contracts Branch. FIN B-6247 NRC-04-77-134 80/09/12 lp.

1

- --8010010281 Mod 5, extending period of performance one yr & increasing funds, to "Central VA Regional Seismic Network"

 KREBS, A H Virginia Tech MORTON, K V Research Contracts Branch
 FIN 8-6249 NRC-04-77-134 80/09/12 4pp
- 8010010286 Notification of contract elecution, Mod 3 to "Career Counseling " Contractor Binder, Elster, Mendelson & Wheeler, Inc.
 HIGOINS, E. J. Administrative Contracts Branch NRC-10-79-387
- --8010010293 Mod 3, extending term of contract & increasing total amount presently obligated to "Career Counseling "MENDELSON, IN Binder, Elster, Mendelson & Wheeler, Inc. MATTIA: M J Administrative Contracts Branch MRC-10-79-387
- 8010010288 Notification of contract elecution, Mod 7 to "Coordination of Federal/State Radiation Control Activities & Assistance in Bolving Radiation Control Programs "Contractor Food & Drug Administration-Public Health Svc FLYNN, M. Administrative Contracts Branch FIN 8-1620 NRC-06-75-247 80/09/18 jp
- --8010010275 Mod 7. increasing funds by add1 \$12,000 to "Coordination of Federal/State Radiation Control Activities & Assistance in Solving Radiation Control Problems"
 GROWN, H H HEW, Dept of, Food & Drug Administration MATYIA. H J Administrative Contracts Branch FIN 8-1620 NRC-06-76-247 80/09/18 1p.
- 8010010291 Notification of contract execution Hod 3 to "Lab Simulation of Tornado Wind Effects on Structures " Contractor Univ of OK BROMBERG.B Research Contracts Branch FIN B-6241 NRC-04-78-207 80/09/12 1p
- --8010010297 Mod 3, extending period of performance & increasing funds to "Lab Binulation of Tornado Wind Effects on Structures " OUFF, C W Oklahoma, Univ of MORTON, K V Research Contracts Branch FIN B-6241 NRC-04-78-207 B0/09/12 4pp
- BO10010279 Notification of contract execution.Mod 1 to "Review of Nonradiological Environ Operating Data " Contractor Environ Science & Engineering Inc HAIRSTON.C Technical Assistance Contracts Branch FIN 8-6854 NRC-03-80-106 80/09/09 1p
- --8010010303 Mgd 2, thanging contractor address to "Review of Nonradiological Environ Operating Data " * Environmental Bystems Corp DOUGHERTY, D Technical Assistance Contracts Branch FIN B-6834 NRC-03-80-106 80/09/09 ip
- B010010300 Notification of contract execution, Hod 2 to "NRC Issuance & Indexes." Contractor Data Composition Svcs. Inc HAONN.T F Administrative Contracts Branch NRC-10-80-661 BD/09/16 1p.
- --8010010304 Mod 2 revising delivery requirements to "NRC Issuances & Indexes."

 WHITE, R J Data Composition Services, Inc MATTIA, M J
 Administrative Contracts Branch NRC-10-80-661 80/09/16 ip
- 8010010310 Revised notification of contract execution, Mod 4 to "Brudy of Crash Loads in Transportation Accidents." Contractor BRI Intl Contract number changed from NRC-03-78-084 to NRC-02-78-084 Mod number changed from 3 to 4 HAIRSTON.C.H Technical Assistance Contracts Branch. FIN 8-6124 NRC-02-78-084 80/08/08 1p
- 8010010366 Notification of contract execution. Hod 3 to "Bafety Assessment of Concrete Nuclear Structures." Contractor HIT BROMBERG, B. Research Contracts Branch FIN B-6618 NRC-04-79-181 80/09/17 io
- --B010010373 Mod 3 extending partod of parformance & increasing funds to "Bafety Assessment of Concrete Nuclear Structures"

 DUMMER: G H , SIMONIDES: C B Massachusetts Institute of Technology MORTON, K V Research Contracts Branch. FIN B-6618.

 NRC-04-79-181 B0/09/17 3pp
- 8010010434 Notification of contract execution, Mod 3 to "Evaluation of Bulk Properties of Radwaste Glass & Ceramic Container Matls to Determine Long-Term Stability." Contractor Catholic Univ of America HAGEV, H Research Contracts Branch FIN 8-6330 NRC-04-78-250 BO/09/17 ip

- --8010010442 Mod 3, extending period of performance & increasing funds to "Evaluation of Bulk Properties of Radwaste Glass & Ceramic Container Motis to Determine Long-Term Stability " MURPHY,J J, CAIN.L F Catholic Univ MORTON,K V Research Contracts Branch FIN 8-6330 NRC-04-78-250 80/09/17 4pp
- 8010020248 Notification of contract erecution "State Transportation Surveillance Program," awarded to NV Dept of Human Resources FLYNN,N J Administrative Contracts Branch FIN 8-1327 NRC-06-80-680 80/09/18 1p
- --8010020255 Contract "State Transportation Surveillance Program," awarded to NV Dept of Human Resqurces CARR:J H New York, State of MATTIA.M J Administrative Contracts Branch SANTMAN.L D Transportation.Dept of FIN B-1327 NRC-06-80-680 80/09/18 89pp
- B010020293 Notification of contract execution.Mod 1 to "Effects on Explosives." Contractor Naval Surface Heapons Ctr HAIRBYON.C Technical Assistance Contracts Branch FIN 8-68120-9 NRC-03-77-153 B0/09/08 1p
- --8010020297 Mod 1:changing NRC representative to "Effects on Explosives" * Navy.Dept of DOUGHERTY.D Technical Assistance Contracts Branch FIN B-6812-9 NRC-03-79-153 80/09/08 Ip
- 8010020589 Notification of contract execution "On-Call & Scheduled Monthly Preventive Maint on ECLIPSE 8/230 Computer Sys," awarded to Computer Sys Support Corp HIGGINS E J. Administrative Contracts Branch NRC-10-80-706 WIGGINS, E J 80/09/23 1p.
- --8010020591 Contract "On-call & Scheduled Monthly Preventive Maint on ECLIPSE \$/230 Computer Sys." agarded to Computer Sys Support Corp RODT,L E Computer Systems Support Corp MATTIA,M J Administrative Contracts Branch NRC-10-80-705 80/ 80/09/23 6700
- 8010020592 Notification of contract execution "Environ Assessment of Surface & Oroundwater Impacts from U Recovery Operations," awarded to Ralph Stone & Co.Inc HAIRSTON.C Technical Assistance Contracts Branch NRC-02-80-028-02 80/09/03 19
- --8010020593 Contract "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Ralph Stone & Co.inc
 & Co.inc
 KAMLER Ralph Stone & Co DBUGHERTY, D J Technical Assistance
 Contracts Branch NRC-02-80-028-02 60/09/03 ip
- 8010020596 Notification of contract execution, Mod 9 to "Design of IFMIS" Contractor Technassociates. Inc HAQAN, T F Administrative Contracts Branch FIN B-5(3) NRC-10-80-395 80/09/15 Ip
- --8010020601 Mod 9,unilaterally changing order to provide for eight oral presentations by contractor to "Design of IFMIS"

 * Technassociates, Inc (MATTIA.H J Administrative Contracts Branch FIN 8-5131 NRC-10-80-395 80/09/15 2pp
- B010020619 Notification of contract execution.Mod 1 to "Review of MCAP-9500" Contractor Nuclear Associates Intl MAIRSTON.C Technical Assistance Contracts Branch. FIN B-6880 NRC-03-80-128 80/09/11 Ip
- --8010020625 Mod 1.deleting L Rubenstein as project officer & substituting W Johnson to "Review of WCAP-9500"

 * Nuclear Associates International DDUGHERTY.D J Technical Assistance Contracts Branch FIN B-6880 NRC-03-80-128
- B010020871 Notification of contract execution "Environ Assessments of Burface & Groundwater Impacts from U Recovery Operations," awarded to Harding-Lawson Associates HAIRETRIN.C Technical Assistance Contracts Branch NRC-02-80-028-05 80/09/04 ip
- --8010020679 Contract "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Harding-Lawson Associates.

 HARDING; R. B., Harding-Lawson Associates DOUGHERTY, D. J. Tech.
 Assistance Contracts Branch NRC-02-80-028-06 80/09/04 ip mir.D J. Technical 80/09/04 Ja
- 8010020598 Notification of contract execution. Mod 1 to "Statistical Review of Documents & Statistical Methods in Risk Assessment " Contractor Small Dusiness Administration. Subcontractor Automated Eciences Group, Inc FLYNN. M. J. Administrative Contracts Branch FIN 8-1321 NRC-07-79-312 80/09/15 ip

- ---8010020703 Mod i.extending period of contract to 801231 & increasing funds to "Statistical Review of Documents & Statistical Methods in Risk Assessment" Methods in Risk Assessment "

 Automated Sciences Group, Inc MATTIA:M J Admin(strative
 Contracts Branch FIN B-1321 NRC-07-79-312 B0/09/15 [p
- B010020711 Notification of contract elecution "State Transportation Surveillance Program," awarded to State of NV Dept of HUMAN Resources
 FLYNN, M J Administrative Contracts Brench FIN B-1327
 NRC-06-80-680 80/09/18 1p
- --8010020716 Contract "State Transportation Surveillance Program," awarded to State of NV Dept of Human Resources CARR, J Nevada, State of MATTIALM J Administrative Contracts Branch SANTMAN.L D Transportation, Dept of FIN 8-1327 NRC-06-80-680 80/09/18 100pp
- BD1003033B Notification of contract execution "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Hittman Associates Inc HAIRBFDI, C Technical Assistance Contracts Branch PERSON, L Uranium Recovery Licensing Branch NRC-02-80-028-04 80/09/03 Is 80/09/03 15
- ---8010030353 Contract "Environ Assessment of Surface & Groundwater Impacts from U Recovery Operations," awarded to Hittman Associates, inc KARN, M J. Hittman Association, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch NRC-02-80-028-04 80/09/03 1p.
- 8010030434 Notification of contract execution, Mod 1 to "Low Level Radwaste Records" Contractor Todd Shipyards Corp BROWN, R B Office of Nuclear Material Safety & Safeguards FIN B-6972 NRC-02-80-058 80/09/10 ip
- --8010030440 Mod f.extending period of performance to 601015 to "Low Level Radwaste Records" HATHWAY,C W Todd Shipyards PERLMAN.J Administrative Contracts Branch Fin 8-6972 NRC-02-80-058 60/07/10 1p
- B0100304B6 Notification of contract execution, Mod 1 to "Const of Nuclear & Fossil Fueled Power Plants" HAIRSTON, C A Technical Assistance Contracts Branch FIN 8-6340 NRC-03-79-125 80/09/24 ip
- --8010030488 Hod 1,increasing funds to "Const of Nuclear & Fossil Fuelta Power Plants "

 4 Labor Dept of DOUGHERTY D J Technical Assistance Contracts Branch FIN 8-6540 NRC-03-79-125 80/09/24 1p
- 8010030543 Natification of contract execution, Hod 3 to "Extension of Blyshine II" Contractor Radiation Research Associates ROSS.D F Division of Systems Integration FIN 0-1199 NRC-03-79-159, 80/09/11 1p
- --8010030945 Mod 3, extending period of performance to 800930, to "Extension of Skyshine II"
 # Radiation Research Associates PERLMAN, J Administrative Contracts Branch FIN 8-11-99 NRC-03-79-159 80/09/11 1p
- 8010040135 Notification of contract execution. Mod 9 to "Design of IFMIS" Contractor Small Business Administration. Bubcontractor Technassociates. Inc. HAGAN. TF Administrative Contracts Branch FIN B-5131 NRC-10-80-395 80/09/15 ip
- --8010060137 Mod 9, providing for eight oral presentations by contractor to "Design for IFMIS" * Small Business Administration * Technassociates. Inc. MATTIA: M J Administrative Contracts Branch FIN 8-5131 NRC-10-80-395 80/09/15 2pp
- 8010090185 Notification of contract execution. Mod 1 to "Environ Monitoring Program W/State of UI " Contractor State of UI BAISDEN.L Administrative Contracts Branch FIN B-5114 NRC-05-80-275 80709729 ip
- --8010080193 Mod i,providing funds for FYBO, to "Environ Manitoring Program W/State of WI" " Wisconsin, State of MORYON, K V Research Contracts Branch FIN B-5114 NRC-05-80-275 80/09/27 1p.
- 8010080302 Notification of contract execution "Environ Assessment of Oroundwater.Contamination in Wood River.RI," awarded to DL Warner, Inc. Administrative Contracts Branch FIN 8-6993-0. LITTLE H NRC-02-80-076

- --8010080305 Contract "Environ Assessment of Groundwater Contamination in Wood River,RI," awarded to DL Warner, Inc WARNER,D L Don L Warner PERLMAN,J Administrative Contracts Branch FIN 8-6993-0 NRC-02-80-076 80/09/17 12pp
- 8010080345 Notification of contract execution "Technical Editing & Writing Assistance for Waste Confidence Proceeding." awarded to Editorial Consultants.Inc MILES.E B Purchasing Section FIN 9-1314 NRC-19-80-473 80/09/24
- --B010080350 Contract "Technical Editing & Writing Assistance for Waste Confidence Proceeding." awarded to Editorial Consultants, Inc. HAVS, M. L. Editorial Experts, Inc. PERLMAN, J. Administrative Contracts Branch FIN 8-1314 NRC-19-80-473 80/09/24 App
- B0100B035B Notification of contract execution, Mod 2 to "Nondestructive Examination (NDE) Mobile Van, Region 1 " Contractor Mobile Bys.
 HIGGINS.E J Administrative Contracts Branch NRC-05-80-259
 B0/09/24 1p
- --8010080361 Mod 2.adding two i1.000 BTU air conditioning units,to
 "Nondestructive Examination (NDE) Mobile Van.Region 1 "
 KIMMEL.J J Mobile 8ystems MATTIA,H J, Administrative Contracts
 Branch NRC-03-80-239 80/09/24 ip
- 8010080611 Notification of contract execution. Hod 1 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst HAIRSTON.C A Technical Assistance Contracts Branch | FIN 8-6590 NRC-03-79-118, 80/09/15 | 1p
- --R0100B0620 Mod 1.developing users manual which provides instructions for access to info & for updating purposes, to "Review Evaluation of Approx 500 Pending Operating Reactor Licensing Actions"

 * Franklin Institute/Franklin Research Center DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-6590 NRC-03-79-118 B0/09/15 2pp
- 8010080619 Notification of contract execution, Mod 4 to "Bys Maint Programming " Contractor Small Business Administration Subcontractor Rehab Group, Inc COLLEMAN.R. Administrative Contracts Branch NRC-10-79-375 80/09/12 ip
- --8010080618 Mod 4,providing ofc space, adding funds & extending period of performance to "Bys Maint Programming" # Rehab Group, Inc COLLING.F M Small Business Administration MATTAIN J. Administrative Contracts Branch NRC-10-79-375 80/09/12 Spp
- 8010080428 Notification of contract execution, Mod 5 to "Kinetics of Chlorine-Ammonia in Sea Water " Contractor Univ of NC JACD85.A. Research Contracts Branch, FIN 8-4248, NRC-04-77-119 80/097/23 ip.
- --B0100B0633 Mod 5.adding funds & extending period of performance.to "Kinetics of Chiorine-Ammonia in Sea Nater."
 HGLCOMB.O R. North Carolina. Univ of MORTON.K V. Research Contracts Branch FIN B-6248 NRC-04-77-119. B0/09/23 App
- 80:0080631 Notification of contract execution Mod 4 to "Bludy of Palezoic Stratigraphy in New Madrid Area of MS Embayment" Contractor:Univ of KY Research Foundation HA0EY.H. Research Contracts Branch NRC-04-76-321 80/09/23 lp.
- --B010080435 Mod 4.extending period of performance & adding funds, to
 "Study of Paleozoic Stratigraphy in New Madrid Area of MS
 Embayment."
 MESLER,F.B. Kentucky, Univ. of MORTON,K V Research Contracts
 Branch, NRC-04-76-321 80/09/23 4pp
- B010080261 Notification of contract execution. Mod 2 to "Steam Generator Tube Rupture Iodine Transport Mechanisms " Contractor Battelle Columbus Labs
 BRAMBERG, B Research Contracts Granch FIN 8-6706
 NRC-04-76-293-1. 80/09/16 ip
- --B010080663 Mod 2, increasing funds, extending period of performence & clarifying workscope, to "Steam Generator Tube Rupture Iodine Transport Mechanisms"
 LUKZ, F. J. Battelle Memorial Institute, Columbus Laboratories, MORTON, K. V. Research Contracts Branch FIN B-6706
 NRC-04-76-293-1 B0/09/16 1p

- 8010080663 Notification of contract execution Mod 6 to "Distribution Coefficients for Transuranic Elements in Aquatic Environ " Contractor Univ of MA JACO88, A Research Contracts Branch NRC-04-76-352 80/09/19 1p
- --8010080667 Mod 6.extending period of performance & providing funds to publish topical repts to "Distribution Coefficients for Transuranic Elements in Aquatic Environ"
 TREIBEL, W C Washington, Univ of MORTOL, K V Research Contracts Branch NRC-04-76-352 80/09/19 4pp
- 8010090006 Notification of contract execution, Mod 1 to "Thermal Stresses in Naste Disposal Sys " Contractor IA State Univ JACOBS.A Research Contracts Branch. FIN 8~6340 NRC-04-78-268 80/09/23 ip
- --8010090011 Mod 1.unilaterally increasing funds.to "Thermal Stresses in Haste Disposal 8ys " HASBROOK.R lowa State Univ MORTON,K V Research Contracts Branch FIN B-6340 NRC-04-78-26\$ 80/09/23 ip
- B010090016 Notification of contract execution, Mod 3 to "3D Redflood Program Intl Communications & Liaison Support " Contractor: NUB Corg BROMDERO, B Research Contracts Branch FIN B-6272 NRC-04-78-202 80/09/23 ip
- --8010090021 Mod 3, increasing cost & funding for payment of foreign income taxes, to "3D Redfinod Program Intl Communications & Liaison Support"
 EDMORDM.L R. NUS Corp MORTON, K V Research Contracts Branch FIN 8-6272 NRC-04-78-202 80/09/23 2pp
- 8010090027 Notification of contract execution. Mod 2 to "Develop Draft Stds on Procedures & Criteria for Assessing Liquefaction Potential of Boils at Nuclear Facilities Bites " Contractor Dept of Army BROMBERG, B Research Contracts Branch FIN 8-10817 NRC-01-77-060 80/09/18 lp.
- --8010070033 Mod 2.deobligating excess funds enabling closeout, to "Develop Draft 8tds on Procedures & Criteria for Assessing Liquefaction Potential of Boils at Nuclear Facilities Sites" GONOVER, N P Army, Dept of MORTON, K V Research Contracts Branch FIN 8-10817. NRC-01-77-060 80/09/18 ip
- 8010070036 Notification of contract execution "Cytogenetic Studies in Grand Junction:CD." awarded to CD Dept of Health OUSTAVE.R Research Contracts Branch FIN 8-71020 NRC-01-80-022 80709723. 1p
- --8010070044 Contract "Cytogenetic Studies in Grand Junction.CO," awarded to CO Dept of Health. TRAYLOR.F A Colorado, State of MORTON.K V Research Contracts Branch FIN 8-71020 NRC-01-80-022 80/09/23 App
- 8010090040 Notification of contract execution,Mod 3 to "Generalized Probable Max Floods in US (OH River Main Stem) " Contractor Nunn Snyder & Associates. BROMBERGO B Research Contracts Branch, FIN B-50927 NRC-01-76-363 80/09/18 ip
- --8010070055 Mod Gideobligating excess funds enabling closeout, to "Generalized Probable Max Floods in US (OH River Main Btem)"
 NNKN, D.E. Nunn, Snyder & Associates, MORTON, K.V. Research Contracts Branch FIN 8-30727. NRC-01-76-363, 80/09/18 1p
- 8Di0090049 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/State of NJ" Contractor State of NJ. BAI8DEN.L Research Contracts Branch. FIN 8-5108 NRC-05-80-270 80/01/01 lp
- ---8010070052 Mod 1, reducing contract amount & providing new monitoring schedule for Squibb facility, to "Environ Monitoring Program W/State of NJ"
 FISHER,E J. New Jersey, State of MORTON, X V Research Contracts
 Branch FIN 8-5108, NRC-05-80-270 80/01/01 3pp
- 8010090856 Notification of contract execution, Mod 6 to "Smismicity & Tectonic Relationships for Upper Great Lakes Precambrian Shield Province " Contractor Univ of MN HAGEY, H Research Contracts Branch. FIN 8-5952 NRC-04-76-289 80/09/22 19

- --8010090061 Mod 6, extending period of performance & adding funds, to "Seismicity & Toctonic Relationships for Upper Great Lakes Precambrian Shield Province" proAntl. AR Hinnesota, Univ of, Minneapolis MORTON, K V Research Contracts Branch FIN 8-3952 NRC-04-76-289 80/09/22
- BOIDO9005B Notification of contract execution, Mod 2 to "Consultant Svcs for NOAA Probable Max Hurricane Study " Contractor Nunn Snyder & Associates anguer « exsociates BROMBERO, B Research Contracts Branch FIN 8-10336 NRC-01-76-325 80/09/18 ip

- --8010090063 Mod 2,deobligating funds enabling closeout,to "Consultant Svcs for NDAA Probable Max Nurricane Study " NUNN,DE Nunn, Enyder & Associates MERTON,K V Research Contracts Branch FIN B-10336 NRC-01-76-325 80/09/18 ip
- B010090059 Notification of contract execution, mud & to "Assessment of Tornado Risks & Analysis of Near Ground Tornadic Wind Field" Contractor TX Tech Univ. NAOEV, H Research Contracts Branch FIN B-5998 NRC-04-76-345 80/09/23 ip
- ---8010070068 Hod A.extending period of performance, to "Assessment of Tornado Risks & Analysis of Near Ground Tornadic Wind Fields "
 JONES,U J Teras Tech Univ MORTON,K V Research Contracts
 Branch FIN B-5998 NRC-04-76-345 80/09/23 2pp
- 8010090040 Notification of contract execution. Mod 9 to "MPA MIS Maint Support Sys " Contractor Small Business Administration Subcontractor Logical Technical Sycs Corp. HAGAN TF Administrative Contracts Branch. NRC-07-77-178 80/09/17 ip
- --8010090054 Mod 9. extending period of performance & increasing funds, to "MPA MIS Maint Support Svcs" quickey, JR Small Susiness Administration MATTIA, M J Administrative Contracts Branch GREEMLEE, E A Logical Technical Service Corp NRC-07-77-178 80/09/17 44pp
- 8010090065 Notification of contract execution, Mod & to "PDR Micrographic Storage & Retrieval Sys " Contractor ACCESS Corp MEDROW, L. A Administrative Contracts Branch NRC-17-79-449.
- --8010090070 Mod 6, increasing quantity & maint coverage, adding software enhancements & increasing total amount of contract, to "PDR Micrographic Storage & Retrieval Sys "
 HEATH, H H Access Corp HATTIA, M J Administrative Contracts
 Branch NRC-17-79-449 80/09/25 10pp
- B010090066 Notification of contract execution, Mod & to "Seismotectonic Study of New England & Adjacent Areas " Contractor Boston College College JACOBS: A Research Contracts Branch FIN B-5961 NRC-04-74-291 80/09/10 jp
- --8010070072 Mod 6, increasing funds unilaterally, to "Geismotectonic Study of New England & Adjacent Areas " O'TOOLE, J Boston College MORTON, K V Research Contracts Branch FIN 8-5961 NRC-04-76-291 80/09/10 ip
- 8010090067 Notification of contract execution.Mod 7 to "Develop Certification Criteria for Industrial Radiographers" Contractor Univ of Lowell OUSTAVER P Research Contracts Branch FIN B-10276 NRC-01-76-337 80/09/23 ip
- --8010090069 Mod 7.extending period of performance, to "Develop Cartification Criteria for Industrial Radiographers" MILER/E F. Lowell: Univ of MORTON, KV Research Contracts Branch. FIN 8-10276 MRC-01-74-337 80/09/23 2pp
- B010090135 Notification of contract execution, Mod 2 to "Development of Official NRC Records Disposition Program " Contractor.
 Bmall Business Administration, Subcontractor UHK Intl Corp LEBO, C D Administrative Contracts Branch NRC-10-80-383
 80/09/16 1p
- --8010090141 Mod 2, adjusting contract deliverables, to "Development of Official NRC Records Disposition Program "
 TUNBSTALL, J E Small Business Administration RUDDEN, M A JVK
 International Corp MATTIA, M, J. Administrative Contracts Branch
 NRC-10-80-383 80/09/16 4pp

- 8010090209 Notification of contrast execution "Gomputer Based Software, Installation. Testing, Documentation, Training & Sys Integration for Implementation of NRC TLD Direct Radiation Monitoring Network," awarded to Applied Physical Technology, MEDROW, A Administrative Contracts Branch NRC-10-80-691 80/09/26 lp
- ~-8010090214 Contract "Computer Based Software Installation, Testing, Documentation, Training, & Sys Integration for Implementation of NRC TLD Direct Radiation Monitoring Network Program," awarded to Applied Physical Technology, Inc MITCHELL, M D Applied Physical Technology, Inc MATTIA, M J Administrative Contracts Branch NRC-10-80-491 80/09/26 78pp
- 8010090220 Notification of contract execution "Acquisition & Installation of 900 LPM Line Printer Subsystem." awarded to Southern Sys. Inc J Administrative Contracts Branch NRC-10-80-689 HIGGINS.E J
- --8010070223 Contract "Acquisition & Installation of 900 LPM Line Printsr Bubsystem." awarded to Bouthern Bys. Inc Bouthern Bystems. Inc MATTIA.M J Administrative Contracts Branch NRC-10-80-609 80/09/24 69pp
- 8010100235 Notification of contract execution "Definition of Bounding Physical Texts Representative of Transport Accidents Reil & Truck." awarded to Ridihalgh Eggers & Associates MCLLETT.8. Research Contracts Branch FIN D-6621 NRC-04-80-102 80/09/08 1p
- --8010100236 Contract "Definition of Bounding Physical Tests Representative of Transport Accidents Rail & Truck." awarded to Ridihalph Eggers & Associates EQOERG.P & Ridihalgh. Eggers & Associates MORTON, K V. Contracts Branch. FIN 8-6621 NRC-04-80-182 80/09/08 App
- 8010100397 Notification of contract execution.Mod 1 to "Licensing Technical Assistance" Contractor Science Applications.Inc. HAIRBTON.C Technical Assistance Contracts Branch FIN 8-6934-0 NRC-02-80-035-0 80/09/22 1p NRC-02-80-035-0
- --8010100379 Mod i, cancelling contract, to "Licensing Technical Assistance" FINDLEY, D.E. Science Applications, Inc. DOUGHERTY, D. Techn Assistance Contracts Branch FIN 8-6934-0 NRC-02-80-035-0.
- 8010140117 Notification of contract execution "Review of Tailings Mgt" awarded to CO State Univ
 HAIRSTON: C Technical Assistance Contracts Branch FIN B-7306-0
 NRC-02-80-082 80/09/26 1p
- --8010140128 Contract "Review of Tailings Mgt," awarded to CD State Univ DOUGHERTY, D J Technical REGNN. J F Colorado State Univ DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-7306-0 NRC-02-80-092 80/09/26 12pp
- Purchasing Section, FIN B-1560 NRC-17-80-452 80/09/29 MILES, E
- --8010140629 Contract "Assessment & Evaluation of Psychological Distress," awarded to A Murphy, Columbia Univ School of Law MURPHY, A W Columbia Univ School of Law PERLMAN, J Administrative Contracts Branch FIN 8-1560, NRC-17-80-452 80/09/29 6pp.
- BOIO140162 Notification of contract execution "Transportation by Sea Verification," awarded to Arms Control & Disarmament Agency. HAIRSTON, C. Technical Assistance Contracts Branch. FIN 8-7302 NRC-02-80-079 80/09/22 ip
- --8010140166 Contract "Transportation by Sea Verification," awarded to Arms Control & Disarmament Agency PASSERO, R.P. U.B. Arms Control & Disarmament Agency, DUO/HERTY, D.N. Technical Assistance Contracts Branch. FIN 8-7302-0. NRC-02-80-079 80/09/22 3pp
- 8010140226 Notification of contract execution "Environ Monitoring Program W/State of MD," awarded to State of MD BAISDEN.L. Research Contracts Branch FIN B-5106 NRC-05-80-269. 80/09/09 1p.
- --8010140230 Contract "Environ Monitoring Program W/State of MD."
 awarded to State of MD
 BUCK.C P. Maryland. State of MORTON.K.V. Research Contracts
 Branch FIN B-3106. NRC-05-80-269 80/09/09 14pp

- 801014023B Notification of contract execution "Technical Assistance in Conduct of Deoscience Operating Reactor Reviews." awarded to DOI HAIRSTON. C Technical Assistance Contracts Branch. FIN B-6876 NRC-03-80-121 80/09/16 1p
- --8010140243 Contract "Technical Assistance in Conduct of Geoscience Operating Reactor Reviews," awarded to DDI PECK, D L Interior, Dept of, Geological Survey DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6876 NRC-03-80-121
- 8010140395 Notification of contract execution "Evaluation of Tailings Mgt Alternatives for Rio Algom, Lisbon Valley Mill," awarded to CO State Univ to CU State Univ HAIRSTON,C Technical Assistance Contracts Branch FIN B-6987-0 NRC-02-B0-073 80/09/26 ip
- --B010140401 Contract "Evaluation of Tailings Mgt Alternatives For Rio Algom, Lisbon Valley Mill." awarded to Co State Univ BROWN, J F Colorado State Univ DDUQHERTY, D J Technical Assistance Contracts Branch FIN B-6987-0 NRC-02-80-073 80/09/26 11pp
- 8010140406 Notification of contract execution "Technical Assistance in Conduct of Geoscience SEP Reviews," awarded to DOI HAIRSTON, C Technical Assistance Contracts Branch FIN B-6877 NRC-03-80-122 80/09716 ip
- --B010140420 Contract "Technical Assistance in Conduct of Geoscience SEP Reviews," awarded to DOI FILBUN.J.R. Interior.Dept of, Geological Survey. DDUGHERTY.D. J Technical Assistance Contracts Branch FIN 8-6877 NRC-03-80-122 B0/09/16 Spp
- 8010140430 Notification of contract execution "Analysis & Verification of CONTEMPT-4 Computer Code:" awarded to Univ of MD FLEENGR.C M Purchasing Section FIN B-7503-0 NRC-03-80-148 B0/097/25. 1p
- --8010140449 Contract "Analysis & Verification of CONTEMPT-4 Computer Code:" awarded to Univ of MD HEDINA,V Heryland, Univ. of PERLMAN,J, Administrative Contracts Branch FIN 8-7503-0 NRC-03-80-148 80/09/25. Spp
- B01014036B Notification of contract execution.Mod 1 to "Analysis & Verification of CONTEMPT-4 Computer Code," Contractor Univ of MD
- Purchasing Section FIN 8-7503-0. NRC-03-80-148 BO/09/25, ip
- --B0:0140374 Mod 1, revising terminology in Article 6 3, to "Analysis & Verification of COMTEMPT-4 Computer Code "

 * Maryland, Univ of PERLMAN, J Administrative Contracts Branch FIN N-7503-0 NRC-03-B0-148 B0/09/25 ip
- 8010150352 Notification of contract execution: "Info Needs for Site Characterization Plans:" awarded to Fugro Inc. OUSTAVE, R P. Research Contracts Branch. FIN B-10190 NRC-01-80-012 B0/09/26 ip.
- --8010150357 Contract. "Info Needs for Site Characterization Plans," awarded to Fugro Inc YOUNG.O.T. FUGRO.INC MORTON.K.V. Research Contracts Branch FIN B-10190 NRC-01-80-012 80/09/24 App.
- 8010130600 Notification of contract execution. "Gregg Shorthand Theory Rawlew,Rapid Reading,ABC Stenoscript Shorthand," awarded to Montgomery County MD Public Schools. LITTLE,M Purchasing Section NRC-10-80-717. 80/09/29 ip
- --8010150649 Contract: "Gregg Shorthand Theory Review, Rapid Reading, ABC Stendscript Shorthand," awarded to Montgomery County MD Public Schools NAOARAJAN, R Montgomery County, MO PERLMAN, J. Administrative Contracts Branch. NRC-10-80-717. 80/09/29 5pp.
- 8010150605 Notification of contract execution, Mod 9 to "Seismic Shear Transfer in Secondary Containment Vessels," Contractor, Cornell Univ HAGEY, H Research Contracts Branch, FIN 8-5688, NRC-04-76-234 80/09/30, 1p,
- --B010180609 Mod 9.extending period of performance & providing add1 funds to "Seismic Shear Transfer in Secondary Containment Vessels." Vessels." RODERS,T R Cornell Univ. MORTON,K V Research Contracts Branch. FIN 8-3689 NRC-04-76-234 80/09/30. 4pp.

- 8010130617 Notification of contract execution.Mod 5 to "Cyprus Mines Corp. Hansen Project Mill Tailings Evaluation " Contractor Fred C Hart. Associates HAIRSTON. C Technical Assistance Contracts Branch FIN 8-6927-0 NRC-02-79-056 80/09/26 ip
- --8010150622 Mod 5,defining Change Order Mod 4,to "Cyprus Mines Corp.Hansen Project Mill Tailings Evaluation" DELANEY,B T Fred C Hart Associates, Inc DOUGHERTY,D J Technical Assistance Contracts Branch FIN B-6927-0 NRC-02-79-056 80/09/26 2pp
- 8010166091 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/Btate of CT " Contractor State of CT BAISDEN,L Research Contracts Branch FIN B-5115 NRC-05-80-276 80/09/29 ip
- --8010160141 Mod 1.providing funding for 1980,to "Environ Monitoring Program M/State of CT" * Connecticut, State of MORTON,K V Research Contracts Branch FIN B-5115 NRC-05-80-276 80/09/29 ip
- 8010160102 Notification of contract execution Mod 2 to "Environ Monitoring Program W/State of NJ" Contractor State of NJ BAISDEN, L Research Contracts Branch FIN 8-5108 NRC-05-80-270 80/09/24 1p
- --B010160144 Mod 2.extending funding for 1980.to "Environ Monitoring Program H/State of NJ." * New Jersey, State of MDRTDN.K V Research Contracts Branch FIN B-5108 NRC-05-80-270 B0/09/26 ip
- 8010160105 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/State of SC " Contractor State of SC BAIBDEN,L Research Contracts Branch FIN B-1112 NRC-05-80-273 80/09/29. ip
- --8010160149 Mod 1, increasing amount of funding for 1980, to "Environ Monitoring Program W/State of 8C " + South Carolina, State of HORTON, K V. Research Contracts Branch FIN 8-1112 NRC-05-80-273 80/09/29 ip
- B010160109 Notification of contract execution. Mod 1 to "Environ Monitoring Program W/State of ME " Contractor State of ME BAIBDEN, L. Research Contracts Branch FIN B-5113 NRC-05-80-274 80/09/29 1p
- --B010160152 Kod 1.extending funding for 1980.to "Environ Monitoring Program W/State of ME " * Maine, State of MORTON, K V Research Contracts Branch FIN B-5113 NRC-05-80-274 80/09/29 ip
- 8010160112 Notification of contract execution:Mod 1 to "Environ Monitoring Program W/8Eate of NY " Contractor State of NY BAIBDEN: Research Contracts Branch FIN 8-5109, NRC-05-80-271. 80/09/29, 1p
- --8010160136 Mad 1.providing funding for 1980.to "Environ Manitoring Program W/Btate of NY" * New York, State of MORTON,K V Research Contracts Branch FIN 8-3109, NRC-05-80-271, 80/09/29 ip
- 8010140116 Notification of contract execution. Mod 1 to "Environ Munitoring Program W/Btate of MD." Contractor: State of MD. BAISDEN.L. Research Contracts Branch FIN 8-5106. NRC-05-80-269 80/09/29 1p
- --8010160159 Mod 1,praviding funding for 1980,to "Environ Monitoring Program W/Btate of MD " * Maryland, State of. MORTON.K V. Research Contracts Branch FIN B-5106 NRC-05-60-269 80/09/29. 1p.
- BD10160122 Notification of contract execution. Hod 1 to "Environ Monitoring Program W/State of CO " Contractor: State of CO BAISDEN,L Research Contracts Branch. FIN 8-5104. NRC-05-80-267 BD/09/29 1p
- ---8010160162 Mod 1.providing funding for 1980.to "Environ Honitoring Program W/Btate of CD." * Colorado. State of. MORTON.K V. Research Contracts Branch FIN 8-5104. NRC-05-80-267 80/09/29 1p
- 8010160125 Notification of contract execution. Hod 1 to "Environ Monitoring Program M/State of CA" Contractor. State of CA BAISDEN.L. Research Contracts Branch FIN 8-5103. NRC-05-80-266 80/09/27 1p

- --B010160167 Hod 1, providing funding for 1980, to "Environ Monitoring Program M/Btate of CA"

 " California: State of HDRTON.K.V. Research Contracts Branch FIN 3-3103 NRC-05-80-266 B0/09/29 ip
- 8010160127 Notification of contract execution. Mod 1 to "Environ Monitoring Program W/State of AL " Contractor State of AL BAISDENIL Research Contracts Branch FIN 8-1233 NRC-03-80-235.
- --8010160170 Mod 1, providing funding for 1980, to "Environ Munitoring Program M/State of AL"

 4 Alakams, Blate of, MORTON, K. V Research Contracts Branch, FIN B-1233 NRC-05-80-255 80/09/29 1p
- 8010160132 Natification of contract execution-Mod 1 to "Environ Monitoring Program W/Commonwealth of PA " Contractor" Commonwealth of PA ATBORN, L. Research Contracts Branch FIN B-5111. NRC-05-80-272 80/09/29.
- --8010160173 Mod 1.providing funding for 1980, to "Environ Monitoring Program M/Commonwealth of PA" * Pennsylvania, State of FIN 8-5111. NRC-05-80-272 80/09/29. 1p.
- 8010160135 Notification of contract execution: "Environ Homitoring Program H/State of DE," awarded to State of DE BAISDENL Research Contracts Branch. FIN 8-1260 NRC-05-80-291 80/09/29, 1p
- --8010160175 Contract, "Environ Monitoring Program W/State of DE," awarded to State of DE HILBON.J.E. Delaware, State of MORTON,K V Research Contracts Branch FIN B-1250, NRC-05-80-291, 80/09/29, 11pp
- 8010160185 Notification of contract execution. "Purchase of Five Secure Voice Terminals W/Desk Sets." awarded to Natl Security Agency.
 FLYNN.H.J. Administrative Contracts Branch NRC-10-80-718.
 80/09/30 [p
- --B010160164 Contract: "Purchase of Five Secure Voice Terminals H/Desk Bets," awarded to Natl Security Agency. DAVIEB.J.L. National Security Agency. MATTIA.M J. Administrative Contracts Branch NRC-10-80-71B. 80/09/30 3pp.
- 8010160191 Notification of contract execution. "Multidimensional Effects in LHR Thermal Hydraulics," awarded to Rensselaer Polytechnic Inst.

 JACUBEA Research Contracts Branch. FIN 8-7272. NRC-04-80-236.
 80709729 ip.
- --8010160196 Contract: "Multidimensional Effects in LWR Thermal Hydraulics:" awarded to Rensselaer Polytechnic Inet LUGUIDICE.J M. Rensselaer Polytechnic Intt. MORTON,K V. Research Contracts Branch. FIN 8-7272. IRC-04-80-238 80/09/29. 7pp.
- 8010160203 Notification of contract execution Mod 11 to "Performance Testing for Personnel Dosinstry " Contractor: Univ of MI OUSTAVE, R. P. Research Contracts Branch. FIN 8-10490 NRC-01-77-180. 80/09/20. ip.
- --8010160208 Mod licauthorizing third round of testing & providing addl funding to "Performance Testing for Personnel Dosimety," MATTHEWS,C. W. Michigan, Univ. of MORTON.K.V. Research Contracts Branch. FIN B-10490. NRC-01-77-180 80/09/30, 1p.
- 8010160217 Notification of contract execution "Classified Bafeguards Program," awarded to ORI.Inc COLEMAN.R. Administrative Contracts Branch. NRC-10-80-367. 80/09/26. 1p.
- --8010160224 Contract: "Classified Bafeguards Program," awarded to ORI, Inc.

 # ORI, Inc. MATTIA, M. J. Administrative Contracts Branch.
 NRC-10-80-369 80/09/26. 125pp
- BO10140233 Notification of contract execution: "Word Processing Svcs." awarded to Automated Correspondence Sys. Inc. COLEMAN.R.H. Administrative Contracts Branch, NRC-10-80-702. B0/09/30. ip.
- --8010160238 Contract: "Word Processing Eves," awarded to Automated Correspondence Bys Inc.

 # Automated Correspondence Eystems: Inc. MATTIA.H.J.

 Administrative Contracts Branch. NRC-10-80-702. 80/09/30. 35pp.

- 8010150317 Notification of contract execution, Mod 2 to "Survey of Bnow Loads on Nuclear Power Plant Structures" Contractor: NBS Ctr for Bldg Technology GUBTAVER P. Research Contracts Branch. FIN B-10870 NRC-01-79-007. 80/09/30 1p
- --B010160322 Mod 2, extending period of performance & providing add1 funding, to "Burvay of Snow Loads on Nuclear Power Plant Structures."

 WISNER, J W Commerce, Dept of, National Bureau of Standards MORTON, K V Research Contracts Branch FIN B-10870 NRC-01-79-009 80/09/30 1p
- B010160327 Notification of contract execution, Mod 2 to "Mobility of Radwaste Matls in Subsurface Migration by Particulate Transport" Contractor GA Inst of Technology, JACOBB, A Research Contracts Branch FIN 8-6338, NRC-04-78-253 80/09/30 ip
- --8010160334 Mod 2, providing 2-month no cost extension, to "Mobility of Redwasts Matls in Subsurface Migration by Particulate Transport"

 ALEEN, D. L. Georgia Institute of Technology MGRTON, K. V. Research Contracts Branch FIN 8-6338, NRC-04-78-253 80/09/30 2pp
- 80:0160337 Notification of contract execution. Hod 1 to "Environ Monitoring Program M/State of DR " Contractor State of DR BAISDEN.L Research Contracts Branch FIN 8-5200 NRC-05-80-278 80/09/27 ip
- --8010160342 Mod 1.providing funding for 1980, to "Environ Monitoring Program M/State of DR " * Oregon, State of MORTON/K.V Research Contracts Branch. FIN B-2200. NRC-05-80-278 80/09/29, ip
- 8010170028 Notification of contract execution "Dispersion of Airborne Effluents from Low Level Radwaste Facilities," awarded to NOAA Environ Research Labs OUSTAVE, R.P. Research Contracts Branch FIN B-71070 NRC-01-80-024, 80/09/25 ip.
- --8010170032 Interagency Agreement: "Dispersion of Airborne Effluents from Low Level Radweste Facilities," awarded to NOAA Environ Research Labs
 FLETCHER, J.O. Gommerce, Dept of, National Oceanographic & Atmospharic Adminstration. MORTON, K, V. Research Contracts Branch FIN B-71070 NRC-01-80-024 80/09/22. Spp
- 80101700B6 Notification of contract execution.Mod 11 to "Amelysis of Hypothetical Accidents Resulting From Core Meltdowns." Contractor: Battelle Columbus Labs.
 BROMBERO: B Research Contracts Branch FIN A-4067 NRC-04-76-293-0. 80/09/22. 1p.
- --B010170093 Mod 11.altering scope of work & adding funds, to "Analysis of Hypothetical Accidents Resulting From Core Meltdowns."

 LUKZ:F.J Battelle Memorial Institute, Columbus Laboratories, MORTON:K V. Research Contracts Branch FIN A-4067.

 RRC-04-76-293-0 B0/09/22 lp
- 8010170307 Notification of contract execution: "Evaluation of Oaotechnical Burveillance Techniques for Monitoring High Level Wasts Repository Performance," awarded to JFT Agapito & Associates, Inc. GUBTAVE.R.P. Research Contracts Branch FIN B~10990, NRC-01-80-019, 80/09/29, 1p.
- --B010170311 Contract "Evaluation of Geotechnical Burveillance Techniques for Monitoring High Level Waste Repository Performance," awarded to JFT Agapito & Associates, Inc. A0APITU.J.F. J.F.T Acapito & Associates, Inc. MORTON, K. V Research Contracts Branch FIN B-10990, NRC-01-B0-019 80/09/29, App
- 8010170314 Notification of contract execution: "Workshop on Sexual Harassment: " awarded to M Fullar. COLEMAN.R. Administrative Contracts Branch NRC-10-80-690 80/09/30. pp.
- --8010170315 Contract; "Workshop on Sexual Harassment," awarded to M Fuller, FULLER, M. M. Fuller, M. MATTIA, M. J. Administrative Contracts Branch, NRC-10-80-690, 80/09/30, 66pp.
- 8010170316 Notification of contract execution. Mod 2 to "Stds for Psychological Assessment of Security Personnel." Contractor: Assessment Designs Inc. OUBTAVE.R. Research Contracts Branch. FIN B-10839. NRC-01-79-002. SO/09/26. ip.

- --B010170317 Mod 2,issuing fund change order via Hod 1, to "Btds for Psychological Assessment of Becurity Personnel" FRANK,F D. Assessment Designs, Inc MORTON, K V Contracts Branch FIN 8-10939 NRC-01-79-002 80/09/30 ip
- 8010170320 Notification of contract execution, "Conference Program for ASLAP Members," awarded to Capitol Communication 8ye, Inc HIOGINB,E Administrative Contracts Branch NRC-10-80-381. 80/09/30. 1p.
- ---8010170323 Contract. "Conference Program for ASLAP Hembers," awarded to Capitol Communication Bys.Inc
 --- Capitol Communication Bystems MATTIA,H J Administrative Contracts Branch. NRC-10-80-081 80/09/30 123pp
- 8010170368 Notification of contract execution: "Environ Munitoring W/ Btate of NC," awarded to State of NC Dept of Human Resources. BAISDEN'L Research Contracts Branch. FIN 8-1239. NRC-05-80-283 80/09/24. jp.
- --80i0170371 Contract: "Environ Monitoring Program W/State of NC," awarded to State of NC Dept of Human Resources.
 HILKERSON: I O. North Carolina, State of MDRTON: K V Research Contracts: Branch FIN B-1209. MRC-05-80-283.
- B010170373 Notification of contract execution "NBB Calibr Measurement Assurance Program to Support NRC Third Pilot-Bludy Test of Personnel Dosimetry Processors." awarded to NBB Ctr for Radiation Research.

 QUSTAVE.R.P. Research Contracts Branch FIN 8-71030,

 NRC-01-80-023, 80/09/26 1p.
- --B010170400 Contract: "NBB Calibr Measurement Assurance Program to Support NRC Third Pilot-Study Test of Personnel Dominstry Processors: awarded to NBS Ctr for Radiation Research EMREVE D B. Commerce: Dept of, National Sureau of Btandards MGRTON.K.V. Research Contracts Branch FIN 8-71030. NRG-01-80-023. B0/09/26 Spp.
- BO10170377 Notification of contract execution: "Environ Monitoring Program W/State of MN." awarded to State of MN Dept of Health. BAISDEN.L. Research Contracts Branch PIN S-1252 NRC-05-80-288 80/09/24 ip
- --8010170380 Contract: "Environ Monitoring Program W/Btate of MN."
 awarded to State of MN Dept of Health.
 PETTERSON, O. R. Minnesota, State of MORTON, K. V. Research.
 Contracts Branch. FIN 8-1252 NRC-05-80-288 80/09/24. Ppp
- 8010170379 Notification of contract execution. "Study of Parameters That Affect NDA Measurement Response & Development of Dasign Baccs to Minimize Effect," awarded to Science Applications, Inc. OUSTAVE,R.P. Research Contracts Branch. FIN B-10780. NRC-01-80-001. 80/07/22 ip
- --B010170388 Contract: "Study of Parameters That Affect NDA Heasurement Response & Development of Design Spece to Minimize Effect," awarded to Science Applications.Inc. MCDONALD, R. J. Science Applications. Inc. MORTON, K. V. Research Contracts Branch. PIN B-10780. NRC-01-80-001. 80/09/22. App.
- 8010170383 Notification of contract execution Mod 1 to "Environ Monitoring Program W/State of QA " Contractor State of QA. BAISDEN,L. Research Contracte Branch. FIN 8-5203. NRC-05-80-279. 80/09/29. 1p.
- --B010170393 Mod 1.providing funding for 1980 sffort:to "Environ Monitoring Program W/State of GA." + Oeorgia, Btate of MORTON, K. V. Research Contracts Branch. FIN B-5203. NRG-05-80-279 80/09/29, ip
- 8010170447 Notification of contract execution Mod 1 to "Environ Monitoring Program W/State of AR." Contractor: Btate of AR. BAISDEN.L. Research Contracts Branch. FIN 8-5207. NRC-05-80-280, 80/09/29. 1p.
- --8010170452 Mod 1, providing funding for 1980 effort, to "Environ Monitoring Program W/State of AR."

 * Arkenses, State of. MORTON, K.V. Research Contracts Branch. FIN 8-5207. NRC-05-80-280. 80/09/29. ip
- BO10170349 Notification of contract execution, Mod i to "MPA-MIS ADP Support Bycs." Contractor: Small Business Administration. Bub contractor: Input Output Computer Bycs. Inc. MARTIN.L L. Administrative Contracts Branch, NRC-10-80-397 BO/09/05. 1p.

- --8010170532 Had 1, superseding ordering procedures reflected under Bubsection H 3, to "MPA-MIB ADP Support Bycs " # Small Business Administration MATTIA:H J Administrative Contracts Branch # Input Output Computer Services, Inc NRC-10-80-397 80/09/05 34pp
- 8010170351 Notification of contract execution, Mod 1 to "Vault Bys Testing " Contractor: Army Math Sys & Analysis Activity HAIRSTON, C Technical Assistance Contracts Branch. FIN B-6411-9 NRC-02-79-022 80/08/18 ip
- --8010170555 Mod 1, extending period of performance, to "Vault Sys Testing."

 * Army, Dept. of, DOUGHERTY, D J. Technical Assistance Contracts
 Branch FIN 8-6411-9, NRC-02-79-022 80/08/15 ip.
- 8010170559 Notification of contract asscution "Micrographic Svcs." awarded to Microtech Industries.Inc MARTIN.L.C. Administrative Contracts Branch FIN 8-4357 NRC-10-80-708 80/09/20. ip.
- --8010170566 Contract "Micrographic Svcs," awarded to Microtech Industries: Inc. RUOCCHIO.J. Microtech Industries, Inc MATTIA, M J Administrative Contracts Branch FIN 8-6357 NRC-10-80-708 80/09/30. 91pp
- 8010170565 Notification of contract execution: "Technical Assistance for Assessment of Repository Siting & Design," awarded to US Bureau of Mines.
 HAIRSTON.C. Technical Assistance Contracts Branch. FIN 8-6934-0 NRC-02-80-075. 80/09/30 1p
- --8010170872 Contract. "Technical Assistance for Assessment of Repository Siting & Design," awarded to US Bureau of Mines. KENMHAN.C.S. Interior, Dept of Bureau of Mines. DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6934-0. NRC-02-80-075 80/09/30, 3pp.
- 8010170574 Natification of contract execution: "State Legislative Reporting Svcs," awarded to Federal-State Repts Inc FLYNN, M. J. Administrative Contracts Branch. FIN B-1392. NRC-04-80-681, 80/09/30, 1p
- --8010170580 Contract. "State Legislative Reporting Bycs," awarded to Federal-State Reports, Inc. "Federal-Btate Reports, Inc. MATTIAN J Administrative Contracts Branch FIN 8-1592 NRC-06-80-681 80/09/30 70pp.
- B010170590 Notification of contract execution. Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Mgt " Contractor Ralph Stone & Co. HAIRBTON. C. Technical Assistance Contracts Branch NRC-02-77-201-28. B0/09/29 ip
- --B010170396 Hod 5, updating terms & conditions, to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Mgt." KAHLE, R. Raiph Stone & Co. DQUOHERTY, D. J. Technical Assistance Contracts Branch NRC-02-77-201-28 80/09/29. 14pp.
- 8010170605 Notification of contract execution. Mod 2 to "Technical Assistance for Fire Protection Program Review & Evaluation." Contractor: Gage, Babcock & Associates.
 HAIRBION.C. Technical Assistance Contracts Branch. FIN 8-6588, NRC-03-79-127. 80/09/29, 1p.
- --8010170612 Mod 2.providing addl funds.to "Technical Assistance for Fire Protection Program Review & Evaluation " w Gage-Babcock Associates, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN 8-6588, NRC-03-79-127 80/09/29.
- 8010170617 Notification of contract execution, Mod 9 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions." Contractor. Franklin Inst. HAIREIDN.C. Technical Assistance Contracts Branch. FIN 8-6590. NRC-03-79-118. 80/09/30. 1p
- --BD10170624 Mod 9.sxtending period of performance, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions."

 ABHTON:A.M. Franklin Institute/Franklin Research Center.

 DOUGHERTY:D.J. Technical Assistance Contracts Branch. FIN 8-6590.

 NRC-03-79-118. B0/09/30 lp.
- B010200076 Notification of contract execution: "Time Shared Use of EPA Computer Data Base STORET," awarded to EPA.
 MILES,E.B. Purchaeing Section. NRC-10-80-713, 80/09/30 ip.

- --8010200080 Contract "Time Shared Use of EPA Computer Data Base STORET," awarded to EPA ERICKEDN, A J Environmental Protection Agency PERLMAN, J Administrative Contracts Brench NRC-10-80-713 80/09/30 3pp
- 8010200219 Notification of contract elecution "Security Force Effectiveness," awarded to Applied Science Associates.inc OUSTAVE, R Research Contracts Branch FIN 8-10970 NRC-01-80-004 80/09/22 ip
- --8010200223 Contract "Security Force Effectiveness," awarded to Applied Science Associates, Inc HEADLEY,K D. Applied Science Associates, Inc MORTON, K V Research Contracts Branch FIN 8-10970 NRC-01-80-004 80/09/22
- 8010200228 Notification of contract execution Mod 3 to "Evaluation of Relative Burface Properties of Alternative Nuclear Haste Encapsulants " Contractor Univ of FL JACOBBA A. Research Contracts Branch FIN B-6352 NRC-04-78-252 80/09/29 1p
- --8010200234 Mod 3-extending period of performance from 791231 to 850930 w/add1 funding, to "Evaluation of Relative Surface Properties of Alternative Nuclear Waste Encapsulants "RANDAZZO, A.F. Florida, Univ of, Oainesville. MORTON, K V Research Contracts Stanch FIN 8-6352 MRC-04-78-252 80/09/29
- 8010200242 Notification of contract execution.Mod 1 to "Environ Monitoring Program M/Commonwealth of VA " Contractor Commonwealth of VA BAISBONL Research Contracts Branch FIN B-5116 NRC-05-80-277 B0/09/29. ip
- ~-8010200250 Mad 3.providing funding for 1980.to "Environ Monitoring Program H/Commonwealth of VA" * Virginia, State of MORTON.K V Research Contracts Branch. FIN B-5116 NRC-05-80-277 80/09/29 ip
- 6010200288 Notification of contract execution "Disease Incidence Rates from Occupational Exposure to Hazardous Substances," awarded to Battalle Columbus Labs.

 OUSTAVE.R P. Research Contracts Branch FIN 8-10660

 NRC-01-80-016 80/09/26 ip
- --B010200271 Contract "Disease Incidence Rates from Occupational Exposure to Hazardous Bubstances," awarded to Battelle Columbus Labs LUKZ,F J Battelle Memorial Institute, Columbus Laboratories MORTON, K V. Research Contracts Branch FIN B-10660 NRC-01-B0-016 B0/09/26 5pp
- 8010200292 Notification of contract execution. "Effective Peak Acceleration for Nuclear Power Plant Design," awarded to Moudward-Clyde Consultants JACOBS.A Research Contracts Branch FIN 8-6680 NRC-04-80-192 80/09/22 ip
- -8010200299 Contract. "Effective Peak Acceleration for Nuclear Power Plant Design." awarded to Woodward-Clyde Consultants. IDR:188. I.M Woodward-Clyde Consultants. Inc MORTON, K. V. Research Contracts Branch FIN 8-6680 NRC-04-80-192 80/09/22 800
- 8010200307 Notification of contract execution, Mod 1 to "Environ Monitoring Program M/State of TN " Contractor State of TN BAISBENL Research Contracts Branch FIN B-5208 NRC-05-80-281 80/09/27 ip
- --8010200319 Mod i.providing funding for 1980.to "Environ Monitoring Program W/State of TN" * Tennessee, State of MORTON.K V Research Contracts Branch, FIN 8-5208 NRC-05-80-201 80/09/29 ip.
- 8010200316 Notification of contract execution, Mod 1 to "Microfiche Byes, dax Ridge, TN, " Contractor Microtech Industries, Inc. MARTIN, L G Administrative Contracts Branch NRC-10-79-658, 80/09/30 1p.
- --8Di0200326 Mod 1,increasing contract ceiling amount, to "Microfiche Bycs,Oak Ridge,TN " KICK,R.C. Microtech Industries, Inc. MATTIA,M J. Administrativa Contracts Branch NRC-10-79-658 80/09/30 2pp.
 - 10200324 Notification of contract execution, Mod 1 to "Comparative Review of Risk Assessments, Bafety Ocals & Related Concepts for Commercial Nuclear Power & Alternative Bources of Energy " Contractor Intl Planning Mgt Corp, HOYLE.A. Administrative Contracts Branch FIN 8-7501 RC-03-80-144 80/09/30 1g.

- ---8010200327 Mod 1.incorporating Phase II option to increase period of performance & funding to "Comparative Review of Risk Assessments, Safety Goals & Related Concepts for Commercial Nuclear Power & Alternative Sources of Energy"

 International Planning Management PERLMAN, J Administrative Contracts Branch FIN 8-7501 NRC-03-80-146 80/09/30 ip
- 8D10200343 Notification of contract execution, Mod 10 to "Design of IFMIS." Contractor Small Business Administration Subcontractor. Technassociates Inc MARTIN.L C Administrative Contracts Branch NRC-10-80-395 8D/09/30 ip
- --8010200364 Mod 10.providing for equitable adjustments to estimated cost 1 fixed fee for performance to "Design of IFMIS"
 YTHIER,P. Technassociates, Inc MATTIA:M J Administrative Contracts Branch COLLINS,F M Small Business Administration NRC-10-80-395 80/09/30 2pp
- 8010200370 Notification of contract execution, Mod 12 to "Document Control Bys." Contractor TERA Advanced Bycs Corp. LEBO, C D Administrative Contracts Branch NRC-10-78-580 80/09/30 1p
- --8010200373 Mod 12.applying add1 increment of funds to "Document Contral Bys" * TERA Corp MATTIA M J Administrative Contracts Branch NRC-10-78-580 80/09/30 2pp
- 8010/200579 Notification of contract execution "Low Level Radwaste Records." awarded to Chem-Nuclear Sys. Inc HAIRBTQN.C Technical Assistance Contracts Branch FIN B-6973-0 NRC-02-B0-062 80/09/30 ip
- ---8010200606 Contract "Low Level Raduasta Records," awarded to Chea-Nuclear Sys, Inc OREDORY, W. T. Chem-Nuclear Systems, Inc DDUGHERTY, D. J. Technical Assistance Contracts Branch FIN B-6973-0 NRC-02-80-062 80/09/30 lipp
- 8010200595 Notification of contract execution Mod 2 to "Publication Distribution Sycs " Contractor Computer Data Sys. Inc MARTIN.L C Administrative Contracts Branch NRC-10-80-362 80/09/30 1p
- --B010Z00600 Mod 2.adding specs for shelving units, to "Publication Distribution Bycs "
 TINSLEY, W. D. Computer Data Systems, Inc. MATTIA, M. J. Administrative Contracts Branch NRC-10-80-362 80/09/30 ip
- B010200634 Notification of contract execution, Mod 1 to "Technical Assistance for Assessment of Repository Siting & Design "
 Contractor US Bureau of Mines
 HAIRBTON C Technical Assistance Contracts Branch FIN B-6934-0
 NRC-02-80-075, 80/09/30 1p
- --B010200642 Mod 1, providing for advance payment, to "Technical Assistance for Assessment of Repository Siting & Design."

 * Interior, Dept of, Bureau of Mines DOUGHERTY.D J Technical Assistance Contracts Branch FIN B-6934-0 NRC-02-80-075 80/09/30, 1p
- 8010200554 Notification of contract execution, Mod 3 to "State Transportation Surveillance Program" Contractor State of WA MARTIN, L. C. Administrative Contracts Branch FIN B-1612 NRC-06-79-305. 80/09/30 ip
- --8010200660 Med 3:adding to scope of work & increasing funds to "State Transportation Surveillance Program" BEARE.J A Washington, State of MATTIA,M J Administrative Contracts Branch NRC-06-79-305 80/09/30 3pp
- 8010200669 Notification of contract execution; "PHR Severe Accident Delipeation & Assessment," awarded to Regente of Univ of CA.
 Los Angeles.
 HAIRSTON.C Technical Assistance Contracts Branch FIN B-6835
 NRC-03-80-101, 80/09/30, 1p
- --B010200666 Contract "PWR Severe Accident Delineation & Assessment," awarded to Regents of Univ of CA,Los Angeles COLDBCHNIDT.P California, Univ of Los Angeles DOUGHERTY,D J Technical Assistance Contracts Branch FIN B-6835 NRC-03-80-101 80/09/30. 25pp
- 8010200698 Notification of contract execution "Support in Geotechnical Engineering for Nonreactor Facilities," awarded to Dept of Army. HAIRSTON.C Technical Assistance Contracts Branch, FIN 8-6846. NRC-03-80-125. 80/09/11

- --B010200701 Contract "Support in Geotechnical Engineering for Nonreactor Facilities," awarded to Dept of Army FRIEDENNALD.R Army Dept of, Corps of Engineers GLAGGLA,A F Technical Assistance Contracts Branch FIN B-6846 NRC-03-80-125 80/09/11 6pp
- B010210060 Notification of contract execution "Environ Assessments of Burface & Oroundwater Impacts from U Recovery Operations," awarded to DE-TEMPO HAIRSTON.C Technical Assistance Contracts Branch NRC-02-B0-028-05 80/10/01 ip
- --8010210064 Contract "Environ Assessments of Burface & Groundwater Impacts from U Recovery Operations "
 ROBBON, L E General Electric Ca DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-80-028-05 80/10/01 22pp
- 8010210098 Notification of contract execution.Mod 4 to "State Transportation Burveillance" Contractor State of MI MARTIN.L C Administrative Contracts Branch FIN 8-1612 NRC-06-77-051 80/09/30 1p
- --8010210105 Mod 4.extending pariod of performance & adding funds.to
 "State Transportation Burveillance "
 REIZEN.H 8 Michigan, State of MATTIA.H J
 Contracts Branch FIN 8-1612 NRC-06-77-051 80/09/30 3pp
- B010210131 Notification of contract execution. "Performance of Benesitivity Analysis of Policy for Placement of Documents in PDR W/Compliance Profile:" awarded to Intersyst Limited MILES.E B Administrative Contracts Branch NRC-10-80-709 80/09/15 ip
- --801021013B Contract "Performance of Bensitivity Analysis of Policy for Placement of Documents in PDR W/Compliance Profile," awarded to Intersyst Limited KILPATRICK,O A Intersyst,Ltd MATTIA,M J, PERLMAN,J Research Contracts Branch NRC-10-80-709 80/09/15 7pp
- 8010220692 Notification of contract execution "NRC Personnel Policies & Practices Seminar for Supervisors & Managers," awarded to Graduate School, USDA COLEMAN, R Administrative Contracts Branch NRC-10-80-370 80/09/24 1p
- --8010220696 Contract "NRC Personnel Policies & Practices Seminar for Supervisors & Managers," awarded to Graduate Echool,USDA * Agriculture, Dept of MATTIA,M J Administrative Contracts Branch NRC-10-80-370 80/09/24 5pp
- 8010230326 Notification of contract execution Mod 3 to "Lease of Class III & Class IV Sedans for NRC Motor Pools "
 Contractor Mike Albert Leasing, Inc
 FLYNN,M J. Administrative Contracts Branch NRC-10-78-416
 80/09/30 ip
- --8010230330 Mod 3, increasing total amount of contract to cover damages to automobiles to "Lease of Class III & Class IV Bedans for NRC Motor Pools"

 MILLER, D.N. Mike Albert Leasing, Inc. MATTIA, M.J. Administrative Contracts Branch. NRC-10-78-416. 80/09/30. 2pp
- 8010230441 Notification of contract execution, Mod 3 to "Lease of Class IV Bedans " Contractor Mike Albert Leasing.Inc FLYNN,M J Administrative Contracts Branch NRC~10-78-588 80/07/30 ip.
- --B010230444 Mod 3, increasing total amount of contract to cover damages to automobile, to "Lease of Class IV Bedans "
 MILLER,D N. Mike Albert Leasing, Inc MATTIA,M J. Administrativa Contracts Branch NRC-10-78-388 80/09/30 2pp.
- BO10230968 Bolicitation offer & award of "State Legislative Reporting Svcs," awarded to Federal-Btate Repts.Inc ALLENDER, O. W. Federal-State Reports.Inc MATTIA. M. J Administrative Contracts Branch FIN 8-1592. NRC-06-80-681 80/09/03 67pp.
- --B010230875 Amend 1. deleting multiple award clause & clarifying descriptive sycs. to "Btate Legislative Reporting Bycs." awarded to Federal-State Repts. Inc. ALLENDER. G. M. Federal-State Reports. Inc. MATTIA. M J Administrative Contracts Branch. FIN B-1592. NRC-06-80-681. B0/07/03.
- 8010240560 Notification of contract execution, Mod 2 to "Statistical Analysis Btudy " Contractor SL Wolfbein. FLYNN, M J Administrative Contracts Branch, NRC-01-80-694, 80/10/09 ip

- --8010240367 Mod 2, sitending period of performance to 801231 to
 "Statistical Analysis Study"
 UGLF8EIN, S. L. Holfbein, S. L. HALMAN, E. L. Division of Contracts
 NRC-10-80-694 80/10/09 1p
- 801024060B Natification of contract execution.Mod 1 to "Environ Monitoring Program W/Gommonwealth of MA" Contractor Commonwealth of MA
 BAISBEN,L Research Contracts Branch FIN B-1247 NRC-05-80-286 80/10/14 1p
- --B010240614 Mod 1.adding modified environ monitoring program to "Environ Monitoring Program W/Commonwealth of MA" FRECHETIE. A L Massachusetts, State of MORTON, K V Research Contracts Branch FIN B-1249 NRC-05-B0-286 80/10/14 9pp
- 8010270004 Notification of contract execution, Mod 2 to "Independent Assessment Destructive Testing & Analysis " Contractor Franklin Inst
 BAISDEN, L Research Contracts Branch FIN B-1212 NRC-05-79-253 80/10/14 1p
- --8010270005 Mod 2 revising hourly employee rate to "Independent Assessment Destructive Testing & Analysis " ROBINSON.F,T Franklin Institute/Franklin Research Center MORTON,K V Research Contracts Branch FIN 8-1212 NRC-05-79-253 80/10/14 Rpp
- 8010270006 Notification of contract execution. Mod 3 to "Durability of Crystalline Nuclear Waste-Forms & Natural Analogs at Geologic Storage Conditions." Contractor Univ of Toledo HAGEY, H Research Contracts Branch FIN B-6624 NRC-04-78-267 B0/10/07 Ip
- --8010270008 Mod 3.4dding no cost extension to "Durability of Crystalline Nuclear Waste-Forms & Natural Analogs at Geologic Storage Conditions " RIEGER.P E Toledo, Univ of MDRTON, K. V. Research Contracts Branch FIN 8-4624. NRC-04-78-267 80/10/07 2pp
- 8010270195 Notification of contract execution "Electrostatic Copying Svcs:" awarded to GraphicData-Inc COLEMAN,R Administrative Contracts Branch MRC-10-80-701 BD/09726 1p
- --8010270200 Contract "Electrostatic Copying Sycs," awarded to GraphicData, Inc MARQVLIES.K Graphic Data, Inc MATTIA, M.J Administrative Contracts Branch. NRC-10-80-701 80/09/26 74pp
- B010270398 "Revision of Detailed Definition of Requirements (DDR)," Vol 1. * Boeing Computer Services, Inc. (subs. of Boeing Co.) NRC-10~80-664. 80/02/28 496pp
- 8010290086 Notification of contract execution, Mod 1 to "Electrostatic Copying Svcs " Contractor GraphicData: Inc CDLEMAN: Administrative Contracts Branch NRC-10-80-701 BD/10/16 ip
- --8010270071 Mod i, providing correct appropriation symbol, to
 "Electrostatic Copying Svcs"

 * Oraphic Data, Inc MATTIA, M. J Administrative Contracts Branch
 NRC-10-80-701 80/10/16 ip
- 80102900B7 Notification of contract execution. Hod 7 to "Dynamic Studies of LMF88 & Nuclear Power Plants " Contractor Univ of AZ HA0EY.H Research Contracts Branch FIN A-4065 NRC-04-75-250 B0/10/09 ip.
- --8010290073 Mpd 7.extending period of performance to 810930 to "Dynamic Btudies of LMFBR & Nuclear Power Flants " HHEELER.J.T Artiona. Univ of MORTON.K V Research Contracts Branch FIN A-4065 NRC-04-75-250 80/10/09, 2pp
- 8010290094 Notification of contract execution:Mod 2 to "Hriting Assignment for NRC Movis" Contractor Claire Merrill LE80,C,D Technical Assistance Contracts Branch FIN 8-1566 NRC-16-77-036 80/10/16 ip
- --8010290099 Mod 2, ratifying agreement to terminate contract effort at conclusion of Phase II of contract, to "Writing Assignment for NRC Movie"

 MERRILL, C Merrill, C, MATTIA, M J Administrative Contracts

 Branch FIN 8-1366 NRC-16-77-036 80/10/16 ip

- 8010300143 Notification of contract execution "Evaluation of Ecosys Simulation Models as Tools for Assessment of Power Plant Impacts of Fish Populations," awarded to Univ of NA HAGEV,H Research Contracts Branch FIN B-7018 NRC-04-80-214 80/09/24 1p
- --801030015B Contract "Evaluation of Ecosys Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations," awarded to Univ of MA RYAN.J F Washington, Univ of MORTON, K. V Research Contracts Branch FIN 8-7018 NRC-04-80-214 80/09/24 6pp
- B010300533 Comments on OH State Unive proposal re development, evaluation & analysis of annual requalification exams NRC has contracted for study of requirements for operator licensing DENICH.H R Office of Nuclear Reactor Regulation, Director 80/10/08 1p
- 8010310534 Notification of contract execution Mod 8 to "JURIS Automatic Legal Research Sys " Contractor DDJ HARTIN-L C Administrative Contracts Branch NRC-10-76-335. 80/09/30 1p
- --8010310538 Mod B.extending period of performance.to "JURIS Automatic Legal Research Sys" KONDOS,O S Justice.Dept of MATTIA.M J Administrative Contracts Branch NRC-10-76-335 80/09/30 2pp
- 8010310572 Notification of contract execution. Hod 14 to "Stemographic Reporting Svcs." Contractor Ace Federal Reporter.Inc. HIGOINS. E. Administrative Contracts Branch NRC-17-77-117 80/10/14 ip
- --8010310377 Mod 14, implementing final settlement for "Stenographic Reporting Sycs." MATSKO,R J. ACE Federal Reporters, Inc. MATTIA,M J. Administrative Contracts Branch NRC-17-77-117. 80/10/14. 2pp.
- 8010310581 Notification of contract execution. Mod & to "Utilization of BKR & PNR Simulator Facilities" Contractor TVA BAISDEN.L Research Contracts Branch. FIN X-1157 NRC-05-76-357 80/09/29 ip.
- --8010310587 Med & extending period of performance & providing funds for FY80, to "Utilization of BUR & PUR Simulator Facilities" HILLIS, W F. Tennessee Valley Authority MORTON, K. V Research Contracts Branch FIN X-1157 N8C-03-76-037 80/09/29 App
- 8010310594 Notification of contract execution Mod 9 to "BMR-Blowdown Heat Transfer Research " Contractor QE BROMBERO, B Research Contracts Branch. FIN B-3104. NRC-04-74-215 80/10/06 1p
- --9010310597 Mod 9.increasing Electrical Power Research Inst funds, to
 "BUR-Blowdown Heat Transfer Research "
 KLEPFER: H General Electric Co MORTON, K V. Research Contracts
 Branch FARRA, A O Electric Power Research Institute FIN
 B-3014 NRC-04-74-215 H0/10/06 2pp.

DISCLOSURE FINANCIAL DISCLOSURE INFORMATION

- 8010230110 Grants exemption from code requirements for participation in matters before NRC affecting Westinghouse Interest in Wastinghouse pension fund not so substantial as to be deemed likely to affect integrity of svcs to NRC DAVIS, J O Office of Nuclear Material Safety & Bafeguards 80/10/03 1p
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8009190539 Comments on draft of "Policy Statement on Alternative Site Evaluation Under NEPA for Nuclear Stations." Paper is suitable for Commission review Value of paper could be enhanced by encl comments. PEOERSEN,K Office of Policy Evaluations 77/07/18 6pp
- ~~8009190546 Comments on proposed policy statement on evaluation of alternate sites Policy statement does not clearly identify how Commission will act to enforce stds Ralated documentation encl
 KELLEY, J. L. Office of the General Counsel 77/07/25 Spp
- 8010020125 Draft outline, "Staff Paper on Procedures to be Followed to Reach Decision on Wide-Scale Pu Recycle " Draft 750917 outline snc! " Commissioners, 75/09/18, [1pp

- --B010020128 Discusses provisional Decision Paper 3 Lists four new safaguard items in Huberman focusing instructions Related documentation encl
 BUILDER: C H Dffice of the Executive Legal Director 75/09/18
- торр
- 9010020096 Partial response to ACTMU FOIA request for files & repts re 800731 fire at Ethicon Inc Forwards PNO-I-80-116 Addl documents will be forwarded at later date FELTON J M Division of Rules and Records 80/09/25 ip
- B010020100 ACTHU FQIA request for files & repts re 800731 fire at Ethican: Inc GILLEN: M AFL-CIO 80/09/08 is
- BO10020104 Add1 response to FOIA request for 47 documents re GEGMO Forwards 11 documents listed in app
 FELTON, J M Division of Rules and Records 80/09/25 2pp
- --8010020109 Discusses possible additions to GESMO provisional views scoping paper Includes discussion of other policies to provide range of options.intl factors & effect of upgraded NRC program upon ERDA & military LEACHMAN.R.B Commissioners 75/09/02 4pp.
- --B010020115 Bubmits proposed action plan for safeguards portion of GESMO Dutline includes assumptions, product, organization & support, schedule & observations
 BUILDER, C. H. Office of the Executive Legal Director 75/09/15
- --8010020120 Forwards questions re 750710 Pu recycle provisional visu issues & alternatives DIRCKS, W. Office of the Executive Director for Operations, 75/09/15 2pp
- 8010020135 Add1 response to FOIA request for it documents re facility. Forwards affidavis of MJ Dircks Info partially withheld (ref FOIA Exemption 1) FELTON, J. H Division of Rules and Records 80/09/24 1p
- SECTIONS OF DIVISION OF KOISS SUG RECORDS SOLVANIA IS
- 80:0020644 Responds to FOIA request for three categories of documents re correspondence between GE & Knowles Atomic Plant, NRC has no documents subj to request Request should be directed to DOE FELTON, J. N Division of Rules and Records 80/09/24 ip
- 8010020665 FOIA request for three categories of documents re correspondence between OE & Knowles Atomic Plant POBT.R. Morgan, Melhuish, Monaghan & Meyer 80/07/12 2pp
- 8010020687 Responds to FOIA request for documents re various organizations including Armadillo Coalition of TX Forwards documents listed in App A FELTON.J M. Division of Rules and Records 80/09/30 2pp
- 8010020694 FOIA request for documents re various organizations including Armadillo Coalition of TX BATCHELOR, K. Armadillo Coalition of Texas 80/08/05 4pp
- B010020704 Responds to FOIA request for War Resisters League files Forwards RJ Bredy 760513 itr to BP Murphy of FRI. FELTON, J M Division of Rules and Records 80/09/25, Rpp
- --8010020710 Requests available pertinent info re Continental Walkers for Disarmament 1 Social Justice 8. War Resisters League Info is assential for maint of viable NRC internal security program in view of planned demonstrations BRADY, R J. Division of Security 76/05/13 ip.
- 8010020706 Forwards E Hedemann FOIA request for Nar Resisters League files BRESSON,T H. Justice,Dept of 80/08/06 2pp
- 8010090040 Responds to FOIA request for 14 specifically listed documents Search for NRC documents is continuing. Other requested documents are available at IAEA, DDE, EPA, Dept of Commerce, DDD & NTIB
 FELTON, J M. Division of Rules and Records 80/10/01 1P.
- 8010030044 Responds to FOIA request for 22 specifically listed documents Forwards documents listed in App A W/o encls FELTON.T.M. Division of Rules and Records 80/10/02. 2pp.
- 80:008:0048 Responds to FDIA request for NRC degraded core rulemaking distribution list Forwards mailing labels of distribution list.W/o encl. FELTON, J. M. Division of Rules and Records. 80/01/02. 1p.

- 8010080097 FOIA request for NRC degraded core rulemaking distribution list PALMER.L W Nucleonics Weeks, pub of McGraw Hill, Inc 80/09/19
- 8010090093 FOIA request for 22 specifically listed documents DOHERTY, J F Doherty, J F 80/09/26 2pp
- 8010080077 FOIA request for 14 specifically listed documents Info is needed to assess public health hazards from abandoned radioactive dumpsites
 DAVIS.W J California, Univ of Santa Cruz 80/09/10 3pp
- 8010090039 Responds to FOIA request D Hoyle 800515 ltr to V Gilinsky & 800516 memorandum & order.CLI-80-18 encl FELTON.J X Division of Rules and Records 80/10/02 ip
- --8010090046 Discusses 800205 speech before India Council of Hashington, DC on UB-Indian nuclear relations Discusses right of US to (mpose full-scope safeguard condition on India Clarifies amend to fuel contract HOYLE, DB Hestinghouse Electric Corp 80/05/15 App
- B010090042 FDIA request for info re affect of US nonproliferation policy on Indian nuclear commitments, amount of US nuclear fuel shipped to India 5 Indian nuclear capabilities SCHERR, J , DARNES, J Center for Law & Social Policy E0/06/30 3pp
- 8010100006 Responds to FOIA request for documents re fines, penalties & violations from 1978 to present Forwards computer printents its ted in App A of civil penalties imposed insp repts, noncompilance items & text Documents are available in FDR FELTON, J M Division of Rules and Records 80/10/03 2pp
- B01010000B FDIA request for documents re fines, penalties & violations cited by NRC from 1978 to present POLLOGK.R P Critical Mass Energy Project 80/09/01 1p.
- --Boloi000ii Computer printouts showing civil penalties imposed & docket number, insp rept number, dates of insp.alphabetical code of noncompliance items & severity level of each noncompliance item from 1978 to present a Commissioners 80/10/03 1203pp
- BO10140073 Responds to FDIA request for three SECY papers listed in hibliography of NUREO-0625, "Rept of Siting Policy Task Force " Documents are evailable in PDR FELTON.J M Division of Rules and Records B0/10/03 ip
- --8010140091 SECY-78-163
 Revises SECY-77-433, "Policy Statement on Alternative Site Evaluations Under NEPA for Nuclear Generating Stations "Recommends that Commission require review & approval of site selection prior to acceptance of CP application HINDOUE, B Office of Standards Development, Director, 78/03/20, 95n
- --8010140093 "Presentation of Alternative Decision Btd for Evaluation of Alternative Sites " Supporting documentation encl OTT,UR Sit & Environ Stds Br (formerly Environ Prot Stds Br) 78/03/20 43pp
- BO10140083 FOIA request for SECY-B0-111. SECY-78-111A & BECY 78-163, listed in bibliography of NUREQ-0625, "Rept of Siting Policy Task Force BAYIS.R J., NUB Carp ESG-80-187 80/09/09 1p
- B010140604 Add1 response to F0IA request for documents re 800731 fire at Ethicon, Inc Forwards documents listed in App A FELTON, J M Division of Rules and Records, 80/10/03 2pp
- --8010140608 IE Insp Rept 30-06990/80-01 on 800809.No noncompliance noted Major areas inspected special insp after 800731 fire in irradiator room during dose mapping ROWE,C.A. Region i, Philadelphia, Office of the Director KINNEMAN, J.D. Region i, Philadelphia, Fuel Facility & Materials Befety Branch 80/08/07 3pp
- --B010140613 Forwards rept on 800731 incident in Co-60 gamma irradiator unit in Bomerville.NJ, in response to NRC 800814 request. KENDRA, E. J. Ethicon, Inc. 80/08/28 2pg
- --8010140615 Ack receipt of B00828 ltr forwarding final rept re 800731 incident at facility. Incident was reviewed during insp conducted on 800805.

 KINNEMAN, J. D. Region I. Philadelphia, Fuel Facility & Materials Bafety Branch, 80/09/17, ip

- BOI0150611 Responds to appeal re denial of FOIA request for records re proposed fire protection rule Forwards documents to be released observables of released documents & all of Document & withheld (ref FOIA Exemption 5) W/o encis CHILK,S J. Office of the Secretary of the Commission 80/10/06 2pp
- --80(0190624 Disagrees w/recommendation in proposed fire protection rule exempting installation of alternate shutdown sys from Oct 1980 deadline Recommends B01101 as implementation date for App R requirements Draft meno encl
 BRADFORD, P A Commissioners 80/03/12 4pp
- --8010150627 Discusses JF Ahearne 800410 memo re SECY-80-088 concerning fire protection rule Disagrees w/811201 date as deadline for SEP alternate shutdown sys Alternative shutdown sys should be installed by 810501 BRADFORD:PA Commissioners 80/04/14 tp
- ---BO10150630 Lists completion dates for alternate or deficated shutdown sys Info partially withheld (ref FOIA Exemption 5) OIBBON-T Commissioners 80/04/08 2pp
- ---8010150634 Informs of proposed rule requiring implementation of mods associated w/fire protection program to be completed by 801101 Info partially withheld (ref FOIA Exemption 5) OIBBON, T Commissioners 80/03/11 2pp
- 8010150518 Appeals partial denial of FOIA request for documents which requested directed or discussed any changes to proposed fire protection rule in SECY-80-098 Bocuments released were not fully responsive to request KNUTH.D.F Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp.) 80/08/04 2pp
- B010160052 Partial response to FOIA request for documents relicense IBNM-79005 Forwards documents listed in App A Search for addl documents is underway FELTON, J B Division of Rules and Records 80/10/03 2pp.
- --9010160062 Informs that SECY-79-118 re import of unirradiated low enriched U from Russia has been reviewed & no physical security concerns were identified Licensee is authorized to receive SNM in quantity & form specified in application MCCORKLE.O W Physical Security Licensing Branch 79/02/28 1p
- 8010160055 FOIA request for documents re License ISNN-79005 MACQREGOR, B A New West Magazine 80/07/22 1p
- 8010200016 Responds to FOIA request for list of addressess w/SN Hanauer 790406 memo Forwards list of addressees FELTON-J H Division of Rules and Records 80/10/10 ip
- 8010210175 Responds to FOIA request for SECY-80-336 & LV Nosento 800504 memo to JR Shea Forwards documents
 FELTON, J M Division of Rules and Records 80/10/10 ip
- --8010210189 SECY-80-336

 Discusses Commission review of Wastinghouse application for license to export two reactors to Korea Recommends that Commission authorize issuance of License AR-033 to Westinghouse SHEA.J.R. Office of International Programs, Director 80/07/21
- --8010210195 Requests that NRC issue license to Hestinghouse to export two reactors to Korea Delay in license issuance could jeopardize contract & could negatively impact future contracts Draft licenses encl HERBCH, M.M. Westinghouse Electric Corp. 80/03/28 App.
- 8010210183 FOIA request for SECY-80-336 & LV Nosenta 800506 memo to JR 8hea NERENBERG, A. L. Center for Development Policy 80/07/25 ip.
- B010220010 Responds to FOIA request for most recent insp repts performed by IE at Okonite & Rockbestos Cos Forwards documents listed in App A FELTON, J M. Division of Rules and Records 80/10/14. 2pp.
- 8010220013 FOIA request for most recent insp repts performed by IE at Okonite & Rockbestos Cos FAY.C.W. Wisconsin Electric Power Co. 80/09/26. 1p.
- QDIO220025 Responds to FOIA request for documents specifically identified by accession number-page number & brief discription Forwards documents listed in App A.Wo encis FELTON, J M. Division of Rules and Records. 80/10/14. 2pp.

- 8010220029 FDIA request for documents specifically identified by accession number & brief description DOHERTY, J. F. Doherty, J. F. 80/10/03 2pp
- B010240531 Responds to FOIA request for 11 categories of info re documents, repts & assessments prepared by Dames & Moore.
 EPA, CEG. DOE, USOS, NRC & States of WI, MI & MN No documents user found sub, to request FELTON, J H Division of Rules and Records 80/10/22 1p
- 8010240535 FOIA request for it categories of info re documents repts & assessments prepared by Dames & Moore, DOE, EPA, CEQ, USGS, NRC & Btates of WI, MI & MN
 CRAHFORD, T. J. Citizens for a Better Environment 80/10/03 3pp.
- 8010240656 Responds to FGIA request for several categories of info re nuclear plants in US & waste disposal methods Forwards documents listed in App A Documents listed in App B may be gurchased at NTIS H/o encls FELTON, J N Division of Rules and Records 80/10/16 3pp
- 8010240659 FOIA request for several categories of info re nuclear plants in US & waste disposal methods
 OARNIG, S. Affiliation Unknown 80/09/21 ip
- 8010270032 Responds to FOIA request for RD Mayer 790202 memo, results of discussion on fuel assembly response to mechanical loads Forwards document FELTON, J. M. Division of Rules and Records 80/10/17 Ip
- 8010270034 FDIA request for RD Meyer 770202 memo, results of discussion on fuel assembly response to mechanical loads DDE 600827 response encl RYAN, C Nuclear Information & Resource Service 80/08/13 2pp
- 8010270037 Responds to FDIA request for three categories of info re fews for withdrawn CP & GL applications Forwards App A documents SECY-364A & JF Ahearne response sheet withheld (ref FOIA Exemption 5) FELTON J H Division of Rules and Records 80/10/15, 2pp
- ~-8010270051 Notifies that Commission has approved recommendation to authorize General Counsel to take action to recover licensing review fees for denied withdrawn suspended or postponed application reviews HOVLE, J C Office of the Secretary of the Commission 80/09/04
- --B010270058 Comments on encl draft paper re face for withdrawn CP & OL applications & other approvals or reviews Lists addl info which should be added to App B MILLER.W O License Fee Management Branch 80/07/07 15pp
- --8010270071 Submits info re four utils which formally withdrew CP applications since 780323. Offective date of revised fee schedule Utils include Public Svc Electric & Os Co Naw England Power Co: AT Public Svc & OH Edison Co MILLER. W O License Fee Management Branch 80/06/02. 3pp
- --8010270081 Forwards list of withdrawn & annoused discontinuance of nuclear glants per 800513 discussion Provides estimation of review costs Util is not required to formally withdraw application MILLER.H O License Fee Management Branch 80/05/21 2pp
- --8010270087 Notifies of Commission request for preparation of revised & updated schadule re fees for facilities & matls licenses Detailed explanation & justification of specific cost items underlying each proposed fee should be on schedule basis CHILMS J Office of the Secretary of the Commission 77/02/07.
- 801027004B FOIA request for three categories of info re fees for withdrawn CP & OL applications KEANY,8 Winthrop, Btimson, Putnam & Roberts 80/09/23 2pp
- 10270127 Responds to FOIA request for Dendix Field Engineering Corp proposal in response to NRC-05-80-290, "Communications Console Design Rept." Document is available in FDR FELTON, J. M. Division of Rules and Records 80/10/22, ip.
- DiO27013O FOIA request for Bendix Field Engineering Corp proposal in response to NRC 05-80-290. "Communications Console Design Rept"
 FADIDA.A CLP Telephone Co. of Maryland. 80/10/07. 1p

- 8010270134 Responds to FOIA request for FYBt purchase orders re three models of Xerox copiers NRC does not lease or own models listed in request FELTON, J H Division of Rules and Records 80/10/22. 1s
- 8010270135 FOIA request for FY81 purchase orders re three models of Xerox copiers CONTESSA, W. B. Gopylease Corp of America 80/10/14 1p
- 8010270160 Application for matl/byproduct license authorizing JE Law te use & or supervise use & disposal of 100 Ci byproduct & source matl & 2 g BNM in any byproduct, source & SNM LAN, J E Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.) 58/05/15 Bpp
- --8010270165 Application for Matl/Byproduct License authorizing JE Law & AL Snith to use %/or supervise use % disposal of 40D C1 byproduct % source matl & SNN in any byproduct source & 6NN Supporting documentation encl LAN, J E Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) 11024 39/05/15 20pp
- 8010270145 FOIA request, on behalf of N Lewis & J Conwell, for documents re sites used for dumping radwaste off Pacific Coast SPAIN, O H Spain, O H 80/08/23 3pp
- 8010280117 Responds to FOIA request for listing of all procurement ofce within NRC & commodities procured by each Forwards listing of addresses for Div of Contracts & regional ofcs, contracts executed in FY80 & bidder mailing list application form FELTON.J M Division of Rules and Records 80/10/16 ip.
- --B01028012& Listing of address, telephone numbers & point of contact for Div of Contracts & each regional ofc procurement operation. 4 Commissioners 80/10/16 1p
- --8010280127 Contracts executed in FY80
 * Division of Contracts 80/08/12 7pp.
- --8010280193 Informs of establishment of contractor bidder mailing list sys Sys allows potential offerors w/capabilities of performing sycs for NRC to receive solicitations within areas of interest & expertise H/related documentation HALMAN,E L. Division of Contracts 77/07/10 11pp
- 8010280122 FDIA request for listing of all procurement ofcs within NRC & commodities procured by each EMPEY.M K Federal Acquisition Counselors 80/09/24 lp.
- 801028013B Addl response to FOIA request for 14 specifically listed documents needed to assess public health hazards from abandoned radioactive dumpsites Formaids documents iisted in App A. Other documents are available in PDR FELTONJ N Division of Rules and Records 80/10/15 2pp
- --B0102B0147 Hatl/Byproduct License 37-0104B-01 for Atlantic Refining Ca is amended in its entirety per 58072B application Amend 4 authorizes use &/or possession of B-35,Ca-45,Sr-99,C-14, Fa-55 & Fe-57 in chemical tracer studies MASCN,J R Atomic Energy Commission, 58/11/12 2pp
- --8010280151 Responds to NRC 601116 ltr Verifies that new disposal solits also applies to programs conducted under Mat1/Byproduct Licenses 37-01048-02 & 37-01048-03 Waste from programs will be handled by Crossroads Marine Disposal Corp MYERB,W A Atlantic-Richfield Co 60/11/22 lp
- --8010280157 Forwards Amend 6 to Matl Byproduct License 37-01048-01 per 601028 application Amend renews license in its entirpty covering only isotopes listed in 601028 application & not all isotopes & uses previously authorized W/o encl BRINKMAN.R E Atomic Energy Commission. 60/11/16 lp.
- --8010280166 Forwards application for renewal of Matl/Byproduct License 37-01048-01 Commercial waste disposal company will handle all radioactive waste in future H/o encl MYERS,W A. Atlantic-Richfield Go 60/10/28 ip
- --B010280172 Discusses 580728 application for renewal of Matl/Byproduct License 37-01048-01 & disposal of waste matl by burial at sea Requests addl info re dispose of wastes to continue review of application MILLER.W O. Atomic Energy Commission. 58/08/25 1p.
- --8010280178 Ack receipt of 580825 request for add1 info re buriel of waste matl.Radwaste from analytical lab is handled in close coordination w/waste disposal at Automotive Lab under direction of HB Jackson Provides waste disposal procedures MYERS,W A, Atlantic-Richfield Co. 58/09/i1 2pp.

- --8010280183 Ack receipt of 580911 ltr describing waste disposal procedures Each drum should be labaled to show date of burial; radiation intensity at surface; radioisotopes contained in drum & quantitly of each,
 MILLER, H O Atomic Energy Commission 58/10/06 ip
- --8010280189 Clarifies waste disposal procedures in response to 581006 request Drum containing radioisotopes for burial at sea will be labeled w/date of burial radiation intensity at surface, radioisotopes contained in drum & quantity
 MYERB,W A Atlantic-Richfield Co 58/10/30 3pp
- --8010280194 Application for Matl/Byproduct License authorizing FW Melgolder to use &/or supervise use of 10 mCi 8-35 in analytical study MELPOLDER, F. W. Atlantic-Richfield Co 56/08/16 3pp
- --80i0280i77 Application for Matl/Dyproduct License authorizing FW Melpoider to use &/or supervise use of 15 mCi Br-90 & 2 3 mCi C-14 in analytical studies in lab • Atlantic-Richfield Co 57/01/28 3pp
- --8010280202 Matl/Byproduct License 37-01048-02 for Atlantic Refining Co is amended in its entirety per 390211 application Amend 3 authorizes use of 150 mCi of any byproduct matl between Atomic Numbers 3-33 in irradiated piston rings for research MASCHJUR Atomic Energy Commission 59/02/26 ip
- --B0102B0205 Matl/Byproduct License 37-01048-02 is amended in its entirety per 580911 & 1030 applications Amend 2 adds symbol (059) below license number & Condition 14 re disposal by burial at sea MASON:J.R. Atomic Energy Commission 58/11/12 ip
- --8010280207 Application for Matl/Byproduct License authorizing HR Jackson to use &/or supervise use of 200 mCi Co-60,Cr-5i, Sc-46 & Fe-57 in cast aluminum cylinder sleeves in cylinder liner to be installed in lab test engine for study Armstrong Civil Defense 61/07/05 3PP
- ---9010280218 Application for renewal of Matl/Byproduct License 37-01048-O2: authorizing HR Jackson to use &/or supervise use of 190 mCi of Fe-55.Fe-59.Co-60 & Cr-51 in internal combustion engine piston ringe MYERB.W.A Atlantic-Richfield Co 16319, 59/02/11 3pp.
- --8010280224 Statement before Joint Committee on Atomic Energy of Congress: Special Bubcommittee on Radiation, re-programs concerning disposal of low level radwaste into oceans LUEDECKE.A.R Atomic Energy Commission 8-21-39 59/07/29 19pp
- --8010280232 Forwards info re sea disposal of solid radwaste for use in inventory, Includes table summarizing radwaste sea disposal operations for 1946-1962 & sea disposal licenses which are still in force.

 8DULE-H.F. Atomic Energy Commission 69/04/01 9pp
- --8010280240 "Radioactive Waste Dumping Off Coast of CA." fact sheet * Environmental Protection Agency 80/08/15. Spp.
- 8010290050 Responds to FOIA request for guidelines used by Load Forecast Panel which visited 22 sites to establish model for const completion NRC has no documents subj to request No formal guidelines exist for Forecast Panel FELTON,J M Division of Rules and Records 80/10/22 ip
- 8010290054 FOIA request for guidelines used by Load Forecest Panel which visited 22 sites to establish model for const completion

 CONNOR: L Doc Search Associates 80/10/06 2pp
- 8010290057 Responds to FOIA request for five categories of info re NRC. Forwards documents listed in App A Recent case decisions are available from NTIS W/o encls
 FELTON.J M Division of Rules and Records 80/10/24 2pp
- 8010290061 FOIA request for five categories of info re NRC, including regulatory powers & duties, recent regulations re hazardous waste disposal & case decisions BRYSON. 8. Affiliation Unknown 80/10/10 1p.
- B010310198 Final response to FOIA requests for documents re transportation of spent nuclear reactor fuel Forwards addl released documents. Info partially withheld (ref Atomic Energy Act) REAMER, C. W Office of the General Counsel B0/10/24 5pp

- --8010310212 Appeals denial of FOIA request for strip charts or route overviews re routes of irradiated nuclear reactor fuel shipments Documents do not contain commercial or financial info Release will not jeopardize security REYNDLDS.W American Friends Service Committee 80/06/26 2pp
- --8010310226 "Spent Fuel Route Survey, Ban Onofre, CA to Morris, IL " Info partially withheld response capabilities summaries for CA, AZ & NM, TX, KB, MO & IL. Bafe Haven & telephone data (ref Atomic Energy Act) 4 Commissioners 79/10/31 30pp
- --B010310235 "Bpent Fuel Routs Survey Pleasanton.CA to ID Falls.ID."
 Info partially withheld response capabilities summaries for CA:NV & ID. Bafe Haven & talephone data (ref Atomic Energy Act)
 - * Commissioners 80/03/31 14pp
- --801031024B "Spent Fuel Route Survey Pleasanton.CA to Hanford/Richland, MA " Info partially withheld response capabilities summaries for CA.DR & MA & telephone data (ref Atomic Energy Act)
 - * Commissioners 79/10/31 17cp
- --8010310282 "Spent Fuel Route Survey.Forked River.NJ to Battelle.West Jefferson.OH " Info partially withheld response capabilities summaries for NJ.PA & OH & Save Haven & telephone data (ref Atomic Energy Act) # Cormissioners. 80/01/31 13pp
- --8010310264 "Spent Fuel Route Survey, Battelle Labs, Columbus, OH to Richland, WA" Info partially withheld response capabilities summaries for OH, IN, IL, IA, WE, WY, UT, ID, OR & WA & Safe Haven & telephone data (ref Atomic Energy Act)
 4 Commissioners 79/10/31 Obpp
- --8010310318 "Spent Fuel Route Survey, Fort Saint Vrain, CO to ID Falls, ID " Info partially withheld: response capabilities summaries for CO, HY, UT & ID & Safe Haven & telephone data * Commissioners 79/09/30 12pp
- --8010310274 "Road Transportation Route, Battelle, Columbus, OH to Richland, WA" info partially withheld mobile telephone vulnerability data
 4 Commissioners 79/11/27 App
- --8010310285 "Road Transportation Route Battelle Columbus OH to Richland, HA" Info partially withheld mobile telephone vulnerability data

 * Commissioners 80/03/18 3oo
- --B010310287 Appeals denial of FOIA request on behalf of VA Bunshins Alliance for documents re transportation of spent nuclear fuel from Portsmouth. VA to Eavannah River Plant in Aiken, BC, Release will not harm competitive position of company MEYER, K. A. Meyer, K. A. B0/07/07 2pp.

GEN TEC 18 GENERIC TECHNICAL ISSUES

- 8010100312 Forwards nonproprietary version of NEDD-24794, "Dynamic Lateral Loads on Mark II Main Vent Downcomer - Correlation of Independent Ref Data " BUCHHOLZ,R H General Electric Co MFN-159-80 80/09/17. Ip
- --8010100318 NEOD-24794

 Nonproprietary version of "Dynamic Leteral Loads on Mark II Main Vent Downcomer Correlation of Independent Ref Data." BORHAUG.J.E Pretect, Inc. MUZZY.R.J., IANNI.P W General Electric Co. 80NED038. 80/09/31 Sipp
- 8010150252 Forwards NEDE-25289-1-P. "Comparison of Single & Multivent Chugging Phase 2." Rept withheld (ref 10CFR2 770). BUCHHOLZ,R H General Electric Co RHB-76-80 80/09/17 ipp.
- 8010160561 Forwards errata to NEDE-24B22-P, "Mark II Improved Chugging Mathodology," on behalf of Mark II owners group; as part of containment program Errata includes aditorial corrections Info withheld (ref 160FR2 790)

 BUCHHOLZ, R H General Electric Co MFN-161-80 80/09/26 1p.
- 8010210332 Forwards errata to NEDO-24822, "Mark II Improved Chugging Methodology," dtd 800912. Major revisions are corrections to Equation 4 32, related figures in rept & editorial corrections.

 BUGHHOLZ, R H General Electric Co. MFN-165-80. 80/10/01, 1p.

- --8010210934 NEDD-24822 ERR ; Errata to NEDO-24822; "Mark II Improved Chugging Nethodology" # General Electric Co ED/08/31 20pp
- 8010280597 Informs that implementation of NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Goolant Pump Supports." has been delayed pending resolution of EPRI Fracture mechanics proposal. SCHERER.A. E C-E Power Systems LD-80-055 80/10/24. 2pp
- 8010270142 Notifies that HUTA has complied w/lab 800530 request for JOHNSON,R E. Generic Issues Branch, 80/10/14 1p.
- 8010300353 Forwards Suppl 1 to NUREQ-0487, "Mark II Containment Lead Plant Program Evaluation & Acceptance Criteria " W/o encl. KNIEL,K. Assistant Director for Generic Projects 80/10/23 1p.

ILE INSPECTION AND ENFORCEMENT

- 8005190055 1E Bulletin 80-22, "Confirmation of Employee Qualifications,"

 a Diffice of Inspection & Enforcement, Diffice of the Director 60/10/02 2pp.
- 8008220239 IE Info Notice 80-34, "Boron Dilution of Reactor Coolant During Steam Generator Decontamination." > Office of Inspection & Enforcement. Office of the Director 80/09/26. 2pp.
- 8008220241 IE Bulletin 79-Ot. Suppl 2, "Environ Qualification of Class IE Equipment,"

 * Office of Inspection & Enforcement, Office of the Director.
 80/09/30 14pp
- 8009030041 PNO-III-80-129, on 800708, regional ofc contacted by person who had purchased two cases of bottles from estate sale.
 Buttles marked "Radioactive Met! Hellinckrodt Nuclear (RUS Site)," Bottles dated 1975 & contactined 1-125,
 PAPERIELLO, C. J., DAVIS, A. B. Region G. Chicago: Office of the 80/07/08 tp.
- 8009080208 PNO-III-80-I36 on 800722. Worth, IL, pulice dept discovered abandoned automobile containing package identified as delivary case used by Nuclear Phermacy, Inc. Package contained radioactive matl. Vehicle bypackage held overnight. DAVIB.A. B. Region 3, Chicago, Office of the Director 90/07/23
- 8010020008 PNA-80-03A; on 800918, event mistitled "Medical Misadministration." Ofc of 8tds Development advises that event involved improperly prepared pharmaceutical Reporting requiremments become efective 801010.

 KERR. G. H. Assistant Director for State Agreements Programs. MCGRATH. J. R. Office of State Programs. Director. 80/09/19
- 6010020011 PNA-BO-94.on 800917.liquid raffinate line leading to evaporation pond broke at Union Carbide Uravan U Mill. Cause not stated. Line was shut upon discovery & immediate cleanup started. KERR.O W. Assistant Director for State Agreements Programs. KENDIO, J. F. Office of State Programs, Director. 80/09/19. ip.
- B010020114 PNA-B0-31:on B00911.WA PIRO held press conference, calling for NRC & Congressional investigation on alleged inability of State of WA to monitor environ & contain radioactive releases at Western Nuclear & Dawn Mining U mills.

 KERR. O. W., KENDIG. J. Office of State Programs, Director. 80/09/12
- 8010020502 EN-80-045:on 800925; notice of violation & notice of proposed imposition of civil penalty to be issued for license. Action based on alleged items of noncompliance re delivery of waste matl w/o proper labeling.

 BROCKETT, T. W., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director. 80/09/23, ip.
- 8010020303 EN-80-044, on 800923, notice of violation & notice of proposed imposition of civil penalty to be issued for license. Action based on alleged item of noncompliance re-procurement of Xe-103 gas
 BROCKETT, T., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/09/23 1p.

- 8010020505 EN-80-043 on 800925 notice of violation & notice of proposed imposition of civil penalty to be issued for license. Action based on alleged items of honcompliance re personnel supciure to approx 7 55 rems Ir-192
 BROCKETT.T.W. THOMPSON.D. Office of Inspection & Enforcement.
 Office of the Director 80/09/25 1p.
- 8010020386 EN-80-029A on 800925, order imposing civil penalties in amount of \$3,000 issued Action based on two items of noncompliance re packaging & labeling of radioactive licensed math.

 BROCKETT.T.W., THOMPSON.D., Office of Inspection & Enforcement, Office of the Director 80/09/25 1p
- 8010030525 PND-I-80-127; on 800909, 10 members of Brandywine Peace Committee demonstrated & entered nondestructive testing area of 9E Vailey Forge Space Ctr No licensed matl used or stored an area. KINNEMAN, J.: SMITH: O Region 1: Philadelphia: Office of the Director 80/09/09. ip.
- 8010030530 PNO-III-80-102 on 800528 Region 3 informed that truck had recommend that the run and the recommend that the run over moisture density gauge containing 10 mgi Cs-137 & 30 mgi Am-241 sealed source Surveys by state verified that source was intact. PAPERTELLO, C. J., DAVIB-A B Region S. Chicago: Office of the Director. 80/05/29 1p
- 8010030333 FNO-III-80-146 on 800807, Region 3 informed that RIA hit containing 3 uci of I-125 had leaked over several packages in truck, Abbott Labs & State of WI are responding NICHOLSON, N. PAPERIELLO, C. J. Region 3, Chicago, Office of the Director. 80/08/07. ip
- 8010030337 PND-III-80-149. on 800731. Region 3 informed that four nuclear medicine technicians of Carle Clinic Association may have received exposures in excess of 10CFR20 whole body limits. Region 3 plans to conduct investigation ADAM.M., PAPERIELLO,C J. Region 3, Chicago, Office of the Director 80/07/31. 1p.
- 8010030540 PNO-III-80-103.Region 3 found Diamond Shamrock Chemical Co-unable to account for gauge w/swaled source of 500 mGi C=-137.Licenese has been instructed to conduct radiation surveys to locate source LABUK, S. R., BCHULTI, W H Region 3, Chicago, Office of the Director DAVIS.A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/09/29. 2pp
- 8010030546 PNO-111-80-145 on 800731 Region 3 received allegations that on 800301; Lakeview Hosp personnel administered radiopharmaceuticals in double quantities.

 Interviews revealed allegations were substantially correct, ADAN, H., PAPERIELLO, C. Region 3, Chicago, Office of the Director 80/08/04, 2pp.
- 8010030547 PNO-III-80-152: on 800813, therapeutic quantity of 8 5 mCi I-131 was administered orally to patient instead of prescribed diagnostic dose, investigation initiated. PAQLIARD.J.A., DAVIS.A.S. Region 3, Chicago, Office of the Director 80/08/14. 2pp.
- 8010060030 PNO-I-80-134: on 800920, Paramus, NJ police received rept of debris on State Highway 17 which was source charger containing 50 Gi Ir-192. After elect by police, second missing source charger was recovered.
 FRIEDMAN, L.F., KINNEMAN, J.D., 8MITH, Q. Region 1, Philadelphia, Office of the Director. 80/09/22 2pp.
- 8010060038 PND-III-80-132, on 800715. Phermatopes van transporting two attache cases containing medical byproduct mati involved in collision in Massilion. DM. Nuclear medicins technologist from Ductors Hosp in Massilion. OH responded. REICHMOLD, M. P. , DAVIS, A. B. Region 3, Chicago, Office of the Director. 80/07/16 2pp.
- 8010060042 PNG-III-80-141, on 800729, Region 3 was informed that 100 mCi dose of Tc-99m in lead container was lost in parking lot of dose of Tc-99m in lead container was lost in parking lot of Detroit Central Hosp Because of 6-h half life, matl will almost completely decay in 3 days.

 PAPERIELLO.C.J. DAVIR.A.B. Region 3. Chicago, Office of the Director. 80/07/29 2pp.
- 8010060044 FNC-III-80-161 on 800828 Region 3 received notification that contamination had been found on security guard & in security bldg at Argonne Netl Lab. Contamination was traced to ruptured luminous gunsight containing Pm-147. PAPERIELLO, C. DAYIS, A.B. Region 3, Chicago, Office of the Director 80/08/29. 2pp.

- 8010060048 PND-III-80-167, on 800903. Region 3 was informed that private aircraft carrying radioactive mat1 had crashed near Midway Airport in Chicago At time of rept. Region 3 personnel had recovered three of five vials of radioactive mat1 involved 8CHULTZ. N H . DAVIS, A B. Region 3, Chicago, Office of the Director 80/09/03 2pp
- 8010060071 PND-III-80-139 on 800716.Region 3 was informed that byproduct mat1 delivered to hosp was inadvertently taken, Mat1 included 90 moi Tc-99m & 14 uCi I-131 Region 3 has dispatched personnel to hosp mathematical Region 3. Chicago, Office of the Director 80/07/16 2pp
- 8010060072 PND-III-80-172 on B0070B, Uhmart guage, containing 100 mCi Cs-137, found to be damaged End of cylinder found bent over Btate of HI Dept of Public Health is responding PAOLIARD.J A. FISHER, W.L. Region 3, Chicago, Office of the Director 80/09/08, 1p.
- 8010050075 PND-III-80-173 on 800709, received allegations of unsafe practices in byproduct mati program at Univ of MI Allegations included sipatting by mouth eating & storing food in hot lab & no film or finger badges assigned PAGLIARO, J A. FISCHER, W L. Region 3. Chicago, Office of the Director. 80/09/10 ip
- GO10060132 PNO-I-80~116. on 800731, Ethicon, Inc reported fire had occurred in Go-60 irradiator Fire department entered through roof plug & extinguished fire after extensive smoke damage.

 No sources damaged & no personnel exposed.

 ROME.C., KINNEMAN.J. Region 1, Philadelphia, Office of the Director.

 80/08/01 1p
- B010070164 PND-IV-B0-029A on B00903.Region 4 inspector investigated loss of BB0 mCi Tr generator which had been discarded in hosp trash Device never found. Reasonable assurance exists that device is covered w/10 ft refuse at sanitary landfill. CAIN.C L Region 4. Dallas. Office of the Director 80/09/08 ip
- 80:0080544 PNO-I-80-122 on 800815, unplanned release of gaseous radioactivity from Unit 3 reactor bldg vent occurred Peak release rate was 33% of Tech Spec limits. Cause believed to be malfunction of Unit 2 offgas sys OREENANNE Region 1. Philadelphia. Office of the Director 80/08/15 ip
- 8010070150 FNO-IV-80-027; on 800821, all offsite telephonei5 communication. including microwaye systwas lost for 3-h bacause of forest fire near plant site. Caused by heat damage to aerial telephone lines. JOHNSDN, W D Region 4, Dallas, Office of the Director. 80/08/22.
- 8010090234 PNO-III-80-158: on 800B22, plant tripped from 55% power due to feedwater pump controller failure. All sys responded as required. No radioactive releases. BDYD, D. C. Region 3, Chicago, Office of the Director. 80/08/25.
- B010090249 PNO-III-80-159. on 800826, while operating at 88% power, plant was manually tripped because of loss of condensate the fastive pumps. Recovery took 2.5-h to regain onscala readings of steam generator levels

 JORGENSEN, B L. Region 3. Chicago, Office of the Director. 80/08/26.
- 8010090205 PNO-III-80-166 on 800903, unit tripped from 93% power due to low steam generator level:caused by feedwater pump trip. Water hammer occurred while steam generator level was below feed ring causing safety injection actuation KOFALER, J.E. Region 3, Chicago, Office of the Director. 80/09/03. 200.
- 8010090270 PNG-III-80-164 on 800902, licensee found leakage from 10-inch core spray piping inside drywell. Two welds in A loop have seepage & one weld in B loop has visible crack. Unit is in refueling outage.
 CHRIBSOTHOS.N. Ragion 3. Chicago, Office of the Director. 80/09/03 3pp
- 8010090274 PNG-III-80-170A.on 600908.ultrasonic test of Unit 2 bolts attaching column supports to steam generators resulted in 3 of 48 bolts w/defects.Licenses has at least 5 of 6 good bolts per column & plans to start up Unit 2. FEIRABERDO.C.E Region 3. Chicago. Office of the Director. 80/09/08. ip.

- 8010090293 PNO-III-80-128A on 800709, plant was started up & while at low power, reactor automatically shut down from high startup rate trip. Caused by faulty instrument. During startup control rod 8 would not move, Repairs are in progress, UCRGENSEN. B L. Region 3. Chicago. Office of the Director, 80/07/10,
- 6010090302 PNO-III-80-170, on 800904, efforts to remove bults from steam generator upper supports resulted in breaking two bolts. Ultrasonic exemination of all of bolts identified addited defects Cause could be stress corrosion cracking. FEIERABEND.C. Region 3, Chicago, Office of the Director 80/09/05, to.
- 8010090306 PND-III-B0-154 on B00B14, sealed source gauge containing B9 mG1 of Ca-137 reported missing. Mer 1980 inventory discovered gauge as missing but no rept was filed NRC inspector dispatched to site to observe licensed radiation survey LASUK.8 R. PAOLIARO.J.A. Region 3. Chicago, Office of the Director. B0/08/15 19
- 8010090523 PNA-80-035 on 800917, State of CO informed NRC of pending release of CO Bureau of Investigation rept critical of Cotter Corp & CO health dept. Findings indicate menipulated data & deficient rafiation control propram Rept requested. KERR, O N. Office of State Programs, Director. 80/09/22 2pp.
- 8010100406 PNO-III-80-111A on 800609, operator discovered improper electrical lineup where two engineered safety feature buses were tied together Improper electrical lineup was satablished for loss of ac power test on 800302.

 8MITH.J. D. Region 3. San Francisco, Office of the Director. 80/06/10. 1p
- 8010100408 PND-III-80-111: on 800609, during power operation, operator found improper breaker lineup of main control board Lineup was immediately corrected. Licensee is investigating. BMITH, J D Region G. Chicago, Office of the Director. 80/06/10. 10.
- 8010140350 PND-TMI-80-040A: on 800716, containment bldg personnel airlock inner door seals failed to pass seal lankage test.

 Subsequent measures to correct leakage failed to meet leakage criterion
 CONTE,R.J. Region 1, Philadelphia, Office of the Director 80/07/17 ip.
- 8010140357 PNO-TMI-80-040. on 800716, containment personnel airlock 2 inner door was successfully opened. Upon closure of inner door, seal rings failed leakage test. Licensee & NRC review of matter continues CONTE.R. J. Region i. Philadelphia. Office of the Director. 80/07/16. 1p.
- 8010140367 PNG-II-80-136; on \$00805, ecram discharge vol water level alarm activated on Unit 1 indicating accumulation of 3 gallons in scram discharge vol instrument vol. Cause balieved to be condensation in clean raswasts vent header JULIAN.C. Region 2. Atlanta, Office of the Director. 80/08/06, 200.
- 8010160031 PNG-V-R0-063: on 800803, interest in Camp Parks Army Base has been sparted by recent articles in local newspaper, Sase had been used for AEC & NRC operations for many yrs.

 800K-M.E. Region 5, San Francisco, Office of the Director, 80/08/05.
- 801014003B PNO-III-80-148: on 800904. Region 3 representatives met w/ Newburgh Heighte, OH public officials to discuss results of NRC survey of waste disposal site. NRC survey found low levels of U at several locations on site. MENCZER: H B., DAVIB: A B Region 3, Chicago, Office of the Director. 89/09/04. 1p.
- 8010160370 PNG-III-80-177: on 800917, Gircuit Court of LaBalis County, IL issued temporary restraining order requiring Luminous Processes, Inc to board up windows & doors within 72-h & gost bldg as hazard PAPERIELLO, C. J. FISHER, W.L. Region 3, Chicago, Office of the Director 80/09/18, 2pp.
- 8010160374 PND-11-80-122 on 800704; leaking cracks were found in spool piece in reactor water cleanup sys. Facility will be placed in cold shutdown to effect repairs. Licensee is evaluating cracks.

 TAYLOR, P. A. Region 2, Atlanta, Office of the Director. 80/07/08, to.

- 8010160530 PNO-II-80-132 on 800727, oil leak developed on turbine governor valve While ramping power down, main feedwater pump tripped & reactor tripped on low steam generator level ECCS did not actuate & plant sys functioned as designed DONAT, T J Region 2, Atlanta, Office of the Director 80/07/30
- 8010160588 PNO-II-80-144 on 800826, reactor trip & safety injection occurred due to spurious steam header to steam line differential pressure caused by entrapped air in bypass around newly installed polishing demineralizers JOHNSON, A Region 2, Atlanta, Office of the Director 80/08/27
- 8010160633 PNG-II-80-139 on 800814, manual reactor trip was initiated to terminate continuous withdrawal of control rod bank D All control rods inserted normally on trip Licensee investigation is in progress
 BANCE.H C. Region 2: Atlanta, Office of the Director 80/08/14 in
- B010160642 PNO-II-80-128 on 800726, unit was manually scrammed to test scram discharge vol Two of four scram level float switches failed to actuate All other sys performed normally during scram
 TAYLOR,P A Region 2, Atlanta, Office of the Director 80/07/28
- 8010160631 PNO-II-80-129 on 800728, contaminated reactor coolant backflowed through plant nitrogen sus & approx 10 gallons leaked from relief valve in plant tank farm outside restricted area Licensee declared Class & emergency MARTIN.R Region 2, Atlanta, Office of the Director 80/07/28 200
- 8010160739 PND-I-80-138 on 800925, vehicle owned by Gamma Diagnostic Labs carrying radiopharms was stolen from Norwood Hosp, MA Truck & contents were recovered within 2-h. CLENN, J. KINNEMAN. J. Region 1, Philadelphia, Office of the Director 80/09/29 ip
- 8010160748 PNO-II-80-II5 on 800620, two 95-gallon barrels containing approx 20 gallons each of contaminated waste oil were inadvertently mised w/2000 gallons of uncontaminated waste oil Waste oil truck has been returned to plant for storage.

 MARTIN, R Region 2, Atlanta, Office of the Director, 80/06/25 ip
- 9010160792 PNO-I-80-133 on 800919, in response to complaint, Region i inspectors found radioactive math stored on driveway of private residence Math contisted of eleven Mo-99/Tc-99m generators; some w/lead shields removed OLENKI, J. KINNEMAN. J. Region 1. Philadelphia, Office of the Director 80/09/22 2pp
- 80:01660797 PNO-II-80-117. on 800626) following spurious reactor trip, HPCI started as designed but tripped on high steam flow differential pressure signal HPCI was manually placed in svc Licensee is investigating cause TAYLOR.P A Region 2, Atlanta, Office of the Director 80/06/26 10
- 8010160778 PNO-II-80-105 on 800611, steam generator tube leak of 95 gallons per day was identified in 8 steam generator. Upward leak rate trend existed for 30 days, Licensee plans to shut down prior to reaching leak rate of 900 gallons per day, GUICK, D. Region 2, Atlanta, Diffice of the Director 80/06/11 ip
- 80(0170002 PNU-II-80-116 on 800528, on Unit 3, cracks were identified in three of eixteen studs used to attach lower manway cover to steam generator Licensee has examined remaining studs & found add1 cracks
 MARTIN.R Region 2. Attanta. Office of the Director 80/06/26, 1p.
- O10170007 PNO-I-80-145 on 801007, while at 96% power. A safety relief valve opened w/o apparent cause. Operators were unable to close valve to manually scrammed reactor Preparations underway to investigate problem MARTIN.T Region i, Philadelphia, Office of the Director 80/10/07 ip
- Di0170254 PNA-80-32-on 800916, state agreement program personnel were notified of State of TX investigation into info supplied by anonymous telephone caller about Nuclear Diagnostic Labs violations re prescribed doses. Hearing set for 801014. (ERR.O.W. 80LLINO.L.A Office of State Programs, Director 30/09/17 1p.
- :10200636 PNO-II-80-1198 on 800628.76 of 185 control rods failed to fully insert due to accumulation of water in scram discharge vol Extensive investigations & tests failed to identify cause of accumulation of water in discharge vol.

 DANCE: H C Region 2: Atlanta. Office of the Director. 80/07/14

- 8010220449 PND-III-80-i71 on 800704, Region 3 informed by Caspersen, Inc of apparent theft of Mo-99/Tc-99m generator Region 3 satimates indicate no significant exposure would result from handling generator unless shielding removed ECNULTI, N H , DAVIS, A B Region 3, Chicago, Office of the Director 80/09/05 is
- 8050220452 PNO-III-80-112 on 800612 radiographer working at fossil fuel generating station in Overisel. MI received estimated 7 650 rems whole body exposure Caused by source not being fully retracted during film changes MIEDEMAN, D O . DAVIS, A B Region 3. Chicago, Office of the Director 80/06/13 ip
- 8010220454 PNO-III-80-157 on 800720, Battelle Columbus Labs employee received dose of 30 710 rems to right hand while removing water filter cartridge following flushing spent fuel cask Region 3 plans to investigate PECK, C C , FIBHER, W L , DAVIS, A B Region 3, Chicago, Office of the Director 80/08/25 ip
- B010220458 PND-II-80-145 on 800926, NRC high frequency radio sys achieved initial operational status Sys consists of 1 kH base station in Region 2 smergency ctr 8 100-watt mobile unit mounted in three vehicles OIBSON 0 T , JENKINS, 0 R Region 2, Atlanta, Office of the Director 80/08/29, 1p
- 8010220460 PND-III-80-108 on 800530. Region 3 was informed that whole body dosineter worn by radiotherapy technician from 800415-0514 at Univ of WI showed dose of 8.63 rems. Co-worker dosimeter for same period showed 30 millirems PAPERIELLO, CJ. J. DAVIS.A 8 Region 3. Chicago, Office of the Director 80/06/02 1p
- 8010220461 PND-IV-80-027 on 800831, licensee lost 880 mCi technecium generator which was inadvartently discarded in hosp trash Search through municipal dump has been initiated by hosp CAIN.C L. Region 4, Dallas. Office of the Director 80/09/04 is
- 8010220463 PNO-III-80-i10 on 800604, Region 3 was informed that package containing 1 uCi I-125 in radioimmunoassay kit was crushed at 0'Hare Airport No activity detected in area or on personnel Apparently, vial had not been broken PAFERIELLO, C J. DAVIS, A B. Region 3, Chicago, Office of the Director 80/06/05 ip
- 8010270039 PND-1-80-149 on 801010 runplanned release of 0 5 Ci of noble gas from sits Caused by personnel error in opening valve on hydrogen analyser All five affected employees to receive whole body counts MCGABE.E C Region 1, Philadelphia, Office of the Director. 80/10/10 1p.
- 8010270226 PNO-IV-80-036A investigation of suspected theft of 1 mCf I-131 disclosed that math had not been stolen but had been inadvertently delivered to wrong hosp 8ACMN.G.D. Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/10/16 1p
- 8010270541 PNA-80-36A on 800920, Ofc of State Programs notified by Region 2 that president of Intl Chemical Workers Union had filed formal complaint w/OBHA re radiation safety at New Hales Div, Intl Minerals Corp, Mulberry,FL KERRO W., BOLLING,L A Office of State Programs, Director 80/10/21 1p
- 8010300401 Forwards IE Circular 80-22, "Confirmation of Employee Qualifications" & draft cover ltr THORNBURG. H, D Division of Reactor Construction Inspection IEC-80-22. 80/10/02 2pp
- 8010300570 PNO-IV-80-036 on 800924.1 nCi I-131 in shipment to Frances Mahon Deaconess Hosp. Olasgou. MT was stolen by delivering cab driver who may have administered I-131 to girlfriend. Dose would not be medically significant BROWN.0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch, 80/10/16. 1p.
- HISC PUBLIC DOCUMENT ROOM MISCELLANEOUS
- 8010030527 Recommends rejection of unsolicited proposal from Science Applications. Inc. "Proposal to Provide NRC w/Reactor Radiation Streaming Analysis Capability "RDS9.D F. Division of Bystems Integration NRC-04-79-179

NONDOCKETED ITEMS

- --8010030327 Submits branch review of Science Applications. Inc "Proposal to Provide NRC w/Reactor Radiation Streaming Analysis Capability " Contract award not recommended SOLBERG, D E Division of Safeguards. Fuel Cycle & Environmental Research NRC-04-79-179 80/07/13 2pp
- --8010030332 Forwards Science Applications, Inc "Proposal to Provide NRC W/Reactor Radiation Streaming Analysis Capability" for review & consideration W/o encl COLEMAN, H E Division of Contracts NRC-04-79-179 BO/07/08
- B010070419 Forwards requested figures re industry credit refund premium.1970
 .0DNEB.B D American Nuclear Insurers 80/09/30 ip
- 8010080658 Responds to 800908 inquiry re concerns expressed by F Straut of Baker Testing Svcs, Inc All monies collected by Commission for licensing or insp activities are forwarded to UB Treasury Fee covers costs re insp activities DIRCKS, U J Office of the Executive Director for Operations 80/09/24 2pp
- --8010080660 Requests info re enci itr from F Straut of Baker Testing Sycs.Inc re fee charged by NRC for routine audits STUDDS:Q E House of Rep 80/09/08 4pp
- BO10100207 Forwards list of cases pending before licensing boards, appeal boards or Commission.Oct 1980 update CHRISTENSURY.E Hearings Division 80/10/01 27ep.
- B010100233 Requests technical assistance of Defense Nuclear Agency in study of plant vulnerability to electromagnetic pulse DENION.H R Office of Nuclear Reactor Regulation, Director B0/09/26 ip
- 801020008B Responds to 800804 memo from 8J Chilk FR notice modified per Item 1 Also, NUREG-071B addresses importance of close util-vendor-architect-engineer integration requested in Item 2
 DENION, H.R. Office of Nuclear Reactor Regulation, Director 80/10/02 ip
- BO10210095 Responds to BO0719 ltr to Senetor Kennedy re-safer nuclear reactors w/better instrumentation Licensees are required to install reactor water level indicators for inadequate core cooling DENIDN.H.R. Office of Nuclear Reactor Regulation, Director BO/097/10 2pp
- --8010210108 Forwards D McGoldrick 800709 ltr re safer nuclear reactors Requests response Supporting documentation and KENNEDY, E M Senate 80/07/29, 7pp
- --B010210117 Speech entitled "Automatic Control of Water Level for PHR Plant w/Natural Circulating Steam Generators During Low Power Operation:" presented at 770907-09 Power Plant Dynamics, Control & Testing Symposium, W/documentation FAN. C. C-E Power Systems 77/09/09 20pg
- 8010220132 "Bummary of NRC Sponsored Two-Phase Flow Instrumentation for Reactor Safety Research:" presented at ANS 800608-12 annual meeting in Las Vegas: NV HBU, Y , HDN, A L Division of Reactor Safety Research. 80/06/12
- 8010270516 Responds to 800923 inquiry to TV Toft concern about NRC assessment of insp fee Fee covers cost of performing routine insp of private practitioner use of radioctive matl in medical program
 DIRCKE, U. Office of the Executive Director for Operations.
 80/10/10 2pp
- --B010270519 Requests explanation of NRC policy on insp fee assessment, to respond to encl TV Toft concerns about fee CHENEY, D House of Rep B0/09/23 3pp
- 8010280112 Responds to 800822 memo re federal training facility for nuclear power plant personnel, NRC does not intend to establish federal training ctr Accreditation procedures & criteria being developed for vendor operated training ctrs DIRCKS, W J. Office of the Executive Director for Operations, 80/10/09. 1p

- NUREG REPORTS AND RELATED CORRESPONDENCE
- 8009100759 SECY-B0-236
 Recommends issuance of final rule 10CFR72 re specific
 licensing requirements for storage of spent fuels in
 independent spent fuel storage installation Draft FR notice
 encl
 MINGOUE, R B Office of Standards Development, Director 80/05/08
 86pp
- 8009170056 NURE0-0090 V3 NO1
 "Rept to Congress on AD's.Jan Mar 1980 "
 * Office of Management and Program Analysis 80/06/30 38pp
- 8009300303 NUREO-0685
 "Environ Assessment for Effective Changes to 10CFR50 & App & to 10CFR50 Emergency Planning Requirements for Nuclear Power Plants"

 DTT.W R Sit & Environ Stds Br (formerly Environ Prot Stds Br) 80/08/31 38pp
- 8010010071 Responds to 800728 ltr re NUREO/CR-1280, "Power Plant Staffing " Info requested not available NRC will direct inquiry to Basic Energy Technology Associates, inc. rept author.

 COLLINS.P.F. Operator Licensino Branch 80/09/16 19
- 8010010393 NUREO/CR-1586
 "Raspirator Studies for NRC Oct 1948-Bept 1980 Evaluation & Performance of Escape-Type Self-Contained Breathing Apparatus," progress rept HACK, A., TRUJILLD, A., CARTER, K. Los Alsmos Scientific Laboratory FIN A-7039 LA-8432-PR 80/07/31 15pp Available at NTIS
- B010010412 NUREO/CR-1537
 "Oap Conductance Test Series Fuel Characterization Data
 Rept "
 CHARYULU,H K , KERHIN,D K EG&O Idaho, Inc FIN A-6041 EGG-2046
 B0/09/30 46pp Available at NTIS
- 8010010531 Bubmits comments on greface to NUREG/CR-1580 draft rept.
 "Human Engineering Quide To Control Room Evaluation." for
 NRC review
 HAGEN.E.W Oak Ridge National Laboratory 80/09/24 3pp
- 8010020642 Forwards comments & suggested revisions to NUREQ-0696, re data acquisition sys for licensees Section V should be rewritten & addl section entitled. "Acquisition & Control of Technical Data:" should be included CROPP.L Sandia Laboratories 80/09/26 11pp
- 8010030404 Forwards comments on NUREQ-0496, "Functional Criteria for Emergency Response Facilities " Util supports & agrees w/basic objectives re improvements in emergency response facilities EDMARDS, D W Vantee Atomic Electric Co 45FR54708 015 80/09/30
- 8010030419 Comments on NUREC-0696, "Functional Criteria for Emergency Response Facilities" Procurement of computer sys w/unavailability of 005 is extremely difficult especially if long-term inservice availability demonstration required GETTLER.F. H. Gibbs & Hill. Inc. (subs. of Dravo Corp.) 80/09/29
- 8010030447 Comments on draft NUREQ/CR+1380. "Human Engineering Quide to Control Room Evaluation " Applicability of guide to existing rooms is questioned Audit should involve util technical mgt in review NICHOLBON,P J Massachusetts Institute of Technology 80/09/30
- 8010030462 Comments on NUREO-0692 re radiation exposure associated w/repair of steam generators at Surry Unit 1 Doses in unrestricted areas will not necessarily remain below normal operating levels (HONO, L. R. Affiliation Unknown 80/09/29 2pp
- 8010030464 Forwards evaluation of proposed mod to HPCI & reactor core isolation cooling sys on behalf of BMR owners group per NUREO-0660 Recommends no change in HPCI setpoints BUCHHOLZ/R H General Electric Co MFN-169-80 80/10/01. 5pp
- B010060014 Comments on draft NUREG-0613, "Residual Radioactivity Limits for Decomissioning " LARBON, H.J. Atomic Industrial Forum, 80/09/15 3pp.

8010060020 Comments on NURSO-0630, "Cladding Swelling & Rupture Models for LDCA Analysis" Adjustment to local blockage could be eliminated & available test data could be used to determine degree of conservation
RETTENHOUSE, P Affiliation Unknown 79/12/20

8010060025 Comments on NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis " Large bundle may not produce smaller coplaner blockage that rept expects Temp scale should be extended to approx 1260 C HOBSON, D D Oak Ridge National Laboratory 1210-25-79 79/12/10

8010040177 Transcript of 800919 public meeting in Washington.DC reproposed amend to 100FR50 concerning ATHS Pp 1-81
* Commissioners 80/09/19 84pp

8010060216 Submits info identifying contents & schedule of BHR owners group submittal addressing NUREO-0660.II K 3 13 requirement for mod of reactor core isolation cooling initiation logic to restart reactor cooling on low water level BUCHHOLZ,R H General Electric Co BUCHHOLZ,R H General Electric Gperating Plant Owners Group MFN 167-80 80/09/29 2pp

8010070281 Informs of distribution of NUREG-0525. "Rept of Siting Policy Task Force" No comments received RICHARDSON, J. R. South Dakota. State of EIS-020181 80/09/29

8010070REB Comments on draft NUREG/CR-1580 re human engineering guide to control room evaluation Supports improving info provided to control room operators by upgrading control board displays where appropriate EDMARDS, D w yanker Atomic Electric Co MYC 60-30 80/10/02 ip

8010070302 Forwards comments on draft rept NUREC/CR-1560 "Human Engineering Quide to Control Room Evaluation " Rept unduly slanted toward aerospace & military practices not widely used in util industry QETTLER,F N Qibbs & Hill, Inc (subs of Dravo Corp) 80/09/29

B010070332 Comments on NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Supports development of advanced data sys to aid operator & facilitate accident recovery More deliberate cost-effective approach suggested MILLS-L M Tennessee Valley Authority 80/09/30 App

8010070448 Forwards preliminary comments on draft NURE9/CR-1580 VOYLES: J. L. Institute of Nuclear Power Operations 80/10/01 80/10/01

--8010070490 Forwards preliminary consents on draft NUREQ/CR-1580, "Human Engineering Quide to Control Roam Evaluation"
PACK: R W Institute of Nuclear Power Operations 80/09/26 11pp

8010070610 NUREC-0452 R3
Revision 3, "STS for Westinghouse PURs " Supersedes Revision 2 Division of Licensing 80/09/30 500pp Available at NTIS

B01008018A NUREQ/CR-1505 JIOOGOBEA NUMEU/CK-1505 "Advanced Reactor Safety Research Division," quarterly progress rept for Jan - March 1980 KQUTG.H J C. KATO.H Y Brookhaven National Laboratory DKL-NUREO-51217 80/04/30 138pp Available at NT18 FIN A-3015

8010080199 NUREQ/CR-1438 "Steam Line Dynamics Computer Program." topical rept WULFF, W Broothaven National Laboratory FIN A-3014. BNL-NUREG-51186 80/04/30 89pp

8010080203 NUREG/08-1166 "COPS Model Estimates of Local Law Enforcement Agency (LLEA) Availability Near Selected Reactor Site " BERKBIGLER.K P 8andia Laboratories FIN A-1173 SAND79-826; 80/07/31 30pp Available at GPU \$3 00

9010080282 NUREO/CR-0055 V2 "Verification of Subsurface Conditions at Selected Rock Accelerograph Stations in CA," Vol 2 * Shannon & Wilson.Inc * Agbabian Associates FIN 8-3015 80/09/30 263pp Available at NTIS

-8010080287 NUREC/CR-0055 V2 APP --8010080290 NUREG/CR-0055 V3 DIOOBO270 NUREG/CR-OOSS V3

"Verification of Subsurface Conditions at Selected Rock
Accelerograph Stations in CA," Vol 3

* Shannon & Hilson.Inc * Agbabian Associates FIN B-3015
BO/09/30 24ipp Available at NTIS

B010090343 NUREG/CR-163B 10080343 NUMECFORM-1638 "Evaluation of In Situ Soil Damping Characteristics " * Bhannon & Wilson, Inc. * Agbabian Associates FIN B-3015 NRC-04-74-200 80/09/30 (80pp Available at 0PO \$5.50 NRC-04-76-200

B010080367 NUREQ-0684 "Summary of Public Comments & NRC Analysis Re Rulemaking on Emergency Planning for Nuclear Power Plants " * Office of Standards Development, Director 80/09/30 100pp Available at NTS \$4.00

8010090372 NUREQ/CR-1071 "Critical Experiments W/Interstitially-Hoderated Arrays of Low-Enriched U Oxide," topical rept on ref critical experiments
ROTHER E , OH, I , OUEBEL, C R Rockwell International Corp F
A-1036 RFP-3008 80/09/30 120pp Available at GPO \$4.25

8010090378 NUREG/CR-1575)10090378 NUREO/CR-1575
"Hydrogen Mixing in Closed Containment Compartment Based on Dne-Dimensional Kodel W/Convective Effects "WILLCUTT, 0 J. 01DD, R O. KOESTEL, A Los Alamos Scientific Laboratory FIN A-7112 LA-8429-MS 80/09/30 3ipp Av. NTIS \$2 00 Available at

86100803B1 NUREG/CR-1468 DIOUSUSSI NUREO/CR-1668
"Advanced Mobile Multi-Processor Gamma-Ray Acquisition &
Analysis Sys "
KILLIAI,E W. MURNEAU,R A EG&O Idaho, Inc. 80/09/30 115pp
Available at NIIS \$4 25

8010080384 NUREG/CR-1649 "Geophysical Investigations of Anna. (IH Earthquake Zone, "
annual progress rept for Jul 1979-Jun 1980
MAUK, F. J. HENRY, B. CHRISTENSEN, D. Michigan, Univ of FN
NRC-04-76-192 80/09/30 265pp Available at 9P0 \$6 90 FIN 8-5545

8010080389 NUREO/CR-1648
"Probabilistic Evaluation of Earthquake Detection & Location Capability for IL, IN, KY, OH & MV"
MAUK, F J . CHRISTENSEN, D Michigan, Univ of FIN 0-545
NRC-04-76-192 80/09/30 215pp Available at 6P0 \$6.00

B010080427 Forwards comments on NUREG-0676. "Functional Criteria for Emergancy Response Facilities " Util resolution of problems integrating comprehensive response capability into organizational structure led to highly effective criteria CROUSE,R P Toledo Edison Co 45FR54708 007 80/09/29 39pp

8010080475 NUREO/CR-1610 VI NO1 "Insp Methods for Physical Protection Project, Quarterly Rept. Mar-May 1780" BOHDEN. D . BRADLEY, R T . OLSON, A N. Lawrence Livermore Laborat FIN A-0143 UCID-18123-80-1 80/08/31 22pp Available at NT Available at NYIS

80:00805i1 Forwards comments on human angineering guide to control room evacuation BOWEN.H M Mau Mauro Associates (C C Mauro Associates, Inc.) 80/09/29

8010080545 Comments on 800905 ltr re-preliminary clarification of TM1 action plan requirements Issues involving degraded core cooling & hydrogen control must be resolved & implemented before new GLs issued Meeting not accessible to public MINDR.0 C MHB Technical Associates 80/09/30 3pp

8010030575 NUREC-0386-01 S2 Suppl 2 to "US NRC Staff Practice & Procedure Digest." Digest 2

* Office of the Executive Legal Director. 80/09/30 15pp
Available at NTIS \$1 75

8010080571 NUREQ/CR-1445 010090571 NUREO/CR-1445
"Preparation of Working Ref Matls Calcined Waste Recovery
"Products Containing U or Pu"
REIN, J E . WATERBURY, O R Los Alamos Scientific Laboratory FIN
A-70050 LA-8348 60/08/31 16pp Available at NTI8

8010070008 NUREQ/CR-1308 V2 Fired Site Neutralization Programmer's Manual," Vol 2, listings ENGI.D., CHAPMAN.L D Sandia Laboratories JUDNICK.W Vec Research.Inc : FIN A-1060 SAND79-2242 79/12/31 530pp 8010090010 NURE0/CR-1548
"NDT-CDMP9 Microcomputer"
BDDD,C V , COWAN,R F Oak Ridge National Laboratory FIN B-0417
DRNL/NURE0/TM-3 B0/09/30 i14pp

B010090022 NUREO/CP-0014 Vi Vol. 1. "Proceedings of ANB/ASME/NRC Intl Topical Meeting on Nuclear Reactor Thermal-Hydraulics " RIPPLER General Electric Co QAY, Rensselaer Polytechnic Inst B0/10/31 350pp Available at NTIS \$12 00

--8010090026 NUREO/CP-0014 V2
Vol 2, "Proceedings of ANS/ASME/NRC Intl Topical Meeting on Nuclear Reactor Thermal-Hydraulics"
RIPPLE, R General Electric Co 04Y, R Rensselaer Polytechnic Inst 80/10/31 350pp Available at NTIS \$11 00

--8010070029 NUREO/CP-0014 V3
Vol 3, "Proceedings of ANS/ASME/NRC Intl Topical Meeting on Nuclear Reactor Thermal-Hydraulics"
RIPPLE, R Oeneral Electric Co OAY, R Rensselaer Palytechnic Inst 80/10/31 350pp Available at NTIS \$12 00

8010090160 Requests extension of time for official & public comments on NUREO-0683 NUELLER: H L Women's International League for Peace & Freedom 80/09/15 ip

B010090397 Forwards comments on NRC 800905 preliminary clarification of TMI action plan requirements Licensee actions based on draft documents should be avoided Required submittals should be staggered over period of time.

EDMARDB, D. W. Yankee Atomic Electric Co. WYC 80-31 80/10/07 4pp

--B010090399 Informs that NRC models & rag guides do not correctly describe behavior of iodine during nuclear reactor accidents Risk to general public is lower than estimated Adequate bass of technology is needed for major revision. GTRATTON WR Los Alamos Scientific Laboratory MALIMAUSKAB.A . CAMPSELL.D O. Dak Ridge National Laboratory 80/08/14 4pp

8010100098 Forwards comments on draft NUREO-0430, "Cladding Swelling & Rupture Models for LOCA Analysis " Requests response to concerns re-proper application of research results in arriving at technically justificable models LOEMEN8TEIN, W Electric Power Research Instityte BO/01/09 3pp

8010100194 Comments on proposed revision to SRP 3 9 6, "Inservice Testing of Pumps & Valves " SRP is apparently being misused as tool for imposing new & more severe requirements GETTLER, F W Oibbs & Hill, Inc. (subs. of Dravo Corp.) 80/07/04 2pp.

B010100200 Forwards comments on NUREG-0430, "Cladding Swelling & Rupture Models for LGCA Analysis " Current course of action for MRBT program will be reoriented to address concerns that began to emerge w/TMI-Z accident C

8010140544 NUREO/CR-1635
"Nuclear Plant Reliability Data Sys,1979 Annual Repts of Cumulative Sys & Component Reliability " Southwest Research Institute NRC-10-80-400 80/09/30 652pp Available at NTIS \$10.00

8010140609 NUREO/CR-1590
"Evaluation Methodology for Fixed Site Physical Protection Sys."
BENNETT,H.A., DLASCDA9A.M T Sandia Laboratories FIN A-1153 SAN980-0505, 80/09/30 28pp Available at NTIS \$1.75

BO10150183 NUREO/CR-1661

"Variability of Dynamic Characteristics of Nuclear Power
Plant Structures, Beismic Safety Margins Research Program
(SBMRP)

WEBLEY, D. A., HABHIMOTA, P. S., NARVER, R. S. Lawrence Livermore
Laboratory, FIN A-0130 UCRL-15267 BO/09/30 76pp

BOIO150171 NUREO/CR-1656
"Util Mgt & Technical Resources," executive summary,Parts I,
II & III.
PODDNSKY,O , SPEAKER,D , COHEN,B Teknekron Research,Inc FIN
B-6824, BO/09/30, 404pp, Available at NTIS, \$8 00

B010150174 NUREO/CR-1637
"Bite Dependent Effects at Strong Motion Accelerograph Stations."

* Bhannon & Hilson, Inc. * Agbabian Associates FIN B~3015 80/09/30. 155pp. Available at NTIS. \$5 00

8010160519 Forwards proprietary & nonproprietary versions of "Analytical Investigation of Detailed Behavior of Fluid in Steam Generator Tubes Under Two-Phase Natural Circulation Conditions "Application for withholding & affidavit encl JURGENSEN,R W. Westinghouse Operating Plants Owners Group OG-43 80/10/13 11pp

--8010160526 WCAP-9721

Nonproprietary version of "Analytical Investigation of Detailed Behavior of Fluid in Steam Generator Tubes Under Two-Phase Natural Circulation Conditions" ANDERED, T M., KELLY, R.D. Westinghouse Electric Corp. 80/07/31 95pc

8010160585 Comments on proposed rule 10CFR50, "Functional Criteria for Emergency Response Facilities " Delays in requiring implementation seem unnecessary & hazardous TILBERG/K Friends of the Earth 45FR54708 001 80/09/16 lp

8010170001 NUREG-0731 DRFT
"Ouidelines for Util Mgt Structure & Technical Resources."

#For fire of Muclear Resources."

ALLENSPACH.F R . CRICKER. L P Office of Nuclear Reactor Regulation,

Director 80/09/30 34pp

8010176003 NUREO/CR-1581 V3
"Evaluation of Mathematical Models for Characterizing Flume
Behavior from Cooling Towers "
DUNN.W E , CAYIN.P M Illinois, Univ of, Urbana-Champaign.
COUPER.O K Miesissippi. Univ of, 80/09/30 16pp Available at
NT18 \$1.75.

8010170020 NUREG-0525 R2
"Bafaguards Summary Event List (SBEL)," Revision 2
DAVIDSDN:J J. MACHURDY,P H Physical Security Development Branch
80/09/30 156pp Available at NTIS \$5 50

B010170023 NUREO/CR-1334

"Validation of Monte Carlo Code for Radiation Streaming
Analyses"

DEGANGIAN, COHEN.M O., WALUSCHKA, E. Mathematical Applications, Inc.
MR-7063 80/07/30 88pp Available at NTIS \$3.75.

80i0170070 NUREO-0430 VI NOS
Orey book "Licensed Fuel Facility Status Rept." status
summary rept for Jul SO
Office of Inspection & Enforcement, Office of the Director
80/07/31 62pp. Available at NTES

8010170074 NUREC/CR-1192
"Mat1 Accounting as Required by US NRC Capabilities & Vunerabilities "
LIM.J. HUEBELJ G Laurence Livermore Laboratory UCRL-52734
80/09/30 400pp. Available at NTIS \$7.00.

BO10170078 NUREO/CR-1581 V2

"Evaluation of Mathematical Models for Characterizing Plume
Behavior from Cooling Towers Vol 2.Salt Drift Deposition
from Natural Drift Cooling Towers "
POLICABTRO, A J. BREIO, M L Argonne National Laboratory DUNN, W E
111inois, Univ of, Urbena-Champaign FIN A-2032 80/09/30 400pp.
Available at GPO \$8.50

8010170140 Forwards three consultant repts prepared in support of NUREO-0703, "Potential Threat to Licensed Nuclear Activities from Insiders." ERICKSON, R A Physical Security Development Branch 80/09/17 2pp

--80i0170147 "Analysis of Insider-Related Threats " BEQUALA Bequail.A 79/10/31 9pp.

--8010170138 "Survey of Insider Threat to Nuclear Industry " BRITTELL.F L Brittel.F C 79/09/30 10pp

---8010170163 "Insider Threat Survey of Analagous Privata Industries " SUTTON-R.H Sutton-R H 79/11/30. 15pp

8010170154 NUREO-0706 VI Qeneric FES on U milling,Project M-25,summary & text # Office of Nuclear Material Safety & Safeguards. 80/09/30 400pp. Available at NTIS #10 00

- BO10:70195 NUREO-0704 V2
 Oeneric FEB on V milling, Project H-25, Apps A-F
 * Office of Nuclear Material Bafety & Bafeguards
 Available at NTIS \$6.50 80/09/30 200pp
- 8010170161 NUREO-0706 V3

 Qeneric FES on U milling, Project M-25, Apps G-V

 * Diffice of Nuclear Material Safety & Safeguards
 Available at NTIS \$7 00 80/09/30 20000
- 8010170277 NUREO/CR-1607 "Canadian Seismic Agreement," annual rept.June 1979-June AVMAN.R B , WETMILLER,R J Canada FIN 8-6275 80/09/30 Available at NTIB \$2 25 43pp
- 8010200413 Forwards comments on NUREG/CR~1580.Vols I & II, "Human Engineering Ouide to Control Room Evaluation " BERNSENS A Bachtel Power Corp (subs of Bechtel Corp) 80/10/13 2pp
- 8010200414 Forwards comments re NUREO/CR-1580, "Human Engineering Ouide to Control Room Evaluation," submitted on behalf of PA Electric Co & Met Ed Rept does not emphasize importance of assessment of operatur needs
 TIPTON, TE General Public Utilities OPU Service Corp E&L-2882 80/10/13 Spp
- 8010200433 Forwards comments re NUREG-0696. "Functional Criteria for Emergency Planning Facilities" JENCKEB,T A Pacific Gas & Electric Co 80/10/02 1p
- --8010200435 Comments on NUREO-0696 Potentially great impact of criteria necessitates careful review of all comments to arrive at reasonable & balanced regulatory position Proposed criteria do not allow flexibility for site specific factors SCHUYLER, J. D Pacific Oas & Electric Co 80/09/26 9pp
- 8010200505 Submits comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities " NUREO-0696 specifies technical requirements rather than functional criteria for amergency response facilities ASH.R F Baltimore Oas & Electric Co 45FR54708 032 80/10/15
- 8010210660 Forwards comments on draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" All requirements resetants or environ qualification should be deleted to permit designer fleribility of readity employing available sys.
 ANDERSON.T. M Hestinghouse Electric Corp. 45FR34708 002 80/09/19
- B010210706 Comments on draft NUREO-0696; "Functional Criteria for Emergency Response Facilities " Intermediate activities of proposed schedule should be deleted due to conflict w/ activities scheduled to meet overall implementation dates JACOBSIS B Stone & Hebster Engineering Corp 45F654708 004 . Врр
- 8010210713 Forwards comments on draft NUREG-0696, "Functional Griteria for Emergency Response Facilities" Interim requirements that are subj to early review & revision should not be included in final document LEPPRE, D. N. SEELEY. O T. Floor Power Service: Inc. 45FR54708 003 80/09/26 3pp
- B010210721 Forwards comments on NUREO-0696. "Functional Criteria for Emergency Response Facilities " Util mgt should make determination if implementation of emergency response ctrs requires single or multiple distributed processing sys MATHEWS.E R Wisconsin Public Service Corp 45FR54708 005. 80/09/26 4 р р
- B010210728 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities," Schedule date for implementation of SPDS portion of integrated sys should be extended Until Apr 1982 UNROENBEN,R,W American Electric Power Co , Inc 45FR54708 016 80/09/29 26pp
- 8010210740 Forwards comments on NUREO-0694. "Functional Criteria for Emergency Response Facilities" Any ref to Reg Ouide 1.97 should be made more specific by referring to applicable sections of particular revisions.w/date of issuance OUDDHIN.C Portland General Electric Co 43FR54708 008 80/09/26
- 8010210745 Forwards comments on NUREG-0696, "Functional Criteria for Edergency Response Facilities" Published criteria are overly prescriptive & in some cases; unreasonable & unjustifiable in light of function of facilities PARKER, W.O. Duke Power Co. 45FR54708 019 80/09/30 9pp

- 8010210750 Forwards comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities" NRC authority, responsibility & accountability for all aspects of accident should be
 - LOOMIS, J 8 Sargent & Lundy, Inc 45FR54708 014 80/09/29 3pp
- 8010210756 Forwards comments on NUREG-0676, "Functional Criteria for Emergency Response Facilities" All prohibitions against use of existing station process computers should be replaced w/set of functional requirements LODMIS, J B Sargent & Lundy, Inc 45FR54708 027 80/10/07 App
- 8010210761 Forwards comments on NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Also endorses comments submitted by KMC. Inc in 800929 1tr JONES.W C Omaha Public Power District 45FR54708 028 80/09/30
- 8010210764 Forwards comments on NUREC-0676, "Functional Criteria for Emergency Response Facilities "BAYKE, J Power Authority of the State of Neu York 45FR54708 031 80/10/10 5pp
- 8010220065 Comments on NUREG-0590, Revision 2 re decommissioning Terminology re capital recovery methods should be clarified NUREO/CR-1481 provides NRC w/basis for promulgating regulations to ensure adequate financial assurance FEROUSDN.J S MWS Consultants. Inc., Middle West Service Co Div 80/09/29 6pp
- B010220112 Comments on NUREO-0694, "Functional Criteria for Emergency Response Facilities " Undue hardship is placed on util licensee or applicant who is espected to expend sizeable resources to implement mode prior to final form DELGEORGE, L O Commonwealth Edison Co '45FR54708 012 80/09/26 1000
- 8010220118 Comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities" Each design should be evaluated on individual basis Proposed criteria do not allow enough flexibility for site-specific factors
 8CHVYLER, J O , HOCK, B Pacific Gas & Electric Co 45FR54708 017 80/09/26 9pp
- 8010220123 Comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities," on behalf of Coordinating Group on Emergency Preparedness Implementation Show cause approach to regulation is unconscionable & should be overturned SUYO,R 8 Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 45FR34708 006 80/07/29 Spp
- 8010220130 Comments on NUREO-0496. "Functional Criteria for Emergency Response Facilities " Strongly endorses NRC integrated approach re facilities designed to facilitate mitigation of abnormal events COUNBIL.W.G Connecticut Yankee Atomic Power Co COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 45FR5470B 018 80/09/27 6pp
- 8010220140 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities" Also strongly endorses comments submitted by KMC Coordinating Oroup on Emergency Preparedness Implementation 1 Yankse Atomic Electric Co EVANS.8 D Maine Yankse Atomic Power Co 45FR94708 030 80/09/30
- 8010220147 Comments on NUREO-0696. "Functional Criteria for Emergency Response Facilities " Emphasis should be placed on monitoring data Refs to control of plant operations, implied or explicit. should be eliminated DRAPER.E L. Oul? States Utilities Co. 48FR54708 029. 80/09/29
- 8010220154 Forwards comments on NUREG-0454, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants "
 DAIL.L C Duke Power Co 44FR75167 205 80/09/25 3pp
- 8010220160 Informs of inability to attend 800928-30 Joint Power Generation Committee dialogue on NUREO-DA96 Requests copies of position papers
 RAMOS, S.L. Emergency Preparedness Development Branch 80/07/23
- 8010220197 Comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities," Comments restricted to items affecting design & const & not on operational considerations of failure reporting & Limiting conditions
 CANNYA L. Bechtel Power Corp (subs of Bechtel Corp) 45FR54708 80/09/29

8010220204 Forwards comments on draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" NRC should fully consider comments prior to final publication since only i day is scheduled between comment expiration & final form HOMELL, S H Atomic Industrial Forum 45FR54708 010 80/09/29 788

8010220209 Forwards comments on draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Fully endorses AIF ZARAKAS,P Consolidated Edison Co of New York 45FR54708 013 80/097/26 4pp

B010220233 Bubmits comments on NUREG-0630 Observed coplanar flow restriction is not heater design artifact It may be effect of steam flow & grid spacers VAN HOUYEN,R Affiliation Unknown 80/02/21 1p

8010230001 NUREG-0020 V4 N09
Grey book "NRC Operating Units Status Rept," data as of 800831

Office of Standards Development, Director 80/09/30 100pp Available at OPU

B010230003 NUREG/CR-1405
"NACOM Code for Analysis of Postulated Bodium Spray Fires in LHFGRs "
TSAI.8 S Brookhayen National Laboratory FIN A-3000
BNL-NUREG-51180 B0/03/31 SSpp Available at NTIB

8010230006 NUREO-0721
"Acceptable Criteria for Physical Protection Upgrade Rule
Requirements for Fixed Sites "
DHYER.P Regulatory Improvements Branch 80/09/30 78pp

8010230007 NUREO/CR-1691 "LNR Safety Research Program Quarterly Progress Rept," Jan-Har 1980 MASSEY,W E , KYGER, J. A Argonne National Laboratory FIN A-2016 ANL-80-86 80/08/31 23pp Available at GPO

B010230009 NUREO/CR-1640
"Experiment Data Rept for Semiscale Mod-3 Small Break Test
Series (Test B-88-P1,8-88-P2 & S-88-P7)"
WEIDERTIL L., CLEGO, L. B. E020 Idaho, Inc. FIN A-6038 'E0G-2053
80/09/30 60pp Available at 0P0

B010230012 NURE0/CR-0985 V5
"Geotechnical & Strong Motion Earthquake Data from US
Accelerograph Stations Fairbanks, AL. Petrolla, CA. Hollister,
CA. Los Angeles, CA & New Madrid, MG. " Vol 5
Shannon & Wilson, Inc. * Agbabian Associates, FIN B-3015
BRC-04-76-200. B0/09/30 400pp. Available at OPO \$11 00

8010230013 NUREO/CR-1474

"Algorithm to Estimate Field Concentrations Under
Nonsteady Mateorological Conditions From Wind Tunnel
Experiments "
BOUNNEESTER.R., KOTHARI,K M, MERONEY,R N Colorado State Univ FIN
B-5829, NRC-04-76-236 80/09/30 92pp Available at GPO

8010230014 NUREO/CR-1671
"Transportation of Radioactive Matl in KY Oct 1978-Dec 1979

Kentucky, State of NRC-06-78-359 80/09/30 53pp Available

B010230015 NUREO/CR-1665

"Equipment Response at E1 Centro Steam Plant During 791015
Imperial Valley Earthquake "
HURRAY.R C., NELSON,T A Lawrence Livermore Laboratory YOUNG.J A
E080, Inc FIN A-0225 UGRL-53005 80/10/31 163pp Available at
GPO.

8010230019 NUREO/CR-1394
"Diffusion Near Bldgs as Determined From Atmospheric Tracer
Experiments"

BAGENDERF, J F Commerce, Dept of National Geanographic & Atmospheric
Adminstration FIN B-5690. ERL ARL-84 80/09/30. 30pp. Available
at OPC

8010230023 NUREO/CR-1340
"Lumped Parameter Models for Transient Conduction in Nuclear Reactor Components"
NULFF, W Brookhaven National Laboratory FIN A-3014
BML-NUREG-51231 80/06/30 42pp Available at QPD

8010230026 NUREO/CR-1615
"Flashing Incaption in Flowing Liquids."
JONES: O C Brookhaven National Laboratory FIN A-3045.
BNL-NUREO-51221. B0/04/30. Sopp. Available at GPD

8010230028 NURED/CR-1506
"Water Reactor Research Div Quarterly Progress Rept, Jan-Mar 1980"
KOUTS.H J C , KATO, W Y , ABUAF, N Brookhaven National Laboratory FIN A-3014 BNL-NUREG-51218 80/06/30 69pp Available at 6P0

8010230034 NUREO/CR-1643
"Geotachnical Data From Accelerograph Stations Investigated During 1975-79," summary rept
* Bhannon & Wilson,Inc * Agbabian Associates FIN B-3015 NRC-04-76-200 80/09/30 157pp Available at OPO \$7

8010230036 NUREO/CR-1475
"Wind Tunnel Measurements of Dispersion & Turbulence in Wakes of Nuclear Reactor Plants," final rept, Jan 1975-Dec 1979.
MERONEY, R N. PETERKA, J A. KOTHARI, K M. Colorado State Univ. FIN B-5829 NRC-04-76-200 80/09/30 53pp Available at GPO

BO1023003B NUREO/CR-0961
"Qualification Test Results on 1550 C & 2200 C 1/16-Inch
Outside Diameter Fuel Centerline Thermocouples for LOFT
Program "
CANNON.C F , CHAN.A I Y Hanford Engineering Development Laboratory
FIN 8-6228 HEDL-TME 79-50 BO/09/30 50pp. Available at GPD

B010230039 NUREO/CR-1676 V1
"Using Advanced Process Monitoring to Improve Matl Control,"
final rept.Sept 1979-Bept 1980
HAWKINSR L . LYNCH.R L . LUMB.R F
NRC-02-79-043-2 80/09/30 100pp Available at 0P0 \$4.00

8010230042 NUREO/CR-1632
"Hydradynamics of Vapor Jet in Bubcobled Liquid."
CATTON.I. CHAN, C K. DHIR, V K. California, Univ. of, Los Angeles.
FIN 8-5875 80/09/30 106pp Available at QFO \$4.25

B010230046 NUREG/CR-0985 V3
"Geotechnical & Strong Motion Earthquake Data from US
Accelerograph Stations Gilroy, CA. Logan, UT, Boreman, MT. Tacoma,
NA & Helena, MT. " Vol 3
* Shannon & Wilson, Inc. * Agbabian Associates FIN 8-3015
80/09/30 295pp Available at OPD #12 00

801023004B NUREO/CR-0985 V4
"Geotechnical & Strong Motion Earthquake Data from US
Accelergraph Stations Anchorage, AK, Beattle, WA, Olympia, WA &
Portland, OR," Vol 4
* Shannon & Wilson, Inc # Agbabian Associates. FIN 8-3015
80/09/30 256pp Available at GPO 412 00

B010230475 NUREO/CR-1576

"Review of Fatigue Crack Growth of Pressure Vessel & Piping Steels in High-Temp Pressurized.Reactor-Orade Hater."

CULLEN Navy.Dept of, Naval Research Laboratory TORRONEN.K Finland 4298 B0/09/19 126pp

B01023051i Comments on NUREO-0696 re functional criteria for emergency response facilities Concurs w/AIF subcommittee comments BALDARINI, C Essaco Bervices Inc. (subs of Enserch Corp.). 45FR5470B 025 80/10/03 4pp

B010230519 Comments on NUREG-0696 re functional criteria for emergency response facilities
SULLIVAN.T J Consumers Pawer Co 45FR5470B 024 B0/10/02 Sep

B010230596 Comments on proposed rules 160FR50.51 & 100 re proposed revision of nuclear plant siting criteria Supports revision R088.D K Affiliation Unknown 45FR50350 051 B0/07/29 14pp

B010240043 NUREO/CR-1620
"Survey of Current State Radiological Emergency Response
Capabilities for Transportation Related Incidents "
HITTER,E L. HUMER D. VILLARDD.F J Indiana Univ FIN 8-1070-8
B0/09/30 200pp Available at GPD

8010240048 NUREO-0103 R4
"STS. Revision 4 for BbW PWRs " Supersedes Revision 3.
" Office of Nuclear Reactor Regulation, Director 80/09/24 600pp Available at OPO

B01024019B Forwards comments on NUREG-0676, "Functional Griteria for Emergency Response Facilities " VAN BRUNT, E. E., Aritona Public Service Co. 45FR54708 020 80/09/24 2pp.

- 8010240340 NUREO/CR-1552
 "Development & Verification of Fire Tests for Cable Sys & Sys Components:" Quarterly Rept 12, Mar-May 1980
 PRZYBYLAL J, CHRISTIAN, W. J. Underwriters Laboratory FIN 8-6197
 UL-USNC-75 Q 80/09/30 29pp Available at GPO 62 00
- 8010240355 Forwards comments on NUREG-0676 re functional criteria for ambreacy response facilities
 TIPTON T E General Public Utilities OPU Service Corp 45FR54708
 022 80/10/01 6pp.
- 8010240550 Comments on proposed rules 10CFR50,51 & 100:agrees w/ ultimate objectives of siting policy task force. BHIELDS,8 H. Public Service Co of Indiana, Inc. 45FR50350 057 80/09/29, 9pp
- 8010270144 Forwards example guidance re reassessment of secondary review responsibility assignments for SRP revisions 80HR0E0ER, F Assistant Director for Generic Projects, 80/10/10
- 8010270164 Comments on NUREG-0696 re functional criteria for emergency response facilities Legal basis for document are not obvious Objective criteria needs to be clarified.
 UHRIO,R E Florida Power & Light Co 45FR54708 023, 80/09/29 388
- 8010270393 Forwards comments on draft NUREO-0696, "Functional Criteria for Emergancy Response Facilities" Document is substantial & unilateral escalation of all criteria & requirements previously set forth by NRC.
 RENBERGER.D. L. Washington Public Power Supply System.
 ELE-KAM-50-037, 80/10/17. 10pp
- 8010270548 Forwards NUREO-0728:-0729 & -0730 re actions taken or being taken to improve NRC response to nuclear plant incidents or emergencies Submittal satisfies requirements in P.L. 90-295 H/o enci AHEARNE, J. F. Commissioners 80/10/03. 4pp
- --B010270557 Forwards NUREO-0728.-0729 & -0730 re actions taken or being taken to improve NRC response to nuclear plant incidents or emergencies Bubmittal sabisfies requirements in P L 90-295.
 AHEARNE.JF Commissioners B0/10/03. 4pp.
- --9010270564 NUREQ-0728

 "Rept to Congress:NRC Incident Response Plan," Oversize charts enci

 * Office of Inspection & Enforcement: Office of the Director 80/09/30, 27pp
- --B010270366 NUREO-0729
 "Rept to Congress on NRC Emergency Communications "
 d Office of Inspection & Enforcement Office of the Director
 B0/09/30 Jopp
- --8010270570 NUREQ-0730
 "Rept to Congress on Acquisition of Reactor Data for NRC Operations Ctr " # Office of Inspection & Enforcement, Office of the Director, 80/09/30 26pp.
- 8010280342 Forwards draft "Benior Reactor Operator Level Instructor Certification Quide." Review & discussion requested. Quideline based on NUREO-0094. ELLIOTT, N. S. Babcock & Wilcox Co. 80/09/11, 1p.
- --8010280365 Draft "Senior Reactor Operator Level Instructor Certification Guide " + Bebook & Wilcax Co. 80/09/11, 14pp.
- 8010280587 Informs that implementation of NUREQ-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports: " has been delayed pending resolution of EPRI Fracture mechanics proposal. BCHERERIA E C-E Power Systems LD-80-055 80/10/24. 2pp
- .8010290171 NUREQ/CR-1831
 "PHR FLECHT SEASET 161-Rod Bundle Flow Blockage Task," task
 plan rept.
 HOCKRETTER.L.E., LEE.N. HCQUIRE.M F.
 NRG-04-77-127. HCAP-9492 80/09/30. 200pp.
- 8010290174 NUREO/CR-1433
 "Examination of Use of Potassium Iodide (KI) as Emergency
 Protective Measure for Nuclear Reactor Accidents "
 ALDRICH.D.C Bandia Laboratories. BLOND, R.M Probabilistic
 Analysis Branch (Pre 791030). FIN A-1042 BANDBO-0981. B0/03/31.
 69pp. Available at OPD.

- 8010290310 NUREO-0518
 DES re proposed rulemaking exemption from licensing requirements for smalted alloys containing residual TC-99 & low enriched U

 # Office of Standards Development, Director 80/10/31 150pp
- B0103004B5 Responds to B01010 request for review of revision to past—TMI requirements clarification itr R Baer B01009 recommendations re Tasks II K 2 13 & 11 K 3 25 should be implemented BCHRGEDER.F Division of Safety Technology B0/10/14 1p
- --B010300490 Recommends that TMI action plan, Task II K 2 13 be imposed on PWR licensees unless licensee proposes method other than feed & bleed to remove decay heat for postulated scenario Task II K 3 25 should be eliminated BAER.R Sefety Program Evaluation Branch B0/10/09 2pp
- B010300499 NUREO/CR-1624
 "Load Combination Program." Progress Rept 5
 CHOU.C.X., LU.S C., BCHWARTZ,M W Lawrence Livermore Laboratory.
 UCID-18674 80/09/30. A3pp
- 8010300537 NUREO/CR-1457
 "Regional Relationships Among Earthquake Magnitude Scales Seismic Safety Margins Research Program "
 CHUKO, D H., BERNREUTER, D L Lawrence Livermore Laboratory FIN A-0139, UCRL-52745 80/09/30 54pp
- 8010300543 NURES/CR-1278
 "Handbook of Human Reliability Analysis M/Emphasis on
 Nuclear Power Plant Applications," draft rept for interim
 use & comment.
 SMAIN.A D.: OUTTMANN.H E. Sandia Laboratories. FIN A-1188
 80/10/21.
- 8010310366 Forwards comments on draft NUREO-0700 & NUREO/CR-1580. NUREO/CR-1580 does not fulfill objectives in NUREO-0660 & other regulatory positions re control room design. Document may have little effect on plant safety improvements BUHL.A.R. Technology for Energy Corp 80/10/24 7pp.
- 8010310396 Forwards proprietary & nonproprietary versions of "C-E N868 Obners' Response to NURCO-0460, Vol 4 (Mar 1980)" Affidavit for withholding info (ref 10CFR2 790) encl LUNDVALL.A.E C-E Operating Plants Owners Group 80/10/28, 1pp
- --8010310399 CEN-134-NP
 Nonproprietary version of "C-E NSSS Owners' Response to NUREG-0460, Vol 4 (Mar 1980)."

 * C-E Power Systems 80/10/28 117pp
- 8010310588 NUREO/CR-1567
 "TRAP.Plotting Package for TRAC," informal rept.
 FEROUSON, J. C. Los Alamos Scientific Laboratory FIN A-7016
 LA-8427-MS, 80/08/31, 43pp. Available at NTI8
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8007070457 Submits requested info re scope & depth of independent 3-yr audits of fire protection programs. Recommends blend of walk-through surveys, audit of existing program, interviews & attention to identified problem areas. CPC outline encl COHN.B.M. Gage-Bebcock Associates, Inc. 7917 80/09/04 App.
- 8010010747 Forwards draft Faderal Radiological Response Plan w/comments on general radiological problems Review focused on application of plan to licensees however substitute language meant to apply to any radiological problem M/o encl.

 WEIRS.B.H. Executive Officer for Operations Support 80/09/18 ip.
- 8010080547 Forwards 1980 IE bulletins, circulars & info notices per IL Dept of Public Health request PAPPAS, H Region 3, Chicago, Office of the Director 80/09/23, 1p
- B010160773 Bubmits comments on ballot action re rules for const of reactor coolant pump motor frames when used as intervening elements in ABME support load paths Vote affirmative w/comment & E Brown B00404 comment should be resubmitted. BCHROEDER, F Division of Safety Technology 80/10/02. 2pp.
- 8010200642 Notifies that IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipments of Radioactive Matls," was sent to listed licensees on 800723 PAPPAS:H Region 3, Chicago, Office of the Director 80/08/24

NONDOCKETED ITEMS

- 8010270512 Notifies that IE Info Notice 80-34, "Boron Dilution of Resector Coolant During Steam Generator Decontamination," was sent to listed utils on 800925 PAPPAB,H Region 3, Chicago, Office of the Director 80/09/30.
- BO10280592 Informs of current status of ultrasonic testing development program supporting planned FFTF secondary weld insp Progress in development of plant equipment & in improving data collecting & analysis techniques has been good CARLISLE, C B Energy, Dept of 80/10/22 2pp
- BO10290331 Discusses NRC review of DOE research plan on LUR safety prepared by Bandia Natl Labs Forwards comments re status of NRC recommendations for DOE LUR safety programs & addl comments on DOE research plan for LUR safety technology, DENTON-H R Office of Nuclear Reactor Regulation, Director 80/10/08. 5pp
- 8010300122 Notifies that IE Circular 80-21, "Regulation of Refueling Creus," has been sent to listed licensees PAPPAS,H Region 3, Chicago, Office of the Director 80/09/15 ip
- 8010300505 Summary of Phase II DDE contract group 801008 meeting reremaining work in Phase II project Draft NRC Manual Chapter 1401 encl. 8CHAUB, L. J. Resources Planning & Evaluation Staff 80/10/07 Bpp.
- --B010300510 Forwards evaluation of Franklin Research Ctr performance under contract NRC-03-79-118 for May June 1980 re containment leakage rate testing SHAPAKER. J Office of the Executive Legal Director NRC-03-79-118 80/06/06 Sipp
- 8010300523 Notification of 801030 meeting w/GRNL in Bethesda, MD rebriefing on reactor noise & related work
 LDIS,L., Standardization & Special Projects Branch. 80/10/20. 2pp.

PR PROPOSED RULE

8009100225 8ECY-80-392
Requests Commission approval of final rulemaking deleting 10CFR20,304 re-burial of small quantities of radionuclides.
Value impact assessment & rept justification for deletion of 10CFR20 304 & proposed FR notice deleting 20 304 encl HINGOUE, R B Office of Standards Development, Director. 80/08/21.

BO09100243 BECY-B0-385
Recommends Commission approval of amends to 10CFR2 713 for publication in final form. Draft proposed FR notice, comparative text of recommended final rule & proposed rule & draft ltr for Congressional committees encl.

BHAPAR.H K Office of the Executive Legal Director. 80/08/15 2800

BOO9100759 BECY-80-236
Recommends issuance of final rule iOCFR72 re specific
licensing requirements for storage of spent fuels in
independent spent fuel storage installation Draft FR notice
encl.
MINGOUE, R.B. Office of Standards Development, Director. 80/05/09
BADD.

8009270471 SECY-80-415
Recommends proposed emends to 10CFR20 to permit disposal of liquid scintillation media animal carcasses containing tracer levels of certain radionuclides. Draft FR notice of proposed rulemaking encl.

DIRCKS, H. J. Dffice of Nuclear Material Safety & Safeguards.

MONDQUE.R. B. Office of Standards Development, Director. 80/09/09.

BO09300303 NUREO-Q485
"Environ Assessment for Effective Changes to IOCFR50 & App E to IOCFR50:Emergency Planning Requirements for Nuclear Power Plants."
OTT, W. R. Sit. & Environ Stds Br. (formerly Environ Prot. Stds. Br.), 80/08/21 58pp

8010010030 SECY-80-279A
Recommends approval to publish FR natice emending 10CFR25 in accommendation in SECY-80-279 Draft notice and DONOGHUE,D.J. Office of Administration. 80/09/05. 7pp

8010020024 Advises of availability of refs cited in DOE 800905 crossstatement re proposed rulemaking on radwasts storage & disposal, in NRC PDR. Related correspondence. BROWN, O. F. Energy, Dept. of. 80/09/26. ip.

- 8010020630 Ack receipt of IL Commission on Atomic Energy comments proposed rule 10CFR50 & 51. "Interim Policy Concerning Nuclear Plant Accident Considerations Under NEPA of 1969 "

 * Docketing & Bervices Branch 45FR40101 015 80/09/12 ig
- ---8010020544 Forwards corrections to comments by IL Commission on a Energy re "Interim Policy Concerning Nuclear Power Plant Accident Considerations Under NEPA of 1957 " NEPA reglaces Nata Emergency Protection Act HUDSON
- 8010020632 Comments on proposed rule 10CFR2 re-procedural assistant adjudicatory licensing proceedings NRC proposel violates intent of Congress Urges Commission to rescind action DEVORE.F W Ban Diego Cas & Electric Co 45FR49535 001 80/08.
- 8010060101 Comments on proposed rules 10CFR80.91 & 100 re considers of adoption of mods or add1 regulation concerning nuclear power plant siting BERNATHL Bouth Carolina Electric & Cas Co 45FR800350 019 80/09/12 10pp.
- 8010060116 Notifies that NJ Btate Clearinghouse has distributed proposed rules 10CFR50.51 & 100 on mod of policy & regulatory practice governing siting of nuclear power plants to appropriate state agencies for review & comment.

 OINMAN,R A. New Jersey, State of 45FR50350 002 80/08/06 14
- 8010060124 Comments on proposed rules 10CFR50.51 & 100 re mod of si policy Projection procedures should be standardised. OREENBERG.H K. Rutgers, New Jersey, State Univ of 45FR50350 000 80/08/22, ip
- 8010060127 Comments on proposed rules 10CFR50,51 & 100 re reactor siting policies. Every reactor site is unique & should be considered accordingly.

 KISTRUP, N.K. Affiliation Unknown 45FR50350 005. 80/08/22 2p
- 8010060136 Comments on proposed rules 10CFR50,51 & 100 re siting policies, present policy should be continued Site approval should not be independent of plant design PFAHLER,R. 0 Affiliation Unknown. 48FR50350 006. 80/08/23. 1p
- B010040144 Comments on proposed rules 10CFR50, 51 & 100 re siting policies Present policy of permitting plant specific design features to compensate for unfavorable site characteristics should be continued.

 ROWLEY, C. W. Affiliation Unknown. 45FR50350 007 80/08/25. 2pp
- 8010040130 Comments on proposed rules 10CFR50.81 & 100 re adding si criteria to licensing requirements TMI-2 accident & subsequent action within nuclear industry demonstrated safety of nuclear power GUAPP.H J Affiliation Unknown. 45FR50350 008 80/08/21 ip.
- B010060137 Comments on proposed rules 10CFR5D,51 & 100 re use of reactor sits isolation & engineered safeguards to improve safety Changes in proposed siting regulations unnecessary SLGTH,E.N. Nebraska Public Power District. 45FR50330 009.
- 8010040163 Comments on proposed rules (OCFRSO, 81 & 100 re siting policies, Opposes increase in siting requirements, BIRCH., M.L. Affiliation Unknown, 48FR50050 013, 80/09/05, 1p.
- 8010060170 Comments on proposed rules (OCFR50,51 & 100 re siting policies. Present siting requirements are sufficient. WALKER, B. H. Affiliation Unknown, 45FR50350 014, 80/09/05, 1p.
- 8010060177 Transcript of 800919 public meeting in Washington, BC reproposed amend to 100FR50 concerning ATWS Pp 1-B1.

 * Commissioners. 80/09/19. 84pp.
- 8010040179 Notifies that ofc of governor has distributed proposed resources, 51 & 100 respectation on siting of nuclear power reactors, to appropriate gove agencies for review & comment. Review is scheduled to close on 800904.

 WHITEHEAD, M. Alaska, State of. 45FR50350 001. 80/08/07. 2pp.
- 8010060186 Comments on proposed rules 100FR80.31 & 10D re site isolation, Current restrictions are stringent enough Plant-specific design policy should be continued. HUGO, M. Affiliation Unknown. 45FR80350 015. B0/09/03.
- 8010040198 Comments on proposed rules 10CFR50,51 & 100 re siting policy. Agrees w/recommendation that benefits & risks of siting at specific location should be fully disclosed & used in site determinations.

 8HIVELY.R.P. Affiliation Unknown. 45FR50350 016 80/09/03, ip.

- B010060202 Comments on proposed rules 10CFR50.51 & 100 re siting policy Present siting policies are strict enough & more stringent siting requirements would only raise cost of nuclear power plants
 WINKER, L J Affiliation Unknown 45FR50350 018 80/09/10 1p
- 8010070047 Comments on proposed rules 10CFR50,51 & 100,re reactor string policies Changes to siting criteria unnecessary Technology should be improved to allow siting flexibility TWA0DDD,F J. Affiliation Unknown 45FR50350 004 80/08/21 2pp
- S010070400 Suggestions urging especitious resolution of proposed rulemaking on radwaste storage & disposal Proceeding must be confined to technical feasibility w/o consideration of social, political & institutional issues
 ZUMBRUR, R A , MOMBOISSE, R M , WHITE, E B Pacific Legal Foundation B0/10/03 5pp
- B010080002 Comments on proposed rules 10CFR50,51 re interim policy on nuclear plant accident considerations under NEPA HUDBON,6 R Illinois, State of 45 FR40101 015 80/09/09 2pp
- 8010080083 Comments on proposed rules 10CFRS0,51 Commission should rescind immediate effectiveness of interim statement proceed to informal rulemaking when all aspects have been sufficiently developed WETTERHAHN.M J Conner, Moore & Corper 45 FR40101 013 80/09/10 3as
- 80100B0090 Comments on proposed rules 10CFR50.51 re nuclear power plant accident considerations under NEPA of 1969 Urges that Commission consider submitted recommendations ELLIBIJ Citizens Association for Sgund Energy 45FR40101 017 B0/09/11 12pp.
- B010080095 Forwards comments on proposed rules 10CFR30,51 on behalf of FL Power & Light Houston Lighting & Power, IA Electric Light & Power & Poyet Sound Power & Light NEWHALL JR Lowenstein, Newman, Reis, Axelrad & Toll 45FR40101 019 B0/09/11 10gg
- B0100B010A Comments on proposed rules 10CFR50.91 Commission should reconsider position on withdrawal of annex from 10CFR50.App D & set forth valid technological basis for action RENBERGER, D. L. Washington Public Power Supply System 45FR40101 020 B0/09/12 Spp
- B0100B0114 Comments on proposed rules 10CFRSO, 51-environ & sactaetonomic impacts during & after serious accident must be considered in NEPA safety reviews, along w/proposed mitigation procedures

 SILVER, C. R. Ban Francisco, City of, CA 45FR40101 029 80/09/10
- BOIOOBOIRI Comments on proposed rules 10CFR50 & 51 if analysis repossible environ impact of Class 9 accidents is required, time limit should not be attached Rule change should not automatically exempt applications in QL stage.

 DEMPSEY.P A. Buffolk County, NY 45FR40101 009 80/08/14 2pp
- 80(10080128 Comments on proposed rules 10CFR50,51 encl draft study, "Need for Realistic Estimates of Consequences of Nuclear Accidents," investigates, basic scientific processes for determining public risks STARR, C. Electric Power Research Institute. 45FR40101 022 80/09/02. 26pp
- 80:0080:04 Comments on proposed rules 10CFR50,51 inclusion of discussion of more serious Class 9 accident scenarios will lead to more realistic economic & political attitudes toward nuclear power & to greater awareness of potential problems BENDIX,8 Affiliation Unknown 45FR40101 011, 80/08/19 ip
- 8010080142 Comments on proposed rules 100FR50 & 51 re interim policy on accident analyses in EIS for nuclear plants
 EPETH, 0 President of US & Executive Offices 45FR40101 010
 80/08/14 7pp
- B010080150 Comments on proposed rules 10CFR50 & 51 re revision of policy on nuclear power plant accidents requiring consideration of Class 9 events in environ repts Urges NRC to remove requirements for submittals ABEL, J 8, Commonwealth Edison Co 45FR40101 008. 80/08/11 2pp
 - 0080269 Suggestions orging (squarce of decision in proposed olemaking on radwaste storage & disposal due to sufficient scord. Suggests procedural steps to complete proceeding. httf:feate of Storage & Storag

- 8010080296 Comments on proposed rules 10CFR90.51 re statement of interim policy withdrawing annex to 10CFR90.App D Changes in approved design of plant should be initiated by Commission only in connection w/safety evaluation of plant LE BOUEF, R J, LAMB, H R, LEIBY, A C LeBosuf, Lamb, Leiby & MacRae 45FR40101 021 80/09/11 2pp
- 8010080367 NUREO-0684
 "Bummary of Public Comments & NRC Analysis Re Rulemaking on Emergency Planning for Nuclear Power Plants "
 # Office of Standards Development, Director 80/09/30 100pp Available at NTIS \$4 00
- B010080427 Forwards comments on NUREQ-0696, "Functional Critoria for Emergency Response Facilities " Util resolution of problems integrating comprehensive response capability into organizational structure led to highly effective criteria CROUSE,R P Toledo Edison Co 45FR54708 007 80/09/29 39pp
- B010090037 Proposes schedule for radwaste disposal hearing Working group rept summarizing record & identifying issues should be issued within 45 days from date determined by presiding officer.w/responses due 45 days after that HEISS.E R New England Coalition on Nuclear Pollution WEISS.E R Naturel Resources Defense Council WEISS.E R Sheldon, Harmon & Weiss. 80/10/06 App
- --B01007004: Memorandum in support of 801006 proposal re further radvasts disposal proceedings Working group must refine factual & legal issues Commission should then decide on need for further evidentiary proceedings
 WEISS,E R New England Coalition on Nuclear Pollution HEISS,E R Natural Resources Defense Council WEISS,E R Sheldon, Harmon & Weiss, 80/10/06 4pp
- 8010100051 Suggestions on further proceedings Record is adequate for Commission decision Commission should issue tentative statement of proposed issues Parties should be allowed to file recommended decisions Certificate of Svc encl
 KNOTTS.J B Atomic Industrial Forum 80/10/06 10pp
- 80:0100:034 Buggestions on further raduaste disposal & storage proceedings Record supports finding of confidence that reasonable assurance exists that waste can be disposed of safely Proceedings should be brought to expeditious close BUCKHAM. J A American Institute of Chemical Engineers 80/10/06 is
- BO10100136 Buggestions for further radwaste storage & disposal proceedings. Ample opportunity has been given for all parties to state positions Comment on working group rept must be allowed Certificate of Svc encl MUCHNICKI.E. D Ohio. State of 80/10/03 3pp
- B010100152 Petitions NRC to rescind Section 20 403 of 10GFR1 Proposed rule would amend previously cited section so that all abnormal incidents should be reported within 1/2-h to IE regional ofc MADERS.J.E Citizens United for Responsible Energy 77/12/27 ip
- 8010100178 Clarifies 800606 ltr to J Axelrad of EPA about 800604 maeting on possible misinterpretation of statements re 10CFR60 changes OREENHOOD.T Massachusetts Institute of Technology 44FR70408 035. 80/08/01 200

;

- --8010100186 Forwards 1tr to J Axelrad of EPA re 800604 meeting w/Martin-Dircts & Brubaker about President's nuclear waste policy implications on draft 10CFR60 GREENNODD, T Massachusetts Institute of Technology 44FR70408 035 80/06/05 6pp
- 8010100206 Comments on proposed rule 10CFR60 re radwaste transportation regulations First priority should be safety of public Notification of state officials should occur at least two working days before waste shipment LONGENECKER, S Affiliation Unknown 80/09/02 1p
- B010100213 Comments on proposed rule 10CFR40 re proposed regulations for disposal of high level wastes Proposed criteria unduly reflect social pressure w/inadequate concern for economic factors
 IRIBH.E.R. Affiliation Unknown 80/07/30 4pp
- B010100224 Comments by NY PIRO on proposed rules 10CFR50 & 51 re nuclear power plant accident considerations under NEPA of 1969 Supports general Intent, but objects to two specific points Neu stds must apply to old as well as new reactors, ROBS.D K Affiliation Unknown 45FR40101 018 80/09/10 4pp

- 8010100231 Comments on proposed rule 10CFR40 re radwaste shipments
 Prenotification is vital first line of defense in case of
 accident, assuring that local state police & emergency
 response units understand nature of accident, if called upon
 PARENT, C D Affiliation Unknown 45FR31373 031 80/09/08 2pg
- BD10100240 Comments on proposed rule 10CFR40 re technical criteria for regulating geologic disposal of high level radwaste Criteria doss not establish defense-in-depth approach w/independent barriers
 YUNN.0. COCHRAN Natural Resources Defense Council 45FR31393 032
 B0/09/11 15pp
- B010100246 Comments on proposed rule 10CFR50 re upgrading requirements for emergency plans Deleting "15 minute warning capability" may dagrade emergency plan LENIS,M I Affiliation Unknown 80/09/04 lp
- 8010100420 Comments on proposed rules 10CFR50.51 & 100 re siting policies for nuclear plants RICE,L Affiliation Unknown 45FR50350 023 80/09/24 3pp
- 8010100427 Comments on proposed rule 10CFR20 regulations need to be simplified & separated into several regulations. CRANE,P A Pacific Gas & Electric Co 45FR18023 072 80/09/04
- B010100430 Comments on proposed rule 10CFR60 proposed rule seems to be inconsistent W/NURE9-0539 RILEY,R W Affiliation Unknown 45FR31393 033 80/09/17 3pp
- 8010100432 Comments on proposed rules 10CFR50,51 & 100 re revision of reactor siting criteria
 LAMROSKI.H American Nuclear Society 45FR50350 021, 80/09/17,
- 8010100433 Comments on proposed rule 10CFR50 PACK,R W Institute of Nuclear Power Operations 45FR45916 030 80/09/26 2pp
- B010600437 Comments on proposed rules 10CFR50.51 & 100 re siting policies for nuclear plants
 FRECK.J Energy, Dept of 45FR50350 024 B0/09/18 2pp
- B010100437 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power plants
 MILLS.L.M Tennessee Valley Authority 45FR45916 027 80/09/19,
 7an
- 80:0140017 Comments on proposed rules 10CFR50 & 51 re withdrawal of proposed Annex to App D of 10CFR50 & suspension of rulemaking proceeding 8UCHMOLZ, R H General Electric Co 45FR40101 012 80/08/28 4pp
- BO10140019 Comments on proposed rules 10CFR50 & 51 re withdrawal of proposed Annex to App D of 10CFR50 Commission has engaged in balancing amount of delay that would be involved in adding review against value to public safety DOHERTY, J F. Affiliation Unknown, BO/09/06 2pp
- 8010140021 Comments on proposed rules 10CFR50 & 51 re statement of interim policy on nuclear power plant accident considerations under NEPA Supports Commission approach as interim guidance iENTSCH.J W Portland General Electric Co. 48FR40101 016 80/09/10 ip.
- 80:01:40025 Requests comments on proposed rule 10CFR2 re propriety of proposed procedural cost reduction program for intervenors in NRC proceedings MCCORMACK.M. House of Rep. 45FR4938 002. 80/09/22, 2pp.
- 8010140036 Comments on proposed rules 10CFR90.51 & 100 re siting policies Present NRC siting policies are strict enough. FUNDERBURK, V Affiliation Unknown 45FR90390 010. 80/09/02 ip
- 80:0140050 Comments on proposed rules iOCFR50.51 & 100 re siting policies. Present NRC siting policies are strict enough & need no amends. MALKER.J. Affiliation Unknown. 45FR50350 011 80/09/02, ip.
- 8010140057 Comments on proposed rules 10CFR50.51 & 100 re siting policies Current siting policies are strict enough. Reactor site isolation is unnecessary & would in fact increase total environ effects due to increased transmission line mileage.

 BAYLOR.J S Affiliation Unknown. 45FR50350 012. 80/08/26. 1p.

- B010140066 Comments on proposed rules 100FR50,51 & 100 re siting policies. AK State Clearinghouse has completed review & has no comment on project WHITEHEAD.M. Alasta, State of 45FR50350 017 B0/09/08 ip
- 8010140074 Comments on proposed rule 10CFR20 major revision should be undertaken only to achieve specific technical objectives & only where such changes are supported by scientific evidence

 8000S.L A American Mining Congress 80/09/09 5pp
- 8010140488 Forwards CPC suggestions on further proceedings dealing w/ storage & disposal of radwaste WILLIAMS.F C Isham, Lincoln & Beale 80/10/06 1p
- --B010140493 Buggestions on further radwaste storage & disposal proceedings Record supports finding that safe offsite disposal will be available between 1997 & 2006 Spent fuel can be stored at site until then M/Certificate of Svc. CALLO.J. WILLIAMS.F.C. Consumers Power Co. GALLO.J. isham. Lincoln & Beale. B0/10/04 Spp.
- 80:0140503 Suggestions as to nature & scope of further proceedings re storage & disposal of radwatte Supports & adopts suggestions submitted by State of MN Certificate of Stor encl MURRAY,M. J. Illinois, State of 80/10/06 App
- 80:0140519 Suggestions as to further proceedings. DDE mined geologic repository program & away-from-reactor storage program present overall waste mgt program capable of storing & disposing of spent fuel, Certificate of Svc encl.

 BROWN, O F , CDLEMAN, L R , DISTEFAND, J. Energy, Dapt. of 80/10/06 ito
- 80:0140549 Suggestions re further raduante storage & disposal proceedings in response to ASLB 800829 order All pertinent issues identified & discussed fully enough to enable Commission to render decision Certificate of Evc encl BAUSER, M.A. Edison Electric Institute. BAUSER, M.A. Louenstein, Newman, Reis, Aselrad & Toll 80/10/06 5pp
- --BOIOI40555 Submits list of corrections to Util Nuclear Haste Mgt Group & Edison Electric Inst BO0905 cross-statement in waste storage & disposal proceeding. Certificate of Svc and BAUSER, M A Lowenstein, Newman, Reis, Azelrad & Toll 80/10/06-700
- 8010150002 Motion to intervene out of time in Case 80-1962, or to file brief amicus curse Petitioner interest will be affected by proceeding outcome Counsel never received petition Certificate of Svc encl Related correspondence.
 REYNOLDE, N. S. . MCGARRY, J. M. Teras Utilities Generating Co. REYNOLDS, N. S. Debevoise & Liberman 80/10/07 lipp.
- 80i0i50i80 Transcript of ACRS Subcommittee on Wasta Hgt 80i003 morning meeting in Mashington.DC re proposed NRC rule on technical criteria for regulating geological disposal of high lavel radwasta & wasta confidence rulemaking Pp 1-234 # ACRS Advisory Committee on Reactor Safeguards. 80/10/03 235nn.
- 8010130611 Responds to appeal re denial of FOIA request for records re proposed fire protection rule. Forwards documents to be released Fortions of released documents & all of Document & withheld (ref FOIA Exemption 5) W/o ancls.

 CHILK: 8 J Office of the Secretary of the Commission. 80/10/06
- --8010150624 Disagress w/recommendation in proposed fire protection rule exempting installation of alternate shutdown sys from Oct 1980 deadline. Recommends 801101 as implementation date for App R requirements. Draft memo
- --B010150627 Discusses JF Ahearne 800410 memo re 8ECY-80-088 concerning fire protection rule Disagrees w/811201 date as deadline for SEP alternate shutdown sys Alternative shutdown sys should be installed by 810501.
 BRADFORD.P A. Commissioners. 80/04/14. 1p.
- --8010150430 Lists completion dates for alternate or dedicated shutdown sys, Info partially withheld (ref FOIA Examption 5), GIBBON, Y. Commissioners 80/04/03 2pp.
- --B0i0i30434 Informs of proposed rule requiring implementation of mods associated wifire protection program to be completed by B0i101. Info partially withheld (ref Fold Exemption 5). OIBBON.T. Commissioners. B0/03/11. 2pp.

- 8010150618 Appeals partial denial of FDIA request for documents which requested directed or discussed any changes to proposed fire protection rule in SECY-80-088 Documents released were not fully responsive to request KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/08/06 2pp
- BO10160766 Comments on proposed rules 10CFR50 & 51 re interim policy on accident considerations under NEPA BULLIVAN, T J Consumers Power Co 45FR40101 024 B0/09/11 3pp
- 8010160410 Forwards comments on behalf of SNUPPS utils.KG Gas & Electric & Union Electric on proposed rule 10CFR50 re Tech Epecs for nuclear power reactors PETRICK.N A Standardized Nuclear Unit Power Plant System 45FR45916
- 8010160976 Summarizes 246th ACRS meeting on 801009-11 re SECY-80-438A; proposed rule on fire protection Extremely prescriptive requirement of Branch Technical Position 9 5-1 does not provide best means to assure safety PLESSET, N S ACRS Advisory Committee on Reactor Bafeguards 80/10/14 2pp
- 8010160585 Comments on proposed rule 10CFR50, "Functional Criteria for Emergency Response Facilities " Delays in requiring implementation seem unnecessary & herardous TILBERO,K Friends of the Earth 45FR54708 001 80/09/16 ip
- 8010160607 Comments on proposed rule 10CFR20 re proposed clarifying amends Constitutes unworkable attempt to evade inescapable responsibility of individual ror own actions Recommends that no change be made

 BAGCS, L. A. Affiliation Unknown 43FR45302 003 80/09/09 3pp
- 80:01606:18 Comments on proposed rule 10CFR20 re "Miscellaneous Clarifying Amends " Doctrine of respondent superior is inapplicable where injury occurs while employee is acting outside legitimate scape of authority SHELLEY.H J. Kerr-McGee Nuclear Corp 45FR45302 002 80/08/27 ip
- BO10160635 Comments on proposed rule 10CFR20 rule would illegally impose "absolute liability" on licenseer egardiess of fault for any excessive dose or exposure Condition for receipt of license is literally impossible to fulfill RICE. 9 B Kerr-McGse Corp 45FR45302 004 B0/07/02 1p
- BOIO160675 Comments on proposed rule 10CFR20 re miscellaneous clarifying amends on behalf of Comm Ed Proposed clarifications ill-conceived & may retard, rather than further to bjectives.

 STRELOM, R , ELLIOTT, E D Leva, Hawes, Symington, Hartin & Oppenheimer 45FR45302 001 80/09/02 11pp
- 8010160683 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power reactors, in response to NRC questions published in 800708 FR 8HIELDS.8 W Public Service Co of Indiana, Inc. 45FR45916 018 80/09/05 500
- 80:10160693 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power reactors in response to NRC questions listed in 800708 FR Tech Specs should be representative of agreement between NRC & facility but allow leaway for research reactors WALSTON.R R Energy, Dept of 45FR45916 019 80/09/08 4pp
- BOIO160699 Forwards comments on proposed rule 10CFR50 "Domestic Licensing of Production & Utilitation Facilities: Tech Specs for Nuclear Power Reactors," from advance notice published in 800708 FR PARKER, U O Duke Power Co 45FR45916 020 80/09/08 App
- 8010160709 Forwards comments on proposed rule iOCFRBO re Tech Specs for nuclear power reactors; in response to advanced notice published in 800708 FR Industry & NRC should cooperate in development of criteria ANDERSON, T M Hestinghouse Electric Corp 45FR45916 016 80/09/04 6pp
- 8010160716 Forwards draft comments on proposed rule iOCFRSO new rule should benefit both licensees & NRC by saving time & by giving fleribility in changing certain Tech Specs COPELAND,R L Energy, Dept of, Clinch River Breeder Reactor Plant 43FR45916 001 80/08/25 3pp
- BO10160721 Comments on proposed rule 10CFR50 agrees that Tech Specs short-term impact on safety WULLER, 0 E Illinois Power Co 45FR45716 002 80/08/27 2pp.

- 8010160728 Comments on proposed rule 10CFR30, on behalf of ANS Working Oroup 58 4 submits responses to NRC questions on Tech Specs for nuclear power plants published in 800708 FR CORCORAN,W R American Nuclear Society 45FR45916 003 80/09/05 400
- 8010160737 Comments on proposed rule 10CFR50 re Tach Spec mods suggested changes would safeguard public by reducing operator time & attention devoted to minor matters & would improve discretionary status of consite NRC representative EICHKOLZ,0 0 Georgia Institute of Technology 45FR45716 005 80/09/08 3pp
- 8010160743 Forwards comments on proposed rule 10CFR50 re Tech Apecs for nuclear plants. Existing Tech Specs should be segregated into items w/immediate safety importance & items of lesser significance

 DUNN: C N Duquesne Light Co 45FR45916 004 80/09/05 App
- 8010160746 Forwards comments on proposed rule 10CFR50 re Tech Specs for nuclear power plants Existing Tech Specs should be segregated into items wimmediate safety importance & items of lesser safety significance
 NICHOLS-T C South Carolina Electric & Oas Co 45FR45916 006 80709705 daps
- 8010160735 Comments on proposed rule 10CFR50.proposal would establish add1 layer of regulation & would be step in wrong direction Licensee should be able to execute safety responsibilities w/reasonably limited NRC surveillance HANN,K M , KORNSLITH,L Affiliation Unknown 45FR45716 007.80/09/08 3pp
- 8010160761 Forwards comments on proposed rule 10GFR50 re Tech Specs for nuclear power reactors on behalf of Boston Edison.FL Power & Light. IA Electric Light & Power & C-E BAUBER, MA Lowenstein, Newman, Reis, Atelrad & Toll, 45FR45916 OICH 80/09/08 7pp
- 8010160767 Forwards comments on proposed rule 10CFR50 generated by Hestinghouse owners group & util Complexity of Tech Specs should be reduced to provide addl assurance that protection of health & safety is maintained JACOBILL R Houston Lighting & Power Co. 45FR45916 009 80/09/08 Bpp
- 8010170128 Forwards comments on proposed rule 10CFR50 rs Tech Specs for nuclear reactors Licensing hearing resulting from licensee electing to adopt new requirements should be limited to contentions on new Tech Specs
 JENB,W H Detroit Edison Co 45FR45916 OOS. 8D/09/05 11pp.
- 8010170201 Comments on proposed rule 10CFR50 re Tech Bpecs for nuclear power reactors Forwards response to NRC questions from advance notice published in 800708 FR Consideration should be given to removal of add unnecesseny items.

 * Portland General Electric Co 45FR45916 022. 80/09/08 Bpp.
- B010170203 Forwards comments on proposed rule 10CFR50 re Tech Bpece for nuclear power reactors Endorses effort Will participate in worthwhile resolution
 ABEL, J G Commonwealth Edison Co 45FR45916 012 80/09/05 6pp
- 8010170209 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power plants. Only safety, limiting safety sys settings & conditions for operation which could have immediate significant effect on operation should be included DRAPER. E. L. Gulf States Utilities Co. 45FR45916 026. 80/09/05 Gpp.
- B010170213 Commants on proposed rule 10CFR50 re Tech Bpecs for nuclear power plants Responses to specific questions encl BRIGHT,R M Florida Power Corp 45FR45916 025 B0/09/04 Bpp
- 8010170218 Forwards comments on proposed rule 10CFR50 re Tech Specs For nuclear power reactors in response to advanced notice published in 800708 FR 0EDR0E, B J. BATUM, O Southern Co Services, Inc. 45FR45716 014.
- 8010170221 Forwards comments on proposed rule 10CFR50 re Tech Specs for nuclear power reactors Concepts have considerable merit Current regulatory trends & policies preclude meaningful implementation CAMPBELL: J R. Affiliation Unknown 45FR45916 013 80/09/08. 8pp
- B010170226 Comments on proposed rule 10CFR50 re Tach Specs for nuclear power reactors Forwards response to questions published in 80070B FR.NRC should maintain open dialogue w/members of nuclear industry BCHERER, A E C-E Power Systems 45FR45916 011. 80/09/05. 5pp.

- B010170230 Comments on proposed rule 10CFR50 re Tech Specs for nuclear power reactors Revisions should return focus to safety Endorses rulemaking goals
 DALE.£ F Mississippi Power & Light Co 45FR45916 023 80/09/11
- 8010170236 Comments on proposed rule 10CFR50 only parameters & requirements under direct control of reactor operators should be addressed in Tech Specs Industry & NRC should cooperate in dovelopment of Tech Spec criteria CCUNSIL,W @ Connecticut Yankee Atomic Power Co CCUNSIL,W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 45FR45916 015 80/09/08 7pp
- 8010170242 Forwards comments on proposed rule 10CFR30 re Tech Specs for nuclear power plants All regulatory requirements re Tech Spec control should be incorporated into one regulation UTLEY, C E Carolina Power & Light Co 45FR45916 024 80/09/11
- B010200006 Comments by Japan Atomic Industrial Forum re proposed rules iOGFR50.51 & 100 re proposed rovision of nuclear plant siting criteria Opposes revision which would establish independent criteria for distance factor MDRI.K Affiliation Unknown 45FR50350 035 80/09/30 ip
- 8010200006 Comments by Japan Atomic Industrial Forum re proposed rules 10CFR50,51 % 100 re proposed revision of nuclear plant siting criteria Opposes revision which would establish independent criteria for distance factor KORI, K. Japan 49FR50350 035 80/09/30 1p
- BD10200006 Comments by Japan Atomic Industrial Forum re proposed rules IOCFR50.51 & 100 re proposed revision of nuclear plant siting criteria Opposes revision which would establish independent criteria for distance factor MORI.K Affiliation Unknown 45FR50350 035 B0/09/30 ip
- B010200007 Comments on proposed rules 100FR50.51 & 100 re proposed revision of nuclear plant siting criteria No clear purpose for revision

 KEARNEY J J Affiliation Unkrown 45FR50350 034 80/07/27 1200
- 8010200007 Comments on proposed rules 10CFR90,51 & 100 re proposed revision of nuclear plant siting criteria NRC should defer action on revision until other issues such as emergency planning & degraded core considerations are resolved CAHN.A L Bechtel Corp 45FR90390 033 80/09/25. App
- B010200031 Comments on proposed rules 10CFRS0,51 & 100 re proposed revision of nuclear plant siting criteria Supports expeditious completion of revision.
 FIGHER, C R General Atomic Co (subs of Oulf Dil Co) 45FR50350 032 B0/09/24 4pp
- 8010200013 Comments by Harza Engineering Co on proposed rules 10CFR50, 51 & 100 re proposed revision of nuclear plant criteria Eupports plan JONES, J C Affiliation Unknown 45FR50350 031. 80/09/26 3pp
- B010200015 Forwards Township of Lower Alloways Creek,NJ comments on proposed rules 100FR30.51 & 100 re proposed revision of nuclear plant citing criteria VALORE.C J Valore, C 49FR30350 030 B0/09/24 11pp
- 8010200017 Comments by IL Commission on Atomic Energy on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria. Revision should be cautious & proceed logically HUBBON G.R Illinois, State of 45FR90350 028 80/09/25. 2pp
- B01020001B Comments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant citing policy Recommends realistic study of all factors influencing accidental doses NULHAN; L 0 Tetra Tech, Inc. 45FR50350 027
- 8010200017 Comments on proposed rules 10CFR50,51 & 100 re proposed revision of reactor siting criteria TODORGVICH,M M Scientists & Engineers for Secure Energy. 45FR50350 026 80/09/26 Spp
- B010200031 Forwards comments by IL Commerce Commission on proposed rules 10CFR30,51 & 100 re proposed revisions of reactor siting criteria HASTEN.H V lilinois, State of 45FR50350 025 80/09/26 4pp
- 8010200179 Comments on proposed rules 100FR50.51 & 100 re proposed revision of nuclear plant siting criteria Supports revision. LENISCH.J W. Portland General Electric Co 45FR50350 049 80/09/29 2pp.

- 8010200187 Forwards comments on proposed rules 10CFR50.51 & 100 re proposed revision of nuclear plant siting criteria Proposed mods are not adequately developed or complete * Pacific Oas & Electric Co 45FR50350 O48 80/09/29 3pp
- 8010200192 Minutes of ACRS Subcommittee on Fire Protection meeting to discuss proposed 10CFR30 rule on fire protection, Rule will be discussed at 243rd ACRS meeting # ACRS Advisory Committee on Reactor Sefeguards 80/07/09, 8pp
- ~~8010200200 Forwards util 800630 comments on proposed fire protection rule W/o encl PARKER, W O Duke Power Co 80/07/03 ip.
- 8010200201 Comments on proposed rules 10CFR90.51 & 100 re proposed revision of nuclear plant siting criteria Requests time extension to submit comments on or before 801020 JACOBS, B Stone & Webster Engineering Corp 45FR50350 047 80/09/30 1p
- 8010200322 Comments on proposed rules 10CFR50, 51 & 100 re proposed revision of nuclear plant siting criteria Proposed action is merely piecemeal solution Such rulemaking activities should be superseded by integrated generic rulemaking proceedings ANDERSON, Y M. Westinghouse Electric Corp. 45FR50350 050 80/09/29
- 8010200369 Forwards outline of value/impact statement for advance notice of proposed rulemaking re consideration of degraded or melted cores in safety regulation MEDEIROS,M S Reactor Systems Standards Branch. 80/09/24 ip
- --8010200374 Outline of valve/impact statement for advance notice of proposed rulemaking re consideration of depraced or melted cores in safety regulation Advance notice will be prepared.

 * Reactor Systems Standards Branch 80/09/24, 4pp
- 8010200376 Forwards original 801006 statement of Niagara Mohawk Power Corp. Cmaha Public Power District. PASNY & PSC of IN Inc re further proceedings for svc & filing per NRC 800128 order, VOIGT. H H LeBoeuf, Lamb, Leiby & MacRae 80/10/06 1p.
- --80102003Bi Asserts that adequate record compiled & no further actions necessary. Suggests that NRC expedite record review & issue final rule Recommends affirmative finalings be made. VOIGT.H H Niegara Mohawk Power Corp VOIGT.H H Omaha Public Power District VOIGT.H H Power Authority of the State of New York. 80/10/06 2pp.
- 8010200505 Submits comments on NURED-0696. "Functional Criteria for Emergency Response Facilities" NURED-0696 specifies technical requirements rather than functional criteria for emergency response facilities

 ASH.R F Daltimore Oas & Electric Co 45FR5470B 032 80/10/15
- B010200567 Requests that encl suggestions on proposed rules 10CFR50 & 51 re storage & disposal of radwasts be filled ω/NRC & that time-stamped copy be returned in encl envelope. MUCHNICKIrE D Ghio. State of. B0/10/03 ip
- --8010200574 Submits suggestions in opposition to NRC opinion that responsibility for further course of proceedings re-proposed rules 100FR00 & 51 rest W/perties rather than Commission Certificate of Svc encl
 BROWN.W J. MUCHNICKI.E D. Ohio. State of 80/10/03 3pp
- 8010200679 Buggestions on nature & scope of further proceedings In order to determine adequate waste disposal will be available when needed, NRC cannot limit consideration to theoretical case. Certificate of Svc encl
 JOHNERUD, J. H. Environmental Coalition on Nuclear Power 80/10/06, 4pp
- 8010210010 Comments on proposed rules 10CFA50,51 & 100 re proposed revision of nuclear plant criteria Rationale & technical basis for imposing rule change are insufficiently explained OIBBB, D.C. Atomic Industrial Forum. 45FR50350 045 80/09/30 15sp.
- 8010210011 Comments on proposed rules 10CFR50.31 & 100 re proposed revision of nuclear plant siting criteria Criteria should be justified on basis of cost/benefit analyses & developed within framework of overall RRC safety philosophy PATTI:F.J. Burns & Ros Co 45FR30350 044 80/09/25, 8pp.

- 8010210012 Comments on proposed rule 10CFR20 relicenses being held responsible for personnel exposure occurring in connection w/licensed activities Licensees should not be penalized for unauthorized employee actions
 PIAZZA,R P Nestinghouse Electric Corp 43FR45302 005 80/07/02
- 8010210118 Forwards comments on proposed rules 10CFR50,51 & 10D resiting policy task force rept Requests that comments delayed by unfortunate oversight, be included in NRC consideration MONTOOMERY, A First National Science Foundation 45FR50350 059 80/10/10 5ns
- 8010210128 Forwards comments on proposed rules 10CFR50,51 & 100 piecemeal attempts to effect substantial changes in regulations should not be considered New approach based on natl reactor safety goal w/uniform assessing methods needed.

 ABEL,J 8 Commonwealth Edison Co 45FR50350 060 80/10/01 8pp
- 8010210137 Comments on proposed rules 10CFR50.51 & 100, "Mod of Policy & Regulatory Practice Governing Siting of Nuclear Power Reactors "Requests that both E15 & value impact statements be integral part of subsequent rulemaking of sub; SULLIVAN:T J Consumers Power Co 45FR50350 058 80/10/02 6pp
- 8010210660 Forwards comments on draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" All requirements re seismic or environ qualification should be deleted to permit designer flexibility of readily employing available sys ANDERSON, T.M. Westinghouse Electric Corp. 45FR54708 002 80/09/19 App.
- 8010210704 Comments on draft NVREO-0496. "Functional Criteria for Emergency Response Facilities " Intermediate activities of proposed schedule should be deleted due to conflict w/ activities scheduled to meet overall implementation dates JACOBS.8 B Btone & Webster Engineering Corp 45FR54708 004 80/09/25 Sp
- 8010210713 Forwards comments on draft NUREQ-0676. "Functional Criteria for Emergency Response Facilities" Interim requirements that are subj to early review & revision should not be included in final document.

 LEPPKE.D M SEELEY.O T Fluor Power Service, Inc. 45FR5470B 003-80/09/24 3pp
- 8010210721 forwards comments on NUREC-0696, "Functional Criteria for Emergency Response Facilities " Util mpt should make determination if implementation of emergency response ctrs requires single or multiple distributed processing sys MATHEMS, E R Wisconsin Public Service Corp 45FR54708 005 80/09726 4pp
- 8010210728 Comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities," Schedule date for implementation of SPDS portion of integrated sys should be extended until Apr 1982

 JURGENSEN, R W American Electric Power Co , Inc 45FR54708 Ol6 80/09/29 26pp
- 8010210740 Forwards comments on NUREO-0576. "Functional Criteria for Emergency Response Facilities " Any ref to Reg Ouide 1.97 should be made more specific by referring to applicable sections of particular revisions.w/date of issuerce, GOODNIN.C. Portland Osneral Electric Co 45FR54708 008 80/09/26 76p.
- 8010210745 Forwards comments on NUREO-0496. "Functional Criteria for Emergency Response Facilities " Published criteria are overly prescriptive & in some cases, unreasonable & unjustifiable in light of function of facilities PARKER, H O Duke Power Co 45FR54708 019 80/09/30 9pp.
- 8010210750 Forwards comments on NUREO-0676, "Functional Criteria for Emergency Response Facilities " NRC authority, responsibility & accountability for all aspects of accident should be defined LOOMIS, J S Sargent & Lundy, Inc. 45FR54708 014, 80/07/29 3pp.
- 8010210756 Forwards comments on NUREG-0496. "Functional Criteria for Emergency Response Facilities." All prohibitions against use of existing station process computers should be replaced w/set of functional requirements

 LOOMIS.J S. Bargent & Lundy. Inc. 45FR54708 027 80/10/07. App.
- 80:02:1076: Forwards comments on NUREQ-0496, "Functional Criteria for Emergency Response Facilities" Also endorses comments submitted by KMC. Inc in 80:0927 ltr UDNES.W.C Omaha Public Power District 45FR54708 028 80/09/30.

- 8010210764 Forwards comments on NUREO-0676, "Functional Criteria for Emergency Response Facilities"
 BAYNE, JP Power Authority of the State of New York 45FR54708 031 B0/10/10 3pp
- B010220065 Comments on NUREO-0590, Revision 2 re decommissioning Terminology re capital recovery methods should be clarified, NUREO/CR-1481 provides NRC w/basis for promulgating regulations to ensure adequate financial assurance FEROUSON.J B MMS Consultants. Inc., Middle Nest Service Co Div 43FR10370 80/09/29 6pp
- B010220112 Comments on NUREO-0695. "Functional Criteria for Emergency Response Facilities " Undue hardship is placed on util licensee or applicant who is expected to expend sizeable resources to implement mods prior to final form DELOEDROE, L O Commenwealth Edison Co 45FR54708 012 80/09/26 10es
- 8010220117 Transcript of 244th ACRS meeting on 801010 in Washington, BC Pp 77-277 Viewgraphs, responses to questions re fire protection rule: BECY-80-438A & draft FR notice encl * ACRS Advisory Committee on Reactor Safeguards 80/10/10 400pp
- 80i0220ii8 Comments on NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Each design should be avaluated on individual basis Proposed criteria do not allow enough flexibility for site-specific factors SCHUYLER-J D : HOCK, B Pacific Oas & Electric Co 45FR54708 017 80/09/24 9pp
- 8010220123 Comments on NUREO-0695, "Functional Criteria for Emergency Response Facilities," on behalf of Coordinating Oroup on Emergency Preparedness Implementation Show cause approach to regulation is unconscionable & should be overturned BUYD, R B, Kerr-McOes Chemical Corp (subs of Kerr-McGee Corp) 45FR84708 006 80709/29 Spp
- 8010220128 Forwards quarterly proposed rule rept as of 800731 FELTON. J. H. Division of Rules and Records 80/10/07. 44pp
- 8010220130 Comments on NUREO-0676, "Functional Criteria for Emergency Response Facilities " Strongly andorses NRC integrated approach re facilities designed to facilitate mitigation of abnormal events
 CDUNSIL. II O. Connecticut Yankee Atomic Power Co CDUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities)
 45FR94708 018 80/09/27 6pp
- 8010220140 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities" Also strongly endorses comments submitted by XMC Coordinating Group on Emergency Preparedness Implementation & Yankee Atomic Electric Co EVANS-S D. Haine Yankee Atomic Power Co 45FR54708 030 80/09/30 780
- 8010220147 Comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities" Emphasis should be placed on monitoring data Refs to control of plant operations, implied or explicit, should be eliminated DRAPER, E.L. Gulf States Utilities Co. 45FR54709 029, 80/09/29, 300
- 8010220136 Forwards comments on NUREG-0634, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparadness in Support of Nuclear Power Plants " DAIL-L C. Duke Power Co 44FR75167 206 80/09/25 3pp
- 8010220197 Comments on NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments restricted to items affecting design & const & not on operational considerations of failure reporting & limiting conditions
 CAIN.A.L. Bechtel Power Corp. (subs. of Bechtel Corp.) 45FR54708
 009 80/09/29 4pp
- 8010220204 Forwards comments on draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" NRC should fully consider comments prior to final publication since only i day is scheduled between comment expiration & final form MOMELL,8 H Atomic Industrial Forum 45FR34708 010 80/09/29 78p
- 8010220207 Forwards comments on draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Fully andorses AIF ZARAKABJF. Consolidated Edison Co of New York 45FR34708 013. 80/09/26. 4pp

- 8010220483 Comments by Japanese Federation of Electric Power Companies on proposed rules iOCFR50.51 & 100 re proposed revision of reactor siting criteria No attention given to Japan & European countries, where population density is high ITO.T Affiliation Unknown 45FR50390 022 80/09/16 6pp
- 8010220484 Comments by State Planning 8vcs Agency on proposed rules 100FR50.51 & 100 re proposed revision of reactor siting criteria Bupports efforts to revise criteria RUDZINSKI,M Indiana, State of 45FR50350 020 80/09/18
- 8010220485 Comments on proposed rule 10CFR50 re Tech Specs, Proposed changes can best be accomplished by segregating Tech Specitems w/immediate safety importance from items w/lesser safety significance CRANE, P A Pacific Gas & Electric Co 45FR45916 029 80/09/17
- B010220487 Comments on proposed rule 10CFR50 re Tech Specs Rule should address applicability to CP.near-term OL & OL plants in fashion similar to existing regulation BAYNE.J P Power Authority of the State of New York 45FR45916 028 80/09/17 6pp
- B010230011 Requests tht draft FR notice re low level radwastes be signed by BJ Chilk & published for 45-day comment period Preliminary value/impact statement of amends to 10CFR20 for disposal of biomedical & aqueous wastes also encl DAVIS, J.O. Office of Nuclear Material Bafety & Safeguards B0/09/29 41pp
- 8D10230223 Comments on proposed rules iOCFR50,51 & 100 Confirms telcon re-extension of time for submitting comments on proposed revision of nuclear plant siting criteria Comments will be submitted within 30 days

 BROUN,R H Housing & Urban Development, Dept of 45FR5035D 036-80/10/01.
- 8010230506 Forwards, on behalf of U mining industry, petition filed w/EPA for reconsideration & revision of radiation protection atom codified in 40CFR190 Requests relief for reasons stated in petition GVERTON, J.A. American Mining Congress 80/10/14 375pp
- 8010230511 Comments on NUREC-0676 re functional criteria for emergency response facilities Concurs w/AIF subcommittee comments.

 8ALDARINI.J C Ebasco Services, Inc. (subs. of Enserch Corp.)
 45FR94708 023 80/10/03 4pp
- 8010230519 Comments on NUREG-0696 re functional criteria for emergency response facilities
 BULLIVANAT J Consumers Power Co 45FR54708 024 80/10/02 8pp.
- 8010230591 Comments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria Licensees should not be required by regulation to submit info on safety issues as part of NRC NEPA site review STETBON,F Atomic Industrial Forum 45FR50350 052 80/10/01 4pp
- B010230594 Camments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria Supports revision R088,D &. Affiliation Unknown 45FR50350 051 80/09/29 14pp
- 8010240001 Forwards comments, on behalf of membership, on proposed rules 100FR50,51 & 100 re proposed revision of nuclear plant string criteria Basic goals of revision unclear REARNEY, J J Edison Electric Institute 45FR50350 034 80/09/29, 120p.
- 8010240170 Comments on proposed rules 10CFR50 & 51 re interim policy on huclear plant accident considerations under NEPA Specific criteria should be used in consideration of previously systemed events.

 ANDERSON: T. M. Westinghouse Electric Corp 45FR40101 025 80/09/29
- --8010240194 Requests that NRC publish advance notice for public comment of integrated set of generic proceedings to resolve outlined issues Flow chart of proposed proceedings & relationships ancl ANDERSON, T M Westinghouse Electric Corp N8-TMA-2267 80/06/19
- 8010240198 Forwards comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities."

 VAN BRUNT, E. E. Arizona Public Service Co. 45FR54708 020. 80/09/24.

- 8010240200 Confirms 800930 comments by Japan AIF re proposed rules iOCFR50,51 & 100 on reactor siting criteria Detailed comments and Opposes distance factor from engineered safety features

 MDRI.K Affiliation Unknown 45FR50350 034 80/09/30 3pp
- 8010240223 Comments on proposed rules 100fR50,51 & 100 re mod of policy governing siting of nuclear power reactors Socioeconomic impacts should be incorporated into rulemaking procedure SDUTH.D W Argonne National Laboratory 45FR50350 053 80/09/29
- 8010240332 Forwards comments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria Safety goals should be defined before proceeding w/rulemaking TIPTON,T E General Public Utilities GPU Service Corp 45FR50350 055 80/10/02 Spp
- 8010240355 Forwards comments on NUREC-0694 re functional criteria for emergency response facilities
 TIPTON.T E. General Public Utilities OPU Service Corp 45FR94708
 022. 80/10/01 6pp
- 8010240358 Comments on proposed rules 10CFR50.51 & 100 re proposed revision of nuclear plant siting criteria 8COTT.J Affiliation Unknown 45FR50350 043 80/10/01 1p
- 8010240471 Transcript of NRC 801016 meeting in Washington,DC to discuss & vote on fire protection program Pp 1-84 Viewgraphs enci * Commissioners 80/10/16 98pp.
- 8010240504 Comments by Boston Edison. Duke Power, JCP&L, Met Ed. Northeast Utils.PA Electric & TX Utils Generating Co on proposed rules 10CPR50, 51 & 100 re revision of nuclear siting criteria Rula should be limited to plants seeking CP after 791001 MCGARRY, J. H., REYNOLDS, N. S. Debevoise & Liberman 45FR50350 042 80/09/29 41pp.
- 8010240514 Comments on proposed rules 10CFR50.51 & 100 re proposed revision of nuclear plant siting criteria Proposal is premature until specific safety goals are developed SALDARINI.J G Envirosphere Go 45FR50350 041. 80/09/29 8pp
- 8010240521 Comments on proposed rules 10CFR50, 51 & 100 re proposed revision of nuclear plant siting criteria Concurs w/AIF comments PATTERBON, J D Middle South Services, Inc. 45FR50350 040 80/09/26. 600
- 8010240529 Comments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria Proposed takes unfortunate narrow view by limiting criteria to population HINDLE.J. C. Kensas State Univ 45FR50350 039 80/09/27 ip
- 8010240540 Forwards comments on proposed rules 10CFR50.51 & 100 re proposed revision of nuclear plant citing criteria Changes could have considerable value to nuclear industry VANCE.J N Affiliation Unknown. 45FR50350 038 80/09/26. 7pp
- 8010240543 Forwards comments on proposed rules 10CFR50.51 & 100 re proposed revision of nuclear plant siting criteria. ZARAKASI P Consolidated Edison Co of New York 45FR80350 037 80/09/29 19pp
- 8010240547 Comments on proposed rules 10CFR50,51 & 100 re proposed revision of nuclear plant siting criteria Certain issues should be addressed before development of proposed rule RENBERGER, D.L. Meshington Public Power Supply System 45FR50350 036 80/09/26 3pg.
- 8010240550 Comments on proposed rules 10CFR50.B1 & 100 agrees w/ ultimate objectives of siting policy task force. BHIELD8.8 W Public Bervice Co of Indiana. Inc. 45FR50350 057 8D/09/27 9pp
- B010270164 Comments on NUREG-0694 re functional criteria for emergency response facilities Legal basis for document are not obvious Objective criteria needs to be clarified. UHRIG.R.E. Florida Power & Light Co 45FR54708 023. H0/09/29. 300.
- 8010280017 Notion for supplementation of ASLB 800328 memorandum & order Assignments enumerated in order must be accomplished by NRC staff. Work product must be offered to participants if relief denied. Certificate of svc encl.

 8AUSER, M. A. Edison Electric Institute BAUSER, M. A. Lowenstein, Newman, Reis, Axelrad & Toll 80/10/22, 9pp.

- 8010300002 Comments on proposed rules 100FR5D,51 & 100 re revision of reactor siting criteria Characteristics re geoscience should be considered on site-specific basis re Class 9 accidents.

 RATHLESSEROUR Interior,Dept of 45FR50350 061 80/10/17 3pp

PRH PETITION FOR RULEMAKING

- 8009110006 BFCY-80-382
 Recommends approval of notice of denial of petition for rulemaking PRM 51-5 re States of NY.GH & WI 791215 proposal for dollar value impacts re nuclear waste activities in U fuel cycle
 BIRCKS-H J Office of Nuclear Material Safety & Safeguards
 BO/08/15 75pp
- B010010121 Forwards Electric Util's, AIF, EPRI et al B00916 patition for rulemaking, 10CFR50 47, re-stds for reduction of risk from ATHB, unresolved safety issue TAP A-9 REVELEY, N T Hunton & Milliams B0/09/16 ip
- --8010010127 Petition for rulemaking 10CFR50-47 re atds for reduction of risk from ATUS, unresolved safety issue TAP A-9, Certificate of Svc enci REVELEY, H T. Atomic Industrial Forum REVELEY, H T Electric Power Research Institute REVELEY, H T Hunton & Williams. 80/09/16, 43pp
- B010070289 Responds to 800805 request for administrative clarification to 100FR30,15(a)(9) Ltr request meets criteria for petition for rulemaking & will be acted upon per 100FR2,802(c) ARLOTTO,0 A Division of Engineering Standards 80/09/09 2pp.
- 8010100152 Petitions NRC to rescind Section 20 403 of 10CFR1 Proposed rule would amend previously cited section so that all abnormal incidents should be reported within 1/2-h to IE regional ofc.

 MAGERS.J E Citizens United for Responsible Energy. 45FR13434 016 77/12/27 1p
- 8010160572 Comments on petition for rulemaking 140-2 re regulation to increase amount of liability insurance required Ignores fact that nuclear insurance policies are result of bargaining between purchasers of policies & suppliers BCHULTZ:H B : MORRISON.A B Public Citizen Litigation Group. 45FR26973 013. 80/08/25. 3pp
- B010310459 Notice of issuance & evailability for public comment of GA Go B00909 petition for rulemaking 30-57 CHILK: B J Office of the Secretary of the Commission. B0/10/07 Gpp.
- --B010310465 Requests clarification of code re licensing of ionizing radiation measuring instruments containing multiple byproduct source matis Byproduct matis in instruments are each eithin exempt quantity limitations HOMPV.# R. General Atomic Co (subs of Oulf Dil Co). 336-2003. B0/08/05 2pp.
- --B010310470 Responds to B00B09 request for clarification of code re licensing of ionizing radiation measuring instruments containing multiple byproduct source metls. Request will be forwarded as petition for rulemaking. ARCGITD.0 Office of Standards Development, Director 80/09/05.

PROJ PROJECTB - PREDUCKET LICENSING

- 1010080353 Burmary of 800630 meeting w/GA Co & ANL re critical experiment program for gas-cooled fast breader reactor. KUZMYCZ: Q. Assistant Director for Licensing. 76/07/13 Gpp
 - 0100206 Comments on proposed rule 10CFR60 re radwasts transportation agulations. Pirst priority should be safety of public stification of state officials should occur at least two strking days before weste shipment.

 NOGENECKER, 8. Affiliation Unknown. 60/09/02. 1p.
 - 70:54 NUREC-0706 VI eric FEB on U milling.Project M-25, summary & text Office of Nuclear Material Befety & Safeguards. 80/09/30, 400pp. vailable at NTIS. \$10.00.

- 8010170155 NUREG-0706 VZ Generic FEB on U milling.Project M-25.Apps A-F * Office of Nuclear Material Safety & Safeguards 80/09/30 200pp, Available at NTIB 66 50
- B010170161 NUREG-0706 V3

 Ceneric FEB on U milling.Project M-25.Apps G-V

 Dffice of Nuclear Material Bafety & Bafeguards 80/09/30 200pp

 Available at NTIB \$7.00
- 8010230333 Summary of NRC 800916-22 trip to Edgement 8D for meeting w/BNML to initiate work on Edgement cleanup action program EADIE, 0 O Uranium Recovery Licansing Branch FIN B-2217 80/10/06 ip
- 8010280B92 Informs of current status of ultrasonic testing development program supporting planned FFTF secondary weld insp Progress in development of plant equipment & in improving data collecting & analysis techniques has been good CARLISLE.G B Energy, Dept of 80/10/22, 2pp
- 8010310262 Forwards 8 Wright 800907 itr commenting on 800630 law requiring that state governors receive prior notification of shipments of nuclear waste Ltr is to become part of official comments WILBON.C. House of Rep , Appropriations, 80/09/i8 2pp.
- 8010310268 Submits questions & comments on law signed by President Carter on 800630 re state governors receiving prior notification of shipments of nuclear waste WRIGHT.B. Affiliation Unknown 80/09/07. 1p
- 8010310281 Comments on regulations re control of radwaste shipments. Notice should be given to state officials at least two days in advance Notification should not prevent officials passing info on to local authorities. BOLINE.M F Affiliation Unknown 80/08/28 ip
- B010310328 Comments on regulations for transportation of radwastes.
 Regulations should be specific & provide severe penalties
 Several days advance notice should be provided w/exact
 times & routes
 OUTELIUS-HATT Affiliation Unknown 80/09/05 ip.
- 8010310335 Comments on Appropriations Act. Section 301 requiring governors receive prior notification of radwaste shipments Rule should place no restrictions on how governors disseminate info re shipments to state & local officials HRITE. D Vermont Public Interest Research Group 80/08/13 2pp
- 8010310339 Comments on Appropriations Authorization Act, Section 301 regovernors receiving prior notification of radwasts shipments Urges adopting only strongest rules to protect safety of people in area of transportation.

 JACOBE, L. Affiliation Unknown 80/09/06 2pp.

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8010020599 Part 21 rept re undetected weld discrepancy involving ASME-8A312 welded pipe which had nondestructive evaluation performed Pipe evaluation performed correctly MCDEMPOTT,R.J. Rockwell International Corp., Energy Systems Div. 806808535 80/09/05 3pp
- 8010240855 Part 21 rept re valve coil Latent defect exists w/magnet wire insulation, polyimide, not being compatible w/polyvinyl coating when subjected to continuous operation at elevated temps. New dasign being implemented.

 BORGO, G. J. Valcar Engineering Corp. BO/10/17. 2pp.
- B010240557 Part 21 rapt re failure of Valcor P/N V70900-21-3 when used in continuous energized mode at elevated temps. Preliminary study indicates problem w/coil winding. Cause of failure under investigation BDROD, G. J. Valcor Engineering Corp. 10CFR 050, 55E 80/09/26. 2pg.
- SO10290084 Part 21 rept re 4-degree rotation of valve actuator occurring during SBE test. Caused by pinning failure. Powell Energy Sys Group & Energy Technology Engineering Ctr will evaluate by SO1014
 FENTON. R. E. . ARCHBOLD, P. . DEBEAR, W. S. Rockwell International Corp. . Energy Systems Div SOETEC-DRF-4476. BO/10/15, 4pp.
- 8010310046 Part 21 rapt re malfunction in control console of Cs-137 calibrator. On 801009, source could not be lowered except by continuously depressing off button, Alarm would sound prior to source elevation
 KNEESGY, A. D. Army, Dept. of 80/10/21, 7pp

QA999 QUALITY ASSURANCE INSPECTIONS

- 8010080063 Forwards GA Program Insp Rept 99900063/80-01 on 800804-08.No noncompliance noted POTAPDVS.V Region 4. Dallas. Vendor Inspection Branch. 80/08/18 200
- --8010080069 GA Program Insp Rept 9990063/80-01 on 800804-08 No noncompliance noted. Major areas insperted implementation of 100FR90. App B, criteria & applicable codes & stds including actions on previous insp findings ROSERDS.H W. BARNES, I Region 4. Dallas. Vendor Inspection Branch 80/08/15 5pp
- BO10090073 Forwards GA Program Insp Rept 99900509/E0-02 on B00616-19, No noncompliance noted POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch B0/07/18
- --8010080081 OA Program Insp Rept 99900509/80-02 on 800616-19 No noncompliance noted Major areas inspected implementation of 10CFR50.App Buriteria in area of followup on regional requests & unresolved concerns of IE Bulletins 79-04 & 14. ANDERSON.D G , BREAUX.D G , HALE,C J Region 4. Dallas, Vendor Inspection Branch. IEB-79-04 80/07/02 10pp
- B010080104 Forwards GA Program Insp Rept 97900251/B0-02 on 900728-0801. No noncompliance noted PDTAPOVB,U Region 4. Dallas, Vandor Inspection Branch 80/08/21.
- --E010080111 GA Program Insp Rept 99900251/80~02 on 800728-0801.No noncompliance noted Major areas inspected implementation of 10CFR50.App B, including GA records & welding control. BRGMN.R L . MHITEBELL.D E. Region 4, Dallas, Vandor Inspection Branch 80/08/20 App
- 8010080148 Ack receipt of 800702 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900302/80-02 POTAPOVE,U Region 4. Dallas, Vendor Inspection Branch. 80/09/10, is.
- --8010080147 Responds to NRC 800808 ltr re deviation noted in GA Program Insp Rept 99500302/80-02 Corrective actions correct weld procedure spec & proper temp sticks given to welder, FRIEDMAN.K A Western Piping & Engineering Co : Inc 80/09/02, ip
- --8010080197 Forwards GA Program Insp Rept 99900302/80-02 on 800714-18 & notice of deviation POTAPOV8.U Region 4. Dallas. Vendor Inspection Branch 80/08/08 25s.
- --B010080160 Notice of deviation from insp on 800714-18,
 # Region 4, Dallas, Office of the Director 80/08/07 ip,
- --8010080167 QA Program Insp Rept 99900302/80-02 on 800714-18
 Noncompliance noted required WPB not at welding station & welder not following welding procedure requirements.
 EUTTON.J W. WHITESELL.D.E. Region 4, Dallas, Vendor Inspection Branch, 80/08/07, 4pp
- 8010080175 Ack receipt of 800808 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99905302/80-02 POTAPGV8.U Region 4. Dallas, Vendor Inspection Branch. 80/09/12. 1p.
- --8010080180 Responds to NRC 8007ii ltr re deviation noted in GA Program Insp Rept 99700802/80-02. Verifies that corrective action, generic consideration & preventive measures for indexing & control of GA manual were as described in 800421 ltr PEIPER. H. B Brown & Root Corp. (subs of Halliburton Corp.). 80/08/08, 4pp
- --8010080188 Forwards QA Program Insp Rept 99900502/80-02 on 800616-20 & notice of deviation.
 PDTAPOVS, U. Region 4, Dallas, Vandor Inspection Branch. 80/07/11.
- --9010080190 Notice of deviation from insp on 800616-20, * Region 4, Dallas, Office of the Director, 80/07/10, 1p.

- --8010080196 0A Program Insp Rept 99900502/80-02 on 800616-20 Noncomplicance noted STP GA program does not implement all STP PSAR commitments w/raspect to organization. 0A program, design control.procurement & audits
 FOX.D F. HALE, C J. Region 4. Dallas, Vendor Inspection Branch 80/07/10 16pp
- B010160288 Ack receipt of 800918 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900019/80-01.
 PUTAPOVS.U. Region 4. Dallas, Vendor Inspection Branch 80/09/25-1p.
- --8010160292 Responds to NRC 800811 ltr re deviation noted in QA Program Insp Rapt 99700019/80-01 Corrective actions Engineering Instruction 7 34 revised to clearly define responsibility, distribution & Closing of technical questions reised JOHNSON, E ITT Grinnell 80/09/18 5pp.
- --8010160297 Forwards GA Program Insp Rept 99900019/80-01 on 800721-23 & notice of deviation EEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/11 200.
- --8010160301 Notice of deviation from insp on 800721-23
 ** Region 4. Dellas, Office of the Director 80/08/07 ip
- --B010160312 GA Program Insp Rept 97900019/B0-01 on B00721-23 Noncompliance noted copies of technical question forms not submitted to director of GA per IYT Orinnell Industrial Piping, Inc 790913 corrective action response lir BARNES I. Region 4, Dallas, Vendor Inspection Branch B0/08/07 4pp.
- 8010160652 Ack receipt of 800915 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900361/80-01. POTAPOVS.U. Region 4. Dailas. Vendor Inspection Branch 80/09/26
- --8010160659 Responds to NRC 800721 ltr re deviation nated in QA Program Insp Rept 99900361/80-01 Corrective actions permanent voltmater has been placed in position outside influence of magnetic field & checked on all welding machines HOME.R. J Q. Dikkers & Go., N V. The Netherlands RJH/AZ/123, 80/09/15, 15pp.
- --8010160563 Forwards GA Program Insp Rept 99900351/80-01 on 800612-13 & notice of deviation PDTAPDV8,U Region 4. Dallas, Vendor Inspection Branch. 80/07/21 200
- --8010160666 Notice of deviation from insp on 800612-13
 * Region 4, Dallas, Office of the Director, 80/07/18, 2pp.
- --B050160674 GA Program Insp Rept 99900361/80-01 on 800612-13.

 Noncompliance noted qualification of hard surfacing welding procedure spec EAP 2443, Rev 1, not in accordance Criterion 5 of 10CFR50. App b.

 BANNES, I, ELLERBHAH, L. E. Region 4, Dellas, Vendor Inspection Branch, 80/07/18. Bpp.
- 8010210451 Ack receipt of 800828 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900280/80-01 PGTAPOVB.U. Region 4. Dallas, Vendor Inspection Branch 80/09/08. ib.
- --8010210455 Responds to NRC 800815 ltr re deviation noted in QA Program Insp Rept 99900250/80-01. Corrective actions.company developed checklist of all essential k nonessential variables that are applicable to welding process.

 SMEAL.L P Benjamin F Shaw Co (subs. of Blount, Inc.).
 80/08/28, lp.
- ---8010210457 Forwards GA Program Insp Rept 99900250/80-01 on 800721-25 & notice of deviation. PUTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch. 80/08/15, 2pp.
- ---8010210459 Notice of deviation from insp on 800721-25, # Region 4, Dellas, Office of the Director, 80/08/11, 1p.
- --B010210443 GA Program Insp Rept 99900250/80-01 on B007R1-25.

 Nencompliance noted: width: frequency or dwell time of accillation was not listed on welding procedure spec as regulared.

 RGERDS:H.M., BARNES,I. Region 4, Dallas, Vendor Inspection Branch. B0/08/11. 3pp.

8010210575 Ack receipt of 800827 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990025/80-02 Repion 4. Dallas. Vendor Inspection Branch 80/09/15

- --8010210602 Responds to NRC 800616 1tr re deviations noted in GA Program Imag Rept 97900025/80-02 Corrective actions pipe codes revised & 800814 instruction session held w/dapt managers MERKE,N H Southwest Fabricating & Welding Co (subs of IU International Corp) 80/08/24 18pp
- --80102(061) Suppl 800812 ltr re thermowell deviation Vendor has not received complete info from Ebasco that would enable completion of response to OA Program Insp Rept 99900025/ 80-02 MOERKE,N H Southwest Fabricating & Welding Co (subs of IU International Corp) 80/08/22 2pp International Corp)
- --8010210732 Informs of insbility to complete response to Item 3 of notice of deviation due to incorrect/incomplete thermowell info furnished by Ebasco HOERKE, N X Southwest Fabricating & Welding Co (subs of IU International Corp.) 80/08/12 1p
- --8010210738 Informs that response to QA Program Insp Rept 97900025/80-02 not complete due to delays in receiving requested clarification of piping spec matl data from Sbasco MERKE:N M. Southwest Fabricating & Welding Co (subs of IV International Corp.) 80/07/18 1p
- --8010210746 Suppls 800718 response to QA Progrem Insp Rept 99900025/80-02 Response to insp rept will be completed during wk of 800804 HOERKEN H 8 Subthwest Fabricating & Welding Co (subs. of IV International Corp) 80/07/30 ip
- --8010210752 Forwards GA Program Insp Rept 99900025/80-02 on 800602-04 & notice of deviation.
 POTAPOVS,U Region 4. Dailss. Vendor Inspection Branch. 80/06/16
- --8010210757 Notice of deviation from insp on 800602-04 # Region 4. Dallas. Office of the Director 80/06 80/06/13
- --8010210763 QA Program Insp Rept 99700025/80-02 on 800602-04
 Noncompliance noted translation of design spec requirements
 not correctly performed at required by Criterion 5 of
 10CFR50.App B
 BARNESII., POTAPOVS, U Region 4. Dalles, Vendor Inspection Branch
 80/06/13. 4pp.
- 8010220010 Responds to FOIA request for most recent insp repts performed by IE at Okonite & Rockbestos Cos Forwards documents listed in App A FELTON.J.M Division of Rules and Records 80/10/14 2pp
- 8010220013 FOIA request for most recent insp repts performed by IE at Okonite & Rockbestos Cos FAY, C W Wisconsin Electric Power Co 80/09/26 ip.
- 8010240014 Forwards GA Program Insp Rept 99900001/80-02 on 800804-08 No noncompliance noted POTAPOVS, U Region 4: Dallas, Vendor Inspection Branch. 80/08/27
- --8010240014 OA Program Insp Rept 99900001/80-02 on 800804-08 No noncompliance noted Major areas inspected; fuel hold down spring failures fuel assembly fabrication & action on pravious insp findings. MCNEILL.H.M., WHITEBELL,D E Region 4: Dallas: Vendor Inspection Branch 80/08/25, App
- 8010240018 Ack receipt of 801001 ltr informing NRC of steps taken to correct deviation noted in GA Program Inap Rept 97900243/ 80-01 POTAPOVS.U. Region 4: Dallas, Vendor Inspection Branch 80/10/14
- -8010240019 Responds to NRC 800922 ltr re deviation noted in GA Program Insp Rept 99900245/80-01 Corrective actions.ltr issued outlining dates for audits.
 GATES.8 M Pittsburgh-Des Moines Steel Co 80/10/01 3pp
- --8010240020 Fowards OA Program Insp Rept 97900243/80-01 on 800825-29 t notice of deviation POTAPOV8.U Region 4, Dallas, Vendor Inspection Brench 80/09/20

- --8010240021 Notice of deviation from insp on 800825-29
 * Region 4, Dallas, Office of the Director 80/09 80/09/19
- --B010240022 GA Program Insp Rept 99900243/80-01 on B00823-29
 Noncompliance noted annual corporate & division audits
 not performed as required by GA manual
 SUTTORI, J W. WHITESELL, D E Region 4. Dallas, Vendor Inspection
 Branch 80/09/19 8pp
- 8010240573 Forwards QA Program Insp Rept 97900394/80-02 on 800811-14 No noncompliance noted POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/08/29,
- --8010240584 GA Program Insp Rept 99700394/80-02 on 800811-14.No noncompliance noted Major areas inspected implementation of 100FR App 8 including audits.training,document control & action on previous insp findings BROWN.R.L. HMITESELL,D E Region 4. Dallas, Vendor Inspection Branch 80/08/25 10pp
- 8010270009 Forwards GA Program Insp Rept 97900313/80-01 on 800728-31 No noncompliance noted POTAPDVS, U Region 4, Dallas, Vendor Inspection Branch. 80/08/29.
- --8010270011 QA Program Insp Rept 97900313/80-01 on 800728-31 No noncompliance noted Major areas inspected implementation of 10CFR App 8 criteria & applicable codes & stds,weld specs, weld mati control & procurement HUNTER,V H, WHITESELL.D E Region 4, Dallas, Office of the Director 80/08/27 9pp
- 8010270754 Ack receipt of 800723 ltr informing NRC of steps taken to correct deviation noted in GA Program lnsp Rapt 99700242/80-01 Region 4, Dallas, Vendor Inspection Branch. 80/10/14.
- --8010270556 Responds to NRC 800828 ltr re deviation noted in GA Program Insp Rept 99900242/80-01 Corrective actions personnel will not be certified w/o physical check of daily records & all OGN/SION, D R Pittsburgh-Des Moines Steel Co DGA-80-127 80/09/23 2pp
- --8010270539 Forwards GA Program Insp Rept 99900242/80-01 on 800728-0801 & notice of deviation POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/08/28
- --8010270561 Notice of deviation from insp on 800728-0801
 * Region 4, Dallas, Office of the Director. 80/08/2
- ---8010270563 GA Program Insp Rept 99900242/80-01 on 800728-0801

 Noncompliance noted personnel being qualified w/o required documentation of practical experience & radiographic examination performed w/o approved technique procedure SUTTON.J W . WHITEBELL.D E. Region 4. Dallas, Vendor Inspection Branch 80/08/25 6pp
- 8010270368 Ack receipt of 800924 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900519780-02 PDTAPOVA.U. Region 4. Dallas, Vendor Inspection Branch 80/10/03.
- --8010270572 Responds to NRC 800827 ltr re deviation noted in GA Program Insp Rept 99700519/80-02 Corrective actions. Procedure FDP-3, evaluation procedure for as-built configuration of nuclear safety-related components for IE Bulletin 79-14, revised KOMES, J. M. Bechtel Power Corp (subs. of Bechtel Corp.), 80/09/24 2pp
- --8010270573 Forwards GA Program Insp Rept 99700519/80-02 on 800721-24 & notice of deviation.
 POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/09/27.
- --8010270975 Notice of deviation from insp on 800721-24.
 * Region 4. Daltas, Office of the Director. 80/08 80/08/21, 1p
- --8010270576 GA Program Insp Rept 99700519/80-02 on 800721-24.

 Noncompliance noted failure to follow procedures during evaluation of as-built configuration of nuclear safety-related piping components

 BRICKLEY.R H Region 4, Dalles, Office of the Director ANDERBON,D,O. Region 4, Dalles, Vendor Inspection Branch.

 YIN.I.T Region 3, Chicago. Office of the Director 80/0 80/0B/21,

- B010280722 Ack receipt of 800912 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700326/80-01 PDTAPDVS,U Region 4. Dallas. Vendor Inspection Branch B0/10/03 is
- --8010280725 Responds to NRC 800827 ltr re deviation noted in QA Program
 Insp Rapt 97900526/80-01 Corrective actions issued revised
 project instructions including more definitive project
 requirements for drawing index
 ADAM.P J Dlack & Veatch 80/09/12 4pp
- --8010280728 Forwards GA Program Insp Rept 99900526/80-01 on 800804-08 & notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/08/27.
- --B010280730 Natice of deviation from insp on 800804-08 * Region 4. Dallas, Office of the Director 80/08/25 3pp
- --B010280735 GA Program Insp Rept 99900526/B0-01 on B00B04-0B Noncompliance noted failure to have procedures controlling maint of engineering change notices log & failure to follow procedures controlling PSAR changes BRICKLEY,R H, AYLHARD,P B, JOHNSON,J M Region 4, Dallas, Vendor Inspection Branch B0/08/25 16pp
- 8010290101 Forwards QA Program Insp Rept 99900718/80-01 on 800710-11 \$ notice of deviation POTAPBY8.U Region 4. Dallas, Vendor Inspection Branch 80/07/29 200
- --8010270105 Notice of deviation from insp on 800710-11
 * Region 4. Dallas. Office of the Director 80/07/28 1
- --8010270108 GA Program Insp Rept 99900718/80-01 on 800710-11 Noncompliance noted required mondsstructive examination of full penetration tee weld joining anchor bolts to base plates of embedments was not performed BRDNNR L , WHITESELL D E Region 4. Dallas, Vendor Inspection Branch 80/07/28 Spp
- 8010290112 Ack receipt of 801002 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700246/80-02 PDTAPGVS,U Region 4. Dallas, Vendor Inspection Branch 80/10/14 is
- --B010270116 Responds to NRC 800725 itr re deviation noted in GA Program Insp Rept 99900266/80-02 Corrective actions, in-process insp procedure being written to include daily check of bevels MODIA: R ARROG.Inc 80/10/02 ip
- --8010270121 Forwards GA Program Insp Rept 97900268/80-02 on 800709-12 & notice of deviation POTAPOVS,U. Region 4, Dallas, Vendor Inspection Branch 80/09/25
- --8010290122 Notice of deviation from insp on 800909-12
 * Region 4, Dallas, Office of the Director 80/09/24 is
- --8010290126 GA Program Insp Rept 99900268/80-02 on 800909-12
 Noncompliance noted failure to meet requirements of
 Procedure 10 & welding procedure Epec 5.Revision 3.for pipe
 ID seam weld edge bevel requirement of 5/16-inch depth.
 OLLER:R E . BARNES:I. Region 4. Dallas: Vendor Inspection Branch.
 80/09/24 11pp

REGOD REGULATORY OUIDES

- 7809\$80012 Value/Impact Assessment of Rev 3 to Reg Ouide 1 35, inservice insp of ungrouted tendons in prestressed concrete containment structures

 w Office of Standards Development, Director 78/09/09 4pp.
- --7809180014 Notice of NRC staff meeting on 770706 to discuss Reg Guide 1 35, re inservice insp of ungrouted tendons for prestressed concrete containment structures ASHAR.H. Structures & Components Standards Branch. 77/07/20.
- --7809180016 Comments on Reg Ouide 1 35.dated Jan 76 entitled "Inservice Revision 2 of Unquoted Tendons in Prestressed Concrete Containment Structure "
 E18ENHUT.D.O Assistant Director for Systems Engineering (Pre 791030). 77/10/29. 2pp.

- 8009110362 "For Comment" marked-up copy of draft Reg Guide SC 705-4, "Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination "

 Office of Standards Development, Director 80/07/29 37pp
- ---8009110366 Comments on Draft 1 of proposed reg guide. "Ultrasonic Testing of Reactor Vessel Welds During Inservice Insp "
 Increases cost of insps by factor of 10 over factors in impact statements.u/no increase in safety
 LENARDSON.J D Toledo Edison Co 79/01/18 Spp
- --BD0911036B Draft "Resolution of Industry Comments to Draft Reg Quide on Ultrasonic Testing of Reactor Vessel Welds During Inservice Examination & its Value/Impact Statement " Unofficial comments encl.

 * Office of Standards Development, Director 80/07/30 i50pp
- 8010060047 Bummarizes NRC 800905 meeting w/industry re Reg Quide 1 97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Assess Plant & Environ Conditions During & Following Accident " Related met! enc!
 HINTZE: A B Reactor Systems Standards Branch 80/09/17 38pp
- 8010060171 Draft value/impact assessment of proposed Reg Guide 1 23. Revision 1 Recommends preparation of in-house revision to guide 2 Office of Standards Development, Director. 80/09/30 App
- 8010090493 Forwards comments on draft reg guide RS 705-4, "Lightning Protection for Nuclear Power Plants" New distribution frequency curve based on stroke data to stricken heights no greater than 60 meters has been developed.

 JOHNSON, I. B. Affiliation Unknown 80/04/10, 98pp.
- B010100146 Comments on proposed Reg Quide DH 902-4, "Instruction re Risk From Occupational Rediation Exposure " Poor organization of guide would create difficulties in implementation RENSERGER, D.L. Washington Public Power Supply System. B0/09/02 288
- 8010100163 Comments on proposed Reg Guide FP 818-4, "Std Format & Content of License Applications:Including Environ Repts, for Insitu U Bolution Extraction " Titles of encl list of reg guides should be put in same format HASHIKOFO:K. Affiliation Unknown. 80/08/12 2pp
- 8010100170 Forwards comments by Bureau of Radiological Health on proposed Reg Quide OH 902-4, "Instruction re Risk From Occupational Radiation Exposure " Quide will be useful in explaining radiation exposure risks, VILLFORTH, J C HEW, Dept of, Food & Drug Administration 80/08/27
- 8010100176 Comments on proposed Reg Ouide RB 110-5, "Nuclear Power Plan Simulators for use in Operator Training " Ouidence for determining other types of partial functions to be included in simulator should be provided B
- 8010100185 Comments on proposed Revision 1 to Reg Guide 10,6 re industrial radiography Reg guide should note that persons who operate placarded vehicles must comply u/federal motor caprier regulations. KOVACS.B Foster Wheeler Corp 80/08/25. 2pp
- 8010150642 Suggests revisions to Reg Ouide 1.97 re defining instrumentation requirements for varied emergency response functions & integration of various needs CATTON. I ACRS Advisory Committee on Reactor Safeguards. 80/08/15 2pp
- 8010200362 "For Comment" issue of second proposed Revision 2 to Reg Ouide 1.8, "Personnel Qualification & Training " Task Number RS 807-3. RICHARDSON 8 D Office of Standards Development, Director 80/09/30 63pp.
- 8010210058 Comments on proposed Reg Ouide R8 110-5, "Nuclear Power Plant Simulators for Use in Operator Training." Endorses reg guide & draft ANS 3 5. Requirements for App A data base need to be more clearly defined, especially re equipment lineups JACOBI.L.R. Houston Lighting & Pawer Co ST-HL-AE-557 80/10/08. 1s.

- B010210061 Comments on proposed Revision 2 to Reg Ouide 1 33 flexibility for ensite QA organizations should be retained Review documents for location of control room instrumentations & controls should include design drawings ANDERSON, C R Rochester Gas & Electric Corp 80/09/08
- 8010210065 Comments on proposed Revision 1 to Reg Guide 10 5, "Guide for Preparation of Applications for Use of Sealed Sources & Devices for Performing Industrial Radiography " Requirements already identified in state & Federal regulations TAYLOR, J H Babcock & Wilcox Co 80/09/15 2pp
- 8010210142 Comments on proposed Reg Guide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " Before reg guide is officially approved,800324 draft of ANS 3 5 should be approved through stds concensus process Comments and ANDERSON,T K Hestinghouse Electric Corp N5-TMA-2313 80/09/23
- 8010210147 Comments on proposed Reg Ouide RS 110-5 simulation should precede hardware (actual product being simulated) & should include may practical number of possible operational conditions & situations

 8ANTSAVER, P Affiliation Unknown PAC-NL-249-80 80/09/12 2pp
- 8010210159 Comments on proposed Reg Guide RS 110-5 malfunction list should include high radiation & fire alarms, loss of diesel generator, loss of circulating water-turbine load & hotwell level control failure & auxiliary feedwater sy failure EDWARDS; N W Affiliation Unknown NKE-080-044 80/09/22 4pp
- 8010210192 Comments on proposed Revision 2 to Reg Quide 1 97 accident monitoring instrumentation inputs should be from sensors that directly measure desired variables MCQUEEN.M M Affiliation Unknown 80/08/ii 3pp
- 8010210196 Comments on proposed Rag Quide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " Exact duplication of control room can detract from proper priority of training objectives FAY.C W Wisconsin Electric Power Co 80/09/18 2pp
- B010210199 Comments on proposed Reg Guide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " Simulator should be able to be used to train operators from similar plants in addition to ref plants JACOBS.S B Stone & Webster Engineering Corp. 80/09/12 1p
- 8010210202 Comments on proposed Reg Quide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " Concurs w/ statements Agrees w/andorsoment of ANS-3 5 Addl clarification should be made to improve guide
- 1010210223 Comments on proposed Reg Quide RS 110-5, "Muclear Power Plant Simulators for Use in Operator Training " Quide should not imply that training on simulators which do not represent specific plant would be meaningless MOODY, J H Yankee Atomic Electric Co WYC 80-27, 80/09/23 2pp
- 8010210228 Comments on proposed Reg Oyide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " FFTF project comments should be passed on to appropriate NRC organization.

 BARBER, R N Energy, Dept of 80/09/30 2pp
- 3010210266 Comments on proposed Reg Guide FP 818-4 distinction should be made between operations having USOS approval & NRC licensing authority Guidelines should be developed jointly for operations where jurisdictions unavoidably overlap MENARD,H W Interior, Dept of, Geological Survey EOS-ER-80/840 BO/09/25 2pp
- 8010210271 Forwards comments on proposed Reg Ouide RS 110-5, "Nuclear Power Plant Simulators for Use in Operator Training " Plant-specific simulators are not necessary to realize significant training benefits TIPTON, T. E. Oeneral Public Utilities OPU Bervice Corp. Etc.-2808. 80/09/18 4pp Oeneral Public Utilities - OPU Bervice Corp. E&L-2808.
- 8010210273 Comments on proposed Revision I to Reg Guide 10 6 info in App B is embiguous & should be clarified BEVAN.W O. Roctwell International Corp , Hanford Operations 80/09/17 1p
- 8010210277 Comments on proposed Revision I to Reg Guide 10 6, "Guide for Preparation of Applications for Use of Sealed Sources & Devices for Industrial Radiography " LEVELIUS,W H. Pittsburgh Testing Laboratory 80/08/27. 2pp

- BO1022014B Second proposed Revision 3 to Reg Guide 1 33. *GA Program Requirements for Nuclear Power Plants **

 * Reactor Systems Standards Branch 80/09/04 24pp
- --8010220174 Draft value/impact assessment of porposed Reg Guide 1 33 MRC staff, w/consent of AMSI.has decided to endorse Draft 5 (Aug 1980) of proposed revision to AMS std * Reactor Systems Standards Branch 80/09/04 26pp
- 8010220172 Submits addl comments on draft reg guide R8 70S-4, "Lightening Protection of Nuclear Power Plants " Submits corrections to 800410 ltr & typed Pages 31-38 in substitution of Pages 31-40 of encl rept byo encl JOHNSON I B Affiliation Unknown 80/04/18 ip
- B01022017B Forwards comments on draft reg guide RB 705-4. "Lightening Protection for Nuclear Power Plants." supplementing 800410 & 18 ltrs Also includes ref page covering Refs 26-40 JOHNSON, I. B Affiliation Unknown 80/05/23 46pp
- 8010240274 Comments on Reg Quide 1 97, Revision 2, "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Following Accident " LIPINSKI, W C Argonne National Laboratory 80/08/13 3pp
- 8010270952 Comments by Harrisburg.PA local union on proposed Heg Guide 8 13, "Instruction Concerning Risk from Occupational Radiation Exposure " Info is vital for job performance w/o unfounded fears Endorses concept SACLE,O W International Brotherhood of Electrical Workers 80/09/08 2pp
- 8010270057 Comments on proposed Revision 1 to Reg Quide 4 14 re U mill monitoring Screening technique recommended 770816, after thorough initial examination more appropriate than technique for assuring doses are less that 40CFR190 1 limits SHELLEY, W J Kerr-McGee Nuclear Corp 80/08/29 2pp
- 8010270061 Commants on proposed Revision 1 to Reg Guide 10 6 Favorable consideration of position will not decrease radiation safety, but will avoid unnecessary requirements which would increase operational time & costs HENDRIA, O W Navy, Dept of, Navel Facilities Engineering Command 109 80/09/03 2pp
- 8010270323 Forwards Draft 3.Revision 2 to Reg Guide 1 97, "Instrumentation for Light-Water Cooled Nuclear Power Plato Assess Plant & Environs Conditions During & Following an Accident "Changes made to address ACRS concern ARLOTTO, O A Division of Engineering Standards 80/10/ 80/10/15. Rpp
- --8010270328 Draft 3.Revision 2 to Reg Guide 1 97, "Instrumentation for Light-Hater-Cooled Nuclear Power Plants to Assess Plant & Environs Conditions During & Fallowing an Accident " HINTZE.A S Reactor Systems Standards Branch 80/10/08 57pp
- 8010270326 Comments on draft reg guide FF 818-4, "8td Format & Content of License Applications, Including Environ Repts, for In Situ U Solution Extraction " Rag guide flawed in philosophy & requirements
 CODK,L.H Chevron Industries, Inc , Chevron Resources Co Div
 80/09/29. 3pp.
- B010270329 Comments on draft Reg Guide FP 818-4, "Std Format & Content of License Applications, Including Environ Repts, for In Situ U Solution Extraction " Forwards more realistic varsion of reg guide CORPSTEIN P.E Everest Minerals Corp 80/09/29 23pp
- 8010270(34 Comments on proposed Reg Guide 5 61. "Intent & Scope of Physical Protection Upgrade Rule Requirements for Fixed Sites " Rule would eliminate controlled storage of weapons at facility, impairing effectiveness of response force EALDARINI.J C. Ebasco Services, Inc (subs of Enserth Corp.) 80/10/01, 2pp
- B010270137 Comments on Revision 1 to Reg Guide 4 14, "Radiological Effluent & Environ Monitoring at U Mills " DURLER, D.L. UB Steel Corp 80/10/01. App.
- 8010300005 Comments on proposed Revision 2 to Reg Guide 1 B repersonnel qualification & training Educational requirements for shift supervisor should be high school diploma, specified number of technical courses & mgt course SEAMAN, 0 0 Canberra Industries. 80/10/10 1p.

NONDOCKETED ITEMS

- 8010310229 Comments on Revision 1 to Reg Ouide 1 23. "Mateorological Programs in Support of Nuclear Power Plants " Ref should be made to OA for design & const since meteorological data are required before plant operation MAASS, W. P. Guality Assurance Branch 80/10/17 1p
- B010310233 Comments on draft Reg Guide OH 941-4, "Info Relevant to Ensuring that Occupational Esposure at U Mills will be ALARA "
 - PEAK, R F Pathfinder Mines Corp 80/10/15 7pp
- 8010310240 Comments on draft Rag Guide CH 710-4, "Health Physics Surveys in U Mills " Yellow cake will show up on any contrasting color Hand rails should be kept clean to prevent snearing workers hands PEAK, R. F. Pathfinder Mines Corp. 80/10/03 3pp
- 8010310233 Comments on Revision 1 to Reg Guide 1 23, "Meteorological Programs in Support of Nuclear Power Plants " RUTLEDGE.C Wyoming Mineral Corp REG-80-473 80/10/17 5pp
- 8010310258 Comments on draft Reg Ouide OH 914-4 re ALARA Inapproriate for application to Freemont Chemical Corp recovery facility Licensing should proceed on case-by-case basis HICKCOX.8 T Affiliation Unknown 80/10/13 2pp

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 8010010B02 "LOFT Fuel Rod Cladding Critical Collapse Pressure Analysis " OLSEN,C B . RUSSELL,M L . HANSON,D J EO&G. Inc USNRC-P 374 80/08/26 7pp
- 8010010866 "LOFT Program," monthly progress rept for Jul 1980 KAUFMAN, N C EG&G. Inc LO-MR-008 80/08/31 106pp
- BO10080194 "Oxygen & Hydrogen Generation in NSSS & in Blowdown Tank After LOCA:" LOFT technical rept KUOERA:D E E0&0 Idaho, Inc LTR 112-149 78/12/01 18pp
- B0100B0210 B010B00210

 *Failure Mode Effect & Consequence Analysis on LOFT
 Pressurizer Relief Line Mod & Small Break Valves for L3-5,"
 LOFT technical rept
 NARRETYO,C J E0&G Idaho: Inc L0-20-80-138 B0/08/29 12pp
- 8010080234 "Analysis Rept for Semiscale Mod-3 Station Blackout Tests B-TR-1 & B-TR-2:" interim rept HANBUN, R O E000 Idaho, Inc FIN A-6038 E00-SEMI-5227 80/08/31 6200.
- BO10130071 "Quick Look Rept on Large Bcale Reflood Test 3 CCTF Test C1-3 (Run 012) Conductivity Liquid Level Detector Data " MCROAN,M A Idaho National Engineering Laboratory, FIN A-6100 EGG-2D/3D-5236, 80/09/30 210pp
- B010150123 "Accident Aerosol Characterization." monthly progress rept for Aug 1980. MISHIMA.J Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2287 80/09/12 24pp
- B010150127 "Quick Look Rept on Large Scale Reflood Test 2 CCTF Test C1-2 (Run 011) Conductivity Liquid-Level Detector Data." HCRGAN.M A Idaho National Engineering Laboratory FIN A-6100. EG0-2D/3D-5235 B0/09/30 230pp
- B010150130 "Calculation of CANON Experiment Using TRAC Gode " LEKACH B.V Brookhaven National Laboratory FIN 3215. BNL-NUREO-28290. 80/08/31. 42pp
- B010150136 "Div of Reactor Safety Research ORNL Programs," monthly progress rept for Aug 1980
 MYNATT,F.R. Dak Ridge National Laboratory 80/09/30 38pp
- BO10150137 "BWR Refill-Reflood Program." monthly progress rept for Aug 1780.
 BURNETTE. Q W General Electric Co FIN B-5877. B0/07/16. 5pp
- 8010150140 "Analysis of LER & Noncompliance Data Related to Licensee Performance Evaluation," POTASH.L.H Ideho National Engineering Laboratory. FIN A-6119. E00-880C-8223, 80/08/31, 81pp
- 8010130142 "Quick Look Rept on Large Scale Reflood Test 4 CCTF Test C1-4 (Run 013) Conductivity Liquid Level Detector Data." MCRGAN, M. A. Idaho National Engineering Laboratory. FIN A-6100 EGG-2D/3D-3237. 80/09/30. 283pp

- 8010150147 "FLECHT-SEASET," monthly progress rept for Aug 1980 MASSIE,H W Hestinghouse Electric Corp NRC-04-77-127 SP-80-672 80/09/24 Bpg
- 8010190223 "Definition of Parameters for Major Accidents at Waste Bolidification & Spent Fuel Storage Facilities." monthly progress rept for Aug 1980 FREDERICK,E J Cas Ridge National Laboratory FIN B-0425. 80/09/15 3pp
- B01013024i "Nondestructive Examination Evaluation Support," monthly rept for Aug 1980 EMITH.J H Oak Ridge National Laboratory FIN B-0233 DRNL/MCD/NEE8-8 80/09/08 4pp
- 8010150528 "Forecasting Electricity Demand by State & by Util Svc Area," progress rept for Jul 1980 CHERN.W B Oak Ridge National Leboratory FIN 8-0190-8 ORNL/ED/EAS-80/ 80/08/19 Spp
- 8010180553 "FLECHT-SEASET Program." monthly progress rept for Jul 1980 MASSIE.H W Westinghouse Electric Corp NRC-04-77-127 SP-80-671 80/09/24 9pp
- 8010150563 "BNR Blaudown/ECC Program," monthly programs rapt for Aug 1980. BURNETTE,O W General Electric Co FIN B-3014 80/09/16 App
- 8010150579 "Environ Statements Project," monthly progress rept for Jul 1980. ZITTEL:H E Oak Ridge National Laboratory FIN 8-0001. ORNL/ED/E18-135 80/07/31 4pp
- 8010150587 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly progress rept for Aug 1930 HUTTON,P.H. KURTZ,R.J. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2088 80/09/18 11pp
- 8010170101 "Environ Assessments of Fuel Cycle Facilities." monthly progress rept for Aug 1980 ZITTEL.H E Gak Ridge National Laboratory FIN B-0279 DRNL/ZD/E18-134 80/08/21 Spp
- 8010170118 "Physical Protection of Nuclear Facilities," monthly progress rept for Aug 1980 CHAPMAN,L D Sandia Laboratories FIN A-1060 80/09/22 6pp
- 8010220599 "Evaluation of Docket Files of Terminated Licenses."
 monthly progress rept for Aug 1980.
 HOLOWAY.C F. WITHERSPOON.J Cak Ridge National Laboratory FIN
 A-9083-7 GRNL/HABRD-92 80/08/21 19pp
- 8010220627 BNL-NUREG-27544
 "Thermal-Hydraulic Effects on Ctr Rod Drop Accidents in
 BWR "
 CHERO, H 8 , DIAMOND, D J Brookhaven National Laboratory FIN
 A-3329 80/07/31 73pp
- 8010220651 "Matl Control & Accounting Effectiveness Evaluation Development," monthly progress rept for Jul 1980. PUGOIG.A Lawrence Livermore Laboratory, FIN A-0115 80/09/05.
- 8010280597 "Safeguards Analysis for Byproduct Matls & Small Quantities of SNM," monthly progress rept for Aug 1780 CHESTER,R O , RANDOLPH.U L Dak Ridge National Laboratory FIN B-6108 ORNL/HASRD-94 80/09/17. 7pp.
- B010300137 "Quick Look Rept on Large Boale Reflood Test-1 CCTF Test Ci-1 (Run 010) Conductivity Liquid Level Detector Data " MDROAN,M A EGGO Idaho: Inc FIN A-6100 EGO-29/3D-5234. B0/09/30 235pp
- 8010300142 "Hater Reactor Research Directorate Monthly Rept for Aug 1980." BOSTNICK, M.E., YBARRDNDD, L.J. EG&G Idaho, Inc. 80/09/30 217pp
- 8010300161 "Fuel Specific Heat Capacity & Fuel Enthalpy," interim rept REYMANN,O A Idaho National Engineering Laboratory, FIN A-6050 E0G-CDAP-5120 80/09/30 30pp
- B01030017B "Measured Release of Radioactive Xenon.Krypton & Iodina From U Dioxide During Nuclear Operation & Comparison W/Release Models." APPELHANS, A D., TURNBULL.J.A. Idaho National Engineering Laboratory FIN A-6041. EGG-TFBP-5251 80/09/30 71pp

- 8010300194 "Best Estimate Prediction for LOFT Nuclear Experiment L3-5/L3-5A," Interim rept MODRO,8 M , CONDIE,K Q , LINEBARGER,J H E0&0 Idaho, Inc FIN A-604B EGG-LOFT-5240 B0/99/30 53pp
- BO10300207 "LOFT L3-1 Preliminary Comparison Rept," interim rept CZAPARY,L S E010 Idaho, Inc FIN A-6047 E0G-CAAP-5288 B0/09/30 41pp
- BO10300232 "LOFT Henthly Progress Rept for Aug 1980 "
 KAUPHAN N C . MOHR, D EGG Idaho, Inc LO-MR-009 80/09/30
 103pp
- BO10300301 "Operational Transient Test Series.Test OPTRAN i-1, Experiment Operating Spec," interim rept LAPOINTER E , MARTINSON, I R EG&G Idaho, Inc FIN A-6041 EGG-TFSP-5213 60/09/30 57pp
- 8010300304 "Environ Statements Project." progress rept for Aug 1980 ZITTEL.H E Oak Ridge National Laboratory FIN 8-0001 DRNL/ED/EIS-137 80/08/31 4pp
- B010300336 BNL-NUREO-28144 "Metallurgical Examination of Steam Generator Feedwater Pipe Cracts:" progress rept for Jul 1980 VYAS,B Brookhaven National Laboratory FIN A-3106 BNL-NUREO-28146 80/07/31 79pp
- 8010300676 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," progress rept ror Aug 1980 GREGORY, W B , MARTIN, R A Los Alamos Beientific Laboratory FIN A-7029 WX-8-3850(R673) 80/09/25 4pg
- 8010310533 "LWR In-Plant Measurement Program." progress rept for Sept 1980 MANDLER.J W E0&0 Idaho, Inc FIN A-6075 80/10/15 4pp
- BO10310560 "Advanced Instrumentation for Reflood Studies (AIRS)," foreign trip rept HERSKGVITZ,K 8, MCCOLLOUGH.N D Oak Ridge National Laboratory FIN B-0413 GRNL/FTR-952 SO/10/08 Spp
- 8010310566 "Decontamination as Precursor to Decommissioning," progress rept for Sept 1980 PERRIGOL D Battelle Memorial Institute. Pacific Northwest Laboratory FIN 8-2303 80/10/06 6pp
- 8010310574 "Accident Aerosol Characterization," progress rept for Sept 1980 DHZARSKI.P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2287 80/10/16 6pp

REVIEW ORP NRC RESEARCH REVIEW GROUPS

- 8010090286 Notification of 801003 & 1103 meetings w/fire protection review group & Sandia Labs in Bethesda-MD to discuss full scale fire replication tests Preliminary test plan enc! FEIT,R Division of Reactor Safety Res
- --8010070288 Draft, "Replication Tests for Fire Protection Sys "
 * Sandia Laboratories 80/09/18 7pp
- 8010170065 Notification of 801028 meeting in Oaithersburg.MD to discuss test methods for early warning fire detection sys.

 FEIT.R Division of Reactor Safety Research 80/10/02 2pp

RM RULEMAKING

- 8009220226 Comments on rulemaking 50-5 GERMO proceedings should be reopened Technical, economic & safety issues must be addressed in order for decisions to be made re use of mixed-axide fuels.

 WEITIBERO, A Affiliation Unknown 80/09/15 1p
- 8009220237 Comments on rulemaking 50-5 GESMO proceedings should be resumed & completed.Reprocessing & recycle of LHR fuel should be considered.
 TSGULFANIDIS,N Affiliation Uninown 80/09/15, ip
- B010020125 Draft outline: "Staff Paper on Procedures to be Followed to Reach Decision on Wide-Scale Pu Recycle " Draft 750917 outline enci, & Commissioners 75/09/18, 11pp,

- --B010020128 Discusses provisional Decision Paper 3 Lists four new safeguard items in Huberman focusing instructions Related documentation ent!
 BUILDER: C.H. Office of the Executive Legal Director 75/09/18
- B010010830 Comments on proposed rule RK 50-5 re NRC termination of efforts on GESMO fuels NRC should resume OESMO proceeding Certificate of Svc & svc list encl PECHER.U Affiliation Unknown 45FR53933 OO: 80/09/03 7pp
- 8010020104 Addi response to FOIA request for 47 documents rø GESMO Forwards 11 documents listed in app FELTON: J M Division of Rules and Records 80/09/25 2pp
- --6010020107 Discusses possible additions to GESMO provisional views scoping paper includes discussion of other policies to provide range of options, intl factors & effect of upgraded NRC program upon ERDA & military, LEACHMAN, R B Commissioners 75/09/02 4pp
- --8010920115 Submits proposed action plan for safeguerds portion of QESHO Outline includes assumptions, product, organization & support, schedule & observations

 BUILDER: C.H. Office of the Executive Legal Director 75/09/15
- --8010020120 Forwards questions re 750910 Pu recycle provisional view issues & alternatives
 DIRCKE,W Office of the Executive Director for Operations
 75/09/15 2pp.
- 8010220718 Comments on relemaking 50-5 GESMD hearings should resume immediately BARRY, D. Affiliation Unknown 45FR53933 023 80/09/14 lp
- B010220529 Comments on rulemaking 50-5 supports resumption of OEBMO proceedings.

 CREIGIEMSKI,P. Affiliation Unknown 45FR53933 022 80/09/16 ip
- 8010220540 Comments on rulemaking 50-5 NRC should not reopen QEBMO or other nuclear recycle-related licensing proceedings Opposes action which would be contrary to US nonproliferation policy MCLAUGHLIN.W. T Affiliation Unknown 45FR53933 019 80/09/12 is
- 8010220663 Comments on rulemaking 50-5 0ESMO proceedings should be respensed Braft article encl which should have some input in forming policy on recycling Pu DEYAR Citizens United for Responsible Energy 45FR53933 017 80
- 8010230231 Comments on rulemaking 50-5 GEBMO proceedings should be resumed Delays will not serve nati security & will increase cost of energy COURTNEY, J C. Affiliation Unknown 45FR337D3 016. 80/09/15 Bp
- 8010230247 Comments on rulemaking 50-5 Commission should reopen GEGMO proceedings
 8ARRY, J E Affiliation Unknown 45FR53933 014 80/09/15 ip
- 8010230265 Comments on rulemaking 90~5.0E8MO proceedings should be resumed HACHNEY,C A Affiliation Unknown 45FR33933 012 80/09/12 ip
- 8010230281 Comments by TN Technological Univ on rulemaking 50~5 GEBMO proceedings should be restarted immediately DEMAS.N O Affiliation Unknown 45FR53933 009 80/09/11 ip
- 8010230291 Comments on rulemaking 50-5: GESMO hearings should be responsed.

 JORES W Affiliation Unknown. 45FR53933 007 80/09/15. 1p
- 8010230304 Comments on rulemaking SO-5 DEBMO proceedings should be resumed UB should do everything to minimize use of foreign oil & extend U reserves by reprocessing of spent fuel.
 PANZANI.F A Affiliation Unknown ASFR83933 015. BO/09/17 ip
- 8010230317 Comments on rulemaking 50~5; GEBMO proceedings should not be reopened TUCKER.C.A Affiliation Unknown. 45FR53933 013. 80/09/14. 1p
- 8010230323 Comments on rulemaking 50-5 re resuming GESIMO proceedings CHU88. N. Affiliation Unknown 45FR53933 011 80/09/14 3pp.

8010230328 Comments on rulemaking 50-5 GEBMD hearings should not be reopened due to problems w/reprocessing Health harards associated w/transport & reprocessing shown to be more serious than previous espectations CLEMENTS. T Affiliation Unknown 45FR53933 010 80/09/13 1p

801023034i Camments on rulemaking 50-5 OEBMO proceedings should be reopened COPE2, C R Affiliation Unknown 45FR53933 006 80/09/12 ip

B010230349 Comments on rulenaking 50-5 supports reopening of GESMO proceedings
LORFING. D. Affiliation Unknown 45FR53933 008 B0/09/ii ip

SECY POSITION PAPERS BEFORE THE COMMISSION

8009100225 SECY-80-392
Requests Commission approval of final rulemaking deleting
10CFR20 304 re burial of small quantities of radionuclides
Value impact assessment & rept justification for deletion
of 10CFR20 304 & proposed FR notice deleting 20 304 encl
HINDGUE.R B Office of Standards Development, Director. 80/08/21

8009100243 BECY-80-385
Recommends Commission approval of amends to 10CFR2 713 for publication in final form Draft proposed FR notice, comparative text of recommended final rule & proposed rule & draft ltr for Congressional committees encl SHAPAR, H K Office of the Executive Legal Director, 80/08/15 28pp

8009100739 SECY-80-236
Recommends issuance of final rule tOCFR72 re specific
licensing requirements for storage of spent fuels in
independent spent fuel storage installation Draft FR notice
enc!
HINOGUE,R B Office of Standards Development, Director 80/05/08

8009110006 BECY-80-382
Recommends approval of notice of denial of petition for rulemaking PRM 51-5 re States of NY,OH & WI 791215 proposal for dollar value impacts re nuclear waste activities in U fuel cycle
BIRCKS.W J Office of Nuclear Material Bafety & Bafeguards 80/08/15 75pp

8009290471 BECY-BO-415
Recommends proposed amends to 10CFR20 to permit disposal of liquid scintillation media animal carcasses containing tracer levels of certain radionuclidas Draft FR notice of proposed rulemaking encl
DIRCKB-RU Office of Nuclear Material Safety & Bafeguards
HONOGUE,R D Office of Standards Development. Director. B0/09/09

B010010030 BECY-80-299A
Recommends approval to publish FR notice amending 10CFR25 in accordance w/Commission decision & recommendation in SECY-80-299 Draft notice enci
DOWGSMUE,D J Office of Administration 80/09/05 7pp

B010050114 BECY-80-0790
Forwards M Hessier 800909 memo re competitive harm aspect of disclosure of GE Reed rept per 10CFR2,790
BICKHIT, L Office of the Oeneral Counsel B0/09/11 1p

B010090541 SECY-B0-401A
Recommends that license be issued to GE for export of 639 g
U-235 \$\frac{1}{2}\$\$ 2 g Pu, contained in 7.864 g U, to Taiwan, Draft
license encl
SHEA.J R Office of International Programs, Director 80/09/18

6010140039 Responds to NRC 800530 ltr requesting meeting to discuss FOIA status of QE Reed Rept Document is protected from disclosure under FOIA due to applicable examptions Arguing against classification as agency record is not practical. BHENEFIELDE.J H Justice, Dept of, Attorney General's Office. 80/07/09. 309

80:10140073 Responds to FOIA request for three 8ECY papers listed in bibliography of NUREG-0625, "Rept of Siting Policy Task Force" Documents are available in PDR FELTON, J. M Division of Rules and Records. 80/10/03 ip

--8010140091 SECY-78-163
Revises SECY-77-433, "Policy Statement on Alternative Site Evaluations Under NEPA for Nuclear Generating Stations."
Recommends that Commission require review & approval of sits selection prior to acceptance of CP application MINOOUE, R 3 Office of Standards Development, Birector 78/03/20 SSpp

--8010140093 "Presentation of Alternative Decision Std for Evaluation of Alternative Sites "Supporting documentation encl OTT,W R Sit & Environ Stds Br (formerly Environ Prot. Stds Br.) 78/03/20 43pp

8010210175 Responds to FQIA request for SECY-80-336 & LV Nosenza 800506 memo to JR Shee Forwards documents FELTON.J N Division of Rules and Records 80/10/10 lp

--8010210189 SECY-80-335

Discusses Commission review of Hestinghouse application for litense to export two reactors to Korea Racommends that Commission authorize issuance of License XR-033 to Hestinghouse BHEA.J R Office of International Programs, Director 80/07/21

--8010210195 Requests that NRC issue license to Westinghouse to export two reactors to Korsa. Delay in license issuance could peopardize contract 3 could negatively impact future contracts Draft licenses and HERBCH.M M. Westinghouse Electric Corp. 80/03/28 4pp

8010210183 FOIA request for SECY-80-336 & LV Nosenzo B00506 memo to JR Shea NERENBERO, A L Center for Development Policy 80/09/25 19

8010230082 SECY-80-439
Waskly info rept for wh ending 800912
REPM-T A Office of the Executive Director for Operations
80/09/19 30pp

8010240337 Brief re intervenors 8 Sholly & BE Hossler & Paople Against Nuclear Energy petitions for review of NRC authority to make license amends effective until completion of adjudicatory hearings Certificate of Suc encl. MOGRHAN, J W Justice, Dept of, Attorney General's Office 80-1783 80/08/29, 27pp

--8010240344 Brief in response to DOJ decision disclaiming NRC authority to make license amends effective until completion of adjudicatory hearings intervenors petitions for review should be denied Certificate of Svc encl
BICKHIT.L. Office of the General Counsel 80-1783 80/08/29

8010240462 Transcript of 801016 Affirmative Session 80-45 in Washington DC to discuss SECY-A-BO-108 Pp 1-5 Commissioners 80/10/16 5pp

8010270051 Notifies that Commission has approved recommendation to authorize General Counsel to take action to recover licensing review fees for denied withdrawn, suspended or postponed application reviews
MOYLE.J C Office of the Secretary of the Commission 80/09/04

8010280492 BECY-8D-451
Informs Commission of Executive Branch response on pending
Transnuclar.Inc license application to export high enriched
U to Hast Germany
SHEA.J.R Office of International Programs, Director, 80/10/01

STATE PROD STATE PROGRAMS

8010010165 Informs of review of math re license renewal at Beatty low level waste burial site Math does not present any significant new info re RB Smith 800703 memorandum Table outlining major concerns re site stabilization encl SHITH.R D. Low Level Waste Licensing Branch. 80/08/08 Gpp

--B010010173 Ack receipt of addl info & errata re Nuclear Engineering Co.
Inc application for license renewal Preacceptance review has
been forwarded to NV
KERR, G I: Assistant Director for State Agreements Programs,
B0/07/22 130pp.

- 8010010273 Notification of contract execution Mod 2 to "State Transportation Surveillance Program" Contractor.SC Dept of Health & Environ Control FLYNN, Administrative Contracts Branch, FIN 8-1612 NRC-06-78-357 80/09/18 1p.
- --8010010282 Mod 2, extending period of performance for addity & increasing total amount of contract by \$15.000 to "State Transportation Burveillance Program"

 DANTZLER, H U South Carolina, State of MATTIA, M J.
 Administrative Contracts Branch SANTMAN, L D

 Transportation, Dept of FIN 8-1612 NRC-06-78-357, 80/09/18
- 8010010288 Notification of contract execution. Mod 7 to "Coordination of Federal/Btate Radiation Control Activities & Assistance in Bolving Radiation Control Programs." Contractor Food & Drug Administration-Public Health Svc FLYNN. M. Administrative Contracts Branch FIN 8-1620 NRC-06-76-247. 80/09/18 1p
- --8010010295 Hod 7, increasing funds by add1 \$12,000 to "Coordination of Faderal/State Radiation Control Activities & Assistance in Bolving Radiation Control Problems,"
 GROWN.H. M. HEW, Dept of, Food & Drug Administration MATTIA, M. J. Administrative Contracts Branch FIN E-1620 NRC-06-76-247, B0/09/18 14.
- 8010020008 PNA-80-83A:on 800918, event mistitled "Medical Misadministration." Ofc of 8tds Development advises that event involved improperly prepared pharmaceutical Reporting requirements become efective 801010.
 KERR.O.W. Assistant Director for State Agreements Programs MCGRATH.J R Office of State Programs. Director. 80/09/19 ip
- 8010020011 PNA-BO-34.on 800917, liquid raffinate line leading to evaporation pond broke at Union Carbide Uravan U Hill Cause not stated Line was shut upon discovery & immediate cleanup started, KERR-0.U Assistant Director for State Agreements Programs KENDIO.U.F Office of State Programs, Director 80/09/19. Ip
- 8010020114 PNA-RO-31 on 800911. HA PIRO held press conference, calling for NRG & Congressional investigation on alleged inability of State of MA to monitor environ & contain redicactive releases at Western Nuclear & Daum Hining U mills KERR. Q. V. KENDIG. J. Office of State Programs, Director 80/09/12, 200.
- 8010020185 Advises that state program for control of agreement matle is compatible w/NRC guidelines. Action should be initiated to upgrade Kaman Sciences Corp & Jay Mfg Co licenses. Previous NRC comments encl. KERR: 0 W Assistant Director for State Agreements Programs. 80/09/08. 7pp
- 8010020248 Notification of contract execution: "State Transportation Surveillance Program," awarded to NV Dept of Human Resources.
 FLYNN.M.J. Administrative Contracts Branch FIN B-1327.
 NRG-06-80-680. 80/09/18. 1p.
- --8010020255 Contract: "State Transportation Surveillance Program," awarded to NV Dept of Human Resources.

 CARR.J. H. New York, State of, MATTIA: M. J. Administrative Contracts Branch BANTMAN, L. D. Transportation, Dept. of FIN B-1327. NRC-06-80-680 80/09/18. 89pp.
- 8010020711 Notification of contract execution "Btate Transportation Burveillance Program," awarded to Btate of NV Dept of Human Resources. FLYNN.H.U. Administrative Contracts Branch FIN 8-1327 NRC-06-80-680. 80/09/18, ip.
- --B010020716 Contract: "Btate Transportation Burveillance Program." awarded to State of NV Dept of Human Resources CARR.J. Nevada, State of. MATTIA.M.J. Administrative Contracts Branch. SANTMAN.L.D Transportation. Dept. of FIN E-1027 NRC-06-80-680. 80/09/18. 100pp.
- 8010060060 Bubmits NRC review re final tailings mgt proposal in response to CO Dept of Health 800811 request, Recommends licensing w/condition that later changes may be required to meet final rules.

 8CARAND.R.A. Uranium Recovery Licensing Branch. 80/09/22, 2pp.
- 8010070541 Responds to 900826 itr requesting assistance in resolving problem re reducate shipment ineps conducted at Chem-Nuclear Bys, Inc in Smelling, 80; New enforcement policy will be published in FR.
 O'RETILLY, J. P. Region 2: Atlanta: Office of the Director. 80/09/82, 28s.

- 8010090036 Natification of contract exacution "Cytogenatic Studies in Orand Junction.CD," awarded to CO Dept of Health GUSTAVER, Research Contracts Branch FIN B-71020 NRC-01-80-022 8D/09/23 1p
- --8010070044 Contract "Cytogenetic Studies in Grand Junction,CO," awarded to CO Dept of Health TRAYLOR,F A Colorado, State of MORTON,K V Research Contracts Branch FIN B-71020 NRC-01-80-022 80/07/23 App
- 8D10090049 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/State of NJ " Contractor State of NJ BAISDEN.L Research Contracts Branch FIN 8-5108 NRC-05-80-270 80/01/01 1p
- --8010070052 Mod 1.reducing contract amount & providing new monitoring schedule for Squibb facility, to "Environ Monitoring Program W/State of NJ" FIHER, E J. New Jersey, State of MORTON, K V Research Contracts Branch FIN 8-5108 NRC-05-80-270 80/01/01. 3pp
- B010090523 PNA-80-035 on 800917, State of CO informed NRC of pending release of CO Bureau of Investigation rept critical of Cotter Corp & CO health dept Findings indicate manipulated data & deficient radiation control program Rept requested KERR, O. W. Office of State Programs, Director, 80/09/22 2pp
- 8010100172 Forwards 800731 NRC/DDT review & prospectus of joint contractual program whereby states undertake surveillance of radioactive matl transportation within respective jurisdictions Response requested W/o encl DIRCKS-N U Office of the Executive Director for Operations 80/09/18 3pp.
- 8010140226 Notification of contract execution "Environ Monitoring Program U/BEate of MD," awarded to State of MD BAISDEN, L Research Contracts Branch FIN B-5106. NRC-05-80-269 80/09/09 tp
- ---8010140230 Contract: "Environ Monitoring Program W/State of MD," awarded to State of MD
 BUCK.C P Maryland. State of KORTON.K V Research Contracts
 Branch. FIN B-5106 NRC-05-80-269 80/09/09 14pp
- 8010160006 Confirms discussion re hRC review of state program for regulation of agreement matl Requests written response re agreement program staffing KERR.G.N Assistant Director for State Agreements Programs 80/09/26 2pp
- --8010160007 Confirms comments re NRC review of radiation control program Requests receipt of new or amended permits on quarterly basis Formal documentation of application & calibr of instruments should be continued. Info notice encl KERR, O N Assistant Director for State Agreements Programs 80/09/26 6pp
- 8010160091 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/State of CT " Contractor State of CT. BAISDEN.L. Research Contracts Branch FIN B-5115 NRC-05-80-276 80/09/29, ip.
- --8010160141 Mod 1, providing funding for 1980, to "Environ Monitoring Program W/State of CT" " Gonnacticut. State of MORTON, K V Research Contracts Branch. FIN 8-5115 NRC-05-80-276 80/09/29 1p
- 8010160102 Notification of contract execution.Mod 2 to "Environ Monitoring Program W/Bitate of NJ." Contractor:State of NJ. 8A180EN.L Research Contracts Branch. FIN 8-5108 NRC-05-80-270 80/09/26. ip.
- --8010160144 Mod 2, extending funding for 1980, to "Environ Monitoring Program M/State of NJ" f New Jersey, State of MORTON, K V Research Contracts Branch FIN 8-5108. NRC-03-80-270. 80/09/26. 1p
- 8010160105 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/State of SC." Contractor, State of SC BAISDEN, L. Research Contracts Branch. FIN 8-1112, NRC-05-80-27J. 80/09729, 1p.
- --8010160149 Mod i,increasing amount of funding for 1980, to "Environ Monitoring Program W/State of 80,"

 * South Carolina, State of, MORTON, K. V. Research Contracts Branch. FIN 8-1112. NRC-05-80-273. 80/09/29, ip.

- B010160109 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/State of ME" Contractor State of ME BAIBDEN.L Research Contracts Branch FIN B-5113 NRC-05-80-274 80/09/29 ip
- --B010160152 Mod i.extending funding for 1980, to "Environ Monitoring Program W/State of ME" # Haine: State of MORTON, K V Research Contracts Branch FIN 8-5113 NRC-05-80-274 80/09/29 ip
- 8010160112 Notification of contract execution. Hod 1 to "Environ Monitoring Program W/State of NY" Contractor State of NY BAIBDENL Research Contracts Branch FIN B-5109 NRC-05-80-271 80/09/29, 1p
- --B010160156 Med 1. providing funding for 1980, to "Environ Manitoring Program W/State of MY "

 * New York, State of MORTON, K V Research Contracts Branch
 FIN B-5107 NRC-05-80-271 80/09/29 1p
- 8010160116 Notification of contract execution, Mod i to "Environ Monitoring Program W/State of MD" Contractor State of MD, BAIBBENL Research Contracts Branch FIN 8-5106, NRC-05-80-269,
- --8010160159 Mod 1.providing funding for 1980.to "Environ Munitoring Program W/State of MD." * Maryland, State of MORTON,K V Research Contracts Branch FIN 8-5106. NRG-05-80-269 80/09/29 1p
- 8010160132 Notification of contract execution. Mod 1 to "Environ Monitoring Program H/State of CO " Contractor State of CO BAIBDEN.L Research Contracts Branch, FIN 8-5104 NRC-05-80-267 80/09/29, 1p.
- --B010160162 Mod 1, providing funding for 1980, to "Environ Manitoring Program W/State of CO "

 + Colorado, State of MORTON, K. V. Research Contracts Branch. FIN 8-5104 NRC-05-80-227 80/09/29, 1p.
- 8010160125 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/State of CA " Contractor State of CA BAISDENIL Research Contracts Branch FIN 8-5109 NRC-05-80-266 80/09/29 ip
- ---B010160167 Mod 1.providing funding for 1980, to "Environ Monitoring Program W/8tate of CA"

 * California, State of MORTON, K V Research Contracts Branch PIN 2-5103 NRC-05-80-266 B0/09/29, ip
- 8010160127 Notification of contract execution, Mod 1 to "Environ Monitoring Program H/State of AL " Contractor State of AL BAIBDENL Research Contracts Branch FIN 8-1233 NRC-05-80-255 80/09/29 1p.
- --8010160170 Mod 1.providing funding for 1980.to "Environ Monitoring Program M/8tate of AL." Alabama. Btate of MORTON, K. V. Research Contracts Branch. FIN 8-1293 NRC-05-80-255. 80/09/29 lp.
- 8010180132 Notification of contract execution, Mod 1 to "Environ Manitoring Program W/Commonwealth of PA" Contractor: Commonwealth of PA. BAKSDENIL. Research Contracts Branch. FIN B-511! NRC-05-B0-272, B0/09/29. 19
- --8010160173 Mod 1, providing funding for 1980, to "Environ Monitoring Program M/Commonwealth of PA"

 * Pennsylvania, State of FIN B-5111, NRC-05-80-272, 80/09/29,
- B010140135 Natification of contract execution "Environ Monitoring Program W/Btate of DE." awarded to State of DE. BAISDENIL. Research Contracts Branch. FIN 8-1260. NRC-05-80-291. 80/09/29. 1p
- --8010160176 Contract: "Environ Monitoring Program W/State of DE,"
 awarded to State of DE
 WILSON, J. E. Delaware, State of, MORTON, K.V. Research Contracts
 Branch, FIN 8-1260 NRC-03-80-291, 80/09/29, 11pp.
- 8010140339 Notification of contract execution.Mod 1 to "Environ Monitoring Program W/8tate of OR." Contractor.State of OR BAISDENL. Research Contracts Branch. FIN 8-5200, NRC-05-80-278. 80/09/29 ip.

- --8010160342 Mod 1, providing funding for 1980, to "Environ Monitoring Program W/State of OR" Dragon, State of MORTON, K V Research Contracts Branch FIN 8-5200 NRC-05-80-278 80/09/29 ip.
- 8010170254 PNA-80-32 on 500916, state agreement program personnel were notified of State of TX investigation into info supplied by anonymous telephone caller about Nuclear Diagnostic Lebs violations re prescribed doses. Hearing set for 801014 KERR.04 H, 80LLING.L.A Office of State Programs, Director 80/09/17 19
- 8010170368 Natification of contract execution: "Environ Monitoring W/ State of NG." ewarded to State of NC Dept of Human Resources
 BAIBDEN.L Research Contracts Branch FIN B-1239 NRC-05-80-283.
 80/09/24 ip.
- --8010170371 Contract. "Environ Monitoring Program W/Btate of NC,"
 awarded to Btate of NC Dept of Human Resources
 WILKERSON, I O North Carolina, Btate of MORTON, K. V Research
 Contracts Brench, FIN B-1237, NRC-03-80-283 80/09/24 9pp.
- B010170377 Notification of contract execution: "Environ Monitoring Program W/Btate of MN," awarded to Btate of MN Dept of Health. Mealeben,L. Research Contracte Branch FIN 8-1252, NRC-05-80-288 80/09/24, 1p.
- --80101703B0 Contract: "Environ Monitoring Program 4/Btate of MN," awarded to State of MN Dept of Health PETTERBON.O.R. Minnesota: State of. MORTON.K V. Research Contracts Branch. FIN 8-1252 NRC-05-80-288. 80/09/24. 9pp
- 8010170383 Notification of contract execution, Mod 1 to "Environ Monitoring Program W/State of QA" Contractor, State of QA. BAIBDENL Research Contracts Branch. FIN 8-5203. NRC-05-80-279.
- --8010170393 Mod 1, providing funding for 1980 effort, to "Environ Monitoring Program M/State of QA" " Georgie, State of. MORTON.K V. Research Contracts Branch. PIN B-5203 NRC-05-80-279 80/09/29 ip
- 8010170447 Notification of contract execution. Mod 1 to "Environ Monitoring Program W/State of AR." Contractor State of AR. BAISDEN.L. Research Contracts Branch. FIN 8-5207 NRC-05-80-280 80/09/29 ip
- --8010170432 Mod 1, providing funding for 1980 effort, to "Environ Monitoring Program W/State of AR."

 4 Arkansas, State of MORTON, K V Research Contracts Branch FIN 8-5207 NRC-05-80-280, 80/09/29, 1p
- 8010170574 Notification of contract execution: "State Legislative Reporting Svcs." awarded to Federal-State Repts.Inc. FLYNN,N.J. Administrative Contracts Branch. FIN 8-1592. NRC-04-80-681. 80/09/30. 1p
- ---8010170580 Contract "State Legislative Reporting Svcs." awarded to Federal-State Repts. Inc. # Federal-State Reports. Inc. MATTIA:M J Administrative Contracts Stanch. FIN 9-1592. NRC-06-80-681. 80/09/30 70pp.
- 8010200070 "Point Lepreau Canada Nuclear Generating Station Offsite Emergency Plan " LANOTON, J. P. Canada, 79/12/31 45pp
- 8010200242 Notification of contract execution, Mod 1 to "Environ Monitoring Program H/Commonwealth of VA." Contractor: Commonwealth of VA BAISDENIL. Research Contracts Branch. FIN B-5116, NRC-05-80-277, 80/09/27.
- --8010200230 Mod 3, providing funding for 1980, to "Environ Monitoring Program M/Commonwealth of VA."
 4 Virginia, Btate of. MGRTON, K.V. Research Contracts Branch.
 FIN 8-5116 NRC-05-80-277. 80/09/29. 1p.
- 8010200307 Notification of contract execution. Mod 1 to "Environ Monitoring Program W/State of TN." Contractor: State of TN. BAISDEN.L. Research Contracto Branch. FIN 8-5208. NRC-05-80-281. 80/09/27. ip
- --8010200319 Mod 1,groviding funding for 1980, to "Environ Monitoring Program M/State of TN."

 * Tennessee, State of. MORTON, K. V. Research Contracts Branch, FIN 8-5208. NRC-05-80-281. 80/09/29. ip.

- 8010200654 Notification of contract execution, Mod 3 to "State Transportation Burveillance Program" Contractor State of HA MARTIN, L. C. Administrative Contracts Branch FIN 8-1612 NRC-06-79-303 80/09/30 ip
- --8010200660 Mud 3.adding to scope of work & increasing funds, to "State Transportation Surveillance Program " BEARE, J A Washington, State of MATTIA, M J Administrative Contracts Branch NRC-06-79-305 B0/09/30 3pp
- 8010210098 Notification of contract execution, Mod 4 to "State Transportation Burveillance" Contractor State of MI MARTIN.L.C Administrative Contracts Branch FIN B-1612 NRC-06-77-051 80/09/30, ip
- --8010210105 Mod 4.extending period of performance & adding funds to
 "State Transportation Surveillance"
 REIZEN.M 8 Michigan. State of MATTIA.M J Administrative
 Contracts Branch Fin 8-1612 NRC-06-77-051 80/09/30 3pp
- 8010210275 Responds to 800702 ltr re NRC review of Bureau for Radiation Control Licensing & insp guidelines implemented Clerk assigned to agreement program & personnel have enrolled in NRC training courses New lab supplies ordered SOLON,L R New York.NY 80/09/02 2pp
- 8010210632 Responds to 800508 ltr requesting partial funding for State of NY radiological health program Authority does not exist under Atomic Energy Act to provide operating funds to states Model state legislation for fees enci
 KERR, G W Office of State Programs. Director 80/10/01 12pp
- ~-BOIORIOGED Discusses NRC audit of radiological health program for State of NY Dept of Labor & requests partial federal funding for program continuation RGSs.P. New York, State of 80/05/08 2pg
- 8010210789 Responds to NRC 800807 itr re radiation control program review Regulations for agreement matls are undergoing revision Schedule was established for periodic review & updating regulations
 EDMARDS, U Georgia, State of 80/08/28 2pp
- MULUMBULA NURED/CR-1671
 "Transportation of Radioactive Matl in KY Oct 1978—
 Dec 1977 "
 * Kantucky, State of NRC-06-78-359 80/09/30. 53pp Available at 0PD
- 8010230122 Responds to NRC 800702 ltr re review of radiation control program for NY City Dept of Health Corrective actions position description for radioactive matls personnel & guidelines re documentation of insps revised FERRER, R A. New York, NY 80/07/03 ip
- 801024060B Notification of contract execution.Mod 1 to "Environ Monitoring Program W/Commonwealth of MA" Contractor Commonwealth of MA BAISBENL Research Contracts Branch FIN B-1247 NRC-05-80-286 80/10/14 1p
- --8010240614 Mod 1:adding modified environ monitoring program to
 "Environ Monitoring Program W/Commonwealth of HA"
 FRECHETTE:A L Massachusetts, State of. MORTON, K V Research
 Contracts Branch. FIN B-1249 NRC-03-80-286 80/10/14 9pp
- 8010270341 PNA-80-36A on 800320,0fc of State Programs notified by Region 2 that president of Intl Chemical Workers Union had filed formal complaint w/OSHA re radiation safety at New Males Div.Intl Minerals Corp. Mulberry.FL.
 KERR.O. W. BOLLING.L A Office of State Programs, Director 80/10/21. ip
- B010290096 Discusses B00923 meeting re state program for regulation of agreement matls. Confirms understanding that NY Dept of Health will provide resources to address deficiencies noted in NR B00906 ltr.
 KERR. O. W. Office of State Programs. Director. B0/10/10 2pp
- --8010290104 Responds to 800815 ltr Forwards ltr addressing outcome of 800923 meeting w/NY State officials. Requests response to 800730 ltr KERR, 0 W Assistant Director for State Agreements Programs, 80/10/10. ip.
- --8010270111 Confirms discussion re results of NRC partial review of Dept of Health program for regulation of agreement matis. Recommends filling of vacant positions, reduction of overdue insps & implementation of four items from previous review KERR, G. W. Office of State Programs, Director 80/08/06. 2pp

- --8010270117 Confirms 800718 dicussion re results of NRC partial review & evaluation of radiation control program Forwards recommedations re technical aspects of agreement matl program, Requests comment KERR,0 II Assistant Director for State Agreements Programs 80/07/30 5pp
- --B010290127 Ack notification of NRC insp of state program for regulation of agreement matis & expresses need for federal revenues to continue
 AKELROD.D. New York, State of 80/09/03 ip
- 8010290130 "Info Rept on State Legislation." Vol 6, Number 11 RYAN,R 0 Office of State Programs, Director 80/08/16 4pp
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8010200175 Notification of 801002 meeting w/Westinghouse in Nashington, DC to discuss applicability of low blockage tests to ECCS models LAUERN, C. N. Reactor Systems Branch, 80/09/26 2pp
- 8005220571 Forwards CE-1-A, "GA Program for Nuclear Generating Stations," Revision 12.Page 1-7 PEOPLES,D L Commonwealth Edison Co 80/05/19 2pp
- --8010160416 CE-1-A R12
 "QA Program for Nuclear Congrating Stations," Revision 12
 * Commonwealth Edison Co 80/02/04 1p
- 8007310256 Notification of 800730-31 meetings w/vendors & consultants in Bar Joss CA to discuss Mark III LOCA-related pool dynamic load criteria FIELDS:H Containment Systems Branch 80/07/21 4pp
- 8009030499 Forwards proprietary & nonproprietary responses to NRC Request 2 for add1 info on WCAP-9300 Proprietary version withheld (ref 10CFR2 790) Application & affidavit for withholding encl.
 ANDERSON, T M Westinghouse Electric Corp NS-TMA-2295 BO/08/27, 2200
- 8007220143 DNS-R6S-001-NP-A "Dow Eys for Solidification of Low Level Radwaste from Nuclear Power Plants," nonproprietary version "Dow Chemical Co 80/04/30 178pp
- 8007260121 Forwards "8td Terms & Conditions for Purchase Orders & Bubcontracts" Ltr & rept sent to all subcontractors & suppliers of company KENT,L.H EG&O Idaho, Inc 80/08/01 ip
- --8009260126 "Btd Terms & Conditions for Purchase Orders & Subcontracts " * E0&G Idaho. Inc 80/07/31 31pp
- 8010010338 Advises that topical repts listed in encl have been determined to be proprietary & will be withheld (ref 10CFR2 770) Nonproprietary versions have been placed in PDR EIBENHUT,D O Division of Licensing 80/09/15 4pp
- 8010010552 Forwards proprietary & nonproprietary "WEQAP Verification W/NRC Sample Problems," App A to WCAP-9401 & application & affidavit re withholding (ref iOCFR2 790) Submittal should not adversely affect NRC review schedule for rept ANDERSON, T. M Westinghouse Electric Corp NB-TMA-2310 80/09/17 11pp
- --801001055B WCAP-9401
 Nonproprietary "WEGAP Verification W/NRC Sample Problems,"
 App A to WCAP-9401/9402, "Verification Testing & Analysis of
 Hestinghouse 17:17 Optimized Fuel Assembly "
 * Westinghouse Electric Corp 80/09/17 34pp
- B010010374 Forwards Revision 2 to Suppl 1 of WCAP-8387, "Equipment Qualification Data Packages." Revision supercedes Revision 1 submitted on 781115
 ANDERSON, T. M. Westinghouse Electric Corp. N8-TMA-2289 80/08/14
- --8010010377 WCAP-8587 SI R2
 "Equipment Qualification Data Packages," Supp 1.Revision 2
 * Westinghouse Electric Corp 80/08/14. 23pp

- 8010020320 Forwards Apps A & B re upper head injection suftware technology & requests gameric approval be granted to appropriate portion of WcAP-9528 for use on all Westinghouse designed MSSS Info withheld (ref 10CFR2 790)
 ANDERSON.T M Westinghouse Electric Corp NB-TMA-2311 80/09/15
 2pp
- 8010020335 Forwards "Mark II Improved Chugging Methodology " BUCHHOLZ.R H General Electric Co BUCHHOLZ.R H General Electric Operating Plant Duners Group MFN-160-80 80/09/12 ip
- ---8010020339 NEDO-24822

 "Mark II Improved Chugging Methodology "

 KUZZY,R J , TOWNSEND,H E , IANNI,P W General Electric Co
 80NEDD49 80706/30 R03pp
- B010020499 NEDE-24011-L-A ADD B
 Errata & Addenda B to NEDE-24011-1-A. "Generic Fuel Reload
 Application " Document should replace incorrect Jul 1980
 submittal
 a General Electric Co 80/07/31 2pp
- 80:0020641 Ack receipt of 800827 ltr providing info re organizational changes in OA Topical Rept. HCAP-8370. Revision 9A Changes described acceptable
 MAASS, M P Guality Assurance Branch 80/09/12 ip.
- 8010030423 Forwards proposed Revision 6.Draft 7 of Topical Rept SL-TR-IA for NRC review Detailed summary of proposed changes enci HCFARLAND, J E Sargent & Lundy, Inc. 80/09/29 17pp
- --B010030427 BL-TR-iA DRFT 7 R6 QA program topical rept for safety-related structures, sys & components.Draft 7. Revision 6 * Bargent & Lundy, Inc 80/09/29 75pp.
- B010030464 Forwards evaluation of proposed mod to HPC1 & reactor core isolation cooling sys on behalf of BUR owners group per NUREQ-0660 Recommends no change in HPC1 setpoints
 BUCHHDLZ,R H General Electric Co MFN-167-BO B0/10/01 Spp
- 8010030482 Discusses Desrasiers attendance at IAEA conference in 8tockholm,8W & NRC funding of costs GRIMES,8 K Emergency Preparedness Program Office 80/09/18 1p.
- 8010060255 Forwards info resulting from review of nine potential sefety concerns since Aug 1977 processed by B&W under 10CFR50 58(e) in response to NRC request TAYLOR, J H Babcock & Wilcox Co 80/09/26 23pp
- B010070275 Forwards add1 info re NEDD-24259, "Generic Info for Barrier Fuel Demonstration Bundle Licensing," per NRC request Approval of rept requested by 801007 ENGEL.R.E. General Electric Co REE-062-80 80/10/02 3pp
- 8010070302 Forwards comments on draft rept NUREO/CR-1580 "Human Engineering Quide to Control Room Evaluation " Rept unduly slanted toward serospace & military practices not widely used in util industry OETTLER, F Q Qibbs & Hill, Inc. (subs of Dravo Corp.) 80/09/29, 900
- 8010070434 Forwards revisions to GA manual CARPENTER,F.D General Atomic Co (subs. of Qulf Dil Co) 80/09/30 ip
- --B010070435 Revisions to GA manual for table of contents, GP-1
 "Organization" & Addendum 1
 * Oeneral Atomic Co (subs of Quif Qil Co) 80/09/30 27pp.
- 8010070589 Responds to NRC 800705 request for outline of work schedule for revising App K small break LUCA analysis model Recommends application of new computer code for model development program ANDERSON, T. M Westinghouse Electric Corp N8-TMA-2318 80/09/26, App
- B010070391 Confirms B00929 telcon re IRC review of Rept B0-67459 Equipment is scheduled for installation in licensed power plant, Expeditious review would prevent delays or possible cancellation, MAJOR, J H Otto H, York Co. Inc B0/10/01 1p.
- 8010090237 Forwards three nonproprietary repts re methodology for BHRs ECCS evaluation model summary description, thermal hydraulics & critical power DMSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 0F0.142:80. 80/10/03. 1p.

- ---8010090241 XN-NF-B0-19(NP) V2
 Vol 2.nonproprietary version of "EXXON Nuclear Methodology
 for BWRs ~ EXEM.ECCS Evaluation Model Summary Description "
 CDLLINOHAM.R E. MORGAN.J N. SOFER.O A. Exxon Nuclear Co., Inc
 (subs of Exxon Corp.) 80/09/26 56pp
- --B010090246 XN-NF-B0-19(NP) V3
 Vol 3:nonproprietary version of "EXXON Nuclear Methodology for BMRs Thermal Hydraulics"
 KRY93NBK1.TL , MDR6NN.J N , BDFER, O A Exxon Nuclear Cb , Inc (subs of Exxon Corp) BD/09/26 46pp
- --8010090250 XN-NF-524(NP)

 "EXXON Nuclear Critical Power Methodology for BURs "
 PATTEN,T W, MOROAN,J N , SGPER,O A Exton Nuclear Co . Inc
 (subs of Exxon Corp.) 80/09/26, 33pp
- 8010100275 Approves of Revision 2 to NEDO-11209-04A. "Nuclear Energy Business Group BMR GA Program Description " Rept reflects organizational changes & alternate position to Reg Guide 1 123 HAABS.W P Guality Assurance Branch 80/09/27 1p
- 8010100312 Forwards nonproprietary version of NEDD-24794, "Dynamic Lateral Loads on Mark II Main Vent Downcomer - Correlation of Independent Ref Data" 8UCHHOLLR H General Electric Co MFN-159-80, 80/09/17 ip
- --8010100318 NEDO-24794
 Nonproprietary version of "Dynamic Lateral Loads on Mark II Main Vent Downcomer Correlation of Independent Ref Data "BORHAUG, J E. Pretech, Inc. MUZZY, R J , IANNI, P. W. General Electric Co. BONEDO98 80/08/31 51pp
- 8010100332 Forwards nonproprietary response re NRC request for info on ODYN computer model BUCHHOLZ:R H General Stactric Co MFN 173-80 E0/10/03. 49pp
- 8010100355 Notifies of change in analysis methods. Reload license submittals & safety analysis repts initiated after early 1981 will use three dimensional BMR stimulator code for analysis of loss of feedwater heating transient ENOEL, R.E. General Electric Co. MFN-168-80 80/07/30. 2pp
- 8010140143 Informs of BLW fee payment for review of Revision 3, "B&W NPOD GA Program for Nuclear Equipment"
 DIGOB,R M License Fee Management Branch 80/09/30, 1g
- 8010140276 Responds to NRC 800527 request for add1 info re XN-76-47, "Combined Seismic LOCA Muchanical Evaluation for Exxon Nuclear 13715 Reload Fuel for Westinghouse PWRs " Drawing withheld (ref 10CFR2 770) Affidavit encl OWELEY.O.F Exxon Nuclear Co . Inc. (subs of Exxon Corp). OFO.141.80 80/09/30. 14pp
- 8010140321 Comments on draft NRC position on Item I C i, "Quidance for Evaluation & Development of Procedures for Transtents & Accidents," in response to NRC 800909 ltr All requirements met & all info submitted or will be submitted shortly, JUROENSEN, R W. Nestinghouse Operating Plants Queers Group, DG-42 80/10/08, 3as
- B010150143 Summary of B00B2B & 29 meeting w/BNL re progress on physics technical assistance program Topic outline encl DUNENFELD: M Core Performance Branch 80/09/29. Upp.
- B010150144 Ack receipt of B00827 ltr re organizational changes in GA program described in B&W-10096A, Revision 3 Changes acceptable, HA885 W P Guality Assurance Brench B0/09/10. 1p.
- 8010150252 Forwards NEDE-25289-1-P. "Comparison of Single & Multivent Chugging - Phase 2 " Rept withheld (ref 10CFR2 790) BUCHHOLZ, R H General Electric Co RHB-76-80, 80/09/17 ipp.
- 8010150472 Forwards Revision 1 of: "Standardized Review Plan for Safe Shutdown Projects:" in response to NRC 800911 request. Includes expanded generic equipment listing for PMR & BWR HALL: R. Brockhaven National Laboratory 80/09/23. 1p
- --80101504BO Revision 1, "Standardized Review Plan for Safe Shutdown Projects." * Brookhaven National Laboratory 80/09/22, 12pg.
- B010150514 Responds to NRC B00909 ltm re instrumentation for detection of inadequate core cooling in PWRs NRC position inconsistent u/previous stance indication of inadequate core cooling assured w/thermocouple systemedous & saturation indicators TAYLOR:J H Babcock & Wilcox Co. 80/10/07 Spp.

- 8010150644 Discusses 800819-20 meeting re BWR scram sys & suggests safety sys be evaluated for possible interfacing w/nonsafety sys to eliminate problems resulting in scram sys failures CATTON-1 ACRS Advisory Committee on Reactor Safeguards 80/09/13 2pp
- BOIO160517 Forwards proprietary & nonproprietary versions of "Analytical Investigation of Detailed Behavior of Fluid in Steam Generator Tubes Under Two-Phase Natural Circulation Conditions "Application for withholding & affidavit encl JURGEMBEN R W, Westinghouse Operating Plants Guners Group GO-43 BO/10/13 11pp
- --8010140526 WCAP-972:
 Nonproprietary version of "Analytical Investigation of Datailed Behavior of Fluid in Steem Generator Tubes Under Two-Phase Natural Circulation Conditions"
 ANDERSON, T M , KELLY, R D Westinghouse Electric Corp 80/07/31
- 8010160950 Summarizes results of 800930 masting in Bathesda, MD re ODYN review NRC should formally notify utils about DDYN implementation requirement to insure successful & timely transition BUCHHOLZ, R H General Electric Co MFN-176-80 80/10/09 2pp
- 80i0160561 Forwards errata to NEDE-24822-P. "Mark II Improved Chugging Methodology." on behalf of Mark II owners group.as part of containment program Errata includes editorial corrections info withheld (ref 10CFR2 790)
 BUCHHOLZ:R H General Electric Co MFN-161-80 80/09/26 ip
- B010160640 Forwards revised "Performance Tests & Engineering Evaluation of Fox-Howlett No-Blip Couplers for Reinforcing Steel Bars "
 Low temp tests added to Oct 1978 rept Matl & test results are unchanged from Nov 1976
 DREUBERT, J R Fox Industries 80/10/07 ip
- --8010160645 Revised "Performance Tests & Engineering Evaluation of Fox-Howlett No-Slip Couplers for Reinforcing Steel Bars " * Fox Industries 78/10/31 194pp
- 8010200427 Forwards corrected Page 4 to administrative manual policies & procedures.NPG-1707-01.Revision 9 Corrections consist of renumbering flow sheet steps to correspond w/steps on previous page
 TAYLOR.J H Bapcock & Wilcox Co BO/10/13 Ip
- --B010200428 Administrative manual policies & procedures.NPO-1707-01. Revision 9.corrected Page 4 * Babcock & Wilcox Co 80/10/13 1p
- 8010210115 Summary of 800919 meeting u/util re proposed criteria that util form basis for future plant-specific mods to BWR scram sys in operating plants
 HANNON, U R Operating Reactors Branch 3 80/10/01 App
- 8010210332 Forwards errata to NEDO-24822. "Mark II Improved Chugging Methodology," dtd 800912 Major revisions are corrections to Equation 4 32 related figures in rept & editorial corrections
 BUCHHOLZ, R H. Ganeral Electric Co. MFN-165-80 80/10/01. 1p
- --8010210334 NEDO-24822 ERR 1 Errata to NEDD-24822. "Mark II Improved Chugging Mathodology." * Opnoral Electric Co 80/08/31 20pp
- 8010210456 Forwards util interpretation of Operational QA Manual (KPL-TDP-IA)design control policy, in response to NRC 801014 telcon REAVES, T E Mississippi Power & Light Co AECM-80/243 £0/10/15
- 8010210572 Requests approval for use of ABME Code Case N-265 in mfg of Model F steam generator channel head costings.
 ANDERBON, T H Wastinghouse Electric Corp NS-TMA-2321, 80/10/07 fp.
- --B010210662 Topical rept evaluation of B&RCE-COM4-1-NP, Revision 2A,
 "Nuclear GA Manual " Rept acceptable
 + Quality Assurance Branch 80/10/02 2pp.

- B010230399 Forwards proprietary & nonproprietary repts WCAP-9739 & MCAP-9740, respectively, "Summary of Westinghouse Integrated Protection Bys Verification & Validation Program " WCAP-9739 withheld (ref 10CFR2 790) Affidavit and ANDERSON, T M Westinghouse Electric Corp NS-TMA-2307 80/09/18
- --8010230362 WCAP-9740
 Nonproprietary version of "Summary of Westinghouse
 Integrated Protection Sys Verification & Validation
 Program "
 ANDERSON, T M , COOK, B M , GENNARO, D V Nestinghouse Electric Corp
 80/09/30 590pp
- 8010230426 Forwards tables listing environ qualification documentation references for early operating plants & supplemental program plants Qualification references only valid for equipment supplied to plants identified in encl tables ANDERSON, T M Westinghouse Electric Corp NB-YMA-2317 80/10/03
- 801024004B NUREQ-0103 R4
 "STB.Revision 4 for BBW PWRs " Supercedes Revision 3
 4 Office of Nuclear Reactor Regulation, Director 80/09/24 600pp
 Available at GPO
- 8010240422 Informs that RB Kelly has been appointed Vice President & manager of QA; effective 801001; replacing NB Cleveland Correspondence should be forwarded to RB Kelly KELLY, R B Stone & Webster Engineering Corp 80/10/15 ip
- 8010280204 Forwards B&ROE-COM4-1-NP-2A.GA manual Revision 2A is not applicable to any plants
 RAUSCH.W P Burns & Roe Co 80/10/23 .ip
- --8010280208 B&RQE-CCM4-1-NP-2A QA manual * Burns & Roe Co. 80/10/05 77pp
- 8010280323 Forwards draft Revision 9 to ETR-1001.0A program manual Final revision.w/signatures & date,will be forwarded pending receipt of NRC approval TENZER.B E Ebasco Bervices, Inc. (subs of Enserch Corp.) 80/10/22 2pp
- --8010280325 Draft Revision 9 to GA program manual + Ebasco Services, Inc (subs of Enserch Corp) 80/10/22 77pp
- 8010280362 Forwards draft "Senior Reactor Operator Level Instructor Certification Ouide " Review & discussion requested Ouideline based on NUREO-0094 ELLIOTT:N S Babcock & Wilcox Co 80/09/11 ip
- --8010280345 Draft "Senior Reactor Operator Lavel Instructor Certification Guide " * Babcock & Wilcox Co 80/09/11 14pp
- 8010280897 Forwards util press release describing organizational changes which do not affect nuclear projects GA program for design.const & preoperational testing.Applicable changes will be incorporated into Section 1 0.
- B010280268 Submits status repts for Aug 1980 re core melt & seperate effects program
 BERMAN,M Sandia Laboratories 4441/ML-15 80/09/29 12pp
- 8010280676 Notifies that 80-TOP-1. Revision 3A is acceptable. Evaluation encl.
 HAASS.W P. Quality Assurance Branch 80/10/16 ip
- --8010280682 Topical rept evaluation of BG-TOP-1, Revision GA, "GA Prograd for Nuclear Power Plants " Rept acceptable * Quality Assurance Branch 80/10/16 2pp.
- 8010290353 Forwards proprietary & nonproprietary responses to NRC 800802 request for add1 info re WCAP-9500, Section 4 3 & Chapter 16, Affidavit & application for withholding encl. Proprietary responses withheld (ref 100FRZ 790) ANDERSON, T M Westinghouse Electric Corp N8-TMA-2323 80/10/24.
- 8010310396 Forwards proprietary % nonproprietary versions of "C-E NB8S Dwners' Response to NUREO-0460, Vol 4 (Mar 1980) "Affidavit for withholding info (ref IOCFR2, 790) encl, LUNDVALL, A.E. C-E Operating Plants Owners Group 80/10/28, 1pp

1

- --8010310399 CEN-134-NP

 Nonproprietary version of "C-E NSSS Owners' Response to NUREO-0460,001 4 (Mar 1980) "

 * C-E Power Systems 80/10/28 117pp
- WASTE MOT NUCLEAR WASTE MANAGEMENT
- B009100713 CUC-106A
 "Evaluation of Effects of Ceil Excavations on Stability of Ancient Land Slides Hansen Project " Oversize drawing encl
 + W A Wahler & Associates, Inc. 17284 80/08/31 ldpp
- B010010165 Informs of review of matl relicense renewal at Beatty low level waste burial site Matl does not present any significant new info re RD Snith B00703 memorandum Table outlining major concerns re site stabilization encl SMITH.R D Low Level Waste Licensing Branch B0/08/08 3pp
- ---B010010173 Ack receipt of add1 info & errata re Nuclear Engineering Co.
 Inc application for license renewal Preacceptance review has
 been forwarded to NV
 KERR, O W Assistant Director for State Agreements Programs
 E0/07/22 130pp
- B010030105 Requests comments on each tentative outline for U mill tailings remedial action program EIB QROELSEMA,D H Energy, Dept of 17402, 80/08/01 27pp
- 8010030192 Forwards map showing current land ownership in Cottonwood River Ranch subdivision near Hansen Project tailings disposal area Also forwards summary of 800815 meeting w/ Wahler Associates re analysis requested by NRC W/o map THOMPSON. II A Cyprus Mines Corp. 17376 80/08/20 3pp
- E010060060 Submits NRC review re final tailings mgt proposal in response to CD Dept of Health 800811 request Recommends licensing w/condition that later changes may be required to meet final rules SCARANOR A Uranium Recovery Licensing Dranch 80/09/22 2pp
- B010060098 Summary of B00902-05 trips to Rapid City & Edgemont, SD & Danver.CO re Edgemont cleanup action plan HUD requirements for grab-working level protocol & coordination of activities & public info were discussed BCARANO, R A Uranium Recovery Licensing Branch B0/09/12 4pp
- E010100147 Forwards first monthly rept for tailings conditioning program MECI,C Los Alamos Scientific Laboratory LSA-80-348 80/08/18 6pp
- 8010140616 Forwards responses to questions & comments on Hansen project tailings disposal area Thick section of impervious claystone underlies most of proposed tailings disposal site Previous areas of cells proposed to be lined w/3-ft compacted clay THOMPSON. H A Cyprus Mines Corp 17389 80/09/12 11pp
- 8010180081 Forwards info re wind speed & direction frequency distributions by stability class & max tailings areas for three-cell options, in response to 0 Onugnoli request THOMESOW 14 A Cyprus Mines Corp 17362 80/04/16 Spp
- 8010180662 Forwards consultant rept "Site & Lab Investigator & Daffnitive Design Rept.Hansen Project.Tailings Impoundment & Raffinate Pond " W/o encl THOMPSON.11 A Cyrus Mines Corp 17493 80/09/18 1p
- 8010210773 Forwards comments on draft EI8 for mill tailings expansion project Inadequacies include lack of required environ analysis, failure to discuss installation of drainage systunder—pond drain sys & hyperion liner SHITH.A B Environmental Protection Agency 17373 80/09/05. 7pp

- 8010210775 Requests City of Edgement confirmation of agreements reached at 800905 meeting re elevated radon in Edgement homes Escrow account will not be necessary once home has been angineered & approved for romedial action by NRC KRUEDER.J P South Dakota. State of 17388 80/09/05 2pp
- 8010229062 Bummary of 800905 meeting w/BNML, HUD, EPA & city officials in Denver, CD re requirements & sampling protocol of Edgemont cleanup action program EADIE, Q Q Userium Recovery Licensing Branch 80/09/15 3pp
- B010220126 Forwards summary of radiological characterization for property in vicinity of designated inactive U mill tailings site Candidates for remedial action will be designated MOTT:WE Energy, Dept of 17497 80/09/15 4pp
- 8010230169 Notifies that resurveys of schoolyards in area of Edgemont facility have shown an area 20 ft in diameter having U mill tailings to depth of 6 inches Affected area will be fenced to control access

 EADIE: 0 0 Uranium Recovery Licensing Branch 80/10/02 lp
- 8010230379 Forwards draft NRC evaluation of Anaconda Copper Co request for exemption from U Mill Tailings Radiation Control Act land comership requirements re proposed Rhode Ranch project Requests comment W/o encl MILLER.H J Uranium Recovery Licensing Branch 80/10/01 lp
- 8010230537 Forwards revised conceptual const.operation & reclamation sequence for Hansen Project three-cell tailings disposal sys Actual const & operational sequence will be determined during final engineering sys design THOMPEON.M A Cyprus Mines Corp 17472 80/09/23 2pp
- 8010240578 Responds to 800828 ltr requesting info re mill circuit changes, wastes & effluents, environ impacts & risks of hazardous emissions Response to EPA comments on draft EIA & response to NRC environ assessment encl
 THOMPSQN, J E Dawn Mining Co 80/09/18 78pp
- B010270074 Bubmits input in response to 800B21 ltr re 17B0 annual status rept to Congress on 800101-0930 U mill tailings remedial action program
 BCARAND.R A Uranium Recovery Licensing Branch 80/09/17 2pp.
- --BD10270078 Requests input for 1980 annual status rept to Congress on U mill talkings remedial actions program to be submitted on 801001 Executive summary & introduction encl for prompt response
 CAMPBELL, R IS Energy, Dept of 80/08/21 9pp.
- 8010270315 Responds to 800912 ltr requesting concurrence w/screening results of Edgemont cleanup action program Recommendation re-problems caused by natural terrestrial radioactivity not acceptable HANNON, 0 J. Housing & Urban Development, Dept. 06. 17861 B0/09/19 200.
- 80i0270350 Forwards responses to Items 2.3 & 5. requested on pages if & iii of NRC EIA Will undertake field investigation program to obtain undisturbed samples of stiff clay ORONEMYER.E L. Mashington, State of 27534 80/10/03 9pp
- 8010300166 Forwards "Tailings Mgt Plan Evaluation, Dawn Mining Co.Ford, WA," final rept NELSON, J D Colorado State Univ 80/09/30 10
- --8010300171 "Tailings Mgt Plan Evaluation, Dawn Mining Co.Ford, WA." final rept.
 NELEDN.J D., ABT. 8 R. Colorado State Univ. 80/08/31 52pp
- 8010310513 Discusses guidance Te Edgemont cleanup action program (B-2217) w/respect to BNNL activities for cleanup of residual radioactivity at offsite locations & delivery of matls to site EADIE, 0 G Uranium Recovery Licensing Brench 80/10/10 2pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8010010119 Submits application to amend license to export U-235 to Suitzerland, increasing quantity to Include DOE allowable tolerances of 32.245 kg U, containing 1 894 kg U-235 MATSDN,V Transnuclear, Inc 80 092/01 80/09/16 ip

- BOICOID124 Executive Branch position re Transmuclear, inc application for license to export 2 951 kg U-235.in 6 5 kg U, to West Germany Recommends issuance of license Ltr of assurance and NOSEMICA, U State Dept of Bureau of Oceans & Internat I Environ & Scientific Affairs 80/09/16 3pp
- 8010010128 Executive Branch position re OA Co application for amend to license to export U-235 to Taiwan increasing amount authorized to 3 98 kg U-235 in 20 kg U Recommends issuance of amend Ltr of assurance encl NGSENZOL V State Dept of Bureau of Oceans & Internati Environ & Scientific Affairs 80/09/12 2pp
- 8010010132 Forwards application for export license for minor nuclear export.htm of assurance required W/o encl DEVINE.JB Assistant Director for Export/Import & International Safaguards 80/09/22 ip
- 8010010137 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl. PETERGON, M.R. Assistant Director for Export/Import & International Safeguards 80/09/22 ip
- 8010010140 Forwards application for export license for minor nuclear axport Ltr of assurance required W/o encl DEVINE.JB Assistant Director for Export/Import & International Safeguards 80/09/22 ip
- 8010010152 License for Transmucisar, Int to export 475 3 kg U-235, contained in 11.053 kg U & 0 043 U-235, contained in 1 kg U, to France
 DEVINE, J B Assistant Director for Export/Import & International Safeguards RBU 327 79-332/ 80/09/08 2pp
- 8010010199 Forwards Transnuclear, Inc application to export U, in form of U haxafluoride, to France
 MATSDN, V Transnuclear, Inc. 80/09/03 1p
- 8010010166 Advises of no matt changed circumstances associated w/export license application from those existing at time of issuance of KBNM-1674 License may be issued.

 MOORER N Assistant Director for Export/Import & International Safeguards 80/09/11 Ip
- 8010010170 Advises of no matl changed circumstances associated w/export license application from those existing at time of issuance of XSNM-1674 License may be issued MODRE, R II Assistant Director for Export/Import & International Safaguards 80/09/11 ip
- B010010223 Litense for Matheson Cas Products to export 90 g deuterium, contained in cylinders to Venezuela DEVINE, J B Assistant Director for Export/Import & International Bafaguards 101-94099-A 80/09/19 2pp
- 8010010240 License for Aldrich Chemical Co. Inc. to export 2 0 kg deuterlum.contained in 10 kg deuterlum oxide.to Chite DEVINE.J P Assistant Director for Export/Import & International Safeguards 17/80 80/09/17 2pp
- 8010010241 Bubmits application to amend license extending expiration data from 801001 to 811001 KLAPOW.R Engelhand Minerals & Chemicals Corp., Philipp Brothers Div 80/09/08 ip
- 8010010243 Requests Executive Branch position re Monsanto Research Corp application for amend to license, adding New Zealand to list of countries PETERSON.M.P Office of International Programs, Director 80/09/22.
- 8010010246 License for B&N to export 430 kg depleted U.in form of U oxide pouder to Japan PETERBON, M.R. Assistant Director for Export/Import & International Bafeguards 575-8012-80-09. 80/07/16 2pp
- 8010010250 License for Sigma Chemical Co to export 10 kg deuterium oxide to Singapore
 DEVINE.U.B. Assistant Director for Export/Import & International Safeguards D-52. 80/09/19. 2pp
- 9010010306 License for Sandvik Special Metals Corp to export 455 piecas (460 lbs) Zircalog-4 guide thimble tubes to Japan DEVINE/J. B. Assistant Director for Export/Import & International Safeguards 93:5. 80/09/17, 1pp.

- HO10010319 License for QA Co to export miscellaneous specially designed parts & components, including fission chambers, ionization chambers & electrical control console, to Belgium PETERSON.M R Assistant Director for Export/Import & Internations; Hafeguards IEL-1197 80/09/16 1p
- 8010010319 License for Marubeni America Corp to export 100 spacer picca parts specially designed for use in nuclear reactor to Japan DEVINE. J B Assistant Director for Export/Import & International Safeguards INDY-1968 80/09/16 ip
- 8010010324 License for Sigma Chemical Go to export 10 O kg deuterium oxide to India DEVINEI, J B Assistant Director for Export/Import & International Safeguards D-91 80/09/22 2pp
- 8010010425 Requests Elecutive Branch position re Transnuclear, Int application for licenses to export highly enriched U & low enriched U to Austria for use in ABTRA research reactor PETERSON.M R Assistant Director for Export/Impurt & International Bafeguards 80/09/17 ip
- 8010010449 Application by Marubeni America Corp for license to export PU-242, enriched more than 90% to Japan KINO.T Marubeni America Corp (subs of Marubeni Corp) 2H-0077-2N 80/09/08 3pp
- 8010010A78 Forwards Executive Branch response on pending export application for EURATOM & Sweden Final review requested to facilitate early response to forthcoming Commission action paper H/o encl
 SHEA, J. R Office of International Programs, Director 80/07/15
- 8010010702 Requests expedited issuance of license to import 406 g U-235, in TRIOA filp fuel elements w/580 g U, from Mexico MDURY, W R General Atomic Co (subs of Gulf Dil Co) IEL-2011 80/09/04 ip
- 8010010732 Forwards Reuter-Stokes 800911 ltr re inquiries from Mexico for reactor components Generic retransfer assurance recommended upon review of application for export license M/o encl.

 DEVINE, J 8 Assistant Director for Export/Import & International Safeguards 80/09/17 ip
- 8010020083 Application by Transnuclear. Inc for license to export 4 584 kg U-235.enriched to max of 19 959%, to Austria End use statement encl MATSON. V. Transnuclear, Inc NUK-344 80-187/ 80/09/08 4pp
- 8010020086 Application by Transnuclear, Inc for license to export 1 704 kg U-235 in form of U hexafluoride or U metal, to Austria End use statement encl
 MATSON, V Transnuclear, Inc NUK-343 80-186/ 80/09/08, 4pp
- 8010020617 Forwards reactor checklist re request from Germany for highly anriched U for NRC records on license applications from Transnuclear, Inc MATSON, V Transnuclear, Inc 80/09/12 2pp
- B010020689 Application by Mitsui & Co(USA). Inc for license to export 626 Kg enriched U dioxide to Japan SAIKI. T Mitsui & Co (USA). Inc (Subs of Mitsui & Co , Ltd. } MBK-HI-R7. 80/09/05 2pp
- B010030516 Application by Eberline Instrument Corp for license to export Model DNB-10 alpha calibr std to Australia JOHNBON, N. R Eberline Instrument Corp 80 873325 80/09/10 1p
- 8010060067 Forwards amended application for license to export up to 10 Cl Cf-252 as cermet wire or pellets & up to 1000 Cl Cm-242 or Cm-244, as powdered gride TAYLOR.R R Honsanto Research Corp 80/09/08 2pp
- --8010060069 Amend to application by Monsanto Research Corp for license to export up to 10 Ci Cfr-252 as commet wire or pellets & up to 1000 Ci Cm-242 of Sm-244, as powdered oxide TAYLOR, R R Monsanto Research Corp 80/09/08 4pp
- 8010060104 Application be QE for license to export 265 kg U dioxide powder to Japan WILSON, 9 D. General Electric Co BDH 80104 80/09/04. Ip
- 80100&01&9 Application by GE for license to export 200 kg natural anrichment oxide powder & pellets to Canada WILSON, B. General Electric Co BDW 80106 80/09/15 ipp

- 8010060182 Bubmits application to renew license to export 400,000 Ci tritium to Taiwan & the Philippines Requests reduction in quantity to 200,000 Ci SNIGERT, B B Timex Corp 80/09/16 ip
- B010050185 Application by Nissho-lwai America Corp for license to export 560 kg heavy water to Japan YAMANA,K. Nissho-lwai American Corp HHM-0210 80/09/15 2pp
- -8010060189 Forwards two applications for export licenses W/o encls
 YAMANA, X Nissho-Iwai American Corp MACPJ 2547KY 80/09/16
- 8010080032 Forwards application for license to export 15,141 kg U, enriched to 3 25% U-235, to Japan SMIMA, B Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-3480-08 80/09/12 2pp
- --B010080035 Application by Mitsubishi Intl Corp for license to export 15,141 kg Urenriched to 3 25% U-235, to Japan End use statement encl SHIMArS, Mitsubishi International Corp (subs. of Mitsubishi Corp) B0/09/12 2pp
- 8010080037 License for Mitsubishi Corp to export 500 mCi Cf-252. rivology Estense for nitsubishi Corp to export 500 mCi Cf-252, contained in cament wire, to Japan DEVINE, J. B. Assistant Director for Export/Import & International Baisguards 80/09/11 2pp
- S010080043 License for Mitsubishi Nuclear Fuel Co to export 493 kg U-235, contained in 15, 141 kg U am U hexafluoride, enriched to 3 25%, to Japan. BEVINE, J B Assistant Director for Export/Import & International Sufeguards 80/09/11 2pp
- B010080047 License for Natl Nuclear Corp to export 395 71 g U-235, contained in 395 71 g U, enriched to 1 914% as one U oxide fuel rod, to West Germany DEVINE, J B Assistant Director for Export/Import & International Ba
- 8010080050 License for Mitsubishi Nuclear Fuel Co to export 719 kg U-235 contained in 25,184 kg U as U hexafluoride enriched to 2 85% to Japan BEVINE, J.B. Assistant Director for Export/Import & International Safeguards. B0/09/11 2pp
- 8010080065 License for Westinghouse to export 0.280 kg U-235, contained in 6 kg U-enriched to 4 5% as U oxide pellets, to Belgium DEVINE, J. B Assistant Director for Export/Import & International Bafeguards. 80/09/11 Spp
- 8010080077 License for OA Co to export 1 943 kg U.enriched to 19 9% as TRIOA fuel elements.to Indonesia PETERSON M.R. Assistant Director for Export/Import & International Bafaguards. IEL-1159, 80/09/20 2pp
- 8010080095 License for Westinghouse to export nuclear reactor pressure vessels, reactor internals, coolant pumps, control rods & steam generators to Republic of Korea PEICRBON, MR Assistant Director for Export/Import & International Safaguards 80/09/22. 2pp
- B010080307 Forwards application for license to export 11,823 kg U containing 337 kg U-235 to Japan BHIMA, B Mitsubishi International Corp (subs of Mitsubishi Corp.) HBA-3480-07 B0/09/12 3pp.
- ---8010080312 Application by Mitsubishi Intl Gorp for license to export 11.823 tg U containing 337 kg U-235 to Japan End use statement encl
 SKIMA, B. Mitsubishi International Corp (subs of Mitsubishi SHIMA, B. Mitsubis Corp.), 80/09/12
- 8010090042 FDIA request for info re effect of UB nonproliferation policy on Indian nuclear commitments, amount of UB nuclear fuel shipped to India & Indian nuclear capabilities. BCHERR.J. Center for Lew & Bocial Policy 80/06/30. Spp
- BO100900BO Withdraws B00902 license amend request.
 MATBON, V. Transnuclear, Inc 79-211/01, S0/09/22 1p
- 8010090456 Advises that NRC has not completed licensing action on application to export low enriched U to Talwan. Favorable Executive Branch views were received 800616 Final Commission action expected in near future SHEA, J. R. Office of International Programs, Director. 80/08/14.

- 8010090486 License for Mitsubishi Intl Corp to export 500 mCi Cf-252 as encapsulated cermet wire to Japan PETERSDIAM R Assistant Director for Export/Import & International Bafeguards 64-7462-80 80/09/23 2pp
- 8010090502 Application by Ediow Intl Co for License to export 19,858 8 kg U as U hexafluoride to India
 HARMON, D V Ediow International Co IN D8 3 (19) 80/09/24 1p.
- 8010090505 Application by Edlow Intl Co for license to export 3 g std ref mat1 U-010 to Japan HARNON, D Edlow International Co 80/09/23 ip
- BO10090515 Application by Edlow Inti Co for license to export 2 g std ref matl U-010 to Japan.
 HARHBURD Edlow International Co 80/09/23 ip.
- B010090520 Application by Edlow Intl Co for license to export 3 g std raf matl U-015 to Japan
 HARMON, D Edlow International Co B0/09/23 ip
- 8010090525 Application by Edlow Intl Co for license to export 2 g std ref matl U-015 to Japan HARMON,D Edlow International Co 80/09/23 ip
- 8010090541 SECY-80-401A Recommends that license be issued to GE for export of 637 g U-235 & 26 2 g Pu.contained in 7.864 g U-to Taiwan Draft license andl BHEAL J. R Office of International Programs, Director 80/09/18.
- 801007057B Executive Branch position re EXXON Nuclear Inc application for license to export 10.000 Kg U. containing 240 Kg U-235, to West Germany Ltr of assurance encl License should be granted granted granted granted NOSENZO, L V State, Dept. of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/09/23 3pp.
- B010100215 Executive Dranch position re QA Co application for license to export 2 955 kg U.containing 0 598 kg U-235, to West Oermany Ltr of assurance encl License should be granted NOSENYOL V Bates. Dept of, Dureau of Oceans & Internat Environ & Scientific Affairs 80/09/23 3pp
- B010100274 Executive Branch position re Westinghouse application for license to export 7,921 kg U.containing 190 kg U-225 to Swefen Ltr of assurance encl License should be granted. OUHIN, M A Btate, Dept of 80/09/29 3pp
- 8010100296 Ltr of assurance re Transnuclear application for license to export 11.03 kg U.enriched to 2 2286% U-235.to France MARCHAL.J European Communities. Commission of. 80/09/19 19
- 8010100297 Executive Branch position re Transmuclear, Inc application for license to export 802 kg U.containing 484 408 kg U-225, to Mest Dermany Ltrs of assurance encl License should be granted NOBENZOL V State, Dept of, Sureau of Oceans & Internati Environ & Scientific Affairs 80/09/19 7pp.
- 8010140140 Forwards Executive Branch response to pending application for license to export highly enriched U to West Germany W/o encl
 SHEA, J.R. Office of International Programs, Director, 80/10/01
- 8010140270 Application for license to import 500 g U.containing 40 g U-235,from United Kingdom MATSON,V Transnuclear, Inc. 80-202/02 80/09/18. 2pp.
- 8010140398 Requests Executive Branch position re Boeing Co request to amend license to add airlines in New Zealand, Bouth Africa & Ivary Coast to list of ultimate consignees to receive emergency spare aircraft counterweights DEVINE, J. 8. Assistant Director for Export/Import & International Bafeguards. 80/10/03 ip
- 8010140622 Executive Branch position re Mitsubishi Intl Corp application for license to export 25,173 kg U.containing 869 kg U-235, to Japan Ltr of assurance encl.License should be granted. GUHIN, M. A. State, Dept of, Bureau of Oceans & Internati. Environ. & Scientific Affairs. 80/09/29 3pp
- 8010130025 Forwards 800715 application for license to export minor nuclear matts & requests required ltr of assurance.Wo encl. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. 80/07/30 ip

- 8010190033 Request comments re Nissho-Iwai American Corp 800915
 Application for license to export 640 kg of heavy water to
 Japen Executive Branch input re compliance w/critaria of
 Atomic Energy Act is required. H/o encl application
 DEVINE, J. B. Assistant Director for Export/Import & International
 Safeguards 80/09/30 ip
- 8010150038 Forwards Transnuclear, Inc 800922 1tr withdrawing 800908 amend request Records should reflect withdrawal, M/o encl DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/09/30 ip
- 8010190546 Requests Executive Branch position re Seamodal Transport Coapplication for license to export SNM to Selgium
 DEVINE.J.B Assistant Director for Export/Import & International
 Bafaguards 80/10/03 ip
- B010150552 Requests Executive Branch position re Edlow Intl Co application for license to export SMM to India DEVINE.J B Assistant Director for Export/Import & International Safaguards 80/10/03 ip
- 8010130560 Requests Executive Branch position re Ediow Intl Co application for license to expart 3 7 mg Cf~252 to India. DEVINE, J B. Assistant Director for Expart/Import & International Bafaguards 80/10/03, ip
- 8010180566 Requests Executive Branch position re Commonwealth of Australia application for license to export 660 kg heavy water to be used as moderator in HIFAR research reactor DEVINE, J. 8, Assistant Director for Export/Import & International Safeguards. 80/10/03 ip
- 80:10:50574 Requests Executive Branch position re Nissho-Iwai Corp application for license to export SNM to Japan.
 DEVINE, J.B. Assistant Director for Export/Import & International Bafayards. 80/10/03 ip
- 80:01:50392 Forwards Transnuctear. Inc 1tr transmitting reactor check list for export license applications W/o encl DEVINE, J B. Assistant Director for Export/Import & International Bafeguards. 80:10/03 ip
- B010150670 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl. DEVINE.J B Assistant Director for Export/Import & International Safeguards 80/10/03 ip.
- 8010160018 Forwards OE request for amend to export application.
 increasing quantity of math for export to Taiwan W/o encl.
 DEVING.J.B. Assistant Director for Export/Import & International
 Bafaguards 80/10/03. ip
- 8010160033 Application by QE for amend to license to export initial core fuel to Taiwan Amend will cover quantity of fuel called for by bid spec.

 MILBONED Qeneral Electric Co 8DW 80107 80/09/18 ip
- SO10160037 Confirms Bandvik Bpecial Matals request for license to export radioactive matis to Japan License KCGM-0296 expired before shipment was made MENTER.L Sandvik Special Metals Corp 80/07/24 ip.
- 8010160043 Application by Transnuclear, Inc. to amend license to export 8:431 tg U containing 227.705 kg U-235
 MATSON:V. Transnuclear, Inc. 80-133/01 RBU 3 80/09/17 ip.
- 8010160052 Partial response to FOIA request for documents re License IBNM-79005. Forwards documents listed in App A. Bearch for add1 documents (s underway, FELTON.J M. Division of Rules and Records, 80/10/03, 2pp.
- --8010160062 Informs that SECY-79-118 re import of unirradiated low anriched U from Russia has been reviewed & no physical security concerns were identified. Licensee is authorized to receive SNM in quantity & form specified in application.

 MCCORKLE.O M. Physical Security Licensing Branch. 79/02/28 ip.
- B010160095 F0IA request for documents re License IBNM-79005. MACOREOUR.B.A. New West Magezine. 80/09/22, 1p.
- **Ol0160064 Bubmits application to renew license to export TRIOA reactor fuel slements containing U-235, enriched to 19, 9%, to Austria LENNKH-R Austria, 6298-A/80, 80/09/05, 1p.

- B010160067 Confirms provise re physical protection compliance w/100FR73 requirements HELFRICH,0 F State,Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/09/24 ip
- 801016006B Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/10/03 1p
- B010160073 Requests Executive Branch position re Timex Corp application for amend to extend License XB-1046 expiration date to B1101 DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/09/30 ip
- 80i0i60074 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl DEVINE.J.B Assistant Director for Export/Import & International Bafaguards 80/10/03 ip
- 8010160079 License for George Uhe Co. Inc to export 1.021 kg heavy water to Hest Germany DEVINE. J B Assistant Director for Export/Import & International Bafeguards. CHEM-4221 80/10/02 2pp
- 8010160082 License for Sigma Chemical Co to export 10 kg deuterium oxide to Brazil.

 DEVINE, J B Assistant Director for Export/Import & International Safeguards D-53 80/10/03 2pp
- G010160087 License for QA Co to export 177 g U-235 contained in 591 g U, to Austria.
 DEVINE.J.B. Assistant Director for Export/Import & International Safeguards. IEL-1199. B0/10/03 2pp.
- B01016010B Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl DEVING.J B Assistant Director for Export/Import & International Safeguards 80/10/03 ip.
- B010160213 Application by Mitsui & Co.(USA). Inc. for license to export 12.433 g. U-233, enriched to 4 91% & contained in std samples of hoke tubes, to Japan YAMAGUCHI, T. Mitsui & Co., Ltd. 80/09/05 3pp
- --8010160219 Forwards application by Mitsul & Co for license to export SNM in form of U fluoride to Japan.
 SAIKI,T Mitsul & Co , Ltd 80/09/05. ip
- 8010160225 Application by Aldrich Chemical Co.Inc for license to export i kg deuterium.contained in 5 kg deuterium oxide.to Columbia.
 EDELSTEIN.S. Aldrich Chemical Co., Inc. (subs. of Bigma-Aldrich Corp.). 19/80. 80/09/23 ip.
- ---B010160227 Forwards application by Aldrich Chemical Co, Inc for license to export deuterium exide to Columbia.

 EDELBTEIN,B. Aldrich Chemical Co, Inc. (subs of Bigma-Aldrich Corp.). B0/09/23. 1p
- 8010160237 Application by Nissho-Iwai American Corp for license to export 55 558 kg U-235 enriched to 12 18% to Japan YAMANA.K. Nissho-Iwai American Corp 00E31-74 80/09/15 ip
- B010160246 Application by Mitsubishi Intl Corp for licence to export 359 kg U-235, anriched to 2,45%, to Japan, SHIMA-B. Mitsubishi International Corp (subs of Mitsubishi Corp.) HSA-5480-09, 80/09/19 2pg
- --B010160249 Forwards application by Mitsubishi Intl Corp for license to export U-235 to Japan. SHIMA:S Mitsubishi International Corp (subs of Mitsubishi Corp.) HBA-5480-09 80/09/19. 2pp.
- 8010160297 Application by Sigma Chemical Co for licanse to export 10 kg deuterium liquid over period of two yre to Brazil STERN.H.C. Sigma Chemical Co. (subs. of Sigma-Aldrich Corp.) D-94. 80/09/23. 1p.
- 8010160260 Application by Commonwealth of Australia for license to export 660 kg fresh untritiated deuterium to Australia, MUNRO,F Australia, AEC RE 20/80. 80/09/25, ip
- B010160261 Application by Air Products & Chemicals for license to export 1,000 g deuterium to England.
 NGVAKOVICH Air Products & Chemicals, Inc. 80/09/25, ip

- 80101&0733 Amend i to Mitsubishi Intl Corp export license, changing and use of matl from Mihama Unit i to Unit 3 All other conditions unchanged DEVINE, J B Assistant Director for Export/Import & International Eafequards HSA-5480-05 80/10/03 1p
 - _____Bafequards
- 8010160736 License for Marubeni America Corp to export 1 g Pu-242. enriched to more than 90% to Japan.

 DEVINE, J B. Assistant Director for Export/Import & International

 Bafeguards ZH-0077-2N 80/10/03 2pp
- 8010160740 Amend 1 to OA Co export license increasing quantity of authorized matl from 1 035 kg to 3 98 kg U-235 DEVINE.J B. Assistant Director for Export/Import & International Bafaguards IEL-1198 80/10/03 1p
- BO10160765 Advises that Commission has accepted George Uhe Co license to export 1.021 kg heavy water to Nest Germany Offc of Intl Programs informed of action by 801002 telcon. CHILMS J. Diffice of the Secretary of the Commission. SBO-442 BO/10/02 1p
- B010170004 Bubmits application to import 1 591 kg.as U-308 at 88 1%, from Ontario Hydro Canada MATSON, V Transnuclear, Inc. 80-204/01/02 80/10/01. 2pp.
- E010170006 Requests extension of License XCOM-0181 expiration date to 811001 MENTER, L. Sandvik Special Metals Corp. 80/07/29. 1p.
- 8010170008 Submits application to amend license to export to add 1 6 kg U as U-308 containing 1.49 kg U-235 MATBON, V Transnuclear: Inc. TN MISC-233 80/10/01, ip.
- BO10170112 Advises that Commissioners have approved proposed Hestinghouse license to export 140,000 kg U.enriched to 4% U-235 in form of U-dioxide in fabricated fuel bundles; to Taiwan, as discussed in BECY-BO-393 & BECY-BO-317. CHITM: B U Office of the Becretary of the Commission, SBO-353, BO/98/22 ip
- 80:0170:15 Advises that Commissioners have approved proposed Mestinghouse license to export 323,622 kg U,enriched to 3,3% U-233 as fuel assemblies,to Taiwan,as discussed in SECY-80-384 & SECY-80-317 CHILKS J. Office of the Secretary of the Commission BSO-354 BO/08/22 ip
- EGIOI70288 Forwards application for license to export 4 416 kg U. containing 2 005 kg U-235 to Buitzerland MATSON, V. Transnuclear, Inc. 80/09/08 is
- -- 6010170291 Application by Transnuclear, Inc for license to export 4 416 kg U.containing 2 005 kg U-235, to Switzerland, End use statement encl Transnuclear, Inc. NUX-34280-185/0 80/09/08 4pp
- 8010170293 Forwards application for license to export TRIQA reactor fuel elements containing 862 g U. to Italy (MDRV.W R. General Atomic Co (subs of Gulf Gil Co) IEL-2013. BO/09/08. 1p
- --8010170295 Application by GA Co for license to export TRIGA reactor fuel elements containing 862 g U.to Italy,
 HOHRY.W R General Atomic Co (subs of Gulf Oil Co.) IEL-2013.
 80/09/08 2pp
- BD10170442 Amend 1 to license for B&W to export 340 kg depleted U, contained in U dioxide powder, instead of 430 kg depleted U. to Japan PETERSON, M R Assistant Director for Export/Import & International Bafeguards, 80/09/22, 2pp.
- 8010170457 Application by Seamodal Transport Corp for license to export 172 NSB Pu stds & 440 NDS U stds to Belgium Purchase request for special nuclear std ref matls encl BYRD. C N Seamodal Transport Corp. A0/1522 80/09/18. 4pp.
- BDI0200300 License for Bigma Chemical Co to export 10.0 kg deuterium oxide to New Zealand DEVINE, J.B. Assistant Director for Export/Import & International Bafaguards 80/10/02, ip.
- 8010200335 License for Transnuclear, Inc to export 0.11175 kg U-235, contained in 11.03 kg U-to France.

 DEVINE: J B Assistant Director for Export/Import & International Safaguards 80/09/29, 2pp.

- 8010210175 Responds to FOIA request for SECY-80-336 & LV Nosenzo 800506 memo to JR Shea Forwards documents.
 FELTON.J M Division of Rules and Records 80/10/10 1p
- --B010210187 SECY-80-336 Discusses Commission review of Westinghouse application for license to export two reactors to Korea, Recommends that Commission authorize issuance of License XR-033 to Mestinshouse Office of International Programs, Director. 80/07/21
- --8010210195 Requests that NRG issue license to Westinghouse to export two reactors to Korsa Delay in license issuance could jacquardize contract & could negatively impact future contracts Draft license sncl HERSCH.M.M Westinghouse Electric Corp. 80/03/28 4pp
- 8010210183 FOIA request for SECY-80-336 & LV Nosenio 800506 memo to JR NERENBERG. A L. Center for Development Policy. 80/09/25, 1p
- 8010220287 Advises that intermediate consigned re 800707 license application should be changed to Transnuclear GmbH, West Germany, HANBEN, L. E. Exxon Nuclear Co . Inc. (subs. of Exxon Corp.) 80/09/25, ip
- 8010220296 Requests views as to whether encl Transnuclear, inc license application to export SNM to Switzerland meets applicable criteria in Atomic Energy Act of 1954.4/o encl. PETERSON.M R Assistant Director for Export/Import & International Bafeguards. 80/09/22 1p.
- 8010220370 Requests early approval of application for license to export TRIOA central rod element w/adapter & components to Austria. Components will not be retrensferred w/o prior UB approval LENNKH.R. Austria. 6816-A/80 80/10/02. ip.
- B0102203B0 Requests Executive Branch position re Exxon Nuclear Co.Inc application for license to export SNM to West Operany DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/08 ip.
- 8010220652 Requests Executive Branch position re Exxon Nuclear Co. Inc application for literate to export SNH to West Germany BEVINE, J.B. Assistant Director for Export/Import & International Bafeguards, 80/10/08. ip.
- 8010230060 Forwards application by Transnuclear, Inc for license to export 15,900 kg U.enriched to 3 35% to Neet Germany, MATBON, V. Transnuclear, Inc. RBU 348 80-2057, 80/10/01, 19.
- --8010230069 Application by Transnuclear, Inc for license to export 15,900 kg U.anriched to 3,35%, to West Germany. End use statement encl MATSON, V. Transnuclear, Inc. RBU 348 80-205/ B0/10/01 Spp.
- B010230319 License for Air Products & Chemicals, Inc to export 1 0 kg dauterium to United Kingdom DEVINE: U B. Assistant Director for Export/Import & International Bafeguards. B0/10/15. 22p
- G010230321 Application by Mitsubishi Intl Corp for license to export 300 mCi Cf-252.as encapsulated termst wire to Japan KUCE.T Mitsubishi International Corp (subs of Mitsubishi Corp.). 64-7475-80. G0/10/06 ip.
- 8010230363 Amend 2 to license for QA Co extending expiration date from B01001 to 821001.
 DEVINE.J.B Assistant Director for Export/Import & International Bafeguards IEL-954. B0/10/14 ip.
- 8010230380 License for Aldrich Chemical Co. Inc. to export 1.0 kg deuterium contained in 5.0 kg deuterium oxide to Columbia. DEVINE: J. B. Assistant Director for Export/Import & International Bafaguards 19780 80/10/15 2pp
- 8010230384 License for Bigma Chemical Go to export 10.0 kg deuterium oxide to Brazil.
 DEVINE, J. B. Assistant Director for Export/Import & International Safeguards, D-84 GO/10/15. App.
- 8010230637 License for Mitsubishi Inti Corp to export 25,173 tg U, containing 867 tg U-235 to Japan.
 DEVINE.J.S. Assistant Director for Export/Import & International Safeguards. HSA-0480-06 80/10/06. 3pp.

- 8010230640 Amend 4 to Westinghouse license increasing amount to 150.012 kg U.containing 4:182 kg U-235 & extending period of performance to 811231 DEVINE, J 8 Assistant Director for Export/Import & International Safeguards PC-AEC-22 80/10/06 Ip
- B010230687 License for Transnuciear. Inc to import 500 g V.enriched to B 0% U-235 as U dioride pellets from Belgium DEVINE, J B Assistant Director for Export/Import & International Safeguards B0/10/008 ip
- 8010230689 Amend i to Sandvik Special Metals Corp export license extending expiration date from 801001 to 811001 DEVINELU B Assistant Director for Export/Import & International Safeguards 80/10/08 Ip
- 8010230690 License for Mitsui & Co.Inc to export 148 kg U-235, contained in 5,427 kg U as U herafluoride, to Japan DEVINE, J B Assistant Director for Export/Import & International Safeguards MSK-F3-R6(A) 80/10/03 2pp
- BO10230893 License for Nitsui & Co.Inc to export 59 kg U-233.contained in 3.640 kg U as U hezaflooride to Japan.
 BEVINE, J B Assistant Director for Export/Import & International Bafaguards NSK-TR-12 B0/10/09 2pp
- 8010230695 Amend i to Exxon Nuclear Co. Inc export license extending appiration date from 801001 to 811001 DEVINE. J B Assistant Director for Export/Import & International Safeguards 80/10/08 ip.
- 8010230698 Amend 1 to Union Carbide Corp export license increasing enrichment from 93 0 to 93 15
 DEVINE, J. B., Assistant Director for Export/Import & International Safeguards NRC-979 80/10/08 ip
- 8010230700 License for GA Go to export TRIOA control rod element w/adaptor & other parts & components including fission chambers to Austria
 DEVINE.J B Assistant Director for Export/Import & International Safeguards IEL-2000 80/10/10 1p
- B010240028 Requests ltr of assurance re application for export license DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/06 1p
- 8010240027 Forwards Executive Branch response to two pending export license applications requiring Commission review & original applications H/o encl SHEA,J R Office of International Programs, Director 60/10/07
- 8010240030 License for QA Co to export 0 588 kg U-235.contained in 2 955 kg U.to Heat Germany DEVINE.J B Assistant Director for Export/Import & International Safeguards. 80/10/07 ipp
- B010240032 Application by DOE for license to export fuel elements for TRIOA research reactor to Romania Unesecuted contract encl MCCOLDRICK,T Energy, Dept of, B0-90 B0/09/26 10pp
- 8010240047 Requests authorization for export of enriched U to India VERMARR B India 80/09/10 2pp
- 8010240197 Forwards Transnuclear, Inc request for Amend 2 to license to export authorising add1 1.6 kg U enriched to 93 3% w/o max, to replace met returned to US Requests comment DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/10/06. ip
- 0010240485 Requests route & part approval to import two casks Model JMTR3200, containing B1 JMTR type fuel elements, from United Kingdom RAVENSCROFT, N Ediow International Co 17377 80/09/03. 1p.
- p010240460 Notifies of 800910 export of 27 irradiated fuel segments in Model 600; to Sweden KIRKLAND, M. W. General Electric Co. 17425. 80/08/29 2pp
- 8010240467 Notifies of 800909 export of 27 segmentes fuel rods in Model 600, to Sweden.
 KIRKLAND M W General Electric Co. 17357 80/08/26 2pp
- 3010240488 Confirms 801001 telcon re withdrawal of 800825 application for license to export nuclear mati to Canada.

 8CHAEFFER.M R RMI Co., RMI Titanium 80/10/01. 1p

B010240492 Ltr of assurance re export of 99 kg U-235, contained in 3,640 kg U, to Japan Japan Atomic Power Co is designated as authorized person MYABAYASHI,M Japan B0/10/01 ip

1

- 8010240499 Application to renew License ISMM-78002.Amend i HENDRICK,N G Texas Nuclear Div (subs of Ramsay Eng Co) 80/10/01 ip
- 8010240505 Recommends approval of GA Co 800704 application for license to import 580 g U.contained in three TRIOA fuel elements, from Mexico MODRE.R N Assistant Director for Export/Import & International Safeguards 80/10/07 1p
- --8010240515 License for GA Co to import 580 g U.anriched to 70% U-235, from Mexico DEVINE.J B Office of International Programs. Director 80/10/07
- 8010240538 Ltr of assurance re export of 148 kg U-235, contained in 5,429 kg U,to Japan Tokyo Electric Power Co.Inc is designated as authorized person MIYABAYASHI,M Japan 80/10/01 lp
- B010270010 Forwards RMI Co B01001 itr requesting withdrawal of export license application W/o ancl DEVINE, J B Assistant Director for Export/Import & International Bafeguards B0/10/08 ip
- 8010270012 Forwards application for export licnese for minor nuclear export Ltr of assurance required W/o and DEVINE, J B Assistant Director for Export/Import & International Bafeguards E0/10/08 ip
- B010270020 Forwards Erxon Nuclear Co, Inc 800925 ltr requesting amend to axport license application changing intermediate consignee to Transnuklear. OmbH issuance of license will be deferred until Executive Branch position is received W/o and DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/10/08 ip
- 8010270082 Cancels 780709 license re export of 180 lb of depleted U to Iran CRAMFORD. D S Dresser Industries, Inc. 80/10/03 ip.
- B0102700B5 Requests amend to extend expiration data until 821001 MDRRY.W R Oeneral Atomic Co. (subs of Gulf Gil Co.) IEL-2020 80/09/29 ip
- 8010270088 Advises that license may be issued due to similarity of maticircumstances associated w/License (SNM-1674 MODRE,R N Assistant Director for Export/Import & International Safeguards 80/10/07 ip
- 8010270/91 Advises that license may be issued due to similarity of mat) circumstances associated w/License KSNM-1674 MODRE,R N Assistant Director for Export/Import & International Safeguards 80/10/07 ip
- 8010270094 Requests Executive Branch position re DDE application to export SNM to Romania DEVINCE.J.B Assistant Director for Export/Import & International Safeguards 80/10/10 ip
- B010270215 Requests Ejecutive Branch position re Carpenter Technology Corp application for license to export Zircaloy reactor components to West Oermany for ultimate use in Atucha-2 nuclear gover station in Argentina DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/10/17 ip
- 8010270294 License for Eberline Instrument Corp to export 0 02 micrograms Pu-239 as Pu-239 alpha calibr std. Model DNB-10, to Australia .
 DEVINE: J B Assistant Director for Export/Import & International Bafeguards 8,0 873325. 80/10/17 2pp
- B010270261 Forwards application by Westinghouse for license to export nuclear fuel to Korea HERBCH,M M Wastinghouse Electric Corp ICS-0708, B0/10/09 2pp
- --8010270267 Application by Westinghouse for license to export U dioxide pellets encapsulated in sealed fuel rods & fuel assemblies to Korea HERSCH, M M Westinghouse Electric Corp. 80/10/08, 1p.

- 8010270325 Forwards info requested by MR Peterson re 800910 application to ship SNM to Australia
 JOHNSOK, N R Eberline Instrument Corp EI-917832 80/10/07 2pp
- 8010270405 License for Edlow Intl Co to export 0 020 g U-235, contained in 2 g U to Japan
 DEVINE, J B Assistant Director for Export/Import & International
 Safeguards 80/10/16 2pp
- SO10280124 License for Ediow Intl Co to export 0 046 g U-235, contained in 3 g U, to Japan DEVINE, J B Assistant Director for Export/Import & International Bafeguards SHIBI1(8-297-80 80/10/16 2pp
- 8010260492 GECY-80-451
- Informs Commission of Executive Branch response on pending Transnuclear, Inc license application to export high enriched
- U to West Germany SHEA, J R Office of International Programs. Director 80/10/01
- 8010280637 Advises of Dresser Industries, Inc 801003 request to withdraw export license application XU-8432 DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/10/10 ip
- 010280697 Forwards application by Transnuciear, Inc for license to export 572 mCi Cf-252, in form of one cermet pellet, to Wast Germany
- MATSON, V Transnuclear, Inc 80-134/01 80/10/15 1p
- --8010280702 Application by Transnuclear, Inc for license to export 372 mCi CF-252, in form of one carmet pellet, to West Carmany + Transnuclear, Inc 80-134/01 80/10/20 ip
- 8010290040 Forwards Covt of India 800910 lbr to DDE re export license X8M-1740 application W/o encl DEVINE.J B Assistant Director for Export/Import & International Bafeguards 80/10/14 ip
- B010270137 Application by Westinghouse for license to export one BF3 proportional counter-Model WL23770, to West Germany PDCHAL-W F Westinghouse Electric International Co ZE-10111 B0/10/16 ig
- B010270149 Application by Byron Jackson Pump Div.Borg-Warner for license to export coolant pump components to Builtzerlans.
 NORTON, J. Borg-Warner Corp Byron Jackson Pump Div 793-W-5823
 80/09/25. 19
- 8010290156 Application by Reactor Experiments, Inc for license to export 0 2014 mg NP-237, electrodeposited onto nickel disc. to India HARMON, D Reactor Experiments: Inc IND3629 80/10/16 ip
- B01029015B Application by Edlow Intl Co for license to export 19.865 to U.a. U hexafluoride.to Bweden HARHOR, D. Edlow International Co 80/10/15 1p
- 8010290159 Amend i to Transnuclear, Inc export license adding Transnuklear GmbH as consignee DEVINE.J.B Assistant Director for Export/Import & International Bafeguards TNP 239 EU/07 80/10/23 ip
- B010290161 Forwards application by Aldrich Chemical Co for license to apport deuterium oxide to Korea.

 E0ELBTEIN, B. Aldrich Chemical Co.. Inc. (subs. of Bigma-Aldrich Corp.) B0/10/13 ip
- --8010290175 Application by Aldrich Chemical Co for license to export i kg deuterium in 5 kg deuterium axide to Korea EDELSTEIN,B. Aldrich Chemical Co., Inc. (subs of Sigma-Aldrich Corp.) 22/80 80/10/13 ip
- 8010270178 Application by Edlow Intl Co for license to expert 100,000 Ci bulk gas tritium to United Kingdom HARMON, D H Edlow International Co 80/10/08 1p
- 8010290182 Application by Edlaw Intl Ca for license to expart 50,000 Ci bulk gas tritium to United Kingdom HARROULD H. Edlaw International Ca 80/10/08 1p
- 0010290184 Forwards application for license to export low enriched U to West Germany. MANDEN,L E. Exxon Nuclear Co , Inc (subs of Exxon Corp.). BO/10/02 ip

- ~-8010270171 Application by Exxon Nuclear Co,inc for license to export 370 kg low enriched U to West Germany HANSEN,L E Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/10/02 2pp
- 8010270195 Denies 800603 application to export one proportional counter for use in Bushehr I reactor to Iran SHEA.J R Office of International Programs. Director 80/10/17
- 8010270273 Executive Branch position re Monsanto Research Corp application for license amend to export 10 Ci CF-252 & 1,000 Ci Cm-242 or 244 per ur to New Zealand License amend should he issued se issued NOSENZO.L V State.Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 8D/10/20 2pp
- 801029027B Requests Executive Branch position re Reactor Experiments, inc application for license to export byproduct matl to
- India DEVINE.J B Assistant Director for Export/Import & International Bafaguards BO/10/23 ip
- 8010290303 Requests Executive Branch position re Ediow Intl Co application for license to export 100,000 Gi bulk tritium gas to United Kingdom DEVINE/J B Assistant Director for Export/Import & International Safeguards 80/10/23 19
- B010290309 Requests Executive Branch position re Ediau Intl Co application for license to export 50,000 Ci bulk tritium gas to United KingGom DEVINE.J B Assistant Director for Export/Import & International Bafeguards. 80/10/23 19
- 8010290390 Recommends license be issued to Transnuclear Inc to import 1,510 kg U as U herafluoride enriched to 1 15% from France Proposed import represents no matl change in circumstances from conditions existing during earlier imports MOORER N Assistant Director for Export/Import & International Bafeguards 80/10/06 lp.
- 8010300277 Forwards application by Aldrich Chemical Co. Inc. for license to export 1 kg deuterium in 5 kg deuterium oxide to India EDELBFEIM B Aldrich Chemical Co. Inc. (subs. of Bigma-Aldrich Corp.) 80/10/08. 1p
- --8010300285 Application by Aldrich Chemical Co.Inc for license to export 1 kg deuterium in 3 kg deuterium oxide to India EDELBYEIN.B Aldrich Chemical Co., Inc. (subs of Sigma-Aldrich Corp.) 21/80 80/10/08 1pp
- 8010300291 Forwards application by Nissho-Iwai American Corp for license to export 2,203 ib deuterium to Japan YAMANA, K. Nissho-Iwai American Corp. MACPJ 2555KY 80/10/06 ip
- --8010300355 Application by Nissho-luaf American Corp for license to export 2,205 lb deuterium to Japan Nissho-luaf American Corp HHM-0214 80/10/06 ip
- 8010300309 Forwards application by TX Nuclear Div for license to export 1 g Pu-238, as exide aixed w/beryllium.to Norway, HENDRICK, N Q Texas Nuclear Div (subs of Ramsay Eng Co) 80/10/06. 1p
- --8010300319 Application by TX Nuclear Div for license to export 1 g Pu-23B.as oxide mixed w/bergliium to Norway HENDRICK, N. Q. Texas Nuclear Div (subs. of Rameay Eng. Co.) 760013. SD/10/D6, 1p
- 8010300329 License for Edlow Intl Co to export 0 030 g U-235,contained in NBB Std U-010, to Japan.

 DEVINE.J B Assistant Director for Esport/Import & International Bafeguards BHIB11(8-297-80 80/10/16 2pp
- 8010300468 Forwards application from Nisho-Iwai America Corp for license to export 2:250 lb deuterium to Japan Requesta Executive Branch position re 1978 Nuclear Nonproliferation Act criteria concerning proposed export N/o encl DEVINELU B Office of International Programs. Director 80/10/16
- 8010300586 Litense for QA Co to export miscellaneous equipment for use in nuclear reactor to West Germany Export of assembled pressure vessels.primary coolant pumps.fuel charging or discharging machines & control rods not authorized DEVIKE.J B Assistant Director for Export/Import & International Bafeguards. IEL-1195, 80/10/23 ip

NONDOCKETED ITEMS

- 8010300593 Amend 1 to License XU-8496 removing condition that no more than 250 kg of matl per country shall be exported to Albania,Romania & China DEVINE,J B Assistant Director for Export/Import & International Bafeguards 80/10/23 lp
- 8010310112 Executive Branch position re Monsanto Research Corp application for amend to license to add New Zealand to list of countries to which export of Pu-238 is allowed Amend should be issued NDSENZO, V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/10/20 3pp
- 8010310157 Requests Executive Branch position re Hestinghouse application for license to export SNM to South Korea for use as initial cores for three reloads & four spare assemblies for KNU power plant Units 7 & 8
 DEVINE, J.B. Assistant Director for Export/Import & International Safeguards 80/10/27 ip
- 8010310161 Amend 3 to license for OE Technical Svcs Co.Inc to export components & associated equipment of one BMR.w/power level of 1.000 MHeradding Fabbricazioni Nucleari SpA as addlintermediate consigned DEVINE.J B Assistant Director for Export/Import & International Safeguards BDM-80044 B0/10/24 1p
- 8010310165 Amend 1 to license for Monsanto Research Corp adding Naw Zsaland to list of countries to which radiation sources may be exported DEVINE, J B Assistant Director for Export/Import & International Befeguards 819 5000 80/10/24 3pp

- 8010310594 Forwards applications by Transnuclear, Inc for licenses to export 2965 1675 kg U to West Garmany Licenses YSNM-1757 & XSNM-1758 not enci MAT80M,V Transnuclear, Inc RBU-351 80-231/ 80/10/24 ip
- --8010310402 Application by Transnuclear, Inc for license to export 2745 1675 kg U,in form of U hexafluoride, to West Germany End use statement encl
 MATEGN, V Transnuclear, Inc RBU-352 80-232/ 80/10/24 3pp
- BO10310610 Application by Westinghouse for license to export one WL-8105 compensated ionization chamber to Indonesia End use statement encl POCHAL-W F Westinghouse Electric Corp ZE-60192 B0/10/22 Rpp
- 8010310614 Application by Wastinghouse for license to export incore nautron detector, containing 0 26 g enriched U-235, to Suitzerland POCHAL, W F Westinghbuse Electric Corp ZC-10327 80/10/22 ip
- E010310617 Amend 7 to license for Boeing Co to export 250,000 lbs depleted U in form of aircraft counterweights to 56 listed airlines List encl DEVINE, J B Assistant Director for Export/Import & International Safeguards 40~7783 80/10/28 3pp
- 8010310622 License for Air Products & Chemical, Inc to export 50 1 g deutarium to Argentina DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/10/28 2pp

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	EUB JECT CATEGORY
AAHODT, M. M	8010270517	50-287 G	AHEARN, C. D.	8010090319	50-445 M	ANDERSON, T, M	8010070589	TOPREP
ABEL, J B.	8010080150	PR	AHEARN, C. D.	8010080289	50-445 M	ANDERSON, T M	8010200322	PR
ABEL, J B	8010100007*	50-373 G	AHEARN, C. D.	8010080319	50-445 M	ANDERSON, T M,	8010240170	PR
ABEL, J B	8010280163*	50-237 G	AHEARN, C. D.	8010140002	50-445 M	ANDERSON, T M	8010230362*	TOPREP
ABEL, J B,	8010010693*	50-254 G	AHEARN, C. D.	8010140002	50-445 M	ANDERSON, R L	8010170066	NUREO
ABEL, J 8.	8010170205	FR	AHEARNE, J. F.	8010290290	50-289 U	ANDERBON, T. M	8010230436	TOPREP
ABEL, J 8.	8010010749*	50-254 Q	AHEARNE, J. F.	8010280284*	50-289 U	ANDERBON, T. M	8010210572	TOPREP
ABEL, J, B	8010170318*	50-275 Q	AHEARNE, J. F.	8010280288*	50-289 U	ANDERBON, T. M	8010290353	TOPREP
ABEL, J 8	8010150225	50-373 Q	AHEARNE, J. F.	8010280287*	50-289 U	ANDOGNINI, Q. C	8010030307	50-293 9
ABEL, J 8.	8010290192*	50-373 Q	AHEARNE, J. F.	8010280294*	50-289 U	ANDREWB, D. L	8010290416*	50-398 9
ABEL. J.S. ABEL. J.S. ABEL. J.S AMERCROMBIE. H ABERCROMBIE. H	8010210128 8010270414* 8010270345 8010130332 8010160507	PR 50-456	AHEARNE, J. F. AHEARNE, J. F. AMEARNE, J. F AMEARNE, J. F AMEARNE, J. F	8010280298* 8010280303* 8010280304* 8010300547 8010300535	50-289 U 50-289 U 50-289 U COMMISSION 50-320 U	Andrue, n J. Andrue, n J Andrue, C. D Ang, M. P Anepach, k G.	8010150650 8010210399* 8010140327 8010030509* 8010150636	40-4492 40-4492 50-367 A 50-369 G 27-39
ABRAMB, R	8010080269	PR	AHEARNE, J.F.	B010300537*	50-320 U	Anspach: K.O.	8010240045	27-39
ABT, B. R	8010300171*	WASTE HOT	AHEARNE, J.F	B010270495	50-320 U	Anspach: K.O	8010280015	27-39
ABUAF, N	8010230028	NUREO	AINGER, K.A	B010310346*	50-304 P	Anthony: J.M	8010210497*	50-327 B
ACKERHANN, N. J	8010060267	50-335 P	AKER, R.E	B010140457*	50-295 8	Appel: R.R.	8010230253	40-8728
ACKERHAN, W G	8010220383	40-8502	AKER, R.E.	B010140431*	50-295 8	Appelhans, A.D.	8010300178	RES
ACOSTA, A, J. ACOSTA, A, P. ACOSTA, A P. ADAN, U ADAN, U	8010200014	ACRB	AKER, R. E	8010210488*	50-295 B	ARCHBOLD, P	8010270084	PT21
	8010030137	40~8584	AKI, K	8010080315*	50-206 P	ARCHITZEL, R	8010010213*	50-317 Q
	8010210403	40~8584	ALBA, A	8010280448*	50-313 F	ARCHITZEL, R. E	8010020270*	50-317 Q
	8010030537	1&E	ALDEN, H. M	8010200458	50-277 P	ARCHITZEL, R	8010230464*	50-317 Q
	8010030546	1&E	ALDEN, H. M.	8010150377*	50-277 R	ARCHITZEL, R	8010240153*	50-317 Q
ADAN, P. J.	8010280725*	0A999	ALDRICH, D. C.	8010270174	NUREO	ARLOTTO, G	8010310470#	PRM
ADANS, J.	8010230712*	50-320 H	ALIKHANLOU, F	8010240558*	70-25	ARLOTTO, G. A	8010070289	PRM
ADANS, J	8010070505*	50-346 B	ALLAN, J	8010070548	50-334 B	ARLOTTO, G. A	8010270323	REGOD
ADLER, T. A.	8010030480*	50-289 G	ALLAN, J. A	8010100032	50-334 Q	ARNOLD, R. C.	8010060211	50-287 P
ADLER, T. A.	8010140570*	50-289 G	ALLENDER, Q. H	8010230568	CONTRACT	ARNOLD, R. C	8010060214#	50-289 P
ADLER: T. A	8010140612	50-289 Q	ALLENDER, Q, H	8010230575*	CONTRACT	ARNOLD: R. C.	8010060237	50-289 P
ADLER: R. W	8010140586	50-289 Q	ALLEN, J R.	8010270416*	50-338 G	ARNOLD: R. C	8010060244*	50-289 P
ADLER: R. W.	8010240069	50-289 Q	ALLEN, D. L.	8010160334*	CONTRACT	ARNOLD: R. C	8010060339	50-289 F
AGAP I TO: J. F.	8010170311*	CONTRACT	ALLENSPACH, F R	8010170001	NUREQ	ARNOLD: R. C	8010070457	50-289 H
AMEARNE: J. F.	8010020403	50-546 U	ALLISON, D. P	8009270143	50-10 P	ARNOLD: R. C	8010170225	50-289 P
AHEARNE, J. F.	8010060033	COMMISSION	ALLREDID L	8010080280	70-2909	ARNOLD, R. C.	8010170481	50-289 P
AHEARNE, J. F.	8010070631	COMMISSION	ALLREDID. L	8010080283*	70-2909		8010170516#	50-289 P
AHEARNE, J. F.	8010080152	40-1173	ALMIL.	8010090495*	50-254 P		8010240494	50-289 P
AHEARNE, J. F.	8010300132	COMMISSION	ANDERSONIS. L.	8010080557*	50-344 P		8010240500#	50-289 P
AHEARNE, J. F.	8010300138*	COMMISSION	ANDERSONIT M.	8010240194*	PR		8010160508	50-320 P
AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F.	8010080192 8010220115 8010220120* 8010100128 8010100130*	COWNISSION COMMISSION COMMISSION COMMISSION	ANDERSON, D. Q ANDERSON, T M ANDERSON, T. M. ANDERSON, D Q. ANDERSON, T M	8010080081* 8010160326* 8010010374 8010270376* 8009030499	QATTT TOPREP TOPREP QATTT TOPREP	ARNOLD, R. C ARNOLD, R. C ARNOLD, R. C, ARONSON, M. G ASH, R. F.	8010210450 8010240428 8010280403 8010280457 8010200418	50-289 F 50-320 P 50-320 P 50-466 H 50-317 P
AHEARNE, J F.	8010220162	70-2313	ANDERSON, C. J. ANDERSON, T. M. ANDERSON, C. R. ANDERSON, C. J. ANDERSON, T. M.	8010090495	50-322 A	ABH, R. F.	8010200505	NUREO
AHEARNE, J F.	8010220075	50-320 P		8010160709	PR	ASHAR, H.	7809180014*	REGOD
AHEARNE, J. F.	8010280085	COMMISSION		8010210061	REGOD	ASHTON, A. M.	8010170624*	CONTRACT
AHEARNE, J F.	8010290280	COMMISSION		8010060102	50-322 A	ASWELL, D. L.	8009300342	50-382 8
AHEARNE, J, F.	8010290281#	COMMISSION		8010020320	TOPREP	ABWELL, D. L.	8009300212	50-382 0
AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F. AHEARNE, J. F. AHEARN, C. D.	8010270284* 8010270288* 8010270348 8010270357* 8010080289	GOMMISSION COMMISSION COMMISSION SO-445 M	ANDERSON, T M ANDERSON, T. M. ANDERSON, T M ANDERSON, C ANDERSON, T M	8010230359 8010010552 8010210660 8010270238 8010210142	TOPREP TOPREP PR 50-322 A REGGD	ABWELL, D. L ABWELL, D. L ABWELL, D. L ABWELL, D. L ABWELL, D. L,	8010010582 8010010587* 8010010575* 8010060352 8010210458	50-382 K 50-382 K 50-382 B 50-382 B

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCERSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
ASHELL, D, L AUSTIN, M A AUSTIN, M A AUSTIN, M A AUSTIN, M A	8010280440 8010060028 8010020691* 8010210247* 8010130543	50-382 C 70-364 70-135 70-135 70-364	BARNES, I BARRETT, E M BARRY, D BARRY, J E BARTH, C, A	8010270126* 8010160762* 8010220518 8010230247 8010160050	0A999 50-516	BEACH, A B. BEARE, J A BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8010310336# 8010200660# 8010010696 8010030470 8010030517	50-458 Q CONTRACT 50-409 Q 50-409 Q
AUSTIN, M A AUSTIN, M A AUSTIN, M A AUTIO, H A AVANT, D.	8009250450 8010020202* 8010070144 8010160460 8010310463	71-6400 70-364 70-364 50-29 8 50-187 P	BARTH, C. A BARTH, C. A BARTLETT, J BARTLETT, J BARTLETT, J	8010220329 8010230481 8010010852 8010080478 8010300458	50-358 0 50-275 0 50-220 0 50-220 S 50-220 S	BECHHOEFER,C BECKHOEFER,C BECK,O P BECK,O P	8010240048 8010280555 80102001024 8010080524 8010210530	50-407 0 50-329 0 50-151 0 50-151 F 50-151 P
AXELROD, D. AXELROD, D. M AXELRAD, M. AXELRAD, M. AXELRAD, M. AYER, J. E.	8010290127#	8tate Prog	BARTLETT, J	8010310448	50-220 8	BECK.G P	8010210537	50-151 P
	8010020387#	COMMISBION	BARTO, J F	8010010296#	40-8385	BECKMAN,D A	8010010813*	50-334 Q
	8010080273	50-376 0	BASKIN, K P	8008150360	50-204 F	BECKMAN,D A	8010080163*	50-334 Q
	8010080273	50-376 0	BASKIN, K P	8010240075	50-361 0	BECKMAN,D	8010270041	50-334 S
	8010080266	70-1257	BASKIN, K P	8010080590	50-361 0	BEDNAR,L F	8010210639*	50-298 S
AYER, J.E AYER, J.E AYER, J.E AYLWARD, P.B. BACHMANN, R.O	8010150626* 8010240553* 8010150048 8010280735* 8010070533	70-1257 70-25 70-1257 0A999 70-1308	Baskin, k p Baskin, k p Baskin, k p Baskin, k p	8010010522 8010070568 8010070277 8010070462 8010080454	50-204 F 50-361 A 50-206 P 50-206 P 50-361 A	BEERS, F C BEERS, F C BEERS, F C BEHNKE, W B BELANGER, J L	8010150305* 8010150402* 8010150325* 8010020081 8010170544*	50-271 R 50-309 R 50-29 R 50-201 9 50-331 Q
Bachmann, R. O	8010170384	50-243 Q	Baskin, k p	8010140326	50-206 P	Belanger, J L	8010270125*	50-10 Q
Bachmann, R. O,	8010300046	70-1308	Daskin, k p	8010150284	50-206 P	Belin, A.	8010070532	50-445 H
Bacon, C. G	8010080431	50-289 H	Baskin, k p	8010080524	50-361 A	Belible, Q. A	8010240012*	50-321 Q
Badham, R. E	8010140607	50-204 H	Baskin, k p	8010150407	50-361 R	Belible, Q. A	8010310199*	50-302 Q
Baer, R. E	8010020636*	50-213 Q	Baskin, k p	8010150372	50-206 P	Belk, D. R	8010010546	50-369 Q
BAER, R. E.	8010220476*	50-933 Q	Backin, K.P	8010210328	50-206 V	BELLAMY, R, R	8010100415	50-320 8
BAER, R. E	8010230428*	50-277 Q	Backin, K.P	8010210636	30-361 A	BELLAMY, R ,	8010270046	50-320 8
BAER, R.	8010300490*	NUREQ	Backin, K.P	8010240491	50-206 P	BELBER, T M	8010200395	50-201 0
BAOAOLIO, H	8010270138*	50-275 Q	Backin, K.P	8010200354	50-206 P	BENDIX, B	8010080134	PR
BAOAOLIO, H	8010280035*	50-275 Q	Backin, K.P	8010280374	50-361 K	BENNETT, A B	8010200277*	50-327 P
BAQDEN, Q	8010270352	40-1162	BATCHELOR, K,	8010020694	FDIA	BENNETT, M 8	8010200160	40-8498
BAQOS, L.A.	8010140807	PR	BATEMAN, H H,	8010010323*	50-354 Q	BENNETT, M	8010200180	71-5026
BAILEY, R.J	8010230719*	50-54 G	BATEMAN, H,	8010080158*	40-1173	BENNETT, M A	8010140609	NUREO
BAILEY, R.J	8010240322*	50-289 G	BATEMAN, H H	8010060073*	50-354 Q	BEQUAI, A	8010170147*	NUREO
BAILEY, R.J	8010220084*	50-333 G	BATEMAN, H H	8010230100*	50-354 Q	BERO, R E	8010020057	40-8585
BAILEY,R J,	8010030142*	50-247 @	BATES, J. W	8010310340*	70-1151	BERKBIGLER, K.P.	8010080203	NUREO
BAILEY,R J,	8010300178*	70-364	BATES, J. W	8010030151*	70-1201	BERKOW, H. N.	8010270151*	50-286 P
BAIR, J, G	8010150449*	50-344 R	BATES, J. U	8010220038*	70-1151	BERMAN, L. N.	8010140197*	50-287 O
BAIRD, J, B	8010040113*	50-285 @	BATES, J. O	8010070529	50-329 A	BERMAN, M.	8010280668	TOPREP
BAIRD, J, B	8010230707*	50-298 F	BATUM, O.	8010170218	PR	BERNATH, L.	8010060101	PR
Baibden, L	8010090049	CONTRACT	BAUER, B	8010090429*	50-254 P	SERNREUTER, D L	8010300537	NUREO
Baibden, L	8010140226	CONTRACT	BAUER, E. O	8010020490*	50-277 P	BERNSTEIN, M R	8010270054*	40-269 H
Baibden, L	8010170368	CONTRACT	BAUER, E. Q.	8010200459*	50-277 P	BERNSEN, B A	8010200413	NUREO
Baibden, L	8010170377	CONTRACT	BAUER, T. L	8010210496	50-192 P	BERNSTEIN, D L	8010200665	50-483 O
Baibden, L	8010160102	CONTRACT	BAUM, P. W.	8010160470*	50-193 R	BERRY, Q T	8010220273	50-333 Q
Baibden, L	8010080185	CONTRACT	BAUM, P W.	8010280467*	50-133 8	BERRY, O T	8010220300	50-285 Q
Baibden, L	8010140091	CONTRACT	BAUM, P W	8010280471*	50-133 8	BERRY, O T	8010230488	50-549 Q
Baibden, L,	8010140105	CONTRACT	BAUSER, M A	8010160761	PR	BETH, R M	8010080418	50-141 J
Baibden, L	8010160107	CONTRACT	BAUSER, M. A	8010140549	PR	BETTENHAUSEN, L	8010100075#	50-272 Q
Baibden, L	8010160112	CONTRACT	BAUSER, M A	8010140555*	PR	BETTENHAUSEN, L	8010230539#	50-311 Q
Baibden, L.	8010160116	CONTRACT	BAUSER, M A BAUSER, M A BAUSER, M. A BAXLEY, B X BAXTER, T. A	8010140549	PR	BEVAN, W O	8010210273	REGOD
Baibden, L.	8010160122	CONTRACT		8010280017	PR	BEVERLY, C, R.	8010100023*	70-143
Baibden, L.	8010160125	CONTRACT		8010280017	PR	BEYEA, J	8010100067	50-287 F
Baibden, L.	8010160127	CONTRACT		8010310410*	50~366 8	BICKWIT, L	8010240344*	50-320 9
Baibden, L.	8010160132	CONTRACT		8010080251	50~483 Q	BICKWIT, L	8010140029	50-556 9
Baibden, L.	8010140139	CONTRACT	BAXTER.T.A BAXTER.T.A BAXTER.T.A BAXTER.T.A BAXTER.T.A	8010080251	50-483 0	Bickwit, L	8010060114	SECY
Baibden, L.	8010140339	CONTRACT		8010140541	50-483 0	Bickwit, L	8010100320	50-466 U
Baibden, L.	8010170383	CONTRACT		8010140541	50-483 0	Bickwit, L	8010200944	50-498 9
Baibden, L.	8010170447	CONTRACT		8010150401	50-483 0	Bielawski, A, P	8010080440	50-255 9
Baibden, L.	8010200242	CONTRACT		8010160025	50-483 0	Bielawski, A, P.	8010150040	50-255 9
Baibden, L. Baibden, L Baibden, L Baibden, L Bajema, D	8010200307 8010310581 8010240408 8010270004 8010200453*	CONTRACT CONTRACT CONTRACT CONTRACT 27-39	BAXTER, T. A	8010160025 8010200665 8010200671 8010200665 8010200671	50-483 Q 50-483 Q 50-483 Q 50-483 Q 50-483 Q	BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P.	8010150040 8010210532 8010210532 8010270384 8010270384	50-255
BAKER, K. R.	8010010857*	50-407 0	BAYLOR, J &	8010140057	PR	BIGIARELLI,H J	8010070335*	50-245 8
BAKER, C. E.	8010220299	40-8681	BAYNE, J P,	8010220487	PR	BIGIARELLI,H J	8010140450*	50-245 8
BALDASSARI, D.	8010220388	50-217 P	J C, SAYNE	8010020558	50-286 F	BIGIARELLI,H J	8010230428*	50-245 8
BALLARD, R. L.	8010140200	50-287 H	J P, SAYNE	8010030417	50-286 P	BINGGELI,B	8010020537*	50-295 8
BALLARD, R. L.	8010290299	50-320 R	J, P,	8010070307	50-286 F	BIRCH, M.L	8010040143	PR
Ballentine; J H Ballentine, J. H. Ballinger, P. L Baltid; R. H Barber, R. W	801015032& 8010150330* 8010140315* 8010220484* 8010210228	50-327 R 50-327 R 50-278 R 50-237 F REGOD	Bayne, J.P. Bayne, J.P. Bayne, J.P. Bayne, J.P. Bayne, J.P.	B010070309* B010100300 B010100315 B010150284 B010140489	50-286 P 50-286 P 50-286 F 50-286 P 50-333 P	BIRD, W. H BIRD, W. H BIRKEL, R. A BIRKEL, R. A. BIRKEL, R. A.	8010230433* 8010230369 8010080293 8010080643 8010140141	50-320 H 50-320 H 50-389 A 50-389 A
Barbour, C. H	8010230374*	50-289 0	Bayne, J. P.	8010160494*	50-933 P	BIRKEL,R A	B010270266	50-369 A
Tarker, J. L.	8010070176	50-249 8	Bayne, J. P	8010200456	50-286 F	BIRKEL,R A	B010270257	50-369 A
Tarker, J.	8010070136	50-10 8	Bayne, J. P	8010210764	PR	BIRKEL,R.	B010310076	50-369 A
Tarley, W	8010100417	50-320 8	Bayne, J. P.	8010200441	50-939 P	BISHOP,T H,	B010150031*	50-397 G
Tarnes, I.	8010210763*	QA999	Bayne, J. P	8010220362	50-286 F	BISHOP,T W.	B010240587*	50-460 G
IARNES, J. 'ARNES, I 'RNES, I. 'RNES, I. 'RNES, I.	8010090042	FOIA	BAYNE, J. P.	8010220528	50-333 F	BISHOP, T W.	8010310018*	50-508 @
	8010160676*	QA797	BAYNE, J. P.	8010280383	50-286 P	BISHOP, C J.	8009160205	50-155 @
	8010160312*	QA797	BAYNE, J. P.	8010290350	50-333 P	BISHOP, C J	8010010697	50-488 @
	8010210463*	QA797	BAYNE, J. P	8010310386	50-333 P	BISHOP, C J	80100220339	50-443 @
	8010080068*	QA799	BEACH, A. B	8010270030*	50-382 G	BISHOP, G J	8010240482	50-367 @

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BISKOP, C. J BISKOP, C. J BISKOP, C. J BISKOP, C. J BISKETT, P. H	8010270508 8010300693 8010300581 8010300589 8010020702*	50-367 0 50-443 0 50-443 0 50-367 0 70-135	Bosnak, R. J Bossenmater, W Bossenmater, W, Bossenmater, W Bostwick, W E	8010170280 8010080292 8010080373 8010130064* 8010300142	50-337 S 50-312 Q 50-312 Q 50-312 Q REB	Brigob, L Brigob, L Brigob, L Brigob, L Brigob, L	8010080348 8010240351* 8010100030* 8010080345 8010010420	50-272 8 50-219 9 50-219 9 50-219 8 50-219 8
BIESETT.P.H BLACK.R.L. BLACK.R.L. BLACK.R.L BLACK.R.L	8010230079* 8010060001 8010060006 8010070005 8010070029	70-371 50-466	BOTHMAN.J BOWKNIGHT.J A BOWKNIGHT.J A BOWKNIA.A BOWKNIA.A	8010100302 8010240063 8010150476 8010090477 8010220396	70-364 50-387 M 50-445 M 50-438 A 50-438 A	BRIGOB, L BRIGOB, L BRIGHT, R M BRIGHT, R M BRIGHT, R M	8010070222 8010080356 8010170213 8010010514 8010150668	50-219 8 50-289 8 PR 50-302 P 50-302 Q
BLACK, R. L BLACK, R. L BLACK, R. L BLACK, R. L BLACK, R. L	8010070033* 8010070495 8010070576 8010140518 8010170343	50-446	Bournia, a Bournia, a Bournia, a Bournia, a, Bournia, a	8010230010 8010210039 8010230594 8010170171 8010290417	50-373 A 50-373 P 50-373 A 50-373 A 50-373 A	BRIGHT,R M BRIGHT,R M BRIGHT,R M BRINDLEY,J H BRINKMAN,R,E	8010150370 8010200405 8010210631 8010280434 8010280157*	50-302 F 50-302 R 50-302 P 50-94 J FOIA
BLACK, R. L BLACK, R. L BLACK, R. L BLAKE, E. L BLAKE, E. L	8010210272 8010220325 8010310446 8010140491 8010140272	50-466	BOUNIAESTER, R BOVENDALE, P. C BOWDEN, D D BOWEN, H M BOWERS, C E	8010230013 8010030519* 8010080475 8010080511 8010010336*	NUREQ 50-156 G NUREO NUREO 70-820	BRINK, T BRINKLER, J E BRITTELL, F L BROCKETT, T W BROCKETT, T	8010280077* 8010140442* 8010170158* 8010020502 8010020503	50-287 H 50-307 B NUREO I&E I&E
BLCHBERO, K BLUHBERO, K BLUHBERO, K BODDY, J. R	8010140353* 8010290176 8010220707* 8010010100* 8010240564	50-275 A NUREO 50-213 G 50-245 G 40-8084	80WER8, E B 80WER8, E, 8 80WER8, E 8 80WER8, E 8 80WER8, E, 8	8010030438 8010030452 8010070004 8010270499 8010280566	50-514	BROCKETT.T W BROCKETT.T W BROCKETT.T W BROCKETT.T W BROCKETT.T W	8010020500 8010170100 8010020505 8010020584 8010290177	40-672 50-321 8 115 115 116 40-8084
Bootke.P J Booden.O. Booden.O. Booden.O. Booden.O.	8010150459* 8009090219 8010020132 8010140171 8010140627	50-295 R 40-1162 40-1162 40-1162 40-1162	BOWERS, E, 8 BOWERS, E 8 BOWERS, E 8 BOYD, D, C BOYD, D, C,	8010280529 8010300572 8010300574 8010140387 8010100412	50-250 0 50-322 0 50-322 0 50-255 8 50-275 8	BROCKETT.T N BROEML, D J BROEML, D J BROEML, D J BROEML, D J	8010200704 8010270367 8010010370* 8010060274 8010210443	50-313 8 50-344 0 50-344 0 50-344 8 50-344 P
Booden, G. Booden, G. Booden, G. Booden, G. Booden, B.	8010150658 8010240004 8010230248 8010270302 8010070628*	40-1162 40-1162 40-1162 40-1162 50-289 0	BOYD, D. C. BOYD, D. BOYD, D BOYD, D C BOYD, D C	8008040274 8009030035 8010090293 8010080371 8010080338	50-282 8 50-255 8 50-255 8 50-255 8	BROEHL: D J BROMBERG: B BROMBERG: B BROMBERG: B BROMBERG: B	8010220351 8010010247 8010010291 8010010366 8010090027	50-344 P CONTRACT CONTRACT CONTRACT CONTRACT
Boger, B. A Bogos, L. A. Bohn, R. J. Bohn, R. J. Bohn, R. J.	8010070639* 8010140074 8010070475 8010150329 8010210526	50-289 0 PR 50-367 R 50-367 R 50-367 R	BOYD, D. C. BOYD, D. C. BOYD, D. C BOYD, D. C BOYD, D. C	8010080362 8010010837* 8010100387 8010100386 8010100418	50-255 8 50-409 0 50-409 8 50-255 8 50-155 8	Bromberg. B. Bromberg. B. Bromberg. B Bromberg. B Bromberg. B	8010070040 8010070058 8010170086 8010070016 8010310574	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
BOLINE, K. F BOLLAG, L. BOLLING, L. A BOLLING, L. A BONETTI, D. J.	8010310281 8010200599 8010170254 8010270541 8010140585*	PRDJ 50-369 0 1&E 1&E 50-289 0	BGYD, D C BOYD, D, C BOYD, D, C BDYD, D, C, BDYD, D, C,	8010090283 8010150126* 8010090234 8010090245 8010090277	50-255 B 50-155 G 50-409 B 50-255 B 50-255 B	BROOKS, J. BROOKS, E. H. BROUN, G. H BROWNLEE, V. L.	8010300552* 8010270068* 8010230223 8008060278 8010300428*	COMMISSION 50-261 Q PR 50-263 S 50-369 Q
BOOK: H E BOOK: H. E BOOK: H E BOOK: H. E.	8010130518# 8010140047# 8010140044# 8010160031 8010210447#	50-320	BOYD.D C BOYD.D C BOYD.D BOYD.D C BOYD.R.S.	8010080250* 8010070280 8010080626 8010270224* 8010220123	50-274	Broun; R. L Brown, C. Brown, O D Brown, R. L Brownlee, V. L	8010270108* 8010150138* 8010010475* 8010080111* 8010170278*	GA999 50-263 G 40-8027 GA999 50-321 G
BOOK, HE BOOK, HE BOOK, HE BOOK, HE. BOOK, HE.	E010270373* E010270371 E010100052* E010100047 E010200034*	70-754 70-754 50-137	BOYD.D.C BOYER,V B BOYER,V B BOYER,J C	8010310585* 8010020490* 8010070333 8010150389 8010290201	50-116 G 50-277 P 50-352 A 50-352 A 50-320 H	Brown, G D Brown, R L Brown, G D Brown, G D	8010010468* 8010240364* 8010070154* 8010040113* 8010070148	40-8027 QA979 40-8502 50-285 Q 40-8502
BOOK, H. E BOOK, H. E BOOK, H. E BOOK, H. E,	8010200021 8010280706* 8010280675 8010280701* 8010310389*	50-361 Q 50-106 Q 50-106 Q 50-206 Q	Boyle, e Brachman, v. Bradford, p. a. Bradford, p. a. Bradford, i	8010310549 8010070440x 8010150624x 8010150627x 8010080225x	FOIA FOIA	BROWN, O D BROWN, G D BROWNLEE, V L BROWN, G D	8010140037 8010040111 8010230707* 8010240463* 8010220644*	50-274 Q 50-285 Q 50-298 F 50-348 Q 40-4472
BOOK, HE, BOOKE, B. C., BOOKE, J. M. BORDENICK, B. M BORDENICK, B. M	8010070211 8010300070* 8010310985* 8010020034 8010010003	50-206 8 40-1162 50-116 0 50-322 0 50-582 0	BRADLEY, R. T BRADLEY, E J BRADLEY, F J BRADLEY, E. J BRADLEY, E. J	8010080475 8010020488 8010020470* 8010080541 8010240522	NUREO 50-277 P 50-277 P 50-277 F 50-171 J	BROWN, G. D BROWN, R. S BROWN, G. D BROWN, G. H	8010220634 8010030434 8010270107* 8010210384* 8010240038*	40-4492 CONTRACT 50-259 Q 40-8584 50-263 Q
BORDENICK, B. M BORDENICK, B. M BORDENICK, B. M BORDENICK, B. M. BOREB, R. J	8010010010 8010160979 8010160770 8010280545 8010060081*	50-514 0 50-322 0 50-592 0 50-498 0 50-29 0	BRADLEY: E J. BRADLEY: E J. BRADLEY: E J. BRADLY: R J. BRAMBERO: B	B010200457 8010200451 8010210329 8010020710 8010080461	50-277 P 50-277 P	DROWN, O. D. BROWN, J. F BROWN, J. F BROWN, D. F	8010210378 8010010485 8010140129* 8010140401* 8010020024	PR
BORES, R J BORES, R J BORES, R, J, BORES, R J BORES, R	8010010224* 8010020218* 8010010382* 8010010404* 8010080380	50-412 G 50-293 G	BRAMLETT.L 8 BRAMLETT.L 8 BRAMLETT.L 8. BRAMLETT.L 8 BRAMLETT.L 8	B010010500; B010170243; B010210423; B010280552; B010280572	50-313 E 50-313 R 50-313 E	9ROWN, O. D 8ROWN, G. D 8ROWN, H. H 8ROWN, H. H 8ROWN, H. H.	8010150043 8010310098 8010030310 8010030385 8010030385	40-8084 40-8084 50-275 Q 50-275 Q
Boreb, R. J. Borchann, E. A. Borchann, E. A. Borchann, E. A. Borchann, E. A. Borco, G. J.	8010240136* 8010240035* 8010090114 8010200313* 8010240557	50-358 Q 50-358 Q	BRAMLETT,L S, Branch,W Braulke,O R Bray,T C. Breaux,D Q	8010280591 8010090234 8010200687 8010230364 8010080081	50-409 8 50-289 T 50-8 J # GA999	Brown IB. Brown II S Brown G. D Brown G. D. Drown W J	8010150313* 8010080515* 8010220343 8010100085 80102005744	50-315 8 40-8102 , 50-274 G
BORGO, Q. J. BORHAUG, J. E. BORBT, F. J. BOSNAK, R. J. BOSNAK, R. J.	8010240555 8010100318* 8010230709* 8010020013 8010170011		BREIG,M L BREITMAYER,F BREBBON,T,H, BRICKLEY,R,H, BRICKLEY,R H,	8010170078 8010020012 8010020705 8010270576 8010280735	FQIA * QA999	eroun, H. H. Brown, H. H. Brown, O. F. Eroun, O. D Broun, S. C.	8010080300 8010080300 8010140519 8010210396 8010150304	50-275 0 50-275 0 PR 40-4472 50-339 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
9ROWN, 8. C, 9ROWN, H H 9ROWN, H, H 9ROWN, H H 9ROWN, H H	8010160580 8010160544 8010160544 8010200662 8010200662	50-339 P 50-275 G 50-275 G 50-275 G 50-275 G		8010240042* 8010140024 8010230704* 8010070497 8010150378	50-483 B	CALDWELL, R A CALHOUN, J R CALHOUN, J R CALHOUN, J R, CALHOUN, J R	8010270531* 800919043B 8010030369 8010030411 8010060299	50-298 0 50-296 8 50-260 8 50-259 8 50-276 8
BROHN, G D. BROWN, L J. BROWN, L J. BRUGGER, R. K	9010270226 8010300590 8010230685 8010230685 8010280378	14E 14E 50~133 G 50~133 Q 50~184 B	BRYAN, J.K. BRYAN, B.E. BRYSON, B. BUCHHOLZ, R. H. BUCHHOLZ, R. H.	80102902514 8010310160 9010290061 8010140017 8010020335	50-483 8 50-237 Q FOIA PR TOPREP	CALHOUN, J R	8010040327 8010040310 8010070572 8010080461 8010080463*	50-259 B 50-296 B 50-327 B 50-259 B 50-259 B
BRUNNER, E J. BRUNNER, E, J. BRUNNER, E, J. BRUNNER, E, J. BRUNNER, E, J.	8010010182* 8010020765* 8010220703* 8010010805* 8010010089*	50-245 Q 50-219 Q 50-334 Q 50-245 Q	BUCHHOLZ,R H BUCHHOLZ,R H BUCHHOLZ,R H, BUCHHOLZ,R H BUCHHOLZ,R H	8010020333 8010100312 8010130252 8010140541 8010400214	TOPREP TOPREP TOPREP TOPREP NUREO	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R. CALHOUN, J. R.	8010080385 8010070485 8010140383 8010210488 8010210727	50-327 8 50-259 8 50-294 8 50-327 8 50-327 8
BRUNNER, E. J.	8010060081* 8010080364 8010010616* 8010100040* 8010080368	50-277 8 50-272 0 50-336 0 50-272 8	BUCHHOLZ, R, H BUCHHOLZ, R, H BUCHHOLZ, R, H BUCHHOLZ, R, H BUCHHOLZ, R, H	8010060216 8010030464 8010210332 8010100352 8010160530	NUREO TOPREP TOPREP TOPREP TOPREP	CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R.	8010140365 8010150513 8010210678 8010210702 8010210514	50-260 B 50-260 B 50-259 B 50-260 B 50-327 B
BRUNNER, E. J. BRUNNER, E J BRUNNER, E J BRUNNER, E J. BRUNNER, E J	8010020282 8010100065# 8010020224 8010010120# 8010080530	50-317 Q 50-272 Q 50-286 Q 50-277 Q 50-273 8	BUCHTER, R BUCK, C. P BUCK, J. H BUCKHAM, J. A BUCKLEY, B. C	8010140275 8010140230* 8010300037 8010100134 8010210045	50-320 P CONTRACT 50-275 T PR 50-275 F	CALHOUN, J R.	8010210654 8010200408 8010210634 8010210658 8010210669	50-327 8 50-257 8 50-327 8 50-260 8 50-327 8
BRUMMER, E J BRUMMER, E J BRUMMER, E J BRUMMER, E, J	8010010171 8010080156 8010010345 8010220135 8010270176*	50-289 @ 50-334 @ 50-286 @ 50-29 @ 50-309 @	BUCKLEY, B C. Buckley, B, C Buhl, A, R. Builder, C H Builder, C H	8010270015 8010270017* 8010310366 8010020115* 8010020128*	50-461 A 50-311 P Nureo Foia Foia	CALHOUN, J R	8010210493 8010210694 8010210435 8010210490 8010210701	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8
BRUNNER, E. J.	8010080544 8010230283* 8010100026 8010210278 8010100055	50-277 8 50-272 9 50-219 9 50-286 9 50-309 9	BURDETTE, T E, BURGESB, B, BURGESB, B, L. BURGER, F, J BURIAN, R, J,	8010300428+ 8008060269 8008060274 8010150305+ 8010020122	50-367 0 50-282 8 50-282 8 50-271 R 71-5957	CALHOUN; J. R CALHOUN; J. R CALHOUN; J. R. CALHOUN; J. R CALHOUN; J. R.	8010210659 8010210682 8010210691 8010270349 8010270483	50-327 6 50-296 6 50-259 8 50-327 6 50-260 8
BRUNNER, E. J.	8010240266* 8010010407 8010240038 8010010603 8010020760	50-271 Q 50-320 Q 50-244 Q 50-272 Q 50-245 Q	BURIAN, R. J. Burkmart, H. Burkmardt, H Burkmardt, H Burnett, J. T	8010010645 8010080266 8010150626* 8010240553* 8010310057*	71-5757 70-1257 70-1257 70-25 40-8084	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R. CALLAHAN, G. J	8010280463 8010280468 8010280518 8010280563 8010020270*	50-327 B 50-259 S 80-327 S 50-259 B 50-317 G
BRUNNER, E J BRUNNER, E J BRUNNER, E J. BRUNNER, E J BRUNNER, E J	8010230112 8010240144 8010240133* 8010230332 8010240127	50-244 Q 50-317 Q 50-247 Q 50-311 Q 50-247 Q	BURNETT, R F. BURNETT, P T. BURNETT, R F. BURNETT, R, F. BURNETT, R, F.	8010070635 8010150053* 8010070629 8010150083 8010100255	70-1257 50-335 0 70-734 70-371 70-1173	CALLAMAN, C, J, CALLAN, L J CALLAN, L J CAMM, F, A	8010240153* 8010240028* 8010210405* 8009250328 8009250329*	50-317 0 50-313 0 50-313 0 50-327 F 50-327 F
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8010240161 8010010107 8010240142 8010240119 8010080563	50-213 Q 50-277 Q 50-247 Q 50-322 Q 50-271 B	BURNETT, R F. BURNETT, R. F. BURNETT, R. F. BURNETTE, O W BURNETTE, O W	8010100256 8010100276 8010150080 8010150137 8010150563	70-364 70-820 70-25 REB REB	CAMPBELL, D. D. CAMPBELL, R. H. CAMPBELL, H. R. CAMPBELL, J. R. CAMPBELL, V. W.	8010070377* 8010270078* 8010200370* 8010170221 8010030477	NUREO WASTE MOT 40-341 PR 50-201 0
BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J	8010090127 8010010795 8010100057 8010240289 8010080545	50-223 8 50-334 Q 50-272 Q 50-27 Q 50-219 S	BURNETT, R. F Burnett, R. F. Burne, D. Burne, B. O. Burne, B. O.	8010150084 8010210755 8010280107 8010060019 8010280598	70-734 70-820 40-8710 50-409 0	CAMPBELL, R A CANADY, K. 8 CANADY, K S CANNON, C P CANNON, J, M	8010210513 8010020077* 8010020068* 8010230038 8010150594	50-275 Q 50-369 Q 50-369 Q NUREO 27-39
BRUNNER, E J. BRUNNER, E J. BRUNNER, E, J. BRUNNER, E J. BRUNNER, E J.	8010010420 8010090222 8010200605 8010220679 8010240332	50-219 8 50-219 8 50-220 8 50-219 0 50-219 0	Durns, g. C. Burrs, g. C. Burrohs, A Burrstein, B Burretein, B	8010280505# 8010300077 8010280648# 8010080172 8009260644	30-409 0 50-255 0 50-313 F 50-266 0 50-266 F	CANNON, J M. CANTRELL, F. 8 CANTRELL, F. GANTRELL, F. 8 CANTRELL, F. 8.	8010150603 8010160353 8010090321 8010020779# 8010160696	27-39 50-553 8 50-566 8 50-436 9 50-566 8
BRUNNER, E. J.	8010090218 8010230268 8010240352 8010170007 8010240252	50-309 8 50-272 9 50-244 9 50-293 8 50-271 9	BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8. BURSTEIN, 8.	8010060355 8010210500 8010210546 8010210625 8010240517	50-266 P 50-266 F 50-266 P 50-266 P 50-266 P	CANTRELL, F. 8 CAPHTON, D. L. CAPHTON, D. L. CAPHTON, D. L. CAPHTON, D.	8010070244* 8010100075* 8010010178* 8010230539* 8010290127	50-518 0 50-272 0 50-287 0 50-311 0 50-223 6
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. RUNNER, E. J.	8010220629 8010270039 8010270041 8010270545 8010310384	50-317 8 50-277 8 50-334 8 50-278 8 50-329 K	BURSTEIN, S BURTON, J. L BURTON, J. L BURHELL, S. B. BURWELL, S. B.	8010240183 8010020663 8010270275* 8010150186 8010270025	50-266 F 50-201 Q COMMISSION 50-445 A 50-445 A	CAPODANNO, G R CAPPUCCI.A.J. CARDONE.A T CARLISLE.C.B. CARLSON,R.T	8010240057 8010200650 8010210286 8010280392 8010060056	50-287 T 50-337 P 50-341 0 PROJ 50-334 Q
IRUNNER, E. J. JRUNO, Q. E. BRYANT, J. C. BRYANT, J. C.	8010310376 8010150492 8010310034* 8010010503* 8010310047*	50-327 Q 50-275 H 50-413 Q 50-483 Q 50-413 Q	BURNELL, 8, 8 BURNELL, 8 B. BUTLER, 8, 0 BUY, J D. BYRD, G, M.	8010300440 8010300358 8010170041* 8010140582* 8010170459	50-445 A 50-445 A 50-327 Q 50-466 Q XPORTLIC	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T CARLBON, R. T, CARLBON, R. T,	8010010314# 8010020144# 8010140033# 8010140056#	50-354 G 50-412 G 50-387 G 80-352 G
BRYANIJ. K BRYANTIJ. G. BRYANIJ. K. BRYANIB. E. BRYANIJ. K.	8010170961# 8010020725# 8010170180# 8010140070 8010270242	50-493 q 50-399 q 50-483 8 50-364 A 50-483 8	CADY, H. B. CAHN, A. L. CAHN, A. L. CAIN, C. L. CAIN, C. L.	6007050268 8010200007 8010220177 8010220461 8010070164	50-382 8 PR PR I&E I&E	CARLBON, R. T CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	8010010396 8010020058 8010010365 8010030017*	50-333 Q 50-277 Q 50-423 Q 50-443 Q 50-443 Q
BRYANT, J. C. BRYAN, J. K. BRYANT, J. C. BRYANT, J. C. BRYAN, J. K.	8010240173* 8010140032* 8010240346* 8010080226* 8010100082*	50-413 G 50-483 S 50-413 G 50-400 Q 50-483 G	CAIN. L. F. CAIN. C. L. CAIN. C. L. CAIN. C. L. CAIN. C. L. CALDWELL, R. A.	8010010442* 8010240360 8010240362 8010240367 8010030181*	CONTRACT 70~2876 40-8611 40-8672 50-274 Q	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	8010100087 8010020205 8010020222 8010100018	50-410 G 50-354 G 50-322 G 50-289 G 50-352 O

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
CARLEON, R. T CARLEON, R. T CARLEON, R. T CARLEON, R. T CARLEON, J. D	8010100099 8010210317 8010020138 8010070675 8010090379*	50-410 G 50-322 G 50-412 G 50-387 A 50-344 G	CARUBO, R. CARUBO, R. CARUBO, R. CABE, E O. CATCHPOLE, O J.	8010060081* 8010230578 8010280148 8010310070* 8010150632	50-27 Q 50-27 P 50-27 F 50-424 Q 40-8745	CRILK.8 J. CHILK.8 J. CHILK.8 J. CHILK.8 J. CHILK.6 J.	8010100131 8010100132 8010100071 8010100124 8010150411	50-579 Q 50-219 Q 50-389 Q 50-346 Q FOIA
CARLSON, R. T CARLSON, R. T CARLSON, R. T. CARLSON, R. T CARLSON, R. T	8010040073* 8010230033 8010040068 8010230153 8010230075	50-354 Q 50-387 Q 50-354 Q 50-336 Q 50-354 Q	CATCHPOLE. 0 J. CATCHPOLE. 0 J. CATCHPOLE. 0 J CATCHPOLE. 0. J CATCHPOLE. 0. J	8010200177 8010230260 8010160529 8010210357 8010210392	40~8745 40~8745 40~8745 40~8745 40~8745	CHILK, 8 J. CHILK, 8 J. CHILK, 8 J. CHILK, 8 J. CHILK, 8 J.	8010310459 8010160077 8010160148 8010200573 8010200551	PRM 50-536 0 50-536 0 50-142 0 50-344 0
CARLEON: R. T CARLEON: R. T. CARLEON: R. T. CARLEON: R. T. CARLEON: J. D.	8010020708 8010230522 8010010417 8010230704 801010363*	50-322	CATCHPOLE: 0 J. CATE: C L CATTON: I. CATTON: I CATTON: I	8010280379 8010140353* 8010210161 8010170084 8010150642	40-8745 50-275 A ACRS 50-327 D ACRS	CHILK: 8 J. CHILK: 8, J. CHILK: 8, J. CHILK: 8, J.	8010210510 8010210519 8010210522 8010210525 8010220532	50-3 0 50-376 0 50-217 0 50-263 0 50-488 0
CARLEON: R T. CARLEON: R T. CARLEON: R T CARLEON: R T CARLEON: R. T	8010010302 8010240281 8010020153 8010150029 8010240242	50-354 Q 50-277 Q 50-354 B 50-410 B 50-423 Q	CATTON, I, CATTON, I, CATTON, I CAVANAUGH, H, CAVANAUGH, H	8010160114 8010150544 8010230042 8010240085 8010070494	ACR8 ACR8 NUREO 50-313 G 50-368 P	CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	9010220542 8010220537 9010230508 8010230513 8010240046	50-599 0 27-39 50-546 0 50-458 0 50-409 0
CARLSON, R. T CARLSON, R. T CARLSON, R. T. CARLSON, R. T. CARLSON, R. T.	8010100024 8010100072 8010140049 8010150211 8010200697	50-352 Q 50-352 Q 50-352 Q 50-354 8 50-443 8	Cavanaugh; W. Cavanaugh; W. Ceibzkiewicz, 8. Celey; J. L	8010070308 8010240541 8010310286 8010210441* 8010140034*	50-313 P 50-368 K 50-313 P 50-10 R 50-413 Q	CHILK/B J, CHILK/B J, CHILK/B, J, CHILK/B, J CHILK/B, J,	8010270038 8010270304 8010270348 8010270347 8010300057	50-327 0 50-250 0 27-39 50-331 0 50-142 0
CARLSON, R. T CARLSON, R. T CARLSON, R. T, CARLSON, R. T, CARLSON, R. T.	8010200703 8010140028 8010100077 8010150182 8010270100	50-443 S 50-387 Q 50-334 Q 50-412 S 50-412 S	Ceragan, D. A Cerne, A. C. Chadhick, J Champagne, A. J. Chan, C. K.	8010090438* 8010030017* 8010210691* 8010030484 8010230042	50-265 P 50-443 0 50-348 H 50-201 0 NUREO	CHILK, B. J. CHILEON, V. T. CHIRIODS, J. N. CHONG, L. K. CHONG, L. K.	8010300567 8010150341* 8010080557* 8010090124* 8010090119*	50-599 Q 50-250 R 50-344 P 50-322 Q 50-322 Q
CARLSON, R. T CARLSON, J. D CARLSON, R. T CARLSON, R. H CARLSON, L. R.	8010270199 8010300438* 8010230710 8010090192* 8010280437	50-462 8 50-243 Q 50-352 G 71-4698 50-263 I	GHAMIA. I.Y. GHANANIA.F.D. GHANANIA.F.D. GHANANIA.F.D. GHANDLER.L.J.	8010230038 8010140497 8010140525 8010160568 8010010602*	NUREQ 50-498 M 50-445 M 50-445 M 50-361 Q	CHONO, L. R CHOULEB, N. G. CHOULEB, N. CHOULEB, N. CHOULEB, N. C.	8010030462 8010300479 8008250080> 8010100288 8010150102*	NUREO NUREO 50-305 8 50-301 9
CARPENTER, F. D CARR, J CARR, J H. CARROLL, J T. CARROL, E. E.	8010070434 8010020716# 8010020255# 8010140255# 8010090480	TOPREP CONTRACT CONTRACT 50-219 P 70-1048	CHANDLER, L. J. CHANDLER, L. J CHANDLER, L. J CHANDLER, L. J CHAPLIN, 8	8010010598 8010030426* 8010030444 8010210286 8010030412*	50-361 0 50-361 0 50-361 0 50-361 0 50-320 8	Chouleb, N C. Chribbotimob, N Chribtopher, R. K Chribbotimob, N	8010160187* 8010100411 8010090252 8010240351* 8010150090*	50-305 Q 50-245 B 50-331 B 50-217 Q 50-254 Q
CARTER, K. CARTER, R. B. CARTER, K. B. CARTER, K. H. CARTER, K. H.	8010010353 8010140217 8010140220# 8010140586 8010240069	NUREQ 50-184 R 50-184 R 50-289 Q 50-289 Q	CHAPLIN: B. D. CHAPLIN: B. D. CHAPLIN: B. D CHAPLIN: B. D CHAPHAN: L. D.	801080474* 801020422* 801020426* 8010310439* 801070008	50-320 8 50-320 8 50-320 8 50-320 8 NUREO	CHRIBTIANBON, W. CHRIBBOTIMOS, N. CHRIBBOTIMOS, N. CHRIBBOTIMOS, N. CHRIBTENBEN, D	8010180112* 8010090270 8010010336* 8010090258 8010080386	50-331 0 50-254 8 50-315 0 50-254 8 NUREO
CARTURIOHT, W. R. CARTURIOHT, W. R. CARTURIOHT, W. R. CARTURIOHT, W. R. CARTURIOHT, W. R.	8010060221 8010060231* 8010070301 8010070304* 8010070499	50-337 8 50-337 8 50-337 8 50-337 8 50-337 8	CHAPMAN, R. H CHAPMAN, L. D CHARNOFF, O. CHARNOFF, O. CHARNOFF, G.	8010100200 8010170118 8010080251 8010080251 8010140541	NUREO RES 50-493 O 50-483 O 50-483 O	Christensen.d. Christian, H. J Christenbury. E. Christoffer. O Christoffer. O	8010080389 8010240340 8010100207 8010170538# 8010290125*	NUREO MIBC 50-255 0 50-10 Q
CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W. R. CARTHRIGHT, W. R CARTHRIGHT, W R	8010070503 8010070512* 8010070513* 8010070515 8010070522	50-339 8 50-339 8 50-339 8 50-339 8	Charnoff, O. Charnoff, O. Charnoff, O. Charnoff, Q. Charnoff, G.	8010140541 8010160025 8010160025 8010200665 8010200671	50-483 0 50-483 0 50-483 0 50-483 0 50-483 0	Chanes a. H. Chang, d. H. Chanes a. H. Chabe a. Y. V.	8010230323 8010220707* 8010100044* 8010300537 8010280523*	50-201 0 50-213 0 50-336 0 NUREQ 50-213 8
CARTHRIOHT, W R CARTERIOHT, W R CARTHRIOHT, W. R. CARTHRIOHT, W. R. CARTHRIOHT, W R.	8010070525* 8010070536* 8010070580 8010070584 8010070590*	50-339 8 50-339 8 50-338 8 50-339 8 50-338 8	Charnoff. Q. Charnoff. Q. Charnoff. G Charvulu, M. K. Chase. J. H.	8010200665 8010200671 8010240435 8010010412 6010230483*	50-483 0 50-483 0 50-266 0 NURE0 50-257 @	CHUNIS, J. A. CIANGIOSI, P. CILLIS, M. CILLIS, H. CLARDY, L. S.	8010280528% 8010280647% 8010310389% 8010270538 8010150112%	50-213 8 50-287 H 50-204 Q 50-206 B 50-331 Q
CARTHRIGHT, H. R. CARTHRIGHT, H. R. CARTHRIGHT, H. R. CARTHRIGHT, H. R. CARTHRIGHT, H. R.	8010070596* 8010070602 8010070607* 8010140397 8010140409*	50-339 8 50-339 8 50-339 8 50-339 8	Chaudhary, B. K. Chaudhary, B. K. Cheney, D. Cheng, H. B. Chern, H. B	8010240351* 8010100103* 8010270519* 8010220627 8010150528	50-410 Q	CLARK, A. T. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8010140158 8010010045 8010010535 8010010707 8010010715	70-1308 50-246 P 50-348 P 50-317 P 50-335 P
CARTHRIONT, W.R. CARTHRIONT, W.R. CARTHRIONT, W.R. CARTHRIONT, W.R. CARTHRIONT, W.R.	8010140415 8010140423# 8010140427 8010140436# 8010150456	50-338 8 50-338 8 50-338 8 50-338 8 50-339 8	CHEBMAN A. CHEBTER R. D. CHILDB H. V. CHILDB W. V. CHILDB W. V.	8010220516 8010280597 8010230185 8010060347* 8010210677*		CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8010010721 8010060107 8010080329 8010010141 8010010547	50-336 P 50-336 P 50-317 P 50-265 P 50-344 P
CARTURIONT; W. R. CARTURIONT; W. R. CARTURIONT; W. R. CARTURIONT; W. R. CARTURIONT; W. R.	8010150466* 8010220479 8010220482* 8010210686 8010210694*	50-339 8 50-339 8 50-339 8 50-338 8 50-338 8	CHILES, L, CHILES, L., CHILK, S. J. CHILK, S. J. CHILK, S. J.	8010280105* 8010080198* 8010270087* 8010100097 8010170092	COMMISSION	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8010060137 8010060141# 8010060143# 8010010147 8010010482	50-335
CARTHRIOHT, W. R. CARTHRIOHT, W. R. CARTHRIOHT, H. R. CARTHRIOHT, W. R. CARTHRIOHT, W. R.	8010220466 8010220470* 8010220477 8010220478* 8010220659	50-337 6 50-337 8 50-338 8 50-338 8 50-338 8	CHILK, 8, J. CHILK, 8. J. CHILK, 8. J. CHILK, 8. J. CHILK, 8. J.	8008130252 8010170112 8010170115 8010010710 8010010687	SO-321 O XPORTLIC XPORTLIC SO-287 O SO-201 O	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, D. Q. CLARK, D.	8010080241 8010080246# 8010080260# 8010140451# 8010070367#	50-317 F 50-317 F 50-317 F 50-254 B 50-254 B
CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R. CARTURIONT, W.R.	8010220645# 8010230414 8010230420# 8010280847 8010280856#	50-336 8 50-336 8 50-337 8	CHILK: \$, J. CHILK: \$, J. CHILK: \$, J. CHILK: \$ J. CHILK: \$, J.	8010010703 8010020715 8010160745 8010100127	50-344 9 50-250 9 XPORTLIO 50-263 9 27-39	CLARK; R. A. CLARK; R. A. CLARK; R. A. CLARK; R. A. CLARK; R. A.	9010090555 9010230343 9010230133 9010230314 9010230314	50-344 P 50-338 F 50-246 F 50-246 P 50-344 P

AUTHOR	ACCESSION NUMBER	SUBJE		AOHTUA	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	BUBJEC'	
CLARK, R A CLARK, R A CLARK, R A CLARK, R. A CLARK, R A	8010280014 8010280018 8010220151 8010280588 8010290363	50-246 50-282 50-317	P P P	COLEMAN, R COLEMAN, R. COLEMAN, R. COLEMAN, R. W COLEMAN, R	8010220692 8010160217 8010270193 8010160233 8010170314	CONTRAC CONTRAC CONTRAC CONTRAC CONTRAC	T T T	CONTE, R. CONTESBA, W B CONTE, R J CONVERSE, W E CONWAY, W F	8010300337* 8010270135 8010300577 8010070298* 8010030513	50-320 FOIA 50-269 50-298 50-271	9
CLARK, R. A CLARK, J. R CLARK, R. A CLARK, R. A CLARK, R. A	8010300437 8010070283 8010240282 80102402926 80102403026	50-338	P P P	COLEMAN, L R. COLEY, J L COLL, N A COLLINGHAM, R E	8010140519 8010270086 8010230262* 8010030312 8010150452*	PR CONTRAC 50-546 50-250 50-10	T Q O P	CONWAY, W F CONWAY, W F CONWAY, W F CONWAY, W F CONWAY, W F	8010030522 8010240262# 8010150300 8010280337 8010280345	50-271 50-271 50-271 50-271 50-271	g e R g
CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8010300460 8010230300 8010230309* 8010230315* 8010240094	50-344 50-336	ь Б	COLLINS, M COLLINS, J T. COLLINS, J T. COLLINS, J T. COLLINS, J	8010140374 8010140357 8010140350 8010100419	50-27 50-320 50-320 50-320 50-320	8 8 8	COOK, J W. COOK, R. J COOK, J W. COOK, J W.	8010030218 8010200335* 8010140332* 8010210077* 8009300507	50-329 50-329 50-329 50-329 50-329	R 9 9 8
CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A	8010240078* 8010240102* 8010280672 8010300351 8010300358*	50-334 50-264 50-344 50-344	ኔ ቴ ቴ	COLLINS, J COLLINS, J COLLINS, R COLLINS, F M	8010100417 8010100415 8010240278* 8010280121* 8010080618*	50-320 50-320 50-271 50-267 CONTRACT	0 0 8	COOK, J. W COOK, J. W COOK, J. W COOK, J. W COOK, L. M	8010030455 8010060260 8010080570 8010090175 8010270326	50-329 50-329 50-329 50-329 RE00D	8 9
CLARK, R A. CLAUSEN, D H CLAUSON, M K CLAYTON, F. L	8010300367* 8010210541* 8010280092* 8010090469 8010010676*	50-304 COMMISS 50-201 50-348	B SION H Q	COLLINS, J, T COLLINS, P F COLLINS, F M COLLINS, J T, COLLINOHAK, R E	8010100374 8010010071 8010010262* 8010030535 8010090241*	50-219 NUREO CONTRACT 50-320 TOPREP	e R	COOK, B M COOK, J. W COOK, J. W COOK, J. W	8010230362* 8010200463 8010200301 8010280266 8010240204	TOPREP 50-329 50-329 50-329 50-329	9 \$ F K
CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L	8010060152* 8010090287 8010030230 8009240519 8010100126	50-348 50-348 50-364 50-364 50-348	Q Q A A Q	COLLING, J T COLLING, F M COLLING, J T COLLING, M COLLING, B J	8010160715 8010200366* 8010220136 8010210528* 8010270043	50-320 CONTRACT 50-320 50-320 50-271	R R 8 9	COOK, J, W COOK, J, W COOK, J, W COOK, J W	8010240214* 8010240221* 8010240230* 8010310402 8010270352	50-329 50-329 50-329 50-329 50-329	XXX
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8010100133 8010060325 8010230488 8010240134* 8010070545	50-348 50-348 50-364 50-364 50-364	Q P Q Q A	COLLING, J COLOMBO, R W. COMPTON, R M COMPTON, R M	8010270046 8010060306* 8010140115* 8010020273* 8010090031*	50-320 50-312 50-250 50-281 50-335	8 0 0	COOK, T. L COOLEY, H J COOLEY, W, J COONEY, H J COONEY, H J	8010300218 8010060094 8010270373* 8010200393 8010020475	50-311 70-734 70-754 50-277 50-277	P P S
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8010070616 8010070295 8010070305 8010070341 8010070395	50-348 50-364 50-364 50-364 50-364	B P P A	CONDIE, K O. CONLON, T.E CONLON, T E CONLON, T, E CONLON, T E	8010300194 8010010228* 8010300428* 8010150671* 8010030094*	RE8 50-413 50-369 50-324 50-335	Q Q Q	COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8010030361 8010030366 8010030371 8010070496 8010080487	50-277 50-278 50-277 50-278 50-278	9 8 9 5
CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L	8010070579 8010080423 8010080452 8010140467 8010140288	50-364 50-364 50-348 50-364 50-364	A B P A	CONLON, T. E CONLON, T E CONLON, T E CONLON, T E. CONLON, T E.	8010020780* 8010020250* 8010170278* 8010090019* 8010140053*	50-438 50-438 50-321 50-280 50-400	Q Q Q	COONEY, M J COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8010140483 8010150375 8010210725 8010210735# 8010270358	50-277 50-277 50-277 50-277 50-277	9 R 8 9 6
CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L	8010140305 8010140344 8010140351 8010240040 8010150387	50-348 50-364 50-348 50-364 50-364	A F G A	CONLON, T E CONLON, T E, CONLON, T E CONLON, T E CONLON, T E	8010240241* 8010240663* 8010280064* 8010290206* 8010270107*	50-328 50-348 50-370 50-375 50-259	0 0 0	GODNEY, M. J. COONEY, M. J. COOPER, J. COOPER, Q. K. COPELAND, R. L.	8010270375 8010310443 8010280111* 8010170003 8010160716	50-278 50-278 40-8710 NUREO PR	8
CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L	8010200425 8010200590 8010210402 8010210718 8010280424	50-364 50-364 50-348 50-348 50-364	A A R SI A	CONNELL, C. CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8010210415* 8010140547 8010140547 8010200517 8010200531*	50-286 27-39 27-39 27-39 27-39	R	COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q	8010010217 8010010217 8010140343 8010140550# 8010140573#	50-466 50-466 50-466 50-466 50-466	00000
CLAYTON, F. L. CLAYTON, F L. CLAYTON, F L. CLAYTON, F L. CLAYTON, F L.	8010280487 8010280462 8010280463 8010280464 8010300459	50-348 50-348 50-364 50-364 50-364	P 8 A P A	CONNER, T. 8 CONNER, T. B. CONNER, T. B. CONNER, T. B CONNER, T. B	8010200537* 8010200545* 8010200550* 8010200560* 8010200517	27-39 27-39 27-39 27-39 27-39		COPELAND, J G COPELAND, J, G. COPELAND, J O COPELAND, J O COPELAND, J O.	8010140589# 8010140599# 8010140543 8010140550# 8010140573#	50-466 50-466 50-466 50-466 50-466	00000
CLEOG.L.B CLEMENTS,T. CLEMENT.C CLUFF,L S CGALWELL,T.N	8010230009 8010230328 8010280541* 8010240274 8010240411	NUREO 50-201 50-336 50-133 50-264	9 P J	CONNER, T B CONNER, T B CONNER, T B, CONNER, T B, CONNER, T B,	8010200531* 8010200537* 8010200545* 8010200550* 8010200560*	27-39 27-39 27-39 27-39 27-39		COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q.	8010140589# 8010140599# 8010160020 8010160020 8010160784	50-466 50-466 50-466 50-466	00000
COCHRAN COELHO, T COGOIN, C COGOIN, C COGOIN, C COGOIN, C	8010100240 8010280343 8010060245* 8010080437* 8010220496*	PR 50-275 50-366 90-321 50-366	H 8 8	CONNER, T. B.	8010170391 8010170391 8010140782 8010160782 8010220508	27-39 27-39 27-39 27-39 27-39		COPELAND, J. Q COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q.	8010160784 8010270522 8010280020 8010270522 8010280020	50-466 50-466 50-466 50-466 50-466	00000
CD00IN,C L CD00IN,C L CD00IN,C L COHEN,I.	8010220506# 8010280681# 8010280377# 8010240284# 8010200361#	50-321 50-321 50-366 70-820 70-1100	9 8 8	CONNER, T. B CONNER, T. B, CONNER, T. B CONNER, T. B CONNER, T. B	8010220515 8010220520 8010220508 8010220515 8010220520	27-39 27-39 27-39 27-39 27-39		COPELAND, J. Q COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q COPELAND, J. Q.	8010270374 8010270374 8010310048 8010310051 8010310048	50-466 50-466 50-466 50-466 50-466	00000
COHEN, M, D COHEN, S COHN, B, M COHN, D, B COHN, D, B	8010170023 8010150171 8009090457 8010020047 8010020055*	NUREO NUREO ORO 50-367 50-367	0	CONNER, T. B. CONNER, T. B CONNOR, L. CONOVER, N P CONRAN, J H,	8010270380 8010270380 8010270054 8010070033* 8010070634*	27-39 27-39 FOIA CONTRACT 50-289	o	COPELAND, J. G. COPELAND, J. G. COPELAND, J. G. CORBETT, J. B CORCORAN, J. M.	8010310051 8010300599 8010300599 8010100424 8010080580	50-444 50-444 50-464 71-6375 40-8502	0
COHN, D, B COLEMAN, H, E. COLEMAN, R COLEMAN, R COLEMAN, R	8010020047 8010020055* 8010030332* 8010080615 8010010109		0	L. O. ALEATENCO CONTE. R. J. CONTE. R. J. CONTE. R. J. J. R. STNOO	8010280282* 8010020384* 8010140374 8010140357 8010140350	50-271 50-320 50-320	0 H 8 S 6	CORCORAN, W. R GORCORAN, T. CORCORAN, T. CORDANI, R. A CORDANI, R. A.	8010270534* 8010030425 8010060021	FR 50-10 50-10 70-27 70-27	U V

AUYHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NVMSER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
CORDANIAR A CORDANIAR A CORDANIAR A CORDANIAR A CORDANIAR A	8010070485 8010150532 8010210759 8010200240 8010230489	70-27 70-27 70-27 70-27 70-27 70-27	CDUNSIL, W O CDUNSIL, W O CDUNSIL, W O CDUNSIL, W O. CDUNSIL, W O.	8010300419 8010300361 8010300417 8010310326 8010310364	50-245 P 50-336 P 50-213 P 50-245 P 50-245 Q	CROUSE, R P CROUSE, R P CROUSE, R P. CROUSE, R P. CROUSE, R P.	8010100228* 8010030288 8010150295 8010080233 8010080427	50-346
CORDERO, Z C CORDERO, Z C CORE, H CORPSTEIN, P E CORREA, H A	8010040108* 8010290110* 8010030418* 8010270329 8010220418	50-461 0 50-546 0 50-285 8 REGOD 50-272 J	COURTNEY, J. C COMAN, B Z COWAN, R F COWOILL, C J CRANE, D B	8010230231 8010030479 8010070010 8010010136* 8010020677*	50-201 0 50-201 0 NUREO 50-277 0 50-461 U	CROUSE, R P. CROUSE, R P. CROUSE, R P. CROW, W T. CROW, W T	8010050359 8010140247 8010310311 8010020512* 8010010471	50-346 F 50-346 P 50-346 P 70-1113 70-698
CORREA, C. CORYELL, G P CORYELL, G P CORYELL, O P COSTELLO, F	8010280382 8010060159 8010090227* 8010220456 8010010298*	50-89 J 70-1151 70-1151 70-1113 70-48	CRANE, P. A CRANE, P. A CRANE, P. A CRANE, P. A, CRANE, P. A	8010100427 8010300384 8010300394 8010300391 8010270031	PR 50-193 @ 50-193 0 50-193 0 50-275 @	CROWLEY, BR CROWLEY, BR CROWLEY, BR CROWLEY, BR	8010210745 8010140178 7809180180 8010070152* 8010240120*	70-2317 70-820 50-518 0 50-280 0 50-413 0
COSTELLO, F COSTELLO, F COSTELLO, D COTE, L COTTLE, H T	6010010395* 8010230428* 8010200394* 8010150145* 8010170041*	70-698 50-277 Q 50-260 R 50-309 F 50-327 Q	CRANE, P. A CRANE, P. A CRANE, P. A CRANE, P. A CRANE, P. A	8010270033 8010080585 8010220485 8010080365 8010270368	50-275 Q 50-133 Q PR 50-275 Q 50-275 Q	Cronn. H. M Cronn. W T Crutchfiled, D Crutchfield, D Crutchfield, D	8010010295* 8010220108* 8010310563 8008060107 8010010051	CONTRACT 70-2609 50-29 P 50-255 P 50-244 P
COTTLE.W T COTTLE.W.T COTTLE.W T COTTLE.W T COTTLE.W.T	8010070598* 8010210517* 8010210657* 8010210642* 8010210679*	50-327 B 50-327 B 50-327 B 50-327 B 50-327 B	CRANE, P A CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8010080501 8010140310 8010140345 8010220521 8010240403	50-275 A 50-275 A 50-275 A 50-275 Q 50-275 F	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D.	8010010041 8010010343 8010010747 8010010773 8010010798	50-213 P 50-237 P 50-245 P 50-409 P 50-155 P
COTTLE, W T COTTLE, H. T COTTLE, W T COTTLE, W. T COTTLE, W T	8010210699* 8010210703* 8010210641* 8010210697* 8010210714*	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8	CRANE, PA CRANE, PA CRAWFORD, T. J CRAWFORD, D. S CRECCO, V.	8010280439 8010280460 8010240535 8010270082 8010070578*	50-133 V 50-133 8 FDIA XPDRTLIC 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	B010140095 B010140101# B010140127# B0100B0578 B0100B0579#	50-219 P 50-219 P 50-219 P 50-255 P 50-255 P
COTTLE, W. T COTTLE, H. T COTTLE, H. T COTTLE, H. T COTTON, O. D	8010210665# 8010270353# 8010280508# 8010280562# 8010100359	50-327 8 50-327 8 50-327 8 50-327 8 50-582 A	CREED, J. R CREED, J. R CREIBZEWBKI, P CREWB, J. L CREWB, J. L.	8010160177# 8010170546# 8010220529 8010090163 8010150070#	50-409 G 50-331 G 50-201 G 50-344 B 50-312 G	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D	8010080586* 8010010035 8010010501 8010020235 8010020251	50-235 P 50-217 P 50-155 P 50-155 Q 50-213 0
COULT.C. H COUNSIL.H.O COUNSIL.H O COUNSIL.H O COUNSIL.H O.	8010140117* 8010020763* 8010220701* 8010010423* 8010010084*	COMMISSION 50-245 Q 50-213 Q 50-423 S 50-245 Q	CREWB, J. L. CREWB, J. L. CREWB, J. L. CREWB, J. L. CREWB, J. L.	8010080113* 8010080159* 8010090377 8010170438 8010090416	50-206 @ 50-344 @ 50-344 @ 50-206 @ 50-344 @	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8010020267 8010020656 8010220154 8010020167 8010020162	50-10 9 50-409 9 50-219 P 50-155 F 50-10 F
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8010020276 8010100038* 8010240202* 8010020756 8010030313	50-245 Q 50-336 Q 50-245 Q 50-245 Q 50-213 Q	CREWS, J. L CREWS, J. L CREWS, J. L CREWS, J. L CREWS, J. L	8010170361 8010300019* 8010270132 8010100409 8010230172	50-397	CRUTCHFIELD. D CRUTCHFIELD. D. CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8010070536 8010100058 8010140126 8010220557 8010230372	50-237 P 50-245 P 50-10 P 50-10 P 50-155 P
COUNSIL. W O COUNSIL. W O. COUNSIL. W. O. COUNSIL. W. O. COUNSIL. W. O	8010030274 8010010660 8010010713 8010010701 8010170236	50-213 Q 50-245 Q 50-245 Q 50-423 Q PR	CREWB. J. L. CREWB. J. L. CREWB. J. L. CREWB. J. L. CREWB. J. L.	8010300433 8010070185 8010310074 8010080076 8010080146	50-243 0 50-312 0 50-27 0 50-206 0 50-344 0	CRUTCHFIELD, B CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8010230398 8010230403 8010200360 8010200364* 8010200372*	50-29 P 50-244 P 50-219 P 50-219 P 50-219 P
Counsil, H. G. Counsil, H. G Counsil, H. G Counsil, H. G. Counsil, H. G	8010020313 8010170236 8010020735 8010020744 8010220021	50-423	CREMB, J. L. CREMB, J. L. CREMB, J. L. CREMB, J. L. CRNICH, J.	8010280016 8010150060 8010280029 8010300015 8010210459	50-206 Q 50-312 Q 50-275 Q 50-312 Q 50-362 B	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8010020026 8010100117 8010130629 8010130631 8010160126	50-237 9 50-206 P 50-244 F 50-255 P 50-27 P
Counsil. H. O Counsil. H. O Counsil. H. O. Counsil. H. O. Counsil. H. O	8010220021 8010240051 8010270242 8010020504 8010270242	50-213	CROCKER, H. W. CROCKER, H. W CROCKER, H. W CROCKER, H. W CROCKER, H. W	8010010309+ 8010010347+ 8010210264+ 8010010617+ 8010020223+	40-8395 70-820 70-135 70-820 70-364	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8010230227 8010040488 8010080397 8010040496 8010300517	50-237
COUNSIL. W. O. COUNSIL. W. O. COUNSIL. W. O. COUNSIL. W. O.	8010020504 8010060302 8010060270 8010230177 8010010569	50-245 P 50-245 F 50-245 R 50-245 P 50-336 P	Crocker, H. W Crocker, H. H. Crocker, L. P Crocker, H. H Crocker, H. H.	B010230148* B010060143 B010170001 B010220204 B010160359	70-820 70-820 NUREO 70-820 50-201 8	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D	8010310119 8010310532 8010310185 8010310203 8010310206*	50-213 P 50-217 P 50-213 P 50-155 P 50-155 P
COUNSIL, H O. COUNSIL, H. O. COUNSIL, H O COUNSIL, H O COUNSIL, H. O	8010040258 8010070554 8010220130 8010220130 8010060323	50~213 P 50~213 P PR PR 50~334 P	CROCKER, H W CRONEY, B T. CRONIN, D. F. CRONIN, D F CRONIN, D F	8010240370 8010230017 8010140208# 8010140213# 8010140224#	70-364 50-250 P 70-820 70-820 70-820	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D	8010310210* 8010310558 8010280675 9010280679* 8010280685*	50-155 P 50-206 P 50-10 P 50-10 P
COUNBIL, H O. COUNBIL, H O COUNBIL, H O COUNBIL, H O, COUNBIL, H O,	8010070183 8010080444 8010100324 8010060319 8010100324	50-336 P 50-245 P 50-213 P 50-245 P 50-213 P	CRONK, R. J. CROPP, L CROBBY, P. J. CROBBY, P. J. CROSSMAN, H. A.	8010140191* 8010020642 8010070486* 8010150479* 8010020183*	40-1162 NUREO 50-219 B 50-219 B 50-445 Q	CRUTCHFIELD, D CULLEN CULP, R. H. CULP, R. H. CULP, R. H.	8010280700 8010230475 8010160020 8010160020 8010240427	30-10 P NUREG 30-466 G 50-466 G
COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O	8010100222 8010150488 8010200325 8010200472 8010200472	50-213 P 50-213 P 50-336 P 50-213 P 50-213 P	CROSSHAN, IF A. CROSSHAN, IF A. CROSSHAN, IF A. CROSSHAN, IF A. CROSSHAN, IF A.	8010160027* 8010020191* 8010270030* 8010270022* 8010270026*	50-445 G 50-382 G 50-482 G	CULVER, N W CUMMINOBAJ J. CUNNINOHAM, O E CUNNINOHAM, O. E CUNNINOHAM, J. D	8010200407* 8010070105* 8010010034 8010270365 8010220526	50-302 R 50-322 Q 71-9134 71-5939 50-269 Q
COUNSIL. W. O COUNSIL. W O. COUNSIL. W O. COUNSIL. W O. COUNSIL. W. Q.	8010240255 8010170396 8010300452 8010240247 8010300372	50-245 P 50-213 P 50-245 P 50-213 P 50-213 P	CROSSMAN, W. A.	8010310536* 8010160794 8010220605 8010300566 8010020075*	50-498 8 50-482 8 50-498 8	CURNINGHAM, J. D. CURRAN, J. M. CURRAN, J. K. CURRAN, J. H. CURRAN, J. H. CURRAN, B. A	8010220526 8010060297* 8010060348 8010060266 8010230396*	20-509 8 20-509 8 20-509 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCEBSION NUMBER	BUBJECT CATEGORY
CURRAN, J M CURRAN, J M CURTIS, N W CURTIS, J. R CURTIS, M, W.	8010210685* 8010150440 8010140031* 8010210449* 8010020089	50-206 B 50-206 R 50-387 G 50-206 G 50-387 Q	DAVIDSON, D R DAVIDSON, D R DAVIDSON, J J DAVIES, J, L DAVIS, A, B	8010030370 8010240070 8010170020 8010160164* 8010030830	50-440 B 50-440 G NUREG CONTRACT 1&E	DENTON, H. R.	8010080303* 8010080304* 8010020483 8010030028 8010030032*	50-250 0 50-250 0 50-463 7 50-331 0 50-331 0
CURTIE, N W CURTIE, N W CURTIE, N W CURTIE, N W CURTIE, N W	8010010684 8010100082* 8010010833 8010060247 8010270194	50-387 Q 50-139 Q 50-387 Q 50-387 B 50-387 Q	DAVIS,A B DAVIS,A B DAVIS,A B, DAVIS,J H DAVIS,A B	9010030540 8010220460 8010220463 8010100020* 8010220452	1&E 1&E 1&E 70-143 1&E	DENTON: HR DENTON: HR DENTON: HR DENTON: HR DENTON: HR	\$010030040* \$010100110 \$010100233 \$010170015 \$010220035	50-331 Q 50-443 H MISC ACRS 50-287 S
CURTIS, J. R. CURTIS, N. W. CURTIS, N. W. CURTIS, N. W. CURTIS, R.	8010280704* 8010060284 8010070086 8010070300 8010310389*	50-104 Q 50-387 S 50-387 S 50-387 S 50-206 Q	DAVIS, A B DAVIS, A B DAVIS, A B. DAVIS, A B, DAVIS, A B	8010030544 8007030041 8010040038 8010040071 8007080208	40-8742 14E 14E 14E 14E	DENTON, H. R DENTON, R. E DENTON, H. R DENTON, H. R DENTON, H. R	8010200088 8010140402* 8010140449 8010240017 8010240023*	MISC 50-317 8 50-275 H 50-327 9 50-327 9
CURTIS, N.W. CURTIS, N.W. CURTIS, N.W. CURTIS, N.W. CURTIS, N.W.	8010140271 8010140274* 8010240045 8010100337 8010140331	50-387 K 50-387 K 50-387 0 50-387 8 50-387 8	DAVIS, A B DAVIS, A, B DAVIS, A B DAVIS, A B, DAVIS, A B	8009150163 8010060042 8010030547 8010010590 8010220454	40-3372 &E &E 50-184 G &E	DENTON, H. R DENTON, H. R.	8010270018 8010270331 8010300533 8010280367 8010210361	50~275 H DRO CONTRACT ACRB 50~367 H
CURTIS, N W. CURTIS, N W CURTISS, J. R. CURTISS, J. R CUTCHIN, J. M	8010210411 8010240456 8010230692 8010280582 8010070613	50-387 A 50-387 B 50-369 0 50-369 Q 50-289 0	DAVIS, A. S DAVIS, A. S DAVIS, A. B DAVIS, A. B DAVIS, A. B	8010030502* 8010030495 8010030515 8010040044 8010080212	50-156 G 50-156 Q 50-156 Q 1&E 50-358 Q	DENTON, H. R DENTON, H. R. DENTON, H. R DESHOND, J. J DESMOND, J. J	8010280134 8010300048# 8010310064 8010080406 8010080408#	50-320 H 50-367 9 50-424 9 50-471 A 50-471 A
CUTCHIN, J M CYR, K D CZAPARY, L, S. D'AMORE, M DAIL, L C	8010200199 8010280598 8010300209 8010310319# 8010220156	50-289 T 50-409 O RES 70-1151 PR	DAVISA B. DAVISA B DAVISA B DAVISA B DAVISA B	8010200113* 8010040048 8010240228* 8010140038 8010080118	50-151 G I&E 50-324 G I&E 70-36	DESPAIN, D. DEUSTER, R. W. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8010140488* 8010070474 8010020082 8010200700* 8010030539	50-285 8 50-201 P 50-443 Q 50-443 B 50-443 Q
DALE: L F.	8010170230 8010080582 8010010658 8010150328 8010150336	PR 50-416 Q 50-416 A 50-416 Q 50-416 Q	DAVIBIA.B BAVIBIA DAVIBIU DAVIBIR JUBIVAD	8010070134 8010220447 801010081 801014083 801014089	50-10 B I&E Commission Foia Foia	DEVINCENTIS; J. DEVINCENTIS; J. DEVINE, J. B DEVINE, J. B DEVINE, J. B.	8010010697 8010200707# 8010010152 8010080039 8010080043	50-443 0 50-443 8 XPORTLEC XPORTLEC XPORTLEC
DALE,L F DALE,L F. DALE,L F. DALE,L F DALE,L F.	8010080384 8010010643 8010070346 8010140239 8010160537	90-416 Q 50-416 A 30-416 A 50-416 A 90-416 K	DAVIS,A B. DAVIS,A B. DAVIS,A B. DAVIS,A B. DAVIS,A B.	8010070262 8010160337 8010220125* 8010010497 8010220114	50-10 8 50-254 0 40-2364 50-483 0 40-2364	DEVINE, J. B. DEVINE, J. P.	8010080047 8010080050 8010080065 8010010319 8010010240	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DALE,L,F, DALE,L F, DALTROFF,B L DALTROFF,B L, DALTROFF,B L,	8010020331 8010010803 8010010816* 8010240338	50-416 H 30-416 0 50-277 0 50-277 0 50-277 0	DAVIS.A B DAVIS.A B DAVIS.L D, DAVIS.A B DAVIS.A B	8010010734 8010290395 8010210104 8010090490 8010290131	50-254 Q 50-264 Q 50-275 Q 50-373 Q 50-123 Q	DEVINE, J. B.	8010010306 8010010732 8010010223 8010010250 8010010132	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DALTROFF, 8 L.	8010020203 8010010208 8010010707 8010010821 8010230104	50-171 Q 50-277 Q 50-277 Q 50-277 Q 50-277 Q	DAVIS.A.B. DAVIS.J G. DAVIS.C E DAVIS.B M DAVIS.A B.	8010200077 8010230011 8010170066 8010060313* 8010310543	50-151 Q PR NUREO 50-317 S 50-123 Q	DEVINE, J B. DEVINE, J, B. DEVINE, J B. DEVINE, J B. DEVINE, J B.	8010010140 8010010324 8010200075 8010200335 8010150025	XPORTLIC XPORTLIC 50-273 P XPORTLIC XPORTLIC
DALTROFF, B. L. DALTROFF, B L. DALTROFF, B L. DAMRELL, C. B. DANCE, H C	8010100350 8010200584 8010200406 8010080408* 8010140027*	50-277 R 50-277 P 50-277 P 50-471 A 50-327 G	DAVIS: J C DAVIS: L D DAWSON, D M DAWSON, D. M DAWSON, D M	8010230110 8010210286 8010100073 8010150572 8010170048	DISCLOBURE 50-361 0 70-1308 70-1308 70-1308	DEVINE, J.B. DEVINE, J.B. DEVINE, J.B. DEVINE, J.B. DEVINE, J.B.	8010150033 8010150038 8010160073 8010160079 8010200300	XFORTLIC XFORTLIC XFORTLIC XFORTLIC XFORTLIC
DANCE, H. C. DANCE, H. C. BANCE, H. C. DANCE, H. C. DANCE, H. C.	8010160374 8010200436 8010160442 8010160433 8010140013*	50-321 8 50-296 8 50-366 8 50-327 8 50-321 G	DE GUZMAN, A B, DEAN, B R DEAN, B DEBEAR, H B DECHER, U	8010200539# 8010010344# 8010070233# 8010270084 8010010830	71-371 50-262	DEVINE, J. B DEVINE, J. B. DEVINE, J. B DEVINE, J. B. DEVINE, J. B	8010140378 8010150546 8010150552 8010150560 8010150566	XFORTESC XFORTLIC XFORTLIC XFORTLIC XFORTLIC
Dance: H C Dance: H. C Danielbon, D Danielb: F T. Danielbon, D. H.	8010170041* 8010230483* 8010100383 8010160161* 8010010647*	50-327 Q 50-259 Q 50-341 B 50-358 Q 50-454 Q	DECK, D.A. DECK, D.A. DEGANGI, N. DECHANEY, B. T.	8010280433 8010310375 8010170023 8010240577 8010150622*	50-320 R 50-320 R NUREO 50-269 G CONTRACT	DEVINE, J. B.	8010130574 8010130592 8010150670 8010160018 8010160068	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELBON, D. H. DANIELBON, D. H. DANIELBON, D. H. DANIELBON, D. H. DANIELB, J. A	8010150156* 8010010722* 8010270124* 8010200470* 8010220307*	50-456 G 50-315 G 50-358 G 50-358 G 50-358 H	DELGEORGE, L. D.	8010240551* 8010220112 8010020435 8010150474 8010160542	50-373 8 PR 50-373 A 50-373 A 50-373 8	DEVINE, J. B. DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B.	8010160074 8010160082 8010160087 8010160108 8010160733	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELBON, D DANIELBON, D. H. DANIELBON, D. H. DANIELBON, D. H. DANIELB, F. T.	8010070270 8010160336* 8010290110* 8010200685* 8010270161*	50-234 8 50-374 Q 50-546 Q 50-331 Q 50-358 Q	DELGEGROE, L. Q DELGEGROE, L. Q DELGEGROE, L. Q, DELONG, S, D DELONG, S, D	8010210338 8010240458 8010280322 8010090362* 8010090371*	50-373 A 50-373 A 50-373 A 50-314 8 50-315 8	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B	8010140736 8010140740 8010230637 8010230640 8010240025	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
'Anielbon, D. Anielbon, D. H. Nielbon, D. H. Ntzler, M. U. Rmitzel, R. W	8010270258 8010270144* 8010270262* 8010010282* 8010150428	50-254 8 50-282 Q 50-483 Q CONTRACT 50-70 P	DEMAS, N. G. DEMPSEY, P. A. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8010230281 8010080121 8010070506* 8010030170 8010060051	50-201 Q 50-322 Q 50-482 A 50-220 P 50-409 P	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8010240197 8010240515* 8010240030 8010220380 8010220652	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XFORTLIC
RMITZEL, R. W VIDSON, J. A VIDSON, D. R. VIDSON, D. R. VIDSON, D. R	8010290347 8010080557* 8010090115 8010090139 8010030296	50-70 P 50-344 P 50-440 Q 50-440 Q 50-440 Q	DENTON, H. R.	8010230452 8010020461 8010210075 8010240567* 8010080277	50-280 H 50-461 U MIBC 50-327 P 50-250 Q	DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8010230687 8010230689 8010230690 8010230693 8010230695	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
DEVINE, J B	8010230498	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	DINITZ, I,	8010280251	50-208 J	DODA.R	8010070523	40-8692
DEVINE, J B	8010270010		DINITZ, I	8010280258	50-390 J	DODD.C V	8010070010	NUREO
DEVINE, J B	8010270012		DINITZ, I	8010280263	50-317 J	DODDS.R T.	8010070370*	50-275 G
DEVINE, J B.	8010270020		DINITZ, I	8010280268	50-13 J	DODDS.R T.	8010240587*	50-440 G
DEVINE, J B.	8010230700		DINITZ, I	8010280273	50-315 J	DODDS.R T.	8010070381*	50-361 G
DEVINE, J. B	8010270094	XPURTLIC	BINITZ, I	8010280277	50-206 J	DODDB,R T	8010100369*	50-508 @
DEVINE, J B	8010280637	XPORTLIC	DINITZ, I	8010280283	50-94 J	DODDB,R T	8010170428*	50-528 @
DEVINE, J B	8010230363	XPORTLIC	DINITZ, I	8010280292	50-171 J	DODDB,R.T.	8010170662*	50-528 @
DEVINE, J B	8010290040	XPORTLIC	DINITZ, I	8010280294	50-263 J	DOHERTY,J F	8010140019	50-466 @
DEVINE, J B.	8010230319	XPORTLIC	DINITZ, I	8010280301	50-219 J	DOHERTY,J F	8010080093	FOIA
DEVINE, J B	8010230380	XPORTLIC	DINITZ, I	8010280307	50-287 J	DOMERTY, J F. DOMERTY, J F DONAT, T J, DONAT, T J DONAT, T J	8010240605*	50-320 P
DEVINE, J B	8010230384	XPORTLIC	DINITZ, I	8010280309	50-33B J		8010220029	FOIA
DEVINE, J B	8010230468	XPORTLIC	DINITZ, I	8010280315	50-250 J		8010080610	50-348 8
DEVINE, J B.	8010270405	XPORTLIC	DINITZ, I,	8010280326	50-4 J		8010160530	50-348 8
DEVINE, J B.	8010280124	XPORTLIC	DINITZ, I	8010280394	50-369 J		8010010018*	50-369 G
DEVINE, J B. DEVINE, J B. DEVINE, J B DEVINE, J B DEVINE, J B	8010300329	XPORTLIC	DINETZ, I	8010280600	50-264 J	DONAT, T. J	8010080205*	50-369 G
	8010270215	XPORTLIC	DINITZ, I	8010280607	50-267 J	DONELSON, B E.	8010200258	70-1113
	8010270254	XPORTLIC	DINITZ, I	8010280613	50-10 J	DONNACHIE, J P	8010220138	50-320 T
	8010270159	XPORTLIC	DINITZ, I,	8010280623	50-324 J	DONOGHUE, D J	8010010030	BECY
	8010270278	XPORTLIC	DINITZ, I	8010280628	50-293 J	BOUOHERTY, D J	8010170855*	CONTRACT
DEVINE, J. B	8010270303	XPORTLIC	DINITZ, I	8010280631	50-305 J	DOUGHERTY, D. J	8010020595*	CONTRACT
DEVINE, J. B	8010270307	XPORTLIC	DINITZ, I	8010280636	50-266 J	DOUGHERTY, D. J	8010030353*	CONTRACT
DEVINE, J. B	8010300586	XPORTLIC	DINITZ, I,	8010280639	50-327 J	DOUGHERTY, D. J.	8010020479*	CONTRACT
DEVINE, J. B	8010300573	XPORTLIC	DINITZ, I	8010280649	50-275 J	DOUGHERTY, D. J	8010010261*	CONTRACT
DEVINE, J. B	8010310161	XPORTLIC	DINITZ, I,	8010280655	50-220 J	DOUGHERTY, D	8010020297*	CONTRACT
DEVINE, J. B	8010310165	XPORTLIC	DINITZ, I.	8010280662	50-99 J	DOUGHERTY, D	8010010303*	CONTRACT
DEVINE, J. B	8010310157	XPORTLIC	DINITZ, I.	8010280670	50-141 J	DOUGHERTY, D	8010020625*	CONTRACT
DEVINE, J. B	8010310617	XPORTLIC	DINITZ, I	8010280680	50-166 J	DOUGHERTY, D	8010080620*	CONTRACT
DEVINE, J. B	8010310622	XPORTLIC	DINITZ, I	8010280684	50-139 J	DOUGHERTY, D. J	8010010232*	CONTRACT
DEV.IN, J. W	8010070548	50-334 8	DINITZ, I	8010280689	50-150 J	DOUGHERTY, D. J	8010140243*	CONTRACT
DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W	8010230719* 8010240322* 8010010264* 8010020084* 8010030142*	50-54 Q 50-289 Q 50-309 Q 50-333 Q 50-247 Q	DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I.	8010280694 8010280696 8010280699 8010280703 8010280713	50-193 J 50-106 J 50-57 J 50-8 J 50-2 J	DOUGHERTY, D. J. DOUGHERTY, D. H. DOUGHERTY, D. H. DOUGHERTY, D. G. DOUGHERTY, D. J.	8010140420* 8010100379* 8010140166* 6010160179* 8010210004*	CONTRACT CONTRACT CONTRACT 50-275 0 40-8743
DEVLIN, J. W DEVLIN, J. W DEVLIN, J. W DEVLIN, J. W DEVLIN, J. W	8010010401* 8010030104* 8010020762* 8010030126* 8010010370*	50-29 G 80-293 G 50-286 G 50-334 G 70-820	DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I. DIPIAZZA, R. DIPIAZZA, R.	8010280715 8010280720 8010380364 8008210613 8010200197	50-294 J 50-37 J 50-142 J 71-6400 70-1151	DOUGHERTY, D. J.	8010030488* 8010200453* 8010140128* 8010140401* 8010150622*	CONTRACT 27-39 CONTRACT CONTRACT CONTRACT
DEVLINJ W DEVLINJ W DEVLINJ W DEVLINJ W	8010230124* 8010030132* 8010240104* 8010300198* 8010240217*	70-33 50-245 G 70-1143 70-364 50-245 Q	DIRCKS, W DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J. DIRCKS, W. J	6010020120* 6010020146* 8010060045* 8009110006 8010020449	FOIA 70-143 COMMISSION SECY 30-271 H	DOUGHERTY, D. J.	8010170596* 8010170612* 8010170572* 8010170624* 8010200606*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DEVORE, F W. DEWEY, L. 8 DEWITT, R B DEWITT, R B DEWITT, R B DEYA, R.	8010020632	PR	DIRCKS, W J	8007270471	SECY	DOUGHERTY, D J	8010200623*	27-10
	8010240063	50-389 N	DIRCKS, W J	8010020381	50-307 H	DDUGHERTY, D J	8010200642*	CONTRACT
	8010070167	50-255 Q	DIRCKS, W J.	8010020418	50-266 Q	DDUGHERTY, D J	8010200666*	CONTRACT
	8010100243*	50-155 P	DIRCKS, W J	8010020430	50-266 Q	DDUGHERTY, D, J	8010210064*	CONTRACT
	8010220663	50-201 Q	DIRCKS, W J	8010100172	State Prog	DGUD, A J.	8010080432	50-315 P
DEYOUNG, R.C.	8010160041	50-321 Q	DIRCKB.W J.	8010020366	50-482 U	DRAPER, E.L.	8010010013	50-458 A
DEYOUNG, R.C.	8010160047*	50-321 Q	DIRCKB.W.J	8010080658	HISC	DRAPER, E.L.	8010170477*	50-458 G
DEYOUNG, R.C.	8010310317	50-321 Q	DIRCKB.W J.	8010100114	50-305 H	DRAPER, E.L.	8010080561	50-458 G
DEYOUNG, R.C.	8010310323*	90-321 Q	DIRCKB.W.J	8010240305	50-275 H	DRAPER, E.L	8010080569	50-458 G
DHIR.V.K.	8010230042	NUREQ	DIRCKB.W.J	8010080662	50-466 U	DRAPER, E.L	8010170209	PR
DIAMOND, D J. DIAZ, N J DICHARRY, R. F. DICK, J W DICKERSON, M W,	8010220627	RES	DIRCKS, W. J.	8010080444	50-446 U	DRAPER.E.L.	8010300435*	50-458 G
	8010070480	70-1068	DIRCKS, W. J.	8010070444	50-449 H	DRAPER.E.L	8010150204	50-458 S
	8010240034	71-102	DIRCKS, W. J.	8010070455	50-275 H	DRAPER.E.L	8010020005	50-201 O
	8010070517*	50-466 Q	DIRCKS, W. J.	8010080469	50-344 H	DRAPER.E.L	8010220147	PR
	8010280121*	50-267 Q	DIRCKS, W. J.	8010100121	50-307 U	DREUBERT.J R.	8010140540	TOPREP
DIETCH, R	B010210337*	50-206 P	DIRCKS, W. J.	8010100106	50-293 H	DREY, K.	9010300072	50~483 Q
DIETCH R.	B010210331	50-206 P	DIRCKS, W. J.	8010230714	50-338 H	DROMERICK, A. W.	8010040110	50~337 P
DIGGS, R. M.	B010140143	TOPREP	DIRCKS, W. J.	8010280118	50-275 U	DROMERICK, A. W.	8010030505	50~337 P
DIGGS, R. M	B010270339*	50-313 P	DIRCKS, W. J.	8010280140	50-259 H	DUCKWORTH, J. P	8010150401	50~201 F
DIGNAN, T. O	B010030474	50-307 Q	DIRCKS, W. J.	8010280072	50-320 H	DUCKWORTH, J. P	8010020274	50~201 Q
DIGNAN, T O DIGNAN, T O. DIGNAN, T. O DIGNAN, T. O DIGNAN, T. O	8010220547 8010220547 8010270513 8010270513 8010310451	50-443	DIRCKE, W. J. DIRCKE, W. T. DIRCKE, W. J. DIRCKE, W. J. DIRCKE, W. J.	8010270539 8010280097 8010140278 8010280112 8010270516	50~250 H 50~250 H 50~275 H MIBC MIBC	DUCKHORTH, J.P. DUCKHORTH, J.P. DUMMER, G. DUMMER, G. H DUNBAR, J	8010160369 8010160362 8010010233* 8010010373* 8010270381*	CONTRACT
DIONAN, T. C BIONAN, T. C BIONAN, T. C BIMEGLIO, A. F BINITZ, I.	8010310451 8010300073 8010300073 8010240528 8010020372	50-293 Q 50-309 Q 50-309 Q 50-193 J 70-824	DIRCKS. H. J. DIRCKS. H. J. DIRCKS. H. J. DIRCKS. H. J. DISE, D. P	8010270532 8010290141 8010290146 8010290271 8010150041*	50-10 U 50-352 U 50-155 H 50-335 H 50-410 8	DUNBAR, J DUNDAB, W. J. DUNDAB, W. J. DUNDAB, W. J DUNENFELD, M.	8010070612# 8010060315# 8010060316# 8010060312 8010150143	* 50-264 J * 50-264 J 50-264 J TOPREP
DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I	8010070355* 8010140142 8010210407* 8010280152 8010280161	50-324 J 70-824 50-97 J 50-149 J 50-20 J	DISE.D.P. DISE.D P. DISE.D P. DISE.D.P DISE.D.P.	8010070264 8010070319 8010150360 8010160516* 8010280585	50-201 P 50-220 P 50-220 P 50-220 P 50-220 P	DUNN, C. N DUNN, C. N. DUNN, C. N DUNN, C. N DUNN, C. N.	8010010801* 8010030121* 8010010210* 8010010823 8010140743	* 50-334 0 * 50-334 0 50-334 0 PR
DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I. DINITZ, I.	8010280179 8010280225 8010280230 8010280238 8010280244	50-22 J 50-87 J 50-280 J 50-94 J 50-346 J	DISTEFANO, J. DIXON, D. R. DIXON, B. DOAN, P. F. DOAN, P. F.	8010140519 8010010327* 8010030440 8010070491* 8010210717*	PR 50-262 0 50-344 H 50-298 B 50-298 B	DUNN, C. N DUNN, C. N. BUNN, B. D DUNN, C. N. DUNN, C. N.	8010010779 8010010829 8010200392 8010010545 8010020491	50-334 0 * 50-280 R 50-334 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT	AUTHOR	ACCESSION NUMBER	BUB JECT CATEGORY
DUNN, W E DUNN, W E DUNN, C N DUNN, C N DUNN, C N	8010170003 8010170078 8010030393 8010060223 8010230296	NUREO NUREO 50-334 P 50-334 P 50-334 Q	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8010240566 8010300134 8010020589 8010030066 8010030071*	50-327 P 50-409 P 50-344 H 50-333 9 50-333 0	ELLIOTT.C W ELLIB.J ELLIB.J. ELLIB.J ELROD.B A	8010270457 8010080090 8010140015 8010200690 8010020737*	50-387
DUNN, C N	8010100351	50-334 F	EISENHUT, D O	8010030074	50-259 0	ELTAWILA,F	8010020397	50-397 A
DUNN, C, N	8010240432	50-334 P	CISENHUT, D O	8010030085#	50-259 0	EMEIOH,C W	8010230194	70-820
DUNN, C N	8010240498	50-334 G	EISENHUT, D O	8010030090	50-298 0	EMPEY,M.K.	8010280122	FDIA
DUNTON, P	8010060269	50-357 G	EISENHUT, D O	8010030095#	50-298 0	EMBWILER,T R	8010020076	71-3971
DUPONT, B	8010090285	50-254 B	EISENHUT, D O	8010030205	50-220 0	ENGELKEN,R H	8010190027	50-397 Q
DUPANT, B G DUPREE, D DURLER, D L DURR, J P DUTTON, D,	8010180090* 8010180830* 8010290137 8010140043* 8009300110	50-254 Q 50-327 R REGGD 50-397 Q 50-424 Q	EISENHUT, D O	801003020B* 8010030213 8010030223* 801003022B 8010030235*	50-220	ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8010230376* 8010240579 8010020137* 8010210444* 8010270398	50-366 P 50-460 Q 50-361 Q 50-206 Q 50-312 Q
DUTTON, D	8010300608	50-424 G	EISENHUT, D O	8010030240	50-331	ENGELKEN, R. H	8010270400	50-344 0
DUTTON, D,	8010300608	50-424 G	EISENHUT, D O	8010030250*		ENGELKEN, R H	8010270402	50-206 0
DUVALL, D D	8007300379	50-369 B	EISENHUT, D. O,	8010040003		ENGELKEN, R H	8010270404	50-528 0
DUYER, P	8010230006	NUREG	EISENHUT, D. O	8010040004*		ENGELKEN, R H	8010270408	50-133 0
DYM, H	8010240063	50-389 M	EISENHUT, D. O	8010040085		ENGELKEN, R H	8010270411	50-397 0
EADIE, O, O, EADIE, O Q EADIE, O Q EADIE, O Q EADIE, O Q	80100&0076 8010220062 8010230169 8010230333 8010310513	40~8200 WASTE MOT WASTE MOT PROJ WASTE MOT	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8010040090* 8010080344 8010080348* 8010080352 8010080357*	50-264 0 50-309 0 50-309 0 50-335 0 50-335 0	ENGELKEN, R H	8010020133 8010080183 8010270504 8010270507 8010140051	30-351 0 50-205 0 30-205 0 50-344 0 50-206 0
EARLEY,A F	8010160527*	50-322	EISENHUT, D. O	8010100037	50-267 0	ENGELKEN, R. H.	8010160054	50-275 5
EARLEY,A F	8010160524		EISENHUT, D. O	8010100039*	50-267 0	ENGELKEN, R. H.	8010160058	50-344 0
EARLEY,A F	8010220513		EISENHUT, D. O.	8010160608	50-368 0	ENGELKEN, R. H.	8010160069	50-397 0
EAST.D	8010220279		EISENHUT, D. O	8010160617*	50-368 0	ENGELKEN, R. H.	8010160076	50-312 0
EAST.D J	8010240044		EISENHUT, D. O	8010160624	50-262 0	ENGELKEN, R. H.	8010160086	50-528 0
EAST.D	8010240180	40-8743	EISENHUT, D Q	8010160630*	50-282 0	ENGELKEN,R H.	8010140270	50-361 @
EBNETER.S D	8010020067*	50-277 Q	EISENHUT, D Q	8010160634	50-336 0	ENGEL,R E.	8010100355	TOPREP
EDNETER.S D	8010100103*	50-410 Q	EISENHUT, D Q	8010160639*	50-336 0	ENGELKEN,R H	8010310385	50-206 @
EBNETER.S	8010100021*	50-287 Q	EISENHUT, D Q	8010200673*	50-10 0	ENGEL,R E	8010070275	TOPREP
EBNETER.S	8010230043*	50-387 Q	EISENHUT, D Q	8010200675*	50-10 0	ENGELKEN,R,H	8010210293	50-206 P
EBNETER, B D	8010230157*	50-336	EISENHUT, D. G.	8010220079	50-3 P	ENGELKEN, R. H.	8010210438	50-206 Q
EBNETER, B D.	8010240574*		EISENHUT, D. G.	8010230121	50-338 0	ENGELKEN, R. H.	6010280021	50-328 0
ECHARDT, J H	8010090381*		EISENHUT, D. G.	8010230125*	50-338 0	ENGELKEN, R. H	8010280023	50-344 0
ECKERT, J P	8010020265*		EISENHUT, D. G.	8010270207	50-313 0	ENGELKEN, R. H.	8010280025	50-133 0
ECKHARDT, J H	8010170428*		EISENHUT, D. G.	8010270212*	50-313 0	ENGELKEN, R. H.	8010280027	50-397 0
ECKHARDT, J H	8010310278*	50-361 G	EIBENHUT, D. O	8010270282	50-312 0	ENGELKEN, R. H.	8010280031	50-312 0
ECONOMOS, K.	8010140136*	50-400 G	EISENHUT, D. Q.	8010270287*	50-312 0	ENGELKEN, R. H	8010280467	50-208 0
ECONOMOS, N	8010140121*	50-400 G	EIBENHUT, D. O	8010270298	50-346 0	ENGI, D	8010090008	NUREO
EDDLEMAN, H	8010100338	50-413 H	EIBENHUT, D. O.	8010270304*	50-346 0	ENGLE, L.	8010210015	50-280 F
EDELBTEIN, B	8010160223	XFORTLIC	EIBENHUT, D. O.	8010270307	50-277 0	ENGLISH, W. F	7902090347*	50-322 A
edelstein, B Edelstein, B Edelstein, B Edelstein, B Edelstein, B	8010140229* 8010300277 8010300285* 8010290141 8010290175*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D.O EISENHUT.D.O	8010270309* 8010270313 8010270317* 8010270321 8010270334*	50-277 0 50-321 0 50-321 0 50-269 0 50-269 0	ERB,C M. ERICKSON,R A ERICKSON,A J EBSIG.T.H. EVANS.B D	8010290110* 8010170140 8010200080* 8010220125* 8010220140	50-345 Q NUREO CONTRACT 40-2384 PR
EDOAR, C.	8010040285*	50-244 8	EIBENHUT, D 0 EIBENHUT, D 0 EIBENHUT, D 0. EIBENHUT, D 0 EIBENHUT, D 0	8010270337	50-302 0	EVERETT, J	8010100410	50-128 8
EDOAR, C.	8010140482*	50-244 8		8010270343*	50-302 0	EVERETT, R. J.	8010070154*	40-8502
EDOAR, Q I,	8010150365	50-556 0		8010300146	50-219 0	EVERETT, R. J.	8010230709*	50-278 F
EDOAR, Q L	8010140538	50-367 0		8010300154*	50-219 0	FABRIKANT, R.	8010060349*	50-445 M
EDMONSON, L R	8010070021*	Contract		8010300516	50-244 0	FABRIKANT, R.	8010060353*	50-445 M
EDMONDSON, P EDWARDS: D L EDWARDS: J EDWARDS: D. L EDWARDS: N W	8010100309 8010220393 8010210789 8010010068 8010210159	50-367 H 40-3453 State Prog 40-3453 REGGD	EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EISENHUT, D O.	8010300522* 8010300527 8010300532* 8010300538* 8010300542	50-244	FABRIKANT, R FABRIKANT, R FABRIKANT, R. FADIDA, A FAHNER, T C	8010140540 8010150640 8010170458 8010270130 8010150537	50-445 M 50-395 M 50-445 K FDIA 87-39
EDWARDS, D. W	8010030404	NUREO	EISENHUT, D O	8010300548*	50-29 0	FAHNER, T. C.	8010150542*	27-39
EDWARDS, D. W	8010070288	NUREO	EISENHUT, D O	8010310298	50-206 0	FAHNER, T. C.	8010150547*	27-39
EDWARDS, D. W	8010070397	NUREO	EISENHUT, D O	8010310304*	50-206 0	FAHNER, T. C.	8010150551*	27-39
EDWARDS, D. W.	8010240504	50-29 P	EISENHUT, D, O	8010180643	50-317 0	FAHNER, T. C.	8010150556*	27-39
EOGERS, P. E	8010100236#	CONTRACT	EISENHUT, D, O,	8010090518	50-315 P	FAHNER, T. C.	8010150562*	27-39
EICH/E.	8010280395*	50-247 R	EISENHUT, D. O	8010230411	50-269 P	FAHNER, T C	8010150567#	27-39
EICH/IOLZ, O. O	8010160737	PR	EISENHUT, D. O	8010230417	50-346 P	FAHNER, T C	8010150569#	27-39
EICH/IORN, W. M	801030510	50-367 Q	EISENHUT, D. G.	8010230425	50-312 P	FAHNER, T. C.	8010150577#	27-39
EICHHORN, W. M	8010030510	50-367 Q	EISENHUT, D. G	8010230447	50-313 P	FAHNER, T C	8010150636	27-39
EICHHORN, W. M	8010270401	50-367 Q	EISENHUT, D. G.	8010230451	50-289 P	FAHNER, T, C,	8010150639	27-39
EICHHORN: WH	8010290401	50-367 0	EISENHUT, D. O.	8010230456	50-302 P	FAHNER, T. C.	8010160774	27-39
EILPERIN: BF.	8010240331	50-320 0	EISENHUT, D. O	8010030099	50-289 Q		8010160777*	27-39
EILPERIN: BF	8010240344*	50-320 0	EISENHUT, D. G.	8010230111	50-344 Q		8010200184	50-347 9
EIBENHUT: D. O.	7809180016*	REGOD	EISENHUT, D. G	8010220278	50-458 A		8010210279	70-1308
EISENHUT: D. O.	8009230052	50-3 P	EISENHUT, D. G.	8010220280#	50-458 A		8010210282	70-1308
EISENHUT: D. O.	8010070014	50-217 F	EISENHUT, D. 0	8010280063	50-352 H	FAMMER, T, C. FAMMER, T C. FAMRNER, W. J FALCONER, D. P. FALCONER, D.	8010240065	27-39
EISENHUT: D O	8010020240*	50-155 Q	EISENHUT, D. 0.	8010310497*	50-329 A		8010270391	70-1308
EISENHUT: D O.	8010020244*	50-155 Q	EL-ASHRY, M T.	8010080497	50-518 R		8010100277	50-407 P
EISENHUT: D. O	8010020257*	50-210 Q	ELDRED, D T	8010030451*	50-346 8		8010080435	50-287 S
EISENHUT: D O	8010020263*	50-210 Q	ELIN, J O	8010230077*	50-275 Q		8010010018*	50-369 Q
EIBENHUT, D O EIBENHUT, D O EIBENHUT, D, O, IBENHUT, D O IBENHUT, D O	8010020277* 8010020281* 8010020730* 8010080337* 8010010338	50-10 0 50-10 0 50-409 0 50-293 0 TOPREP	ELLERGHAH, L, E ELLETT, W H. ELLIOTT, E D, ELLIOTT, N, S. ELLIOTT, C, W.	8010140474* 8010220341 8010140475 8010280362 8010220403	0A999 50-277 0 PR TOPREP 50-320 P	FAN, G. FARNELL, A, 8 FARNELL, A 8 FARNELL, A 8. FARNELL, A 8.	8010210117* 8010020734 8010020736 8010100045 8010100048	MISC 50-329 0 50-329 0 50-329 0

ROHTUA	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
FARNELL, A. S FARNELL, A. S FARNELL, A. S FARRELL, A. S FARRELL, A. S	8010100045 8010100048 8010160758 8010160758 8010310597*	50-329 0 50-329 0 50-329 0 50-329 0 CONTRACT	FELTON, J H FELTON, J, H FELTON, J H FELTON, J H FELTON, J H	8010220128 8010140591 8010140598 8010140621 8010200016	PR 40-299 40-1341 40-1162 FOIA	FIGRELLIO FIGRECLIO FIGRECLIO FIGRECLIO FIGRECLIO	8010100009 8010200688 8010160324 8010160330 8010160244	50-373 Q 50-546 Q 50-327 Q 50-374 Q 50-483 Q
Fasano, A. N Fasano, A. N Fasano, A. N Fasano, A Fasano, A	8010140374 8010140357 8010140350 8010100419 8010300337*	50-320 \$ 50-320 \$ 50-320 \$ 50-320 \$ 50-320 Q	FELTON, J. K. FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. K.	8010210175 8010220010 8010220025 8010270037 8010280138	FOIA FOIA FOIA 50-286 P FOIA	FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O FIORELLI,O	8010290128 8010230674 8010240325 8010290102 8010200693	50-346 Q 50-327 Q 50-329 Q 50-546 Q 50-331 Q
Fasang, a Fasang, a n Fasang, a n Fasang, a. n Faulkenberry, b	8010100417 8010150511* 8010100374 8010300577 8010150079*	50~320 B 50~320 G 50~217 B 50~287 S 50~312 Q	FELTON, J M FELTON, J. K FELTON, J. M FELTON, J M FELTON, J M	8010240656 8010280119 8010270001 8010270032 8010270140	F01A F01A 40-1341 F01A 27-10	FIORELLI, O FIORELLI, O FIORELLI, O. FIORELLI, O. FIORELLI, O	8010150091 8010010691 8010170300 8010200676 8010270338*	50-546 8 50-546 8 50-341 9 50-546 0 50-341 0
FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B. FAULKENBERRY, B FAULKENBERRY, B	8010090133 8010080126* 8010170466* 8010300024* 8010100409	50-312 8 50-204 0 50-206 0 50-312 0 50-361 8	FELTON, J K FELTON, J. K FELTON, J M FELTON, J K FELTON, J M	8010240531 8010270127 8010270134 8010270046 8010270050	FOIA FOIA FOIA 50-320 H FOIA	FIGRELLI, O FIGRELLI, O FIGRELLI, O FIGRELLI, O	8010290140 8010290148 8010290297 8010170125 8010170173	50-282 Q 50-461 Q 50-483 Q 50-461 Q 50-483 8
FAULKENBERRY, B. FAULKENBERRY, B. FAULKENBERRY, B. FAVRETTO, R. J. FAVRETTO, R. J.	8010310082* 8010100287 8010280019* 8010060349* 8010060353*	50-27 0 50-206 8 50-204 0 50-445 H 50-445 M	FELTON, J H. FELTON, J H FENNELL, M FENTON, R. E FEROUSON, J C	8010280723 8010290057 8010020554 8010290084 8010310589	50-219 P FOTA 50-369 H PT21 NUREQ	FIGRELLI, O FIGRELLI, O FIGRELLI, O FIGRELLI, O	8010200305 8010200392 8010100079 8010170095 8010170047	50-358 8 50-327 8 50-483 0 50-483 0 50-461 0
FAN.R E FAY.C.W FAY.C.W FAY.C.W FAY.C.W	8010070333 8005150348 8007300440 8010030521 8010020477	50-188 P 50-266 F 50-266 F 50-266 9 50-266 8	FEROUBON, J 8 FEROUBON, J H FEROUBON, J H FERRER, R A	8010220055 8010210545 8010280409 8010310411 8010230122	PR 50-338 P 50-339 P 50-280 P State Prog	FIGRELLI, O FIGRELLI, O FIGRELLI, O FIGRELLI, O	8010170185 8010170195 8010170199 8010210072 8010130463	50-461 B 50-329 S 50-546 S 50-329 S 50-237 P
FAYICH FAYICH FAYICH FAYICH FAYICH	8010020482* 8010210194 8010040354 8010070561 8010070569*	50-266 B REGOD 50-266 P 50-301 B 50-301 B	FERRELL,C FIDELL,E R. FIELDS,M FIELDER,J FIELD,K P	8010070388* 8010280724 8007310254 8010080412 8010020563	50-466 0 50-219 P TOPREP 50-327 J 50-201 0	FIGRELLI, O FIGRELLI, O FIGRELLI, O FIGRELLI, O	8010210394 8010300464 8010300467 8010240546 8010270181	50-456 0 50-546 8 50-546 8 50-373 8 50-373 0
FAY, C W FAY, C W FAY, C, N FAY, C N. FAY, C, N	8010220019 8010200462 8010150397* 8010150379 8010150384*	FOIA 50-266 Q 50-266 R 50-266 S 50-266 S	FIELDER. J. FIELDER. J. FIELDER. J FILSON. J R. FINDLEY. D E	8010140461 8010150420 8010150354 8010140420# 8010100377#	50-250 J 50-259 J 50-335 J Contract Contract	FIGRELLI.O. FIGRELLI.O FIGRELLI.O FIGRELLI.O. FIGRELLI.O.	8010230680 8010230702 8010270394 8010280053 8010270246	50-546 0 50-483 0 50-483 0 50-440 0 50-483 8
FAY, C, W FAY, C, U FEC, W, FEE, W, F FEE, W, F	8010190394 8010280401 8010160473 8010020276 8010100038*	50-266 R 50-266 R 50-20 P 50-245 Q 50-336 Q	Finfrock, I R Finfrock, I. R Finfrock, I. R Finfrock, I. R Finfrock, I. R	8010010414* 8010030309 8010060125 8010010652 8010010656	50-219	FIORELLI,O FIORELLI,O FIRESTONE,E A FISCHER,U L FIGH,R F	8010270228 8010270413 8010240408 8010060075 8010200034*	50-373 8 50-456 0 50-367 0 1&E 50-361 0
FEE, W. F. FEE, W. F. FEE, W. F. FEE, W. F.	8010020796 8010010640 8010010719 8010220021 8010010569	50-245	FINFROCK.IR. FINFROCK.I.R FINFROCK.I.R FINFROCK.IR FINFROCK.IR	8010010834 8010070153 8010270201 8010070474 8010070314	50-219 0 50-219 8 50-219 0 50-219 8 50-219 8	FISHER: E. J. FISHER: W L FISHER: R E FISHER: W L FISHER: W. L	8010090032* 8009150145* 8010160424 8010010601* 8010220454	CONTRACT 40-3392 70-1151 50-186 G 1&E
FEE, N. F. FEE, N. F. FEE, N. G FEE, N. F. FEE, N. F.	8010060323 8010070183 8010080444 8010100324 8010060319	50-336 P 50-336 P 50-245 P 50-213 P 50-245 P	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I.R.	8010090415 8010140244 8010140252 8010150470 8010210493	50-219 P 50-219 P 50-219 P 50-219 B 50-219 B	FISHER, W L FISHER, W L FISHER, W L FISHER, W L FISHER, W L	8010030517* 8010200124* 8010220496* 8010080136* 8010060072	50-154 Q 50-151 Q 50-237 F 70-36 ILE
FEE, H F FEE, W F FE LERABEND, C FEBERABEND, C E. FEBL, R	8010100222 8010170396 8010070302 8010070274 8010010372*	50-213	FINFROGK: I R. FINFROGK: I. R. FINFROGK: I R FINFROGK: I. R FINKEL: A E.	8010200475 8010210419 8010240477 8010310414 8010020067*	50-219 F 50-219 R 50-219 R 50-219 B 50-277 G	FIBHER, W. L FISHER, W. L FISHER, W. L FISHER, C. R. FIGHER, W. L.	8010080360 8010160370 8010200413* 8010200011 8010310547*	50-315 8 I&E 50-264 0 PR 50-123 0
FEIL.R. FEIL.R FEIT.C. K. FEIT.R FEIT.R.	8010230528* 8010240248* 8010010554 8010070286 8010170065	50-410 G 50-423 G 50-445 A REVIEW ORP REVIEW GRP	FINKEL, A E FINKLE, A E. FINLEY, A O FINLEY, A O. FIDRELLI, Q.	8010230157* 8010240574* 8010010193* 8010270389* 8010100373	50-336 0 50-272 0 50-304 0 50-155 0 50-327 5	FITTI,C J. FITTI,C J. FITTO 1800NS,R FITTO 1800NS,R FITTO 1800NS,R	8010270180* 8010270117* 8010270330 8010070411 8010210523	50-477 A 50-548 A 50-237 0 50-10 0 50-237 0
FELTON: J. H. FELTON: J. H. FELTON: J. K. FELTON: J. K. FELTON: J. K.	8010080048 8010150114 8010150119* 8010020135 8010020196	FDIA 70-820 70-820 70-143 70-143	FIGRELLI.O. FIGRELLI.O FIGRELLI.O. FIGRELLI.O.	8010100383 8008060283 8010090204 8010100421 8010010376	50-341 B 50-546 B 50-461 B 50-455 S 50-483 Q	FITTPATRICK, BE FITTSIMMONS, T FITTSIMMONS, Y FLANNIGAN, R. FLEENOR, C M	8010140187* 8010090279 8010090112 8010210649* 8010140430	50-305 Q 71-5088 71-5601 50-298 8 CONTRACT
FELTON: J. M FELTON: J M. FELTON: J M FELTON: J. M FELTON: J. M	9010020464 9010020096 9010020104 9010020704 9010020689	FOIA FOIA FOIA FOIA	FIORELLI, 0. FIORELLI, 0 FIORELLI, 0 FIORELLI, 0. FIORELLI, 0.	8010060122 8010060103 8010060037* 8010060034 8010010427	50-483 Q 50-461 Q 50-483 Q 50-483 Q 50-440 Q	FLEENOR, C M FLEISCHAKER, D FLEISCHAKER, D. FLEISCHAKER, D. FLEICHER, J O	8010140568 8010200174 8010200174 8010210497 8010170032*	CONTRACT 50-275 0 50-275 0 50-275 0 CONTRACT
FELTON, J. M FELTON, J. M. FELTON, J. M FELTON, T. M FELTON, J. K	8010040077 8010080040 8010070528 8010080044 8010070037	70-143 FOIA 50-445 H FOIA FOIA	FIORELLI.O. FIORELLI.O FIORELLI.O. FIORELLI.O. FIORELLI.G.	8010010505 8010010542 8010010711 8010140150 8010150146	50-454 Q 50-454 Q 50-315 Q 50-461 Q 50-456 Q	FLYNN, J. D. FLYNN, M. J. FLYNN, H. FLYNN, H. FLYNN, H. J	8008200140 8010020498 8010010273 8010010289 8010020249	50-358 F CONTRACT CONTRACT CONTRACT CONTRACT
FELTON: J. M. FELTON: J. M. FELTON: J. M. FELTON: J. M. FELTON: J. K.	9010100006 9010140060 9010140073 9010140604 9010160052	FOIA 50-358 H FOIA FOIA FOIA	FIGRELLI, Q. FIGRELLI, Q. FIGRELLI, Q. FIGRELLI, Q. FIGRELLI, Q.	8010200657 8010200672 8010090265 8010270115 8010200577	50-358 Q 50-454 0 50-358 B 50-358 Q 50-237 Q	FLYNN, M. J. FLYNN, M. J. FLYNN, M. J. FLYNN, M. J. FLYNN, M. J.	8010020711 8010160155 8010170574 8010230326 8010230441	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT

ROHTUA	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGOR/
FLYNN, M J	B010240560	CONTRACT	GALLEN, K P	8010030514	50-409 Q	OILLIEB, D, C	8010200447*	50-367 A
FDOO, H O	B010280604	50-255 K	GALLEN, K P	8010290387	50-409 Q	GILMAN, A, R	8010220149*	40-672
FOLEY, T	B010220148*	50-29 Q	GALLEN, K P	8010290387	50-409 Q	GILMAN, A, R	8010220159*	40-672
FOLEY, T,	B010240296*	50-29 Q	GALLEN, K P	8010300044	50-409 Q	GINMAN, R, A,	8010060116	PR
FONO, F T	B010140049*	50-274 Q	GALLEN, K P	8010300044	50-409 Q	DIRARD, E, H	8010170052*	50-327 9
FORD, H	8010020413*	50-546 U	GALLO, J	8010140493*	PR	OIRARD, E. H	8010270060*	50-518 4
FORD, E J	8010240249*	50-395 Q	GALLO, J.	8010140493*	PR	OIROUARD, P	8010140593	40-299
FORNEY, W L	8010100389	50-409 B	GALLO, J.	8010150364	50-201 0	OLAGOLA, A F	8009230181*	50-445 M
FORTUNA, R A	8010090110*	50-322 Q	GALLO, J.	8010240364	50-155 0	OLAGOLA, A F	8010200701*	CONTRACT
FOBTER, H	8010090164	70-1151	GALLO, J	8010240364	50-155 0	OLAZER, B. A.	8010030514	50-409 9
FOSTER, L E FOUCHE, R E FOULSHAM, P A FOULSHAM, P A FOX, D F.	8010070424*	50-344 Q	GANLEY, D E	8010070487	70-371	OLAZER, B. A.	8010030514	50-409 9
	8009300413	50-287 H	GANLEY, D E	8010200522	70-371	OLENN, J.	8010070648*	COMMEDSION
	8010140340	50-293 J	GANNIE, 8	8010240659	FOIA	OLENN, J.	8010160792	18E
	8010310350	50-293 J	GARCIA, P J	8010070542	40-3453	OLENN, J	8010160739	18E
	8010080176*	QA999	GARNER, D J	8010210270	50-312 F	OLICKHAN, D.	8010020374*	50-402 U
FOX,8 C FRALEY,R F FRALEY,R F FRALEY,R F	8010070425* 8010270143* 8010270110* 8010210512 8010210539	50-254 P 50-477 A 50-568 A ACRB ACRS	GARRARD, S GARRETT, E Q. GARY, R J. GARY, R J. GARY, R J	8010220414 8010220207# 8010070341# 8010170444# 8010310104	50-320 P 50-309 F 50-445 Q 50-445 Q 50-445 Q	QODDARD, R. J QODDARD, R. J QODDARD, R. J QODY, A. T. QOEBEL, Q. R	8010020027# 8010140498 8010140511 8010170030# 8010080372	50-237 8 50-367 8 50-237 8 50-312 8 NUMEO
Francis, E.	8010020087	40-8745	GARY, R J	8010010532	50-445 C	ODFF.C.W. OOLDBEROER.L. OOLDBERO.B.C. OOLDBERO.B.C	8010010297#	CONTRACT
Francis, E.	8010270558	40-2259	GARY, R J	8010080202	50-445 G		8010240423#	50-320 P
Frank, L	8010030345	50-344 P	GARY, R J	8010150391	50-445 F		8010010001	50-320 0
Frank, F. D.	8010170317*	CONTRACT	GARY, R J	8010200343	50-445 K		8010140520	50-250 0
Frechette, A L	8010240614*	CONTRACT	GARY, R J,	8010170502	50-445 B		8010146004	50-367 9
FREDERICK, E J	8010150223	RE8	OARY, R J	8010170479	50-445 B	QOLDBERO, 8 C. ODLDBERO, 8 C. ODLDBERO, 8 C. QOLDBERO, 8 C. QOLDBERO, 8 G.	8010220694	50-103 4
FREDRICKBON, P	8010240012*	30-321 Q	CARY, R J	8010200416	50-445 B		8010280615	50-367 9
FREDRICKBON, P	8010310199*	50-302 Q	CARY, R J	8010280354	50-445 B		8010300043	50-367 9
FREEMAN, J.	6010230258	40-1341	CARY, R J,	8010280358	50-445 B		8010300040	50-367 9
FRICK, J.	8010100437	PR	CASEARRO, D P	8010090322#	50-219 B		8010300055	50-367 9
FRIEDHAN, K A	B010080149*	GA999	OASBARRO, D P	8010210475*	50-219 B	OOLDMAN, H. L. OOLDBTEIN, M B OOLDBCHMIBT, P OOODHOPE, A. C. OOODHOPE, A. C.	8010270270#	50~155 P
FRIEDENHALD, R	B010200701*	CONTRACT	OASBARRO, D P	8010310421*	50-219 B		8010140270	50~320 P
FRIEDHAN, M	B010020669	50-416 8	OASCHLER, J. A.	8010070532	50-267 J		8010200666#	CONTRACT
FRIEDHAN, L F	B010060030	I&E	OATEB, B. H	8010240019*	6A999		8010070372	50~471 0
FROHRE, R	B010310466*	50-346 8	OATEB, H O	8010270376*	50-285 B		8010240074	27~39
FROWNE, R	8010070458*	50-346 B	gavin, p. k.	8010170003	NUREO	000DH0PE, A. C	8010240093	70-1308
FROST, B R.	8010080592	50-255 G	gay, r	8010090022	NUREO	000DMAN, L. B	8010150373#	50-409 R
FRYSEROER, P	8010060277	50-369 H	gay, r	8010090026*	NUREO	000DWIN, W, L	8010200287	70-1181
FULLER, M M	8010170315*	CONTRACT	gay, r	8010090029*	NUREO	000DWIN, C	8010300678	50-344 9
FULLER, J K	8010300349	50-267 G	gelbton, a h	8010070578*	50-327 B	000DWIN, C	8010080151#	50-344 9
FULLER, J K. FUNDERBURK, V FURBUBH, H H FURR, B J FURR, B, J	8010270362 8010140036 8010240544 8010150346 8010150256	50~267 P PR 50~133 0 50~324 0 50~261 0	OERNARO, D. V. OEOROIOU, B. S. OEOROE, S. J. OEOROIOU, B. S. OEOROIOU, B. S.	8010230362# 8010240311# 8010170218 8010160583 8010160544	TOPREP 50-275 H PR 50-275 Q 50-275 Q	OCCOMIN, C. OCCOMIN, M. L OCCOMIN, C. OCCOMIN, C. OCCOMIN, C.	8010080369 8010310319* 8010210740 8010010559 8010030432	50-344 ¢ 70-1151 PR 80-344 ¢ 50-344 ¢
FURR. B. J. FURR, B. J. FURR, B. J. FURR, B. J.	8010150265 8010210270 8010240067 8010240201 8010240286	50-261 Q 50-324 Q 50-325 Q 50-261 Q 50-261 Q	GEORGE, K D GERETY, H F GERMINE, T. J GERMINE, T J GERBINER, W C	8010280408 8010220425* 8010150366 8010240577 8010280505	50-54 P 50-219 J 50-289 Q 50-289 O 50-461 B	GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L. GRAEBBER, K. L.	8010020478 8010020532 8010140452 8010140426 8010210535	50-275 8 50-275 8 50-275 8 50-275 8 50-276 8
FURR, B. J	8010070297	50-325 Q	OERVASIO, B	B010270080*	50-320 H	GRAEBBER, K. L.	8010210644	50-295 8
FUTTER, J. L	8010160522	50-516 Q	OEST, R. E.	B010210174	70-754	GRAEBBER, K. L.	8010210683	50-295 8
FUTTER, J. L	8010160762*	50-516 Q	OETYLER, F. H	B010100194	NUREO	GRAEBBER, K. L.	8010310343	50-304 F
FUTTER, J. L	8010240076	50-596 Q	OETYLER, F. H	B010030419	NUREO	GRAHAM, M. J.	8009080194	50-93 8
QAD, R K	8010220547	50-443 Q	OETYLER, F. H	B010070302	NUREO	GRAHAM, M. J.	8010270186#	50-387 6
CAD, R. K.	8010220547	50-443 0	OIBBON, T. OIBBONS, T. OIBBONS, T. D. OIBBONS, T. D. OIBBONS, T. D.	8010150634*	FDIA	Graham, E. T.	8010060246*	50-293 8
CAD, R. K.	8010270513	50-443 0		8010150630*	FDIA	Graham, H. E.	8010070352	50-324 J
CAD, R. K.	8010270513	50-443 0		8010010228*	50-413 Q	Graham, E. T.	8010140454	50-293 8
CAD, R. K.	8010300072	50-309 0		8010240241*	50-328 Q	Graham, R. L.	8010160787	50-267 9
CAD, R. K.	8010300073	50-309 0		8010280064*	50-370 Q	Graham, E. T	8010210724*	50-29J 8
GAGE, L GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8010100021# 8010010344# 8010070233# 8010010072# 8010040178#	50-287 Q 50-242 Q 50-284 Q 50-285 Q 50-267 Q	OIBBS, D C OIBBS, D C, OIBSON, A. F. OIBSON, A F. OIBSON, O T.	8010020019 8010210010 8010240539* 8010020236* 8010220458	50~201 9 PR 50~335 F 50~364 G	ORAHAM, R. L. ORAHAM, E. T. ORAHAM, E. T ORAVES, R. H. ORAVES, R. H	8010200589 8010220535# 8010010674# 8010030468 8010150465	50-367 0 50-293 8 50-293 8 50-213 8 50-213 8
OAOLIARDO, J. E. OAHM, J. W. OAHM, J. W. OAHM, J. W. OAHM, J. W.	8010210605* 8010070407* 8010070416* 8010080339* 8010210719*	50-313	OIBSON, A. F. OIBSON, O. T. OIBSON, D. L. OIDO, R. O. OILBERT, L. D	8010160689 8010270295* 8010270423 8010080378 8010020191*	50-324 B 70-143 71-9039 Nureq 50-443 Q	ORAVEB, R. H ORAVEB, R. H ORAVEB, R. H. ORAVEB, R. H. ORAY, J. R.	8010160484 8010130367 8010280455 8010280458 8010070388	50-213 50-
OAHM J. H. OAHM J. H. OAHM J. H OAHM J. H OAHM J. H.	8010130517* 8010210456* 8010280477* 8010280551* 8010280586*	50-247 8 50-247 8 50-247 8 50-247 8 50-247 8	OILBERTS, D. E.	8010100381* 8010060112 8010060117 8010060120 8010080651	50-282 Q 50-263 Q 50-282 Q 50-263 Q 50-282 Q	ORAY, J. R. GREENMAN, E. O GREENMOOD, T. GREENMAN, E. O. GREENMAN, E.	8010190010 8010300243* 8010100184* 8010220707* 8010010100*	50-142 9 50-272 9 PR 50-213 9 50-245 0
OALLAOHER, E. J. OALLAOHER, E. J. OALLAOHER, J. H. OALLAOHER, J. H OALLAOHER, E. J.	8010240248 8010300600* 8010100431* 8010010244 8010240330*	ACRB 50-237 Q 50-277 Q 50-277 Q 50-329 Q	OILBERT, L. D. OILBERTS, D. E. OILES, P. B. OILINGKY, V. OILLESPIE, F. P.	8010310536* 8010220124 8010140476* 8010280495 8010310340*	50-458 Q 50-282 Q 50-275 H COMMISSION 70-1151	Greenman, E. Greenman, E. O, Greenmodd, T. Greenman, E. Greenberg, M. K	8010100044* 8010010136* 8010100178 8010080544 8010060124	50-336 0 50-277 0 PR 50-277 0 PR
OALLACHER, J. H. OALLACHER, J. H. OALLACHER, J. H. OALLACHER, J. H. OALLEN, K. P.	8010270214 8010070339 8010280372 8010280423 8010030514	50-320 P 50-277 P 50-277 P 50-277 P 50-409 Q	OILLEN, M. OILLEN, D. M. OILLEN, D. M. OILLETT, H. T. OILLETT, H. T.	8010020100 8010070104 8010220159 8010200410# 8010200415#	FOIA 40-8584 40-297 50-316 R 50-315 R	GREENHAN, E. GREENLEE, E. A. GREEN, D. GREEN, D. G. GREEN, H. J.	8010240064* 8010070064* 8010150335* 8010140004 8010270136*	00-244 \$ CONTRACT 50-237 \$ 50-445 H 50-123 \$

AUTHOR	ACCEBBION NUBBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	6UBJECT CATEGORY
OREGORY, H B	8010150548	70-820	ORIER, B. H	8010280171	50-27 Q	HAIRSTON, C A	8009230171	50-445 M
OREGORY, H B	8010300676	RES	GRIER, B. H	8010280173	50-245 Q	HAIRSTON, C	8010020592	CONTRACT
OREGORY, H T.	8010200606*	CONTRACT	ORIER, B. H	8010280174	50-287 Q	HAIRSTON, C	8010030338	CONTRACT
ORIER, B H.	8010200241*	50-272 G	GRIER, B. H.	8010280187	50-220 Q	HAIRSTON, C	8010020471	CONTRACT
ORIER, B H	8010300275*	50-272 G	GRIER, B. H.	8010280188	50-217 Q	HAIRSTON, C,	8010010255	CONTRACT
CRIER, BH. CRIER, BH. CRIER, BH CRIER, BH CRIER, BH	8010070077* 8010030124* 8010040077 8010300310* 8010010377	50-322	GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	8010280210 8010280214 8010280216 8010280219 8010280223	50-307	HAIRBTON, C HAIRBTON, C. HAIRBTON, C. HAIRBTON, C. HAIRBTON, C.	8010020293 8010010299 8010020619 8010200698 8010080611	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ORIER.8 H	8010010378	50-293	ORIER, B. H.	8010280224	50-277 0	Hairbton: C	8010010229	CONTRACT
CRIER.8 H	8010240343*		GRIER, B. H	8010280227	50-363 0	Hairbton: C.	8010140238	CONTRACT
CRIER.8 H	8010150500		ORIER, B. H.	8010280231	50-286 0	Hairbton: C	8010140404	CONTRACT
ORIER.8 H	8010230461		ORIER, B. H.	8010280233	50-293 0	Hairbton: C.	8010100397	CONTRACT
CRIER.8 H	8010020239		ORIER, B. H.	8010280237	50-3 0	Hairbton: C	8010140162	CONTRACT
GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H. GRIER, B. H.	8010070150 8010220076 8010070161 8010010416 8010240557	70-135 50-333	ORIER, B. H.	6010280239 6010280241 6010280243 6010280248 6010280250	50-334 G 50-213 G 50-317 G 50-322 G 50-412 G	HAIRSTON, C. A HAIRSTON, C. HAIRSTON, C. HAIRSTON, C. HAIRSTON, C.	8010160192 8010210002 8010030494 8010200646 8010140119	50-275
ORIER.B.H	8010030128	50-245 Q	ORIMES, B K ORIMES, B, K ORIMES, B K ORIMES, B, K, ORIMES, B K	8008240004	50-339 F	HAIRBTON, C	8010140375	CONTRACT
ORIER.B.H	8010040091	50-289 Q		8010150158	50-309 F	HAIRBTON, C.	8010150617	CONTRACT
ORIER.B.H	8010020175	50-245 Q		8010220187	50-309 F	HAIRBTON, W. O.	8010070621*	50-348 8
ORIER.B.H.	8010010078	50-245 Q		8010030482	TOPREP	HAIRBTON, C.	8010170570	CONTRACT
ORIER.B.H.	8010010177	50-317 Q		8010210475	50-348 H	HAIRBTON, C.	8010170605	CONTRACT
ORIER.B H	8010240129	50~213	ORIMEB, B. K	8010170537	50-334 F	Hairston, C.	8010170545	CONTRACT
ORIER.B H	8010010409		OROCE, R. H	8010200342	50-309 F	Hairston, C.	8010170617	CONTRACT
ORIER.B.H	8010040088		OROCE, R. H	8010240373	50-309 P	Hairston, C.	8010200579	CONTRACT
CRIER.B H	8010020150		GROELSEMA, D. H	8010030105	HABTE HOT	Hairston, C	8010200613	27-10
ORIER.B H	8010200359		ORONEMYER, E. L	8010270350	HABTE HOT	Hairston, C	8010200634	CONTRACT
ORIER, BH	8010200655	50-320 F	GROBBMAN, H	8010030435	50-367 0	Hairston, C,	8010200663	CONTRACT
ORIER, BH	8010210240	70-135	GROSBMAN, H	8010070021	50-367 0	Hairston, W o	8010210406*	50-348 R
ORIER, B.H	8010270111	50-293 Q	GROBBMAN, H	8010270359	50-155 0	Hairston, C,	8010210060	CONTRACT
ORIER, B.H	8010300224	50-272 Q	GROTENHUIB, M.	8010060019	50-250 H	Hairston, W o,	8010080457*	50-348 8
ORIER, B.H	8010270220	50-219 P	GROTENHUIB, M	8010160704	50-250 P	Hairston, W, o	8010210726*	50-348 6
ORIER.B.H	8010270428	50-317 Q	GROTENHUIB, H. QUODENHEIM, B. QUHIN, H. A. QUHIN, M. A. QUIDEMOND, W. Q	8010280182	50-250 P	Hairston, W C	B010210731*	50-348 8
ORIER.B.H	8010270432	50-213 Q		8010200276*	40-2061	Hairston, W, C	B0102B0502*	50-348 8
ORIER.B.H	8010270434	50-3 Q		8010100274	XPORTLIC	Haist, D. P	B010150031*	50-397 0
ORIER.B.H	8010270437	50-286 Q		8010140622	XPORTLIC	Haist, D. P.	B010100369*	50-508 0
ORIER.B.H.	8010270440	50-334 Q		8010010863*	50-266 Q	Haist, D	B010310314*	50-397 0
ORJER, B. H	8010270442	50-309	QUSTAFSON, R. B	8010070482	70-371	HAIBT.D P	8010230084*	50-397 G
ORJER, B. H	8010270445		QUSTAVE, R. P.	8010170377	CONTRACT	HALE.C J	8010080081*	GA979
ORJER, B. H	8010270447		QUSTAVE, R.	8010200219	CONTRACT	HALE.C.J.	8010080194*	GA979
ORJER, B. H	8010270451		QUSTAVE, R.	8010070036	CONTRACT	HALE.C.J	8010270576*	GA979
ORJER, B. H.	8010270453		QUSTAVE, R. P.	8010070067	CONTRACT	HALE.C.J	8010280735*	GA979
ORIER.B. H	8010270456	50-27	QUSTAVE: R. P.	8010170028	CONTRACT	HALL, R. E.	8010160027*	50-482 G
ORIER.B H	8010270186		QUSTAVE: R. P.	8010130352	CONTRACT	HALL, R. E	8010020191*	50-445 G
ORIER.B H	8010300058		QUSTAVE: R. P.	8010170316	CONTRACT	HALL, R. E.	8010270030*	50-382 G
ORIER.B. H.	8010300108		QUSTAVE: R. P.	8010170373	CONTRACT	HALL, R. E.	8010150472	TOPREP
ORIER.B. H.	8010300114		QUSTAVE: R. P.	8010200288	CONTRACT	HALL, R. E.	8010310536*	50-458 G
ORIER, B. H	8010300123	50-219	OUSTAVE, R. P.	8010170309	CONTRACT	Halhan, E, L	8010280133*	FOIA
ORIER, B. H.	8010300127		OUSTAVE, R. P.	8010160203	CONTRACT	Halhan, E L	8010240547*	CONTRACT
ORIER, B. H.	8010240110		OUSTAVE, R. P.	8010160319	CONTRACT	Hantlton, M	8010090483	50-201 F
ORIER, B. H.	8010240113		OUTELIUS-WATT	8010310328	PROJ	Hanback, G B	8010080308*	50-275 0
ORIER, B. H.	8010240116		OUTTHANN, H. E	8010300543	NUREG	Hanback, G B.	8010080308*	50-275 0
ORIERIB.H ORIERIB.H ORIERIB.H ORIERIB.H,	8010240118 8010240121 8010240123 8010240125 8010240128	50-213	OHYNN, T. P. Haass, W. P. Haass, W. P. Haass, W. P. Haass, W. P	8010160161* 8010150144 8010020641 8010100273 8010210628	50-358 G TOPREP TOPREP TOPREP TOPREP	Hangdok, J. A. Hangdok, J. A. Hangdok, J. A. Hangdok, J. A. Hangdok, J. A	8010210741 8010280370 8010066317 8010060227 8010070285	50-302 6 50-302 V 50-302 6 50-302 8 50-302 8
ORIERIB H,	8010240130	50-277	Haabb, W. P.	8010289676	TOPREP	Hangdok, J. A	8010310187*	50-302 0
ORIERIB H	8010240135		Haabb, W. P.	8010310229	REQOD	Hangdok, J. A.	8010200473	50-302 8
ORIERIB, H	8010240137		Hachney, C. A.	8010230265	50-201 Q	Hangdok, J. A	8010200479	50-302 8
ORIERIB, H	8010240139		Hack, A.	8010010353	NUREO	Hangdok, J. A.	8010280397	50-302 8
ORIERIB H	8010240141		Hafner, B.	8010220410	50-320 P	Hangdok, J. A.	8010280549	50-302 0
ORIER, B. H.	B010240143	50-219 Q	HAGAN, T. F.	8010020596	CONTRACT	Hangock, J. A	8010280531	50-302 8
ORIER, B. H.	B010240145	50-485 Q	HAGAN, T. F.	8010060135	CONTRACT	Hanek, J. F.	8010300218	50-311 P
ORIER, B. H.	B010240147	50-322 Q	HAGAN, T. F.	8010010300	CONTRACT	Hannon, G. J.	8010270315	WASTE MOT
ORIER, B. H.	B010240150	50-29 Q	HAGAN, T. F.	8010090060	CONTRACT	Hannon, J. N.	8010210115	TOPREP
ORIER, B. H.	B010240152	50-412 Q	HAGEN, E. W.	8010010551	NUREO	Hannum, D.	8010020417*	50-265 8
ORIER, B. H	8010240155	50-443 Q	Hagey, H.	8010010240	CONTRACT	Hannum, D.	8010140375*	50-254 8
ORIER, B. H	8010240158	50-352 Q	Hagey, H.	8010010434,	CONTRACT	Hansen, R.	8010270072*	50-320 H
ORIER, B. H,	8010240162	50-354 Q	Hagey, H.	8010090034	CONTRACT	Hansen, L. E.	8010070308	70-1257
ORIER, B. H,	8010240165	50-286 Q	Hagey, H.	8010080431	CONTRACT	Hansen, W. A.	8010010383*	50-403 G
ORIER, B. H,	8010240168	50-333 Q	Hagey, H.	8010090039	CONTRACT	Hansen, L. E.	8010220287	XPORTL1C
GRIER, B. H	8010240169	50-272	Hagey, H.	8010300143	CONTRACT	Hansen, L. E.	9010270184	XPORTLIC
GRIER, B. H	8010240171		Hagey, H.	8010150605	CONTRACT	Hansen, L. E	9010270191*	XPORTLIC
GRIER, B. H	8010240175		Hagey, H.	8010270006	CONTRACT	Hansen, W. A.	9010270385*	50-489 G
GRIER, B. H,	8010300279		Hagey, H.	8010270087	CONTRACT	Hanson, D. J	9010010802	RES
GRIER, B. H	8010280156		Haging, E. E	8010030131	50-409 Q	Hanson, R. G	9010080234	RES
ORIER, B. H.	8010280160	50-443 Q	Haqinb, E. E.	8010200677	50-275 9	Hanson, W. H	8010270435	40-299
ORIER, B. H.	8010280162	50-485 Q	Haque, R.	8010090191	50-301 B	Hardin, A. K	8010160668	50-280 8
ORIER, B. H.	8010280165	50-410 Q	Haque, R. L.	8010010863*	50-266 G	Hardin, A. K.	8010090309	50-281 8
ORIER, B. H.	8010280167	50-387 Q	Hairbton, C. H.	8010010310	CONTRACT	Hardin, A. K	8010100254*	50-261 0
ORIER, B. H.	8010280168	50-352 Q	Hairbton, C.	8010170551	CONTRACT	Harding, R. S.	8010020679*	CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	BUBUECT CATEOOFT
HARDWICK, R J HARMON, D HARMON, D HARMON, D HARMON, D	8010150671* 8010070019* 8010070505 8010070515 8010070520	50-324 @ 50-280 @ XPORTLIC XPORTLIC XPORTLIC	HEISEY, R HEISHMAN, R. F HEISHMAN, R. F HEISHMAN, R. F HEISHMAN, R. F	8010150396 8010140381 8010140387 8010100406 8010090191	50-289 H 50-266 8 50-255 8 50-266 8 50-301 8	HENBLEY, K D HEPLER, A B HERBEIN, J O HERBEIN, J O HERBEIN, J G	8010310300 8010230717* 8010240309* 9010010203 8010010762	70-143 50-339 h 50-289 6 50-289 6
HARMON, D	8010070525	XPORTLIC	HEISHMAN, R. F	8010070174	50-301 B	HERBEIN, J Q	8010040133	50-289 1
HARMON, D	8010070502	XPORTLIC	HEISHMAN, R. F	8010070174	50-247 B	HERDT, A. R	8010140115*	50-250 8
HARMON, D	8010270178	XPORTLIC	HEISHMAN, R. F	8010070183	50-305 B	HERDT, A	8010010028*	50-327 1
HARMON, D	8010270182	XPORTLIC	HEISHMAN, R. F	8010100411	50-265 B	HERDT, A R	8010030509*	50-369 1
HARMON, D	8010270188	XPORTLIC	HEISHMAN, R. F	8008040278	50-263 B	HERDT, A R	8010140156*	50-403 1
HARMON, D HARRAN, Q HARR ISON, J HARR ISON, J HARR ISON, P	8010290156 8010210430* 8010200691* 8010200678* 8010080482*	XPORTLIC 50-245 R 50-546 Q 50-546 Q 50-220 B	HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF,	8010090285 8009080200 8009080216 8010080371	50-254 8 50-331 8 50-249 8 50-346 8 50-255 8	HERDT, A R	8010070152* 8010020273* 8010070031* 8010270407* 8010170052*	50-280 1 50-281 1 50-335 1 50-324 1 50-327 1
HARRISON, P	8010200535*	50-220 8	HEISHMAN.R F	8010090197	50-304 \$	HERDT, A.R.	8010140034+	50-413
HARRISON, P	8010300463*	50-220 8	HEISHMAN.R F	8010080338	50-255 \$	HERDT, A.R.	8010230262+	50-366
HARRISON, P	8010310454*	50-220 8	HEISHMAN.R F.	8010080347	50-346 \$	HERDT, A.R.	8010270060+	50-318
HARTER, E S	8010100078*	70-1703	HEISHMAN.R F.	8010080362	50-255 \$	HERDT, A.R.	8010240120+	50-413
HARTER, E S	8010100076*	70-1703	HEISHMAN.R F	8010150133	50-263 \$	HERDT, A.R.	8010140121+	50-400
HARTER, E S HARTFIELD, R A HARTFIELD, R A HARTMAN, C, J HASBROOK, R	8010230643 8010150433* 8010070593 8010140448 8010090011*	70-2933 50-312 P 50-324 8 50-155 R CONTRACT	HEIBHMAN, RF. HEIBHMAN, RF HEIBHMAN, RF HEIBHMAN, RF. HEIBHMAN, RF.	8010100422 8010010853 8010100389 8010100386 8010100418	50-304 \$ 50-407 Q 50-407 8 50-255 8 50-159 8	HEREFORD, J. M HERLIHY, D. M. HERMANN, R. A. HERNANDEZ, Q. HERNANDEZ, Q.	8010080392* 8010150443 800828073 801028087* 801010108	50-327 40-9776 50-305 50-460 50-508
Hashindfo, k	8010100163	REGOD	HEIBHMAN, R F	8010150096	50-331	HERNANDEZ, V. A	8010060232*	50-302 1
Hashindta, p s	8010150153	NUREO	HEIBHMAN, R F	8010140161		HERSCH, M. H	8010210195*	FOLA
Hasten, m v	8010200031	PR	HEIBHMAN, R F,	8010150085		HERSCH, M. M	8010270261	XPORTLIC
Hastinds, w	8010210565	50-514 Q	HEIBHMAN, R F,	8010150106		HERSCH, M. M	8010270267*	XPORTLIC
Hastinds, w	8010210571*	50-514 O	HEIBHMAN, R F,	8010160153		HERSKOVITZ, M. B.	8010310360	RES
HASTINGS, W	8010290378	50-514 0	HEISHMAN, R F	8010070283	50-255 8	HEYER, R. HEYER, R. 8 HEYER, R. 8 HICKCOX, S. T. HICKEY, C. R	8010060055	40-858\$
HATHWAY, C, W	8010030440>	CONTRAGT	HEISHMAN, R F,	8010070287	50-305 5		8010230335	40-8502
HAUGHNEY, C J	8010100123>	50-201 H	HEISHMAN, R F	8010070277	50-305 6		8010220146	40-8727
HAUGHNEY, C J,	8010070674	50-201 J	HEISHMAN, R F	8010150118	50-155 0		8010310258	RECOD
HAUGHNEY, C J	8010080649	50-201 P	HEISHMAN, R F	8010070276	50-305 8		8010170345	50-320 A
HAUGHMEY.C J HAUGHMEY.C J HAUGHMEY.C J HAUGHMEY.C J	8010070076 8010100120 8010220093 8010130088 8010310621	50-201 P 50-201 H 50-201 P 50-201 H 50-201 H	HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F, HEISHMAN, R F HEISHMAN, R F	8010150230 8010160133 8010010859 8010090234 8010090245	50-341 Q 50-373 Q 50-266 Q 50-409 B 50-255 B	HIESHMAN, R F. HIESTAND, O S HIESTAND, O S HIESTAND, O. S. HIESTAND, O S.	8010160182 8010030514 8010270387 8010270387 8010300044	50-305 1 50-409 4 50-409 6 50-409 6
HAVERKAMP, DR	8010100374	50-217 8	Heishman, R. F	8010070277	50-255 8	HIQOINS, J. C	8010020231*	50-286 8
HAWKINS. F	8010070314	50-546 8	Heishman, R. F	8010070280	50-155 6	HIQOINS, J. C.	8010240124*	50-322 8
HAWKINS. FC	8010270133*	50-546 G	Heishman, R. F	8010080228	50-274 0	HILL, W. M	8010010631*	50-272 8
HAWKINS. RC	8010230037	NUREG	Heishman, R. F	8010090302	50-282 8	HILL, W. M.	8010230274*	50-272 8
HAYDEN, LE	8010230192	50-413 B	Heishman, R. F	8010090274	50-282 8	HIMEBAUCH, N	8010140455*	50-155 8
HAYEB, D. W HAYEB, D. W HAYEB, D. W. HAYEB, D. HAYEB, D. W	8010080553 8010010432* 8010010620* 8010090314 8010300600*	50-546 8 50-440 0 50-454 0 50-546 8 50-237 0	HEISHMAN, R.F. HEISHMAN, R.F. HEISHMAN, R.F. HEISHMAN, R.F. HEISHMAN, R.F	8010090262 8010080626 8010240031* 8010100003 8010240037	50-10 8 50-255 8 50-255 0 50-373 0 50-263 0	HINCKLEY, D. O. HIND, J. A. HIND, J. A. HIND, J. A. HIND, J. A	8010170090* 8010010193* 8010010184 8010010396* 8010010349	50-312 b 50-304 b 50-304 b 50-315 b
HAYEB, D. W.	8010240330*	50-329 Q	HEIEHMAN, R F	8010100225	50-346 Q	HIND, J. A	B010010685	50-254 4
HAYEB, D W.	8010290133*	50-546 Q	HEISHMAN, R F	8010140088	50-409 Q	HIND, J. A.	B010160177*	50-409 4
HAYEB, D W	8010290151*	50-461 Q	HEISHMAN, R F	8010170313	50-275 Q	HIND, J. A	B010170546*	50-331 4
HAYMAN, R E.	8010170277	NUREO	HEISHMAN, R F	8010140670	50-274 Q	HIND, J. A	B010170538*	50-255 4
HAYNEB, R C	8010150031*	50-397 Q	HEISHMAN, R F.	8010240033	50-358 Q	HIND, J. A.	B010170533	50-255 4
HAYNES,R C	8010310018*	50-508 @	HEISHMAN, R F	8010310580	50-116 Q	HIND, J. A	8010170343	50-331 8
HAYNES,J O.	8010080274	50-204 @	HEISHMAN, R F	8010270216	50-255 Q	HIND, J. A	8010230056*	50-346 8
HAYNES,J O.	8010300682	50-206 @	HEISHAN, R F,	8010070255	50-304 E	HIND, J. A	8010230049	50-346 8
HAYNES,R C	8010310314*	50-397 @	HEISTAND, O S	8010300044	50-409 Q	HIND, J. A.	8010270394*	50-150 8
HAYNES,R C.	8010230077*	50-275 @	HELFRICH, O F.	8010160067	XPORTLIC	HIND, J. A.	8010270386	50-155 8
HAYNES, J O	8010040289	50-204 8	Heller, J.	8010080371	50-255 8	HIND, J A	8010270387*	50-155 ± 50-150 ± 50-155 ± 50-155 ± 50-155 ±
HAYNES, R. C	8010230084*	50-397 0	Heller, J	8010080338	50-255 8	HIND, J A,	8010270392	
HAYNES, J. O	8010270370	50-206 0	Heller, J	8010080362	50-255 8	HIND, J, A,	8010270155*	
HAYNES, R. C	8010280041*	50-397 0	Heller, J. K	8010240031#	50-255 0	HIND, J A,	8010270125*	
HAYNES, R. C	8010310278*	50-361 0	Heller, J. K	8010270224#	50-255 0	HIND, J, A.	8010270153	
HAYNES, J. Q HAYNES, R. C HAYNES, J. Q. HAYNES, M. L.	8010210673 8010280026* 8010270378 8010270379* 8010080350*	50-206 8 50-275 Q 50-206 8 50-206 8 GONTRACT	HELWICK.C HEMANDEZ.V A HENDRIX.O W HENDRIE.J M HENDRIE.J.M	8010010233 8010210747* 8010270041 8010140001 8010140114	50-142 Q 50-302 B REGOD COMMISSION COMMISSION	Hind, J. A. Hines, E. Hines, E. Hines, E. Hines, E	8010270120 8010220057 8010070107 8010200572 8010270273	50-60 8 50-341 8 50-341 8 50-341 8 50-341 6
HEAD, W. J. HEADLEY, K. D. HEARN, P. L. HEATH, H. H HECKLER, M. M	8010230215 8010200223* 8010070639* 8010090070* 8010100111*	40-7869 CONTRACT 50-289 O CONTRACT 50-293 H	HENDRIE, J M HENDRIE, J, M HENDRIE, J, M HENDRIE, J, M	8010060005 8010060008 8010210786 8010020384 8010200003	COMMISSION COMMISSION COMMISSION COMMISSION	Hines, e Hines, e. Hines, e Hintze, a. s. Hintze, a. s.	8010150538 8010270187 8010240513 8010060047 8010270328*	50-341 8 50-341 8 50-341 8 REQUD REQUD
HEGNER, T. D.	8010010813*	50-334 Q	Hendrie, JK,	8010200004	COMMISSION XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-416 8	HOBSON, D O,	8010060025	NUREQ
HEIDER, L. H	8010010817	50-271 Q	Hendrick, WG,	8010240499		HOCHREITER, L. E	8010290171	NUREQ
HEIDER, L. H.	8010010577	50-271 Q	Hendrick, WG,	8010300309		HOCK, B,	8010220118	PR
HEIDER, L. H	8010010727	50-27 Q	Hendrick, WG	8010300318*		HODGES, J W	8010230137*	70-1113
HEIDER, L. H.	80100150267	50-27 P	Henkel, HL	8010210003		HOFFMAN, D P.	7904120234	50-233 P
HEIDER, L. H	8010150461	50-271 P	HENKEL; H. L. HENRY, S. HENRY, L. HENBLEY, K. D. HENBLEY, K. D.	8010200710	50-416 B	HOFFMAN, D. P	7904170157	50-235 P
HEIDER, L. H	8010160571	50-29 P		8010080386	NUREO	HOFFMAN, D. P.	8001020430	50-255 P
HEIDER, L. H	8010280221	50-271 P		8010100308	50-57 J	HOFFMANN, D. P.	8004010289	50-255 P
HEIM, G. E	8010300119*	27-39		8010150612	70-143	HOFFMAN, D. P	8010090514	50-155 8
HEINANDY, VA,	8010280710*	50-302 8		8010210485	70-143	HOFFMAN, D. P.	8010220475	50-155 F

RDHŢŲA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8010220448 8010070303 8010220480 8010020307 8010020347	50-155 P 50-155 P 50-155 P 50-155 Q 50-255 Q	HOVEY, G K HOWARD, T R HOWARD, J, E HOWARD, J, E HOWER, P, W	8010310426 8010200263 8010020476 8010140382 8010140131*	50-320 8 40-3453 50-293 P 50-471 B 50-400 0	HUNTER, V H HUNTER, R & HUNTER, R. B HUNTER, R S HUNTER, R S	8010270011* 8010010539 8010030388 8010200340 8010020497	0A777 50-316 P 50-316 P 50-315 Q 50-315 P
HOFFHAN, D P HOFFHAN, D P HOFFHAN, D P HOFFHAN, D P	8010070595 8010090410 8010220131 8010060305 8010100237	50-255 B 50-155 P 50-155 Q 50-255 B 50-155 P	HOVE, R. J. HOWE, P. W. HOWE, P. W. HOWE, P. W. HOWELL, J. C.	8010160659# 8010140035 8010310341# 8010080215 8010060158#	0A999 50-400 G 50-400 G 50-400 G 50-348 G	HUNTER, R S	8010150412 8010160534 8010210370 8010280431 8010270121	50-315 P 50-315 P 50-315 I 50-315 F 40-8743
HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8010160601 8010140411 8010150271 8010150403 8010150503	90-255 P 50-155 8 50-155 P 50-155 P 50-255 6	HOWLE, J HOWLETT, G H HOYLE, D B HOYLE, J C	8010270399* 8010220204 8010210435* 8010070044* 8010170064	50-327 Q PR 50-336 R FOIA ACRS	HUSSEY, JR HUTTON, PH HYNESIE, H IANNI, PW IANNI, PW	8010140557* 8010150587 8010230376* 8010020337* 8010100318*	50-466
HOFFHAN, D.P. HOFFHAN, D.P. HOFFHAN, D.P. HOFFHAN, D.P.	8010150311 8010160559 8010200440 8010200555 8010230393	50-255 F 50-255 8 50-255 Q 50-255 P 50-155 8	HOYLE, J C HOYLE, J. C HOYLE, J. C HOYLE, J C HOYLE, J C	8010170467 8010170279 8010220182 8010220189 8010270031#	ACRB ACRB ACRB ACRB FOIA	IDRISS.I K INORAM.F L IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8010200299* 8010220304 8010080333 8010020450 8010020026	CONTRACT 50-352 H 50-273 Q 50-259 P 50-237 Q
HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOLCOMB, O.R. HOLEMAN, O.R.	8010270285 8010310452 8010310353 8010080633* 8010060040*	50-155 P 50-155 P 50-255 P CONTRACT COMMISSION	Hayle, A Hayle, J C Hayle, J C Hayle, J C. Hayle, J, C	8010200324 8010150004 8010160166* 8010270187 8010300502	CONTRACT 50-556 O 50-556 O 10CFR 10CFR	IPPOLITO, Y A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T, A IPPOLITO, T, A	8010230227 8010010765 8010060024 8010060061 8010060012	50-237 0 50-133 P 50-220 P 50-333 F 50-237 P
HOLLAND: P HOLL INOSWORTH HOLCDY: D. J HOLDDY: D. J HOLDWAY: C. F	8010210524* 8010150278* 8010240114* 8010230077* 8010220579	50-237 8 50-312 R 70-135 70-371 RES	HOYLE, J. C. HOYLE, J. C HOYLE, J. C HOVLE, J. C HOU, Y RUBACEK, N. O	8010300511 8010300518 8010300525 8010220132 8010270022*	10CFR 10CFR 10CFR MISC 50-482 G	IPPOLITO, T. A	8010070263 8010080390 8010080453 8010080455 8010080534	50-271 P 50-298 P 50-220 P 50-339 P 50-259 P
HONIA L HOPKINS, J B HORINIS A HORINIS A HORINIS A	8010220132 8010150102* 8010020729 8010080263 8010080263	MISC 50-331 Q 50-445 Q 50-445 G 50-445 G	Hudacek, W. O Hudacek, W. O Hudbon, O. R. Hudbon, O. R Hudbon, B. D.	8010160774 8010300566 8010080002 8010020644* 8010200605	50-498 8 50-498 8 PR PR 50-220 8	IPPOLITO, T A IPPOLITO, T A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A	8010080574 8010080613 8010080621 8010070240 8010150357	50-293 P 50-263 P 50-324 P 50-237 P 50-325 P
HORIN, HA HORIN, HA HORIN, HA HORIN, HA HORN, AJ	8010210503 8010210503 8010310436 8010310436 8010170466*	50-445	HUDSON, O R HUKILL, H D HUKILL, H D	8010200017 8010170074 8010040186 8010200647 8010020395	PR NUREO PR 50-289 G 50-289 P	IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T. A IPPOLITO, T. A	8010150361# 8010150363# 8010160723 8010210793 8010280001	50-325 P 50-325 P 50-331 F 50-271 F 50-273 P
HORN, A HOSEY, C. M HOSEY, C. H HOUSTON, K. D. HOUSTON, K. D.	8010100287 8010240539* 8010160689 8010100035 8010200711	50-206 8 50-335 F 50-324 B 50-440 K 50-440 K	HUKILL, H D HUKILL, H D HUKILL, H, D HUKILL, H, D	8010230205 8010030402 8010060208 8010070371 8010070418	50-289 Q 50-289 F 50-289 P 50-289 P 50-289 P	IPPOLITO, T A IPPOLITO, T A IPPOLITO, T, A IPPOLITO, T A IPPOLITO, T A	8010280002* 8010280003* 801024003 8010240081* 8010240091*	50-293 P 50-273 P 50-259 P 50-259 P 50-259 P
HOUSTON, M D HOUSTON, M D HOUSY, O, K HOUSY, O K HOUSY, O K	8010280058* 8010270331 8010230214 8010040140 8010060145	50-440 Q 50-440 C 50-320 S 50-320 Q	HUKILL:H D HUKILL:H D HUKILL:H D. HUKILL:R D HUKILL:R D	8010070323 8010070542 8010070335 8010080514 8010100279	50-289 P 50-289 P 50-289 P 50-289 Q 50-289 V	IPPOLITO,T A IPPOLITO,T A IRELAND,J H IRISH,E R IRWIN,D P	8010270193 8010310125 8010210447 8010100213 8010020651	50-271 P 50-324 Q 50-255 J PR 50-201 O
HOVEY, OK HOVEY, OK, HOVEY, OK, HOVEY, OK	8010030305 8010010733 8010140308 8010200005 8010200375	50-320 P 50-320 G 50-320 B 50-320 G 50-320 Q	HUKILL,# D HUKILL,# D HUKILL,# D HUKILL,# D HUKILL,# D	8010140462 8010150484 8010220476 8010160479 8010200423	50-287 P 50-287 8 50-287 V 50-287 I 50-287 P	IBLEY, T. ITO, T. Jabbour, K n Jablon, R. A Jablon, R. A	8010010513* 8010220483 8010230615 8010150399* 8010150419*	50-346 8 PR 50-275 A 50-387 M 50-389 M
HOVEY, O K, HOVEY, O K HOVEY, O K. HOVEY, O K HOVEY, O, K	8010030409 8010270182 8010010441 8010010454 8010300287*	50-320 8 50-320 0 50-320 P 50-320 8 50-320 Q	HUKILL, H D. HUKILL, H D. HUKILL, H D. HUKILL, H D. HUKILL, H D	8010200486 8010200460 8010210429 8010210445 8010210453	50-287 P 50-287 P 50-287 R 50-287 P 50-287 P	JABLON, R.A. JABLON, R.A. JACKIH, I.N. JACKBON, L.L. JACKBON, O.	8010150372 8010170364 8010240133* 8010160061* 8010230647*	50-387 M 50-389 M 50-247 Q 50-324 Q 70-2933
HOVEY, O K HOVEY, O K. HOVEY, O K. HOVEY, O K HOVEY, O K	8010070428 8010090401 8010070447 8010230212 8010230306	50-320 P 50-320 S 50-320 P 50-320 G 50-320 G	HUKILL, H. D HUKILL, H. D HUKILL, H. D. HUKILL, H. D. HUKILL, H. D.	8010210465 8010210474 8010240453 8010300457 8010280482	50-289 P 50-289 P 50-289 P 50-289 P 50-289 P	JACKBON.T J. JACKBON.T J JACKBON.G. JACKBON.K E. JACKBON.J B	8010010224* 8010020218* 8010280114* 8010230523 8010270357*	
HOVEY, O, K. HOVEY, O, K. HOVEY, O, K HOVEY, O, K	8010310423* 8010080471 8010100343 8010140413 8010140418	50-320 P 50-320 8 50-320 P 50-320 8 60-320 P	HULMAR, L. C. Hume, R. D. Hunnicutt, D. K Hunnicutt, D. M Hunnicutt, D. K	8010200018 8010240043 8010010180* 8010070150 8010246028*	PR NUREO 50-285 G 50-313 E 50-313 G	JACOBB.L JACOBB.A JACOBB.A JACOBB.B.B. JACOBB.A	8010310339 8010160767 8010090066 8010210199 8010010274	PROJ PR CONTRACT REGGO CONTRACT
HOVEY, O K HOVEY, O K HOVEY, O K	8010140424 8010150385 8010310021 8010160499 8010200419	50-320 J 50-320 V 50-320 Q 50-320 P 50-320 8	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D, M HUNNICUTT, D, K HUNNICUTT, D, K	8010090148 8010210405* 8010070158 8010040057 8010300571	50-313 B 50-313 Q 50-313 B 50-368 S 50-313 B	JACOBB: A JACOBB: A JACOBB: A JACOBB: A JACOBB: B	8010080665 8010200292 8010080628 8010070006 8010210706	CONTRACT CONTRACT CONTRACT CONTRACT FR
HOVEY, O. K HOVEY, O. K HOVEY, O. K HOVEY, O. K.	8010200424 8010210527 8010200438 8010200452 8010210640	50-320 8 50-320 \$ 50-320 P 50-320 P 50-320 P	Hunstad; A. A Hunstad; A. A Hunstad; A. A. Hunstad; A. A. Hunstad; A. A.	8010150502* 8010150471* 8010150482* 8010200548* 8010210705*	50-282 R 50-282 8 50-282 8 50-304 8 50-304 8	JACOBB. A. JACOBB. A. JACOBB. B B JACOBB. A JACOBI. L. R	8010160191 8010200228 8010200201 8010160327 8010210058	CONTRACT CONTRACT PR CONTRACT REGOD
HOVEY, O K HOVEY, O K HOVEY, O. K HOVEY, O. K HOVEY, O. K	8010220431 8010310418 8010210507 8010230500 8010280428	50-320 R 50-320 R 50-320 P 50-320 P 50-320 P	HUNT, M. HUNT, M. D. HUNT, M. D. HUNT, M. D. HUNTER, D. R.	8010080445 8010010057* 8010240173* 8010240042* 8010170050*	50-413 0 50-364 0	JAMIBON, J. D. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F. JANECEK, R. F.	8010150628 8010270355 8010070157 8010200282 8010100241	70-1257 50-10 P 50-237 G 50-237 G 50-237 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIO"	京 日 P "#" ,
JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	8010100250 8010190665> 8010070374 8010070420 8010140215	50-237 P 50-237 P 50-10 P 50-254 P 50-237 P	JONES, W C JONES, J L JONES, W C JONES, G B JONES, W C	8010140337 8010070546* 8010300508* 8010210005 8010070374	50-285 F 50-269 8 50-285 Q 50-354 8 50-285 P	KANE, W KANE, W KANE, W KANE, W KANE, W	8010233106 8010169243 8010140145 8010160245 8010070120	
JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	8010070534 8010280235 8010150343 8010150434 8010150444	50-237 P 50-237 P 50-10 P 50-10 P 50-10 P	JONES, J L JONES, B W JONES, B H	8010140325* 8010160549* 8010200400 8010160597 8010160605	50-207 8 50-205 P 50-205 R 50-327 0 50-329 0	KANE, W KANE, W KANE, W KANE, W KANE, W	8010090444 8010140107 8010230553 8010230491 8010230030	# 1
JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	6010240203 6010210401 6010260254 6010270333 6010270366	50-237 P 50-10 P 50-373 K 50-237 P 50-10 P	DOMES'N C NOMES'N C NOMES'N C NOMES'N C	8010210539* 8010240208 8010300492 8010240479* 8010280388*	50-270 8 50-285 F 50-285 0 50-270 8 50-270 8	KANE,W F KANE,W F KANE,W F KANE,W F KANE,W	8010230576 8010270219 8010170133 8010280127 8010270934	Section 1
JANUSKA: A Q JAPE: F JAUDON: J. P JAUDON: J. P JENCKES: T. A	8010160346* 8010010131* 8010010072* 8010050178* 8010200433	50-254 Q 50-269 Q 50-285 Q 50-267 Q NUREQ	JONES, R A JONES, B W JORDAN, L V JORDAN, L V JORDAN, E L.	8010310321 8010300094 8010150635 8010210283 8010280711	50-285 P 50-329 0 70-27 70-27 50-282 P	KANE, W F KANE, W Kane, W F Kaplan, A L Kaplan, A L	8010280201 8010300577 8010300575 8010060027 8010230197	50 295 A 50 295 A 70-11 71-62-4
Jenkins. O r Jenkins. O r Jenkins. O r Jenkins. A	8010080439 8010160703 8010220458 8010270295* 6010240623*	50-261 5 50-339 5 1&E 70-143 50-320 P	JORDAN, W 8 JORDAN, W 8 JORDAN, W 8 JORDAN, W 8 JORDAN, W 8	8010070037 8010070041* 8010070037 8010070041* 8010210260	PR PR PR PR 50-443 G	Kaplan, a l Kaplan, a l Kaplan, d a Kaplan, d a Kaplan, a l	5010020127 8010150119 8010060349* 8010060353* 8010310507	71-9 72 1' : 52 667 5 53-847 5 73-11-
JENKINS, OR JENKINS, RV JENS, WH JENSEN, W.L JENSEN, W	8010270416* 8010020484* 8010170128 8010070637* 8010200222*	50-338 0 50-295 8 PR 50-289 0 50-289 T	JORDAN, H 8 JORGENSEN, B L JORGENSEN, B L JORGENSEN, B L JORGENSEN, B L	8010210240 8010140387 8009030035 8010090293 8010100386	50-443 0 50-255 8 50-258 8 50-255 8 50-255 8	KAPLAN, D. A. KARMAN, M. KARMAN, M KATO, W. Y KATO, N. Y	8010150549 8010140007 8010140011 8010080185 8010230028	50-005 M 50-454 & 50-404 & 50-404 & 50-504 & 50-505 50-50
Jenson, C. M Jernigan, E. P Johnson, I. B Johnson, I. B Johnson, I. B	8010010245* 8010240290* 8010080434 8010090493 8010220172	50-72 R 50-277 G 50-461 H ACRB ACRS	JORGENSEN, B. L. JORGENSEN, B. L. JORGENSEN, B. JORGENSEN, B. JORGENSEN, B. C.	8010090245 8010090277 8010090280 8010080626 8010240031*	50-255 S 50-255 S 50-155 S 50-255 S 50-255 Q	KAUFFMAN, J T KAUFMAN, N C KAUFMANN, R KAUFMAN, N C KAUSCH, T J	8010070585 8010010604 8010150107 8010300232 8010090070	50-307 A RES 40-3708 RES 50-254 Q
JOHNSON, I B JOHNSON, I R JOHNSON, W D JOHNSON, W D JOHNSON, P H	8010220178 8010240234 8010080170* 8010070150 8010070379*	ACR8 ACRS 50-344 Q 50-313 S 50-344 Q	JOYNER, J. H. JOYCE, J. H. JOYCE, J. H. JOYNER, J. H. JONNER, B. L. JOYNER, B. L.	8010270224* 8010150454* 8010070636* 8010140070* 8010020702*	50-255 0 50-206 R 50-289 0 70-1143 70-135	KEANY, 8, KEARNEY, J J KEARNEY, J J KEARNEY, J J KEHRET, D	8010270048 8010200007 8010240001 8010030471 8010160371>	# # # # # # # # # # # # # # # # # # #
JOHNEDN, J. K JOHNSTON, B. F JOHNSON, A. H JOHNSON, A. JOHNSON, W. D	8010280735* 8010230115* 8010020787* 8010160588 8010240028*	QA999 50-244 G 50-369 G 50-281 B 50-313 G	ONKEY'N H YN YBBAND YN YBBAND YN YBBAND YN YBBAND	8010010341* 8010010417* 8010240114* 8010240284* 8010200361*	70-371 70-135 70-135 70-820 70-1100	KEHRET, D KEIMIO, R. R. KEIMIO, R. R. KEIMIO, R KEIMIO, R. R	8010300444* 8010020771* 8010010431* 8010080358 8010080450	50-249 4 50-272 4 50-272 5 50-272 5
JOHNSON, W D JOHNSON, W D JOHNSON, W D JOHNSON, N R JOHNSON, C. R	8010070168 8010210605* 8010070158 8010030516 8010070188	50-313 S 50-313 Q 50-313 S XPORTLIC 71-6698	JOYNER, J H JUDNICK, W JULIAN, C JULIAN, C JULIAN, C A	6010230099* 8010090008 8010090329 8010140027* 8010160797	70-371 NUREO 50-327 8 50-327 0 50-321 5	KEIMIO, R KEIMIO, R R KEIMIO, R R KEIMIO, R R KEIMIO, R R	8010080376 8010240351* 8010230294* 8010100030* 8010240176*	50-200 i 50-210 i 50-210 i 50-210 i
JOHNSON, C. W JOHNSON, E JOHNSON, A. D JOHNSON, B. R JOHNSON, R. W	8010230190* 8010160292* 8010310082* 8010270356* 8010010364	50-344 Q QA999 50-27 Q QA999 50-344 Q	JULIAN, C JURGENSEN, R (I JURGENBEN, R (I JURGENBEN, R (I KAHLE, J. B	8010140367 8010210728 8010140321 8010160519 8010100020*	50-259 S PR TOPREP TOPREP 70-143	KEIMIO, R. KEIMIO, R. KEIMIO, R. KEIMIO, R. KEIMIO, R.	8010080565 8010010420 8010090222 8010080356 8010270040	#C-21F E 50-21G F 50-22G F 50-22G F
POHNOEN, W P RICENTIAN P. ROSENBOL P. ROSENBOL R. RICENBOL POHNOENBOL	8010040331 8010070365 8010140204 8010200679 8010270325	50-307 P 50-263 J 50-309 P PR XPORYLIC	KAHLE, J B Kahle, J B. Kahle, J B. Kahle, R Kahle, J, B	8010040087 8010040082 8010070227* 8010020595* 8010030151*	70-143 70-1151 70-1151 CONTRACT 70-1201	KELLEY, J. L KELLEY, D. L KELLOGO, P J. KELLOGO, P J. KELLOGO, P J	8009190544* 80100101804 8010080597 8010160446 80102301434	FDIA 50-135 1 50-339 1 50-29: 1 50-395 1
OHNSRUD, J. H. OHNSON, R. E. OHNSON, R. G. OHNSON, W. R.	8010210515 8010290142 8010210769 8010210492 8010300037	50-387 Q GEN TEC IS 50-289 Q 50-263 J 50-275 T	XAHLE, J B KAHLE, J B KAHLE, R KAHLE, J B KAHN, M J	8010160724* 8010220038* 8010170596* 8010230137* 8010030353*	70-27 70-1151 CONTRACT 70-1113 CONTRACT	KELLOGO, P J.	8010090309 8010150565* 8010100254* 8010030492* 8010160568	50-281 ¥ 50-370 J 50-416 M 50-281 S
ACHMBON, R W MCHMBON, W D. MCNES, D C MCNES, W C MCNES, W C	8010300027 8010300571 8010230026 8010210791 8010210768	50-344 @ 50-313 \$ NUREQ 50-289 Q 50-285 Q	Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n	8010020406 8010020425 8010070500 8010160345 8010070359	50-265 8 50-265 8 50-254 8 50-254 8 50-254 8	KELLOGO,P J KELLOGO,P J KELLY,R.D KELLY,J A F	8010080205* 8010080225* 8010240228* 8010160526* 8010030181*	50-369 3 50-364 3 50-324 8 109888 50-214 3
FONER, C E FONER, L FONER, H C FONER, H C FONER, H C	8010100421 8010140625 8010240106 8010270210 8010230095	50-455 8 40-1162 50-285 Q 50-285 Q 50-285 Q	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N.	8010140500 8010140440 8010150309 8010210504 8010210783	50-254 S 50-254 S 50-254 R 50-265 S 50-254 S	KELLY, J A F KELLY, N G KELLY, J, KELLY, J, A KELLY, J, A	8010030176 8010240616* 8010220218 8010270551* 8010270547*	50-274 3 50-320 4 50-278 3 50-278 3
NONES, L KONES, W KONES, W CONES, W CONES, W CONES, W CONES, W CONES, C	8010140601 8010230271 8010060344 8010070068* 8010060270	40-1341 50-201 Q 50-285 P CONTRACT 50-285 F	Kalivianakis, n Kalman, g Kalman, g Kammerer, c. c Kammerer, c.	B010300441 B010100417 B010270046 B010280123* B010270506	50-245 8 50-320 S 50-320 B 50-275 U 50-201 Q	KELLY,R B, KEMP,E, KEMPER,J B, KEMPER,J S	8010240422 8009240156 8010030100 8010230713* 8010020253*	TOPREP 40-44%2 40-44%2 50-3%2 3 50-3%2 4
ICNES, J. C IONES, D 14. IONES, B D IONES, W C IONES, J. C	8010200013 8010160724* 8010070419 8010210761 8010080445*	PR 70-27 Hisc PR 50-269 8	KAMMERER, C KANG IRUK, P KANE, W KANE, W KANE, W	8010270524 8010060009* 8010080642 8010220068 8010070230	50-320 P 50-466 Q 50-395 A 50-395 A 50-382 A	KEMPER, J. S KEMPER, J. S KEMPER, J. S. KEMPER, J. S. KEMPER, J. S	8010100094+ 8010020117 8010020197 80100140034+ 8010230711+	50-352 5 50-352 7 50-352 3 50-352 4

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PEMPER, J S XEMPER, J S PEMPER, J S KEMPER, J S KEMAKAN, C B	8010010840 8010010848 8010010623 8010230191 8010170572*	50-352 0 50-352 0 50-352 0 50-352 0 CONTRACT	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q	8010160264 8010160268 8010160272 8010160279 8010160282	50-303 0 50-461 G 50-367 0 50-359 0 50-440 0	D INMEMANIX KINNEMANIJ D KINNEMANIJ D KINNEMANIJ D	8010010294 8010060132 8010010389 8010140608* 8010100257	70-49 & E 70-498 FOIA 40-6920
KENDALL,R. MENDIG,J MENDIG,E FENDRA,E JENNA,N	8010230627* 8010020114 8010020011 8010140613* 8010100017*	50-275 A 1&E 1&E FOIA 70-143	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8010140275 8010140300 8010140305 8010140304 8010140314	50-341 0 50-463 0 50-546 Q 50-409 Q 50-10 Q	H H H H H H H H H H H H H H H H H H H	8010060145 8010100072* 8010100068 8010030525 8010010287	70-820 70-1703 70-1703 1&E 40-8385
KERNA H B KERNA H B KERNA H B KERNA H B KERNA H B	8010100020* 8010060087 8010060082 8010060157 8010060156*	70-143 70-143 70-1151 70-1151 50-348 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J. O KEPPLER, J. O KEPPLER, J O	8010210071 8010170034 8010270353 8010280034 8010280036	50-155 Q 50-255 P 50-483 Q 50-327 Q	KINNEMAN. J D. KINNEMAN. J D. KINNEMAN. J D KINNEMAN. J D KINNEMAN. J D	8010140172 8010200383 8010200384 8010220143 8010140615#	70-1447 40-2791 40-341 40-672 FDIA
KENNA.H B KENNA.H B KENNA.H B KENNA.H B KENNA.H B	8010020270# 8010090221 8010220456 8010310322# 8010240191#	70-27 70-1151 70-1113 70-1151 70-143	KEPPLER: J 0. KEPPLER: J 0 KEPPLER: J. 0. KEPPLER: J 0 KEPPLER: J. 0	8010280075 8010280078 8010280082 8010280084 8010280120	50-358 0 50-305 0 50-266 0 50-346 0 50-546 0	KINNEMAN, J. D KINNEMAN, J KINNEY, U. U KIND, T	8010040030 8010140792 8010140739 8010220204 8010010449	1&E 1&E 1&E 70-820 XPDRTL1C
Kenna, H B Kenna, H B Kenna, H B Kenna, H B Kenna, H B	8010270397* 8010030145 8010100014 8010020258 8010060148	50-327	KEPPLER: J. Q KEPPLER: J. Q KEPPLER: J Q KEPPLER: J Q KEPPLER: J Q	8010280627 8010280638 8010280643 8010280646 8010280650	50-10 0 50-331 0 50-263 0 50-407 0 50-440 0	KINTER, L KINTER, L KINTER, L KINTER, L KINTION, A E.	8010080604 8010220080 8010090217 8010220052 8010220371*	50-364 V 50-364 A 50-364 A 50-341 A 50-576 0
Kenna. H B Kenna. H B. Kenna. H B Kenna. H B Kenna. H B.	8010020259 8010030329 8010160719 8010220034 8010230131	50-327	KEPPLER.J.O. KEPPLER.J O KEPPLER.J O KEPPLER.J O. KEPPLER.J O.	8010280652 8010280656 8010280657 8010280664 8010240265	50-461	KINTIOHA E KINTNERAL L KINTNERAL L KINTNERAL L KINTNERAL L	8010240082* 8010170143 8010030304 8010080546 8010070020	50-576 Q 50-364 A 50-364 A 50-364 A
Kenna, U B. Kenna, U B Kenna, U B. Kennedy, C P Kennedy, R P	8010240178 8010270395 8010310313 8010020626 7902090347*	70-143 50-327 G 70-1151 50-275 S 50-322 A	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8010300550 8010270014 8010270018 8010270020 8010270021	50-305 F 50-407 Q 50-341 Q 50-315 Q 50-327 Q	KINTNER, L. KINTNER, L. KINTNER, L. KINTNER, L. L. KINTNER, L. L.	8010090226 8010100063 8010170304 8010170310 8010170312	50-364 A 50-364 A 50-364 A 50-364 A
MERCHEDY, E H MERCHEDY, D M RESBYY, T RESHY', T RESHY', J R	8010210108* 8010150442 8010210302* 8010240148* 8010030479	MISC 50-255 R 50-284 Q 50-247 Q 50-201 Q	Keppler. J O Keppler. J O. Keppler. J O Keppler. J O Keppler. J. O	8010270022 8010270023 8010270024 8010270025 8010270027	50-155 Q 50-440 Q 50-358 Q 50-461 Q 50-331 Q	KINTNER: L. L. KINTNER: L. L. KINTNER: L. L. KINTNER: L. L. KINTNER: L.	8010230086 8010240163 8010150638 8010210278 8010230187	50-364 A 50-364 A 50-364 A 50-364 A
KENTON,T J. Kenyon,T J. Keppler,J O Keppler,J. O	8009240121 8010150433 8010040031 8010210008 8010210013	TOPREP 50-370 A 50-266 F 50-10 Q 50-331 Q	KEPPLER, J O. KEPPLER, J G. KEPPLER, J G KEPPLER, J G KEPPLER, J G	8010290028 8010290029 8010290031 8010290032 8010290035	50-367 Q 50-346 Q 50-463 Q 50-546 Q 50-263 Q	KINTNER, L. L. KINTNER, L. L. KIRCHNER, P. KIRK, H. F. KIRK, H. F.	8010280186 8010270297 8010140286 8010070476 8010200247	50-364 A 50-364 A 50-320 P 70-371 70-371
KEPPLER.J O KEPPLER.J O KEPPLER.J G KEPPLER.J G	8010210016 8010210017 8010210026 8010210030 8010210034	50-254 Q 50-346 Q 50-315 Q 50-275 Q 50-305 Q	KEPPLER, J Q KEPPLER, J Q. KEPPLER, J Q. KEPPLER, J. Q. KERR, Q. H.	8010270036 8010270037 8010270039 8010310260 8010010173*	50-266 0 50-305 0 50-10 0 50-237 0 WASTE HOT	KIRK, O B. KIRK, O B. KIRK, G B KIRK, G B KIRK, G B	B010210517* B010210657* B010210642* B010210679*	50-327 8 50-327 6 50-327 8 50-327 8 50-327 8
KEPPLER, J G KEPPLER, J. G KEPPLER, J G KEPPLER, J G. KEPPLER, J G	8010210043 8010210053 8010210063 8010230140 8010230145	50-266 Q 50-263 Q 50-407 Q 50-282 Q 50-285 Q	KERR, Q. W. KERR, O. W. KERR, O. W. KERR, O. W. KERR, O. W.	8010270117* 8010270111* 8010020185 8010020114 8010170254	State Prog State Prog State Prog I&E I&E	KIRK, G B KIRK, G B. KIRK, G B. KIRK, G B. KIRK, G, B	8010210703* 8010210541* 8010210714* 8010210645* 8010280542*	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8
KEPPLERIJ Q KEPPLERIJ Q KEPPLERIJ Q KEPPLERIJ Q KEPPLERIJ Q.	8010220439 8010020070 8010080438 8010140137* 8010290241	50-237 F 50-346 Q 50-10 S 50-10 Q 50-255 Q	KERR. O W KERR. O W KERR. O W. KERR. O W.	8010020008 8010020011 8010070523 8010160006 8010160007*	I&E I&E 40-8692 State Prop State Prop	KIRKLAND, M W. KIRKLAND, M W. KIRBCH, D F KIRBCH, D F KIRBCH, D F	8010240467 8010240460 8010090370* 8010230077* 8010280026*	XPORTLIC XPORTLIC 50-275 Q 50-275 Q 50-275 Q
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8010240029 8010060118 8010100289 8010270146 8010270335	50-255	KERR. O W. KERR. O W. KERR. O W. KERR. O W. KERWIN, D. K	8010210532 8010270076 8010270104* 8010270541 8010010412	Btate Prog State Prog State Prog I&E NUREO	KIRTLEY, J. KIBTER, H B. KIBTER, H KIBTER, H. KIBTER, H B.	8010020012 8010020231* 8010010352* 8010210302* 8010230115*	50-201 0 50-286 0 50-286 0 50-286 0 50-244 0
KEPPLER, J O. KEPPLER, J O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8010100375 8010280155 8010270459 8010270443 8010270444	50-282	KETCHUK: A. O KETCHEN: E. Q. KETZLACH: N KETZLACH: N. KEY: W. J.	8010240597* 8010200622 8010210203 8010270528 8010140168*	50-320 P 50-369 H 70-1100 70-2932 50-275 Q	KISTER, H KISTER, H B. KISTER, H B. KISTRUP, N. K. KLAPOW, R.	8010240148* 8010240133* 8010240124* 8010040129 8010010241	50-247 @ 50-322 @ PR XPORTLIC
KEPPLER, J O. KEPPLER, J O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O	8010270470 8010270472 8010270473 8010270477 8010150116	50-255 G 50-275 G 50-315 G 50-305 G 50-440 A	KEY, W. J. KEY, W J. KEYEB, D. C KICK, R C. KILLIAN, E. W.	8010010722* 8010200485* 8010200508* 8010200326* 8010080381		KLEPFER, H. H KNAPP, P. J. KNAPP, P. J. KNAPP, P. J. KNAPP, P. J.	8010310597# 8010240565# 8010020656# 8010020676# 8010010329#	50-286 0 50-213 6 50-333 6 50-334 0
XEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	8010160171 8010160224 8010160230 8010160235 8010160237	50-409 G 50-247 G 50-315 G 50-155 G 50-255 G	Kilpatrick, o a Kimmel, J. J Kinney, W. H. Kinneman, J. D. Kinneman, J. D.	6010210138* 6010080361* 8010010347* 8010100270* 8010100268*	CONTRACT 70-820 40-6920	KNAPP: P. J. KNAPP: P. J. KNAPP: P. KNAPP: P. J KNAPP: P. J	80102306284 80102306704 8010170005 8010270040 8010270545	
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	8010160245 8010160248 8010160254 8010160255 8010160258	50-266 Q 50-263 Q 50-346 Q 50-331 Q 50-327 Q	Kinneman, J D Kinney, W W. Kinneman, J. Kinneman, J. D. Kinneman, J	8010140184 8010010617# 8010010278# 8010220667 8010010395#	70-820 70-49 70-92	KNEEBBY, A. D. KNIGELEY, J. KNIEL, K KNIEL, K KNIEL, K, F	8010310046 80101705384 80102703944 8010300333 8007050288	50-255 G

AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCEASION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATE COAY
KNOESPEL, P D	8010210760*	50-254 B	LAMKEN.D C. LANDSMAN.R B LANDSMAN.R M LANDSMAN.R M LANDSMAN.R C	8010100361	50-10 P	LESBOR, L C	8010230059	50-298 9
KNOKE, J R	8010080459*	50-341 A		8010240330*	50-327 Q	LESSOR, L C	8010210633	50-298 8
KNOKE, J R	8010080462*	50-341 A		8010150024	50-445 H	LESSOR, L C	8010210645	50-298 8
KNOP, R C	8010100373	50-329 B		8010150024	50-445 H	LESSOR, L C	8010140312	50-298 R
KNOP, R C	8010060128*	50-483 Q		8010240057	50-289 T	LESSOR, L C	8010210708	50-298 8
KNOP.R C	8010060108*	50-441 0	LANGTON, J P	8010200070	State Prog	LESSY.R P	8010150082	50-463 9
KNOP.R C	8010140155*	50-441 0	LANIK, O	8010270317*	50-296 P	LESSY.R P,	8010150005	27-39
KNOP.R C	8010160332*	50-329 0	LANPHER, L C	8010080300	50-275 G	LESSY.R P	8010150048	27-39
KNOP.R C	8010160250*	50-483 0	LANPHER, L C	8010080300	50-275 G	LESSY.R P	8010200166	50-463 9
KNOP.R C	8010230677*	50-329 0	LANPHER, L C	8010160544	50-275 G	LESSY.R P	8010210249	50-443 9
KNOP, A C	8010270385*	50-483 Q	LANPHER, L C	8010160544	50-275 0	LESBY, R P	8010220319	27-39
KNOP R C	8010010383*	50-483 Q	LANPHER, L C	8010200682	50-275 0	LESBY, R P	8010280011	50-443 0
KNOTTS, J B	8010080289	50-445 M	LANPHER, L C	8010200682	50-275 0	LEVELIUS, W H	8010210277	RECOD
KNOTTS, J B	8010080319	50-445 M	LANTZ, E	8010200222*	50-289 T	LEWIS, R C	8010080442	50-327 B
KNOTTS, J B	8010100051	PR	LAPHAM, W W	8010020379	50-367 A	LEWIS, R C	8010010102#	50-269 0
HOTHE, F	8010080289	50-445 M	LAPHAM, W	8010200447*	50-367 A	LEWIS.R C	8010090329	50-327 8
B C'ELLONN	8010080319	50-445 M	LAPOINTE, R E	8010300301	RES	LEWIS.R C	8010160748	50-249 8
B C'ELLONN	8010140002	50-445 M	LARBON, T L	8010200207	40-9348	LEWIS.R C	8010170002	50-269 8
B C'ELLONN	8010140002	50-445 M	LARBON, H J	8010040014	Nureo	LEWIS.R. C	8010140018	50-327 0
B 'ELLONN	8010150618	FOIA	LABUK, B R	8010030540	I&E	LEWIS.R C	8010010047#	50-302 0
KOCH, L. J	8010170072*	50-461 Q	LAGUK, B R. LATHAM, B B LATHAM, B B LAUBEN, Q N LAVERTY, J H	8010090306	1&E	LEWIS, R. C	8010170017*	50-250 9
KOCH, L. J	8010170131*	50-461 Q		8010140529*	50-322 0	LEWIS, R. C	8010200636	50-295 6
KOESTER, O. L	8010060149*	50-462 Q		8010140523	50-322 0	LEWIS, R. C	8010160530	50-348 8
KOESTER, O. L	8010080378	Nureo		8010200175	TOPREP	LEWIS, R. C.	8010150581*	50-250 0
KOESTER, O. L	8010160546	50-482 A		8010150001	50-142 0	LEWIS, R. C	8010140367	30-259 8
KOHLER, J. E KOHLER, J. E KOHLER, J. E KOHR, J. C	8010100412 8010100422 8010140148* 8010070255 8010020508	50-275 S 50-304 S 50-295 G 50-304 S 50-289 H	LAVERTY, J H LAVERTY, J H LAW, J. E, LAW, J. E LAW, J E	8010150003 8010300053 8010270149* 8010270156* 8010270160*	50-142 0 50-142 0 27-10 27-10 FOIA	LEHIB, R. C LEHIB, R. C LEWIB, R. C. LEWIB, R. C LEWIB, R. C	8010140633 8010140008* 8010020732 8010150555* 8010170035*	50-327 B 50-321 0 50-335 0 50-338 0 50-327 0
KOMES, J.M.	8010270572*	GA999	Law, j e	8010270165*	FOIA	LEWIB, R C	8010010014*	50-349 0
KONDOS, O.S	8010310538*	CONTRACT	Lawroski, h	8010100432	PR	LEWIB, R C	8010150047*	50-335 0
KONKLIN, J.E.	8010200674*	50-454 Q	Lawson, j d.	8010230722*	50-287 H	LEWIB, R. C.	8010020784*	50-349 0
KONKLIN, J.E	8010280058*	50-440 Q	Lawton, m d.	8010300478	40-8084	LEWIB, R C	8010030490	50-416 0
KOPACZ, J	8010020436*	50-265 8	Lazarus, w j	8010270209*	50-309 Q	LEWIB, R C	8010100251	50-241 0
KORCHYNBKY, M	8010070544*	90-237 9	LAZARUB, W	8010100059*	50-307 Q	LEWIS, R. C	8010080200*	50-369 0
KORCHYNBKY, M	8010150515*	50-237 8	LAZO, R. M	8010270126*	50-548 A	LEWIS, R. C.	8010080220	50-364 0
KORNBLITH, L	8010140755	PR	LAZO, R. H	8010020719	50-582 0	LEWIS, R. C.	8010080051	50-335 0
KOBINBKI, F E	8010100023*	70-143	LAZO, R. H	8010070380	50-483 Q	LEWIS, M. I.	8010100246	PR
KOTHARI, K M	8010230013	NUREO	LAZO, R. H	8010280573	50-282 Q	LEWIS, R. C	8010240219	50-324 0
KOTHARI, K, M KOTBCH, J, L KOUTB, H J C KOUTB, H J, C KOVACB, B,	8010230036 8010220159 8010230028 8010230028 8010100185	NUREO 40-277 Nureo Nureo Reood	LAZO, R. M LAZO, R. H LE BDUEF, R. J. LEACHMAN, R. B. LEAR, G	8010300585 8010300623 8010080296 8010020109* 8010280731*	50-275 0 50-389 M PR FOIA 50-219 P	LENIS, R. C LEWIS, R. C LEWIS, R. C LEWIS, R. C LEWIS, R. C	8010230103 8010240246 8010010040 8010240649 8010270065	50-393 0 50-393 0 50-361 0 50-261 0
KOVACS, D. J.	8010220451	50-920 P	LEAR, Q	8010280737*	50-219 P	LEWIS, R C	8010270190	50-395 4
KONBA, B	8010080410	50-244 I	LEBO, C D	8010090135	CONTRACT	LEWIS, R. C.	80103101923	50-302 9
KREBB, A. H	8010010281*	Contract	LEBO, C D	8010200370	CONTRACT	LEWIS, R. C	8010010438	50-346 9
KRUEGER, J. P	8010210775	Waste Mot	LEBO, C, D,	8010290094	CONTRACT	LEWIS, R C	8010230479	50-259 9
KRUMPOS, P. J.	8010150491*	50-282 B	LEE, E W K,	8010010649*	50-454 Q	LEWIS, R C	8010010080	50-269 9
KRYBINGKI, T. L.	8010040350*	50-285 P	LEE,E W,K	8010150156*	50-456 Q	LEWIB: R C.	8010140046#	50-269 0
KRYBINGKI, T. L.	8010090244*	TOPREP	LEE,E W.K	8010270262*	50-483 Q	LEWIB: R C.	8010270183#	50-369 0
KUDERA: D. E	8010080194	RES	LEE,J.C.	8010220260	ACR8	LEWIB: R. C.	8010140003	50-321 0
KUQE: T.	8010230321	XPORTLIC	LEE,N	8010270171	NUREO	LEWIB: R C	8010150037	50-335 0
KUNXEL: H	8010220032*	50-320 H	LEE,O.R	8010060155*	50-267 Q	LEWIB: R C	8010170010	50-250 0
KURTZ, R. J	8010150587	RES	LEE. O. R	8010230052	50-267 Q	Lewis, R C	8010170027	50-327 0
KUEHNER, W. L.	8010140090#	70-1143	LEE. O. R	8010230073	50-267 Q	Lewis, R. C	8010150550	50-338 0
KUZMYCZ, Q	8010080353	PROJ	LEE. O. R	8010160535	50-267 P	Lewis, R. C.	8010150570	50-250 0
KYGER, J. A.	8010230007	NUREO	LEE. O. R	8010160341*	50-267 P	Lewis, R C	8010200333	50-280 0
LABRASCA, C. J.	8010240593#	50-320 P	LEE. O. R	8010080464	50-267 P	Lewis, R. C	8010310182	50-302 0
LACEY, L. R.	8010240539*	50-335 F	LEE, O. R	8010080467*	50-267 P	LI,R C	8010270576*	0A999
LACEY, W. B.	8010020472*	50-334 8	LEE, R. L.	6010010432*	50-440 G	LIBRIZZI,F P,	8010040286*	50-272 P
LACEY, W. B.	8010070373*	50-334 8	LEE, R. L	8010290151*	50-461 Q	LIBRIZZI,F,P	8010040279*	50-272 P
LACEY, W. B	8010070464*	50-334 8	LEE, H. F.	8010030313	50-213 Q	LIBRIZZI,F P,	8009150235	50-272 F
LACEY, W. B.	8010070526*	50-334 8	LEE, W. F.	8010230177	50-245 P	LIBRIZZI,F P	8010040271	50-272 P
LACEY, W 8.	8010070531*	50-334 8	LEIBY, A C.	8010080294	PR	LIBRIZZI,F P	8010030449	50-272 9
LACEY, W 8.	8010070559*	50-334 8	LEKACH, B V.	8010150130	RE8	LIBRIZZI,F P	8010070530	50-272 P
LACEY, W 8.	8010100310*	50-334 8	LEMPGEB, T E.	8010020105	50-220 G	LIBRIZZI,F,P,	8010040219	50-361 8
LACEY, W 8.	8010200583*	50-334 8	LEMPGEB, T E.	8010020101	50-220 G	LIBRIZZI,F,P	8010040283	50-272 9
LACEY, W 8.	8010240441*	50-334 8	LEMPGEB, T E.	8010010438	50-220 G	LIBRIZZI,F,P	8010040291	50-272 9
LACEY, N. S.	8010240454*	50-334 S	LEMPGES, T. E	8010200398	50-220 P	LIBRIZZI,F P. LIBRIZZI,F,P. LIBRIZZI,F,P. LIBRIZZI,F,P. LIBRIZZI,F,P.	8010080421	50-272 F
LACEY, N. S.	8010240461*	50-334 S	LEMPGES, T. E	8010300647	50-220 P		8010060272	50-272 F
LACEY, N. S	8010240473*	50-334 B	LEMPGES, T. E.	8010150404	50-220 R		8010100193	50-272 F
LACEY, N. S.	8010280519*	50-334 B	LEMPGES, T. E.	8010200528	50-220 B		8010100264	50-272 F
LADUN, R. H.	8010010401*	50-29 Q	LEMPGES, T. E	8010310379	50-220 P		8010100327	50-272 S
Ladun, R. H.	8010240104*	70-1143	LENAHAN, J. J.	8010300428*	50-369 G	LIBRIZZI,F.P	8010100340	50-311 8
Lagiehski, J. S	8010040241*	50-318 8	LENAHAN, J. J.	8010020780*	50-438 G	LIBRIZZI,F.P.	8010200591	50-272 8
Lagiehski, J. S	8010140573*	50-318 8	LENARDSON, J. D	8009110366*	REGOD	LIBRIZZI,F.P.	8010210380	50-316 P
Lagiehski, J. S	8010140445*	50-316 8	LENNKH, R	8010160064	XPORTLIC	LIBRIZZI,F.P.	8010210472	50-272 P
Lagiehski, J. S	8010200434*	50-318 8	LENNKH, R	8010220370	XPORTLIC	LIBRIZZI,F.P.	8010290320	50-272 P
LAGIEWSKI, J.S.	8010240426*	50-317 8	LENTECH, J. H	8010140021	PR	LIBRIZZI,F.P.	8010270376	50-272 8
LAINAS, O.C.	8010010637	50-206 8	LENTECH, J. H	8010200179	PR	LIBRIZZI,F.P.	8010310301	50-272 F
LAMAN, J.T.	8007100817	40-8714	LEPPKE, D. H.	8010210713	PR	LICCIARDO,R B	8010270023	50-305 F
LAMB, H.R	8010080276	PR	LEBBOR, L. C	8010070294	50-278 8	LICITRA,E.A.	8010170150	50-369 A
AMB, J.C	8010310447	50-272 0	LESBOR, L. C.	8010070480	50-278 8	LIM,J.J.	8010170076	NUREO

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	EUÐJEGT CATEODRY	ROHTUA	ACCEBBION NUMBER	BUBJECT CATEGORY
LINDBERGIJA	8010140233*	70-920	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E.	8010100145	71-385	MADBEN. 0 L	8010010335*	50-242 Q
LINDBLAD.W J	8010270280	50-514 A		8010010777	71-395	MADBEN. 0 L	8010010175	50-285 Q
LINDER.F	8010070548	50-407 P		8010010358	71-4581	MADBEN. 0 L	8010010344*	50-262 Q
LINDER.F	8010070953*	50-407 P		8010010362*	71-6581	MADBEN. 0 L	8010070233*	50-284 Q
LINDER.F	8010160170	50-407 Q		8010100234	71-9033	MADBEN. 0 L.	8010010009	50-298 Q
LINDER, F	8010140170	50-409 Q	MACDONALD, C. E	8010100238	71-9010	MADSEN.O L	8010010017*	50-298 Q
LINDER, F	8010020504	50-409 V	MACDONALD, C. E	8010100253	71-9853	MADSEN.O L	8010010064	50-285 Q
LINDER, F	8010140223	50-409 P	MACDONALD, C. E	8010220283	71-6717	MADSEN.O L	8010090150	50-313 8
LINDER, F	8010210594	50-409 P	MACDONALD, C. E	8010230618	71-9096	MADSEN.O L	8010090225	50-284 Q
LINDER, F	8010160507	50-409 P	MACDONALD, C. E	8010150607	71-6346	MADSEN.O L	8010060173	50-267 Q
LINDER, F	8010140335	50-407 P	MACDONALD, C E MACDONALD, C E, MACDONALD, C E MACDONALD, C E MACDONALD, C E	8010150610*	71-6346	MADSEN, G L	8010240024	50-313 G
LINDER, F	8010150371	50-409 R		8010150613	71-5926	MADSEN, G L	8010070168	50-313 S
LINDER, F	8010150494	50-409 P		8010150614*	71-5926	MADSEN, G. L	8010210600	50-313 G
LINDER, F	8010160478	50-409 P		8010270389	71-6744	MADSEN, G. L	8010210605*	50-313 G
LINDER, F	8010210308	50-409 P		8010080275	71-396	MADSEN, G. L	8010070158	50-313 B
Linder, F Linder, F Linebarger, J. H Linehan, J. J Linehan, J. J.	8010220538 8010260353 8010300194 8010150128 8010030534	50-407 P 50-409 P RE8 40-8452 40-8452	MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8010080301* 8010100258 8010090075 8010100027 8010100028	71~396 71~6601 71~6717 71~5971 71~9044	MADSEN, Q. L., MADSEN, Q. L. MADSEN, Q. L. MADSEN, Q. L. MADSEN, Q. L.	8010280110 8010280279 8010010021 8010010321 8010010002	50-267
Linekan, J J	8010070104	40-8584	MACDONALD, C. E.	8010100261	71-5908	MADSEN, Q. L. MADSEN, Q. L. MADSEN, Q. L. MAGERB, J. E. MAGNUSON, H. Q.	8010060057	50-368 B
Linekan, J J	8010150077	40-3453	MACDONALD, C. E.	8010150074	71-9074		8010030186	50-284 G
Linekan, J J	8010280175	40-3453	MACDONALD, C. E.	8010150076	71-9018		8010060153	50-267 G
Linekan, J J	8010040055	40-8585	MACDONALD, C. E.	8010150109	71-5971		8010100152	PR
Linekan, J J	8010220159	40-299	MACDONALD, C. E.	8010210025	71-5971		8010080672*	50-344 H
Linehan, J. J.	8010230335	40-8502	MACDUNALD, C E	8010210027*	71-5971	MAHAN, R. R	8010140535	50-395 Q
Linehan, J. J.	8010220146	40-8727		8010220374	71-6722	MAHAN, R. R.	8010140596	50-395 Q
Linehan, J. J.	8010220354	40-8502		8010220421	71-5796	MAIER, J E	8010280420	50-244 P
Linehan, J. J.	8010240147	40-4492		8010220437	71-9057	MAIER, J E,	8010310256	50-244 F
Linehan, J. J.	8010310516	40-8102		8010220445	71-6347	MAJOR, J. H	8010070591	TOPREP
LINENBERGER.G	8010080247	50-466 Q	MACDONALD, C E	8010220450	71-6273	MAKATURA: L	8010200449*	50-346 B
LIPINSKI.W C	8010240274	ACRS	MACDONALD, C E	8010220435	71-5274	MAKEPEACE: J M	8010150498*	50-247 B
LIPFOLD.W J	8010160513	50-317 P	MACDONALD, C E	8010220646	71-6089	MALINAUBKAB: A	8010070397*	NUREO
LITTLE.W.B	8010070252	50-331 B	MACDONALD, C, E	8010220687	71-5998	MALLORY: K	8010070240*	50-327 P
LITTLE.W S	8010150138*	50-263 Q	MACDONALD, C E.	8010220690*	71-5998	MALMROS: M H.	8010080170*	50-344 Q
LITTLE, W S	8010150112*	50-331 Q	MACDONALD, C E. MACDONALD, C E MACDONALD, G. E MACDONALD, G. E MACDONALD, C E	8010220482	71-9044	MALMROS, M H	8010230180*	50-344 G
LITTLE, W S	8010150235*	50-341 Q		8010220484*	71-9044	MALONEY, G. P.	8010020240	50-315 G
LITTLE, W	8010080310	50-206 P		8010270429	71-5805	MANDLER, J. W	8010230017	50-250 P
LITTLE, W	8010070302	50-282 S		8010280007	71-9011	MANDLER, J. W	8010310553	RES
LITTLE, W S	8010070274	50-282 S		8010280032	71-5059	MANGUSI, J	8010150423	70-2479
LITTLE, W 8	8010240038*	50-263 Q	MACDONALD, C. E	8010280037	71-5641	Mann, H. M	8010160755	PR
LITTLE, H.	8010080302	CONTRACT	MACDONALD, C. E	8010270072	71-5450	Manry, H	8010170412	50-321 R
LITTLE, H	8010150600	CONTRACT	MACDONALD, C. E	8010270075*	71-5450	Manry, M.	8010170422*	50-321 R
LIVERHORE, H H	8010140155*	80-461 Q	MACDONALD, C. E	8010270118	71-9022	Manry, M	8010280385	50-321 V
LOCKE, R F	8010240544	50-193 Q	MACDONALD, C. E	8010270122*	71-9022	Manry, H	8010060240	50-366 B
Loehenstein, W.	8010100078	NUREO	MACDONALD, C. E	8010270128	71~9049	MANRY, H	8010060242	50-366 B
Loguidice, J. H.	8010160174*	CONTRACT	MACDONALD, C. E	8010270131*	71~9049	MANRY, M	8010060254	50-366 B
Lois, L.	8010300523	DRO	MACDONALD, C. E	8010280671	71~6058	MANRY, M	8010060357	50-366 B
Long, R.	8010220474	50-201 O	MACDONALD, C. E	8010270137	71~9019	MANRY, H	8010080375	50-366 B
Longenecker, S	8010100206	PR	MACDONALD, C. E	8010270141*	71~9019	MANRY, H	8010080433	50-321 S
LOOMIB, J. 8 LOOMIB, J. 8 LOPEZ-C R LOPEZ-ARAMBULA LORFINO, D	8010210750 8010210756 8010230341 8010010681 8010230347	PR PR 50-201	MACDONALD, C. E. MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8010310246 8010310150 8010310153* 8010310115 8010310120*	71-5088 71-371 71-371 71-18 71-18	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	8010160472 8010160479 8010210410 8010210418 8010220473	50-366 B 50-321 B 50-366 R 50-321 R 50-321 B
LORIO,P K LOVENDALE,P C LOVENDALE,P C LOVING,L J LOWENSTEIN,R	8010170075 8010010601* 8010270403* 8010080547 8010150455	70~882 50~186	MacGreodr, B. A MacHalinski, H MacHon, R. D MacHon, M. KacHon, R. D	8010160055 8010300119* 8010220054 8010060239 8010270213	FOIA 27-39 50-293 0 50-293 8 50-293 0	MANRY, H MANRY, H MANRY, H MANRY, H HANRY, H.	8010220493 8010220488 8010220500 8010280473 8010280213	50-346 8 50-346 8 50-321 8 50-321 8 50-346 8
LU/8 C LUEDECKE, A R. LUKZ, F. J LUKZ, F. J LUKZ, F J	8010300477 8010280224* 8010080663* 8010170073* 8010200291*	NUREO FOIA CONTRACT CONTRACT CONTRACT	MACHON, R D MACHON, R D. MACHON, R. D. MACHON, R D MACHON, R D.	8010010506 8010010667 8010020453 8010070347 8010210712	50-293 8 50-293 8 50-293 8 50-293 8 50-293 8	MANRY, H MANRY, H. MANRY, H. MANSER, W. C	8010280375 8010280421 8010280470 8010310406 8010020370	50-366 8 50-366 8 50-366 8 50-366 8 70-143
LUMB,R F	8010230037	NUREO	MACHON; R. D.	8010160464	50-293 R	MANSER.W C. MANSER.W C. MANSER.W C. MANSER.W C. MANSER.W C.	8010240185*	70-143
LUNDVALL,A E.	8010010170*	50-317 G	MACHON; R. D.	8010070518	50-293 8		8010270285	70-143
LUNDVALL,A E	8010010174*	50-317 G	MACHON; R. D.	8010210715	50-293 8		8010070386	70-143
LUNDVALL,A E,	8010010201*	50-317 G	MACHON; R. D.	8010200429	50-293 8		8010070424	70-143
LUNDVALL,A E	8010020184	50-317 G	MACHON; R. D.	8010220511	50-293 8		8010150417	70-143
EUNDVALL, A E	8010020211	50-317 Q	Machon, R. D	8010280497	50-293 8	MANBER, W. C.	8010160493	70-143
EUNDVALL, A E	8010240268	50-317 G	Machon, R. D.	8010240410	50-273 8	Manber, W. C	8010210325	70-143
EUNDVALL, A E	8010310263	50-317 F	Machon, R. D	8010280407	50-273 8	Marchal, J.	8010100276	XPORTLIC
EUNDVALL, A, E	8010310396	NUREQ	Machon, R. D.	8010280490	50-273 8	Maroulieb, K	8010270200*	CONTRACT
EYDGN, J. M	8010380406	50-471 A	Machon, R. D.	8010280574	50-273 8	Marianyi, J. J	8010310346*	50-304 P
LYNCH, M. C LYNCH, R. L. LYNCH, M. D MACARTHUR, T. C MACARTHUR, T. C	8010210780* 8010230039 8010280687 8010100438* 8010100441*	50-367 Q NUREQ 50-367 A 50-277 Q 50-277 Q	Macki, T. M MacMurdy, F. H MacNair, 9. Madden, M. Madden, H	8010080468 8010170020 8010270045# 8010010264# 8010020762#	50-309 9	MARIBILA V. Marranzinola P. Mareh.R. J. Mareh.R. J Marehall.B. O.	8010160657 8010100089# 8010150588 8010170052* 8010210471*	50-250 0 50-327 0 50-289 T
MACARTHUR, T. C. MACARTHUR, T. C MACARTHUR, T. C MACARTHUR, T. C. MACARTHUR, T. C.	8010300367* 8010280274* 8010270410* 8010300179* 8010310068*	50-280	MADEDA, T. J MADEDA, T. J MADEDA, T. J. MADISON, A MADISON, A. L.	8010010356* 8010230056* 8010270155* 8010150138* 8010240038*	50-346 @ 50-155 @ 50-263 @	MARSOLAIS, L. D. MARSOLAIS, L. D. MARTIN, H. Q MARTIN, H. Q MARTIN, H. Q	8010240056 8010030413 8010230718 8010140084 8010230716	

	400=====						-	
AUTHOR	ACCEBBION NUMBER	CATEODRY	AUTHOR	ACCEESION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOPLEUB
MARTIN, R D MARTIN, R D MARTIN, R, D, MARTIN, W O, MARTIN, R D	8010080435 8010080610 8010010131* 8010010257* 8010170026*	50-287 8 50-348 8 50-269 0 50-309 0 50-250 0	MASSEY, W. E MASSIE, H. N MASSIE, H. N. MATERS, B. R MATHEWS, E. R	8010230007 8010150147 8010150553 8010210623 8010240272*	NUREQ RES RES 50-341 A 50-305 Q	MATTIA, H. J MATTIA, M. J HATTIA, M. J. HATTIA, M. J. HATTIA, M. J.	8010200600* 8010200660* 8010210105* 8010230330* 8010230444*	CONTRACT TOARTHOO TOARTHOO TOARTHOO TOARTHOO
MARTIN, R MARTIN, R. MARTIN, R. D MARTIN, T J, MARTIN, W. O.	8010140748 8010170002 8010010052* 8010020209* 8010030138*	50-269 8 50-269 8 50-302 0 50-354 0 50-247 0	Matheub, e. r Matheub, e. r Matheub, e. r Matheub, e. r Matheub, e. r	8010060121* 8010030538 8010080655 8010090512 8010090494	50-305 Q 50-305 Q 50-305 Q 50-305 Q	MATTIA, M J HATTIMOE, J J HATTIMOE, J J MATTIMOE, J J, MATTIMOE, J J	8010310538+ 8010070187 8010300017+ 8010140468 8010140473	CBNTRACE 50-312 F 50-312 F 50-312 F
MARTIN, H O MARTIN, H O MARTIN, H O MARTIN, T. T.	8010020697* 8010020759* 8010010392* 8010030101* 8010220148*	70~195 50~284	Mathews, e. r Mathews, e. r. Mathews, e. r. Mathews, e. r. Mathews, e. r.	8010200294 8010210721 8010030391 8010070410 8010070572	50-305 & PR 50-305 F 50-305 P 50-305 J	MATTINGE, J, J MATTINGE, J J MATTINGE, J J, MATTINGE, J, J MATTINGE, J, J	8010160551 8010160480 8010150426 8010170445 8010200527	50-312 F 50-312 F 50-312 F 50-312 F
MARTIN, R. D HARTIN, R. HARTIN, W O, HARTIN, W O,	8010150588# 8010160451 8010240315# 8010080530 8010240205#	50-250 G 50-302 S 50-287 G 50-293 B 50-245 G	MATHEWS, E. R.	8010140459 8010300216 8010300330 8010200480 8010210502	50-305 R 50-305 G 50-305 F 50-305 P 50-305 P	MATTIHOE, J J. MATTIA.M J KATTIA.M.J HATTIA.M J MATTIALD, J,	8010210448 8010310577# 8010290091# 8010290097# 8010280426	50-312 6 CONTRACT CONTRACT CONTRACT 50-312 P
HARTIN, H. O. HARTIN, T. T HARTIN, T. J. HARTIN, W. O.	8010010334 8010010406 8010270207# 8010010311# 8010010385	70-371 70-135 50-307 Q 50-354 Q 70-820	Mathewb, e. r. Mathewb, e. r Mateko, r. J Mateon, v. Mateon, v.	8010210450 8010280446 8010310577* 8010010158 8010020083	50-305 P 50-305 S CONTRACT XPORTLIC XPORTLIC	MATTIMOE, J J MATTSON: R. J MAUK, F. J. MAUK, F. J. MAURIN: L. V.	8010280457 8010150544* 8010080384 8010080389 8010140302	50-312 F 50-302 F NUREO NUREO 50-302 A
MARTIN, T MARTIN, T MARTIN, T MARTIN, T MARTIN, R D	8010100059# 8010240278# 8010080168 8010020158# 8010020737#	50-309 Q 50-271 Q 50-271 Q 50-354 B 50-335 Q	Matson, V. Matson, V. Matson, V Matson, V Matson, V	8010020084 8010170288 8010170291* 8010020617 8010010119	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MAURIN, L. V. MAVROULES, N. MAVROULES, N. MAXWELL, O. F. MAXWELL, Q. F.	8010310419 8010100102* 8010100100 8010310034* 8010310047*	50-382 A 50-443 H 50-443 H 50-413 Q
MARTIN, W. Q. MARTIN, W. Q. MARTIN, R. D. MARTIN, W. Q. MARTIN, W. Q. MARTIN, W. Q.	8010030192* 8010730120 8010010018* 8010010245 8010010381	50-245 Q 70-33 50-369 Q 50-309 Q 50-29 Q	Matson, V Matson, V. Matson, V. Matson, V. Matson, V.	8010160043 8010140270 8010090080 8010170004 8010170008	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MAXWELL, R. B MAXWELL, G. F MAY, K MAYER, L. D. MAYER, L. O.	8010220453 8010080226* 8010240609* 8010060229 8010070315	50-327 B 50-400 G 50-320 P 50-263 F 50-282 F
MARTIN, H O. MARTIN, H O. MARTIN, H, O MARTIN, H, O MARTIN, H, Q.	8010020684 8010030113 8010080205* 8010240095 8010240108	70-135 50-247 Q 50-369 Q 70-1143 70-135	Matson, V. Matson, V. Matson, V. Matson, V. Matson, V.	8010230040 8010230049* 8010280497 8010310594 8010310402*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O.	8010020648 8010060303 8010100262 8010100295 8010140333	50-263 F 50-262 P 50-263 F 50-263 P 50-282 P
MARTIN, R. D. MARTIN, R. D. MARTIN, T. J. MARTIN, T. J. MARTIN, T. J.	8010080057# 8010080225# 8010150215# 8010010817 8010170549	50-335 Q 50~364 G 50-354 B 50-354 G CONTRACT	HATTED, A. J HATTHENB, C. W, HATTIA, J. C. HATTIA, J. C. MATTIMDE, J. J,	8010100012* 8010160208* 8010140063* 8010010632* 8010070187*	50-373 Q CONTRACT 50-352 Q 50-352 Q 50-312 Q	MAYER.L O. MAYER.L O. MAYER.L O. MAYER.L O. MAYER.L O. MAYER.L O.	8010150460 8010150409 8010150497 8010160340 8010160347*	50-262 8 50-263 R 50-262 R 50-263 P 50-263 P
MARTIN, T. T MARTIN, H. Q. MARTIN, T. T. MARTIN, W. Q. MARTIN, W. Q.	8010080563 8010240277 8010240276* 8010020752 8010030098	50~271 8 70~820 50~29 0 50~285 0 30~293 0	MATTIA, B. U. MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. MATTIMDE, J. J. MATTIA, M. J.	8010230568 8010230575* 8010170552* 8010010570 8010080618*	CONTRACT CONTRACT CONTRACT 50-312 P CONTRACT	MAYER, L. O.	8010200450 8010210552 8010270364 8010200465 8010200540	50-292 8 50-292 8 50-263 F 50-263 F
MARTIN, W. Q. MARTIN, R. D. MARTIN, W. Q. MARTIN, J. B. MARTIN, W. Q.	8010030118 8010270186# 8010300193# 8010140146 8010140068	50-334 G 50-369 G 70-364 Haste Mgt 70-1143	HATTIA; H. J. HATTIA; H. J. HATTIA; H. J HATTIA; H. J. HATTIA; H. J.	8010020401* 8010020703* 8010040139* 8010210138* 8010010304*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MAYER, L. O. MAYER, L. O	8010220495 8010210692 8010280524 8010310355 8010310424	50-263 F 50-306 B 50-263 G 50-263 F 50-263 P
MARTIN, T. J. MARTIN, R. D. MARTIN, T. D. MARTINI, D. H. MARTIN, T. T	8010270116 8010140051# 8010020654# 8010020603	50-354 G 50-269 Q 50-263 F 50-327 8 50-220 B	MATTIA, M. J. MATTIA, M. J. MATTIA, M. J. MATTIA, H. J. MATTIA, H. J.	8010090141* 8010010278* 8010010273* 8010090044* 8010010113*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MAYER, L., C. MGBREARTY, R. A MGBREARTY, R. A. MGBREARTY, R. A MGBREARTY, R. A	8010310454 8010140043* 8010010403* 8010100071* 8010230528*	50-282 F 50-387 Q 50-333 Q 50-410 Q 50-410 Q
MARTIN, W. O. Martin, W. O. Hartin, R. A Martin, W. O. Martin, W. G.	8010240174 8010230073 8010300674 8010240303 8010300188	50-245 G 70-371 RES 50-287 G 70-364	HATTIA, M.J. HATTIA, M.J. HATTIA, M.J. HATTIA, M.J. HATTIHOE, J.J.	8010010282* 8010010295* 8010020255* 8010020716* 8010010567	CONTRACT CONTRACT CONTRACT CONTRACT SO-312 P	MGBRIDE, J. A. MGBRIDE, J. A. MGGABE, E. C. MGGABE, E. G. MGGABE, E. G.	8010140202* 9010140221* 8010010213* 8010010813* 8010020290*	70-820 70-820 50-317 Q 50-334 Q 50-317 Q
IARTINGON, Z.R. IARTIN, L.C. IARTIN, L.C. IARTIN, L.C. RTIN, L.C.	8010300301 8010170559 8010200316 8010200363 8010200595	RES CONTRACT CONTRACT CONTRACT CONTRACT	MATTIMOE, J J, HATTIA MATTIA, H, J, HATTIA, H, J, HATTIA, H, J,	8010040300 8010010242* 8010020591* 8010080341* 8010080223*	50-312 B CONTRACT CONTRACT CONTRACT CONTRACT	MCCABE, E.C. MCCABE, E. MCCABE, E.C. MCCABE, E.C. MCCABE, E.C.	8010230664* 8010080364 8010010136* 8010080163* 8010240183*	50-317 0 50-277 8 50-277 0 50-374 0 50-317 0
TIN, L. G. IN, L. G. G. T.	8010200654 8010210098 8010310534 8010090218 8010300111	CONTRACY CONTRACY GONTRACY 50-309 8 27-39	MATTIA: M. J. MATTIA: M. J. MATTIA: M. J. MATTIA: M. J. MATTIA: M. J.	9010220676* 8010070070* 8010070214* 8010140177* 8010160224*	CONTRACT CONTRACT CONTRACT 30-289 CONTRACT	MCCABE, E. C. MCCABE, E. C. MCCABE, E. MCCABE, E. C. MCCANN, J	8010220629 8010270039 8010270041 8010270545 8010100044*	50-317 8 50-277 8 50-334 8 50-278 8 50-336 0
۹,	8010170007 8010270043 8010100028 8010230331 8010100362	50-293 8 50-271 8 70-1193 50-416 F 50-255 P	MATTIA: M, J. MATTIA: M, J. MATTIA: M, J. MATTIA: M, J. MATTIA: M, J.	8010270200* 8010160164* 8010160238* 8010170315* 8010170323*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HCCLANAHAN; H. H. HCCLOBKEY; P. N. HCCOLLDUGH; N. D. HCCONNAUGHHAY HCCONNELL; J. H.	8010200233 8010290293* 8010310560 8010270214 8010150621*	70-27 COMMINSION RES 50-320 P 50-289 0
	8010020490 8010280147* 8010280205* 8010280202* 8010090247	50-201 G FOIA FOIA FOIA 50-316 B	Hattia, M. J. Hattia, M. J. Hattia, M. J. Hattia, M. J. Hattia, M. J.	8010170846# 8010170880# 8010200326# 8010200366# 8010200373#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCCORKLE, Q, H, MCCORKLE, Q, H, MCCORKLE, Q, H, MCCORKLE, Q, H, MCCORKLE, Q, H,	8010140062* 8010100075* 8010150104 8010150221 8010150073	FOIA COMMISSION 70-2924 70-1181 70-2609

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
NCCORKLE. O. N. NCCORKLE. O. W. NCCORKLE. O. W. NCCORKLE. O. W. NCCORKLE. O. W.	8010150078 8010070517 8010150087 8010150087 8010150089	70-36 70-143 70-27 70-734 70-25	MCGRATH, J R MCGREW, J W MCGREW, J. W. MCGUIRE, D. R MCGUIRE, D. R	8010020008 8010140176 8010240189 8010020275> 8010060158+	1&E 71-6744 71-46 70-27 50-34B Q	HIDURA,H J HIDURA,H J. MEERNICKI,H H MILAVICKAB,L.R. HILAVICKAB,L.R	8010200382 8010240372 8010160573* 8010210533*	50-311 R 50-247 8 50-318 8 50-151 P 50-151 P
MCCORKLE, O, W MCCORKLE, O, W MCCORKLE, O, H MCCORKLE, O, H MCCORHACK, H	8010070521 8010070524 8010240049 8010070509 8010140025	70-754 70-734 50-206 P 70-824 PR	MCGUIRE, D R MCGUIRE, H F. MCGUIRE, M F MCGUIRE, H F MCGURREN, H, J	8010270399+ 8010140578* 8010290171 8010210637 8010010646	50-327 G 50-466 9 NUREO 50-498 C 50-307 0	MILEB,E B. MILEB,E D. MILEB,E MILEB,E,B MILEY,G H.	8010210131 8010080345 8010140159 8010200076 8010200108*	CONTRACT CONTRACT CONTRACT CONTRACT 50-151 Q
MCCBRKLE, 9 W MCCBRKLE, 9 W MCCBRKLE, 9, W MCCBRKLE, 9, W MCCBRKLE, 9, W	8010240172 8010200138 8010160004 8010160008 8010220360	50-409 P 70-2478 70-371 70-27 70-8	MCQURREN, H, J MCQURREN, H, J, MCQURREN, H, J, MCQURREN, H, J MCQURREN, H, J	8010030115 8010140553 8010140571* 8010150048 8010150540	50-376 0 50-376 0 50-376 0 40-1162 30-483 9	MILHIBER, R J MILHOLLIN, O. L MILHOLLIN, O L. MILLER, W. O MILLER, W. O	8010210458 8010160778 8010310447 8010280172* 8010280183*	50-382 8 50-237 0 50-272 0 FOIA FOIA
MCGUISTION, R. M. MCDERHOTT, R. J. MCDONALD, J. R. MCDONALD, R. J. MCDONALD, C. E.	8010140554* 8010020599 8010240558* 8010170388* 8010310250*	50-466 0 PT21 70-25 CONTRACT 71-5088	McOurren, H. J. McOurren, H. J McOurren, H. J McOurren, H. J McOurren, H. J	8010170345 8010300090* 8010200164 8010300082 8010300063	50-483	HILLER, W. O. HILLER, W. O HILLER, W. O HILLER, W. O HILLER, W. O	8010270102* 8010270106* 8010270081* 8010270071* 8010270064*	50-568 A 50-348 A FOIA FOIA 50-568 A
MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M. A. MCFARLAND, C. R. MCFARLAND, C. R	601015028B 8010270400 8010310393 8010020725* 6010240346*	50-400 Q 50-400 R 50-400 A 50-387 Q 50-413 Q	McKeoun, L. H. McKeoun, L. K McKibben, J. C. McLauohlin, H T. McLauohlin, K. T.	9010230124* 8010240217* 8010280378 8010220540 8010010511*	70-33 50-245 @ 50-186 8 50-201 9 50-273 8	MILLER, H O MILLER, H H. MILLER, H. O. MILLER, L MILLER, H. J.	8010270058* 8010030074* 8010040027 8010080126* 8010040076	FOIA 50-335 0 70-1201 50-204 0 40-8200
HCFARLAND, J. E HCGARRY, J. M. HCGARRY, J. M. HCGARRY, J. M. HCGARRY, J. M.	8010030423 8010020037 8010020054* 8010240504 8010020054*	TOPREP 50-446 0 50-369 0 PR 50-369 0	MGLOUGHLIN, M. T. MGLOUGHLIR, M. T. MGLOUGHLIN, M. T. MGLOUGHLIN, M. T. MGLOUGHLIN, M. T.	8010020462* 8010090352* 8010070527* 8010210647 8010310501	50-293 B 50-293 B 50-293 B 50-293 B 50-293 B	Miller, H. J. Miller, J. R. Miller, J. R. Killer, J. H Miller, W. O	8010150107 8010230016 8010230018* 8010240007* 8010020190	40-8728 50-5 P 50-5 P 50-321 G 70-687
HCGARRY, J. H. HCGARRY, J. H HCGARRY, J. H. HCGARRY, J. H HCGARRY, J. H	8010020042 8010020050* 8010020050* 8010020050*	50-369	MCLOUGHLIN, M T. MCLOUGHLIN, M, T. MCLOUGHLIN, M T. MCLOUGHLIN, M, T MCLOUGHLIN, M T.	8010200431* 8010210356 8010210354 8010280503* 8010240418*	50-273 8 50-273 8 50-273 8 50-273 8 50-273 8	Miller: W. O. Miller: W O Miller: H. J. Miller: E. F. Miller: H. J.	8010140132 8010010035 8010240138 8010070067* 8010240005*	40-8348 70-143 40-8714 CONTRACT 50-321 G
MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M	8010040002 8010070555 8010070555 8010150002 8010150002	50-367 0 50-369 0 50-369 0 PR PR	MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T. MCMILLEN, N, H MCMULLEN, R. B.	8010280414* 8010280474* 8010280579* 8010040341 8010020604*	50-273 8 50-273 8 50-273 8 50-445 M 50-344 H	MILLER, L. MILLER, D. N MILLER, D. N MILLER, H. J MILLER, H. O	8010280017* 8010230330* 8010230444* 8010230379 8010210300	50-205 G CONTRACT CONTRACT WASTE MOT 50-329 A
HCGARRY, J. K. HCGARRY, J. H. HCGARRY, J. M. HCGARRY, J. H. HCGARRY, J. H.	8010140507 8010140507 8010150006 8010150006 8010210772	50-369	MCNAMARA, A E. MCNEILL, H H MCNEILL, H H MCNEILL, H H MCPHILLIPS, J.	8010230382* 8010210258* 8010220572* 8010240016* 8010070071	50-244 R 71-9016 71-9011 GA999 70-2909	MILLER, W O. MILLER, J. R. MILLER, J. R. MILLER, J. R MILLER, J. R	801022000B 8010170069 8010170079* 8010170110* 8010210083	50-329 A 50-112 P 50-112 P 50-112 P 50-112 P
HCOARRY, J. M. HCOARRY, J. M. HCOARRY, J. H. HCOARRY, J. H. HCOARRY, J. H.	8010210777 8010210772 8010210777 8010230692 8010240552	50-369 0 50-369 0 50-369 0 50-369 0 50-269 0	McPhillips, J McQueen, M. M Meci, C Medeirob, M. 8. Medina, V.	8010140016 8010210192 8010100147 8010200369 8010140449#	70-2909 REGOD WABTE MOT PR CONTRACT	Miller, E. M. Miller, D. S. Miller, W. O. Miller, J. R. Miller, W. O.	8010240417 8010150095 8010280055 8010220448 8010280491	50-29 0 50-309 0 70-33 50-267 P 50-443 A
MCGARRY, J. M. MCGARRY, J. M. MCGAUGHY, R. W MCGAUGHY, R. W. MCGAUGHY, R. W.	8010230692 8010240352 8010010323+ 8010020131* 8010140043*	50-369 0 50-269 0 50-354 9 50-412 9 50-387 9	MEDROW, L. A MEDROW, L. A. MEDROW, L. A MEINERT, D. L. MELPOLDER, F. H	8010070045 8010070207 8010140175 8010080506* 8010280174*	CONTRACT CONTRACT 50-287 0 50-518 R FOIA	MILLER, W. O. MILLER, W. O. MILLER, W. O. MILLER, L. K MILLER, L. K	8010280484 8010280488 8010290386 8010200378* 8010200384*	50-220 0 50-313 P 50-277 P 50-272 R 50-311 R
HCGAUGHY, R. W. HCGAUGHY, J. P. HCGAUGHY, R. W. HCGAUGHY, R. W. MCGAUGHY, R. W.	#EA00140063 #260010036# #2600100108 #2760100108	50-352 Q 50-416 Q 50-352 Q 50-423 Q 50-443 Q	MELBTAD, K. MENARD, H. W. MENCZER, W. B. MENDELEON, I. N. MENTER, L.	8010010597* 8010210266 8010160038 8010010293* 8010160037	50-346 B REOOD 146 CONTRACT XPORTLIC	MILLER, V. L. MILLER, E. B. MILLER, M. E. MILLER, W. O. MILLER, D. B	8010270259* 8010200515 8010200602 8010270327 8010270448	100FR 50-309 H 50-445 H 50-346 P 50-309 0
MCGAUGHY, R. W. HCGAUGHY, R. W. HCGAUGHY, R. W. HCGAUGHY, R. W.	8010210322* 8010040073* 8010230100* 8010230528* 8010230707*	50-322 Q 50-354 Q 50-354 Q 50-410 Q 50-412 Q	HENTER: L. MERONEY: R. N. MERONEY: R. N. MERR I WEATHER: N. MERR I WEATHER: N.	8010270006 8010230013 8010230036 8010270206*		MILLER, B. HILLER, J. R HILLER, J. R. HILLER, M. I. MILLER, M. I	8010300686 8010310142 8010310147* 8010290384 8010290384	50-498 9 50-151 P 50-151 P 50-454 9 50-454 9
MCGAUGHY, R. H MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8010240248* 8010030436 8010230138 8010060256 8010010561	50-423 Q 50-416 B 50-416 B 50-416 S 50-416 K	MERRILL, C MERSON, B. D. MERSON, B. D. MERTOOUL, R. MEBLER, R. B.	8010290079N 8010230434 8010230438N 8010210451N 8010020464	50-317 R 50-317 R	MILLER, W. O. MILLS, L. M. MILLS, L. M MILLS, L. K. MILLS, L. K.	8010310579 8010170123# 8009100414 8010020749 8010090102	50-267 P 50-327 G 50-328 S 50-289 G 50-259 G
MCQAUGHY, J. P. MCQAUGHY, J. P. MCQAUGHY, J. P. MCQAUGHY, J. P.	8010010566* 8010080416 8010210007 8010160504 8010160514	50-416 K 50-416 S 50-416 S 50-416 B	Mesler, F. B. Messitt, B. R. Meyer, K. A. Meyer, J. L. Michelson, C.	8010080635# 8010080057# 8010010289# 8010240417 8010220039#	50-335 Q FOIA 50-29 Q	Mille, L. K Mille, L. M. Mille, L. M. Mille, L. M. Mille, L. M.	8010170031* 8010080391 8010010861 8010020480 8010100439	50-327 0 50-327 0 50-518 8 50-259 P
MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8010210355 8010200487 8010210630 8010300497 8010310511	50-416 S 50-416 G 50-416 B 50-416 B	Michel, C. J. Michel, C. J. Michel, G. J. Michel, C. J. Michel, C. J.	8010070172 8010210766 8010240288 8010200348 80100070177	70-143 70-143 70-143 70-143 70-143	MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M. MILLB, L. M.	8010150320 8010200212 8010070074 8007300400 8007300375	50-259 0 40-1341 50-327 0 50-259 P 50-328 8
HCGAUGHY, J. P. HCGAUGHY, J. P. HCGAUGHY, J. P. HCGAUGHY, J. P. MCGAUGHY, J. P. MCGOLDRICK, T.	8010210478 8010310517 8010310523 8010240438 8010240032	50-416 8 50-416 8 50-416 8 50-416 8 XPORTLIC	Michel.C.J. Michelson.C. Michel.C.J. Midura.H.J. Midura.H.J.	8010150657 8010290165 8010200420 8010060130 8010200377	70-143 50-29& P 71-5059 50-272	MILLB,L.M. MILLB,L.H. MILLB,L.H MILLB,L.H. MILLB,L.H.	8010040241 8010070332 8010080427 8010080519 8010270394	50-327 P NUREQ 50-390 B 50-553 B 50-327 Q

AUTHOR	ACCERSION NUMBER	BUBJEC		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATECORY
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8010030394 8010090407 8010070342 8010070470 8010150358	50-259 50-390 50-518 50-327 50-438	F 88 P 8	MITCHELL, D O MITTER, E L MITTL, R L MITTL, R L MITTL, R L	B010210431* 8010240043 8010160486 B010160516 B010160510	50-287 R NUREO 50-311 P 50-311 P 50-311 V	MORI,K MORI,K MORIARTY,J M MORIARTY,J M MORIBI,A V	8010200006 8010240200 8010010435 8010140343 8010010215	PR PR 90-395 8 50-395 8 50-293 0
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8010290319 8010150430 8010090386 8010150368 8010160533	50-566 50-438 50-257 50-370 50-438	G G P S S	MINAAYAGANIM MINAAYAGANIM MINAAYAGA	8010240492 8010240538 8010010028# 8010300428# 8010020273#	XPORTLIC XPORTLIC 50-327	MORIBI, A V MORIBI, A V MORIBI, A V MORIBI, A V MORIBI, A V	8010010237 8010020314 8010060318 8010070445 8010270351	50-293 F 50-293 F 50-293 P 50-293 P 50-293 P
MILLS, L K MILLS, L K MILLS, L K MILLS, L K	8010240419 8010150393 8010150463 8010160523 8010150370	50-438 50-259 50-259 50-328 50-327	3 3 8 8 P	MODENOS, L MODENOS, L MODRO, 8 M MOERKE, N H MOERKE, N H	8010070031* 8010270407* 8010300174 8010210738* 8010210746*	50-335 Q 50-324 Q Res Ga999 Ga999	MORIBI,A V MORIBI,A V MORIBI,A V MORIBI,A V MORNEAU,R A	8010210618 8010240237 8010270316 8010310401 8010080381	50-293 F 50-293 R 50-293 P 50-293 F NUREO
MILLB, L M MILLB, L M MILLB, L M MILLB, L M MILLB, L K	8010160536 8010160579 8010210489 8010210365 8010210397	50-438 50-438 50-390 50-390 50-566	8 8 9 5	MOERKE, N. H MOERKE, N. H MOERKE, N. H HOFFETT, T MOHR, D	8010210732* 8010210411* 8010210402* 8010270275* 8010300232	GA999 GA999 GA999 COMMISBION RES	MORRIBON, A B MORSE, A K MORTON, K, V MORTON, K, V MORTON, K, V	8010160592 8010100054 8010070052* 8010100236* 8010140230*	PRH 50-409 Q Contract Contract Contract
MILLS, L. K MILLS, L. K, MILLS, L. H MILLS, L. H, MILLS, L. H	8010210483 8010210588 8010210369 8010210481 8010240436	50-294 50-259 50-327 50-259 50-438	P 8 F 8	MOMBOIBBE, R, M MONDOVE, R B, MONTOOMERY, D M MONTOOMERY, D, M MONTOOMERY, C R	8010070400 8009290471 8010010283* 8010240174* 8010070484	PR SECY 50-338 Q 50-348 Q 50-146 R	MORTON, K V MORTON, K, V MORTON, K, V MORTON, K, V MORTON, K, V	8010070072* 8010010253* 8010010268* 8010010281* 8010010297*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8010200529 8010210348 8010210405 8010210560 8010210578	50-259 50-259 50-328 50-328 50-438	P R 8 8	MONTODHERY,A F MONTI,W A MONTI,W A MONTI,W A MOODY,D E	8010210118 8010010519 8010150447 8010240391 8010010251*	PR 50-247 B 50-3 R 50-247 S 50-309 G	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8010080663* 8010010269 8010010279* 8010010373* 8010010442*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS,L H MILLS,L H, MILLS,L, H MILLS,L H MILLS,L H	8010210590 8010210596 8010220505 8010220395 8010270351	50-327 50-327 50-257 50-296 50-327	8 P P P	MOODY, D E MOODY, D E MOODY, D E MOODY, D E	8010010386* 8010010716 8010010178 8010010634 8010010720	50-27 G 50-27 G 50-27 G 50-27 G 50-307 G	MORTON, K. V MORTON, K. V. MORTON, K. V MORTON, K. V. MORTON, K. V	9010090033* 8010090055* 8010090063* 8010080667* 8010090061*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS.L M MILLS.L M. MILLS.L M. MILLS.L M.	8010280442 8010280451 8010280478 8010280596 8010280611	50-327 50-438 50-390 50-566 50-566	9 9 9	MOODY, D. E MOODY, D. E, MOODY, D. E MOODY, J. H MOODY, D. E	8010270189* 8010200371 8010270191 8010210223 8010040308	50-309 0 50-309 0 REGOD 50-29 P	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8010170032* 8010170093* 8010170388* 8010200223* 8010200297*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8010280400 8010280427 8010280617 8010280626 8010280368	50-438 50-328 50-438 50-390 50-328	8 8 8 8	MOODY, D E, MOODY, J H MOODY, D, E MOODY, D E MOODY, D. E	8010080354 8010160695 8010150400 8010150322 8010270360	50-27 Q 50-201 Q 50-307 R 50-27 R 50-29 V	MORTON, K, V. MORTON, K, V. MORTON, K, V. MORTON, K, V. MORTON, K, V.	8010080633* 8010080635* 8010070011* 8010070021* 8010070044*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8010280371 8010280373 8010280394 8010280445 8010280459	50-438 50-438 50-329 50-566 50-390	8 8 8	MOODY, D & MOON, B T MOON, R. E MOON, C. W MOON, C. W.	8010310369 8010240653* 8010290116* 8010070035* 8010070523*	50-27 V 50-261 G QA999 50-466 G 50-466 G	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V.	8010070048* 8010070049* 8010170371* 8010170380* 6010300158*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS, L M MILLS, L M MILLS, L, M MINECK, D L MINECK, D L	8010310338 8010310400 8010310333 8010150439 8010150475	50-566 50-438 50-259 50-331 50-331	A P 8	HODN.C H HOON.C H HOON.C H	8010060015 8010100388 8010170164 8010150072 8010240182	90-466 Q 90-454 A 50-454 A 50-466 Q 40-8502	MORTON, K. V. MORTON, K. V. MORTON, K. V MORTON, K. V, MORTON, K. V,	8010150357* 8010160144* 8010170400* 8010200291* 8010080193*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
Mineck, D L Mineck, D L Mineck, D L Mineck, D, L Mineck, D L	8010150421 8010150457 8010150490 8010210404 8010220471	50-331 50-331 50-331 50-331 50-331	8 8 8 R	MOORE, J. B MOORE, D. E. MOORE, R. L. MOORE, R. L MOORE, R. N	8010140072* 8010060158* 8010030197* 8010030200* 8010010166	70-1143 50-348 Q 71-6346 71-6346 XPORTLIC	MORTON, K. V.	8010160141* 8010160149* 8010160152* 8010160156* 8010160157*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MINOLE, J. O MINOQUE, R. B. MINOQUE, R. B. MINOQUE, R. B. MINOR, Q. C.	8010240529 8010140091* 8009100759 8009100225 8010080545	PR FOIA SECY SECY NUREO		MOORE, R. N. MOORE, W. H MOORE, O. H MOORE, R. N MOORE, R. N	8010010170 8010020682 8010020359 8010270370 8010240505	XPORTLIC 50-201 0 50-334 R XPORTLIC XPORTLIC	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	9010160162* 8010160167* 9010160170* 9010160176* 8010160176*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MIRACLIA.F J. MIRACLIA.F MIRACLIA.F, J. MIRACLIA.F, J MIRACLIA.F, J	8010030015 8010300376 8010310504 8010220284* 8010220286*	50-275 50-275 50-458	P H E A A	MODRE, R. N MODRE, R. N MODRE, J. E. MODRE, J. E. MODRE, J. E.	8010270088 8010270091 8010200190 8010220313 8010220333	XPORTLIC XPORTLIC 50-155 0 50-155 0 50-155 0	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8010140342* 8010170311* 8010170393* 8010170452* 8010200234*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MIRAGLIA, F J MIRAGLIA, F J MIRAGLIA, F, J MIRAGLIA, F, J	8010220292* 8010240011 8010240172 8010270252 8010270013	50-275 50-275 50-275	A H H A P	MOORE, J. E MOORE, J. E, MOORE, J. E, MOORHAN, J. W. MOREAU, W. N,	8010240580 8010290033 8010300098 8010240337* 8010220423	50-155 0 50-155 0 50-155 0 50-380 0 50-219 J	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	8010200230* 8010200317* 8010310587* 8010150607* 8010160208*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MIRAGLIA, F. J MIRAGLIA, F. J MIRAGLIA, F. J. MIRAGLIA, F.	8010270014* 8010270038 8010270244 8010310494 8010310500*	50-204 50-275 50-329	P H H A A	MOROAN, J. N MOROAN, H. E MOROAN, J. N MOROAN, J. N MOROAN, J. N	8010150452* 8010160080 8010070241* 8010070246* 8010070250*	50-10 P 40-7783 TOPREP TOPREP TOPREP	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V, MORTON, K. V	8010160322* 8010160334* 8010170317* 8010310597* 8010270008*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
Hiraqlia, F. J. Mighima. J. Hitchell, Q. J. Hitchell, M. D. Mitchell, D. Q.		50-275 8 RE8 50-307 U CONTRACT 50-289 8		MORGAN, M. A MORGAN, M. A. MORGAN, M. A MORGAN, M. A MORI, K	8010300137 8010150071 8010150127 8010150142 8010200006	REB REB REB REB PR	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORELEY, N. C. MOTES, B. Q	8010270003* 8010240614* 8010270003* 8010210160 8010230017	CONTRACT CONTRACT CONTRACT 50-237 Q 50-250 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MOTL.O.P MOTT.N.E MONRY.H R MONRY.H R MONRY.H R	8010070343* 8010220126 8010310465* 8009170170 8009170179	50-364 A WASTE MOT PRM 71-7034 71-7037	MURPHY, C E MURPHY, A H MURPHY, C E MURPHY, C E MURPHY, C E	8010170107 8010140629* 8010140092 8010150661 8010240101	50-327 Q CONTRACT 50-250 Q 50-324 Q 50-390 Q	NAUGHTON, H F NAUGHTON, H F NAUGHTON, H F. NAUGHTON, H F NAUGHTON, H F	8010140253 8010150427 8010160485 8010220550 8010210460	50-295 F 50-295 P 50-295 P 50-295 P 50-295 P
MOURY, U.R. MOURY, U.R. MOURY, U.R. MOURY, U.R. MOURY, U.R. MOURY, U.R.	8010030189 8010010702 8010170293 8010170293* 8010230224	71-6346 XPORTLIC XPORTLIC XPORTLIC 71-6487	MURPHY, C E MURPHY, W P MURPHY, W P MURPHY, W P	8010070368* 8010060251 8010060257* 8010060263 8010060268*	50-316 8 50-271 8 50-271 8 50-271 8 50-271 8	NAUGHTON, W F NAUGHTON, W F. NEFF, R D NEILSON, C C NEISLER, J H	8010280287 8010310347 8010230709* 8010020654* 8010100012*	50-295 P 50-295 P 50-298 F 50-263 F 50-373 Q
MOURY, M.R. MOURY, M.R. MOURY, M.R. MOURY, M.R. MOYER, M. B.	8010270105 8010270085 8010270108 8010300674 8010010272*	71~6089 XPORTLIC 71-6347 71-9057 40-8385	MURPHY, N. P. MURPHY, N. P. MURPHY, X. P. MURPHY, X. P. MURPHY, X. P.	8010150437 8010150448* 8010270419 8010200399 8010200404*	50-271 8 50-271 9 50-413 Q 50-271 8 50-271 6	NEISLER, J H NELSON, R L NELSON, R L NELSON, R L NELSON, R L	8010070265 8010070183 8010070287 8010070277 8010070276	50-358 8 50-305 8 50-305 8 50-305 8
MROCIKA, E. J MROCIKA, E. J MROCIKA, E. J. MROCIKA, E. J. MROCIKA, E. J	8010070325 8010070373 8010070447 8010140437 8010150537	50-245 8 50-245 8 50-245 8 50-245 8 50-245 8	MURPHY, W.P. MURPHY, W.P. MURPHY, C.E. MURPHY, C.E. MURPHY, C.E.	8010200466 8010200469* 8010280050 8010290392 8010300380	50-271 8 50-271 6 50-370 0 50-324 0 50-369 0	MELSON, R. L. NELSON, J. D. NELSON, J. D. NELSON, K. F. NELSON, T. A.	8010160187* 8010300171* 8010300166 8010280349 8010230015	50-305 Q HASTE HOT HASTE HOT 50-349 H NUREO
MROCIKALE J MROCIKALE J MROCIKALE J MROCIKALE J MROCIKALE J.	8010210426 8010210432 8010230385 8010230422 8010280386	50-245 R 50-336 R 50-336 8 50-245 8 50-245 8	MURPHY, W. P MURPHY, W. P MURPHY, C. E. MURPHY, C. E MURPHY, C. E	8010230407 8010230410* 8010310022 8010310035 8010310329	50-271 8 50-271 8 50-413 0 50-413 0 50-400 0	NERENBERO, A L. NERBEB, V NEUMANN, M R NEUMANN, M R, NEUMANN, M R	8010210183 8010230127 8010070165 8010230550 8010230560	FOIA 50-295 P 40-8497 40-8380
MROCZKAJE U MROCZKAJE U MROCZKAJE U MROCZKAJE U MACHNICKIJE D	8010240407 8010280537 8010280387 8010300455 8010100136	50-245 B 50-336 B 50-245 B 50-245 B PR	MURPHY, C. E MURPHY, P. M MURPHY, W. P. MURPHY, W. P MURRAY, T. D	8010300450* 8010270384 8010310471 8010310478* 8010020372	50-315 8 50-454 0 50-271 8 50-271 8 50-346 8	NEUMANN, H R NEUMANN, M R NEUMANN, M R NEUSGHAEFER, E NEUSGHAEFER, E	8010230544 8010270342 8010240572 8010200477* 8010200485*	40-8697 40-8697 40-8697 50-302 8 50-302 8
MUCHNICKI, E D MUCHNICKI, E, D MUDIB, J MUELLER, R MUELLER, M L	8010200567 8010200574* 8010010042* 8010070511* 8010070160	PR PR 71-9134 50-285 8 NUREG	MURRAY, H. MURRAY, J. P MURRAY, R. MURRAY, T D MURRAY, T D,	8010020499 8010010135 8010160365* 8010010512 8010010591	50-201 0 50-266 0 50-254 8 50-346 8 50-346 8	NEWMARK, N. M. NEWMAN, J. R NEWMARK, N. M. NEWMAN, J. R NEWMAN, J. R	7702070367* 8010080075 8010140179* 8010010217 8010010217	50-322 A PR 50-275 0 50-466 0
MARLLER, R MULLER, K MULLER, D, R MULLER, D, R MANIS, J,	8010140447* 8010240523 8010210778 8010310576 8010010037*	50-265 8 40-8714 50-366 H 50-219 P 71-9136	MURRAY, T D MURRAY, J P. MURRAY, T. D MURRAY, T D MURRAY, M J	8010030445 8010020027 8010070472 8010070451 8010140503	50-346 8 50-266 0 50-346 8 50-346 8 PR	NEWHAN, J. R NEWHAN, J. R NEWHAN, J. R NEWHAN, J. R NEWHAN, J. R	8010140843 8010140550* 8010140573* 8010140587* 8010140597*	50-466 Q 50-466 Q 50-466 Q 50-466 Q
Hurphy, C. E. Hurphy, C. E. Hurphy, C. E. Hurphy, C. E.	8010010039* 8010160260 8010010044* 8010140107* 8010010214*	71-7136 XPORTLIC 30-416 Q 50-250 G 50-413 Q	MURRAY, R MURRAY, T. D MURRAY, J. D MURRAY, J. P MURRAY, M. J.	8010210309* 8010200444 8010150321 8010310075* 8010230387	50-265 8 50-346 8 50-346 R 50-424 Q 50-237 Q	r (namian R Lahahan J R Lahahan J R Lahahan R Lahahan	8010140543 8010140550* 8010140573* 8010140589* 8010140599*	50-466 Q 50-466 Q 50-466 Q 50-466 Q
HURPHY, C E HURPHY, C E HURPHY, C. E HURPHY, C. E	8010300388* 8010010023* 8010130649* 8010310029* 801030086*	50-367	MURRAY, T D, MURRAY, T D MURRAY, R. C. MURRY, T D MUSGER, M	8010270387 8010310460 8010230015 8010200436 8010140617	50-344 8 50-344 8 Nureo 50-344 8 50-320 P	nehman, J r Nemman, J r Nemman, J r Nemman, J r Nemman, J r,	8010140403 8010150455 8010240427 8010270522 8010280020	50-498 0 50-367 0 50-498 0 50-466 0
MURPHY, C E HURPHY, C E, MURPHY, C E HURPHY, C E HURPHY, C, E	8010310042* 8010020772 8010020244 8010020774 8010020721	50-413 G 50-438 G 50-438 G 50-438 G 50-389 G	MUZZY: R. J. MUZZY: R. J. MYERS: H. A. MYERS: H. A. MYERS: H. A.	8010020339* 8010100318* 8010280178* 8010280189* 8010280218*	TOPREP TOPREP FOIA FOIA	NEUMAN, J R NEUMAN, J R NEUMAN, J R NEUMAN, J R NEUMAN, J R	8010270522 8010280020 8010270374 8010270374 8010310048	50-466 0 50-466 0 50-466 0 50-466 0
MURPHY, C, E MURPHY, C, E MURPHY, C E, MURPHY, C E, MURPHY, C E	8010020266 8010090013 8010090024 8010090149 8010170271	50-281	Hyers, H. A. Myers, M. A Myers, D Myers, R. V. Myers, R. V.	8010280166# 8010280151# 8010140051# 8010020337 8010020343#	FOIA FOIA 50-269 G 50-522 A 50-522 A	Mewman, J R Memman, J R. Memman, J R Memman, J R Memman, J. R	8010310051 8010310048 8010310051 8010300597 8010300597	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
HURPHY, C E HURPHY, C E HURPHY, C E HURPHY, C E	8010140137* 8010070236 8010220486* 8010140030* 8010140045*	50-400	MYNATT: F, R MYRABD: A L NAGARAJAN: R NAIDU: K R. NAIDU: K R.	8010150136 8010150411* 8010150647* 8010040128* 8010010620*	REB 50-263 R CONTRACT 50-483 Q 50-454 Q	NENTON, F NICHOLBON, W. NICHOLB, T. C NICHOLB, T. C NICHOLB, T. C	8007250330* 8010030533 8010010178* 8010160746 8010010655	50-327 F 11E 50-289 G PR 50-375 A
HURPHY, C.E. Hurphy, C.E. Hurphy, C.E. Hurphy, C.E. Hurphy, C.E.	9010230254 8010240235 8010010031 8010010020 8010240160*	50~566	NALEPKA, D. 8 NAPUDA, Q. NAPUDA, Q. NARBUT, P. P NARBUT, P. P.	8010280554* 8010300263* 8010240064* 8010090381* 8010310278*	50-305 8 50-272 0 50-244 0 50-361 0 50-361 0	NICHOLB, T, C NICHOLSON, P J. NICHOLB, T C, NICHOLB, T, C NICHOLB, T C.	8010020353 8010030447 8010060225 8010070257 8010070187	50-395 A NUREG 50-395 A 50-395 F 50-395 K
HURPHY, C E HURPHY, C E HURPHY, C, E, HURPHY, C, E HURPHY, C E	8010240339* 8010270085 8010280054* 8010290397* 8010010186	50~413	NARBUT, P. P. NARDACCI, G A NARDACCI, G A. NARDACCI, G. A NARDACCI, G A	8010280026* 8010170353* 8010170347* 8010170349* 8010170352*	50-275 G 50-320 R 50-320 R 50-320 R 50-320 R	NICHOLB, T C. NICHOLB, T C. NICHOLB, T C. NICHOLB, T C. NICHOLB, T, C.	8010290198 8010140272 8010160912 8010200457 8010160903	50-375 Q 50-375 A 50-375 A 50-375 B 50-375 K
НОЯРНУ, С Е НОЯРНУ, С Е НОЯРНУ, С Е НОЯРНУ, С, Е НОЯРНУ, С Е	8010240111# 8010240661 8010270202# 8010080221# 8010270099	50-413	NARDACCI, G, A NARDACCI, G A. NARRETTO, C, J NARROW, L. NARROW, L.	8010170355* 8010170357* 8010080210 8010020151* 8010210322*	50-320 R 50-320 R RE8 50-412 G 50-322 G	NICHOLB, T C. NICHOLB, T C NICHOLB, T C NIELBEN, L A NIMITZ, R. L	8010160553 8010230401 8010240442 8010060350* 8010240565*	50-375 F 50-375 K 50-375 F 50-285 P 50-286 Q
MURPHY, J J. MURPHY, C E. MURPHY, C E. MURPHY, C E. MURPHY, C, E.	8010010442* 8010030068 8010240041* 8010030489 8010140112	CONTRACT 50-335 Q 50-344 Q 50-349 Q 50-400 Q	NARROW, L NARVER, R. 8 NAUOHTON, H. F. NAUOHTON, H. F. NAUOHTON, H. F.	8010230707* 8010150153 8010020284 8010020439 8010070587	50-412 G NUREO 50-295 P 50-454 A 50-295 P	NIX.R.T. NIX.R.T. NIX.R.T. NIX.R.T. NIX.R.T.	8010060247* 8010060257* 8010060360* 8010080382* 8010160475*	50-366 8 50-366 8 50-366 8 50-366 8 50-366 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT
NIX.R T NIX.R T NIX.R T NIX.R T NOONAN,V S	9010140482* 9010220474* 8010280425* 8010280476* 8010230280	50-321 5 50-366 8	O'REILLY, JP O'REILLY, JP O'REILLY, JP O'REILLY, JP,	8010140154 8010140157 8010140160 8010140180 8010140184	50-424	OBANN,E W OBTER,J OBTER,J OBTRANDER,F W OTT,W R	8010210776 8010070329* 8010070326 8010300092 8010140093*	50-367 ¢ 50-10 J 50-10 J 50-344 ¢ FOIA
NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDLINGER, M S	8010010285 8010140041 8010140094 8010140098 8010010630	50-344 Q 70-1257 50-243 Q 70-734 70-143	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8010140174 8010140201 8010140205 8010160212 8010160216	50-259 G 50-302 G 50-395 G 50-348 G 50-364 G	OTT, W. R. OTTOBON, H. L. OUZTB, J. E. OVERLID, T. W. OVERTON, J. A	800930303 8010080283 8010240228* 8010280533* 8010230506	NUREO 50-204 0 50-224 0 50-263 9 PR
NORELIUB, C E NORRHOLM, L J NORTON, J NORTON, B	8010100414 8010010631* 8010230294* 8010270149 8010240544		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P,	8010160275 8010160286 8010160273 8010160278 8010160220	50-488	OWBLEY, O F OWBLEY, O F OWIARSKI, P C PACE, P, L PACE, P, L	8010140276 8010070237 8010310874 8010070474* 8010070437*	TOPREP TOPREP RES 50-335 & 50-335 &
NORTON, B NORTON, B NORTON, B NORTON, B	8010240544 8010160056 8010160056 8010160053 8010160053	50-133	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P, O'REILLY, J P	8010270007 8010270411 8010270530 8010270537 8010270544	70-143 50-269	PACE, P. L PACE, P. L PACE, P. L. PACE, P. L PACE, P. L	8010070453* 8010070477* 8010080217* 8010080673* 8010100323*	50-335 8 50-335 8 50-335 8 50-335 8
NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8010010128 8010010124 8010100297 8010090578 8010100215	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P	8010270549 8010270552 8010270555 8010270560 8010270565	50-321 Q 50-250 Q 50-280 Q 50-395 Q 50-416 Q	PACE, P. L PACE, P. L PACE, P. L PACE, P. L PACE, P. L.	8010100331* 8010100334* 8010100322* 8010100317* 8010100314*	50-335 8 50-335 8 50-335 8 50-335 8 50-335 8
NOSENIO, L V NOSENIO, L V. NOVAK, T M NOVAKOVICH	8010270273 8010310112 8010030007 8010070229 8010160261	XPORTLIC XPORTLIC 50-209 F 50-360 P XPORTLIC	O'REILLY, J P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J, P. O'REILLY, J P.	8010270567 8010270578 8010270579 8010240003 8010290041	50-302 Q 50-348 Q 50-437 Q 50-321 Q 50-416 Q	PACE, P. L PACE, P. L PACE, P. L PACE, P. L PACE, P. L	8010100345* 8010280690* 8010310398* 8010310433* 8010310441*	50-335 8 50-250 8 50-250 8 50-250 8 50-250 8
NOVAK,T K NOVAK,T K NOVARRO,J P NOVARRO,J P NOVARRO,J P	8010210252 8010200034* 8010020714* 8010020322 8010070334	50-302 P 50-147 H 50-322 Q 50-322 Q 50-322 M	O'REILLY, J P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J P.	8010270042 8010270043 8010270045 8010270047 8010270047	50-395 Q 50-348 Q 50-302 Q 50-321 Q 50-250 Q	PACK, R H. PACK, R H. PACKER, 9 PAGE, B M. PAGE, R O.	8010070450* 8010100433 8010020600* 8010220165 8010020606	NUREG PR 50-344 H ACRB 70-1113
NOVARRO, J P NOWICKI, S J NOWICKI, S J NOWICKI, S J	8010210473 8010270390 8010280043 8010300154 8010100385	50-322 K 50-206 P 50-206 P 50-206 P 50-244 P	O'REILLY, J P D'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P	8010270052 8010270056 8010270058 8010270060 8010270066	50-269 Q 50-488 Q 50-261 Q 50-280 Q 50-259 Q	PAGE, R. O PAGE, R. O. PAGE, R. G. PAGE, R. O. PAGE, R. O.	8010030137 8010150152 8010220094 8010290135 8010300495	70-143 70-143 70-2609 50-390 A 50-328 A
NOWICKIES J NUGENTEL NUNNED E NUNNED E	8010140135 8010280047 B010010669 8010090055* 8010090063*	50-206 P 50-206 P 40-2259 CONTRACT CONTRACT	G'REILLY, J P, D'TOOLE, J, OBERG, C, T OBERG, C, R, OESTHAN, M, J	8010270072 8010070072* 8010060071 8010270022* 8010080218*	50-437 G CONTRACT I&E 50-482 G 50-358 G	PAGLIARO, J A. PAGLIARO, J A PAGLIARO, J, A PAGLIARO, J, A PAGLIARO, J A	8010030547 8010070306 8010060072 8010060075 8010220125*	18E 18E 18E 18E 40-2384
NUNN, D. E NUSBBAUMER, D A O'HANLON, J, P O'NEIL, R A O'NEIL, R A	8010240398 8010140228* 8010070489 8010020073 8010030125	50-361 8 70-820 50-368 8 50-445 0	GESTMANN, M. V OH, I DLASCOAGA, M. T. OLLER, R. E OLMSTEAD, W. J	8010220486* 8010080372 8010140609 8010290126* 8010200630	50-237 F NUREO NUREO GA999 50-275 O	PAINTER.K.J PALMER.L W PALMER.C PANETTA.L E. PANOBURN.G.C.	8010200547* 8010080087 8010070471 8010270275* 8010210276	50-498 0 FOIA 50-366 8 COMMISSION 27-47
O'NEILL,R A O'NEILL,J O'NEILL,J O'REILLY,J P O'REILLY,J P,	8010030125 8010230446 8010230447* 8010140057 8010240533*	50-445 M 50-155 Q 50-155 Q 50-324 Q 50-335 F	OLMSTEAD. W J OLSEN, D. OLSEN, A F. OLSEN, C S. OLSEN, A, F	8010160552 8010290287* 8010070527 8010010802 8010200253	50-275 0 50-195 P 70-824 RES 70-824	PANZANI,F,A PAOLINO,R.J PAOLINO,R. FAOLINO,R PAOLINO,R PAPAY,J L.	8010230304 8010020151* 8010230043* 8010230707* 8010080107*	50-201 0 50-412 0 50-387 0 50-412 0 50-206 0
O'REILLY, J P, O'REILLY, J P, O'REILLY, J P O'REILLY, J P O'REILLY, J P	8010030500* 8010140078* 8010240009* 8010200628 8010200632	50-369 0 50-364 A 50-321 G 50-321 Q 50-261 Q	Olsen, A. F. Olsen, F. M. Olsen, L. Olson, A. W Olson, R. E.	8010060282 8010100056* 8010140001 8010080475 8010020675	50-13 J 50-409 Q 50-284 P NUREQ 50-201 Q	PAPAY, L T. PAPAY, L T. PAPAY, L T. PAPERIELLO, C J. PAPERIELLO, C J	8010080187* 8010210442* 8010150279 8010030530 8010220460	50-206 Q 50-206 Q 50-206 R 14E 14E
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P	8010200637 8010200652 8010200656 8010230064 8010230067	50-259 @ 50-332 @ 50-437 @ 50-395 @ 50-302 @	OPREA, O. W OPREA, O. W OPREA, O. W. OPREA, O. W. OPREA, O. W	8010010146 8010130208 8010130199 8010150188 8010130181	50-498 8 50-498 8 50-498 8 50-498 8 50-498 8	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C. J PAPERIELLO, C J. PAPERIELLO, C	8010220463 8007030041 8010060042 8010030537 8010030546	14E 14E 14E 14E
O'REILLY, J P O'REILLY, J P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J P.	8010230069 8010230072 8010230074 8010230089 8010230090	50-416 Q 50-348 Q 50-488 Q 50-250 Q 50-260 Q	Oprea, o H. Oprea, o H. Oprea, g. W. Oprea, g. W. Oprea, g. H	8010150193 8010150162 8010150169 801010661 8010210452	50-478 8 50-478 8 50-478 8 50-478 A 50-478 8	PAPERIELLO, C. J PAPERIELLO, C. J PAPERIELLO, C PAPERIELLO, C. J PAPERIELLO, C. J.	8010030533 8010080218* 8010060044 8010160346* 8010220125*	1&E 50-358 Q 1&E 50-254 Q 40-2384
O'REILLY, J P O'REILLY, J, P O'REILLY, J, P, O'REILLY, J P, O'REILLY, J P	8010230108 8010170046 8010070641 8010270479 8010270482	50-267 G 50-327 Q State Prog 50-261 G 50-269 G	OPREA, O. W. OPREA, O. W. OPREA, O. W. OPREA, O. W. OPREA, O. W.	8010160565 8010160556 8010210313 8010310528 8010310295	50-498 C 50-498 S 50-498 A 30-498 B 50-498 B	Paper Iello, C. J. Paper Iello, C. J Pappas, H Pappas, H Pappas, H.	8010160370 8010290136# 8010200662 8010300122 801030647	1&E 50-123 G ORO ORO ORO
O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8010270484 8010270488 8010270493 8010270497 8010270502	50-302 Q 50-327 Q 50-348 Q 50-280 Q 50-250 Q	OPREA, O, W OPREA, Q W. OPREA, O, W. ORDERB, W. T. ORDERB, W.	8010240420 8010280360 8010280360 8010010131* 8010140051*	50-478 A 50-478 S 50-498 S 50-247 G 50-249 G	Pappab, H. Pappab, H. Parent, C. D. Parker, W. G. Parker, W. G.	8010200433 8010270512 8010100231 8010200200* 8010010070*	50-10 H ORG PR ACRB 50-269 G
O'REILLY, J P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J P.	8010160121 8010160130 8010160138 8010160146 8010160150	50-261 Q 50-280 Q 50-369 Q 50-332 Q 50-416 Q	ORTH, W C. ORTLOFF, Ø D. DSANN, E. W. DSANN, E. W DBANN, E. W	8010240562# 8010020713 8010160787 8010200589 8010210776	50-249 G 40-8102 50-367 G 50-367 O 50-367 O	PARKER, W. O.	8010010204* 8010270580 9010300385* 8010310025* 8010030476*	50-413 0 70-2623 50-369 0 50-413 9 50-369 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT CATEGORY	′	ROHTUA	ACCEBBION	SUBJECT CATEODRY
KER, W O KER, W O KER, W O KER, W D KER, W O	8010010197* 8010030491* 8010160699 8010010038* 8010010014	50-413 Q 50-369 Q PR 50-413 Q 50-369 Q	PATE, R. J PATON, H. PATON, H. D PATON, H. D PATON, H. D	8010020137# 8010020041 8010030127 8010040013 8010070409	50-329 50-329 50-329	9 9 9 0	PETRICK, N A PETRICK, N A PETRICK, N A PETRICK, N A PETRONE, C D	8010010844 8010140410 8010080555 8010270208+ 8010240124+	50-482 0 PR 50-492 8 50-492 8 50-322 0
KER.W O KER.W O KER.W O KER.W O	8010020762 8010090203 8010170204 8010080449 8010130275	50-349 0 50-249 0 50-249 0 50-349 0 50-269 0	PATON, W D	8010140508 8010150017 8010150066 8010270503 8010300038	50-329 50-329 50-329	0 0 0	PETTERSON, G R PETTIT. 8 PFAFF, S J PFAFF, S J PFAFF, S J	8010170380* 8010160547 8010160653* 8010140624 8010220117	CONTRACT 50-139 J 40-6659 40-6659 40-6659
KER, H D KER, H D KER, H D KER, H D KER, H D	8010080197 8010150314 8010100219 8010140023 8010010538	50~369 G 50~269 G 50~369 G 50~413 G 50~269 G	PATON, W D PATON, W D PATTARINI PATTERSON, J P PATTEN, T W	8010300042 8010300062 8010240563 8010010173* 8010070250*	90-329 50-341	0 0 8 0	PFAHLER, R O, PHILLIP, O PHILLIP, O A PHILLIPS, M P PHILLIPS, M P	8010040136 8010100363 8010100414 8010080218* 8010220125*	PR 50-341 8 50-546 8 50-358 0 40-2384
KER, NO KER, NO KER, NO KER, NO.	8010140041 8010010608 8010030459 8010060281 8010290169	50~269 Q 50~269 F 50~369 B 50~413 B 71~5939	PATTERSON, J D PATTERSON, T L PATTERSON, J P PATTI, P J PATMARDHAN, A 8	B010240521 B010200402+ B0102703B9+ B010210011 B010240274	50-155 PR	R G P	PHILLIPS, J PIAZZA, R P PIEHL, R H PIERBON, G H PIERBON, G H	8010200174 8010210012 8010210671* 8010070539 8010150647	50-275 0 PR 50-315 8 40-4492 40-4492
RKER, H O RKER, W O RKER, W O RKER, W O RKER, W D	8010150454 8010070405 8010210745 8010240156 8010240335	50~369 Q 50~269 P PR 50~413 Q 50~413 Q	PAUL: R. A. PAUL: R. A. PAUL: R. A. PAUL: R. A. PAUL: SON: W. A.	8010010501+ 8010200124+ 8010220486+ 8010310547+ 8010280740+	50-151 50-237 50-123	Q Q P Q P	PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8010160093 8010200072 8010220249 8010240323 8010210280*	50-298 Q 50-298 Q 50-298 Q 50-298 Q 50-298 Q
RAER, IF O RXER, IF. O. RKER, IF. O RKER, IF O RKER, IF O	8010280057* 8010240107 8010270427* 8010080443 8010080548	50~370 Q 50~413 Q 50~413 Q 50~269 B 50~369 A	PAULSON, W A PAULSON, W A PAULSON, W A PAULSON, W A PAULSON, W	8010280742* 8010280745* 8010280748* 8010280750* 8010220291	50-219 50-219 50-219	P P P P	PILANT, J H PILANT, J H PILANT, J H PILANT, J H PILANT, J, M	8010210276 8010230065 8010010006* 8010240126 8010130376	50-29B Q 50-29B Q 50-29B Q 50-29B Q 50-29B A
RKER, W O. RXER, W O. RKER, W O RKER, W O.	8010070422 8010070266 8010070387 8010070537 8010270181	50-247 P 50-349 A 50-270 P 50-249 8 50-349 Q	PAULSON, W PAULSON, W A PAULSON, W A PEAK, R F PEAK, R. F.	8010220428 8010230322 8010310484* 8010310240 8010310233	50-219	P Q	PILANT, J H PILANT, J H PILANT, J H PIRTLE, G L PIRTLE, G L	8010240431 8010260327 8010260381 8010160177* 8010230086*	50-298 P 50-298 P 50-298 P 50-409 Q 50-346 Q
WKEW'H O WKEW'H O WKEW'H O WKEW'H O	8010140324 8010150333 8010200525 8010200958 8010230408	50-287 & 50-349 A 50-349 B 50-369 A 50-369 A	PECK, C. C PECK, C. C PECK, C. C PECK, C. C. PECK, D. L,	8009150165* 8010220454 8010080136* 8010080360 8010140243*	40-3392 1&E 70-36 50-315 CONTRACT	8	PIRTLE, O L PISH.M D PLASKON, R E PLASKON, R E PLEABANT, E M	8010270195* 8010310371* 8010030534 8010200675 8010070543	50-155 Q 50-282 F 50-516 Q 50-516 Q 50-289 Q
RKER, H O RKER, H O RXER, H O RKER, H O	8010200430 8010170369 8010170540 8010230459 8010210434	50-369 A 50-369 A 50-269 P 50-369 A 50-269 R	PEDERSEN.K PEIPER.W B PELTIER.I A PELTIER.I A PELTIER.I.A	8009190539* 8010080180* 8010060070 8010090007 8010230075	50-358	F A A	PLEBET, M. 8 PLEBET, M. 8 PLEBET, M. 8 PLEBET, M. 8 PLETTHAN, 8	8010170024* 8010230123 8010140574 8010310325 8010010007	ACRS ACRS ACRS ACRS 50-466 0
RKER.W O RKER.W O RKER.W O RKER.W O RKER.W O	B010210541 B010230404 B010210534 B010210551 B010240397	50-413 R 50-267 P 50-270 8 50-269 8 50-270 P	PELTIER, I.A PENCE, W.B. PENDERGRAFT, R PENDERGRAFT, R PEOPLES, D.L.	8010270314 8010030397* 8010070577* 8010210428* 8005220571	50-317 50-368	A 8 8 R	PLUMLEE, K E PLUMLEE, K PLUMLEE, K E POCHAL, W F. POCHAL, W F	8010230570* 8010160380 8010270040 8010270137 8010310610	50-146 0 50-217 8 50-272 8 XPORTLIC XPORTLIC
ARKER, W O ARKER, W O, ARKER, W O ARKER, W O ARKER, W O	8010240412 B010240475 B010270348 B010280384 B010310405	50-269 P 50-270 B 50-369 J 50-270 B 50-269 P	Perlman, J Perlman, J. Perlman, J Perlman, J Perlman, J.	8010080315± 8010030440+ 8010030545± 8010210138* 8010080305*	50-205 CONTRACT CONTRACT CONTRACT CONTRACT	P	POCHALIN F PODONSKY, Q POGOID, A POINDEXTER, T C POIRIER, H R	8010310614 8010150171 8010220651 8010100415 8010150024	XPDRTLIC NURED RES 50~320 B 50~445 M
ARKER, W O ARR, R O ARBONE, C H. ARTLOW, J O. ARTLOW, J O	8010310438 8010010268* 8010240570* 8010150580 8010100272	50-369 A CONTRACT 50-320 P 70-1113 70-27	Perlman, J. Perlman, J. Perlman, J. Perlman, J. Perlman, J.	8010080350+ 8010140449+ 8010140574+ 8010140527+ 8010150649+	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		POIRIER, M R POIRIER, M R POLICASTRO, A J POLLARD, R D POELARD, R. D	8010170385 8010200387 8010170078 8010070011 8010070015	50~445 M 50~445 M NUREO 50~287 O 50~287 O
ARTLON.J O ARTLON.J.O. ARTLON.J.O ARTLON.J O. ARTLON.J O.	8010200133 8010080119 8010080132 8010020046 8010230250	70-135 70-27 70-371 70-820 70-143	PERLMAN, J FERLMAN, J. PERROTTI, D. PERROTTI, D. J PERROTTI, D. J	8010200080* 8010200329* 8010310566 8010160703 8010270416*		s Q	POLLARD, R D POLLARD, R D POLLOCK, R P. POOLE, D C PORT, E A	8010100353 8010160013 8010100008 8010280569 8010200270	50-458 A 50-289 T FOIA 50-302 G 40-2061
ARTLOW, J. C., ABEDAG, W. F ABBERD, R. P. ASTERNAK, R. J. ABTERNAK, R. J.	8010230423 8010290162* 8010140166* 8010010815 8010010644	70-143 50-155 H CONTRACT 50-333 Q 50-333 Q	PERRY, J C. PERRY, J, C PERRY, J C PERBON, L PETERMAN, P C	8010090344* 8010210707* 8010210748* 8010030338 8010270093*	50~344 44E~08 TOART/00	8 6 6	PORTER, W. L PORTER, W. L PORTER, W. L PORTER, W. L PORTER, W. L	8010020054* 8010020042 8010020050* 8010060002 8010070553	50-369 0 50-369 0 50-369 0 50-369 0
'ASTERNAK, R. J. 'ASTERNAK, R. J 'ASTERNAK, R. J 'ASTERNAK, R. J. 'ASTERNAK, R. J.	8010010679 8010020308 8010220668* 8010010740 8010220027	50-333 0 50-333 0 50-333 0 50-333 0	PETERBON: M R PETERBON: M R PETERBON: M R. PETERBON: M. R PETERBON: M. R	8010010245 8010010315 8010010425 8010080077 8010010243	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		PORTER, W. L. PORTER, W. L. PORTER, W. L. PORTER, W. L. POST, R	8010210772 8010210777 8010240552 8010310306 8010020665	50-369 0 50-369 0 50-269 0 50-269 0 FOIA
'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ASTERNAK, R. J.	8010230514 8010070524 8010040333 8010240002 8010100290	71-6244 50-333 P 50-333 B 71-5026 50-333 R	PETERBON, M R	B010010137 B0100B0085 B010170442 B010220276 B010070486	YPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		POTAMI, A.R POTAPOVS, U POTAPOVS, U. POTAPOVS, U POTAPOVS, U	8010070061* 8010210763* 8010210752* 8010080189* 8010080073	Contract Gasss Gasss Gasss Gasss Gasss
'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ASTERNAK, R. J. 'ATCHES, S	8010310017 8010200587 8010210670 8010280419 8010180396	50-333 6 50-333 8 50-333 8 50-333 8	PETERBON. J. M PETERKA: J. A PETERBEN: H E. PETRICK: N A PETRICK: N A	8010270253 8010230035 8010280559 8010020189 8010010835	50~482	ე დ	POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U. POTAPOVB. U.	8010160663# 8010270101 8010210248# 8010220589 8010080157#	QA999 QA999 71-9014 71-9001 QA999

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUDJECT CATEGORY
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8010210457 8010080063 8010080104 8010240014 8010270573	0A999 0A999 0A999	RANDOLPH, J M RANDOLPH, J RANDOLPH, J H RANDOLPH, J K RANDOLPH, J K	8010040280* 8010100334* 8010100348* 8010200592* 8010270377*	50-272 8 50-311 8 50-272 8	REID, R W REID, R W REID, R W REID, R W, REID, R W	8010210087 8010210090* 8010210099* 8010210201 8010210207*	50-346 F 50-346 F 50-346 F 50-321 F 50-321 P
POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U. POTAPOVS. U	80102807286 80102705596 8010240573 8010270009 8010210451		RABIN, H H RASKIN, D D RASKIN, D B RASKIN, D B RASKIN, D B	8010020062* 8010060301 8010060301 8010160784 8010160784	50-367 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q	REID, R W REID, R W REID, R W REID, R, W REID, R W	8010210212# 8010210040 8010210044# 8010210054# 8010270255	50-321 P 50-249 P 50-249 P 50-249 P 50-249 P
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8010080148 8010080175 8010210599 8010210239 8010240020*	0A999 0A999 0A999 71-9016 0A999	RASKIN, D B RATHLESBERGER RATKOPF, C L RAUSCH, J K RAUSCH, J K	8010240427 8010300002 8010300430* 8010080446 8010010057*	50-49B 0 PR 50-275 H 50-400 S 50-416 Q	REID,R W REID,R W REID,R W REID,R W REID,R W	8010270260 8010270320 8010280479 8010200209* 8010200230*	50-312 F 50-277 F 50-147 J 50-209 T 50-209 T
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8010160288 8010270121* 8010270368 8010280722	0A797 0A799 0A799 0A799 0A799	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, H P RAVENSCROFT, N	8010080600 8010020454 8010220139 8010280204 8010240455	50-275 Q 50-373 K 50-237 Q TOPREP XPORTLIC	REIMANN, F REIMANN, F W REIMANN, F W REIMANN, F W REIN, J E	8009030035 8009080200 8010090136 8010090262 8010080671	50-255 B 50-249 B 50-10 B 50-10 B NUMEO
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTASH, L M POTTER, J, P	8010240018 8010270554 8010270112 8010150140 8003240287*	GA979 GA979 GA979 RES 50-160 Q	RAYBURN, C L RAYMOND, H J RAYMOND, H J RAYMOND, H J READ, J B J	8010210694* 8010240278* 8010080563 8010270043 8010070588*	50-317 B 50-271 Q 50-271 B 50-271 B 50-466 Q	REIB.E J REIB.E J REITER.L REITLER.E K REITLER.E X	8010280010 8010280621 8010210286 8008210614* 8008210615*	27-39 27-39 50-361 0 71-6400 71-6400
POTTER, J P	8004080147* 8005120230* 8004040082* 8010100438* 8010100441*	50-250 G 50-259 G 50-10 Q 50-277 G 50-277 G	REAMER,C W REAVEB,T E REAVIB.J A REBELOWBKI,T REBELOWBKI,T	8010310198 8010210456 8010210437* 8010010352* 8010210302*	FOIA TOPREP 50-249 R 50-286 G 50-286 G	REIZEN,M B REKEMEYER,P C. REMAKLUB,L REMLEY,M E REMLEY,M,E	8010210105# 8010270308 8010010632# 8010220212 8010220220#	CONTRACT 40-299 50-232
POTTER, J POTTER, J POTTER, J P POTTER, J P POTTER, J P.	8010160680 8010170016 8010280274* 8010290410* 8010300179*	50-333 8 50-327 8 50-261 0 70-27 50-335 0	REBELOWSKI,T REBELOWSKI,T E REED, J O REED,C	8010240148* 8010240133* 8010070465 8010070048 8010070430	50-247 Q 50-247 G 50-483 Q 50-483 O 50-10 P	REMLEY, M E. REMLEY, M. E. RENBERGER, D L. RENBERGER, D L. RENBERGER, D L.	8010130358 8010020074 8010270035 8010280610 8010280625	70-25 71-3008 50-308 q 50-377 q 50-508 q
POTTER, J P POTTER, J P PREISTER, D. PRICE, D B PRICE, J E	8010300369* 8010310048* 8010010007 8010240012* 8010310169*	50-280 Q 70-1151 50-466 Q 50-321 Q 50-324 Q	REED.J O REED.C REED.J O REED.J O	8010090045 8010070009* 8010310267* 8010290387 8010290405	50-483 0 50-466 0 50-237 0 50-483 0	RENBERGER, D. L.	8010100146 8010280618 8010070083 8010080576 8010080106	REGOD 50-440 0 50-440 0 50-397 0 PR
PRIOR, JE PROXHIRE, W PRIYBYLA, L J. PUGILLO, A C PURPLE, R A	8010310179* 8010020424* 8010240340 8010010279* 8010030107*	50-324 Q 50-266 0 Nureo Contract 50-287 0	REED.C REEVEB.E A REEVEB.E A REEVEB.E REEVEB.E A	8010310280 8010090460 8010090281 8010090552 8010270300	50-295 P 50-348 F 50-295 P 50-295 P 50-295 P	RENBERGER.D L. RENBERGER.D L RENBERGER.D L RENBERGER.D L. RENBERGER.D L.	8010080573 8010080639 8010080646 8010310030* 8010270374	50-460 0 50-397 0 50-397 0 50-397 0 50-390 0
PURPLE.R A GUAPP, W J GUICK, D GUICK, D R GUICK, D R	8010230116* 8010040150 8010140798 8007080194 8010150053*	50-344 0 PR 50-348 8 50-83 8 50-335 Q	REHM.TA REHM.TA REHM.TA REHM.TA REHM.TA	8010230082 8010060080 8010150217 8010230274 8010280049	COMMISSION COMMISSION COMMISSION COMMISSION	RENBERGER, D. L.	8010280694 8010300694 8010240547 8010310012* 8010080425	50-509 4 50-440 8 PR 50-509 4 50-097 A
GUICK, D R GUICK, D R GUICK, D R GUICK, T H	8010240249* 8010240453* 8010270049* 8010270193* 8010170133	50-375 Q 50-261 Q 50-261 Q 50-395 Q 40-8743	REH1,T A REICHHOLD,W P REID,A B REID,R W REID,R W	8010300275 8010060038 8010270003 8010220227 8010020060	COMMISSION I&E 40-1341 50-289 P 50-269 P	RENDERGER, D. L. RENDERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L.	8010310080 8010090484 8010180380 8010210379 8010170120	50-508 0 50-347 A 50-508 A 50-347 C
GUIGLEY, T H GUIGLEY, T H GUILLIN, R H	8010210014 8010240327 8010070064* 8010240039 8010100346	40-8743 40-8743 CONTRACT 40-8743 50-346 H	REID, R W REID, R W REID, R W REID, R W REID, R W	8010020064* 8010030019 8010030022* 8010030025* 8010010058	50-269 P 50-289 P 50-289 P 50-289 P 50-302 P	RENBERGER, D. L. RENBERGER, D. L. RESNIKOFF, M. REVELEY, W. T.	8010270393 8010280486 8010280510 8010070483 8010010121	NUREO 50-397 6 50-397 K 50-201 P
RADER, R M RADER, R M RADER, R, M RADER, R, M	8010140547 8010140547 8010220508 8010220515 8010220520	27-39 27-39 27-39 27-39 27-39	REID, R. W REID, R. W REID, R. W. REID, R. W. REID, R. W.	8010010106* 8010010114* 8010060147 8010080155 8010080161*	50-302 P 50-302 P 50-277 P 50-277 P 50-277 P	REVELEY, H T, REVELEY, H T, REVELEY, H T, REVELEY, H T, REVELEY, H T,	8010010127* 8010010127* 8010010127* 8010160762* 8010160762*	PRM PRM PRM 50~514 0
RADER, R. H RADER, R. H. RADER, R. K RADER, R. K RAGE, R. O	B010220508 B010220515 B010220520 B010230424 B010140153	27-39 27-39 27-39 27-39 70-143	REID, R W REID, R W REID, R W REID, R W	8010080173* 8010080179 8010080604 8010090529 8010090534*	50-277 P 50-346 P 50-277 P 50-302 P 50-302 P	REVELEY, W T. REVELEY, W T REVELEY, W T REYEB, L. REYEB, L.	8010160527* 8010160754 8010160754 8007080216 8010080347	50-322 0 50-516 9 50-516 9 50-514 8 50-346 8
RAGER.M S. RAGER.M S RAGER.M S RAGER.M.S RAGER.M S	8010150480* 8010150483* 8010150431* 8010150467* 8010150499*	50-331 8 50-331 8 50-331 8 50-331 8 50-331 8	REID,R W REID,R W REID,R H. REID,R H.	8010090540* 8010220225 8010220400 8010100345 8010100370*	50-302 P 50-312 P 50-312 P 50-302 P 50-302 P	REYMANN, O A, REYNOLDB, W, REYNOLDB, B, REYNOLDB, B D REYNOLDB, N, B	8010300161 8010310212* 8010010372* 8010100074* 8010240504	RES FOIA 50-423 9 50-352 9
RAGER, M. B RAMOS, B. L RANDALL, W. B RANDAZZO, A. F. RANDALL, W. B	8010220472* 8010220160 8010220160* 8010220234* 8010270361*	50-331 8 NUREO 50-320 P CONTRACT 50-320 P	REID,R W REID,R W, REID,R W REID,R W REID,R W,	8010100372* 8010140157 8010160120 8010220086 8010220356*	50-302 P 50-312 P 50-289 H 50-289 H 50-289 H	REYNOLDS, N. S REYNOLDS, N. S, REYNOLDS, N. S, REYNOLDS, N. S, REYNOLDS, N. S,	8010020729 8010080263 8010080263 8010130002 8010130002	50-445 0 50-445 0 50-445 0 PR
RANDOLPH, U L RANDOLPH, J M RANDOLPH, J M RANDOLPH, J, M RANDOLPH, J, M	8010280597 8010030454+ 8010060234+ 8010060287+ 8010060295+	RES 50-272 S 50-311 S 50-272 B 50-272 S	REID, R. W. REID, R W REID, R W REID, R W REID, R. W.	8010160745 8010160751* 8010160757* 8010200024 8010200045	50-346 P 50-346 P 50-346 P 50-147 W 50-277 P	REYNOLDS, J R REYNOLDS, J R REYNOLDS, N B REYNOLDS, N S.	8010220554 8010220554 8010200174 8010210503 8010210503	50~275 0 50~275 0 50~275 0 50~445 0 50~445 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHGR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEODRY
REYNOLDS, N S. RHOADES, H J	8010280472 8010310436 8010310436 8010310432 8010300618	50-313	ROSS.D K ROSS.D F ROSS.D F ROSS.D K ROSS.N J	8010100224 8010030543 8010030527 8010230596 8010070116	PR CONTRACT MISC PR SO-334 A	BALZMAN, R 8 GANDERS, W SANDERS, W L GANTMAN, L D BANTMAN, L D	8010300037 8010100021* 8010210491 8010010282* 8010020255*	50-275 T 50-289 Q 50-443 Q CONTRACT
RHODE, O K RHODE, O K RHODE, O K RHODE, O K RHODE, O K	8010010794 8010010850 8010020317 8010200403 8010100249	50-410 Q 50-410 Q 50-410 Q 50-410 Q 50-410 S	ROSS, W J ROSTOHEKI, J ROSTOHEKI, J ROTH, T	8010300475 8010300619 8010090432* 8010070632* 8010100118*	50-272 Q 50-272 P 50-254 P 50-289 Q 50-305 H	BANTMAN, L D BANTORD, M P BANTBAVER, P. BARBOUR, B BAUNDERS, B L	8010020716* 8010100265* 8010210147 8010150323* 8010080637	CONTRACT 40-6920 REGOD 50-346 R 50-250 Q
RHODE, 0 K. RHODE, 0 K RHOE, 0. B RICE, L RICE, W. M.	8010070460 8010160492 8010160635 8010100420 8010210006	50-410 A 50-410 B PR PR 50-498 B	NOTH; J ROTH; J ROTH; J ROTH; J	8010210264* 8010210167* 8010020223* 8010230148* 8010160357	70-135 70-162 70-364 70-820 50-201 5	BAVINI, F SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A	8010200261* 8010150135 8010210697 8010060095 8010140149	50-320 H 40-8084 40-3453 40-8584 40-3453
RICHARDSON, J.R.	8010070281	NUREO	ROTH, A. J	8010150392	50-389 M	Scarand, R A	8010050098	HASTE HOT
RICHARDSON, S.D.	8010200342	REGOD	ROTH: J.	8010240370	70-364	Scarand, R A	8010270074	HASTE HOT
RIDOWAY, K.R.	8010070293	50-255 S	ROTHE: R E	8010080372	NUREO	Scarand, R A	8010150159	40-1341
RIDOWAY, K.R.	8010010857*	50-409 Q	ROTHFLEISCH: J	8010170114	40-8771	Scarand, R A	8010050060	WASTE MOT
RIDOWAY, K.R.	8010070283	50-255 8	ROTHFLEISCH: J	8010060089	40-8745	Scarand, R A	8010220301	40-299
RIDONAY, K R	8010080250*	50-294 Q	ROTHFLEISCH, J	8010240138	40-8714	SCARAND, R. A	8010240015	40-8714
RIDONAY, K R.	8010310585*	50-114 Q	ROTHFLEISCH, J	8010230339	40-8692	SCARAND, R. A	8010270344	40-8502
RIEGER, P. E	8010270008*	CONTRACT	ROTHSCHILD, K V	8010230370*	50-336 S	SCARAND, R. A	8010220275	40-8434
RIEGER, J.	8010240374	50-438 J	ROTHSCHILD, K V	8005140419	50-445 O	SCARAND, R. A,	8010220278*	40-8434
RIGBERO S	8010140045	50-358 H	ROTHSCHILD, K V	8005140440*	50-445 O	SCARAND, R. A	8010220303	40-8727
RICEY, R W	8010100430	PR	ROTHSCHILD, H V	8010070562	50-445 Q	BCARAND, R. A	8010240013	40-1162
RILEY, J L	8010140587	50-247 0	ROTHSCHILD, H V.	8010140515	50-445 Q	BCHAEFFER, K R	8010240468	XPORTLIC
RILEY, J L.	8010230492	50-347 0	ROTHSCHILD, H V	8010150008	50-445 Q	BCHAPKER, J F	8010010620*	50-454 G
RIPPLE, R.	8010070022	NUREO	ROTHSCHILD, H V	8010220314	50-445 Q	BCHAUB, L. J	8010300505	ORO
RIPPLE, R	8010070026*	NUREO	ROTHSCHILD, H V	8010240059	50-445 Q	BCHERR, J	8010090042	FOIA
R 1 PPLE.R.	8010070027*	NUREO	ROTHSCHILD, K U	8010280478	50-445 Q	SCHERER, A E	8010170226	PR
R EGINO.B. A	8010210112	70-162	ROTHSCHILD, M U	8010300033	50-445 H	SCHERR, S J	8010160027	50-437 0
R ETTENHOUSE.P.	8010040020	NUREO	ROTHSCHILD, M U	8010310487	70-1308	SCHERR, B. J	8010160032	50-237 0
R EVENBARK.Q. H.	8010240133*	50-247 Q	ROUSE, L C	8010040115	50-564 A	SCHERER, A. E	8010280587	NUREO
R EVENBARK.Q. H.	8010210281*	50-364 A	ROUSE, L C	8010070644	50-201 P	SCHLIGHT, F O	8010140602*	50-466 0
R1220,P	8010060261*	50-318 8	ROUSE, L C.	8010080272*	70-1257	SCHMIDT, A.D.	8010070466	50-335 S
	8010060273*	50-318 8	ROUSE, L C	8010130620	70-1257	SCHMIDT, A.D.	8010070431	50-335 B
	8010060313*	50-317 8	ROUSE, L C	8010240543	70-25	SCHMIDT, A.D.	8010070443	50-335 S
	8010200434*	50-318 8	ROWE, J	8010280033*	50-289 H	SCHMIDT, A.D.	8010070420	50-335 S
	8010210672*	50-318 8	ROWE, C.	8010060132	I&E	SCHMIDT, A.D.	8010080207	50-335 S
RTZZG, P. O.	8010240426*	50-317 B	ROHE, C.A. ROWE, C.A ROWLEY, C.W ROWLEY, E. ROWLEY, E.	8010140608*	FOIA	SCHMIDT, A D	8010090470	50-335 8
RTZZG, P. O	8010310315*	50-318 B		8010100072*	70-1703	SCHMIDT, A C	8010010556	50-445 A
REZZG, P. O.	8010310357*	50-317 B		8010060144	PR	SCHMIDT, A D	8010020034	50-347 9
ROBATEL, M	8010210243*	71-9016		8010140494*	50-237 6	SCHMIDT, A D	8010100319	50-335 8
ROBERTS, K.	8010080530	50-293 B		8010140247	50-346 P	SCHMIDT, A D	8010100326	50-335 8
ROBERDS, H. W. ROBERDS, H. W. ROBERTS, E. W. ROBERTS, J. O. ROBERTS, L. B.	8010210463* 8010080068* 8010300202 8010070523* 8010240591	QA999 QA999 50-289 P 50-466 Q 50-369 8	ROWSOME, F H RUDDEN, M A RUDDLPH, R L. RUDZINSKI, M RUHLMAN, W A	8010200216* 8010070141* 8010290321 8010220484 8010240012*	50-287 T CDNTRACT 50-320 P PR 50-321 G	SCHMIDT, A. D. BCHMIDT, A. D. BCHMIDT, A. D. BCHMIDT, A. D. BCHMIDT, A. D.	8010100329 8010040264 8010100316 8010100313 8010100311	50-335 8 50-445 C 50-335 8 50-335 8 50-335 8
ROBINSON, J.K.	8010230715*	50-338 H	RUHLMAN.W.A	8010310199#	50-302 Q	SCHMIDT, A D	8010100339	50-335 8
ROBINSON, F. T.	8010270005*	CONTRACT	RUOCCHIO,J	8010170566#	CONTRACT	SCHMIDT, A D	8010190338	50-250 R
ROBSON, L. E.	8010210064*	CONTRACT	RUSSELL.M L	8010010802	RES	SCHMIDT, A D	8010280686	50-250 8
ROBRIGUEZ, R. J.	8010150274	50-312 R	RUSSELL.L.B	8010160207	50-317 S	SCHMIDT, A D	8010310375	50-250 8
ROGERB, R. F.	8010140013*	50-321 Q	RUSSELL.L.B	8010030398	50-317 S	SCHMIDT, A D	8010310428	50-250 8
Rogers, T. R.	8010150609*	CGNTRACT	RVSSELL,L B.	8010060252	50-318 8	GCHMIDT, A D	8010310435	50-250 8
Rogers, W. H	8010220489*	50-366 B	RVSSELL,L B.	8010060265	50-318 8	GCHNEIDER, F. W.	8010010609#	50-272 0
Rohand, F. R	8010280070*	50-352 H	RVSSELL,L B.	8010060311	50-317 8	BCHWEIDER, F W	8010100061#	50-272 0
Rohan, T. H	8010150406*	50-220 R	RVSSELL,L B	8010140372	50-317 8	BCHNEIDER, F W	8010240368	50-272 0
Ronvik, A.	8010230381	50-367 0	RVSSELL,L B	8010160567	50-318 8	BCHNEIDER, F W	8010020285	50-272 0
8000.H	8010020022	50-361 A	RUSSELL, L. B.	8010200432	50-318 8	BCHNEIDER, F. U	8010010826	50-272
8000.H	8010210274	50-361 A	RUSSELL, L. B.	8010200432	50-318 8	BCHNEIDER, F. U	8010230276#	
8000.H	8010170145	50-361 F	RUSSELL, L. B	8010210666	50-318 8	BCHNEIDER, F. U	8010230640	
8000.H	8010210734	50-361 F	RUSSELL, L. B	8010210476	50-317 8	BCHNEIDER, F. U	8010230200	
8000.H	8010300151	50-361 A	RUSSELL, L. B	8010240421	50-317 8	BCHNEIDER, F. U	8010210475#	
ROOD.H. ROONEY,H.A ROONEY,H.A ROONEY,H.A. ROONEY,K.A.	8010210284	50-341 0	RUGSELL, L. B.	8010280571	50-317 8	BCHRDEDER.F	8010160773	ORO
	8010150570	70-1308	RUGSELL, L. B.	8010310320	50-317 8	BCHRDCK.C A	8010140328	50-305 P
	8010170359	70-1308	RUSSELL, L. B.	8010310310	50-318 8	BCHRDEDER.F	8010270144	Nureo
	8010170359	70-1308	RUBSELL, L. B.	8010310330	50-317 8	BCHRDEDER.F	8010300485	Nureo
	8010210582	70-1308	RUTLEDOE, C	8010310253	REGOD	BCHVEBBLER.W J	8010090074	50-464 Q
ROOT, E. E.	8010020591#	CONTRACT	RYAN, C	8010270034	FOIA	SCHUESSLER, W J	8010240570	50-466
ROOT, E. D.	8010030407	50-331 P	RYAN, R. C	8010270130	State Prog	SCHULER, T R	8007140552*	
ROOT, L. D	8010150317	50-331 P	RYAN, J. F	8010300158*	CONTRACT	SCHULER, T R	8007140570*	
ROOT, L. D.	8010270063#	50-289 H	BABELKO, E	801020501	50-409 H	SCHULTZ, W. H	8010030540	
ROOT, L. D.	8010240220	50-331 P	BACKEIM, H	8010240623*	50-320 P	SCHULER, T. R	8007140567*	
ROOT, L D	8010300480	50-331 P	SAGENDORF.J F	8010230019	NUREO	SCHULTZ, W B	8010160592	PRN
ROOCHYNSKY, M	8010130501*	50-237 S	SAGLE.O W	8010270052	REGOD	SCHULTZ, W, H	8010060048	1&E
ROREH, B L.	8010300084	70-1308	BAIKI.T.	8010160219*	XPORTLIC	SCHULTZ, W H	8010220449	1&E
ROSENTHAL, A S.	8010270170*	50-477 A	SAIKI.T	8010020659	XPORTLIC	SCHULTZ, O R,	8010270214	50-320 P
ROSENTHAL, A S.	8010270142*	50-568 A	SALDARINI.J.C	8010240514	PR	SCHULTZ, W, B	8010020047	50-367 Q
Rosenthal, A. B.	8005140447*	50-445 0	SALDARINI. J C	8010290134	RE00D	BCHULTZ, W. B.	8010020059*	50-367 0
Rosenthal, A. B.	8010230381	50-407 0	SALDARINI. J. C	8010230511	PR	BCHULTZ, W. B.	8010020047	50-367 0
Rose, P.	8010210638*	State Prog	SALTZMAN. J	8010240532*	50-193 J	BCHULTZ, W. B	8010020055*	50-367 0
Rose, D. A.	8010240338*	50-217 0	SALTZMAN. J	8010230002	50-94 J	BCHULTZ, O. R.	8010270510	50-387 0
Rose, D. F.	8010090195	50-269 P	SALTZMAN. J.	8010310547	50-34B J	BCHUMACHER, M. C	8010220486*	50-237 F

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	r	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
D LIVERT O C C. RELIVENCE O C C. RELIVENCE O C C. RELIVENCE O C C C C C C C C C C C C C C C C C C	8010200435 8010220118 8010270270 9010300477 8008060283	PR + 50-155 NUREO	P S	SEYFRIT, K, V SEYFRIT, K, V, SEYFRIT, K, V SEYFRIT, K, V SEYFRIT, K, V,	8010310052 8009100349 8009100370 8009100371 8009100373	40-8084 70-2896 70-2185 70-1363 70-1406	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8010240402 8010240409 8010240457 8010240414 8010270365	50-546 \$ 50-546 \$ 50-546 \$ 50-546 \$ 50-546 \$
BCHNENCER, A BCHNENCER, A BCHNENCER, A BCHNEIMER, R BCHNEMCER, A	8010270245 8010010411 8010170249 8010270529 8010240575	50-275 50-327 50-320	ዘ ዘ P P	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8010230703 8010230703 8010300014 8010300025 8010270420	70-2560 50-258 F 50-267 Q 50-313 Q 50-265 Q	Shields, S. W Shima, S. Shima, S. Shima, S Shima, S.	8010270367 8010080032 8010080035* 8010080307 8010080312*	50-546 B XPORTLIC XPORTLIC XPORTLIC XPORTLIC
SCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A SCHWENCER, A	8010220069 8010070246 8010070248 8010140548 8010170210	50-461 50-461 50-364	H A A E H	SEYFRIT, K V SEYFRIT, K, V SEYFRIT, K, V SEYFRIT, K, V, SEYFRIT, K, V	8010270424 8010160089 8010160093 8010160097 8010160101	50-313	Shima, 8 Shima, 8. Shimeflug, M Shipway, 9. Shisbias, J. A	8010160246 8010160247* 8010210342 8010280648* 8010210648	XPORTL1C XPORTL1C 50-10 H 50-313 F 50-272 P
SCHMENCER, A BCHMENCER, A SCHMENSFEIR, R BCHMENSFEIR, R BCHMENSFEIR, R	8010270247 8010290247 8010210567 8010210480 8010280524	60-382 / 50-327 / 70-33 70-33 70-33	A P	SEYFRIT.K V, BEYFRIT.K V BEYFRIT.K V BEYFRIT.K V BEYFRIT.K V	8010140104 8010140107 8010140113 8010140117 8010270518	50-492 Q 50-498 Q 50-392 Q 50-298 Q 50-498 Q	BHIBBIAB, J A BHIVELY, C, N BHIVELY, R, P, BHIVELY, C, N BHIVELY, C	8010270334 8010070625* 8010060195 8010070423* 8010070384*	50-272 P 50-313 S PR 50-313 S 50-368 S
SCHWENSFEIR,R SCOTT,D.J SCOTT,D.J. SCOTT,D.J. SCOTT,J	8010280532* 8010070535 8010070603 8010270380 8010240358	50-237 6 50-249 6	8 9 8	BEYFRIT, K V BEYFRIT, K, V BEYFRIT, K, V, SEYFRIT, K, V, BEYFRIT, K, V,	8010270520 8010270523 8010270525 8010270527 8010230139	50-482 Q 50-458 Q 50-382 Q 50-445 Q 50-448 Q	SHIVELY, C N	8010070543* 8010070622* 8010070549* 8010070582* 8010280536*	50-348 8 50-349 8 50-313 8 50-313 8 50-313 8
BCOTT.D J BCOTT.D J BCOTT.D J BCOTT.J,H	8010140489 8010100066 8010150494 8010150506 8010160016	50-237 6 50-466 6 50-237 6 50-237 6 50-2466 6	3	BEYFRIT, K. V. SHAFER, W. D SHALLER, D. V SHALLER, D. V	8010270535 8010170050* 8010070424* 8010080403 8010070356	50-278 Q 50-312 Q 50-344 Q 50-315 B 50-316 B	SHIVELY, C N SHOLLY, S C. SHON, F. J SHORS, E, M SHREVE, D. S.	8010080430* 8010160763 8010310447 8010370355 8010170400*	50-348 8 50-289 0 50-272 0 50-367 A
BCOTT, D. J. BCOTT, D. J. BCOTT, D. J. BCOTT, J.	8010210520 8010210455 8010210440 8010280448 8010240404	50-237 8 50-237 8 50-10 R 50-237 8 50-466 H	l l	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V SHALLER, D. V SHALLER, D. V	8010070367 8010200407 8010200412 8010210664 8010300447	50-315 8 50-316 R 50-315 R 50-315 8 50-315 8	BHUM, E. Y. BHUM, E. Y. BHUM, E. Y. BHUM, E. Y. BILBERO, J. E	9010070278 8010230134 8010270224 80103300546 8010140502	70-1113 70-1257 70-1257 70-1257 50-387
BEAL: M M BEAL: M M BEAL: M M, BEALE: R: L BEAMAN, W H	6010270073* 6010270083* 8010220367* 6010200659 6010160003	50-320 H 50-320 H 50-287 H 50-327 Q 50-206 P		BHANDAKY, M. SHANDAKY, M. K BHAPAKER, J BHAPAR, H. K BHAPAR, H. K.	8010300337* 8010150511* 8010300510* 8009100243 8010170351	50-320 Q 50-320 B ORO SECY 50-443 O	BILBERO, J E BILBERO, J E BILBERO, J E BILBERO, J E BILBERO, J, E,	8010140502 8010300606 8010300561 8010300561 8010300606	50-387 9 50-387 9 50-387 9 50-387 9
BEAMAN, Q Q, BEELEY, Q T BEIDLE, H, C, BEIDLE, H, C, BEIDLE, H, C,	8010300005 8010210713 8010020181 8010160024 8010020186	REGOD PR 50-445 Q 50-462 Q 50-445 Q		SHAPAR, H K. SHATTERLY, L. W. SHAUS, E. T. SHEA, J R SHEA, J R	B010210774 8010060071 8010010100* 6010210189* 8010090456	50-275 Q 1&E 50-245 Q FOIA XPORTLIC	SILBERO, J. E. BILBERO, J. E. BILBERO, J. E BILBERO, J. E BILVERIO, N T	8010300613 100000108 1000000606 110000613 8010100293*	50-387 9 50-387 9 50-387 0 50-387 0 50-272 F
SEIDLE, H. C SEIDLE, H. C SEIDLE, H. C SEIDLE, N. C.	8010270021 8010270027 8010270024 8010090337 8010060146	50-462 Q 50-382 Q 50-382 Q 50-445 Q 50-482 Q		BHEA, J.R. BHEA, J.R. BHEA, J.R. BHEA, J.R. BHEA, J.R.	8010010698 8010090541 8010140140 8010280492 8010240027	XPORTLIC BECY XPORTLIC BECY XPORTLIC	BILVER, C. R. BILVER, H. BILVER, H. BIMONETTI, O. BIMONETTI, O.	8010080114 8010040092 8010200397 8010300243* 8010240044*	PR 50-289 F 50-289 F 50-272 Q 50-244 Q
BEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C BEIDLE, H.C. BEIKEN, B.J.	8010310535 8010170454 8010170469 8010300432 8010210272	50-458 Q 50-445 Q 50-458 Q 50-458 Q 50-482 Q		SHEA, K. H. SHEA, K. H SHEA, K. H. SHEA, J. R SHEDLOSKY, J. T	8010130433 8010200669 8010200669 8010290193 8010020771*	50-367 Q 50-367 Q 50-367 Q XPORTLIC 50-245 Q	Simonides, C B Sinderbrand, C. Sinoer, L, N Binoer, L, N Binoer, L, N	8010010373* 8010080465 8010140522 8010140527 8010140532	CONTRACT 50-266 0 27-39 50-289 0 50-320 0
BEKULER, 8. N BEKULER, 8. N BEKULER, 8. N BEKULER, 8. N BEKULER, 8. N	8010140548 8010150537 8010150542* 8010150547* 8010150551*	50-482 A 27-39 27-39 27-39 27-39		SHELLEY, W. J. BHELLEY, W. J BHELLEY, W. J.	8010070531 8010160618 8010220241 8010270057 8010310040	70-1173 PR 40-8727 REGOD 40-8768	Binibgalli, A, A, Binke, G, J Binwell, J, F Bklar, J. B, Bklar, J. B,	9010070588* 8010030180 8010150540* 8010210425* 8010240480*	50-444 9 71-9090 90-344 P 50-219 R
BEKULER, B, N. BEKULER, B N. BEKULER, B N BEKULER, B, N. BEKULER, B, N.	8010150554* 8010150562* 8010150567* 8010150569* 8010150577*	27-39 27-39 27-39 27-39 27-39		SHELLEY, N. J. SHELLEY, N. J. SHENEFIELDE, J. H SHEPLEY, B. E.	8010020219 8010210608 8010210620 8010140039* 8010160145*	70-925 40-8027 70-925 8ECY 50-373 Q	BKLAR, J B. BKOLDS, J, L BLOAN, D. E BLOAN, D. E BLOAN, D. E.	8010240485* 8010230143* 8010240344* 8010020615	50-219 R 50-395 0 50-320 0 50-329 8 50-358 8
BEKULER, B, N, BEKULER, B, N, BEKULER, B, N, BEKULER, B, N, BEKULER, B, N,	8010150639 8010160774 8010160777# 8010200184 8010210279	27-39 27-39 27-39 50-367 0 70-1308		SHEPPARD, R. E. SHEPPARD, R. E. SHEPPARD, R. E SHEPPARD, R. E. SHERWOOD, M. R	8010240322* 8010030104* 8010030132* 8010240217* 8010230685	50-289 Q 50-273 Q 50-245 Q 50-133 Q	BLODODIEN, M. BLOTH, E. N. SMEAL, L. P. SMITH, J. R SMITH, R, H.	8010080380 8010060157 8010210455* 8010080401	50-399 8 PR QA999 50-471 A 50-289 Q
BEKULER, B. N. BEKULER, B. N BELKOWITZ, L. B, ELKOWITZ, L. B, ELKOWITZ, L. B.	8010210282 8010230694 8010140560 8010140560 8010140565*	70-1308 50-367 0 50-289 0 50-289 0		SHERWOOD, M. R SHERWOOD, M. R. SHIELDS, W. M. SHIELDS, S. W. SHIELDS, S. W.	8010230685 8010230685 8010220182 8010160683 8010100176	50-133 0 50-133 0 ACRE PR RECOD	Bmith, J. D. Bmith, J. D. Bmith, J. D. Bmith, J. D. Bmith, J. D.	8010140381 8010100408 8010100406 8010090191	50-246 8 50-246 8 50-266 9 50-301 8 50-301 8
ELKOHITZ, L. B. ELLB, D. ELLB, D. ELLB, D. ERABIAN, J. A.	8010140583* 8010170247 8010310521 8010310103 8010020636*	50-287 0 50-352 A 50-352 A 50-352 A 50-213 Q		Shields, S. W. Shields, S. W. Shields, S. W. Shields, S. W. Shields, S. W.	8010150079* 8010070107 8010170206* 8010270207 8010230683*	50~546 8 50~546 Q 50~546 B 50~546 8 50~546 Q	BMITH, Q. SMITH, B. W. SMITH, Q. H. SMITH, Q. H. SMITH, Q.	8010220084* 8010010052* 8010010340* 8010210251*	50-333
SEÑABIAN.J.A. BERABIAN.J.A BEYFRIT,K.V. BEYFRIT,K.V. BEYFRIT,K.V.	8010220676* 8010010329* 8010300028 8010300029 8010160297*	50-333 Q 50-334 Q 50-285 Q 50-298 Q GAPPP		SHIELDB, B, W, SHIELDB, B, W, SHIELDB, B, W, SHIELDB, B, W.	8010060224 8010060288 8010240350 8010150296 8010300484	50-546 B 50-546 B PR 50-546 A 50-546 B	SMITH, O. H. BMITH, O. H. BMITH, O. H. SMITH, O. SMITH, O. BMITH, O. H.	8010010611 8010020629 8010020213 8010080376	70-820 80-213 0 80-412 0 50-286 B 70-82

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOUNT OF THE SHITH A H SHITH A R D SHITH O H SHITH O	8010010216* 8010240351* 8010010165 8010020206* 8010010370*	50-334 G 50-219 G HASTE MOT 70-364 70-820	ENYDER, B. J SNYDER, B. J SNYDER, B. J. SNYDER, B. J. SNYDER, B. J.	8010230438 8010230708	50-320 H 50-320 H 50-320 H 50-320 H 50-320 P	SPINDEL, N. M. SPINDEL, N. W. SPITZBERG, D. B. SPITZBERG, D. B. SPRINGER, E. R.	8010240074 8010240074 8010220644* 8010210384* 8010030442	50-574 Q 50-574 Q 40-4492 40-8584 50-287 Q
SKLTH, O. H SHLTH, O. H SHLTH, O. H SMLTH, O SMLTH, O	8010100434* 8010220471* 8010010318* 8010080380 8010230141	50-277 0 50-333 0 50-334 0 50-388 8 70-820	SNYDER, B, J, SNYDER, B J. BNYDER, B, J. SNYDER, B J. SNYDER, B J.	8010240582 8010270077 8010270095 8010270114 8010270120	50-320 F 50-320 H 50-320 H 50-287 H 50-320 H	SRENIAHENI,D J STAHLE,C STALL,D H STAMPELOS,J STAMPLEY,N,L	8010030544 8010290172 8010080539 8010170319 8010200357	40-8742 50-327 P 50-6 J 50-245 B 50-416 I
SMITH, TH SMITH, OH SMITH, OH, SMITH, RE SMITH, AB	8010240176* 8010010330 8010060165 8010010760 8010210773	50-213 Q 70-820 70-820 50-271 Q Waste Mot	Snyder, B. J. Bnyder, B. J. Bnyder, B. J Bnyder, B. J Snyder, B. J.	8010270123 8010270042 8010270050 8010270059 8010270067	50-320 H 50-320 H 50-289 H 50-289 H 50-320 H	STANSHERRY, E. R. STARKEY, R. B STARK, R. H. STARK, R. M. STARKEY, R. B	8010310269 8010150212 8010220072 8010210324 8010070529	50-182 F 50-241 Q 50-387 V 50-387 A 50-241 8
Balth o H. Balth P. Balth J. R Balth o H Balth o	8010230665 8010140280 8010150241 8010230623 8010030525	50-146 Q 50-320 P REB 50-277 Q 1&E	Bnyder, B. J. Bnyder, B. J. Bnyder, B. J. Bnyder, B. J. Bnyder, B. J.	8010270089 8010270097 8010280603 8010280642 8010280634	50-320 H 50-320 H 50-289 H 50-289 H 50-320 P	STARKEY, R. B STARKEY, R. B STARKEY, R. B. STARKEY, R. B. STARKEY, R. B.	8010070531* 8010070600 8010070604* 8010130443 8010200575	50-261 8 50-261 8 50-261 8 50-261 R 50-261 8
H 5-HT1M8 H 5-HT1M8 H 5-HT1M8 H 5-HT1M8 H 5-HT1M8	8010010202 8010010307 8010020193 8010100428 8010200532	50-334	BNYDER, B. J. BNYDER, B. J. BNYDER, B. J. BNYDER, B. J. BNYDER, B. J.	8010270356 8010280073 8010280083 8010280030 8010310004	50-320 P 50-289 H 50-289 H 50-289 H 50-320 T	STARKEY, R. S. STARK, R. M. STARK, R. M. STARKEY, R. B. STARKEY, R. B	8010200581* 8010290415 8010290180 8010270382 8010270383*	50-241 B 50-387 V 50-387 A 50-241 B 50-241 B
EMITH.O EMSTH.O.H EMITH.O.F. EMITH.O.H	8010060030 8010220662 8010160012* 8010170005 8010160380	14E 50-333 0 70-27 50-213 8 50-217 8	Bobon, L. J Bofer, O. A. Bofer, O. A. Bofer, Q. A. Bofer, Q. A	7902090343 8010150452* 8010090241* 8010090246* 8010090250*	50-322 A 50-10 P TOPREP TOPREP TOPREP	BTARR, G. BTEENLAND, P. R. BTEFFEB, C. BTELLO, V. BTELLO, V	8010080128 8010240337* 8010070509* 8010280734* 8010280736*	PR 50-320 G 50-254 B 50-219 P 50-219 P
SHITHIN P SHITHIN SHITHIN SHITHIR.L. SHITHIR L	8010160040* 8010030465 8010080485* 8010060262 8010060276	50-10	Schinki 8, M. Sclberg, D. E, Bolon, L. R. Bodno, A. L. Bouder, J. L	8010140009 8010030529* 8010210275 8010210164 8010060058	50-465 0 MISC State Prog 70-162 50-369 F	STELLO, V. STELLO, V. STELLO, V. STELLO, V	8010060192 8010090113 8010090137 8010090144 8010090156	50-546 A 50-546 A 50-546 A 50-546 A
SMITH, I. W SMITH, H SMITH, I W SMITH, R D SMITH, R. L	8010030477 8010070567* 8010030421 8010300465 8010100218	50-289	SOUDER, J. L. SOUDER, J. L. SOUDER, J. L. SOULE, H. F. SOUTH, D. W.	8010040162 8010140316 8010300036* 8010280232* 8010240223	50-267 F 50-352 F 50-445 H FOIA PR	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	8010070081 8010230720 8010040044 8010030541 8010020790	50-322 H 50-322 H 50-257 Q 50-324 Q 50-286 Q
SMITHO H. SMITHO H SMITH, R. L. SMITHOR L SMITHO H.	8010220204 8010140339 8010140581 8010210318 8010240370	70-820 50-201 8 50-271 0 50-271 P 70-364	BPAIN.O H BPANOLER.R.O BPEAKER.D. BPECIALE.J R BPECTOR.A	8010270145 8010010017* 8010150171 8010160465* 8009090223*	FDIA 50-298 G NUREG 50-318 8 40-1162	BYELLO, V STELLO, V. STELLO, V. STELLO, V.	8010170049 8010220227 8010060188 8010100242 8010140193	50-312
BM1 TK, R. L. BK1 TH, R. L. BM1 TH, R. L. SM1 TH, T. H. SM1 TH, R. L.	8010200449 8010210336 8010230454 8010220498 8010240449	50-271 P 50-271 P 50-271 P 50-289 0 50-271 P	BPENCER, O. 8 BPENCER, O. 8 BPENCER, O. B. BPENCER, O. B. BPENCER, O. B.	8010070359 8010070380 8010020137* 8010100355 8010170419	50-275 Q 50-361 Q 50-361 Q 50-508 Q 50-528 Q	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	8010160415 8010160421* 8010170036 8010170036* 8010170687	50-333 0 50-333 0 50-245 0 50-245 0
SMITH & L SMITH I. W SMITH I. W SMITH R. L. SMITH I. W.	8010270485 8010220534 8010220545 8010280419 8010300051	50-271 P 50-387 M 50-289 Q 50-271 P 50-289 Q	BPENGER, O. B. BPENGER, G. B. BPENGER, O. B. BPENGER, G. B. BPENGER, G. B.	8010310014* 8010170544 8010310307 8010230066 8010230079	50-508 Q 50-528 Q 50-397 Q 50-275 Q 50-397 Q	STELLD, V. STELLD, V. STELLD, V STELLD, V. STELLO, V.	8010170493* 8010200227 8010200236* 8010200239 8010200249*	50-219 0 50-298 0 50-298 0 50-277 0 50-277 0
SMOKER, C. S. SMOKER, C. S SMOKONSKI, R. T BN LEZEK, J. H BN 16ZEK, J. H	8010280543* 8010280548* 8010160378* 8010200615 8010200616	50-305 B	BPENCER; Q. 8. BPENCER; Q. B. BPENCER; Q. B. BPENCER; Q. B. BPENCER; Q. B	8010280039 8010310272 8010280022 8010310007 8010310049	50-397 Q 50-361 Q 50-275 Q 50-508 Q 50-397 Q	STELLO, V. STELLO, V. STELLO, V. STELLO, V STELLO, V.	8010200252* 8010200280 8010200283* 8010200287 8010200274*	50-277 9 50-220 9 50-220 9 50-237 9 50-237 9
SNITEZEK, J. H. SNIEZEK, J. H. BNIEZEK, J. H BNOH, B. A. SNOH, R. A.	8010200419 8010200421 8010200425 8007140542* 8007140570*	50-278	Spesbard: R. L. Spesbard: R. L. Spesbard: R. L. Spesbard: R. L. Spesbard: R. L.	8010070176 8010100411 8010070285 8007080200 8010070197	50-247 8 50-265 8 50-254 8 50-247 8 50-304 8	BTELLO, V BTELLO, V. STELLO, V BTELLO, V. BTELLO, V.	8010200297* 8010200302* 8010200306* 8010200614 8010200620*	50-237 9 50-237 9 50-237 9 50-271 9 50-271 9
Berchi B A. Browl B. A. Bryder B. J. Bryder B. J. Bryder B. J.	8009140347* 8010230377 8010020049 8010220081* 8010100279	50-244 R 50-320 P	spessard.r.l spessard.r.l spessard.r.l spessard.r.l. spessard.r.l.	8010100422 8010140158* 8010150090* 8010160145* 8010090255	50-304 B 50-275 Q 50-254 Q 50-373 G 50-304 B	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	8010200627 8010200631* 8010210165 8010210170* 8010210176*	50-273 9 50-273 9 50-257 9 50-257 9 50-257 9
SMYDER: 3. J SMYDER: 3. J SMYDER: 3. J SMYDER: 8. J SMYDER: 8. J	8010030408 8010200257 8010200563 8010230094 8010240131	50-320 H 50-320 H 50-287 H 50-289 H 50-320 H	Spessard, R. L Spessard, R. L Spessard, R. L Speth, O. Spiegel, Q.	8010090270 8010080638 8010090258 8010080142 8010150408	50-254 8 50-10 8 50-254 8 FR 50-369 M	etello, V. Byello, V. Byello, V. Byephenson, J. H.	8010210179* 8010210204 8010210222 8010270571 8010030430	50-259 9 50-271 9 50-237 9 50-313 9 50-370 H
BMYDER: B. J. BMYDER: B. J. BMYDER: B. J. BMYDER: B. J. BMYDER: B. J.	8010270079 8010280089 8010220030 8010240050 8010100107		BP EOEL O. BP EOEL O. BP EOEL O. BP EOEL O.	8010070541 8010070541 8010180024 8010180024 8010220316	80-445 M 50-445 M 50-445 M 50-445 H 50-445 H	STEPHENS, C. R. STEPTOE, P. P. STEPTOE, P. STEPTOE, P. STEPTOE, P.	8010030456 8010020065 8010020740 8010070054 8010160036	50-320 9 50-237 9 50-237 9 50-237 9 80-10 9
Snyder, D. J. Snyder, B. J. Snyder, B. J. Snyder, B. J. Snyder, B. J.	8010150074 8010230431 8010230437 8010230450 8010230453	50-320 H 50-320 H 50-320 H	Spiegel, g Spiegel, g. Spiegel, g. Spieles, p. R. Spindel, n u	8010220320* 8010220320* 8010270439 8004090384 8010220383		BTEPTOE, P. BTEPTOE, P. STEPTOE, P. STEPTOE, P. BTEPTOE, P. P	8010160045* 8010160036 8010160045* 8010230464 8010280535	50-10 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY
STEPTOE, P P STEPTOE, P P STEPTOE, P P STERNBERO, D M STERNBERO, D M	8010290385 8010280535 8010290385 8010090163 8010080170*	50-237 0 50-237 0 50-237 0 50-237 0 50-344 8 50-344 Q	SUMPTER, JR SUNSER, JJ SUNSER, J, J SUTHERLAND, JT SUTHERLAND, JT	8010140594* 8010010375 8010220492 8003240244 8010230677*	50-466 0 50-220 F 50-220 F 50-160 0 50-329 0	TEDESCO: R L	8010010025 8010010726 8010020119 8010020303 8010220235	50-373 A 50-397 A 50-387 A 50-364 A 50-416 A
STERNDERO, D M STERNBERO, D M STERNBERO, D M STERNBERO, D M STERN, W C	8010090379* 8010170363* 8010270138* 8010230180* 8010160257	50-344 0 50-397 0 50-275 0 50-344 0 XPORTLIC	EUTTON, R. H BUTTON, J. W BUTTON, J. W BUTTON, J. W BUTTON, J. W BUATN, A. D	8010170169* 8010080167* 8010270363* 8010240022* 8010300343	NUREO GA999 GA999 GA999 NUREO	TEDESCO: R L TEDESCO: R L TEDESCO: R L TEDESCO: R L TEDESCO: R L	8010070235 8010220216 8010180100 8010100423 8010210320	50-327 P 50-498 A 50-389 I 50-259 P 50-416 A
STERNBERG, D M STERNBERG, D M STETMA: T F. STETSON: F STEVENSON: R L	8010300438* 8010280035* 8010010052* 8010230571 8010010617*	50-243 Q 50-275 Q 50-302 Q PR 70-820	Shajkowski, r h Shan, w b Shan, f h Shandy, c t Shandy, c t	8010150590 8010090244* 8010240274 8010150656 8010200085	70-1308 50-518 0 50-133 P 40-3453 40-3453	TEDESCO, R L TEDESCO, R TEDESCO, R L TEDESCO, R, L TEDESCO, R L	8010220041 8010230004 8010230427 8010240004 8010220363	50-387 A 50-339 P 50-311 P 50-369 Q 50-498 A
STEVENBON, R L STEVENB, S C STEVENBON, R L STEVENBON, R L	8010020412* 8010030415 8010070504 8010010477 8010220108*	70-1113 50-285 8 50-285 8 70-371 70-2609	SWANBY, O T SWANBON, D T SWART, F. E SWART, F. E SWART, F. E	8010200171 8010150055 8010210263 8010230097 8010270361	40-3453 50-287 0 50-267 P 50-267 Q 50-267 P	TEDESCO, R.L. TEDESCO, R.L. TEDESCO, R.L. TEDESCO, R.L. TEDESCO, R.L. TEDESCO, R.L.	8010240008 8010280040 8010220107 8010230241 8010280663	50-375 F 50-275 A 50-358 A 50-349 A 50-341 A
BTEVENSON, R L STEVENSON, R L STEVENSON, R L STEVENSON C	8010230118 8010140480 8010270228 8010140443 8010270374	70-157 50-285 S 70-371 50-285 S 50-285 S	SWART, F E SWEENEY, L, E SWEENEY, L, E SWEENEY, L E SWEENEY, L E	8010310388 8010010467 8010030493 8010090389 8010160490	50-267 P 50-287 Q 50-287 Q 50-287 Q 50-287 P	TEDESCO, R. L.	8010300443 8010280692 8010290200 8010310555 8010310569	50-352 A 50-327 A 50-387 P 50-395 Q 50-395 A
STEVENSON, R. L STEWART, R C STEWART, R C STEWART, D K STILLMAN, J R	8010270234 8010270030* 8010270026* 8010200445 8010100293*	70-1374 50-382 Q 50-382 Q 50-367 A 50-272 F	SHEENEY, L E SHEENEY, L E SHEENEY, L E SHEENEY, L E SHEENEY, L E	8010200568 8010210469 8010220405 8010220367 8010230394	50-289 T 50-289 T 50-289 I 50-289 T 50-289 G	TENZER, B E. TERC, N, M TERC, N M TERC, N M TERC, N M TERRY, B, H	8010280323 8010010382* 8010010404* 8010240136* 8010160697*	TDPREP 50-293 G 50-219 G 50-213 G 50-294 G
STILLMAN,I M STODDART,P O STOHR,J P STOHR,J P STOHR,J P	8010240420* 8010070445* 8004080145 8005120223 8006040077	50-320 P 50-287 G 50-250 G 50-259 G	SWEENEY, LE SWETLAND, PD. SWETLAND, PBMETLAND, PDSWIGERT, BB	8010310477 8010270207# 8010100057# 8010070218 8010040182	50-287 T 50-307 Q 50-307 Q 50-307 8 XPORTLIC	THATCHER, D F. THIEB, A, C THINNEB, R G THINNEB, R G THOM, T	8010270418* 8010070413 8010200624 8010210144 8010150335*	50-373 A 50-369 A 50-295 P 50-295 P 50-259 R
9 U,RHOT8 9 U,RHOT8 9 U,RHOT8 9 U,RHOT8 9 U,RHOT8	8010160061* 8008060178 8010240537* 8010010271* 8010160680	50-324 Q 50-259 Q 50-335 F 50-338 Q 50-333 B	SYLVESTER, K. SYLVIA, B R SYLVIA, B R SYLVIA, B. R SYLVIA, B R	8010220044* 8010010263* 8010010247* 8010010478 8010160079	50-275 H 50-338 G 50-339 G 50-280 P 50-280 G	THOMAS, R.D. THOMAS, R.D. THOMAS, J. THOMAS, J. THOMAS, J. THOMAS, R,D	8010150518* 8010140049* 8010240351* 8010100030* 8010060094	50-320 q 50-274 q 50-219 q 50-219 q 70-734
STOHR, J P GTOHR, J P GTOHR, J P STOHR, J. P STOHR, J P	8010070235* 8010170016 8010010254* 8010020227 8010240146*	70-1151 50-327	EYLVIA, B. R SYLVIA, B. R SYLVIA, B. R, SYLVIA, B. R SYLVIA, B. R,	8010070180 8010070312 8010170214 8010070148 8010070178	50-280 P 50-280 P 50-280 Q 50-280 Q 50-280 P	THOMAS, R.D. THOMAS, M. THOMAS, R.D. THOMAS, R. THOMAS, R. THOMAS, R.D.	8010270373* 8010160696 8010220188 8010020007 8010220546	70-754 50-564 B 27-10 50-201 G 27-48
STOHR, J. P STOHR, J P STOHR, J P STOHR, J. P STOHR, J P	8010240174* 8010010238 8010270289* 8010280267 8010290406	50-348 G 50-338 G 70-143 50-261 G 70-27	SYLVIA, B R SYLVIA SYLVIA, B R SYLVIA, B, R. SYLVIA, B, R.	8010070378 8010080436 8010160560 8010150248 8010160456	50-280 P 50-280 P 50-338 R 50-280 P 90-338 R	THOMAS, E. B THOMAS, W. N THOMAS, E. B THOMPSON, M. A THOMPSON, G. A	8010160515 8010240446 8010310378 8010150081 8010220161	50-220 P 50-280 P 50-220 P WASTE MOT ACRB
2048, J P 81048, J P 81048, J P 81048, J P 81048, J P	8010270412* 8010300168 8010300340 8010310055 8010270409	50-338	Sylvia, B. R Sylvia, B. R. Bylvia, B. R Sylvia, B. R Sylvia, B. R	8010200387 8010200453 8010200446 8010210350 8010240261	50-280 R 50-280 P 50-339 P 50-281 P 50-339 J	THOMPBON, M A THOMPBON, M A THOMPBON, J. E THOMPBON, M. A THOMPBON, T	8010030192 8010140616 8010240578 8010150662 8010200439*	WASTE HOT WASTE HOT WASTE HOT WASTE HOT 50-346
STOHR, J.P STOHR, J.P STOICK, A.F STOICK, A.F STOICK, A.F	8010240115 8010240519 8010230386* 8010230383 8010230389*	50-348 0 50-335 F 40-8663 40-8663 40-8663	eylvia, e .r eylvia, e. r eylvia, e. r eylvia, e r. eylvia, e r	8010240452 8010240525 8010240443 8010240451 8010270372	50-338 Q 50-338 P 50-338 P 50-280 P 50-338 F	THOMPSON. D THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON. K	8010020502 8010020503 8010020500 8010170100 8010230537	14E 146 40-672 50-321 B Waste Kot
Stone, R. Stone, R Stout, R & Stone, W S Strasma, J.	8010270542* 8010270275* 8010060350* 8010160506 8008060267	50-250 H 50-335 H 50-265 P 50-293 J 50-282 8	SYLVIA: B R. SYLVIA: B R. SYSLO: J SZHAJKOHEKI: R SZHAJKOHEKI: R.	8010310468 8010310336 8010270388* 8010170357 8010170357	50-338 P 50-280 F 50-946 8 70-1308 70-1308	THOMPSON, D THOMPSON, D. THOMPSON, D. THOMPSON, D THOMSEN, F. T.	8010020505 8010020586 8010270177 8010200706 8010070313	1&E 1&E 40-8084 50-313 B 50-522 G
Btrasma, r J Btrasma, r. J. Btratton, w. r Btrauss, d a Btreeter, J	8010080553 8010080638 8010070399* 8010240337* 8010090267	50-544 8 50-10 8 NUREO 50-320 0 50-314 8	TATERBALL, A. P TAUDER, H. TAYLOR, P. A TAYLOR, P. A TAYLOR, P. A	8010180563* 8010160525 8010080442 8010160797 8010160374	50-338 0 50-341 F 50-327 8 50-321 8 50-321 8	THOMSEN, F. T THONUS, L. H THORNBURO, H. D. THORNBURO, H. D. THORNBURO, H. D. THORNBURO, H. D.	8010200437 8010150511* 8010090087* 8010220090* 8010300401	50-522 A 50-320 G 50-322 G 50-320 P I&E
STREETER, J. F. STREETER, J. F. STRELOW, R. STRICKLER, D. STUDDS, O. E.	8010150102* 8010240031* 8010160675 8010280660*	50-331 G 50-255 G PR 50-320 P MISC	TAYLOR, P.A. TAYLOR, R.Q. TAYLOR, C.H TAYLOR, R.R TAYLOR, R.R	8010160642 801020183* 8010150608 801006067 801006067*	50-366 8 50-445 0 70-143 XPORTLIC XPORTLIC	THORNTON, P THORNTON, P. TIEPEL, E, W TIEPEL, E W. TILBERG, K	8010240364 8010240364 8007070152 8010230238 8010160585	50-155 0 50-155 0 40-8502 40-8502 PR
IU.T M IUCEVIC, J M IULLIVAN, T. J. IVLLIVAN, R F LLIVAN, T J	8010070498 8010150540* 8010160066 8010230483* 8010210137	50-447 A 50-366 P PR 50-257 G PR	TAYLOR, J. H TAYLOR, P. A. TAYLOR, J. H TAYLOR, J. H. TAYLOR, J. H. TAYLOR, J. H.	8010210065 8010270416# 8010060255 8010150514 8010200427	REGOD 50-338 Q TOPREP TOPREP TOPREP	TILLMAN, A. TILLMAN, A TING, W. W TINSLEY, W. D TIPTON, T. E	8010070227* 8010270379* 8010080659 8010200600* 8010210271	70-1151 50-327 0 50-201 F CONTRACT RECOD
LIVAN, T J LIVAN, D F. LIVAN, D F MERS, R. J MERS, R.	8010230519 8010070524* 8010070638* 8010020702* 8010240284*	PR 50-289 0 50-289 0 70-135 70-820	TEABDALE, J. P TEDEBCO, R. L.	8010020693* 8010010066 8010020643 8010010032 8010010022	50-483 T 50-410 A 90-454 A 50-387 A 50-438 A	TIPTON, T. E TIPTON, T. E TIPTON, T E TOBIN: W J. TODOROVICH, M M.	8010240355 8010240352 8010200414 8010020275* 8010200019	PR PR NUREO 70-27 PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
TODORGVECH, H. N. TOULESON, E. A. TOULESON, A. C. TOULESON, A. C. TOULESON, A. C. TOULESON, A. C.	8010020663 8010150666* 8010060207 8010060213* 8010060272	50-201 0 50-324 0 50-324 8 50-324 8 50-325 8	TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C. TRIMBLE.D.C TRIMBLE.D.C	8010240112 8010270333 8010230081 8010070442 8010010563	50-313 Q 50-313 Q 50-313 Q 50-349 R 50-313 F	UHRIO, REUHRIO, REUHRIO, REUHRIO, REUHRIO, REUHRIO, REUHRIO, REUHRIO, REUHRIO, RE	8010140099* 8010150282 8010150042* 8010270237 8010060236	50-250 G 50-250 G 50-335 G 50-335 G 50-250 F
TOLLISON, A. C.	8010060278* 8010070441 8010070447* 8010070557 8010070566*	50-325 8 50-324 8 50-324 8 50-325 8 50-325 8	TRIMBLE, D C TRIMBLE, D C. TRIMBLE, D, C TRIMBLE, D C TRIMBLE, D C	8010010494 8010070617 8010010516 8010070280 8010070510	50-313 8 50-313 8 50-313 R 50-313 P 50-313 F	UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, R.E	8010060274 8010060307 8010010648 8010010537 8010010547	50-389 A 50-250 P 50-250 P 50-250 P 50-250 P
TOLLISON, A C	8010070575	50-325 8	TRIMBLE, D, C	8010070363	50-348 8	UHRIGIR E	8010270164	PR
TOLLISON, A C	8010070586*	50-325 8	TRIMBLE, D C	8010070376	50-348 8	UHRIGIR E	8010270275	50-367 Q
TOLLISON, A C	8010070601*	50-324 8	TRIMBLE, D C	8010070834	50-348 8	UHRIGIR E	8010270292	50-335 Q
TOLLISON, A C	9010070547	50-324 8	TRIMBLE, D. C	8010070614	50-349 9	UHRIGIR E	8010080223	50-250 P
TOLLISON, A C	8010070558*	50-324 8	TRIMBLE, D. C,	6010070293	50-313 F	UHRIGIR E	8010080392	50-250 H
TOLLISON: A C. FOLLISON: A C TOLLISON: A C TOLLISON: A C TOLLISON: A C	8010230357 8010100325 8010100332* 8010100335 8010100341*	50-324 G 50-324 B 50-324 B 50-324 B 50-324 B	TRIMBLE, D C TRIMBLE, D, C TRIMBLE, D, C TRIMBLE, D, C TRIMBLE, D, C	8010070461 8010070540 8010070573 8010080477 8010070560	50-348 P 50-313 B 50-319 B 50-348 B 50-313 B	WHRIGHE UHRIGHE UHRIGHE UHRIGHE UHRIGHE UHRIGHE	8010080340 8010150263 8010290326 8010210341 8010210347	50-389 A 50-250 F 50-389 I 50-335 F 50-250 F
TOLLISON: A C. TOLLISON: A C TOLLISON: A C TOLLISON: A C TOLLISON: A C	8010140460	50-324 8	TRIMBLE, D. C	8010080331	50-313 F	UHRIGAR E	8010200317	50-250 P
	8010140472*	50-324 8	TRIMBLE, D. C	8010080428	50-388 8	UHRIGAR E	8010200454	50-250 G
	8010140481	50-325 8	TRIMBLE, D. C.	8010210454	50-313 P	UHRIGAR E	8010210413	50-335 P
	8010140487*	50-325 8	TRIMBLE, D. C.	8010170512	50-313 P	UHRIGAR E	8010220501	50-336 P
	8010150386	50-324 R	TRIMBLE, D. C.	8010170238	50-313 8	UHRIGAR E	8010240216	50-250 F
TOLLISON/A C. TOLLISON/A C TOLLISON/A C TOLLISON/A C TOLLISON/A C TOLLISON/A C	8010150504 8010150510 8010150520 8010150521* 8010150523	50-325 8 50-324 8 50-324 8 50-324 8 50-325 8	TRIMBLE, D. C TRIMBLE, D. C TRIMBLE, D. C, TRIMBLE, D. C TRIMBLE, D. C,	8010170523 8010200443 8010210420 8010210424 8010220497	50-369 P 50-313 P 50-313 R 50-369 R 50-313 P	UHRIO, RE UHRIO, RE UHRIO, R.E UHRIO, R.E	8010240229 8010240267 8010280297 8010300444 8010280334	90-387 A 90-251 G 50-250 P 50-250 G 50-335 P
Tollison, a c	8010150526*	50-324 8	TRIMBLE, DC	6010280331	50-313 P	ULLRICH, W T	8010270124	50-277 8
Tollison, a c	8010150527*	50-325 8	TRIMBLE, DC	8010280546	50-313 8	ULLRICH, W T,	8010270353	50-277 8
Tollison, a c	8010150531*	50-325 6	TRIMBLE, D.C.	8010280227	50-348 X	UNDERWOOD, P R	8010210414*	50-346 R
Tollison, a c	8010150316	50-324 R	TRIMBLE, D.C.	8010290337	50-313 P	UNDERWOOD, P, R	8010210421*	50-321 R
Tollison, a c	8010200588	50-324 8	TRIMBLE, D.C.	8010240376	50-313 P	UPRIGHT, C M	8010240012*	50-321 G
TOLLISON, A C	8010200597*	50-324 8	TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C.	6010280644	50-313 F	UPRIGHT, C.M	8010020787*	50-367 G
TOLLISON, A C	8010210674	50-324 8		8010280522	50-313 B	Upright, C.M	8010310197*	50-302 G
TOLLISON, A C	8010210680*	50-324 8		8010280583	50-313 B	Urban, J.R	8010240063	50-387 M
TOLLISON, A C	8010240463	50-324 8		8010280444	50-313 B	Urban, J.R	8010150640	50-395 M
TOLLISON, A C	8010240472*	50-324 8		8010310394	50-313 P	Utley, E.E	8010170242	PR
TOLLISON, A.C. TOLLISON, A.C. TOLLISON, A.C. TOLLISON, A.C. TOLLISON, A.C.	8010210498 8010210501* 8010210667 8010240548 8010280570	50-324 8 50-324 8 50-324 8 50-324 8 50-324 8	TRIMBLE, D. C, TRIMBLE, D. C TRIPP, L. E. TRIPP, L. E. TRIPP, L. E.	8010310345 8010310381 8010010403* 8010100071* 8010100074*	50-313 P 50-313 R 50-333 Q 50-410 Q 50-352 Q	UTLEY, E E	8010020363 8010020469 8010070454 8010100338 8010180423	50-324 P 50-261 P 50-261 F 50-261 P 50-261 P
TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C. TOLLIBON, A.C.	8010280576* 8010280538 8010280542* 8010280402 8010280406*	50-324 B 50-325 B 50-325 B 50-325 B 50-325 B	TRIPP, L. E. TROMPETER, K. M. TROSKOSKI, M. TROUP, O. L. TROUP, O. L.	8010240290* 8010280392 8010090127 8008040179* 8010010283*	50-277 0 50-528 C 50-223 E 50-259 G 50-338 G	UTLEY, E E, UTLEY, E E UTLEY, E E UTLEY, E E	8010160517 8010170547 8010240405 8010210477 8010200471	50-324 P 50-261 P 50-324 P 50-325 P 50-261 P
TOMELNSON, D.P. TOMPKINS, B.A. TOMPKINS, B.A. TOMPKINS, B.A. TOMPKINS, B.A.	8010160027* 8010010005 8010020743 8010020031 8010070017	50-482	TROUP, Q. L. TROWERIDGE, Q. F. TROWERIDGE, Q. TROWERIDGE, Q. F. TROWERIDGE, Q.	8010020236* 8010080240 8010080281 8010080240 8010080281	50-364 0 50-289 0 50-289 0 50-289 0 50-289 0	UTLEY,E E VALENTINE,K VALORE,C J VAN BRUNT,E E VAN BRUNT,E.E	8010280377 8010070391 8010200015 8010300145 8010020446	50-261 F 50-20 J PR 50-528 0 50-528 8
TOMPKENS, BA TOMPKENS, BA TOMPKENS, BA TOOLE, R. J TOOLE, R. J	8010070382	50-275 0	TROWBRIDGE, O. F	8010130007	50-289 0	VAN BRUNT,E E	8010240198	PR
	8010100137	50-275 0	TROWBRIDGE, O. F	8010130035	50-289 0	VAN BRUNT,E E	8010060253	50~528 8
	8010140014	50-275 0	TROWBRIDGE, O. F.	8010130007	50-289 0	VAN BRUNT,E E	8010310089	50~528 0
	8007300506	50-287 8	TROWBRIDGE, O. F	8010130035	50-289 0	VAN BRUNT,E E	8010100306	50~528 K
	8010200516	50-287 8	TRUJILLO, A	8010010353	NUREO	VAN BRUNT,E E	8010160539	50~528 8
TOOLE, R. J	8010240489	50-289 8	TBAI, 8. 8.	8010230003	NUREO	VAN BRUNT,E E	8010210417	50-528 A
TORCIVIA, J A	8010240057	50-289 T	TBOULFANIDIS, N	8009220237	50-564 0	VAN BRUNT,E E.	8010290371	50-528 8
TORRONEN, K.	8010230475	NUREO	TUBBS, R. C.	8010160352*	50-254 8	VAN BRUNT,E E	8010280417	50-528 A
EQTH. A. D	8010210314*	50-397 G	TUBBS, R.	8010150313*	50-254 R	VAN BRUNT,E E	8010290324	50-528 B
TOYH, A. D	8010280041*	50-397 Q	TUCKER, C. A.	8010230317	50-201 0	VAN HOUTEN,R	8010220253	NUREG
TOURTELLOTTE, J	8010090057	50-289 Q	TUFFIN, W B. TUNSTALL, J E. TURT, O. P. TURK, B. E. TURK, B. E. TURK, B. E	8010160646	40-672	VAN NEBB.B C	8010010491*	50-269 0
TOURTELLOTTE, J	8010150591	50-289 Q		8010070141*	CONTRACT	VAN BICKEL, J	8010210408*	50-331 R
TOURTSEND, H. E	8010020339*	TOPREP		8010070545	27-39	VANCE, J. N	9010240540	PR
TRACER, E. A	8010160276	40-1341		8005140417	50-445 0	VANDEL, T	8010090204	50-461 8
TRACER, E. A	8010240157	40-1341		8010210267	70-2909	VANDENBURGH, D	8010080492	50-29 P
Tracqto.r P	8010280523*	50-213 B	TURLEY, R E	8009300449	50-72 R	VANDEL, T. E	8010220605	50-492 S
Tracqto.r.p.	8010280528*	50-213 B	TURLEY, R E.	8010010265*	50-72 R	VANDENBURGH, D.	8010300356	50-29 P
Trammell.c H	8010070068	50-344 P	TURNAQE, K. Q	8010170066	NUREQ	VANSICKLE, D.	8010100566*	50-466 G
Travieso-Diaz	8010300606	50-387 Q	TURNBULL, J. A.	8010300178	RES	VARELA, A	8010100103*	50-410 G
Travieso-Diaz	8010300613	50-387 Q	THAQOOD, F. J.	8010070047	PR	VARGA, S. A	8010010029	50-315 P
TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVLOR,F. A TREIBEL, W.C. TRIESCHMAN, W.E	8010300604 8010300613 8010090044* 8010080667* 8010290357*	50-387 0 50-387 0 CONTRACT CONTRACT 50-320 P	TYLER, P. E. TYLER, P. E. UDY, A. C. UDY, A. C. UHRIO, R. E.	8010040220 8010040226* 8010300186 8010300225 8010010542	50-170 P 50-170 P 50-333 P 50-344 P 50-250 P	VARQA, B. A.	8010010041 8010010069 8010010074 8010010439 8010010443*	50-305 P 50-305 P 50-250 9 50-315 P 50-315 P
TRIMBLE, D, C	8010160712	50-313 0	UHRIO, R. E.	8010170019*	50-250 Q	VARÇA: B. A	8010010450#	50-315 P
TRIMBLE, D C	8010210246	50-313 0	UHRIO, R. E.	8010140104*	50-250 Q	VARÇA: B. A	8010010151	50-295 P
TRIMBLE, D C	8010010024*	50-313 0	UHRIO, R. E.	8010240327*	50-335 F	VARÇA: B. A.	8010010156	50-247 P
TRIMBLE, D C.	8010070620	50-313 8	UHRIO, R. E.	8010030081*	50-335 Q	VARÇA: B. A	8010010161	50-286 P
TRIMBLE, D, C	8010010613	50-348 P	UHRIO, R. E.	8010150576*	50-250 Q	VARÇA: B. A	8010010164	50-261 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	CVIEGG4A CVIEGG4A
VARGA.8 A	8010010172	50-280 P	WALPOLE, J R	8010300090#	40-1162	WEITZBERG, A	8009220226	8H
VARGA.8 A	8010010176	50-250 P	WALPOLE, J R	8010300048	40-1162	WELLHOUSER, H N	8010200269	70-734
VARGA.8 A	8010010179	50-272 P	WALPOLE, J R	8010300048	40-1162	WELLHOUBER, H N	8010200096	70-734
VARGA.8 A	8010010183	50-334 P	WALBH, E. J	8010140742#	50-516	WENDERLICH, R L	8010030399*	50-317
VARGA.6 A	8010010188	50-348 P	WALBKE, C	8010020001	0	WENDERLICH, R L	8010060273*	50-318 B
VAROA,8 A VAROA,8 A VAROA,8 A VAROA,8 A VAROA,8 A	8010010171 8010140020 8010140022* 8010140026* 8010200345	50-315 P 50-334 P 50-334 P 50-334 P 50-272 P	WALSTON, R R WALTERS, D X WALTER, D K WALTON, G A WALTON, G A	8010160693 8010300428* 8010290206* 8010230100* 8010230707*	PR 50-367 0 50-375 0 50-354 0 50-412 0	WENDERLICH, R L WENDERLICH, R L WENDERLICH, R L WENDERLICH, R E WENSLAWSKI, F A	8010210672* 8010210684* 8010310315* 8010310359* 8010210449*	50-318 50-317 50-318 50-317 50-206 9
VARGA, B. A	8010200349*	50-272 P	WALUSCHKA, E	8010170023	Nureo	WENGLAWSKI,F A WENGLAWSKI,F A WENGLAWSKI,F WENGLAWSKI,F A WENGLAWSKI,F	8010100052#	50-139
VARGA, B. A	8010200351*	50-272 P	WAMBACH, T V	8010080464	50-235 8		8010200034#	50-36L
VARGA, B. A	8010140147	50-261 P	WANAT, S W	8010150594	27-39		8010280706#	50-106
VARGA, B. A	8010140148*	50-261 P	WANAT, S W	8010150403	27-39		8010310387#	50-206
VARGA, B. A	8010140154*	50-261 P	WARD, K D	8010200470#	50-358 0		8010090211	9
VAROA, S.A	8010150303	50-315 F	WARD. % D	8010160336*	50-374 0	WERLING, J A	8010280438	50-334 V
VAROA, S.A	8010080448	50-286 P	WARD. % D	8010270373	50-445 0	WERLING, J A	8010010534	50-334 S
VAROA, S.A	8010080458	50-295 P	WARD. % D	8010270144*	50-282 0	WERLING, J A	8010020466	50-334 S
VAROA, S.A	8010090256	50-247 P	WAREMECURG. D W	8007100240	50-267 F	WERLING, J A	8010070404	50-334 S
VAROA, S.A	8010100036	50-286 P	WAREMEGURG. D	8010070401	50-267 8	WERLING, J A	8010060222	50-334 S
VARQA, B A VARQA, B A VARQA, B A VARQA, B A VARQA, B A	8010200245 8010210125 8010210132* 8010210141* 8010210795	50-250 P 50-334 P 50-334 P 50-334 P 50-250 Q	WAREMBOURO, D WAREMBOURO, D WAREMBOURO, D WAREMBOURO, D WAREMBOURO, D	8010070412 8010210711 8010080334 8010150505 8010210652	50-267 S 50-267 B 50-267 R 50-267 B 50-267 B	WERLING. J A	8010070352 8010070369 8010070456 8010070519 8010070521	50-334 8 50-334 8 50-334 8 50-334 8
VARQA, B A	8010310217	50-241 P	Harembourg, D.	8010210542	50-267 P	WERLING, J A	8010070550	50-334 \$
VARQA, B A.	8010310220*	50-241 P	Harembourg, D	8010280474	50-267 B		8010100307	50-334 \$
VARQA, B A	8010310228*	50-241 P	Harembourg, D	8010280516	50-267 B		8010140432	50-334 \$
VARQA, B A	8010090497	50-280 F	Harembourg, D	8010280527	50-267 B		8010200576	50-334 \$
VARQA, B A	8010230269	50-334 F	Harner, D, L	8010080305#	CONTRACT		8010240433	50-334 \$
VAROA, S. A.	8010300614	50-348 P	Warnick, R, F	8010140381	50-246 8	WERLING, J A	8010240447	50-334 B
VAROA, S. A.	8010270223	50-272 P	Harnick, R, F	8008250080*	50-305 8	WERLING, J A	8010240468	50-334 B
VAROA, S. A.	8010300481	50-275 P	Harnick, R, F	8010100288	50-305 8	WERLING, J. A	8010280450	50-334 B
VAROA, S. A.	8010280272	50-247 P	Warnick, R, F,	8010100408	50-266 8	WERMIEL, J	8010200222#	50-287 T
VAROA, S. A.	8010270376	50-305 P	Warnick, R, F	8010100406	50-266 8	WERNER, R	8010080476	50-445 C
Varga. B. A	8010300346	50-295	WARNICK,R F	8010090194	50-301 8	WESCOTT, H M	8010060128*	50-483 Q
Varga. B. A	8010310129		WARNICK,R F.	8010090183	50-305 8	WESCOTT, H M	8010060108*	50-461 Q
Varga. B. A	8010310135*		WARNICK,R F	8008040278	30-263 6	WESCOTT, H M	8010160250*	50-483 Q
Varga. B. A	8010310140*		WARNICK,R	8009080214	50-346 8	WESLEY, D A	8010150153	NUREO
Verma. R. B	8010240047		WARNICK,R F	8010080347	50-346 8	WESTERMAN, T F	8010010017*	50-298 Q
VERRELLI.D M	8010200394	50-277 F	WARNICK, R F	#161010161	50-358 G	WESTERMAN, T F	8010040178*	50-267 Q
VERBAGE,D A	8010210403	50-97 J	WARNICK, R, F	PESOPOO108	50-305 B	WESTERMAN, T F	8010280121*	50-267 Q
VILARDD,F J.	8010240043	Nureg	WARNICK, R F	PRSOPO0108	50-305 B	WESTERMAN, T F	8010280292*	50-382 Q
VILLFORTH,J C	8010100170	Reged	WARNICK, R, F	ESB0100108	50-266 G	WETMILLER, R J	8010170277	NUREQ
VISBING,O B	8010150530	50-302 P	WARNICK, R, F	#2680100108	50-305 B	WETTERHAHN, M J	8010080083	PR
VIBBING, O	8010230589	50-269 P	Warnick, R, F	8010160187#	50-305 Q	WETTERHAHN, M J	8010270357	90-449 K
VOOLEWEDE, J C	8010070639*	50-269 C	Warnick, R F	8010270161#	50-358 Q	WHARTON, R J	8010010402#	50-361 C
VOOT, R J	8010150588*	50-250 G	Waterg, D. K	8010020250#	50-438 Q	WHARTON, R J	8010010602#	50-361 Q
VOOT-LOWELL, R	8010170026*	50-250 G	Waterbury, O R	8010080671	NUREO	WHARTON, R J	8010030444	50-361 Q
VOIGT, H, H	8010200376	PR	Watford, M	8010150462#	50-261 R	WHEELER, D M	8010140353#	50-275 A
VOIOT, H H VOIOT, H H VOIOT, H H VOIOT, H H	8010200381* 8010200381* 8010200381* 8010200381*	PR PR PR PR PR	WATSON, E C HATTS, K HEBD, T. M WEBSTER, E H WEBSTER, E, H	8010150628* 8010140196 8010210584 8010280597 8010150565*	70-1257 40-4492 50-537 A 50-339 S 50-338 G	WHEELER, J T WHICHER, J M WHICHER, J M WHICHER, J M WHITEBELL, D E	8010270073* 8010160787 8010160787 8010200589 8010270108*	CONTRACT 50-367 0 50-367 0 50-367 0 GA999
VOLLEN, R, J VOLLEN, R, J VOLLEN, R J VOLLEN, R J VOLLEN, R J	8010160787 8010200589 8010200589 8010210776 8010210776	50-347	WEDEL: PO WEIDERT; L, L WEIL; E 8 WEINHOLD, E. H	8010140178* 8010160469 8010230009 8010300488 8010270433	70-1447 50-133 R NUREO 50-478 6 50-443 Q	WHITESELL.D E WHITESELL.D E WHITESELL.D E WHITESELL.D E	8010210258* 8010080374 8010220572* 8010060179 8010080167*	71-9014 50-286 B 71-9001 PR GA999
VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R, J.	8010300061 8010300067* 8010300075* 8010300088* 8010300061	50-367 Q 50-367 Q 50-367 Q 50-367 Q 50-367 Q	Weiss, D. Weiss, E. R Weiss, D. Weiss, D. Weiss, D.	8010200352* 8010020200 8010230203* 8010010747 8010140641	70-143 70-143 71-6294 ORO 40-6659	WHITE, D WHITEBELL, D E WHITEBELL, D E WHITEBELL, D E	8010310335 8010080111* 8010020113 8010240016* 8010240584*	PROJ QA999 50-244 g QA999 QA999
VOLLEN, R. J.	8010300069*	50-367 Q	Weiss, E. R.	8010020670	50-201 0	WHITESELL, D E	8010270543*	GA999
VOLLEN, R. J.	8010300075*	50-367 Q	Weiss, E. R	8010020670	50-201 0	WHITE, L D	8010020075	50-244 G
VOLLEN, R. J.	8010300088*	50-367 Q	Weiss, E. R	8010030111	50-289 0	WHITESELL, D, E	8010270011*	GA999
VORDERBRUEGOEN	8010170662*	50-528 Q	Weiss, E. R	8010030111	50-289 0	WHITE, L D	8010010825	50-244 G
VOTH, M. H.	8010200638	50-54 P	Weiss, E. R	8010080422	50-289 0	WHITE, L D	8010010788	50-244 G
VDYLEG, J. L	8010070448	NUREO	Wetss, E. R	8010140012	50-287 0	WHITE, L D	8010010666	50-244
VRANKEN, J. V.	8010290391	70-1308	Weiss, E. R	8010080420	50-443 0	WHITEHEAD, M,	8010140066	
VYAG, B.	8010300336	RE8	Weiss, E. R	8010140012	50-289 0	WHITE, L, D	8009160559	
HAGNER, A. G	8010030492*	50-416 Q	Weiss, N.	8010150374	50-289 H	WHITE, L D	8010010831	
HAGNER, H. J	8010170428*	50-528 G	Weiss, E. R	8010070037	PR	WHITENER, H L,	8010270193*	
Hadner, H J	8010230084*	50-997 G	Weiss, e. r.	8010070041*	PR	WHITE,R J	8010010304#	CONTRACT
Hatel, H, W	8010210009	50-255 S	Weiss, e. r.	8010070037	PR	WHITE,L D	8010240055#	50-244 G
Wafel, H W	8010270171	50-255 S	Weiss, e. r.	8010070041*	PR	WHITEBELL,D,E	8010240022#	GA999
Walbridge, W C.	8010070190*	50-312 G	Weiss, e. r.	8010100393	50~45B A	WHITE,L D	8010010719	50-244 P
Walbridge, W C.	8010230184	50-312 Q	Weiss, e. r.	8010070037	PR	WHITE,L D.	8010020376	50-244 P
WALBRIDGE, W.C. WALKER, R.D. WALKER, J. WALKER, B.H. WALL, L.B.	8010300480 8010140145# 8010140050 8010040170 8010270489	50-312 G 50-373 G PR PR 40-8743	HE188, E. R HE188, D HE188, E. R HE188, E. R WE188, E. R.	8010070041* 8010160684 8010210260 8010210260 8010270452	PR 71-9010 30-443 0 50-443 0 50-443 0	WHITE, L D. WHITE, L D. WHITE, L D. WHITE, L D. WHITE, E B.	8010030375 8010300637 8010170005 8010060276 8010070400	50-244 F 50-244 G 50-213 S 50-244 S

	ACCEBSION NUMBER	BUBJECT CATEGORY		ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
AVTHOR MATTE, L. D MATTE, L. O	8010090372 8010140477 8010160476 8010310373 8010160468*	50-244 J 50-244 S 50-244 V 50-244 Q 50-293 R	ROHTUA LINDBJIH B KINDBJIH J CINDBJIH J CINDBJIH KINDBJIH	8010010584* 8010160176* 8010080516 8010080439 8010080441*	50-280 8 CONTRACT 50-369 0 50-280 8 50-280 8	HULLER, O E HULLER, O E HULLER, O, E HUNDERLICH, J R WUNDERLICH, J R	8010160721 8010070078 8010210375 8010160358* 8010140512*	PR 50-461 Q 50-461 A 50-254 S 50-254 S
WICHERS, D.L. WICHERS, D.L. WICHERS, D.L. WICHERS, D.L. WICHERS, W.A.	8010030203 8010020566 8010020415 8010270562 8010140003*	40-8502 40-8502 40-8502 40-8502 50-321 G	HILBON, J L HILBON, J L HILBON, J, L HILBON, J L HILBON, H E.	8010080395 8010080399* 8010150481 8010150486* 8010220490	50-280 8 50-280 8 50-280 8 50-280 8 50-27 F	Yamaquch I, T Yamana, K Yamana, K Yamana, K Yamana, K	8010160213 8010060185 8010160237 8010060189* 8010300291	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
WIDMER.W A WIDMER.W A WIDMER.W A WIDMER.W A WIDMER.W A	8010070273 8010190340 8010210352 8010150381 8010150536	50-321 Q 50-321 G 50-321 F 50-321 P 50-366 P	MILSON, J. L WILSON, J. L WILSON, J. L WILSON, J. L	8010200491 8010200499* 8010200506* 8010200513* 8010200524*	50-290 8 50-280 8 90-280 8 50-280 8 50-280 8	YANDELL,L A YBARRONDO,L J YEAGER,W A YIN,I T YIN,I.T	8010010072* 8010300142 8010220101 8010270576* 8010290124*	50-285 G RES 50-320 T GA999 50-358 G
WIDNER, WA WIDNER, WA WIDNER, WA WIDNER, WA WIDNER, WA	8010210612 8010210303 8010230418 8010240213 8010230368	50-321 P 50-321 Q 50-321 P 50-321 P 90-366 P	Hilson, J.L Hilson, J.L Hilson, J.L Wilson, J.L Hilson, J.L	8010280558 8010280565* 8010270166* 8010280506 8010280512*	50-280 8 50-280 8 50-280 8 50-281 8 50-281 8	YORE, J. R YOUNG, O YOUNG, T YOUNGBLOOD, B J YOUNG, Q T	8010140042* 8010170319 8010270138* 8010010811 8010150357*	50-556 0 50-245 0 50-275 0 50-339 P CONTRACT
HIDMER, WA HIEDEMAN, DO. HIEDEMAN, D HIEGEMANN, RA HIEGEMANN, RA	8010310361 8010220452 8010220125* 8010070270* 8010100301	50-321 P I&E 40-2384 50-369 A 50-247 P	WILVERDINO, O. H WILVERDINO, O. H WILVERDINO, O. H WINDHAM, J. R. WINKER, L. J	8010220413 8010280374 8010280378 8010210781* 8010060202	50-333 P 50-284 H 50-333 H 50-364 H FR	YQUNOBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8010100232 8010160022 8010160321 8010160331 8010170039	50-438 F 50-440 A 50-369 F 50-369 F
NEOCINS, J T WICOINS, J, WICOINS, J T WICOINS, E J WICCINS, E J	8010100075* 8010240064* 8010240124* 8010010272 8010010286	50-272	HIBNER, J W. WITHERBPOON, J HITHERB, B D WITHERB, B D WITHERB, B, D	8010180322* 8010220599 8010020341 8010020345* 8010070299	CONTRACT REB 50-344 P 50-344 P 50-344 F	AONAGETOOP B 7 AONAGETOOP B 7 AONAGETOOP B 7 AONAGETOOP B 7	8010170044 8010210751 8010280035* 8010300472 8010230015	50-460 A 50-275 Q 50-367 A NUREQ
Nicointon, d Nicoins, e J. Nicoins, e J. Nicoins, e J. Nicoins, e J.	8010080606 8010010252 8010020585 8010080358 8010070220	50-954 V CONTRACT CONTRACT CONTRACT CONTRACT	WITHERS, B. D WITHERS, B. D WITHERS, B. D WITHERS, B. D WITHERS, B. D	8010080522 8010080592 8010280447 8010280498 8010280597	50-344 H 50-344 P 50-344 F 50-344 G TOPREP	YDUNKER, L. YTHIER, P YUHAB, O P, YUHAB, O YUNDT, C. P	8010200276* 8010200366* 80103160788 8010160788 8010200187	CONTRACT 50-206 0 50-206 \$ 71-9010
MEGGINS, E MEGGINS, E MILBORN, L MILBORN, L MILGOX, J. D	8010170320 8010310572 8010220644* 8010210384* 8010020779*	CONTRACT CONTRACT 40-4492 40-8584 50-439 G	HITHERB, B, D HITHERB, B, D HITHERB, B D, HITHROW, O, C HITHROW, O C	8010310390 8010300421 8010300424* 8010070501 8010070520*	50-344 F 50-344 P 50-344 F 50-255 S 50-255 S	YUNDT.C P YUNDT.C P YUNDT.C P. YUNDT.C P.	8010070337 8010140474 8010150439 8010160587 8010150383	50-344 B 50-344 B 50-344 B 50-344 B 50-344 B
HILCOX, DP HILDERF. E HILKERSON, I. O HILKEY, A H HILKEY, A H	8010140378* 8010100113* 8010170371* 8010270353* 8010280508*	50-201 R 50-443 H CONTRACT 50-327 B 50-327 8	WITHROW, O. C WITHROW, O. C WITHROW, O. C. WITHROW, O. C WOESSNER, J. D	8010200554 8010210574 8010220533 8010220654 8010170050*	50-155 8 50-155 P 50-155 P 50-155 8 50-312 G	YUNDT.C.P YUNDT.C.P YUNDT.C.P. YUNDT.G.P. YUNN.G	8010210700 8010210742 8010210385 8010280347 8010100240	50-344 8 50-344 B 50-344 F PR
MILKINSON E P MILLCUTT O. J. MILLETT D. J. MILLETT D. J. MILLIAMS C. C.	8010210202 8010080378 8010170363* 8010300438* 8008060283	REGOD NUREG 50-397 G 50-243 G 50-546 B	HOFFORD, A. W HOFFORD, A. W. HOFFORD, A. W. HOHLD, P. R. WOHLBEN, A. B.	8010020230* 8010030378 8010200421 8010240031* 8010230457*	50-322	ZABLOCKI, C. J. ZAHLER, R. E ZAHLER, R. E ZAHLER, R. E ZAHLER, R. E	8010280013 8010280013 8010280013 8010270383 8010270383	90-289 0 50-289 0 50-289 0 50-289 0
HILLIAMS C C HILLIAMS C C HILLIAMS C L. HILLIAMS C C. HILLIAMS R L	8010200691* 8010100421 8010160002* 8010200674* 8010020746	50-546	HOLF, J F WOLFBEIN, B L WOLFE, B J HOLFE, B, J WOLFE, B, J	6010070023 8010240547* 8010100328* 8010020724 8010030448	50-237 0 CDNTRACT 50-466 U 50-466 0	zahlerir.e Zahlerir e Zanardi, g Zarakabip Zarakabip.	8010300687 8010300687 8010230376# 8010030133# 8010010692	50-269 9 50-366 P 50-247 @ 50-3 G
Halliams, F. J. Halliamson, E. L. Halliams, C. C. Halliams, C. C. Halliams, C. C.	8010240133* 8010170052* 8010070314 8010100012* 8010070245	50-247	HOLFE, S. J.	80100B0247 8010160772 8010200481 8010200609 8010200598	50-466	Zarakas, p Zarakas, p Zarakas, p. Zarakas, p. Zarakas, p.	8010220049 8010300654 8010270217 8010220209 8010200310	50-3 0 50-247 0 PR 50-247 R
WILLIAMS, C. C WILLIAMS, R. L WILLIAMS, C. C. WILLIB, F. WILLIB, F.	8010270133+ 8010230614 8010200678+ 8010310387+ 8010150318+	40-299 50-546 G CONTRACT	WOLFE, B J. WOLFE, B J. WOLFE, B J. WOLFE, B. WOLTNER, E. WONG, T.	8010240053 8010300060 8010100235 8010010341# 8010280371	50-466	Zarakab, p Zarakab, p. Zarakab, p Zarakab, p. Zarakab, p.	B010240543 8010070605 B010310491 8010150382 8010150493	PR 50-247 P 50-247 Q 50-3 J 50-247 S
WILLIS, H. M. PICLIS, H. M. WILLIAMS, F. C. WILLIAMS, F. C. WILLIAMS, F. C.	8010210518 8010210518 8010140488 8010140493 8010140493	+ 50-275 0 PR + PR	HOOD, E C HOODHEAD, C P. HOODHEAD, C P HOODHEAD, C P. HOODB, G. R	8010140437 8010070492 8010170367 8010310458 8010010233	50-309 B 50-409 0 50-510 G 50-219 0 50-142 0	Zarakab, p Zarakab, p Zarakab, p Zarakab, p Zarakab, p.	8010150487 8010280393 8010240425 8010240519 8010240510	90-247 R 90-3 R 90-3 W 50-247 P
MICLIANS, O. L. HILLIANS, O. L. MILLIANS, O. L. MILLIANS, O. L. MILLIANS, O. L.	8010140261 8010140261 8010160589 8010140263 8010140263	50-389 M 50-389 M 50-389 M * 50-389 M * 50-389 M	HOODSMALL, N A. HOOLEVER, E J HOOLEVER, E. J HOOLEVER, E. J HOOLEVER, E. J.	8010140458* 8010150203* 8010020110 8010010690 8010270104*	50-412 8 50-412 9 50-412 9	ZAVADOBKI:R W ZEFF.D W ZEIDERB:R H ZIBULBKY:H ZIBULBKY:H	8010240539 8010170059 8010290290 8010010417 8010240284	70-1201 * 50-155 P * 70-135 * 70-820
WILLIAMS, G. Q. WILLIAMS, L. Q WILSON, B. D. WILSON, A. E. WILSON, B.	8010280058 8010310430 8010060104 8010040174 8010040169	* 50-440 G 70-2909 XPORTLIC * 50-284 G	WOOLEVER, E. J WRAY, J. R. WRIGHT, R. W WRIGHT, R. WRIGHT, G. C.	8010200380 8010160061* 8010160353 8010070321 8010150126*	50~553 B 50-366 B	ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIMMERMAN, R. P.	7812080199 7901300018 7912180081 8003270083 8010020771	50-255 P 50-253 P 50-255 P * 50-245 Q
Milbon, B. D. Milbon, C. Milbon, D. M. Milbon, J. L. Milbon, J. L.	8010160033 8010310269 8010020401 8010010576 8010010586	90-369 H 50-280 B	HRIGHT, B HUERTH, U HULFF, H. HULFF, H HULLER, Q. E	8010310268 8010140323 8010080199 8010230023 8010060065	PRGJ 50-387 Q NUREO NUREO 50-461 Q	ZIMMERMANJR P ZINN, P. K ZIRNITE, P ZIRWAG, K ZIRWAG, K.	8010240176 8010230645 8010270214 8010210661 8010280914	# 50-320 H 50-320 P # 50-237 B

41171400	ACCEBBION	SUBJEC	
AUTHOR	NUMBER	CATEGO	RY
ZITTEL,H E	B010150579	RES	
ZITTEL,H E	B010170101	RES	
ZITTEL.H E	8010300304	RES	
ZUDANS, J J	B010070619*	50-289	0
I L'BNADNZ	8010200205#	50-289	T
ZUFELT.E L	8010100291*	50-333	R
ZUKOR, D	8010170319	50-245	0
ZULLA, 8, 8	8010020757*		
ZULLA, S S	8010010673		
ZULLA, 8 8	8010010221	50-284	a
ZULLA, B B	8010270198	50-286	G
ZULLA, B, B	8010070286	50-286	P
ZULLA, B B	8010210412	50-284	R
ZUMBRUN, R. A	8010070400	PR	
ZURAKOWSKI, P	8010150518#	50-320	G
ZWETZIO, Q. B	8010150079#	50-312	a
ZHETZIO, O, B	8010090153		
ZWETZIO, O B	8010100391	90-206	8
ZWETZIO, O H	8010300024+	50-312	ã

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

АОНТОЯ	ACCESSION	ans/ec.	r	AUTHOR	10055574514	011b 1505
AFFILIATION	NUMBER	CATEOD	RY	AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ACE Federal Reporters, Inc	8010310577*	CONTRAC	1		8010230488	50-364 Q
AFL-C10 ARMCO, Inc	8010020100 8010270116#	FOIA GA999			9010240040 8010240134*	50-364 Q 50-348 Q
AUSTIN COLLEGE SHERMAN, TX	8010160002*	COHMISS	BION		B010240134*	50-34B Q
Access Corp	8010090070*	CONTRAC			8010280424	50-364 A
Advisory Council on Historic Preservation Asbabian Associates	8010270489 8010080282	40-8743 NUREO	1		8010280462	50-34B B
- Inmater Hassified	8010080287*	NUREG			8010280463 8010280464	50-364 A 50-364 P
	8010090290*	NUREO			8010280497	50-348 P
	8010080343	NUREG			B0102B0502#	50-349 B
	8010150174 8010230012	NUREG		Alabama, State of	8010300459 8010160170*	50~364 A CONTRACT
	8010230034	NUREQ		Alaska, State of	8010060179	PR
	8010230044 8010230048	NUREO		Aldrich Chamical Co , Inc (subs of	8010140066 8010160225	PR XPORTLIC
Agriculture, Dept of	8010220696*	CONTRAC	• •	Sigma-Aldrich Corp)	B0101802K3	AFORILAG
Air Force, Dept of	8010010272#	40-8385			8010160227#	XPORTL10
Ata Bardanta t at t a a	8010010296#	40-8385			8010290141	XPORTLIC
Air Products & Chemicals, Inc Air and Water Pollution Patrol	8010160261 8010280070*	XPORTLI:			8010290175* 8010300277	XPORTLIC XPORTLIC
					8010300285*	XPORTL1C
Alabama Power Co	8009240519 800924052 2 *	50-364 50-364	Å	Allan Spector & Associates, Ltd	8009090223#	40-1162
	8010010676#	50~349	à	Allegheny Electric Cooperative, Inc	B010300561	50-387 Q
	8010030230 8010040152#	50~344 50~348	A		8010300561 8010300606	50-387 G 50-387 G
			P		40400E010B	50-387 G
	8010060325 8010070275	50~348 50~364	P		8010300413	50-387 Q
	B010070305	50-364	P		8010300613	50-387 Q
	8010070341 8010070395	50-364 50-364	A	Allied Chemical Corp Allis-Chalmers Corp.	8010230017 80102902904	50-250 P 50-155 P
				American Association of Physicists in	8010040040*	COMMISSION
	8010070398* 8010070545	50~364 50~364	A	Medicine		
	8010070599	50-364	Ä	American Electric Power Co , Inc	8010210728	PR
	8010070616	50-348	8	American Friends Service Committee American Institute of Chemical Engineers	8010310212* 8010100134	FQIA PR
	E010070621*	50-348		American Mining Congress	8010140074	PR
	8010080423 8010080452	50-344 50-348	A B		8010230506	PR
	B0100B0457*	50-348	8	American Nuclear Insurers	8010070419	MISC
	8010090287	50-348 50-348	G G	American Nuclear Bociety	8010100432 8010150596	PR 27-39
	8010100126				B010150603	27-39
	8010100133	50-348	9		8010160728	PR
	8010140289 8010140305	50-364 50-348	A P	American Warming & Ventilating, Inc.	8010020415	50-329 8
	8010140305	50-349	P	Annual An Annual Webs No.	B010240549	50-358 8
	B010140346	50-364	A	Anatonda Co. Anaconda Ketal Hora Div.	8007050288 8007050273*	50-382 B
	8010140351	50-348 50-348	F	Anti-Nuclear Oraup Representing York	B010100067	50-287 T
	8010140467 8010150387	50-344	A	Applied Physical Technology, Inc	8010090214#	CONTRACT
	B010200425	50-364	A	Applied Science Associates, Inc.	9010200223+	CONTRACT
	8010200590	50-364	A	Argunne National Laboratory	8010170078 8010230007	NUREO NUREO
	8010210402	50-348	R		8010240223	PR
	8010210406# 8010210718	50-348 50-348	R 8		8010240274	ACRS
	8010210726*	50-348	8		8010240559*	70-25
	B010210731*	50-34B	8	Arizona Public Service Co	8010020446	50-528 B

AUTHOR AFFIL IATION	ACCEBBION NUMBER	EUBJEC CATEO	DRY .	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT
	8010040253 8010100304 8010140539 8010210417 8010240198	50-529 50-528 50-528 50-528 PR	8		801 0280444 801 0280522 801 0280536* 801 0280544 801 0280552*	50-313 8 50-313 8 50-313 8 50-313 8 50-313 8
	8010280417 8010290324 8010290371 8010300145 8010310089	50-528 50-528 50-528 50-528 50-528	A 8 8 0		8010280572* 8010280583 8010280591* 8010280644 8010290337	50-313 B 50-313 B 50-313 B 50-313 F 50-313 F
Arizona. Univ of Artansas Power & Light Co	8010290093# 8010010024# 8010010494 8010010500#	CONTRAC E1C-OE 50-313 50-313 50-313	or o s s		8010310285 8010310285 8010310294* 8010310294* 8010310345	50-313 P 50-313 P 50-313 P 50-313 P
	8010010516 8010010517* 8010010563 8010010613 8010070280	50-313 50-313 50-313 50-368 50-313	R R F P	Arkansas, State of Armadillo Coalition of Texas	8010310345 8010310381 8010310394 8010170452* 8010020694	50-313 P 50-313 R 50-313 P CDNTRACT FOIA
	8010070280 8010070293 8010070293 8010070308 8010070308	50-313 50-313 50-313 50-313 50-313	Р Р Р	Armstrong Civil Defense Army, Dept. of Army, Dept. of, Corps of Engineers	8010280207* 8010070033* 8010170555* 8010310044 8010200701*	FOIA CONTRACT CONTRACT PT21 CONTRACT
	8010070310* 8010070310* 8010070376 8010070384* 8010070442	50-313 50-313 50-369 50-369 50-369	P B S R	Assessment Designs, Inc Atlantic-RichPield Co	8010290357* 8010170317* 8010280151* 8010280166* 8010280178*	50-920 P CONTRACT FOIA FOIA FOIA
	8010070461 8010070489 8010070494 8010070498* 8010070510	50-348 845-05 50-368 50-368 50-313	я В Р Р	Atias Minerals	8010280187* 8010280194* 8010280197* 8010280218* 8010010068	FOIA FOIA FOIA FOIA 40-3453
	8010070510 8010070534 8010070540 8010070543# 8010070549#	50-313 50-368 50-313 50-368 50-313	F 8 8 8 8		8010150454 8010200085 8010200171 8010220373 8010220398#	40~3453 40~3453 40~3453 40~3453 40~3453
	8010070560 8010070563 8010070567# 8010070573 8010070577#	50-313 846-06 50-313 50-313 50-368	6 9 9 8	Atomic Industrial Forum	8010010127* 8010020001 8010060014 8010100051 8010210010	PRM 50-201 9 NUREO PR PR
	8010070\$B2# 8010070414 8010070417 8010070420 8010070422*	50-313 50-369 50-313 50-313 50-368	S 8 9 8	Australia Austria	8010220204 8010230591 8010160260 8010160064 8010220370	PR PR XPORTLIC XPORTLIC XPORTLIC
	8010070423* 8010070625* 8010080331 8010080428 8010080430*	50-313 50-313 50-313 50-369 50-368	8 5 8	Automated Correspondence Systems, Inc. Automated Sciences Oroup, Inc. Automateion Industries, Inc Babcock & Hilcox Co	8010140238* 8010020703* 8010100245* 8010020491* 8010040225	CONTRACT CONTRACT 40-4920 70-138 TOPREP
	8010080477 8010080485* 8010160712 8010160712 8010170238	50-368 50-368 50-313 50-313 50-313	8 0 0 8		8010040282 8010070144 8010070327 8010150314 8010150635	50-13 J 70-364 70-924 TOPREP 70-27
	8010170245* 8010170512 8010170523 8010200443 8010210246	50-313 50-313 50-368 50-313 50-313	8 P P Q		8010150435 8010150435 8010150435 8010150435 8010170059 8010200253	70-27 70-27 70-27 70-1801 70-824
	8010210246 8010210420 8010210423* 8010210424 8010210428*	50-313 50-313 50-313 50-368 50-368	Q R R R		8010200427 8010200426* 8010210065 8010210263 8010210283	TOPREP TOPREP REGOD 70-27 70-27
	8010210430* 8010210454 8010220499 8010220499 8010230081	50-245 50-313 50-313 50-313 50-313	R P P Q		8010210283 8010210283 8010210283 8010270423 8010280362	70-27 70-27 70-27 71-7039 TOPREP
	8010240085 8010240112 8010240112 8010240396	50-313 50-313 50-313 50-313	9 9 9 P	Babcock & Wilcox Co., Naval Nuclear Fuel Div	8010280365#	TOPREP 70-27
	8010240541 8010240542*	50~368 50~369	k к		8010040021 8010040023# 8010040465	70-27 70-27 70-27
	8010270333 8010280227 8010280331 8010280331	50-313 50-348 50-313 50-313	Q K P	Babouck & Milcox Co., Nuclear Haterial Div.	8010210759 8010230469 8008210614#	70-27 70-27 71-6400

AUTHOR AFFILIATION	ACCESSION KUMBER	BUBJECT CATEGORY	Y	AUTHOR AFFILIATION	ACCEBBION NUMBER	GUBJECT CATEOOR	Y
	8008210615* 8009250450 8009250454* 8010020202* 8010060028	71-6400 71-6400 71-6400 70-364 70-364		Bechtel Corp	8010310574 8010010671* 8010040320* 8010060322* 8010060326*	RES 50-250 50-293 50-293 50-293	P P P
	8010150592 8010150543 8010200233 8010200240 8010210247*	70-27 70-364 70-27 70-27 70-135			8010040328* 8010040332* 8010150405* 8010160403* 8010160640*	50-293 50-293 50-155 50-255 50-293	6 6 6
Saker & Botts	8010010219 8010140543 8010140550+ 8010140573* 8010140589*		0000	Bechtel Mational, Inc. Bechtel Power Corp. (subs. of Bechtel Corp.)	8010200009 8010290287* 8010290321 8010300470* 8010200413	PR 50-195 50-320 50-364 NUREQ	P P A
	8010140599+ 8010140020 8010140784 8010270522 8010280020	50-466	0000		8010210005 8010210009 8010220197 8010270171 8010270372*	50-354 50-255 PR 50-255 GA799	8 8
Baltimore Gas & Electric Co	8010270374 8010300377 8010310048 8010310051 8010010170#	50-466 50-466	0 0 0 0	Belser, Belser, & Baker Benjamin F. Shaw Co (subs. of Blount, Inc.)	8010300473* 8010200395 6010210455*	50-364 50-201 GATT	Å
	8010010174* 8010010201* 8010020184 8010020184 8010020211	50-317 50-317	0 0 0 0	Bequail.A. Binder, Elster, Hendelson & Wheeler, Inc. Black & Veatch Black Hills Alliance	8010170147* 8010010278* 8010010273* 801010260725* 8010140593 8010140601	NUREO CONTRACT CONTRACT QAYYY 40-297 40-1341	
	8010020211 8010030378 8010030377* 8010060252 8010060261*	50-317 50-317	9 8 8	Boeing Co. Boeing Computer Services, Inc. (subs. of	8010140625 8010270003 8010160080	40-1162 40-1341 40-7783 CONTRACT	
	8010060265 8010060273*	50-318 50-318	8	Boring Co 1 Borg-Harner Corp Byron Jackson Fung Div Boston College	8010290149 8010090072#	XPORTLIC CONTRACT	
	8010060311 8010050313* 8010140372 8010140402*	50-317 50-317 50-317 50-317	8 8	Boston Edison Go.	8010010215 8010010237 8010010304 8010010311# 8010010467	50-293 50-293 50-293 50-293 50-293	G 8 8
	8010160207 8010160463 8010160465# 8010160513	\$0-317	8 8 P		8010010474* 8010020314 8010020453 8010020462*	50-273 50-273 50-273 50-273 50-273	8 F 8
	8010160367 8010160573# 8010200418 8010200432 8010200434#	50-318	6 6 8 8		8010020496 8010020498* 8010030307 8010060239	50~293 50~293 50~293 50~293 50~293	P P G SS S
	8010200505 8010210666 8010210672* 8010210676 8010210684*	50-317	8 8 8		8010040246* 8010040319 8010070445 8010070518 8010070527*	50-293 50-293 50-293 50-293	P P 88
	8010230434 8010230434 8010230438* 8010230438*	50-317 50-317 50-317	R R R	`	8010090401 8010090404 8010090408* 8010090347	50-471 50-471 50-471 50-273	8 A A 8
	8010240268 8010240421 8010240426*	50-317	0 8 8		8010070352* 8010140340 8010140392	50-293 50-293 50-471	E DE
	8010280571 8010310263 8010310310 8010310315*	50-317 50-318 50-318	8 F 8		8010140496 8010140496 8010160466 8010160468*	50-471 50-293 50-293 50-293	BERR
Barr Engineering Co	8010310320 8010310330 80103103594 8010270435	50-317	\$ \$ \$		8010160506 8010160657 8010200427 8010200431*	50-293 50-293 50-293 50-293	J F 8
Battelle Memorial Institute, Columbus Laboratories	8010010645	71-5957			8010210554 8010210556	50-293 50-293	8
	8010010653* 8010020076 8010020122 8010080539		J		8010210618 8010210647 8010210712 8010210715	50-293 50-293 60-293 60-293	F8980
Battelle Memorial Institute, Pacific Northwest Laboratory	8010080863* 8010170073* 8010200291# 8010150078*	CONTRACT CONTRACT CONTRACT 70-1257			8010210722+ 8010210724+ 8010220054 8010220511	50-293 50-293 50-293 50-293	8 808
	8010150123	REB			B010220536# B010240237	50-293 50-293	R
	8010150597 8010150628# 8010310566	RES 70-1237 RES			8010240240# 8010240410	50-293 50-293	R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUDJEC.	45
	8010240418* 8010270213 8010270314 8010280407 8010280414*	50-293 50-293 50-293 50-293 50-293	8 0 8 8		8010070441 8010070449+ 8010070454 8010070528 8010070547	50-324 50-324 50-261 50-261 50-324	8 8 F & &
	8010280490 8010280494* 8010280497 8010280503* 8010280574	50-273 50-273 50-273 50-273 50-273	8 8 8		8010070551* 8010070557 8010070558* 8010070564* 8010070575	50-261 50-325 50-324 50-325 50-325	8 6 6
	8010280577* 8010290351 8010310350 8010310401 8010310451	50-293 50-293 50-293 50-293 50-293	8 P F O		8010070586* 8010070593 8010070600 8010070601* 8010070604*	50-325 50-324 50-261 50-324 50-261	9 8 9 8
Brand-Rex Co Brigham Young Univ Brittel:F C Brookhaven National Laboratory	8010310501 8010240591 8010010327* 8010170158* 8010080186	50-273 50-369 50-262 NUREO NUREO	8 9 0		8010080215 8010100325 8010100332* 8010100335 8010100338	50-400 50-324 50-324 50-324 50-261	9 9 8 P
	8010080177 8010150130 8010150472 8010150480* 8010220627	NUREG RES TOPREP TOPREP RES			8010100341* 8010140035 8010140131* 8010140440 8010140472*	50-324 50-400 50-400 50-324 50-324	8 0 8 8
	8010230003 8010230023 8010230024 8010230028 8010300334	NUREO NUREO NUREO NUREO RES			8010140481 8010140487* 8010150212 8010150256 8010150265	50-325 50-325 50-261 50-261 50-261	8 0 0
Brown & Root Corp (subs of Halliburton Corp)		QA999			801015028B 8010150316	50-400 50-324	Q R
Brown & Williams	8010210006 8010140261 8010140263*	50-498 50-389 50-389	B H		8010150318* 8010150346 8010150386	50-324 50-324 50-324	8 0 8
Brownsville,TX Bruce Norton	8010070541 8010190024 8010220320* 8010160053 8010160056	50-445 50-445 50-275 50-275	H H H G G G		8010150386 8010150389* 8010150389* 8010150423 8010150425*	50-324 50-324 50-324 50-261 50-261	RRRPP
Burns & Roe Co G&P Telephone Co. of Maryland	8010240544 8010010279* 8010210011 8010280204 8010280208* 8010270130	50-133 CONTRACT PR TOPREP TOPREP FOIA			8010150445 8010150462* 8010150503 8010150504 8010150510	50-261 50-261 50-255 50-325 50-324	R 8 8 8
C-E Operating Plants Cwners Group C-E Power Systems	8010310396 8010170226 8010210117* 8010280587 8010310399*	NUREO PR MISC NUREO NUREO			8010150520 8010150521* 8010150523 8010150524* 8010150527*	50-324 50-324 50-325 50-324 50-325	
CONOCO, Inc (Continental Oi) Co) California Institute of Technology California, State of	E010170133 8010240039 8010240327 8010200014 8010030385	40-8743 40-8743 40-8743 ACR8 50-275	o		8010150531* 8010150646* 8010160517 8010170242 8010170547	50-325 50-324 50-324 PR 50-261	9 0 P
	8010080300 8010080300 8010080308* 8010080308* 8010160167*	50-275 50-275 50-275 50-275 CONTRACT	0000		8010200471 8010200476* 8010200575 8010200581* 801020058B	50-261 50-261 50-261 50-261 50-324	P 8 8 8
California, Univ. of, Los Angeles	8010160544 8010160583 8010200682 8010240311* 8010010233	50-275 50-275 50-275 50-275 50-142	0 0 0 H 0		8010200597* 8010210270 8010210479 8010210498 8010210501*	50-324 50-324 50-325 50-324 50-324	8 9 8
California, Univ of, Santa Cruz Canada	8010200666* 8010230042 8010080099 8010170277 8010200070	CONTRACT NUREG FOIA NUREG State Pr			8010210667 8010210667 8010210674 8010210680* 8010230185	50-324 50-324 50-324 50-324 50-400	8 8 8
Cenberra Industries Capital Legal Foundation Capitol Communication Bystems Carolina Environmental Study Group	8010300005 8010020663 8010170323* 8010140587 8010230692	REOOD 50-201 CONTRACT 50-269 50-369	6		8010230357 8010230357 8010240067 8010240286 8010240405	50-324 50-324 50-325 50-261 50-324	0 0 0 P
Carolina Power & Light Co.	8010020363 8010020469 8010060209 8010060213* 8010060292	50-324 50-261 50-324 50-324 50-325	P P 8 8		8010240463 8010240472* 8010240548 8010240548 8010270301	50-324 50-324 50-324 50-324 50-261	8 8 6
	8010040298* 8010070297 8010070352 8010070352	50-325 50-325 50-324 50-324	CCDB		8010270382 8010270383* 8010270400 8010270400 8010270400	50-261 50-261 50-400 50-400 50-400	9 8 8 8

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEOURY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	
	B010270400 B010270402* B010270402* B010270402* B010270402*	50-400 F 50-400 F 50-400 F 50-400 F 50-400 F		8010020286 8010020286 8010020406 8010020417* 8010020425	50-295 50-295 50-265 50-265 50-265	P 8 9
	8010280379 8010280402 8010280406* 8010280538 8010280542*	50-241 F 50-325 F 50-325 F 50-325 F 50-325 F		6010020435 8010020435 9010020436* 8010020437 8010020437	50-373 50-373 50-265 50-454 50-454	A A B A A
	8010280570 8010280576* 8010280606* 8010310341* 8010310393	50-324 6 50-324 6 50-255 6 50-400 6 50-400 6		8010020439 8010020439 8010020444# 8010020444# 8010020444#	50-454 50-454 50-373 50-373 50-373	AAAK
	8010310393 8010310393 8010310393 6010310397* 8010310397*	50-400 A 50-400 A 50-400 A 50-400 A		8010020454 8010020459* 8010020459* 8010020471* 8010020478	50-373 50-373 50-373 50-261 50-295	X X X P &
Catholic Univ Center for Development Policy Center for Law & Social Policy	8010310397* 8010310397* 8010010442* 6010210183 8010090042	50-400 A 50-400 A CONTRACT FOIA FOIA		8010020484* 8010020532 8010020537* 8010070326 8010070329*	50-295 50-295 50-295 50-10 50-10	
Center for Law in the Public Interest Chem-Nuclear Systems, Inc	8010070532 8010200174 8010220554 8010070343* 8010100424	50-445 F 50-275 G 50-275 G 50-364 A 71-6375		8010070359 8010070347* 8010070374 8010070430 8010070430	50-254 50-254 50-10 50-10 50-10	8 8 8 8
Chemtron Corp Chemapeats Bay Foundation Chevron Industries: Inc., Chevron Resources Co. Div.	8010200604* 8010230172 8010240614* 8010270326	CONTRACT 50-413 E 50-320 F REGOD		8010070430 8010070430 8010070430 8010070430 8010070430	50-10 50-10 50-10 50-10 50-10	P P P
Cincinnati Gas & Electric Co Citizens Association for Bound Energy	8008200140 8010270313* 8010240035* 8010240035 8010140015	50-358 F 50-358 C 50-358 S 50-358 O FR 50-445 C		8010070430 8010070430 8010070500 8010070509* 8010070535	50-10 50-10 50-254 50-254 50-237	P B B
Citizens Concerned About Nuclear Power,	8010200690 8010200690	50-445 G 50-498 G		8010070544+ 8010070554 8010070554 8010070554	50-237 50-237 50-237 50-237	8 P P
Citizens United for Responsible Energy Citizens for a Better Environment	8010100152 8010220663 8010240535	PR 30-201 G FOIA		8010070554 8010070554	50-237 50-237	P P
Cleveland Electric Illuminating Co	8010030296 8010030370 8010030370 8010090115	50-440 E 50-440 E 50-440 E		8010070554 8010070587 8010070587 8010070603	50-237 50-275 50-275 50-249	P P B
Claveland-Cliffs Iron Co.	8010090139 8010240070 8010240070 8009100819 8009100820*	50-440 G 50-440 G 50-440 G 40-8714 40-8714		8010070612* 8010080150 8010080600 8010070070 8010070157	50-247 PR 50-275 50-254 50-237	g 0 0
Cohn, D B. Cole & Go Colorado State Univ	8007100823* 8010020047 8010020055* 8010140197* 8010140128*	40-8714 50-367 0 50-367 0 50-289 0 CONTRACT		8010070159 8010070159 8010070159 8010090159 8010090159	50-237 50-237 50-237 50-237 50-237	0 0 0 0
	8010140401* 8010230013 8010230036 8010300166 8010300171*	CONTRACT NUREG NUREG WASTE MOT WASTE MOT		8010090420 8010090420 8010100007* 8010100241 8010100241	50-254 50-254 50-373 50-237 50-237	P Q Q
, Colorado, State of Colt Endustries, Inc.	8010070044* 8010160162* 8010010435 8010140343	CONTRACT CONTRACT 50-375 8 50-375 8		8010100241 8010100241 8010100241 8010100250 8010100250	50-237 50-237 50-237 50-237 50-237	9 9 9 9
Columbia Univ. Columbia Univ. School of Law	8010170095 8010140629*	70-882 CONTRACT		8010100250	50-237	Q
Combustion Engineering, Inc Commerce,Dept of, National Eureau of Standards	8010070609* 8010140217 8010140220*	50-255 S 50-184 R 50-184 R		8010100250 8010100361 8010100361 8010100361	50-237 50-10 50-10 50-10	G P P
Commerce. Dept of National Oceanographic (8010140322* 8010170400*	CONTRACT CONTRACT CONTRACT		8010100361 8010100361 8010100361 8010100361	50-10 50-10 50-10 50-10	P P P
Atmospheric Adminstration	8010230019	NUREO		8010100361	50-10	P
Commonwealth Edison Co.	8005220571 8010010693* 8010010743*	TOPREP 50-254 9 50-254 9		8010140215 8010140253 8010140424 8010140431*	50-237 50-275 50-275 50-275	PFBB
	8010020081	50-201 9		8010140440	50-254	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8010140451* 8010140452 8010140457* 8010140489 8010140496*	50-254 50-295 50-295 50-237 50-237	8 8 8 8 8 8 8 8 8 8 8		8010240210* 8010240210* 8010240210* 8010240210* 8010240425	50-237 50-237 50-237 50-237 50-237	P P P P P P P
	8010140500 8010140512* 8010150225 8010150225 8010150309	50-254 50-254 50-373 50-373 50-254	8 9 0 0 R		8010240425 8010240425 8010240458 8010240458 8010240551*	50-3 50-3 50-373 50-373 50-373	R R A B
	8010150309 8010150313* 8010150313* 8010150343 8010150348*	50-254 50-254 50-254 50-10 50-10	R R P P		8010270366 8010270366 8010270380 8010270381* 8010280163*	50-10 50-10 50-237 50-237 50-237	P 93 93 01
	8010150382 8010150427 8010150427 8010150434 8010150435*	50-3 50-295 50-295 50-10 50-295	J P P P		8010280235 8010280254 8010280254 8010280257* 8010280257*	50-237 50-373 50-373 50-373 50-373	P K K K K
	8010150436* 8010150444 8010150474 8010150474 8010150494	50-295 50-10 50-373 50-373 50-237	P A A S		8010280260* 8010280260* 8010280287 8010280287 8010280293*	50-373 50-373 50-295 50-295 50-295	X K P P
	8010150501* 8010150506 8010150515* 8010150665* 8010150665*	50-237 50-237 50-237 50-237 50-237	8 8 8		8010280293* 8010280322 8010280448 8010280514* 8010280535	50-295 50-373 50-237 50-237 50-237	P A S S O
	8010160036 8010160036 8010160040# 8010160045# 8010160345	50-10 50-10 50-10 50-10 50-254	0 0 0 8		8010280535 8010280535 8010280535 8010280535 8010280535	50-237 50-237 50-237 50-237 50-237	00000
	8010160352+ 8010160358+ 8010160345+ 8010160371+ 8010160375+	50-254 50-254 50-254 50-254 50-254	\$ \$ \$ \$ \$ \$		8010270172* 8010270172* 8010270333 8010270333 8010270334*	50-373 50-373 50-237 50-237 50-237	О С Р Р
	8010160416* 8010160485 8010160485 8010160485 8010160485	TOPREP 50-295 50-295 50-295 50-295	6 6 6 5		8010290336* 8010290345 8010290355 8010290364 8010290365	50-237 50-295 50-10 50-454 50-237	P P 0 0
	8010160542 8010170205 8010170318* 8010200282 8010200282	50-373 PR 50-295 50-237 50-237	8 0 0		8010290385 8010290385 8010290385 8010290385 8010290385	50-237 50-237 50-237 50-237 50-237	00000
	8010200282 8010200282 8010200282	50-237 50-237 50-237 50-237 PR	Q Q Q Q		8010270414* 8010300441 8010300444* 8010310267* 8010310267*	50-456 50-265 50-265 50-237 50-237	9
	8010210401 8010210440 8010210440 8010210441* 8010210441*	50-10 50-10 50-10 50-10 50-10	P R R R		8010310280 8010310280 8010310343 8010310346* 8010310347	50-275 50-275 50-304 50-304 50-275	4 4 4
	8010210441* 8010210440 8010210504 8010210509* 8010210520	50-10 50-295 50-265 50-25 50-237	8 8 8 8	Computer Data Systems, Inc Computer Systems Support Corp	8010310347 8010310349* 8010310349* 8010200600* 8010020591*	50-278 50-275 50-275 CONTRACT	
	8010210524* 8010210535 801021053B 8010210541* 8010210644	50-237 50-304 50-373 50-304 50-275	8 8 8 8	Connecticut Yankee Atomic Power Co.	8010020735 8010020744 8010030274 8010030468 8010060258	50-213 50-213 50-213 50-213 50-213	0 0 8 8
	8010210451* 8010210455 8010210441* 8010210483 8010210488*	50-295 50-237 50-237 50-295 50-275	8 8 8 8		8010070556 8010070571* 8010100222 8010100324 8010150367	50-213 50-213 50-213 50-213	5 5 5 8
	8010210759 8010210760* 8010220112 8010220139 8010220550	50-254 50-254 PR 50-237 50-295	8 8 0 P		8010150347* 8010150445 8010150488 8010160484 8010170236	50-213 50-213 50-213 50-213 PR	Я В В
	8010220550 8010240203 8010240203 8010240203 8010240203	50-295 50-237 50-237 50-237 50-237	P P P P		8010170376 8010200472 8010220021 8010220130 8010220701*	50-213 50-213 50-213 PR 50-213	р О О

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION		ACCESSION NUMBER	SUBJECT	
	8010240247 8010240250* 8010270242 8010280455 8010280455	50-213 (50-213 (50-213 (50-213 (- P Q S S			8010100048 8010100237 8010100243* 8010100362 8010140411	50-327 50-155 50-155 50-255 50-155	P P P
	8010280528* 8010280528* 8010300372 8010300377* 8010300417	50-213 50-213 50-213	S 5 P P			8010140416# 8010140422# 8010140448 8010140455# 8010140473#	50-155 50-155 50-155 50-155 PR	, 8 8 8 8
Connecticut. State of Corner, Koore & Corber	8010070578* 8010160141* 8010080083 8010140547 8010140782	50-213 CONTRACT PR 27-39 27-39	P			8010150040 8010150291 8010150311 8010150403 8010150442	50-255 50-155 50-255 50-155 50-255	Q P P R
	8010170391 8010200517 8010200531* 8010200537* 8010200545*	27-39 27-39 27-39 27-39 27-39				8010150457* 8010150507* 8010160066 8010160557 8010160562*	50~255 50~255 FR 50~255 50~255	8 8
	8010200550* 8010200540* 8010220508 8010220515 8010220520	27-39 27-39 27-39 27-39 27-39				8010160601 8010160603* 8010160758 8010160758 8010200335*	50-255 50-255 50-329 50-329 50-329	PPOGG
Conoco Coal Development Co Consolidated Edison Co of New York	8010230424 8010270357 8010270380 8010210014 8010010517	27-39 40-8743	ន			8010200440 8010200463 8010200463 8010200301 8010200501	50-255 50-329 50-329 50-329 50-329	0 8 8 8
	8010010672 8010030133* 8010070605 8010100301 8010150447	50-247 50-247 50-247	G G P P R			8010200554 8010200555 8010200564* 8010200571* 8010210077*	50-155 50-255 50-155 50-155 50-329	8 P & & 8
	8010150497 8010150493 8010150498* 8010200310 8010200519	50-247 50-247 50-247	R 8 9 R W			8010210137 8010210447 8010210332 8010210374 8010210379*	PR 50-255 50-255 50-155 50-155	J g p
	6010200523* 8010220049 8010220209 8010240391 8010240310	50-3 PR 50-247	N Q B P			8010220131 8010220468 8010220475 8010220480 8010220481*	50-155 50-155 50-155 50-155 50-155	Q P P P
	8010240543 8010270217 8010280373 8010280375* 8010300654	50-247 (50-247 (G R R O			8010220533 8010220656 8010220660* 8010230393 8010230399*	50-155 50-155 50-155 50-155 50-155	P 8 8 8
Consumers Pawer Co	8010310491 7904120234 7904170157 8001020430 8004010289	50~255 50~255 50~255	û P P P			6010230519 8010230692 8010240204 8010240204 8010240214*	PR 50-369 50-329 50-329 50-329	g K K
	8009300507 8009300507 8010020307 8010020367 8010020736	50-329 50-155	A A G G			8010240214* 8010240221* 8010240221* 8010240230* 8010240230*	50-329 50-329 50-329 50-329 50-329	K K K
	8010030218 8010030455 8010030455 8010040240 8010040240	50-329 50-329 50-329	የ ል ል ይ			8010240344 8010280246 8010280404 8010270285 8010270352	50-155 50-329 50-255 50-155 50-329	Q F K P R
	8010060305 8010070303 8010070306* 8010070501 8010070520*	50-155 50-155 50-255	S P P 8 S			8010310353 8010310376 8010310384 8010310402 8010310452	50-255 50-329 50-329 50-329 50-155	40 7 6 4
	8010070595 8010080570 8010080570 8010080570 8010080592	50-329 50-324 50-329	8 G G G	Copylease Corp of America Cornsil Univ Coulee Region Energy Coalition Critical Mass Energy Project		8010270135 8010150609* 8010210403 8010100054 8010100008	FOIA CONTRAC' 50-97 50-409 FOIA	T U Q
	B010090167 B010090175 B010090175 B010090410 B010090411+	50-329 50-329 50-155	0 0 0 P P	Cyprus Mines Gorp		8010030192 8010140516 8010150081 8010150662 8010230537	Waste M Waste M Waste M Waste M Waste M	OT OT OT
	8010090413* 8010090514 8010100045 8010100045 8010100048	50-155 50-329 50-329	P G G G	D'Appolonia Consulting Enginea	rs, Inc	8007070134* 8007070137* 8007070147* 8007070178* 8007070185*	40-8502 40-8502 40-8502 40-8502 40-8502	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	ΥF	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8007090193* 8007090201* 8007090211 8007090218* 8007090225*	40-8502 40-8502 40-8502 40-8502 40-8502		Delaware, State of	8010060226* 8010060233* 8010060238* 8010060243* 8010160176*	50-170 50-170 50-170 50-170 50-170 CONTRAC	P P P
•	8009090251* 8009090255* 8009090243* 8009090270* 8009090275*	40-8502 40-8502 40-8502 40-8502 40-8502		Detroit Edison Co	8010070107 8010150538 8010160525 8010170128 8010200572	50-341 50-341 50-341 PR 50-341	9 8
	8007070284* 8007070292* 8007070318* 8007070324* 8007070327*	40-8502 40-8502 40-8502 40-8502 40-8502			8010210623 8010220039 8010240513 8010270187 8010270293	50-341 50-341 50-341 50-341 50-341	A 0 8 0 A
	8007070334* 8007070340* 8007070345* 8007070360* 8007070366*	40-8502 40-8502 40-8502 40-8502 40-8502		Doc - Search Associates Doherty, J F Don L. Harner	80102700\$4 8010080093 8010220027 8010240605* 8010080308*	FOIA FOIA FOIA 50-320 CONTRACT	r P
Dade County, F1	8007070372* 8007070377* 8007070390* 8007070396* 8010080637	40-8502 40-8502 40-8502 40-8502 50-250	Q	Dow Chemical Go Dresser Industries, Inc Duke Power Co	9007220143* 8010080468 8010240411 8010270082 8010010014	TOPREP 50-264 50-264 XPORTLIC 50-369	H J
Dairyland Power Gooperative	8010020506 8010030514 8010070548 8010070553* 8010100277	50-409 50-409 50-409 50-409 50-409	V		8010010090* 8010010197* 8010010206* 8010010538 8010010608	50-269 50-413 50-413 50-269 50-269	999
	B010140223 B010140227* B010140335 B010150371 B010150373*	50-407 50-407 50-407 50-407	요 다 다		8010020042 8010020042 8010020030* 8010020050* 8010020054*	50-369 50-369 50-369 50-369 50-369	9999
	8010150496 8010160190 8010160478 8010160507 8010210308	50-409 50-409 50-409 50-409 50-409	ն 6 0		80100200\$4* 8010020062* 8010020062* 8010020068* 8010020068*	50-369 50-369 50-369 50-369 50-369	0 0 0
	8010210594 8010210598* 8010220538 8010280353 8010290387	50-409 50-409 50-409 50-409 50-409	6 6 6		8010020077* 8010020782 8010030459 8010030491* 8010030496*	50-369 50-369 50-369 50-369 50-369	0 0 0 0
Dames & Hoore	8010300044 8010060228* 8010060248* 8010140557* 8010240564	50-409 50-170 50-170 50-466 40-8084	e P P		8010040002 8010040002 8010040281 8010070244 8010070244	50-369 50-369 50-413 50-369 50-369	9 9 0
Data Composition Services.Inc Dawn Mining Co Debevoise & Liberman	8010010304* 8010240578 8010020037 8010020042 8010020042	CONTRACT WASTE MG 50-466 50-369 50-369			B010070387 B010070405 B010070413 B010070537 B010070546*	50-270 50-269 50-369 50-269 50-269	P A 8 8
	8010020050* 8010020050* 8010020054* 8010060002 8010070555	50-369 50-369 50-369 50-369 50-369	00000		8010070355 8010070555 8010080197 8010080443 8010080445*	50-369 50-369 50-369 50-269 50-269	888
	8010080289 8010080289 8010080289 8010080289	50-445 50-445 50-445 50-445 50-445	о м м м м		E010080447 B010080548 B010080548 B010070203 B010070203	50-369 50-369 50-369 50-269 50-269	Q A A Q
	8010090319 8010080319 8010080319 8010080319 8010140002	50-445 50-445 50-445 50-445 50-445	м м м н		8010090203 8010090422 8010090422 8010090422 8010090428*	50-269 50-269 50-269 50-269 50-269	6 6 6 b
	8010140507 8010150002 8010150006 8010210503 8010210772	50-369 PR 50-369 50-445 50-369	9 9 9		8010090428* 8010090428* 8010100219 8010140023 8010140041	50-269 50-269 50-369 50-413 50-269	P P Q Q
	8010210772 8010210777 8010210777 8010230692 8010240804	50-369 50-369 PR	0 0 0		8010140324 8010140325* 8010140507 8010140507 8010150006	50-287 50-287 50-369 50-369 50-369	8 0 0
Defense, Dept of, Defense Nuclear Agency	8010240852 8010280472 8010310432 8010310436 8010080220	50-313 50-313 50-445	0 0 0 9		8010150275 8010150314 8010150333 8010150333 8010150454	50~269 50~269 50~369 50~369 50~369	9 9 4 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8010150454 8010140497 8010170204 8010170204 8010170204	50-369 PR 50-269 50-269 50-269	0 0 0		8010270427* 8010270580 8010280057* 8010280384 8010280388*	50-413 70-2623 50-370 50-270 50-270	Q 8 8
	8010170369 8010170540 8010170540 8010170540 8010170544*	50-369 50-269 50-269 50-269 50-269	A P P P		8010300385* 8010310025* 8010310038* 8010310306 8010310405	50-369 50-413 50-413 50-269 50-269	0 0 0 P
	8010170544* 8010170544* 8010200200* 8010200430 8010200525	50-269 50-269 ACRS 50-369 50-369	P P A S		8010310405 8010310405 8010310409* 8010310409* 9010310409*	50-249 50-249 50-249 50-249 50-269	P P P
	8010200525 8010200558 8010200558 8010200545* 8010200545*	50-369 50-369 50-369 50-369 50-369	8 A A A	Duquesne Light Co	8010310438 8010010210* 8010010534 8010010545 8010010490	50-369 50-334 50-334 50-334 50-412	A Q 8 F Q
	8010200570* 8010200570* 8010200577* 8010200577* 8010200580*	50-349 50-349 50-349 50-369 50-349	A A A A		8010010779 8010010801* 8010010823 8010010829 8010020110	50-334 50-334 50-334 50-334 50-412	@ @ @ @
	B010200580* B010200585* B010200585* B010210434 8010210434	50-369 50-369 50-369 50-269 50-269	A A R R	•	8010020359 8010020466 8010020472* 8010020491 8010020492*	50-334 50-334 50-334 50-334 50-334	R 9 R R
	8010210434 8010210437* 8010210437* 8010210437* 8010210534	50-269 50-269 50-269 50-269 50-270	R R R R		8010030121* 8010030393 8010040222 8010060223	50-334 50-334 50-334 50-334 50-334	9 P P 9 P
	8010210537* 8010210551 8010210561 8010210561 8010210566*	50-270 50-269 50-413 50-413 50-413	\$ 6 R R		8010070369 8010070373* 8010070404 8010070456 8010070464*	50-334 50-334 50-334 50-334	9 8 8 8 8
	8010210566* 8010210745 8010210772 8010210772 8010210777	50-413 PR 50-369 50-369 50-369	R C G		8010070519 8010070521 8010070526* 8010070531* 8010070550	50-334 50-334 50-334 50-334 50-334	8 8 8
	8010210777 8010220154 8010230404 8010230404	50-349 PR 50-269 50-269 50-369	C P P		8010070552 8010070559* 8010100307 8010100310* 8010100251	50-334 50-334 50-334 50-334 50-334	888
	8010230408 8010230412* 8010230459 8010240107 8010240107	50-369 50-369 50-369 50-413 50-413	A A Q Q		8010140432 8010150203* 8010160743 8010200380 8010200574	50-334 50-412 PR 50-412 50-334	8 8
	8010240156 8010240156 8010240335 8010240335 8010240397	50-413 50-413 50-413 50-413 50-270	Q Q Q P		8010200583* 8010230296 8010240432 8010240433 8010240437*	50-334 50-334 50-334 50-334 50-334	8 9 8 P
	8010240377* 8010240412 8010240412 8010240412 8010240413*	50-270 50-269 50-269 50-269 50-269	P P P P		8010240441* 8010240447 8010240454* 8010240461* 8010240468	50-334 50-334 50-334 50-334 50-334	8 8 8 8
	8010240415# 8010240415# 8010240475 8010240479# 80102404552	50-269 50-269 50-270 50-270 50-269	P 8 8		8010240473* 8010240478 8010270104* 8010280438 8010280443*	50-334 50-334 50-412 50-334 50-334	2 2 3 3 3
	8010240552 8010240552 8010240552 8010240552 8010240552	50-269 50-269 50-269 50-269 50-269	0 0 0	EQLO Idaho. Inc	8010280450 8010280519* 8009260121 8009260126* 8010010412	50~334 50~334 TOPREP TOPREP NUREO	6 8
	8010240562* 8010240562* 8010240562* 8010240562* 8010240562*	50-269 50-269 50-269 50-269 50-269	0 0		8010080174 8010080210 8010080234 8010080381 8010230007	RES RES RES NUREO NUREO	
	8010240562# 8010270181 8010270348 8010270348 8010270427#	50-269 50-369 50-369 50-369 50-413	0 0		8010330017 8010300137 8010300142 8010300185 8010300194	50-250 RES RES 50-333 RES	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEODR	ŧΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8010300232 8010300207 8010300218 8010300225	50-269 RE8 50-311 50-344 RE8	P P	Environmentalists, Inc Envirosphere Co. Essex Corp Ethicon: Inc European Communities, Commission of	8010020007 8010240514 8010070240* 8010140413* 8010100274	50-201 0 PR 50-327 P FOIA XPORTLIC
EQ4.9, Inc	8010300301 8010310553 8010010802 8010010806	RES RES RES RES		Everest Minerals Corp Exxon Minerals Co., UBA Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	8010270327 8010020713 8010040350*	REGGD 40-8102 50-295 P
	8010230015	NUREO	P	sury /	8010090237 8010090241#	TOPREP TOPREP
Earthquake Engineering Systems, Inc Eastman Kodak Co Ebasco Services, Inc (subs of Enserch Corp)	B010160577* B010100076* B010100076* B010230643 B010200482*	50-29 70-1703 70-1703 70-2933 50-213	Р		8010070246# 8010070250# 8010070308 8010140276 8010150452#	TOPREP TOPREP 70-1257 TOPREP 50-10 P
	8010200483* 8010200488* 8010200472* 8010200474* 8010200497*	50-213 50-213 50-213 50-213 50-213	P P P P	FUGRO, INC. Federal Acquisition Counselors	8010220287 8010290184 8010290191* 8010150357* 8010280122	XPORTLIC XPORTLIC XPORTLIC CONTRACT FOIA
	8010200502* 8010200507* 8010200509* 8010230511 8010280323	50-213 50-213 50-213 PR TOPREP	ե ե	Federal American Partners	B010070537 B010140176 B010140241* B010150647 B010150650	40-4492 40-4492 40-4492 40-4492 40-4492
Ebarline instrument Corp Ecological Analysts, Inc.	8010280325* 8010290134 8010030516 8010270325 8010150508*	TOPREP REGOD XPORTLIC XPORTLIC 50-247		Federal Emergency Management Agency	8010210399* 8009250328 8009250329* 8009250330* 8010150621*	40-4492 50-327 F 50-327 F 50-327 F 50-289 Q
Edison Electric Institute	8010030471 8010140549 8010240001 8010280017	50-201 PR PR PR	G -	Federal-State Reports, Inc	8010170580* 8010230548 8010230575* 8010230475	CONTRACT CONTRACT CONTRACT NUREO
Editorial Experts, Inc Edlow International Co	8010080350* 8010090502	XPORTLIC	;	Flæischaker, D S	8010200174 8010210497	50-275 0 50-275 0
	8010090505 8010090515 8010090520 8010090525	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	}	Florida Cities Florida Power & Light Co	8010150392 8010150408* 8010170364 8010010537	50-389 M 50-389 M 50-389 M 50-250 P
Eichhorn,Eichhorn & Link	8010240455 8010270158 8010270178 8010270182 8010030510	XPORTLIO XPORTLIO XPORTLIO XPORTLIO 50-367	}		8010010537 8010010542 8010010542 8010010544* 8010010544*	50-250 P 50-250 P 50-250 P 50-250 P 50-250 P
Electric Power Research Institute	8010290401 8010010127* 8010080128 8010100078 8010310597*	50-367 PRM PR NUREO CONTRACT	о Г		8010010549 8010010549 8010010668 8010030081* 8010060236	50-250 P 50-250 P 50-250 P 50-335 Q 50-250 F
Emerson Consultants, Inc Emmerson Kemp & Associates, Inc Energy, Dept. of	8010220299 8007240156 8010030100 8010020024 8010030106	40-9681 40-4492 40-4492 PR WABTE MG	er .		8010060236 8010060294 8010060309 8010060309 8010070420	50-250 F 50-250 P 50-250 P 50-250 P 50-235 8
	8010030365 8010030460 8010080158* 8010070112 8010070279	50-344 50-344 40-1193 71-6601 71-5088	P H		8010070431 8010070437* 8010070443 8010070453*	50-335 8 50-335 8 50-335 8 50-335 8
	8010100437 8010140519 8010160693 8010210228 8010220126	PR PR PR RECOD WASTE HO	эт		8010070474* 8010070477* 8010080209 8010080217* 8010080223	50-335 8 50-335 8 50-335 8 50-335 8 50-250 P
	8010240032 8010270078* 8010270253 8010280572 8010300430*	XPORTLIC WASTE MG 71-9132 PROJ 50-275			8010080223 8010080332 8010080332 8010080332 8010080340	50-250 P 50-250 H 50-250 H 50-250 H 50-367 A
Energy, Dapt. of. Clinch River Breeder Reactor Plant	8010160716	PR			8010080670 8010080673*	50-335 8 50-335 8
Engalhard Minerals & Chemicals Corp., Philipp Brothers Div.	8010010241	XPORTLIC			B010100311 B010100313	50-335 B
Environmental Coalition on Nuclear Power	8010200679 8010210515 8010210769	PR 50-367 50-269	0		8010100314* 8010100316	50-335 8 50-335 8
Environmental Protection Agency	8010020746 8010200080* 8010210773 8010220541	40-8602 CONTRACT WASTE MG 50-277			8010100317* 8010100317 8010100322* 8010100323*	50-335 8 50-335 8 50-335 8 50-335 8
Environmental Systems Corp.	8010230414 8010280240* 8010010303*	40-299 FOIA CONTRACT	•		8010100326 8010100327 8010100331* 8010100334*	50-335 8 50-335 8 50-335 8 50-335 8

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGORY
	8010100339 8010100345# 8010140099# 8010140104# 8010130042#	50-335 50-335 50-250 50-250	8 0 0 0	Fred C. Hart Associates, Inc Friends of the Earth	9010310179# 8010150622# 8010010602# 8010030444 8010160585	50-324 @ CONTRACT 50-361 0 50-361 0 PR
	8010150243 8010150282 8010150338 8010150338 8010150338	50-250 50-250 50-250	F Q R R R	Fuller, H O. Ditters & Co , N.V The Netherlands Gage-Babcock Associates, Inc.	8010230685 8010170315* 8010160659* 8009090457 8010170612*	50-133 0 CONTRACT GA999 GRO CONTRACT
	8010150341# 8010150341# 8010150341#	50-250 50-250	R R R G	Cary. IN Cansral Atomic Co (subs. of Gulf Dil Co)	8010020047 8010020055* 8009170190	50-367
	8010150574* 8010170013*	50-250	a		8009170193# 8009170199	71-9034 71-9037
	8010200317 8010200454 8010210341 8010210347 8010210413	50-250 50-335 50-250 50-335	P G F F P		8009170203* 8010010681 8010010702 8010030189 8010030197*	71-9037 50-267 P XPORTLIC 71-6346 71-6346
	8010210416* 8010220501 8010240063 8010240216 8010240216	50-335 50-369 50-250	P P M F F		8010030200* 8010070434 8010070435* 8010170273 8010170275*	71-6346 TOPREP TOPREP XPORTLIC XPORTLIC
	8010240229 8010240267 8010240527* 8010270164 8010270292	50-251 50-335 PR	A G F a		8010200011 8010200096 8010200269 8010230224 8010270085	PR 70~734 70~734 71~6489 XPORTLIC
	8010270239 8010270275 8010280297 8010280302* 8010280334	50-389 50-250 50-250	а а Р Р	General Electric Go	8010270105 8010270108 8010300474 80103104654 7902090367*	71-6089 71-6347 71-9057 PRM 50-322 A
	8010280484 8010280490* 8010290324 8010200444 8010300449*	50-250 50-389 50-250	8 1 0		8010010034 8010010037* 8010010039* 8010010042* 8010020335	71-9136 71-9136 71-9136 71-9136 TOPREP
	8010310395 8010310398* 8010310428 8010310433* 8010310435	50-250 50-250	8 8 8 8		8010020339# 8010020494# 8010020494# 8010020495# 8010020495#	70PREP 50-277 P 50-277 P 50-277 P 50-277 P
Florida Power Corp	8010310441# 8010010514 8010060227 8010060232# 8010060317	50-302 50-302	8 8 8 0		8010020499 8010030464 8010060104 8010060169 8010060216	TOPREP TOPREP XPORTLIC XPORTLIC NUREG
	8010070285 8010070290* 8010150390 8010150669 8010170213	50-302 50-302	8 F Q		8010070275 8010070022 8010070026* 8010070027* 8010070425*	TOPREP NUREO NUREO NUREO 50-254 P
	8010200405 8010200407# 8010200473 8010200477# 8010200477	50-302 50-302 50-302	R R S S S		8010070427* 8010070432* 8010070435* 8010070448* 8010070440*	50-254 P 50-254 P 50-254 P 50-265 P 50-265 P
	8010200485* 8010210431 8010210741 8010210747* 8010280370	50-302 50-302 50-302	8 8 8 V		8010100093 8010100312 8010100316# 8010100352 8010100355	70-1308 TOPREP TOPREP TOPREP TOPREP
	8010280397 8010280531 8010280549 8010280710* 8010310187*		8 8 9 9		8010140017 8010150139 8010150252 8010150428 8010150563	PR RES T <i>OPREP</i> 50-70 P RES
Florida, Univ of, Oninesville	8010070480 8010200234*	70-1068 CONTRACT PR			8010150590 8010160033	70-1308 XPORTLIC
Fluor Pawer Bervice: Inc. Fort Pierce:F1	8010210713 8010140241 8010140243#	50~389	н		8010160538 8010160550 8010160561	50-367 G TOPREP TOPREP
Foster Wheeler Corp. Fos Industries Fot: Fatt & Cunningham	8010140587 8010100185 8010140440 8010140448* 8010220526	50~389 REOOD TOPREP TOPREP 50~267	о о		8010170048 8010170357 8010210064* 8010210174 8010210332	70-1308 70-1308 CONTRACT 70-734 TDPREP
Franklin Institute/Franklin Research Canter	8010080420* 8010170424* 8010270008* 8010310147*	CONTRACT CONTRACT CONTRACT 50-324			8010210334* 8010230376* 801024040B 8010240440	TOPREP 50-364 P 50-367 G XPORTLIC

AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
General Electric Co , Nuclear Energy	8010240467 8010270365 8010290347 8010310597* 7902090343	XPDRTL 10 71-5939 50-70 CONTRACT 50-322	P		8010240213 8010280213 8010280375 8010280377* 8010280385	50-321 P 50-366 8 50-366 8 50-364 9 50-321 V
Products Div	8010040027 8010070157 8010150115 8010150572	70-1113 70-1113 70-1113 70-1308			8010280385 8010280389* 8010280389* 8010280421 8010280425*	50-321 V 50-321 V 50-321 V 50-366 B
General Electric Operating Plant Owners	8010230197 8010310507 8010020335	71-6294 70-1113 TOPREP			9010290470 8010290476* 8010290473 8010290481*	50-366 8 50-366 8 50-321 9 50-321 8
Group General Public Utilities - OPU Service	8010060216 8010200414	NUREO NUREO			8010300608	50-424 0
Corp	6010200687	50-289	τ		8010310361 8010310406 8010310410*	50-321 P 50-366 S 50-366 S
	8010210271 8010220423	REGGD 50-219	J	Georgia, State of	8010170393* 8010210781*	TOARTINGS H 66E-98
	8010220425* 8010240352 8010240355	50-219 PR PR	J	Getty Oil Co , Petrotomics Co Div	8010210789 8010140624 8010220119	State Prog 40-6659 40-6659
Queral Services Administration	8010240428 8010280428 8010200390*	50-320 50-320 40-341	P P	Gibbs & Hill, Inc (subs of Brave Corp		NUREG NUREG NUREG
Georgia Institute of Technology	8010160334* 8010160737	CONTRACT PR		Gould-Brown Boveri Graphic Data, Inc	8007300379 8010270200*	50-367 8 CONTRACT
Ocorgia Power Co	8009300110 8010060240	50-424 50-366	9	Gulf States Utilities Co	8010270071* 8010010013	CUNTRACT 50-458 A
	8010060242 8010060245* 8010060247*	50-366 50-366 50-366	8 8 8		8010020005 8010080541 8010080541	50-201 0 50-458 0 50-458 0
	8010060254 8010060257* 8010060357	50-366 50-366	8 9 8		8010080549 8010080549	50-458 Q
	8010060360# 8010070471	50-366 50-366 50-366	8 S		8010150204 8010170209 8010170477* 8010220147	50-458 6 PR 50-458 9 PR
	8010080375 8010080382* 8010080433	59-366 50-321	6 8 8		8010300435*	50-458 Q
	8010090437* 8010090273 8010140005*	50-321 50-321 50-321	8 0	H J Gruy & Associates, Inc HEW, Dept of: Food & Drug Administration Hanford Engineering Development	8010010557* 8010010295* 8010100170 8010230038	50-445 A CONTRACT REGOD NUREG
	8010150340 8010150381 8010150381	50-321 50-321 50-321	g P P	Laboratory Harding-Lawson Associates	8010020679*	CONTRACT
	8010150534	50-386	P	Hill Christopher & Phillips	8010300117* 8010030310	27-39 50-275 0
	8010160472 8010160475* 8010160479 8010160482*	50-346 50-346 50-321 50-321	5 8 8		8010030310 8010030385 8010030385	50-275 0 50-275 0 50-275 0
	8010170412 8010170412	50-321 50-321	R R		8010080300 8010080300 8010080308*	50-275 ¢ 50-275 ¢ 50-275 ¢
	8010170422* 8010170422* 8010170431*	50-321 50-321 50-321	R R R		8010080308* 8010160544	50-275 0 50-275 0
	8010170431# 8010210303	50-321 50-321	R Q	Hilti Fastening Systems	8010200482 8010020669 8010200710	50-275 Q 50-416 9 50-416 B
	8010210303 8010210352 8010210410	50-321 50-321 50-366	Ö F R	Hittman Association, Inc.	8010210003 8010030353*	50-416 B CONTRACT
	8010210414#	50-366	R	Holland & Hart House of Rep	8010300048 8010020584*	40-1162 50-271 H
	8010210418 8010210421# 8010210612	50-321 50-321	R R P		9010020477* 9010080440* 9010100111*	50-461 U M150 50-273 H
	8010210612 8010220473	50-321 50-321	P 8		8010100118* 8010140025	50-305 H PR
	8010220474* 8010220488 8010220489*	50-321 50-366 50-366	8 8 8		8010140607 8010200549# 8010200549*	50-204 H 50-478 0 50-478 0
	8010220493 8010220496#	50~366 50~366	8		8010200557* 8010200557*	50-478 0 50-478 0
	8010220500 8010220506# 8010230368	50-321 50-321 50-366	8 8 P		8010230715* 8010270519* 8010270534*	50-338 H MISC 50-10 U
	8010230372# 8010230418	50-366 50-321	p P		8010280092*	COMMISSION
	8010230418 8010230491*	50-321 50-321	P P	House of Rep., Appropriations	8010280343 8010290295* 8010310242	COMMISSION PROJ
	8010230491* 8010240005* 8010240005*	50-321 50-321 50-321	P G G	House of Rep , Foreign Affairs House of Rep , Government Operations	8010020440* 8010290295*	50~264 0 COMMISSION
1	8010240007#	50-321	Q P	House of Rep , Interstate & Foreign	8010300552* 8010030425	COMMISSION 50-10 U
	8010240213	50-321	r	Commerce		

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOD	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOGR	łY
Pause of Rep , Science & Technology Fouse of Rep , Ways and Means	8010020374# 8010100075# 8010100100 8010100102# 8010020682	50-482 CDMMISS 50-443 50-201	U	Idaho State Univ. Illinois Power Co	8010300178 8010030194* 8010040045 8010040098 8010140721	RES 50-284 50-461 50-461 PR	Q Q Q
Housing & Urban Davelopment, Dept of Houston Lighting & Power Co	8010230223 8010270315 8010010146 8010010219 8010010661	PR HASTE MO 50-498 50-446 50-498	GT B O A	Illinois Safe Energy Alliance	8010170072* 8010170131* 8010210375 8010280505 8010210342	50-461 50-461 50-461 50-461 50-10	0 0 8 H
	8010010661 8010010665* 8010010665* 8010060301 8010140004	50-498 50-498 50-498 50-466 50-445	A A G H	Illinois, State of	801002044* 8010060269 8010080002 8010140503 8010150537	PR 50-367 PR PR 27-39	0
	8010140497 8010140497 8010140543 8010140550* 8010140554*	50-498 50-498 50-466 50-466 50-466	M 0 0		8010150542* 8010150547* 8010150551* 8010150556* 8010150562*	27-39 27-3 9 27-39 27-39 27-39	
	8010140573* 8010140578* 8010140582* 8010140589* 8010140594*	50-466 50-466 50-466 50-466 50-466	0 0 0		8010150567* 8010150569* 8010150577* 8010150636 8010150639	27-39 27-39 27-39 27-39 27-39	
	8010140579* 8010140602* 8010150162 8010150167 8010150181	50-466 50-466 50-498 50-498 50-498	0 8 8		8010160774 8010160777* 8010200017 8010200031 8010200184	27-39 27-39 PR PR 50-367	٥
	8010150181 8010150188 8010150193 8010150193 8010150199	50-498 50-498 50-498 50-498 50-498	5 8 8 8		8010210279 8010210282 8010230387 8010230596 8010240065	70-1308 70-1308 50-237 50-367 27-39	0
	8010150208 8010160020 8010160556 8010160565 8010160565	50-478 50-466 50-498 50-498 50-498	C C C C	Illinois, Univ. of, Urbana-Champaign	8010280015 8010290391 8010080524 8010170003 8010170078	27-39 70-1309 50-151 NUREO NUREO	F
	8010160569# 8010160569# 8010160767 8010160784 8010210058	50-498 50-498 PR 50-466 REGOD	C C		8010200102* 8010200102* 8010200108* 8010200108* 8010210530	50-151 50-151 50-151 50-151 50-151	G G G P
	8010210313 8010210313 8010210452 8010210637 8010240420	50-498 50-498 50-498 50-498 50-498	A A B C A	Illinois, Univ. of, at Chicago Circle India Indiana & Michigan Electric Co.	8010210533* 8010210537 8010200276* 8010240047 8010010539	50-151 50-151 40-2061 XPORTL16 50-316	ф 9 2
	8010270522 8010280020 8010280340 8010280540 8010290374	50-466 50-466 50-498 50-498 50-466	0 9 8		8010010541* 8010020260 8010020497 8010030388 8010090403	50-316 50-315 50-315 50-316 50-315	P P P 8
	8010300599 8010310048 8010310051 8010310295 8010310528	50-466 50-466 50-466 50-478 50-478	9 9 8		8010080432 8010080432 8010080515* 8010090356 8010090362*	50-315 50-315 50-315 50-316 50-316	6 6 8
Hober, Magill, Laurance & Farrell	8010310528 8010220383 8010220383 8010240076 8010240076	50-478 50-596 50-596 50-596 50-596	8 0 0 0		8010070348* 8010070347 8010070371* 8010150412 8010140534	50-316 50-315 50-315 50-315 50-315	888
Hunton & Williams	8010010121 8010010127* 8010020651 8010160524 8010160527*	PRM PRN 50-201 50-322 50-322	0 0 0		8010200340 8010200348 8010200409 8010200410* 8010210370	50-315 70-143 50-316 50-316 50-315	Q R R
17T Orinnell 1chthyological Associates, Inc.	8010160754 8010160762# 8010220513 8010160292# 8010170347#	50-516 50-516 50-322 GA999 50-320	Q Q R		8010210370 8010210664 8010210671* 8010280431 8010300447	50-315 50-315 50-315 50-315 50-315	1 8 F 8
	8010170347± 8010170352± 8010170353≠ 8010170356≠ 8010170357≠	50-320 50-320 50-320 50-320 50-320	R R R R	Indiane & Hichigan Power Co. Indiana Univ	8010300450* 8010140234 8010200412 8010200415* 8010240043	50-315 50-315 50-315 50-315 NUREQ	9 R R
Edaho National Engineering Laboratory	8010150071 8010150127 8010150140 8010150142 8010300161	REB REB REB REB		Indians, State of Input Output Computer Services, Inc. Institute of Nuclear Power Operations	8010220484 8010170552* 8010070448 8010070450* 8010100433	PR CONTRAC NUREO NUREO PR	T

AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Interior,Dept of	8010280474* 8010010232* 8010140327 8010200453* 8010280392	50-10 CONTRAC 50-367 27-39 50-528	o F A C	Japan Jersey Contral Power & Light Co	8010200006 8010240492 8010240538 8010010414* 8010010467	PR XPORTLIC XPORTLIC 50-219 Q 50-209 Q
Interior,Dapt of, Bureau of Mines Interior,Dapt of, Geological Survey	8010300002 8010170572* 8010200642* 8009240161* 8009240166*	PR CONTRAC CONTRAC 40-4492 40-4492	Γ		8010010652 8010010656 8010010836 8010030309 8010030493	50-219 0 50-219 0 50-219 0 50-219 0 50-289 0
	8009240167* 8009240170* 8010020379 8010100089* 8010140243*	40-4492 40-4492 50-367 50-274 CONTRAC	A Q		8010030494 8010060125 8010070155 8010070160* 8010070476	50-219 B 50-219 Q 50-219 B 50-219 B 50-219 B
International Brotherhood of Electrical Workers	8010140420* 8010200445 8010200447* 8010210266 8010270052	CONTRACT 50-367 50-367 REGGD REGGD	r A A		8010070486* 8010070316 8010070322* 8010070387 8010070415	50-219 \$ 50-219 \$ 50-219 8 50-289 \$ 50-219 P
International Nutronics, Inc International Planning Management Intersyst, Ltd Iowa Electric Light & Power Co	8010290169 8010200329* 8010210138* 8010030407 8010150317	71-5939 CONTRAC CONTRAC 50-331 50-331			8010140244 8010140252 8010140255* 8010150470 8010150479*	50-219 P 50-219 P 50-219 P 50-219 S 50-219 S
	8010150421 8010150431* 8010150439 8010150450* 8010150457	50-331 50-331 50-331 50-331 50-331	8 8 8 8		8010160490 8010200475 8010200569 8010210387 8010210419	50-289 P 50-219 F 50-289 T 50-289 T 50-219 R
	8010150467* 8010150475 8010150483* 8010150490 8010150499*	50-331 50-331 50-331 50-331	9 9 9		8010210425* 8010210469 8010210493 8010210493* 8010220388	50-219 R 50-289 T 50-219 8 50-219 8 50-219 P
	8010210404 8010210408* 8010220471 8010220472* 8010240220	50-331 50-331 50-331 50-331	R R S S		8010220387* 8010220405 8010230394 8010240338* 8010240477	50-219 P 50-289 I 50-289 G 50-219 G
Iowa State Univ Isham, Lincoln & Scale	8010240225* 8010300480 8010090011* 8010020065 8010020736	50-331 50-331 CONTRACT 50-237 50-329	P P		8010240480* 8010240485* 8010270201 8010310414 8010310421*	50-219 R 50-219 R 50-219 0 50-219 8
	8010020740 8010080440 8010070054 8010100045 8010100045	50-237 50-255 50-237 50-329 50-329	0 0 0	Jones: Brown & Clifford Justice,Dept of	8010310477 8010310484* 8010230685 8010020706 8010060347*	50-289 T 50-219 G 50-133 G FOIA 50-445 H
	8010100048 8010100048 8010140488 8010140493* 8010150040	50-329 50-329 PR PR 50-255	G G		8010060353* 8010140497 8010140540 8010150640 8010170458	50-445 N 50-498 H 50-445 H 50-375 M 50-445 N
	8010150364 8010150364 8010160036 8010160036 8010160045*	50-201 50-201 50-10 50-10 50-10	0 0 0	Justics.Dapt of, Attorney General's Office	8010240063 8010240337* 8010310538* 8010140037*	50-389 M 50-320 0 CONTRACT BECY 50-320 0
	8010180758 8010210523 8010210532 8010230464 8010240364	50-329 50-237 50-255 50-10 50-155	G G O	Kansas Gas & Electric Co Kansas State Univ.	8010240337* 8010060149* 8010160546 8010020464 8010070333 8010240529	50-482 G 50-482 A 50-149 R 50-188 P
	8010280535 8010280535 8010280535 8010290330	50-237 50-237 50-237 50-237	0 0 0	Kentucky, State of Kentucky, Univ of Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8010230014 8010080435* 8010150418	NUREG CONTRACT FOIA
	8010290384	50-454	0	Kerr-McGes Corp	B010220123 B010160635	PR PR
Izaak Walton League of America, Porter County Chapter	8010270385 8010270385 8010270385 8010160787	50-237 50-237 50-237 50-367 50-367	0	Kerr-McGss Nuclear Corp	8010020219 8010030180 8010090531 8010140418 8010210408	70-925 71-9090 70-1193 PR 40-8027
	8010210776 8010300061 8010300069* 8010300075* 8010300088*	50-347 50-347 50-347 50-347 50-367	0	Labor, Dept of	8010210620 8010220241 8010270057 8010310040 8010030488*	70-925 40-8727 REGOD 40-8768 CONTRACT
J Ray McDermott & Co. J.F.T Acapito & Associates, Inc. JMK International Corp.	8010100302 8010170311* 8010070141*	70-364 CONTRACT CONTRACT		Lancaster General Hosp, Lancaster,PA Lancaster, PA Lawrence Livermore Leboratory	8010140178* 8010230457* 8010080475	70-1447 50-320 H NUREG

AUTHOR AFFILIATION	ACCESS ION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8010150153 8010170076 8010220451 8010230015 8010300499	NUREG NUREG RES NUREG NUREG		Lucius Pitkin. Inc MHB Tachnical Associates	8010300599 8010310048 8010310051 8010210112 8010080545	50-466 50-466 50-466 70-162 NUREG	o o c
LeBoruf, Lamb, Leiby & MacRae	8010300537 8010080296 8010160515 8010160545	50-285	P P	MPR Associates, Inc MMS Consultants, Inc , Hiddle West Service Co Biv. Maine Yankes Atomic Power Co	8010010251#	50-155 PR 50-309	P Q
Leva, Hauss, Bymington, Martin &	8010200381* 8010200381* 8010280724 8010310378 8010140475		P F		8010010720 8010030474 8010060331 8010140206 8010140210#	50-309 50-309 50-309 50-309	G P P P C
Oppenheimer Logical Tethnical Service Corp	8010090064*	CONTRACT			8010140437 8010140442*	50~307 50~307	8 \$
Long Island Lighting Co	8010020230* 8010020322 8010020714* 8010030378 8010030378	50-322 50-322	а а н н		8010150400 8010150402* 8010200342 8010220140 8010240373	50~309 50~309 50~309 PR 50~309	R R F
	8010030534 8010070336 8010160522 8010160522 8010160754		а н о о	Maine, State of	8010270191 8010270360 8010290189* 8010300073 8010150165*	50~309 50~309 50~309 50~309 50~309	@ > @ @ F
	8010160762* 8010160762* 8010200421 8010200695	50~516 50~516	о о н q	Harsh & McLennan, Inc., H & M Nuclear Consultants, Inc. Div.	8010080412 8010080549	50-327 50-339	r J
	8010210473		ĸ		8010140461 8010150354	50-250 50-335	J
	8010210476* 8010240076 8010240076 8010240082* 8010240082*	50~576 50~576 50~576	K 0 0 0	Marubeni America Corp (subs of Marubeni	8010150420 8010220418 8010240394 8010280382 8010010449	50-259 50-272 50-438 50-89 XPORTL16	,,,,,,
Los Alamos Scientific Laboratory	8010240087 8010240087 8010010353 8010080378 8010080671		0	Corp) Maryland, State of Maryland, Univ of	8010140230* 8010140159* 8010270214 8010140449*	CONTRACTO	T P T
Louisiana Power & Light Co	8010090399* 8010100147 8010300676 8010310588 8009300212		Q	Massachusetts Institute of Technology	8010140574* 8010010253* 8010010373* 8010030447 8010070391 8010080315*	CONTRAC' CONTRAC' CONTRAC' NUREO 50-20 50-206	۲
	8007300342 8010010582 8010010587# 8010010595% 8010030374*	50-382 50-382 50-382	# # # # # # # # # # # # # # # # # # #	Hassachusetts, State of	8010100178 8010100186* 8010160473 8010240414* 8010170023	PR PR 50-20 CONTRAC	P
	8010030380* 8010060352	50-382	K 8	Mathematical Applications, Inc. Mauro Associates (C.C. Mauro Associates,		NUREO	
	8010070025 8010140302 8010210458 8010280440	50-382 50-382	K A S	Inc.) Mayer, Brown & Platt Herrill, C	8010170359 8010210582 8010290099#	70-1308 70-1308 CONTRAC	
Lowell, Univ of Lowenstein, Newman, Reis, Axelrad & Toli	8010280447* 8010310419 8010070069* 8010010219	50-382 50-382 Contract 50-466	C A Q	Metropolitan Edison Co	8009300506 8010010203 8010010454 8010010459* 8010010641	50-289 50-289 50-320 50-320 50-320	0 9 8
	8010060301 8010080099 8010080273 8010140343	PR 50-376	o o		8010010733 8010010762 8010020395 8010030305 8010030402	50-320 50-287 50-320 50-287	0 0 p F
	8010140550* 8010140555* 8010140573* 8010140589*	50-466 PR 50-466 50-466	0 0		8010030409 8010020412* 8010050133 8010060140 8010060145	50-320 50-320 50-289 50-320 50-320	8 8 0
	8010140599* 8010140609 8010150455 8010150476 8010150476	50-498 50-367 50-445 50-445	о о и м м		8010060208 8010060211 8010060214* 8010060218*	50-287 50-287 50-287 50-289	P P P
	8010160020 8010160761 8010160784 8010200669 8010240427	PR 50-446 50-367	Q Q Q		8010060237 8010060244* 8010060250* 8010060339	50-289 50-289 50-289 50-289	P P P
	8010270522 8010280017 8010280020 8010290394	30-466 PR 50-466	o o		8010040337 8010070323 8010070335 8010070338*	50-289 50-289 50-289 50-289	F P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	GUBJECT CATEODRY
	E010070428 E010070447 E010070457 E010070457 E010070542	50-320 P 50-320 P 50-329 H 50-289 H 50-289 P		8010280482 8010290383 8010300287* 8010300457 8010300687	50-289 P 50-289 0 50-320 0 50-289 P 50-289 0
	8010080240 8010080281 8010080471 8010080474* 8010080514	50-287 0 50-289 0 50-320 8 50-320 8 50-287 0		8010310021 8010310375 8010310418 8010310423* 8010310426	50-320 Q 50-320 R 50-320 R 50-320 P 50-320 8
	8010090391 8010090401 8010090418 8010100299 8010100343	50-289 P 50-320 S 50-289 P 50-289 V 50-320 P	Hayer, K A Hichigan State Univ Hichigan, State of Hichigan, Univ of	8010310437* 8010310289* 8010160497* 8010210105* 8010080386	50-320 S FOIA 50-274 Q CONTRACT NUREQ
	8010140308 8010140413 8010140418 8010140424 8010140462	50-320 B 50-320 S 50-320 P 50-320 J 50-289 P	Microtech Industries, Inc	8010080389 8010160208* 8010220240 8010170366* 8010200326*	NUREO CONTRACT ACR9 CONTRACT CONTRACT
	8010150007 8010150035 8010150385 8010150484 8010150492*	50-289 0 50-289 0 50-320 V 50-289 8 50-289 8	Middie Bouth Services, Inc Mike Albert Leasing, Inc. Miller, Balis & O'Neil	8010240521 8010230330* 8010230444* 8010020073 8010030125	PR CONTRACT CONTRACT 50-445 0 50-445 H
	8010160014* 8010160488 8010160499	50-289 T 50-320 P 50-289 I	Miller, D. S Minerals Exploration Co (subs of Union Oli Co, of California)	8010270448 8010030139	50-307 G 40-8584
	8010140508 8010170225	50-320 P 50-287 P	Minnesota Power & Light Co Minnesota, State of	8010030150* 8010240438 8010170380*	40-8584 50-416 B CONTRACT
	8010170232* 8010170481 8010170516* 8010170518* 8010200005	50-289 P 50-289 P 50-289 P 50-289 P 50-320 Q	Hinnesota, Univ of, Minnespolis Hississippi Power & Light Co	8010070061* 8010010036* 8010010361 8010010361 8010010366*	CONTRACT 50-416 G 50-416 K 50-416 K
	8010200375 8010200417 8010200422* 8010200423 8010200424	50-320 0 50-320 8 50-320 8 50-287 P 50-320 8		8010010566* 8010010575* 8010010575* 8010010658 801001063	50-416 K 50-416 K 50-416 K 50-416 A 50-416 A
	8010200426* 8010200438 8010200452 8010200460 8010200486	50-320 S 50-320 P 50-320 P 50-287 P 50-287 P		8010010643 8010030436 8010060256 8010070346 8010070346	50-416 A 50-416 B 50-416 B 50-416 A 50-416 A
	8010200516 8010200647 8010210429 8010210431* 8010210445	50-287 S 50-287 C 50-287 R 50-287 R 50-287 P		8010080384 8010080416 8010080416 8010080582 8010140239	50-416 0 50-416 8 50-416 8 50-416 0 50-416 A
	8010210453 8010210465 8010210467* 8010210474 8010210507	50-287 P 50-289 P 50-289 P 50-289 P 50-320 P		8010140239 8010150328 8010150328 8010150336 8010150336	50-416 A 50-416 Q 50-416 Q 50-416 Q 50-416 Q
	8010210508* 8010210527 8010210528* 8010210640 8010210650	50-320 P 50-320 B 50-320 B 50-320 P 50-289 F		8010160504 8010160504 8010160514 8010160514 8010160537	50-416 8 50-416 8 50-416 8 50-416 8
	8010220101 8010220138 8010220431 8010220432* 801022047&	50-320 f 50-320 f 50-320 f 50-320 f 50-269 V		8010140537 8010170230 8010200338 8010200338 8010200357	50-416 K PR 50-416 H 50-416 H
	8010230205 8010230205 8010230212 8010230214 8010230304	50-287 @ 50-287 @ 50-320 @ 50-320 @ 50-320 @		8010200357 8010200487 8010200487 8010210007 8010210007	50-416 I 50-416 Q 50-416 Q 50-416 B
	8010230500 8010240057 8010240040* 8010240309* 8010240453	50-320 P 50-289 T 50-289 T 50-289 Q 50-289 P		8010210355 8010210355 8010210456 8010210478 8010210478	50-416 8 50-416 8 TOPREP 50-416 8 50-416 8
	8010240487 8010240494 8010240500+ 8010240508* 8010240512*	50-287 P 50-287 P 50-287 P 50-287 P 50-269 P		8010210531 8010210531 8010210630 8010210630 8010230138	50-416 0 50-416 0 50-416 8 50-416 8 50-416 8
	8010270182 8010280013 8010280403 8010280433 8010280433	50-320 Q 50-287 Q 50-320 P 50-320 R 50-320 R		8010230138 8010300497 8010300497 8010310511	50-416 8 50-416 8 50-416 8 50-416 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	APFILIATION	ACCESSION NUMBER	TOBLEUB
	8010310511 8010310517 8010310517 8010310523 8010310523	50-416 8 50-416 9 50-416 9 50-416 8 50-416 8	New England Muclear Corp New Jarsey, State of	8010070041# 8010210260 8010210180 8010010491# 8010050116	PR 50-443 0 71-5026 50-289 0 PR
Hississippi, Univ of, Hissouri, State of Missouri, Univ of, Columbia	8010170003 8010020693* 8010020709* 8010280378	NUREC 50-463 T 50-483 T 50-186 6		8010070052* 8010150366 8010160144* 8010200573*	CONTRACT 50-289 O CONTRACT 50-289 T
Missours, Univ of, Rolla Missours, Univ of, Rolla	8010080032	71-5088 XPDRTL1C		8010210371* 8010210471*	50-289 T 50-289 T
Mitsubishi Carp)	8010080035* 8010080307 8010080312* 6010160246	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	New Hest Magazine	8010230396* 8010240577 8010310480* 8010160055	50-269 Q 50-289 Q 50-269 T FGIA
Mittvi & Co. (U B.A), Inc. (Bubs of Mittvi & Co., Ltd.)	8010160247* 8010230321 8010020559	XPORTLIC XPORTLIC XPORTLIC	New York State Electric & Gas Corp	8010220391* 8010220391* 8010240076 8010240076 8010240082*	50-596 0 50-596 0 50-596 0 50-596 0 50-596 0
Mitsut & Co , Ltd	8010160213 8010160219*	XPDRTLIC XPDRTLIC		6010240092# 6010240087	50-596 Q 50-596 Q
Mabile Systems Monsanto Research Corp	8010080361* 8010060067 8010060069*	CONTRACT XPORTLIC XPORTLIC	New York Univ New York: State Univ of, Buffalo	8010240087 8010240623* 8010100308	50-574 Q 50-320 P 50-57 J
Mantgomary County, MD Margam, Lewis & Bockius	8010150649 ± 8010030514	CONTRACT 50-407 0	New York, State Univ. of, Stony Brook New York, State of	8010010269* 8010020255*	CONTRACT
Kargan-Melhuish-Monaghan & Meyer	801015036\$ 80102703B7 8010300044 801002066\$	50-554 G 50-409 G 50-409 G FOIA	NO 15111 Stead of	8010080269 8010160156* 8010219638*	PR CONTRACT State Prog
Mountain States Hineral Enterprises, Inc. H H Nesmark Consulting Engineering	8010200160 8010160199#	40-8698 50-275 0	New York, RY	8010290127* 8010210275 8010230122	State Prog State Prog State Prog
Bervices ML Industries, Inc	8010200624 8010210144	50-295 P 50-295 P	Newberry Township THI Steering Committee	8010140280 8010220526	50-320 P 50-289 0
Mr3 Corp	8010090021* 8010140083	CONTRACT FOIA	Niagara Mohawk Power Corp	8010010375 8010010438 8010010774	50-220 F 50-220 Q 50-410 Q
MUSAC.Inc National Science Foundation National Security Agency Natural Resources Defense Council	8010230037 8010210118 8010160164* 8010020670	NUREG PR CDNTRACT 50-201 G		8010010850 8010010852 8010020101	50-410 G 50-220 G 50-220 G
	8010070037 8010090041*	PR PR		8010020105 8010020317 8010070264	50-220 Q 50-410 Q 50-201 P
Nave, Dapt of	8010100240 8010160029 8010160032 8010020297*	PR 50-437 G 50-237 G CONTRACT		8010070319 8010070460 8010080478 8010080482*	50-220 P 50-410 A 50-220 B 50-220 B
Mavy, Rept of, Naval Pacilities Engineeri	8010200532 8010270041	71-371 REGOD		8010090481 8010100249	50-220 B 50-410 B
ng Gormand Nazy, Dept. of, Naval Research Laboratory Nazy, Dept of, Electronics Systems Engineering Canter, SC	8010230475 8010200537*	NUREG 71-371		8010150041* 8010150360 8010150404 8010150406*	50-410 B 50-220 P 50-220 R 50-220 R
Webrasha Public Power Bistrict	8010200547* 8010010004*	71-371 50-278 G		8010160472	50-410 8
	8010060157 8010070294 8010070298* 8010070480	PR 50-298 8 50-298 8 50-298 8		8010160518* 8010160520* 8010200381* 8010200378 8010200403	50-220 P 50-220 P PR 50-220 P 50-410 G
	8010070491* 8010140312 8010140315* 8010150376 8010160093	50-278 8 50-278 R 50-278 R 50-278 P 50-278 Q		8010200528 8010200535+ 8010220492 8010280585 8010300458	50-220 8 50-220 8 50-220 F 50-220 F 50-220 8
	8010200072 8010210274 8010210280* 8010210437*	50-298 Q 50-298 Q 50-298 Q 50-298 S 50-298 B		8010300463* 8010300647 8010310379 8010310448 8010310454*	50-220 B 50-220 P 50-220 P 50-220 B 50-220 B
	8010210447* 8010210447* 8010210708 8010210717* 8010220249	50-298 8 50-298 8 50-298 8 50-298 8 50-298 8	Nissho-Iwai American Corp.	8010060185 8010060189* 8010160237 8010300291 8010300355*	XPORTLIC KPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8010230059 8010230065 8010240126 8010240323 8010240431	50-278 Q 50-278 Q 50-278 Q 50-278 Q 50-278 P	North Carolina State Univ North Carolina, State of North Carolina, Univ. of Northeast Nuclear Energy Co (subs of Northeast Utilities)	8010230364 8010170371* 8010080633* 8010010084*	50-8 J CONTRACT CONTRACT 50-245 G
	8010280327 8010280380*	50-278 P 50-278 P		8010010423* 8010010660	50-423 8 50-245 Q
Hevada: State of New England Coalition on Nuclear Poliution	8010280381 8010020716* 8010090037	50-298 P CONTRACT PR		8010010701 8010010713 8010020276	50-423 G 50-245 G 50-245 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	9010020313 8010020504 8010020504 8010020756 8010020753	50-423 50-245 50-245 50-245 50-245	а Р Р а а		8010100262 8010100262 8010100295 8010100298* 8010100381*	50-282 F 50-282 F 50-263 P 50-263 P 50-282 Q	
	8010030313 0720400108 4720400108 *8720400108 601030303	50-218 50-245 50-245 50-245 50-245	0 R R R		8010140333 8010140333 8010140334* 8010140334* 8010150409	50-282 P 50-282 P 50-282 P 50-282 P 50-263 R	
	8010040319 8010040323 8010060330* 8010070183 8010080444	50-245 50-336 50-336 50-336 50-245	Ե ե Ե		8010150411* 8010150460 8010150471* 8010150482* 8010150491*	50-243 R 50-282 B 50-282 B 50-282 B 50-282 B	
	80100804474 8010080469* 8010090325 8010090335* 8010100038*	50-245 50-245 50-245 50-245 50-334	P P S S G Q		8010150497 8010150502* 8010140340 8010140347* 8010140351*	50-262 R 50-263 P 50-263 P 50-263 P	1
	8010100324 8010100324 8010170235 8010200325 8010200472	50-213 50-213 PR 50-334 50-213	P P P		8010160483 8010200450 8010200465 8010200540 8010200548#	50-263 P 50-282 8 50-263 F 50-306 8 50-306 8	
	8010210426 8010210432 8010210435* 8010220021 8010220130	50-245 50-336 50-336 50-213 PR	R R R Q		9010210492 8010210552 8010210492 8010210705* 8010220124	50-263 J 50-282 8 50-304 8 50-304 8 50-282 0	3
	8010230177 8010230385 8010230370# 8010240051 8010240202#	50-245 50-336 50-336 50-245 50-245	P 8 8 P 0		8010220124 8010220475 8010270364 8010280437 8010280437	50-282 0 50-263 P 50-282 8 50-263 I 50-263 I	3
	8010240255 8010270242 8010270242 8010280386 8010280387	50-245 50-213 50-213 50-245 50-245	P Q B B		8010280526 8010280533* 8010310355 8010310424 8010310456	50-263 8 50-263 8 50-282 F 50-263 P 50-282 F	3
	8010280537 8010280541* 8010300361 8010300365* 8010300419	50-336 50-336 50-336 50-336 50-245	8 8 P P	Northrop Corp. Nuclear Associates International Nuclear Assurance Corp Nuclear Dynamics	9010310443 8010020425* 8010070188 8010070172* 8010230383	50-187 P CONTRACT 71-6698 71-6698 40-8663	ı
Northeast Utilities	8010300422* 8010310324 8010310332* 8010310364 8010010569	50-245 50-245 50-245 50-245 50-336	ም የ Q የ	Nuclear Epergy Bervice, Inc. Nuclear Engineering Co., Inc., (subs. o. Taledyne, Inc.)		40-8663 40-8663 50-3 W 27-39	1
	8010020504 8010020756 8010090373 8010090373 8010090449	50-245 50-245 50-245 50-245 50-245	6 6 8 8 8 8		8010140782 8010170391 8010200517 8010200531* 8010200537* 8010200545*	27-39 27-39 27-39 27-39 27-39 27-39	
	8010070449 8010140439 8010140450* 8010150539 8010230422	50-245 50-245 50-245 50-245 50-245	8 8 8 8		8010200350* 8010200560* 8010200623* 8010220508 8010220515	27-39 27-39 27-10 27-39 27-39	
	8010230428* 6010240407 8010300452 8010300453* 6010300455	50-245 50-245 50-245 50-245 50-245	8 8 P P 8		8010220520 8010270149* 8010270156* 8010270160* 8010270165*	27-39 27-10 27-10 FOIA FOIA	
Northern Indiana Public Service Co.	8010030510 8010070475 8010150327 8010200669	50-367 50-367 150-367 50-367	Q R R	Nuclear Fuel Services: Inc. (subs of Oatty Oil Co.)	8010270380 8010020274	27-39 50-201 û	ì
	8010210524 8010270355 8010270401	50-367 50-367 50-367	R A Q		8010020370 8010070283 8010070386	70-143 70-143 70-143	
Northern States Power Co.	B010020648 B010040112 B010060117 B010060120	50-263 50-263 50-262 50-263	F Q Q		8010070424 8010090172 8010090177 8010090474 8010150417	70-143 70-143 70-143 50-201 P 70-143	5
	8010040235* 8010040235* 8010040303 8010060303	50-262 50-263 50-263	6 t t t t		8016150408 8010150412 8010150457 8010140342	70-143 70-143 70-143	R
	6010070318 8010070314* 8010070314* 8010070545 8010080451	50~282 50~282 50~263 50~263	F F J Q		8010160349 8010160378# 8010160493 8010200420	50-201 R 50-201 R 50-201 R 70-143 71-5059	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8010210325 8010210485 8010210766 8010240185*	70-143 70-143 70-143 70-143	Ott Water Engineers, Inc Otto H York Co. Inc PRC Planning & Economics. Alan M Yoorhees & Associates Div Partier Co. & Starter Co.	8010210004# 8010070591	40-8743 TOPREP 50-341 F
	8010240288	70-143	Pacific Gas & Electric Co	8010080345 1050800108	50-275 Q 50-275 A
Noclear Fuel Services, Inc., West Valley Reprocessing Flant	8010270285 8010310300 8010150601	70-143 70-143 50-201 F		8010080585 8010100427 8010140310	50-133 Q PR 50-275 A
Nuclear Information & Resource Service Nuclear Metals: Inc	8010270034 8010160646	FOIA 40-672		8010140310 8010140345	50-275 A 50-275 A
Muclear Technology, Inc (Nutech) Rucleonics Neeks, pub, of McGraw Hill, Inc.	8010220149* 8010220155* 8010020654* 8010080087	40-672 40-672 50-263 F FDIA		8010140345 8010140053 8010140054 8010140056 8010140449	50-275 A 50-275 Q 50-275 Q 50-275 Q 50-275 Q
Namm. Boyder & Associates	8010090055*	CONTRACT		B010140470+	50-193 R
QR1, int. Cei Rifge National Laboratory	8010070063* 8010160224* 8010010351 8010060007* 8010060025	CONTRACT CONTRACT NUREO 50-466 O NUREO		8010200189 8010200433 8010200435* 8010220118	PR NUREO NUREO PR
	8010070009* 8010070517* 8010090010 8010090399* 8010100200	50-466 0 50-466 0 NUREO NUREO NUREO		8010220485 8010220521 8010240403 8010240544 8010270031	PR 50~275 Q 50~275 P 50~133 Q 50~275 Q
	8010150134 8010150223 8010150241 8010150528 8010150579	REG RES RES RES RES		8010270031 8010270033 8010270033 8010270348 8010260439	50-275 Q 50-275 Q 50-275 Q 50-275 Q 50-133 V
	8010170066 8010170101 8010220579 8010280597 8010300304	NUREO REB REB RES REB		8010280460 8010280467# 8010280471# 8010300386 8010300391	50-133 8 50-133 8 50-133 8 50-133 0 50-133 0
Ogle Petroleum, Inc.	8010310540 8010150432 8010140529 8010200177 8010210357	RES 40-9745 40-9745 40-9745 40-9745	Pacific Legal Foundation Pacific Power & Light Go. Pathfinder Mines Corp.	8010300376 8010070400 8010020355* 8010010647 8010010672*	50-133 Q PR 50-522 A 40-2259 40-2259
Ohio River Basin Commission Ohio, State of	8010210372 8010230240 8010280379 8010080434 8010100136	40-8745 40-8745 40-8745 50-461 H	Pannsylvania Slectric Co Pennsylvania Power & Light Co	8010310233 8010310240 8010030442 8010010684 8010010833	REGOD REGOD 50-287 O 50-387 O 50-387 O
Oklahana: Umiv. of Omaha Public Power District	8010100346 8010200567 8010200574* 8010010297* 8010030415	D-346 H PR PR CONTRACT 50-285 8		8010020089 8010040247 8010040247 8010040284 8010070086	50-387 0 50-387 8 50-387 8 50-387 8 50-387 8
	8010030418* 8010040290 8010040344 8010070504 8010070511*	50-285 8 50-285 F 50-285 P 50-285 8 50-285 8		8010070084 8010070300 8010070300 8010070585 8010070585	50-397 B 50-397 B 50-397 B 50-397 A 50-397 A
	8010090394 8010140337 8010140443 8010140447* 8010140480	50-285 F 50-285 F 50-285 B 50-285 B		8010100337 8010100337 8010140031# 8010140271 8010140271	50-387 8 50-387 8 50-387 0 50-387 K
	8010140485# 8010140349# 8010160355# 8010200381#	50-285 8 50-285 P 50-265 P FR		8010140274# 8010140274# 8010140279# 8010140279# 8010140331	50-387 K 50-387 K 50-387 K 50-387 K 50-387 S
	8010200400 8010200402* 8010210761 8010210768 8010210761	50-285 R 50-285 R PR 50-285 Q 50-285 Q		8010140502 8010210411 8010240045 8010240045 8010240456	50-387 0 50-387 A 50-387 0 50-387 B
	8010230065 8010240104 8010240208 8010270210 8010280359	50~285 Q 50~285 Q 50~285 F 50~285 Q 50~285 J		8010270174 8010270174 8010300561 8010300561 8010300606	50-387 Q 50-387 Q 50-387 Q 50-387 Q 50-387 Q
Service St. L.	8010270374 8010270376* 8010300472 8010300508* 8010310321	50~285 8 50~283 8 50~285 0 50~285 0	Pennsylvania, State of	8010300606 8010300613 8010300618 8010300618	50-387 0 50-387 0 50-387 0 50-387 0 50-287 0
Orlando Utilities Commission Osann, E. W.	8010160342+ 8010300092 8010290329+ 8010210776	CONTRACT 50-344		8010160173* 8010220070* 8010240069 8010240599*	CONTRACT 50-320 P 50-289 Q 50-320 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ
Perkins, Coie, Stone, Olsen & Williams Philadelphia Electric Co.	8010070313 8010200437 8010010114# 8010010116# 8010010208	50-522 \$0-522 50-277 50-277 50-277	0 A Q Q	Pittsburgh Testing Laboratory Pittsburgh-Dae Moines Steel Co	B010210505* 8010210277 8010240019* 8010270356* 8010230215	50-305 REGGD GA999 GA999 40-7869	
	8010010244 8010010623 8010010707 8010010707 8010010803	50-277 50-352 50-277 50-277 50-277	9 9 9	Portland General Electric Co	8010230523 8010010364 8010010370* 8010010559 8010020341	40-8698 50-344 50-344 50-344 50-344	0 P P
	8010010803 8010010821 8010010821 8010010840 8010010840	50-277 50-277 50-277 50-352 50-352	0 0 0 0		B010020345* 8010020347* 8010020378* 8010030432 8010030437*	50-344 50-344 50-522 50-344 50-344	9 A 9 9
	8010010848 8010010848 8010020117 8010020117 8010020197	50-352 50-352 50-352 50-352 50-352	0 0 0		8010040274 8010070299 8010080151* 8010080349 8010080322	50-344 50-344 50-344 50-344 50-344	S F Q O H
	8010020197 8010020203 8010020253* 8010020331 8010020475	50-352 50-171 50-352 50-277 50-277	0		8010080552 8010070337 8010070344* 8010140021 8010140474	50-344 50-344 50-344 PR 50-344	P 8 6
	8010020488 8010020488 8010020490* 8010020493* 8010020493*	50-277 50-277 50-277 50-277 50-277	6 6 6		80101503B3 8010150438 8010150449* 80101605B7 8010170201	50-344 50-344 50-344 50-344 PR	8 R 8
	8010030361 8010030366 8010030371 8010070337 8010070496	50-277 50-278 50-277 50-277 50-278	8 8 9		8010200179 8010200187 8010210385 8010210443 8010210545	PR 71-9010 50-344 50-344 50-514	8 P
	8010080487 8010080541 8010080541 8010090333 8010100094#	50-277 50-277 50-277 50-352 50-352	8 F A		8010210545 8010210571# 8010210571# 8010210700 8010210707#	50~514 50~514 50~514 50~344 50~344	9 9 9
	6010100350 8010100431# 8010140054# 8010140054# 8010140483	50-277 50-277 50-352 50-352 50-277	R Q Q S		8010210740 8010210742 8010210748* 8010220351 8010270280	PR 50-344 50-344 50-344 50-514	S B P A
	8010190375 8010190375 8010190377* 8010150377* 8010150388	50-277 50-277 50-277 50-277 50-352	R R R A		8010270367 8010280347 8010280449 8010280452* 8010280498	50-344 50-344 50-344 50-344 50-344	4
	8010200393 8010200408 8010200451 8010200451 8010200458	50-277 50-277 50-277 50-277 50-277	6 6 6		8010280599 8010290378 8010290378 8010290382* 8010290382*	TOPREP 50-514 50-514 50-514 50-514	0
	8010200459 8010200459# 8010200459# 8010200461# 8010200461#	50-277 50-277 50-277 50-277 50-277	6 6 6		8010300027 8010300421 8010300424# 8010300425# 8010300478	50-344 50-344 50-344 50-344 50-344	0000
	8010200464* 8010200464* 8010200584 8010200584 8010210329	50-277 50-277 50-277 50-277 50-277	Р Р Р	Power Authority of the State of New York	8010310390 8010010221 8010010644 8010010673 8010010679	50-344 50-286 50-333 50-286 50-333	F 0 0 0 0
	8010210668 8010210725 8010210735# 8010230104 8010230104	50-278 50-277 50-277 50-277 50-277	8 8		8010010740 8010010815 8010020308 8010020558 8010020757*	50-333 50-333 50-333 50-286 50-286	0 0 0 F
	8010230191 8010230711* 8010230713* 8010240522 8010270124	50-352 50-352 50-352 50-171 50-277	9 (9)		8010030417 8010060333 8010060347* 8010070286 8010070307	50-286 50-333 50-333 50-286 50-286	Р 8 8 8 8
	8010270358 8010270363 8010270375 8010280372 8010280372	50-277 50-277 50-278 50-277 50-277	8 8 8		8010070309* 8010070311* 8010070524 8010100290 8010100291*	50-286 50-286 50-333 50-333 50-333	P P R R
Thysicians for Bocial Responsibility Tickeré Lowe & Garrick, Inc.	8010280423 8010310443 8010020600# 8010140353# 8010210464#	50-277 50-278 50-344 50-275 50-275	P B H A P		8010100300 8010100315 8010190286 8010160487 8010160494*	50-286 50-286 50-333 50-333	Р Р Р

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	ŧγ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQOR	
	8010140500* 8010200381* 8010200441 8010200454 8010200587	50-333 PR 50-333 50-286 50-333	P P E		8010170206* 8010170206* 8010200381* 8010230683* 8010240402	50~546 50~546 PR 50~546 50~546	8
	8010200594* 8010210412 8010210415* 8010210670 8010210677*	50-333 50-286 50-286 50-333 50-333	8 R R S		8010240402 8010240409 8010240409 8010240414 8010240457	50-546 50-546 50-546 50-546 50-546	8 8 8
	8010210764 8010200027 8010220273 8010220300 8010220362	PR 50-333 50-333 50-286 50-286	0 0 F		8010240457 8010240550 8010270207 8010270207 8010270365	50-546 PR 50-546 50-546 30-546	8 8 8
	8010220413 8010220487 8010220528 8010220668* 8010230516	50-333 PR 50-333 50-333 71-4244	P F Q	Public Service Co of New Hempshire	8010270367 8010300484 8010010697 8010020082 8010020082	50-546 50-546 50-443 50-443 50-443	9 0 0
	8010230689 8010240002 8010270198 8010280376 8010280383	50-349 71-5026 50-286 50-286 50-286	0 G H P		8010030539 8010200700* 8010200700* 8010200707* 8010200547	50-443 50-443 50-443 50-443	9 9 6
	8010280398 8010280419 8010280429* 8010290350 8010310017	50-333 50-333 50-333 50-333 50-333	H 8 8 P 0	Public Service Electric & Gas Co of New Jersey	8010270513 8009150235 8009150341* 8009150341* 8010010311*	50-443 50-272 50-272 50-272 50-354	o F F G
Power Conversion Products, Inc President of US & Executive Offices	8010310386 8010300488 8010080142 8010220367# 8010230645#	50-333 50-498 PR 50-289 50-320	Р 8 Н Н		8010010A07* 8010010B19 8010010B2A 8010010B2A 801002015B*	50-272 50-354 50-272 50-272 50-354	9 9 9 9
Pretech. Inc Public Citizen Litigation Group Public Bervice Co of Colorado	8010270073* 8010270083* 8010100318* 8010160572 8007100240	50-320 50-320 TOPREP PRM 50-267	H H		8010020207* 8010020285 8010030447 8010030454* 8010060130	50-354 50-272 50-272 50-272 50-272	9 8 9
	8007100246* 8010060155* 8010070401 8010070407* 8010070412	50-267 50-267 50-267 50-267 50-267	6 8 8		8010040219 8010040234* 8010040271 8010040272 8010040279*	50-311 50-311 50-272 50-272 50-272	88789
	8010070416# 8010070532 8010080334 8010080339# 8010080444	50-267 50-267 50-267 50-267 50-267	8 J A A P		8010050280* 8010050283 8010050285* 8010050287* 8010050291	50-272 50-272 50-272 50-272 50-272	88488
	8010080467* 8010080472* 8010150505 8010150517* 8010140595	50-267 50-267 50-267 50-267 50-267	P B G P		8010040295# 8010070530 8010080421 8010100061# 8010100193	50-272 50-272 50-272 50-272 50-272	8 P P O F
	8010160541# 8010160543# 8010210263 8010210542 8010210652	50-267 50-267 50-267 50-267 50-267	P P P 8		8010100193 8010100197# 8010100264 8010100264 8010100293*	50-272 50-272 50-272 50-272 50-272	****
	8010210454* 8010210711 8010210717* 8010230052 8010230073	50-267 50-267 50-267 50-267 50-267	g 8 8		8010100327 8010100336# 8010100340 8010100348# 8010150215#	50-272 50-272 50-311 50-311 50-354	8 8 8
	8010230097 8010270361 8010270362 8010280474 8010280479*	50-267 50-267 50-267 50-267 50-267	0 P 8 8		8010160486 8010160510 8010160516 8010200377 8010200378*	50-311 50-311 50-311 50-272 50-272	P V P R
	8010280516 8010280527 8010280551* 8010280586* 8010300547	50-267 50-267 50-267 50-267 50-267	8 6 9 9		8010200382 8010200384* 8010200591 8010200592* 8010210380	50-311 50-311 50-272 50-272 50-311	R R B B
Public Bervice Co. of Indiana, Inc.	8010310398 8010040224 8010040224 8010040289 8010040288	50-267 50-546 50-546 50-546 50-546	P 8 8 8		8010210472 8010210475* 8010210477* 8010210648 8010230200	50-272 50-272 50-272 50-272 50-272	P P P G
	8010070107 8010100176 8010150099* 8010150296 8010160683	50-546 REGOD 50-546 50-546 PR	g A		8010230200 8010230276# 8010240372 8010270093#	50-272 50-272 50-247 50-477	G G A

author Affiliation	ACCESSION NUMBER	SUBJECT CATEOUR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	6UBJECT CATEGORY
	8010270114 8010270374 8010270377*	50-354 50-272 50-272	0 8 8	Rockwell International Corp , Hanford Operations	8010290084 8010210273	PT21 RECOD
	6010540353* 8010540350	50-272 50-272	P P	Rocky Mountain Energy Co	8009090385 8009090393* 8010090165	40-8697 40-8697 40-8697
	8010290334 8010300640 8010310301 8010310301 8010310305*	50-272 50-272 50-272 50-272 50-272	ያ 0 F F F		8010230544 8010230550 8010230540 8010240572 8010270342	40-8697 40-8380 40-8380 40-8697 40-8697
Puarto Rico Electric Power Authority Puget Sound Power & Light Co	8010310305* 8010080273 8010020337 8010020337 8010020343*	50-272 50-376 50-522 50-522 50-522	F 0 A A	Ropes & Gray Rutgers, New Jarsey, State Univ. of	8010220547 8010270513 8010300073 8010310451 8010060124	50-443 0 50-443 0 50-309 0 50-293 0 PR
Purdue Univ R W Beck & Associatos	8010020343* 8010020347* 8010020347* 8010310247 8010310247	50-522 50-522 50-522 50-182 50-445	A A F M	SRI International Sacramento Municipal Utility District	8010310371* 8010010547 8010010570 8010040300 8010040306*	50-282 F 50-312 P 50-312 P 50-312 B 50-312 B
RMI Co , RMI Titanium Radiation Research Associates Radiation Services, Inc. Radiation Therapy Associates Detroit,MI Ralph Stone & Co	8010240488 80100305454 8010000270 8010280107 8010020595*	XPORTLIC CONTRACT 40-2061 40-8710 CONTRACT	T		8010070187 8010080292 8010080373 8010090197# 8010090190#	50-312 F 50-312 Q 50-312 Q 50-312 Q
Reactor Experiments, Inc Rehab Group, Inc Rensselaer Polytechnic Inst	8010170596* 8010270156 8010010262* 8010080618* 8010070022	CONTRAC' XPORTLIC CONTRAC' CONTRAC' NUREO	C T		8010140468 8010140473 8010150064* 8010150294 8010150298*	50-312 F 50-312 F 50-312 Q 50-312 R 50-312 R
Rhode Island, State of	8010070026* 8010070027* 8010160196* 8010240528 8010240532*	NUREG NUREG CONTRAC 50-193 50-193	r J		8010150426 8010160480 8010160851 8010170445 8010170531*	50-312 P 50-312 P 50-312 F 50-312 P 50-312 P
Ridihalgh, Eggers & Associates Rio Algom, Ltd Robatel StPI Genas,France Rochester Gas & Electric Corp	8010100235* 801030047B 8010310057* 6010210243* 8007160559	CDNTRAC 40-8084 40-8084 71-9016 50-244			8010200527 8010210448 8010230184 8010280426 8010280457	50-312 P 50-312 0 50-312 P 50-312 P
	8009160562* 8009160567* 8009160568* 8009160570* 8009160574*	50-244 50-244 50-244 50-244 50-244	P P P	Bafe Energy Alliance	B010300017* 8010300680 8010020554 B010090071 B010140016	\$0-312 0 50-312 0 50-369 H 70-2909 70-2909
	8009160576* 8009160577* 8009160578* 8009160580*	50-244 50-244 50-244 50-244 50-244	₽ ₽ ₽ ₽	Ban Diego Gas & Electric Co Ban Francisco, City of, CA San Luis Obispo Mothers for Peace	8010020632 8010100359 8010080114 8010200174 8010210518*	PR 50-582 A PR 50-275 0 50-275 0
	8010010464 8010010717 8010010768 8010010825 8010010831	50-244 50-244 50-244 50-244 50-244	9 9 9 0	Sanders & McDermutt Sandia Laboratories	8010210491 8010020642 8010080203 8010090008 8010090288*	50-443 G NUREO NUREO NUREO REVIEW ORF
	8010020095 8010020113 8010020374 8010030375 8010040274	50-244 50-244 50-244 50-244 50-244	9 9 9		8010140609 8010170118 8010280668 8010290176 8010300543	NUREG RES TOPREP NUREG NUREG
	8010060285* 8010080410 8010090372 8010140477 8010140482*	50-244 50-244 50-244 50-244 50-244	8 J 8 8	Sandvik Special Metals Corp Sargent & Lundy, Inc	8010160037 8010170006 8010020271* 8010020271* 8010020278*	XPORTLIC XPORTLIC 50-295 P 50-295 P 50-295 P
	8010160476 8010210061 8010230377 8010230382* 8010240055*	50-244 REQUD 50-244 50-244 50-244	V R R G		8010020278* 8010020448* 8010020448* 8010020456*	50-275 P 50-454 A 50-454 A 50-454 A
Rockwell International Corp	8010280420 8010300637 8010310256 8010310373 8010020074	50-244 50-244 50-244 50-244 71-5088	P Q		8010020465* 8010020465* 8010020507* 8010020507* 8010020509*	50-454 A 50-454 A 50-454 A 50-454 A
Rockwell International Corp , Energy Systems Div.	8010020085* 8010080372 8010020599	71-5088 NUREQ PT21			8010020507* 8010020510* 8010020510*	50-454 A 50-454 A 50-454 A
wy static Mars	8010070529 8010070539*	50-329 50-329	Â		8010020511* 8010020511*	50-454 A 50-454 A
	8010150558 8010220212 8010220220* 8010280434	70-25 70-25 70-25 50-94	J		8010020512* 8010020512* 8010020513* 8010020513*	50-454 A 50-454 A 50-454 A 50-454 A

AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFIL IATION	ACCESSION NUMBER	SUBJECT CATEOORY
	8010020515# 8010020515# 8010020521# 8010020521# 8010020526#	50-454 A 50-454 A 50-454 A 50-454 A 50-454 A		8010080290* 8010080343 8010150174 8010230012 8010230034	NUREO NUREO NUREO NUREO NUREO
	8010020533* 8010020533* 8010020537* 8010020537* 8010030423	50-454 A 50-454 A 50-454 A 50-454 A TOPREP	Shaw, Pittman, Potts & Trombridge	B010230046 B010230048 B010080240 B010080251 B010080281	NUREO NUREO 50-289 O 50-483 O 50-289 O
	8010030427# 8010070564# 8010070570# 8010070579# 8010090425#	TOPREP 50-237 P 50-237 P 50-237 P 50-234 P		8010140292 8010140491 8010140502 8010140541 8010150007	50-287 0 50-287 0 50-387 0 50-483 0 50-289 0
	8010090429* 8010090432* 8010090435* 8010090448* 8010090440*	50-254 P 50-254 P 50-254 P 50-265 P 50-265 P		8010150035 8010150401 8010150401 8010160025 8010160025	50~287 G 50~483 G 50~483 G 50~483 G
	8010210750 8010210754 8010220552* 8010220558* 8010220560*	PR PR 50-275 P 50-275 P 50-275 P		8010200665 8010200671 8010240435 8010280013 8010270383	50~483 0 50~483 0 50~266 0 50~289 0 50~289 0
	8010220565* 8010220569* 8010220573* 8010220574* 8010220575*	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P	Bheldon, Harmon & Weiss	8010300606 8010300613 8010300687 8010020200 8010020670	50-387 0 50-387 0 50-289 0 70-143 50-201 0
	8010220577* 8010220577* 8010220581* 8010220582* 8010220585*	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P		8010030111 8010080420 8010080422 8010090037 8010090041*	50-287 0 50-443 0 50-289 0 PR PR
	8010220586* 8010220588* 8010220588* 8010220574* 8010220597*	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P	Sherwood, M R Shoreham Opponents Comlition	8010140012 8010210260 8010270452 8010230685 8010140527+	50-289 0 50-443 0 50-443 0 50-133 0 50-322 0
	8010220404* 8010220408* 8010220411* 8010220412* 8010220415*	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P	Sierra Club Sigma Chemical Co (subs. of Bigma-Aldri ch Corp) Small Business Administration	8010140533* 8010090483 8010230685 8010160257	50-322 0 50-201 P 50-133 G XPORTLIC
	8010220617* 8010220617* 8010220621* 8010220622* 8010220625*	50-295 P 50-295 P 50-295 P 50-295 P 50-295 P	OHERT BUSINESS HORITIDES GOLDS	8010040137* 8010080618* 8010090064* 8010090141* 8010170532*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
Sæiton Nuclear Experimental Corp	8010220526* 8010220530* 8010220536* 8010220641* 8010070484	50-295 P 50-295 P 50-295 P 50-295 P 50-146 R	Spriety Against Nuclear Energy Source Production & Equipment Co , Inc. South Carolina Electric & Oas Co	8010200366* 8010020501 8010240034 8010240036* 8010010655	CONTRACT 50-409 H 71-102 71-102 50-395 A
Scanit Shoreline Preservation Conference, In: Schult: W B Science Applications, Inc	8010070488* 8010220554 8010020047 8010020055* 8010100399*	50-146 R 50-275 Q 50-367 Q 50-367 Q CONTRACT		8010020353 8010040101 8010040225 8010040230* 8010070187	50-395 A PR 50-395 A 50-395 A 50-395 K
Scientists & Engineers for Secure Energy Seamodal Transport Corp	8010170388> 8010200258 8010020663 8010200019 8010170459	CONTRACT 70-1113 50-201 G PR XPORTLIC		8010070192* 8010070257 8010070240* 8010140272 8010140535	50-375 K 50-375 F 50-375 F 50-375 A 50-375 Q
Senate	8010020413* 8010020424* 8010100125* 8010210109* 8010220494	50-546 U 50-266 Q 50-309 U MIBC 50-201 Q		8010140594 8010160503 8010160512 8010160553 8010160558*	50-375 O 50-375 K 50-375 A 50-375 F 50-375 F
Senate, Appropriations	8010270529* 8010270542* 8010280105* 8010290275* 8010080672*	50-320 P 50-250 H 50-290 H 50-345 H 50-344 H		8010160745 8010200457 8010230401 8010240442 8010240445+	PR 50-375 8 50-375 K 50-375 F 50-375 F
Senate, Qovernmental Affairs Sensible Maine Power Saymour & Willis	8010070448* 8010080198* 8010150095 8010210513 8010210513	COMMISSION COMMISSION 50-309 ¢ 50-275 0 50-275 9	South Carolina. State of South Datota: State of	8010290198 80100102824 8010160149* 8010070281 8010210775	50-375 O CONTRACT CONTRACT NUREO WASTE MOT
Shannon & Hilson, Inc	8010210518* 8010210518* 8010080282 8010080287*	50~275 0 50~275 G NUREO NUREO	Southern Celifornia Edison Co	8008150360 8010010522 8010060266 8010060289	50-206 F 50-206 F 50-206 B 50-206 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	3Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	٧
	8010040297* 8010040348 8010070277 8010070278* 8010070462	50-206 50-206 50-206 50-206 50-206	8 8 9 9	4	8010010844 8010010844 8010010844 8010020189 8010080555	50-482 50-482	0 0 0
	8010070548 8010070548 8010070574* 8010070574* 8010080107*	50-361 50-361 50-361 50-361 50-208	A A A Q		8010080555 8010080555 8010160410 8010160410 8010160410		8
	8010080189* 8010080274 8010080283 8010080454 8010080459*	50-206 50-206 50-206 50-361 50-361	Q Q Q A		8010160548 8010210292 8010270208* 8010270208* 8010270208*	50-462 50-462 50-462 50-462 50-462	A 0: 8: 8: 8:
	8010080459* 8010080462* 8010080462* 8010080526 8010080526	50-361 50-361 50-361 50-361 50-361	A A A	Stanford Univ State.Dept of State.Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs	8010080418 8010220165 8010100294 8010010124	50-141 ACR8 XPORTLIC XPORTLIC	1
	8010080590 8010080590 8010140326 8010150279 8010150284	50-341 50-341 50-204 50-204 50-204	O O P R P		8010070128 8010100218 8010100277 8010140622 8010160067	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8010150372 8010150407 8010150407 8010150440 8010150454*	50-206 50-361 50-361 50-206 50-206	e R R R	Steel, Hector & Davis Stone & Webster Engineering Corp	8010270273 8010310112 8010030312 8008200164* 8010160584*	XFORTLIC XFORTLIC 50-250 50-338 50-337	:
	8010140003 8010200354 8010210328 8010210331 8010210337*	50-204 50-204 50-204 50-204	P V P P		8010160570* 8010160574* 8010200201 8010210197 8010210706	50-339 50-339 PR REGOD PR	P
	8010210343# 8010210442# 8010210636 8010210636 8010210643#	50-204 50-206 50-361 50-361 50-361	F G A A A	Suffolk County, NY Susquehanna Environmental Advocates Susquehanna Valley Alliance	8010240422 8010080121 8010270214 8010270510 8010270358*	TOPREP 50-322 50-320 50-387 50-320	0 P 0 P
	8010210443* 8010210673 8010210685* 8010240075 8010240398	50-361 50-206 50-206 50-361 50-361	A 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	Sutton,R H TERA Corp Target Rock Corp. Technassociates: Inc	8010170163* 8010080512* 8010200373* 8010240543 8010020601*	NUREO 50-275 CONTRACT 50-361 CONTRACT	8
	8010240491 8010270370 8010270378 8010270379* 8010280374	50-206 50-206 50-206 50-206 50-361	а 8 К	Technology for Energy Corp Teknakron Research, Inc.	8010060139* 8010200366* 8010060267 8010310366 8010150171	CONTRACT CONTRACT COEE-08 NORUM OBRUN	
Southern Co. Services, Inc. Southern Systems, Inc Southwest Fabricating & Weiding Co (subs of IU International Corp.)	8010300682 8010170218 8010300608 8010070223* 8010210602*	50-206 PR 50-424 CONTRAC GAPPP	G G T	Teledyne Energy Systems Tennessee Valley Authority	8010140176 8010140181* 8010140265* 8010240187 8009100414	71-6744 71-6744 71-6744 71-46 50-928	8
Southwest Research Institute	8010210611* 8010210732* 8010210738* 8010210746* 8010140544	0A999 0A999 0A999 0A999 NUREO			8009190438 8009190448* 8009300395 8009300400 8010010841	50-296 50-296 50-328 50-259 50-518	8 8 9 8
Bouthwest Taxes Electric Cooperative Spain:0 H Spiegel & McDiarmid	8010030125 8010270145 8010070541 8010150024 8010150399*	50-445 FOIA 50-445 50-445 50-397	н н н		8010010861 8010010861 8010010861 8010010861 8010010861	50-518 50-518 50-518 50-518 50-518	8 8 8
	8010150419* 8010170385 8010170385 8010170385 8010170385	50-389 50-445 50-445 50-445 50-445	м м м м		8010020480 8010020480 8010020480 8010020480 8010020480	50-260 50-260 50-259 50-260 50-260	4444
	8010200387 8010200387 8010200387 8010200387 8010220316	50-445 50-445 50-445 50-445 50-445	M M M		8010020480 8010020480 8010020749 8010030349 8010030373*	50-260 50-260 50-259 50-260 50-260	P 0 8 8
	8010220316 8010220316 8010220316 8010220320*	50-445 50-445 50-445 50-445 50-445	м м м м		8010030396 8010030396 8010030397* 8010030397*	50-259 50-259 50-259 50-259 50-259	11111
Standardized Nuclear Unit Power Plant Bystem	8010220320# 801027043P 8010010835	50-445 50-445 50-482	M Q		8010030397# 8010030411 8010060241 8010060299	50-259 50-259 50-327 50-294	F 8 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFICIATION	ACCESSION NUMBER	SUBJECT	
	8010040307# 8010040310 8010040314# 8010040329 8010040335#	50-294 50-294 50-294 50-259 50-259	9 9 8		8010200220* 8010200403 8010200417* 8010200529 8010200529	40-1341 50-259 50-259 50-259 50-259	\$ B B P
	8010070332 8010070332 8010070332 8010070332 8010070332	NUREG NUREG NUREG NUREG NUREG			8010200329 8010200534# 8010200534# 8010200534# 8010210348	50-259 50-259 50-259 50-259 50-259	P P P R
	8010070332 8010070332 8010070332 8010070332 8010070332	NUREG NUREG NUREG NUREG NUREG			8010210348 8010210348 8010210365 8010210367 8010210367	50-259 50-259 50-390 50-327 50-327	R R 8 8
	8010070332 8010070342 8010070470 8010070479* 8010070479*	NURE9 50-518 50-327 50-327 50-327	5 5 5 6		8010210397 8010210405 8010210481 8010210483 8010210484*	50-544 50-329 50-259 50-294 50-294	8 F P
	8010070485 8010070490* 8010070592 8010070598* 8010080385	50-259 50-259 50-327 50-327 50-327	88888		8010210488 8010210489 8010210514 8010210517* 8010210560	50-327 50-370 50-327 50-327 50-328	9 8 8
	8010080391 8010080392* 8010080429 8010080429 8010080461	50-327 50-327 50-390 50-390 50-259	9 8 8		8010210578 8010210588 8010210590 8010210590 8010210596	50-438 50-259 50-327 50-327 50-327	8 8 8
	8010080443* 8010080497 8010080506* 8010080506* 8010080506*	50-259 50-519 50-519 50-518 50-518	8 R R R		8010210596 8010210634 8010210635 8010210641* 8010210642*	50-327 50-327 50-327 50-327 50-327	9 9 8
	8010080506# 8010080519 8010080519 8010090094 8010090102	50-518 50-553 50-553 50-327 50-259	R 8 9 0		8010210454 8010210457# 8010210458 8010210459 8010210463#	50-327 50-327 50-260 50-327 50-260	8 8 8
	8010090102 8010090384 8010090384 8010090407 8010100437	50-259 50-259 50-259 50-390 PR	0 P 8		8010210665* 8010210667 8010210678 8010210679* 8010210682	50-327 50-327 50-259 50-327 50-296	8 8 8
	8010140365 8010140371* 8010140383 8010140390* 8010150320	50-240 50-240 50-296 50-296 50-259	8 8 9		8010210489* 8010210490 8010210491 8010210493 8010210495*	50-294 50-327 50-259 50-327 50-259	8888
	8010150326 8010150330* 8010150332 8010150332 8010150332	50-327 50-327 50-259 50-259 50-259	R R R R		8010210696 8010210697* 8010210698* 8010210699* 8010210701	50-327 50-327 50-259 50-327 50-327	8 8 8 8
	**CECCC10108 **CECCC10108 **CECCC10108 **CECCC10108 **CECCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC	50-257 50-438 50-390 50-327 50-259	R 8 9		8010210702 8010210703* 8010210710* 8010210714* 8010210727	50-260 50-327 50-260 50-327 50-327	8 8 8 8
	8010130393 8010150393 8010150398* 8010150398*	50-259 50-259 50-259 50-259 50-259	8 8 8		8010220395 8010220399* 8010220453 8010220455* 8010220505	50-296 50-296 50-327 50-327 50-259	P R R
	8010150430 8010150463 8010150513 8010150525* 8010160507	50-438 50-259 50-260 50-260 50-259	G S S R		6010220505 8010220505 8010220509* 8010220509* 8010220507*	50-259 50-259 50-259 50-259 50-259	P P P
	8010160309 8010160309 8010160311* 8010160311* 8010160311*	50-259 50-259 50-259 50-259 50-259	R R R		8010240419 8010240426 8010270349 8010270351 8010270351	50-438 50-438 50-327 50-327 50-327	6 6 9 P
	8010160523 8010160533 8010160533 8010160536 8010160536	50-328 50-438 50-438 50-438 50-438	8 8 8 8		8010270353* 6010270396* 6010270483 6010270491* 8010280368	50-327 50-327 50-260 50-260 50-328	8 8 8
	8010140379 8010140579 8010170031* 8010170123* 8010200212	50-438 50-438 50-327 50-327 40-1341	8 9		8010280371 8010280371 8010280373 8010280373 8010280376	50-438 50-438 50-438 50-438 50-328	8888

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY	Y	AUTHOR AFFILIATION	ACCEBBION NUMBER	BUB JECT CATEGORY	
	8010280400 8010280400 8010280427 8010280427 80102804427	50-438 50-438 50-328 50-328 50-327	8 8 8	Texas Utilities Services, Inc Texas, State of	8010310104 8010310434 8010010556 8010080476 8010010007	50-445 50-445 50-445 50-445	G A G
	8010280445 8010280451 8010280459 8010280465 8010280468	50-566 50-438 50-390 50-327 50-259	8 Q 8	Texas, Univ of Thomas & Hair Three Hile Island Alert Timex Corp	8010210494 8010210499* 8010270457 8010140540 8010040182	50-192 50-387	P 0 0
	8010280478 8010280508* 8010280511* 8010280518 8010280562*	50-370 50-327 50-257 50-327 50-327	û 8 8 8	Todd Shipyards Tolado Edison Co	8010030440# 8007110364# 8010010312 8010010313# 8010010371	50-346	8
	8010280363 8010280368* 8010280376 8010280376 8010280611	50-259 50-259 50-546 50-546 50-546	8 8 8 9		8010010597# 8010020075# 8010020372 8010030288 8010030445	50-346 50-346 50-346	8 9 9
	8010280611 8010280617 8010280617 8010280626 8010280626	50-566 50-438 50-438 50-370 50-370	0 8 8 8		8010030451* 8010060359 8010070451 8010070458* 8010070492	50-346 50-346 50-346	8 8 8
	E010270317 E010310333 E010310338 E010310400 E010310587*	50-566 50-259 50-566 50-438 CONTRACT	Q P A		8010070305# 8010080233 8010080237# 8010080427 8010080427		B P
Tennesses, State of Tatum Exploration Drilling Co., Inc. Tetra Tech, Inc Texas Instruments, Inc.	8010200319# 8010210584 8010230283 8010200018 8010210480	CONTRACT 50~537 40-8728 PR 70-33	A		8010100228* 8010140247 8010140249* 8010130275 8010130321	50-346	Q P Q R
Texas Nuclear Div. (subs. of Ramsay Eng. Co.)	8010210567 8010280524 8010280532* 8010240499	70-33 70-33 70-33 XPDRTLIC			8010150323* 8010200434 8010200437* 8010200444 8010200448*		R 8 8 8 8
Texas Public Interest Research Group Texas Tech Univ.	8010300309 8010300318* 8010100066 8010160016 8010090068* 8010240558*	XPORTLIC XFORTLIC 50-466 50-466 CONTRACT 70-25	0		8010270387 8010270388* 8010310311 8010310460 8010310464*	50-346 50-346 50-346 50-346 50-346	8 8 P 8
Texas Utilities Co. Texas Utilities Generating Co.	8010010554 8010010532 8010010532 8010010533* 8010010533*	50-445 50-445 50-445 50-445 50-445	A C C C C	Toledo, Univ. of Touche Rosa & Co. Transamerica Delaval, Inc. Transnuciear, Inc.	8010270008* 8010140117* 8010020403 8010010119 8010010158	XPORTLIC XPORTLIC	8 N
	8010020729 8010020729 8010060264 8010080202 8010080202	50-445 50-445 50-445 50-445 50-445	0 0 0 0		8010020083 8010020084 8010020417 8010090080 8010140270	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8010080263 8010080289 8010080289 8010080289 8010080289	50-445 50-445 50-445 50-445 50-445	о м м м		8010150623 8010160043 8010170004 8010170008 8010170288	70-2476 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8010080319 8010080319 8010080319 8010080319 8010090341#	50-445 50-445 50-445 50-445 50-445	м н м		8010170291* 8010230060 8010230068* 8010280697 8010280702*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8010140002 8010150002 8010150391 8010150391 8010170464#	50-445 PR 50-445 50-445 50-445	M F F Q	Transportation, Dept. of	8010310574 8010310402* 8010010282* 8010020255* 6010020716*	XPORTLIC XPORTLIC CONTRACT CONTRACT CONTRACT	
	8010170479 8010170302 8010200343 8010200343 8010200346#	50-445 50-445 50-445 50-445 50-445	8 8 K K K	Turner, College & Braden, Inc. Twomey. Letham & Schmitt U.S. Arms Control & Disarmament Agency US Steel Corp.	8010060341 8010140566* 8010140523 8010140166* 8010290137	50-445 50-466 50-322 CONTRACT REGOD	H 0 0
	8010200344* 8010200347* 8010200347* 8010200416 8010210503	50-445 50-445 50-445 50-445 50-445	K K K 8	Union 76 Minerals Exploration Co. Union Carbide Corp.	8007030276* 8010240340 8010200207 8010210603 8010100023*	50-392 NUREQ 40-8348 40-8584 70-143	8
	8010280354 8010280354 8010280358 8010280358	50-445	8 9 9		8010200638 8010270308 8010280391 8010280408 8010280412*	50-54 40-277 40-277 50-54 50-54	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCEBBION NUMBER	EUBJEC CATEGO	
vilan Electric Co	8010010503* 8010070497 8010080251 8010100082* 8010140032*	50-483 50-482 50-483 50-483 50-483	8 0 8	Virginia Electric & Power Co	8010280418 8010310471 8010310478* 8010010249* 8010010263*	50-271 50-271 50-271 50-338 50-338	P 8 9
	8010140541 8010140541 8010150378 8010160025 8010170061*	50-493 50-483 50-483 50-483	9 8		8010010576 8010010576 8010010580* 8010010586* 8010010678	50-280 50-280 50-280 50-280 50-280	8 8 8 8
	8010170180# 8010200668 8010200665 8010200671	50-483 50-483 50-483 50-483 50-483	9 0		8010010678 8010010678 8010010678 8010010678 8010010688*	50-338 50-280 50-338 50-280 50-280	P P
Union of Concerned Beientists	8010230704# 8010290242 8010290251# 8010030111 8010070011	50-483 50-483 50-483 50-287 50-289	88 00		8010010688* 8010010688* 8010060221 8010060231* 8010070168	50~280 50~280 50~339 50~339 50~280	P B B
Voited Nuclear Corp	8010070015 8010100353 8010140012 8010160013 8010010336*	50-259 50-458 50-289 50-289 70-820	A Q T		8010070148 8010070178 8010070178 8010070180 8010070180	50-280 50-280 50-280 50-280 50-280	Q P P
	8010140208# 8010140213# 8010140224# 8010140233# 8010150443	70-920 70-920 70-920 70-920 40-9778			8010070301 8010070304+ 8010070312 8010070312 8010070378	50-339 50-339 50-280 50-280 50-280	8 6 6 7
United Nuclear Corp , UNC Recovery Sastins Div.	8010150453# 8010150548	40-9778 70-820			8010070378 8010070378 8010070497	50~280 50~280 50~339	P B
United Nuclear Corp (Naval Products Div.	8010090476 8010090482 8010090487	70-371 70-371 70-371			8010070503 8010070512*	50~339 50~339	8
Utah, Univ. of Vaicor Engineering Corp	8010200247 8010200522 8007300449 8010010265* 8010240555	70-371 70-371 50-72 50-72 PT21	R R		8010070513# 8010070515 8010070522 8010070525# 8010070536#	50-339 50-339 50-339 50-339 50-339	8 8 8
Valore, C. Vactor Research, Inc., Vestor Public Interest Research Group Versent Yankee Nuclear Power Colp.	8010240557 8010200015 8010090008 8010310335 8010010477	PT21 PR NUREO PRQJ 50-271	a		8010070580 9010070584 8010070590* 8010070596* 8010070602	50-336 50-337 50-338 50-339 50-339	8 8
	8010010760 8010010817 8010030413 8010030313 8010030322	50-271 50-271 50-271 50-271 50-271	0 P 0		8010070607* 8010080395 8010080397* 8010080436 8010080438	50-339 50-280 50-280 50-280 50-280	8 9 P
	8010040251 8010040257* 8010040242 8010040243 8010040248*	50-271 50-271 50-271 50-271 50-271	8 8 8 8		8010GBC441* 8010140397 8010140409* 8010140415 8010140423*	50-280 50-337 50-339 50-338 50-338	8 8 8
	8010040276 8010100218 8010150267 8010150271* 8010150300	50-271 50-271 50-271 50-271 50-271	P P P		8010140427 8010140436# 8010150249 8010150304 8010150456	50-338 50-338 50-280 50-337 50-337	8 9
	8010150305* 8010150437 - 8010150448* 80101504461 8010150448*	50-271 50-271 50-271 50-271 50-271	** *** *** *** *** *** *** *** *** ***		8010150466* 8010150481 8010150486* 8010160099 8010160099	50-339 50-280 50-280 50-280 50-280	8 8 0
	8010160581 8010160586* 8010200379 8010200404*	50-271 50-271 50-271 50-271	0 8 8		8010160099 8010160099 8010160456 8010160458*	50-280 50-280 50-338 50-338 50-338	Q Q R R
	8010200449 8010200466 8010200469* 8010210316 8010210336	50-271 50-271 50-271 50-271 50-271	P 8 8 P		8010140540 8010140540 8010140544* 8010140584* 8010140580	50-338 50-338 50-338 50-338 50-339	R R R
	8010230407 8010230410* 8010230454 8010240056 8010240262*	50-271 50-271 50-271 50-271 50-271	8 8 9 0		8010170214 8010200387 8010200389 8010200392* 8010200394*	50-280 50-280 50-280 50-280 50-280	Q R R R
	8010240449 8010270488 8010280221 8010280337 8010280345	50-271 50-271 50-271 50-271 50-271	P P Q V		8010200444 8010200453 8010200453 8010200491 8010200491	50-337 50-260 50-260 50-260 50-280	4 9 8 8

AUTHOR AFF1LIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8010200499* 8010200506* 8010200513* 8010200524* 8010210350	50-280 50-280 50-280 50-280 50-281	9 8 8 9 9		8010280618 8010280625 8010280634 8010280634 8010300684	50-460 50-508 50-508 50-508 50-460	0 0 0
	8010210549 8010210548* 6010210686 8010210694* 8010220*66	50-338 50-338 50-338 50-338 50-339	P	Hashington Univ Hashington Water Power Co	8010310012# 8010310050# 8010310080 8010220490 8010020361#	50~50B 50~397 50~50B 50~27 50~522	0 0 0 F A
	8010220470 + 8010220477 8010220478 + 8010220479 8010220482 +	50-339 50-338 50-339 50-339 50-339	\$ \$ \$ \$	Washington, State of Washington, Univ of	8010200660* 8010270350 8010080667* 8010160547 8010300158*	CONTRACT WASTE MO CONTRACT 50-139 CONTRACT	OT T J
	8010220459 8010220445* 8010230414 8010230420* 8010240261	50-338 50-338 50-338 50-338 50-339	8 8 8 9	Western Nuclear, Inc (subs of Phelps Dodge Corp)	8009090219 8010020132 8010140171 8010140191*	40-1162 40-1162 40-1162 40-1162	
	8010240443 8010240446 8010240446 8010240446 8010240451	50-338 50-280 50-280 50-280 50-280	P P P P		8010140627 8010150458 8010230248 8010240004 8010270302 8010300068	40-1162 40-1162 40-1162 40-1162 40-1162 40-1162	
	8010240451 8010240451 8010240452 8010240525 8010270372	50-280 50-280 50-338 50-338 50-338	P G P F	Western Nuclear, Inc Western Piping & Engineering Co , Inc Westinghouse Electric Corp	8010300070* 8010270352 8010080147* 8008210613 8009030499	40-1162 40-1162 GA979 71-6400 TOPREP	
	8010270372 8010280409 8010280409 8010280415# 8010280415#	50-338 50-338 50-338 50-338 50-338	F P P		8010010543* 8010010552 8010010558* 8010010574 8010010577*	50-316 TOPREP TOPREP TOPREP TOPREP	þ
	8010280504 8010280512* 8010280547 8010280556* 8010280558	50-281 50-281 50-339 50-339 50-280			8010020320 8010020626 8010030011* 8010030479 8010070270*	TOPREP 50-275 50-269 50-201 50-369	8 F O A
	8010280558 8010280565* 8010280565* 8010270166* 8010270166*	50-280 50-280 50-280 50-280	8 8 8 8 8 6		8010070589 8010080557* 8010090046* 8010140072* 8010140316*	TOPREP 50-344 FOIA 70-1143 50-275	p A
	8010310336 8010310411 8010310411 8010310417* 8010310447*	50-280 50-280 50-280 50-280 50-280	£ ₽ ₽ ₽		8010150147 8010150540* 8010150553 8010160424 8010160427*	RE8 50-366 RE8 70-1151 70-1151	P
Virginia Tech Virginia, State of Virginia, Univ of Vollen, R J	8010310468 8010010281* 8010200250* 8010270357* 8010010113*	50-338 CONTRACT CONTRACT 50-320 CONTRACT	P		8010160526* 8010160709 8010200322 8010210012 8010210142	TOPREP PR PR PR REGOD	
VOLUME N	8010160787 8010200587 8010210776 8010300061 8010300067*	50-367 50-367 50-367 50-367	0		8010210195* 8010210572 8010210660 8010230357 8010230362*	FOIA TOPREP PR TOPREP TOPREP	
W A Wahler & Associates, Inc Washington Public Power Supply System	B010300088# B009100713# B0100B0106 B0100B0425	50-347 50-347 WASTE MG PR 50-397	A		8010230436 8010240190 8010240194* 8010270261 8010270267*	TOPRCP PR PR XPORTLIC XPORTLIC	
	8010080576 8010080637 8010080645 8010070083	50-460 50-397 50-397 50-397 50-460	Q Q Q		8010290171 8010290353 8010310319* 8010310610 8010310614	NUREO TOPREP 70-1151 XPORTL 10 XPORTL 10	
	8010100146 8010150380 8010170120	50-397 REQQD 50-508 50-397	A K	Westinghouse Electric Corp , PWR Systems Div	8010090164	70-1151	
	8010170122* 8010210379 8010210383* 8010240547 8010270035	50-397 50-397 50-397 PR 50-508	K C C	Westinghouse Electric International Co. Hastinghouse Operating Plants Owners Group	8010200197 8010200287 8010290139 8010140321	70-1151 70-1151 XPDRTLIC TOPREP	
	8010270374 8010270374 8010270374 8010280486 8010280510	50-508 50-508 50-506 NUREO 50-397 50-397	ж о о	Wharton & Pogalies Widoff, Reager, Selkowitz & Adler	8010160519 8010010602* 8010030480* 8010140560 8010140565*	TOPREP 50-361 50-289 50-289 50-289	0000
	8010280610	50-397	Q .		8010140570* 8010140583*	50-289 50-289	0

author Affiliation	ACCESSION NUMBER	SUBJECT CATEGORY	•	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
the marks & Associates	8010140612 8008150368*	50-289 50-206		Wisconsin, State of	8010280554* 8010300216 8010080193*		0
winthrop. Biimson, Putnam & Roberts Wisconsin Electric Power Co	8010270048 8005150348 8005150353*	50-266	F	Holfbein,S L Women's Intermetional League for Peace &	6010080465 8010240567* 8010090160	50-266 CONTRACT NUREG	G
	8007300440 8007300444* 8007260644 8007260647*	50-266 50-266 50-266	F F F	Freedom Woodward-Clyde Consultants, Inc	8010200299* 8010240274	CONTRACT 50-133	P
	8010020477 - 8010020482* 8010030921 8010040312	50-266 50-266 50-266 50-266	8 0	Hyle taboratories Hyeming Mineral Corp	8010240279* 8010240283* 8010280648* 8009090152 8009090407*	50-133	P P F
	8010040312 80100403154 8010040316*	50-266 50-266))) P		8010020097 8010020415 8010020566	40-8585 40-9502 40-8502 40-8502	
	8010040354 8010040355 8010040355 8010070541	50-266 50-266 50-266 50-301	P P S		8010030203 8010080580 8010080588*	40-8502	
	8010070567* 8010080172 8010150379 8010150384*	50-301 50-266 50-266 50-266	8 0 8	. Wyeming Outdoor Council	9010230238 8010270562 8010310253 8010220277	40-8502 40-8502 Regod 40-8745	
	8010150394 8010150397* 8010200462	50-266 50-266	R R Q	Hyoming, State of	8010240044 8010240180 8010300070* 8010020087	40-1162 40-8743 40-1162 40-8745	
	8010210194 8010210500 8010210544	REGOD 50-266 50-266	F P	Mypaing, State of	6010220385 8010240182 8010240523 8010270558	40-8502 40-8502 40-8714 40-2259	
	8010210625 8010220013 8010240183 8010240517	50-266 50-266 50-266	P F P	XYZYK Information Corp Yentre Atomic Electric Co	8010010251* 8010010198	CONTRACT	0
Wisconsin Public Service Corp	8010280401 8010030391 8010030538	50-266 50-305 50-305	R F Q		8010010384* 8010010634 8010010716 8010010727	50-29 50-29 50-29	a a
	8010060121* 8010070410 8010070572	50-305 50-305 50-305	0 P J		8010030404 8010040309 8010070298	NUREO 50-29 Nureo 50-29	9
	8010080655 8010070494 8010090512 8010140328	50-305 50-305 50-305 50-305	0 0 8		8010080354 8010080492 8010080496*	50-29 50-29	P P
	8010140459 8010140464# 8010200296	50-305 50-305 50-305	R R Q		8010090397 8010150322 8010150325* 8010160460	NUREO 50-27 50-27 50-27	R R B
	8010200330 8010200480 8010200489#	50-305 50-305 50-305	F P P		8010160461* 8010160571 8010160574* 8010160695	50-29 50-29 50-29	8 P O
	9010210450 8010210502 8010210721 8010240272*	50-305 PR 50-305 50-305	P 0 8		8010200371 8010210223 8010240504	50-27 REGOD 50-29	a P
	8010280446 8010280543* 8010280548*	50-305	8		\$6005010B \$61000010B \$45015010B	50-29 50-29 50-29	P

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	DTHER REPORT NUMBER	REPORT NUMBER	ACCESS 10N NUMBER	EUBJECT CATEGORY	OTHER REPORT NUMBER
80-1105 8010010802 8010010806 8010080194	8010200447* 8010010802 8010010806	RES RES	UBOSHRI78-138 UBNRC-P 394 LO-MR-008	GADR-55 R2 J234 KY/L-1050	8010030200+ 8009090223+ 8010100023+ 8010290292+	71-6346 40-1162 70-143 50-155 P	17297 17091
8010080234	8010080194 8010080234	RES RES	LTR 112-149 EGG-SEMI-5227	MPR-664 R1 NAC-E-803	8010270272*	71-6698	
8610150071 8010150123 8010150127	6010150071 6010150123	RES RES	EGO-2D/3D-5236	NEDE-24011-L-A ADD 8 NEDD-24010-2-01 NEDD-24081 ADD 6	8010020499 7902090367* 8010020493*		78NED362 77NED355
9010150130 8010150136	8010150127 8010150130 8010150136	RES RES RES	EGG-2D/30-5235 BNL-NUREG-28270	NEDD-24082 ADD 2 NEDD-24794	8010020474* 8010100316*		77NED336 80NED038
8010150139 8010150140 8010150142	8010150139 8010150140 8010150142	RES RES	£90-580C-5223 £60-20/39-5237	NEDO-24822 NEDO-24822 ERR 1 NUREG-0020 V4 ND9	8010020337* 8010210334* 8010230001	TOPREP TOPREP NUREQ	BONEDD49
8010150147 8010150223	8010150142 8010150147 8010150223	RES RES	SP-60-672	NUREG-0090 V3 NOI NUREG-0103 R4	8009170056 8010240048	NUREO NUREO	
8010150241 8010150528 8010180553	8010150241 8010150528 8010150553	res Res Res	ORNL/MCD/NEE9-8 GRNL/ED/EAB-80/ 6P-80-471	NUREC-0117 NUREC-0117 DRFT NUREC-0386-01 82	8010080396 80102202824 8010080575	50-364 E 50-364 A NUREO	
8010150563 8010150579	8010150563 8010150579	reb Reb	CRNL/ED/ETE-135	NUREG-0430 V1 NOS NUREG-0452 R3	8010170070 8010070610	NUREO NUREO	
8010150587 8010170101 -8010170118 8010220599 8010220451	8010150587 8010170101 8010170118 8010220599 8010220651	RES RES RES RES	ORNL/ED/ET9~134 ORNL/HABRD-92	NUREG-0518 NUREG-0525 R2 NUREG-0558 R1 NUREG-0475 B11 NUREG-0484	8010290310 8010170020 8010080393 8010230005 8010080367	PR NUREO 50-327 P 50-275 E NUREO	
8010280397 8010300137 8010300142 8010300161 8010300178	8010280597 8010300137 8010300142 8010300161	REB REB REB REB	ORNL/HAGRD-94 E0G-29/3D-5234 E0G-CDAP-5120 E0G-TEBP-5251	NUREG-0685 NUREG-0686 NUREG-0706 V1 NUREG-0706 V2 NUREG-0706 V3	8009300303 8010280688* 8010170154 8010170155 8010170161	NUREO 50-10 P PROJ PROJ PROJ	
8010300186 8010300209 8010300209 8010300218	8010300178 8010300186 8010300174 8010300202 8010300207 8010300218	RES 50-289 P RES	EGG-FA-5249 EGG-LOFT-5240 EGG-EA-5259 EGG-CAAP-5255 EGG-EH-5257	NUREO-0721 NUREO-0722 NUREO-0727 ADD NUREO-0728 NUREO-0729	8010230006 8010080276* 8010160785 8010270564* 8010270566*	NUREO 70-1297 50-348 D COMMISSION COMMISSION	
8010300225 8010300232 8010300301 8010300304 8010300676	8010300225 8010300232 8010300301 8010300304 8010300676	SO-344 P RES RES RES RES	EGG-EA-5252 LG-MR-007 EGG-TFBP-5213 GRNL/ED/EIS-137 WK-B-3850(R673)	NUREG-0730 NUREG-0731 DRFT NUREG-0732 NUREG/CP-0014 V1 NUREG/CP-0014 V2	80102705704 8010170001 8010240030 8010090022 8010090026*	COMMISSION NUREO 50-320 P NUREO NUREO	
8010310553 8010310540 8010310546 8010310574 8010800210	8010310553 8010310560 8010310566 8010310574 8010080210	RES RES AES AES RES	ORNL/FTR-992	NUREG/CP-0014 V3 NUREG/CR-0055 V2 NUREG/CR-0055 V3 NUREG/CR-0055 V3 NUREG/CR-0941	8010070027* 8010080282 8010080287* 8010080270# 8010230038	NUREO NUREO NUREO NUREO NUREO	HEDL-TME 79~50
BARCE-COM4-1-NP-2A BML-NUREG-27544 BML-NUREG-28146 CE-1-A R12 CEN-134-NP	8010280208* 8010220627 8010300336 8010160416* 8010310395*	TOPREP RES RES TOPREP NUREO	F0-50-60-13a	NUREO/CR-0785 V3 NUREO/CR-0785 V5 NUREO/CR-1071 NUREO/CR-1166	8010230046 8010230048 8010230012 8010080372 8010080203	NUREO NUREO NUREO NUREO NUREO	BRC - 04-76-200 RFP-3008 SAND79~8261
CONS4H CUC-106A DHS-RSS-001-NP-A EL 486 GADR-55 ADD 1 R1	80101505084 8009100713* 8009220143* 8010150540* 8010030197*	50-247 R WASTE KOT TOPREP 50-346 P	17284 172870	NUREO/CR-1192 NUREO/CR-1278 NUREO/CR-1308 V2 NUREO/CR-1334 NUREO/CR-1394	8010170076 8010300343 801009008 8010170023 8010230019	NUREO NUREO NUREO NUREO NUREO	UCRL-52734 SAND79-2242 MR-7068 ERL ARL-84

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER BNL-NUREG-51180 SANDBO-0781 BNL-NUREG-51186 LA-9348 UCRL-52745	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREQ/CR-1405	8010230003	NUREG	PMI - MIDEO-51100	NUREO/CR-1671	8010230014	NUREO	
NUREQ/CR-1433	6010290176	NUREO	DANDON-ADDI	NUREG/CR-1676 V1	8010230039	NUREO	NRC-02-79-043-2
NUREO/CR-1438	6010080199	NUREO	DAN MIDEO BICO	NUREG/CR-1483	8010300119*		HLA-9906-001-14
NUREO/CR-1445	B0100B0671	NUREO	UNL-NUREG-31186	NUREG/CR-1691	8010230007	NUREO	ANL-80-86
NUREO/CR-1457		NUKEU	LA-6348	PLO-0140 R3	8010230007	50-275 A	HMC-00-00
NOREG/CR-143/	8010300537	NUREO	OCKE-32/45	FEG-0140 K3	0010140333*	30-8/5 M	
NUREG/CR-1474	8010230013	NUREO	KRC-04-76-236	PNL-3315	8010150628*	70-1257	UC-20E
NUREO/CR-1475	8010230036	NUREC	NRC-04-76-200	RH-80-7-802	8010220455*	50-327 R	17413
NUREO/CR-1505	8010080184	NUREO	BNL-NUREQ-51217	RR-92-80	8010220432*	50-320 R	
NUREG/CR-1506	8010330058	NUREG	BNL-NUREO-51218	BECY-78-163	8010140091*	FOIA	
NUREG/CR-1515	8010230026	NUREO	BNL-NUREO-51221	SECY-79-383	8010030170	50-220 P	
	05.0200020	Honce	Die Holle Gills		40.4400	10 220 ,	
NUREG/CR-1531	8010270171	NUREO	NCAP-9692	SECY-80-079F	8010140029	50-556 C	
NUREO/CR-1537	8010010412	NUREO	EGQ-2046	SECY-80-0790	8010060114	SECY	
NUREO/CR-1540	8010230023	NUREO	BNL-NUREO-51231	SECY-80-236	8009100759	SECY	
NUREO/CR-1548	8010090010	NUREO	ORNL/NUREG/TM-3	BECY-80-299A	8010010030	SECY	
NUREO/CR-1552	8010240340	NUREO	UL-USNC-75 Q	EECY-80-334	8010210187*	FOIA	
NUREO/CR-1567	8010310588	NUREO	LA-8427-M9	SECY-80-382	8009110006	SECY	
NUREQ/CR-1575	8010080378	NUREO	LA-8429-M9	SECY-80-385	8009100243	SECY	
NUREO/CR-1976	8010230475	NUREO	4298	SECY-80-392	8009100225	SECY	
NUREG/CR-1581 V2	8010170078	HUREO		SECY-80-401A	8010090541	BECY	
NUREO/CR-1581 V3	8010170003	NUREO		SECY-80-415	8009290471	SECY	
			LA-8432-PR GAND80-0505 UCID-18123-80-1				
NUREO/CR-1584	8010010353	NUREO	LA-8432-PR	SECY-80-439	8010230082	COMMISSION	
NUREO/CR-1570	8010140609	NUREO	6AND80~0505	SECY-80-451	8010280492	SECY	
NUREQ/CR-1610 VI NO1	8010080475	NUREG	UCID-18123-80-1	8ECY-A-80~126	8010240331	50-320 G	
NURE@/CR-1620	8010240043	NUREO		SECY-A-89-142	8010230581	50-409 Q	
NUREG/CR-1624	8010300499	NUREG	UCID-18674	SL-TR-1A DRFT 7 R6	8010030427#	TOPREP	
111770 (00 4/00				In aca			
NUREO/CR-1629	6010230017	50-250 P		UL 360	8007050296*	50-382 5	
NUREO/CR-1632	B010230042	NUREC		VER-0209	8010290290*	50~155 P	
NUREO/CR-1635	B010140544	NUREO		WCAP-8587 81 R2	B010010577*	TOPREP	
NUREG/CR-1637	B010170277	NUREO		WCAP-9401	8010010558*	TOPREP	
NUREO/CR-1638	8010080343	NUREG	NRC-04-74-200	WCAP-9469	80100805574	50-344 P	
NUREO/CR-1639	8010150174	NUREO	E00-2053 NRC-04-76-200 ORNL/NURE0/TM-4 NRC-04-76-192	WCAP-9721	8010160526*	TOPREP	
NUREG/CR-1640	B010230009	NUREO	E00-2052	HCAP-9740	80102303624	TOPREP	
NUREG/CR-1643	B010230034	NUREG	190-04-74-000	HR (70)-50-10-80 1	80100805064	50-518 R	
NUREG/CR-1647	B010170066	NUREG	OBJE /HUSEA/TW-A	XN-NF-507 R1	80100603504	50-285 P	
NUREO/CR-1649		NUKEG	URNL/RORES/IN-4	XN-NF-524(NP)	8010090250*	TOPREP	
NVICEU/UN-104G	8010080389	NUREO	447-04-/0-172	VIA-IAL-SEA/IAL)	a010070230#	IOPREF	
NUREO/CR-1649	9010080386	NUREQ	NRC-04-76-192	XN-NF-79-95 (NP) R1	8010150452*	50-10 P	
NUREO/CR-1656	8010150171	NUREG		XN-NF-80-19 (NP) V2	8010090241*	TOPREP	
NUREG/CR-1661	8010150153	NUREO	UCRL-15267	XN-NF-80-19(NP) V3	8010090246*	TOPREP	
NUREG/CR-1665	8010230015	NUREG	UCRL-53005	Y1003J01A10	8010230376*		
NUREQ/CR-1669	BO10080381	NUREO					

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION HUMBER

MCCESSIO	N NONDEK			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	CATEGOR	
7809180014	7809180012	78/09/08	REGOD	
7809180016	7807180012	78/09/08	REGOD	
7812080207	7812080199	79/11/29	50-10	Ρ
7902090367	7902090343	79/02/05	50-322	Α
8003240287	8003240244	79/12/31	50~160	Q
8004080147	B0040B0145	80/02/26	50~250	Q
8005120230	8005120223	80/03/20	50-259	Q
8005140440	8005140419	B0/05/12	50-445	9
8005140447	8005140419	80/05/12	50-445	Q
8005150353	8005150348	80/05/07	50-246	F
8004040082	8004040077	80/04/14	50-10	Ġ.
8007300444	8007300440	80/07/25	50-246	F
9008060179	8008060175	80/06/23	50-259	Ġ.
B9E0618008	0000150360	10/80/08	50-206	F
8008200164	8008500170	80/08/18	50-358	F
8008210614	8008210613	80/07/28	71-6400	
8008210615	8008210413	80/07/28	71-6400	
B008250080	8008250073	80/07/16	50-305	8
8009050293	8009050288	B0/08/29	50-382	5
8007050296	8007050288	80/08/29	50-382	8
8009090156	8007070152	80/08/21	40-B502	
8007070159	8009090152	80/08/21	40-9502	
8007090169	8009090152	80/08/21	40-8502	
8009090178	8009090152	80/08/21	40-8502	
8007090185	8007070152	80/08/21	40-8502	
8009090193	8009090152	80/08/21	40-8502	
8009090201	8009090192	80/08/21	40-9502	
8007090216	8007090152	80/08/21	40-8502	
8009090223	8009090219	80/08/04	40-1162	
8007070225	8009090152	80/08/21	40-8502	
8007070291	8007070152	80/08/21	40-8502	
8009090255	8009090152	80/08/21	40-8502	
8004040593	8007090152	80/08/21	40-8502	
8009090270	8009090152	80/08/21	40-8502	
8007070275	8007070152	80\08\51	40-8502	
8009090284	8009090152	80/08/21	40-8502	
8009090292	8009090152	80/08/21	40~8502	
81509090318	8009090152	80/08/21	40-8502	
8009090324	8007070152	80/08/21	40~8502	
8009090329	8009090152	80/08/21	40-8502	
8009090334	8009090152	80/08/21	40-8502	
8009090340	8009090152	80/08/21	40-8502	
8009090345	8009090132	80/08/21	40-8502	
8009090360	8009090182	80/08/21	40-8502	
9004040399	8009090182	80/08/21	40-B502	
8007070372	8007070132	80/08/21	40-8502	
8009090379	8009090152	80/08/21	40-8502	
8007070370	8007070152	80/08/21	40-8502	
8009090393	8007070386	80/08/29	40-8697	
96E060600B	8009090152	80/08/21	40-8502	

ENCLOSURE	PRINCIPAL DOCUMENT	DATE 158UED	GUBJECT CATEGORY	,
8009090407 8009100246	8009090152 8009100240	80/08/21	40-8502 50-267	F
6009100713	8009100703	80/08/29	WASTE MOT	ſ
8009100820	8009100819	80/08/26	40-B714	
8004100853	8009100819	80\08\54	40-8714	
8009110364 8009110366	8009110362 8009110362	80/07/29 80/07/29	REGOD REGOD	
8007110369	8009110362	80/07/29	REQUI	
8009150165	8009150163	80/07/28	40~3392	
8007150341	8009150235	80/09/04	50-272	۴
8009160562	6009160559	80/09/10	50-244	P
B009160967	8009160559	80/09/10	50-244	P
8009160568	8009160559	80/09/10	50-244	P
0009160570	8009160559	90/09/10	50-244	P
8009140574	8009160559	80/09/10	50-244	P
8009160576	8009140959	80/09/10	50-244	P
8009160577	8009160559	80/09/10	50-244	P
8007160578	8007160557	80/09/10	30-244	Þ
8007160580	8009160559	80/09/10	50-244	P
8009140582	8009160559	80/09/10	50-244	P
H009170193	8009170190	80/08/28	71-9034	
8009170203	8007170199	80/08/28	71-9037	
8007170448	8007170438	80/09/12	50-276	e
8009190539	8009190299	80/09/04	FOIA	
8009190346	8009190299	80/09/04	FOIA	
8009220143	5009220139	80/09/18	TOPREP	
8009230181	8009230171	80/08/20	50-445	М
8009240161	8009240156	80/07/03	40-4492	
8009240146	8009240154	89/09/03	40-4492	
8009240169	8007240154	80/09/03	40-4492	
8009240170	8009240156	80/09/03	40-4472	
8009240522	8009240519	80/09/22	90-344	Α
8009250329	8009250328	80/08/07	30-327	F
8009250330	8009250328	80/08/07	50-327	F
8009250454	8009250450	80/09/04	71~6400	
8009260126	8009240121	BO/08/01	TOPREP	
8009260647	8007260644	80/09/23	50-266	F
6010010006	8010010002	80/09/16	50-298	Q
8010010012	\$010010004	81/80/08	50-29B	q
8010010014	8010010014	80/09/12	50-369	Q
8010010017	B010010009	80/09/18	50-278	G
B010010018	B010010014	80/09/12	50~369	ü
8010010023	8010010020	80/09/10	50~327	G
8010019024	B010010051	80/09/12	50-313	G
8010010026	8010010050	80/09/10	90-327	Q
8010010028	8010010020	80/09/10	50-327	G
B010010035	8010010031	80/07/05	50-416	Q
6010010037	8010010034	60/08/15	71-7136	
8010010037	8010010034	BO/OB/15	71-9136	
8010010042	4E00100108	80/08/15	71-9136	

ACCEBBION					ACCESSION NUMBER	ı	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC		FRINC ENCLOSURE DOGU		SUBJECT CATEODRY
8010010044 8010010044 8010010047 8010010052 8010010057	8010010031 8010010031 8010010040 8010010040 8010010031	80/09/05 80/09/05 80/09/11 80/09/11 80/09/05	50-416 50-416 50-302 50-302 50-416	9	8010010335 801001 8010010335 801001 8010010339 801001 8010010340 80100 8010010341 80100	0321 80/09/12 0330 80/08/27 0321 80/09/12 0330 80/08/27	50-262 G 70-820 50-262 G 70-820 70-371
8010010084 8010010089 8010010090 8010010092 8010010095	8010010078 8010010078 8010010080 8010010064 8010010078	80/09/04 80/09/04 80/09/16 80/08/19 80/09/04	50-245 50-245 50-269 50-285 50-245	0 0 0	8010010342 80100 8010010344 80100 8010010347 80100 8010010352 80100 8010010354 80100	0321 80/09/12 10330 80/08/27 10343 80/08/13	70-820 50-262 Q 70-820 50-286 Q 50-315 Q
8010010100 8010010101 8010010102 8010010104 8010010111	8010010078 8010010061 8010010080 8010010058 8010010058	80/09/04 80/08/20 80/09/14 80/09/17 80/09/17	50-245 50-213 50-269 50-302 50-302	0 P 0 P	8010010362 801001 8010010372 801001 8010010372 801001 8010010373 801001 8010010379 801001	0364 80/09/26 0365 80/08/18 0366 80/09/17	71-4581 50-344 Q 50-423 Q CONTRACT 50-483 Q
8010010112 8010010113 8010010114 8010010116 8010010120	8010010080 8010010109 8010010058 8010010107 8010010107	80/09/14 80/09/18 80/09/17 80/09/03 80/09/03	50-269 CONTRACT 50-302 50-277 50-277	G G	80100103B2 801001 80100103B3 801001 80100103B4 801001 90100103P2 801001 80100103P2 801001	0376 90/08/14 0381 80/08/27 0385 80/08/15	50-293 Q 50-483 Q 50-27 Q 70-820 50-27 Q
8010010124 8010010127 8010010131 8010010134 8010010173	8010010107 8010010121 8010010080 8010010107 8010010165	80/09/03 80/09/16 80/09/16 80/09/03 80/80/08	50-277 PRM 50-269 50-277 WASTE MG	Q Q Q	8010010375	0381 80/08/27 0376 80/08/04 0397 80/08/07	70-698 50-29 q 50-333 q 50-219 q 50-219 q
8010010178 8010010180 8010010182 8010010190 8010010193	8010010171 8010010175 8010010177 8010010177 8010010184	80/08/11 80/08/15 80/09/03 80/09/05 80/09/10	50-289 50-285 50-317 50-317 50-304	9	8010010417 801001 8010010423 801001 8010010432 801001 8010010442 801001 8010010443 801001	0419 80/09/03 0427 80/08/28 0434 80/09/17	70-135 50-423 8 50-440 Q CONTRACT 50-315 P
8010010194 8010010197 8010010201 8010010204 8010010207	8010010177 8010010186 8010010177 8010010186 8010010177	80/09/05 80/09/11 80/09/05 80/09/11 80/09/05	50-317 50-413 50-317 50-413 50-317	0 0 0	8010010447 801001 8010010430 801001 8010010439 801001 8010010488 801001 8010010489 801001	0437 80/09/11 0454 80/09/24 0485 80/09/18	50-315 P 50-315 P 50-320 B 40-8027 40-8027
8010010210 8010010213 8010010214 8010010216 8010010218	8010010202 8010010177 8010010184 8010010202 8010010186	80/09/10 80/09/05 80/09/11 80/09/10 80/09/11	50-334 50-317 50-413 50-334 50-413	0 0 0	8010010491 801001 8010010495 801001 8010010500 801001 8010010508 801001 8010010508 901001	0485 80/09/18 0494 80/09/24 0497 80/09/16	50-287 0 40-8027 50-313 8 50-483 0 50-155 P
8010010220 8010010224 8010010228 8010010232 8010010249	8010010202 8010010202 8010010184 8010010229 8010010238	80/09/10 80/09/10 80/09/11 80/09/16 80/09/15	50-334 50-334 50-413 CONTRACT 50-338	0 0 0	8010010511	0512 80/09/29 0514 80/09/26 0532 80/09/17	50-293 8 50-346 8 50-313 R 50-445 C 50-316 P
8010010251 8010010253 8010010254 8010010257 8010010241	8010010245 8010010247 8010010238 8010010245 8010010255	80/08/27 80/09/12 80/09/15 80/08/27 80/09/05	50-309 CDNTRACT 50-338 50-309 CDNTRACT	Q Q Q	8010010343 801001 8010010344 801001 8010010357 801001 8010010358 801001 8010010566 801001	0342 80/07/22 0354 80/09/22 0352 80/09/17	50-316 P 50-250 P 50-445 A TOPREP 50-416 K
8010010262 8010010263 8010010264 8010010265 8010010268	8010010232 8010010238 8010010245 8009300449 8010010260	80/09/22 80/09/15 80/08/27 80/09/23 80/09/12	CONTRACT 50-336 50-309 50-72 CONTRACT	q q R	8010010375 801001 8010010377 801001 8010010580 801001 8010010586 801001 8010010589 801001	0574 80/08/14 0576 80/09/26 0576 80/09/26	50-416 K TOPREP 50-280 B 50-280 B 50-382 K
8010010271 8010010274 8010010278 8010010277 8010010281	8010010238 8010010238 8010010272 8010010249 8010010276	80/09/15 80/09/15 80/09/17 80/09/17 80/09/12	50-338 50-338 CONTRACT CONTRACT CONTRACT	g G	8010010574 901001 8010010575 801001 8010010577 901001 8010010401 801001 8010010402 801001	0582 80/09/26 0591 80/09/29 0590 80/08/22	50-186 Q 50-382 K 50-346 B 50-186 Q 50-361 0
8010010282 8010010283 8010010292 8010010293 8010010295	8010010273 8010010238 8010010287 8010010286 8010010298	80/09/18 80/09/15 80/09/09 80/09/17 80/09/18	CONTRACT BEE-08 40-8385 CONTRACT CONTRACT	O	8010010409 801001 8010010412 801001 8010010414 801001 8010010417 801001 8010010420 801001	0606 80/08/28 0603 80/08/27 0611 80/07/29	50-272
8010010297 8010010298 8010010303	8010010287 8010010291 8010010294 8010010299 8010010300	80/07/09 80/07/12 80/08/01 80/09/09 80/09/16	40-8385 CONTRACT 70-48 CONTRACT CONTRACT		8010010422 801001 8010010431 801001 8010010449 801001 8010010449 801001 8010010653 801001	0603 80/08/27 0625 80/07/28 0642 80/08/28	50-272 0 50-272 0 50-352 0 50-454 0 71-5957
8010010311 8010010312 8010010314	8010010287 8010010302 8010010287 8010010302 8010010302	80/07/07 80/07/07 80/07/09 80/07/07	40-8385 50-354 40-8385 50-384 50-354	G Q Q	8010010465 801001 8010010671 801001 8010010672 801001 8010010674 801001 8010010676 801001	0669 80/09/28 0669 80/09/28 0667 80/09/29	50-498 A 50-250 P 40-2259 50-293 B 50-348 Q
8010010322 8010010323 8010010327	8010010309 8010010309 8010010302 8010010321 8010010309	80/09/10 80/09/10 80/09/09 80/09/12 80/09/10	50~262	9	8010010488 801001 8010010473 801001 8010010714 801001 8010010722 801001 8010010749 801001	0695 80/09/12 0711 80/08/28 0711 80/08/28	50-280 P 50-254 Q 50-315 Q 50-315 Q 50-254 Q

ACCESSION					ACCESSID	NUMBER			
ENCLUSURE	PRINCIPAL DOCUMENT	DATE	BUBJECT CATEGORY	,	ENCLGSURE	PRINCIPAL DOGUMENT	DATE 188UED	SUBJECT CATEGORY	,
8010010757 8010010801 8010010805 8010010807 8010010813	8010010747 8010010745 8010010745 8010010745 8010010745	80/08/20 80/09/11 80/09/11 80/09/11 80/09/11	50-245 50-334 50-334 50-334 50-334	P 0 0 0 0	8010020462 8010020465 8010020471 9010020472 8010020482	8010020453 8010020437 8010020469 8010020466 8010020477	80/09/29 80/09/24 80/09/26 80/09/26 80/09/10	50-273 50-454 50-261 50-334	8 A P 8
8010010855 8010010857 8010010860 8010010863 8010020029	8010010853 8010010853 8010010857 8010010857 8010020026	80/09/14 80/08/22 80/08/22 80/08/14	50-407 50-407 50-266 50-266 50-237	0 0 0	8010020484 8010020490 8010020492 8010020493 8010020494	8010020478 8010020488 8010020491 8010020488 8010020488	80/09/22 80/09/20 80/09/29 80/09/30 80/09/30	50-277 50-334 50-277	9 P P P
8010020050 8010020053 8010020054 8010020055 8010020062	8010020042 8010020046 8010020042 8010020047 8010020042	80/09/30 80/09/19 80/09/30 80/09/30	50-349 70-820 50-349 50-347 50-349	000	8010020495 8010020498 8010020507 8010020509 8010020510	8010020488 8010020496 8010020439 8010020439 8010020439	80/09/30 80/09/29 80/09/24 80/09/24 80/09/24	50-273 50-454 50-454	P A A A
8010020064 8010020067 8010020069 8010020075 8010020077	8010020040 8010020058 8010020042 8010020070 8010020042	80/09/15 80/08/13 80/09/30 80/09/15 80/09/30	30-267 50-277 50-349 50-346 50-369	P 0 0 0	8010020511 8010020512 8010020513 8010020515 8010020521	8010020439 8010020439 8010020439 8010020439 8010020439	80/09/24 80/09/24 80/09/24 80/09/24 80/09/24	50-454 50-454 50-454	A A A A
8010020080 8010020085 8010020109 8010020115 8010020120	8010020074 8010020074 8010020104 8010020104 8010020104	80/09/08 80/09/08 80/09/25 80/09/25 80/09/25	71-3088 71-3088 FOIA FOIA FOIA		8010020326 8010020333 8010020337 8010020339 8010020384	8010020439 8010020439 8010020532 8010020439 8010020449	80/09/24 80/09/24 80/09/22 60/09/24 80/09/04	50-454 50-275 50-454	A B A H
8010020125 8010020128 8010020137 8010020144 8010020146	8010010104 8010010104 8010020133 8010020138 8010020135	80/09/25 80/09/25 80/09/18 80/08/22 80/09/24	FOIA FOIA 50-361 50-412 70-143	q q	8010020591 8010020593 8010020600 8010020601 8010020604	9010020585 8010020592 8010020587 8010020596 8010020589	80/07/23 80/07/03 80/07/19 80/07/13 80/07/19	CONTRACT	H H
8010020147 8010020151 8010020158 8010020183 8010020191	8010020138 8010020138 8010020153 8010020181 8010020186	60/08/22 80/09/12 80/09/12 80/08/25 80/08/26	50-412 50-412 50-354 50-445 50-445	О В О	8010020612 8010020625 8010020616 8010020644 6010020654	8010020604 8010020619 8010020629 8010020630 8010020648	80/09/11 80/09/11 80/07/29 80/09/12 80/09/30	PR	a F
8010020202 8010020206 8010020207 8010020217 8010020218	8010020193 8010020193 8010020193 191020113	80/09/10 80/09/10 80/08/21 80/09/10 80/07/30	70-364 70-364 50-364 70-364 50-412	a a	6010020477 8010020479 8010020491 8010020493 8010020497	8010020661 8010020671 8010020684 8010020683 8010020684	B0/09/08 B0/09/04 B0/09/27 B0/09/23 B0/08/27	CONTRACT 70~135	T
8010020223 8010020230 8010020231 8010020234 8010020240	8010020173 8010020222 8010020224 8010020227 8010020235	80/09/10 80/08/21 80/07/30 80/08/21 80/08/29	70-364 50-322 50-286 50-364 50-155	Q Q Q	8010020702 8010020703 8010020709 9010020710 8010020714	8010020484 8010020498 8010020483 8010020704 8010020708	80/08/27 80/09/15 80/09/23 80/09/25 80/08/29	FOIA	T a
8010020246 8010020250 8010020253 8010020253 8010020257	8010020235 8010020244 8010020237 8010020248 8010020251	80/08/29 80/08/20 80/08/21 80/09/18 80/08/29	50-155 50-438 50-352 CONTRACT 50-213	0	8010020716 8010020725 8010020730 8010020737 8010020737	8010020711 8010020721 8010020656 8010020732 8010020752	80/09/18 80/08/21 80/08/29 80/08/20 80/09/10	50-409 50-335	@ @ @
8010020263 8010020265 8010020270 8010020273 8010020275	8010020251 8010020258 8010020258 8010020258	80/08/29 80/09/17 80/09/17 80/08/22 80/09/17	50-213 70-27 70-27 50-281 70-27	o a	8010020759 8010020762 8010020763 8010020765 8010020767	8010020752 8010020752 8010020760 8010020760 8010020760	80/09/10 80/09/10 80/08/27 80/08/27 80/08/27	50-286 50-245 50-245	G G G G
8010020277 8010020281 8010020290 8010020291 8010020297	8010020269 8010020269 8010020282 8010020286 8010020293	80/08/29 80/08/29 80/07/28 80/09/24 80/09/08	50-10 50-10 50-917 50-295 CONTRACT	0000	8010020771 8010020776 8010020777 8010020779 8010020780	8010020740 8010020772 8010020774 8010020774 8010020772	80/08/27 80/08/18 80/08/20 80/08/20 80/08/18	50-438 50-438 50-438	G G G G
8010020298 8010020339 8010020343 8010020345 8010020347	8010020286 8010020335 8010020337 8010020341 8010020341	80/09/24 80/09/12 80/09/26 80/09/30 80/09/30	50-295 TOPREP 50-522 50-344 50-344	P A P	8010020764 8010020787 8010020797 8010020797 8010030010	8010020782 8010020782 8010020790 8010020790 8010030007	80/09/15 80/09/15 80/08/22 80/08/22 80/09/19	50-369 50-286 50-286	0 0 0 F
8010020347 8010020355 8010020361 8010020374 8010020378	8010020337 8010020337 8010020337 8010020366 8010020337	80/07/26 80/07/26 80/07/26 80/07/17 80/07/26	50-522 50-522 50-522 50-492 50-522		8010030011 8010030017 8010030022 8010030024 8010030025	8010030007 8010030014 8010030019 8010030019	80/09/19 80/08/20 80/09/18 80/09/15 80/09/16	50-443 50-289 50-289	F G P P
8010020387 8010020413 8010020417 8010020424 8010020436	8010020384 8010020403 8010020406 8010020418 8010020425	80/07/16 80/07/02 80/07/22 80/07/12 80/07/22	COMMISSI 50-544 50-245 50-246 50-245	8 0 0 0 0 0	801003q032 8010030040 8010030071 8010030081	8010030028 8010030028 8010030044 8010030048 8010030074	80/09/24 80/09/19 80/09/19 80/09/17	50-331 50-333 50-335	00000
8010020440 8010020444 8010020448 8010020456	8010020430 8010020435 8010020439 8010020439 8010020454	80/09/12 80/09/29 80/09/24 80/09/24 80/09/26	50-246 50-373 50-454 50-454 50-373	O A A A K	8010030086 8010030082 8010030082 8010030094 8010030095	8010030048 8010030048 8010030048 8010030070	80/09/17 80/09/17 80/09/17 80/09/17 80/09/19	50-335 50-335 50-335	9999

ACCESSION NUMBER			ESSION NUMBER		
	DATE SUBJECT SSUED CATEGORY	ENCLOSE	PRINCIPAL URE DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8010030104 8010030098 80, 8010030107 8010030099 80, 8010030121 8010030118 80	//09/10 50-293 //09/10 50-293 //09/25 50-289 //09/25 50-334 //09/10 50-334	9 801006 0 801006 0 801006 0 801006	0226 8010060220 0228 8010060220 0230 8010060225 0231 8010060221	80/10/03 80/10/03 80/09/30 80/10/01 80/10/01	50-170 P 50-170 P 50-395 A 50-339 8 50-302 8
8010030132 8010030128 80 8010030133 8010030113 80 8010030138 8010030113 80	0/09/10 50-334 0/08/26 50-245 0/08/27 50-247 0/08/27 50-247 0/08/27 50-247	0 801006 0 801006 0 801006 0 801006 0 801006	0234 8010060219 0235 8010060229 0238 8010060220	80/10/03 80/09/29 80/09/26 80/10/03 80/10/03	50-170 P 50-311 S 50-263 F 50-170 P 50-170 P
8010030151 8010030145 80. 8010030181 8010030176 80. 8010030174 8010030186 80.	0/08/27 40-8584 0/09/16 70-1201 0/09/19 50-274 0/09/23 50-284 0/08/28 71-6346	20108 801004 901004 901004 901004	0245 8010060240 0246 8010060237 0248 8010060220	80/09/30 80/09/23 80/09/23 80/10/03 80/09/30	50-289 P 50-366 S 50-293 B 50-170 P 50-366 S
8010030208 8010030205 80. 8010030223 8010030213 80. 8010030235 8010030228 80.	708/28 71-6346 709/19 50-220 709/19 50-324 709/19 50-263 709/19 50-331	00108 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 00100000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 001000 001000 001000 001000 001000 001000 001000 0010000 001000 0010000 0010000 001000000	0257 8010060251 0259 8010060254 0261 8010060252	80/09/30 80/10/03 80/09/30 80/09/29 80/10/03	50-289 P 50-271 8 50-364 8 50-318 8 50-271 8
8010030373 8010030369 80. 8010030376 8010010582 80. 8010030380 8010010582 80.	/09/03 CONTRACT /09/26 50-260 /09/26 50-382 /09/26 50-382 /09/30 50-334	8 801006 K 901006 K 901006 K 801006 P 801006	0275 8010040270 0278 8010040270 0279 8010040271	80/10/01 80/09/26 80/09/26 80/09/24 80/10/01	50-318 8 50-245 R 50-245 R 50-272 P 50-272 B
8010030399 8010030398 80. 8010030412 8010030409 80. 8010030418 8010030419 80.	7/10/01 50-259 7/09/24 50-317 7/09/22 50-320 7/09/17 50-285 7/10/02 50-361	F 801006 8 801006 9 801006 8 801006 0 801006	0284 8010060271 0287 8010060283 0275 8010060271	80/09/29 80/09/24 80/09/29 80/09/29 80/09/17	50-244 \$ 50-272 P 50-272 B 50-272 B 50-206 \$
8010030437 8010030432 80, 8010030440 8010030434 80, 8010030451 8010030445 80,	/09/29 TOPREP //09/30 50-344 //09/10 CONTRACT //09/29 50-346 //09/26 50-272	P 801006 801006 8 801006 8 801006	0304 B010060300 0307 B010060299 0313 B010060311	80/09/26 80/09/22 80/09/29 80/10/01 80/09/30	50-325 B 50-312 B 50-276 B 50-317 B 50-276 S
8010030480 8010030477 80, 8010030488 8010030486 80, 8010030491 8010030489 80,	/10/01 50-320 /10/01 50-287 /09/24 CONTRACT /09/24 50-369 /08/26 50-416	9 801006 9 801006 801006 9 801006 9 801006	0355 8010090318 0350 8010090318 0319 8010090315	80/09/30 80/09/30 80/09/29 80/09/29 80/09/29	50-266 J 50-266 J 50-273 P 50-273 P 50-273 P
8010030500 8010030489 80, 8010030502 8010030495 80, 8010030504 8010030489 80,	/09/24 50-369 /09/24 50-369 /08/28 50-156 /09/24 50-369 /09/24 50-369	Q 801006 Q 801006 Q 801006 Q 801006	0333 8010040323 0332 8010040318 0335 8010040329	80/09/29 80/09/30 80/09/29 80/09/29 80/10/01	50-273 P 50-336 P 50-293 P 50-259 8 50-333 8
8010030527 8010030527 807 8010030532 8010030527 807 8010030545 8010030543 807	/08/28 50-156 /09/19 MISC /09/15 MISC /09/11 CONTRACT /09/17 50-285	801006 801006 801006 801006 901006	0350 8010060344 0353 8010060341 0356 8010060188	80/10/01 80/09/19 80/10/01 80/09/23 80/09/30	50-445 M 50-285 P 50-445 M 50-272 Q 50-366 B
8010040009 8010060006 807 8010060023 8010060021 807 8010060037 8010060034 807	/06/05 70- 27	0 801007 9 801007 9 801007 9 801007 N 801007	0007 8010070005 0033 8010070027 0035 8010070029	80/10/02 80/10/02 80/10/02 80/10/02 80/09/19	50-466 0 50-466 0 50-466 0 50-466 0 50-219 8
8010040047 8010040047 807 8010040073 8010040048 807 8010040081 8010040077 807		N 801007 801007 2 801007 2 801007 9 801007	0240 8010070235 0248 8010070246 0251 8010070246	80/10/03 80/09/24 80/09/23 80/09/23 80/10/02	50-375 K 50-327 P 50-461 A 50-461 A 50-375 F
8010060108 8010060103 807 8010060113 8010060111 807 8010060121 8010060118 807	/08/20 50-461 /07/03 50-285 /07/19 50-305	801007 801007 90 801007 9 801007 9 801007	0278 8010070277 0290 8010070285 0298 8010070296	80/10/03 80/10/02 80/10/01 80/07/08 80/10/01	50-369 A 50-206 P 50-302 B 50-298 B 50-339 B
8010040139 8010040135 807 8010040141 8010040137 807 8010040143 8010040137 807	/07/15 CONTRACT /07/18 50-335 /07/18 50-335	9 801007 801007 801007 9 801007 9 801007	0309 8010070307 0310 8010070308 0311 8010070307	80/09/25 80/09/29 80/09/29 80/09/29 80/09/26	50-155 P 50-286 P 50-313 P 50-286 P 50-282 F
8010060155 8010060153 807 8010060156 8010060148 807 8010060158 8010060148 807	/09/25 50-267 /09/17 50-348 /09/17 50-348	801007 801007 801007 801007 801007 801007	0338 8010070335 0343 8010070341 0355 8010070352	80/10/01 80/10/03 80/09/30 80/10/01 80/09/24	50-10 J 50-287 P 50-364 A 50-324 J 50-254 8
8010040187 8010040185 807 8010040213 8010040207 807 8010040214 8010040211 807	/09/15 XFORTLIC /09/23 50-324	801007 801007 801007 801007 801007	0394 8010070376 0398 8010070395 0407 8010070401	80/09/30 80/09/29 80/09/30 80/10/01 80/10/01	50-334 B 50-368 B 50-364 A 50-267 B 50-267 B

ACCESSION N	UMBER				ACCESSIO:			
	RINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATECOR'	Y		PRINCIPAL	DATE	SUBJECT
8010070435 86 8010070437 86 8010070449 86 8010070450 86		80/09/30 80/09/19 80/09/30 80/10/01 80/09/22	TOPREP 50-335 50-324 NUREO 50-335	s s s	B010080111 8010080113 8010080120 8010080124 8010080124	B010080104 B010080076 B010080076 B010080117 B010080076	189VED 80/09/25 80/09/25 80/09/16 80/09/25	CATEGORY 0A979 50-206 Q 50-206 Q 70-27 50-206 Q
8010070464 86 8010070474 86 8010070477 86	010070451 010070454 010070466 010070420 010070470	80/10/03 80/09/30 80/09/18 80/09/24 80/10/03	50-346 50-334 50-335 50-335 50-327	8 8 8 9 9	8010080136 8010080143 8010080149 8010080151 8010080157	8010080118 8010080132 8010080148 8010080146 8010080148	80/09/04 80/09/17 80/09/10 80/09/23 80/09/10	70-36 70-371 0A999 50-344 G GA999
8010070490 B0 8010070490 B0 8010070491 B0	010070476 010070484 010070485 010070480 010070494	80/10/01 80/07/25 80/10/03 80/07/12 80/09/17	50-219 50-146 50-259 50-298 50-368	8 8 8 9	8010080158 8010080157 8010080160 8010080161 8010080163	8010080152 8010080146 8010080148 8010080155 8010080156	80/09/11 80/09/25 80/09/10 80/09/22 80/08/12	40-1193 50-344 G GA999 50-277 P 50-334 G
8010070506 80 801007050B 80 8010070509 80	010070492 010070497 010070499 010070500 010070504	80/10/02 80/10/01 80/10/02 80/09/22 80/09/17	50-346 50-482 50-466 50-254 50-285	B A Q S S	8010080164 8010080167 8010080169 8010080170 8010080173	8010080146 8010080148 8010080155 8010080146 8010080155	80/09/25 80/09/10 80/09/22 80/09/25 80/09/22	50-344 Q QA999 50-277 P 50-344 Q 50-277 P
8010070513 86 8010070517 86 8010070520 86	010070499 010070503 010070495 010070501 010070495	80/10/01 80/10/02 80/09/20 80/09/20	50-339 50-339 50-466 50-255 50-466	8 8 9 5 0	8010080182 8010080182 8010080189 8010080190	8010080175 8010080179 8010080175 8010080183 8010080175	80/07/12 80/07/23 80/07/12 80/07/23 80/07/12	GA979 50-346 P GA979 50-206 G GA979
8010070526 86 8010070527 86 8010070531 86	010070515 010070517 010070518 010070521 010070522	80/10/01 80/07/30 80/01/03 80/09/30	50-334 50-293 50-293 50-334 50-339	8 8 8 8	8010080193 8010080194 8010080198 8010080200 8010080205	8010080185 8010080175 8010080192 8010080197 8010080197	80/09/29 80/09/12 80/09/16 80/09/18 80/09/18	CONTRACT GA999 COMMISSION 50-369 G 50-369 G
8010070543 80 8010070544 80 8010070546 80	010070529 010070534 010070535 010070537 010070540	80/10/01 80/09/29 80/09/26 80/10/03 80/10/01	50-329 50-369 50-237 50-269 50-313	A 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	8010080217 8010080218 8010080221 8010080225 8010080226	8010080209 8010080215 8010080215 8010080220	80/07/24 80/08/27 80/07/22 80/08/28 80/09/22	50-335 8 50-358 0 50-400 0 50-364 0 50-400 0
8010070553 86 8010070558 86 8010070557 86	010070528 010070548 010070547 010070550 010070554	80/10/02 80/08/28 80/10/01 80/09/30 80/10/01	50-261 50-409 50-324 50-334 50-237	8 P 8 6 P	6010080237 6010080239 6010080246 6010080250 6010080252	8010080228 8010080233 8010080241 8010080228 8010080241	80/08/27 80/09/29 80/09/19 80/08/29 80/09/19	50-294 G 50-346 P 50-317 P 50-294 G 50-317 P
8010070547 80 8010070549 80 8010070570 80	010070557 010070560 010070561 010070554 010070556	80/07/30 80/10/02 80/07/26 80/10/01 80/07/27	50-325 50-313 50-301 50-237 50-213	8 6 6 P	8010080257 8010080260 8010080272 8010080276 8010080285	8010080241 8010080241 8010080246 8010080266 8010080280	80/10/01 80/09/19 80/09/12 80/09/12	50-317 P 50-317 P 70-1257 70-1257 70-2909
8010070577 80 8010070578 80 8010070579 80	010070568 010070563 010070556 010070554 010070576	80/09/29 80/09/28 80/09/29 80/10/01 80/10/02	50-361 50-368 50-213 50-237 50-466	A B P P Q	8010080287 8010080290 8010080301 8010080303 8010080304	8010080282 8010080282 8010080275 8010080277 8010080277	80/09/30 80/09/30 80/09/26 80/09/18 60/09/18	NUREO NUREO 71-376 50-250 0 50-250 0
8010070586 80 8010070588 80 8010070590 80	010070573 010070575 010070576 010070580 010070584	80/10/01 80/09/30 80/10/02 80/10/01 80/10/01	50-313 50-325 50-466 50-338 50-339	6 8 0 8 5	8010080305 8010080308 8010080312 8010080315 8010080337	8010080302 8010080307 8010080307 8010080333	80/09/17 80/10/06 80/09/12 80/08/22 80/08/27	CONTRACY 50-275 0 XPORTLIC 50-206 P 50-293 0
8010070601 B0 8010070604 B0 8010070607 B0	010070592 010070593 010070600 010070602 010070595	80/10/01 80/09/30 80/10/02 80/10/01 80/09/30	50-327 50-324 50-241 50-339 50-255	8 6 6 8	8010060337 8010060348 8010080350 8010080359 8010080361	8010080334 8010080344 8010080345 8010080352 8010080358	60/10/03 97/90/08 44/90/08 97/90/08 44/90/08	50-267 R 50-309 0 CONTRACT 50-335 0 CONTRACT
8010070617 86 8010070621 86 8010070622 86	010070616 010070614	80/09/26 80/10/02 80/09/29 80/09/29 80/09/25	50-249 50-289 50-348 50-368 50-313	8 0 8 8 8	8010080382 8010080392 8010080399 8010080408 8010080430	8010080375 8010080385 8010080375 8010080406 8010080428	60/09/30 60/10/03 60/03/01 60/10/03	50-366 8 50-327 8 50-280 8 50-471 A 50-368 8
8010070425 86 8010070428 86 8010070432 86	010070613 010070620 010070613 010070613 010070613	80/10/02 80/08/27 80/10/02 80/10/02 80/10/02	50-289 50-313 50-289 50-289 50-289	0 8 0 0	8010080437 8010080441 8010080445 8010080447 8010080457	8010080433 8010080439 8010080443 8010080444 8010080432	80/10/02 80/10/02 80/07/30 80/10/03	50-321 B 50-280 B 50-269 B 50-245 P 50-346 S
8010070639 80 8010070639 80 8010070645 80	010070613 010070613 010070613 010070613 010070631	80/10/02 80/10/02 80/10/02 80/10/02 80/09/11	50-289 50-289 50-289 50-289 COMMISSI	0 0 0 0 0	8010080459 8010080462 8010080463 8010080467 8010080469	8010080454 8010080454 8010080461 8010080464 8010080444	80/10/04 80/10/03 10/03/08 80/09/30	50-361 A 50-361 A 50-259 E 50-267 P 50-245 P
8010080057 80 8010080068 80 8010080081 80	010080032 010080051 010080063 010080073 010080076	80/09/12 80/08/29 80/08/18 80/07/18 80/09/25	XPORTLIC 50-338 GA999 GA999 50-206	a a	8010080472 8010080474 8010080482 8010080485 8010080496	8010080464 8010080471 8010080478 8010080477 8010080492	80/10/03 80/10/02 80/09/29 80/10/01 80/09/16	50-267 P 50-320 B 50-220 B 50-369 B 50-27 P

ACCESSION NUMBER			ACCEBSION NUMBER	
PRINCIPA ENGLOSURE DOCUMEN		SUBJECT CATEGORY	PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	GUBJECT CATEGORY
8010080506 8010080 8010080512 8010080 8010080515 8010080 8010080557 8010080 8010080579 8010080	01 60/10/02 03 60/10/01 52 60/10/02	50-518 R 50-275 A 50-315 S 50-344 P 50-255 P	8010090435 8010090420 80/09/30 8010090438 8010090420 80/09/30 8010090440 8010090420 80/09/30 8010090534 8010090529 80/09/24 8010090537 8010090529 80/09/24	50-254 P 50-265 P 50-265 P 50-302 P 50-302 P
8010080581 8010080 8010080586 8010080 8010080588 8010080 8010080618 8010080 8010080620 8010080	78 80/08/21 880 80/08/22 15 80/09/12	90-255 P 90-295 P 40-8502 CONTRACT CONTRACT	8010070540 8010070529 80/07/24 8010100007 8010100003 89/09/18 8010100011 8010100008 80/10/03 8010100012 8010100009 80/09/04 8010100017 8010100014 80/09/16	50-302 P 50-373 Q FDIA 50-373 Q 70-143
8010080433 8010080 8010080435 8010080 8010080440 8010080 8010080463 8010080 8010080467 8010080	31 80/09/23 38 80/09/24 61 80/09/16	CONTRACT CONTRACT MISC CONTRACT CONTRACT	8010100020 8010100014 80/09/16 8010100021 8010100018 80/08/21 8010100023 8010100014 80/09/16 8010100030 8010100026 80/08/20 8010100038 8010100032 80/09/17	70-143 50-289 Q 70-143 50-219 Q 50-336 Q
8010080672 8010080 8010080673 8010080 8010090011 8010090 8010090019 8010090 8010090019 8010090	070 80/09/24 006 80/09/23 014 80/08/25	50-344 H 50-335 B CONTRACT 50-219 F 50-280 Q	8010100037 8010100037 80/09/19 8010100040 8010100032 80/09/17 8010100042 8010100032 80/09/17 8010100044 8010100032 80/09/17 8010100052 8010100049 80/09/04	50-267 0 50-336 0 50-336 0 50-336 0
8010090021 8010090 8010090026 8010090 8010090029 8010090 8010090031 8010090 8010090033 8010090	022 80/10/31 022 80/10/31 024 80/08/25	CONTRACT NUREO NUREO 50-335 Q CONTRACT	8010100056 8010100054 80/10/02 8010100059 8010100055 80/08/22 8010100064 8010100057 80/09/12 8010100065 8010100057 80/09/12 8010100069 8010100057 80/09/12	50-409 0 50-309 0 50-272 0 50-272 0 50-272 0
8010090041 8010090 8010090044 8010090 8010090044 8010090 8010090052 8010090 8010090035 8010090	36 80/09/23 39 80/10/02 49 80/01/01	PR CONTRACT FOIA CONTRACT CONTRACT	8010100072 8010100068 80/09/05 8010100074 8010100062 80/08/21 8010100075 8010100057 80/09/12 8010100076 8010100068 80/09/05 8010100078 8010100068 80/09/05	70-1703 50-352 0 50-272 0 70-1703 70-1703
8010090063 8010090 8010090064 8010090 8010090068 8010090 8010090069 8010090	58 80/09/18 60 80/09/17 59 80/09/23	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	8010100082 8010100079 80/07/30 8010100089 8010100085 80/10/02 8010100091 8010100087 80/08/20 8010100074 8010100092 80/09/15 8010100095 8010100081 80/09/08	50-483 Q 50-274 Q 50-410 Q 50-352 Q COMMISSION
8010070070 80100700 8010070072 80100700 8010070087 80100700 8010070105 80100700	66 80/09/10 81 80/08/12 81 80/08/12	CONTRACT CONTRACT 50-322 Q 50-322 Q 50-322 Q	8010100102 8010100100 80/08/01 8010100103 8010100099 80/08/21 8010100111 8010100106 80/09/30 8010100113 8010100110 80/09/26 8010100118 8010100114 80/09/25	50-449 H 50-410 G 50-299 H 50-449 H 50-305 H
8010090110 80100900 8010090119 80100900 8010090124 80100900 8010090141 80100900 8010090152 80100900	81 80/08/12 81 80/08/12 35 80/09/16	50-322 Q 50-322 Q 50-322 Q CONTRACT 50-280 Q	8010100123 8010100120 80/07/08 8010100125 8010100121 80/07/27 8010100130 8010100128 80/07/23 8010100142 801001034 80/08/20 8010100144 8010010773 80/08/20	50-201 H 50-309 U COMMISSION 50-237 P 50-409 P
8010090154 8010090; 8010090187 8010090; 8010090190 8010090; 8010090192 8010090; 8010090214 8010090;	85 80/09/22 85 80/09/22 88 80/09/12	40-8502 50-312 Q 50-312 Q 71-6478 CONTRACT	801010014B 8010010798 80/08/20 8010100186 8010100178 80/08/01 8010100197 8010100193 80/10/03 8010100228 8010100225 80/09/19 8010100226 8010100223 80/09/08	90-155 P PR 50-272 F 50-346 G CONTRACT
8010090223 8010090; 8010090227 8010090; 8010090228 8010090; 8010090233 8010090; 8010090235 8010090;	21 80/08/22 25 80/08/22 25 80/08/22	CONTRACT 70-1151 50-284 Q 50-284 Q 70-1151	8010100243 8010100237 80/10/03 8010100245 8010100242 80/07/26 8010100244 8010100242 80/07/26 8010100254 8010100251 80/08/26 8010100255 8010100257 80/08/27	50-155 P 40-672 40-672 50-261 Q 40-6920
8010090241 80100903 8010090244 80100903 8010090246 80100903 8010090250 80100903 8010090288 80100903	36 80/08/28 37 80/10/03 37 80/10/03	TOPREP 50-518 Q TOPREP TOPREP REVIEW ORP	8010100268 8010100257 80/08/27 8010100269 8010100257 80/08/27 8010100270 8010100257 80/08/27 8010100291 8010100290 80/10/03 8010100293 8010100264 80/10/03	40-6920 40-6920 40-6920 50-333 R 50-272 F
8010070322 80100703 8010070335 80100703 8010070341 80100703 8010070344 80100703 8010070352 80100703	25 80/10/03 37 80/09/12 37 80/10/02	50-219 8 50-245 8 50-445 0 50-344 8 50-293 8	8010100798 8010100295 80/10/04 8010100310 8010100307 80/10/03 8010100314 8010100311 80/10/02 8010100317 8010100313 80/10/02 8010100318 8010100312 80/07/17	50-243 P 50-334 8 50-335 8 50-335 B TOPKEP
8010070362 B0100703 8010070365 B0100703 8010070368 B0100703 B010070370 B0100703 8010070371 80100703	59 80/05/19 E0/01/08 65 59 80/05/19	50-316 B 50-275 Q 50-316 B 50-275 Q 50-315 B	8010100322 8010100314 80/07/30 8010100323 8010100317 80/07/25 8010100328 8010100320 80/10/02 8010100331 8010100326 80/07/25 8010100332 8010100325 80/07/25	50-335 8 50-335 8 50-466 U 50-335 8 50-324 8
8010090377 80100903 8010090381 80100903 8010090399 80100903 8010090411 80100904 8010090413 80100904	80 80/08/22 97 80/10/07 10 80/10/01	50-344 Q 50-361 Q NUREG 50-155 P 50-155 P	8010100334 8010100329 80/07/26 8010100336 8010100327 80/10/06 8010100341 8010100335 80/10/03 8010100345 8010100339 80/10/03 8010100348 8010100340 80/10/06	50-335 8 50-272 8 50-324 8 50-335 8 50-311 8
8010090424 8010090 8010090425 8010090 8010090428 8010090 8010090429 8010090	20 80/09/30 22 80/10/02 20 80/09/30	50-344 Q 50-254 P 50-269 P 50-254 P 50-254 P	8010100369 8010100366 80/09/03 8010100370 8010100365 80/09/29 8010100372 8010100365 80/09/29 8010100381 8010100375 80/09/23 8010100399 8010100397 80/09/22	50-508 Q 50-302 P 50-302 P 50-282 Q CONTRACT

ACCESSION	NUMBER			ACCESSION NUMBER	
ENCLOBURE	PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE	SUBJECT
	DOCUMENT	18SUED	CATEGORY	ENCLOSURE DOCUMENT ISSUED	CATEGORY
8010100431	8010100428	80/09/15	50-277 (8010140243 8010140238 80/09/16	CGNTRACT
8010100434	8010100428	80/09/15	50-277 (6010140249 8010140247 80/10/07	50-346 P
8010100436	8010100428	80/09/15	50-277 (8010140235 8010140232 80/10/07	50-219 P
8010100438	8010100428	80/09/15	50-277 (8010140263 8010140261 80/10/07	50-389 H
8010100441	8010100428	80/09/15	50-277 (6010140265 8010140176 60/09/22	71-6744
8010140005 8010140008 8010140010 8010140013 8010140022	8010140003 8010140003 8010140003 8010140003	80/09/29 80/09/29 80/09/29 80/09/29 80/09/12	50-321 (50-321 (50-321 (50-321 (50-334 (8010140274 8010140271 80/09/30 8010140279 8010140271 80/09/30 8010140315 8010140312 80/10/03 8010140316 8010140310 80/10/09 8010140325 8010140324 80/10/08	50-287 K 50-387 K 50-298 R 50-275 A 50-287 B
8010140026	8010140020	80/09/12	50-334 F	8010140334 8010140333 80/10/08	50-282 P
8010140027	8010140018	80/06/26	50-327 C	8010140353 8010140345 80/10/09	50-275 A
8010140030	8010140023	80/09/22	50-413 C	8010140371 8010140365 80/10/07	50-260 8
8010140031	8010140028	80/09/17	50-387 C	8010140386 8010140382 80/10/10	50-471 B
8010140032	8010140024	80/09/19	50-483 S	8010140390 8010140383 80/10/06	50-296 9
8010140033 8010140034 8010140039 8010140040	8010140028 8010140023 8010140028 8010140027 8010140037	80/09/17 80/09/22 80/09/17 80/09/09 80/09/02	50-387 (50-413 (50-387 (8ECY 50-274 (8010140401 8010140395 80/09/26 8010140402 8010140392 80/10/03 8010140409 8010140397 80/10/07 8010140416 8010140411 80/10/10 8010140420 8010140406 80/09/16	CONTRACT 50-317 8 50-339 8 50-155 8 CONTRACT
8010140042	8010140029	80/09/09	50-356 (8010140422 8010140411 80/10/10	50-155 S
8010140043	8010140028	80/09/17	50-387 (8010140423 8010140415 80/10/07	50-338 S
8010140044	8010140037	80/09/02	50-274 (8010140431 8010140426 80/10/07	50-275 S
8010140045	8010140035	80/09/18	50-400 (8010140436 8010140427 80/10/07	50-338 S
8010140046	8010140041	80/09/24	50-269 (8010140442 8010140437 80/10/02	50-307 S
8010140047	8010140037	80/09/02	50-274 (8010140447 8010140443 80/10/07	50-285 8
8010140051	8010140041	80/09/24	50-269 (8010140449 8010140430 80/09/25	CONTRACT
8010140053	8010140035	80/09/15	50-400 (8010140450 8010140430 80/09/25	50-245 8
8010140054	8010140048	80/09/15	50-352 (8010140451 8010140440 80/09/30	50-254 8
8010140056	8010140048	80/09/15	50-352 (8010140455 8010140448 80/10/06	50-155 R
8010140059 8010140063 8010140072 8010140078 8010140084	B010140048 B010140048 B010140058 B010140070 B010140068	80/09/15 80/09/15 80/09/15 80/08/27 80/09/15	50-352 0 50-352 0 70-1143 50-364 7	8010140457 8010140452 80/10/03 8010140464 8010140459 80/10/06 8010140472 8010140464 80/10/03 8010140476 8010140464 80/10/08 8010140462 8010140477 80/10/07	50-295 8 50-305 8 50-324 8 50-275 H 50-244 8
8010140090	8010140068	80/07/15	70-1143	8010140485 8010140480 80/10/03	50-285 8
8010140091	8010140073	80/10/03	FOIA	8010140487 8010140481 80/10/03	50-325 8
8010140099	8010140073	80/10/03	FOIA	8010140493 8010140488 80/10/06	PR
8010140099	8010140072	80/07/27	50-250 (8010140494 8010140489 80/10/01	50-237 8
8010140101	8010140075	80/08/20	50-219 F	8010140512 8010140500 80/09/29	50-254 8
8010140104 8010140107 8010140111 8010140115 8010140117	8010140092 8010140092 8010140092 8010140092 8010140114	80/09/29 80/09/29 80/09/29 80/09/29 80/09/10	50-250 (50-250 (50-250 (50-250 (80(0140529 8010140923 80/10/06 80(0140533 80(0140523 80/10/06 80(0140550 80(0140543 80/10/02 80(0140555 80(0140543 80/10/02 80(0140555 80(0140549 80/10/06	50-322 0 50-322 0 50-446 0 50-466 0 PR
8010140121	8010140112	80/09/25	50-400 (8010140587 8010140543 80/10/02	50-466 0
8010140123	8010140075	80/08/20	50-219 F	8010140565 8010140560 80/10/03	50-289 0
8010140127	8010140075	80/08/20	50-219 F	8010140366 8010140934 80/10/03	50-466 0
8010140128	8010140117	80/09/26	CONTRACT	8010140570 8010140560 80/10/03	50-289 0
8010140131	8010140112	80/09/25	50-400 (8010140571 8010140563 80/10/08	50-376 0
8010140137	8010140133	80/09/30	50-10 (8010140573 8010140543 80/10/02	50-466 0
8010140139	8010140112	80/09/25	50-400 (8010140574 8010140548 80/07/25	CONTRACT
8010140144	8010140112	80/09/25	50-400 (8010140578 8010140543 80/10/02	50-466 0
8010140148	8010140147	80/09/19	50-261 F	8010140582 8010140543 80/10/02	50-466 0
8010140151	8010140147	80/09/19	50-261 F	8010140583 8010140540 80/10/03	50-289 0
8010140152 8010140154 8010140155 8010140156 8010140164	8010140150 8010140147 8010140150 8010140112 8010140161	80/08/28 80/09/19 80/08/28 80/09/25 80/08/19	50-461 0 50-261 F 50-461 0 50-400 0 50-295 0	8010140585 8010140540 80/10/03 8010140589 8010140543 80/10/02 8010140594 8010140543 80/10/02 8010140599 8010140543 80/10/02 8010140602 8010140543 80/10/02	50-289 0 50-466 0 50-466 0 50-466 0
8010140166	8010140162	80/09/22	CONTRACT	8010140608 8010140604 80/10/03	FOIA
8010140166	8010140161	80/08/19	50-295	8010140613 8010140604 80/10/03	FOIA
8010140178	8010140172	80/09/11	70-1447	8010140615 8010140604 80/10/03	FOIA
8010140181	8010140176	80/09/22	71-4744	8010140627 8010140159 80/09/29	CONTRACT
8010140184	8010140172	80/09/11	70-1447	8010150031 8010150027 80/06/17	50-397 G
8010140190	8010140172	80/07/11	70-1447	8010150041 8010150029 80/09/12	50-410 8
8010140191	8010140171	80/07/07	40-1162	8010150042 8010150037 80/09/30	50-335 9
8010140197	8010140175	80/07/26	50-289	8010150047 8010150037 80/09/30	50-335 9
8010140202	8010140178	80/07/17	70-820	8010150053 8010150037 80/09/30	50-335 9
8010140208	8010140178	80/07/17	70-820	8010150053 8010150037 80/09/30	50-335 9
8010140210	8010140206	80/10/03	50-309 F	8010150064 8010150060 80/10/01	50-312 0
8010140213	8010140178	80/09/19	70-820	8010150070 8010150060 80/10/01	50-312 0
8010140220	8010140217	80/09/26	50-184 F	8010150073 8010150060 80/10/01	50-312 0
8010140221	8010140178	80/09/19	70-820	8010150079 8010150069 80/09/23	70-1257
8010140224	8010140178	80/09/19	70-820	8010150079 8010150060 80/10/01	50-312 0
8010140228	8010140178	80/09/19	70-820	8010150070 8010150085 80/08/19	50-254 0
8010140229	8010140223	80/09/12	50-409 F	8010150097 80101550071 80/09/18	50-546 B
8010140230	8010140224	80/09/09	CONTRACT	8010150102 8010150074 80/08/18	50-331 0
8010140233	8010140178	80/09/19	70-820	8010150112 8010150104 80/08/19	50-331 0
8010140241	8010140174	80/09/17	40-4492	8010150117 8010150114 80/09/16	70-820

ACCESSIO						ACCESSION			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR			ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEOGRY
8010150126 8010150138 8010150148 8010150156 8010150165	8010150118 8010150133 8010150144 8010150146 8010150158	80/08/20 80/08/07 80/08/29 80/08/28 80/09/14	50-155 50-263 50-456 50-456 50-307	0 0 0 F		8010130353 8010130354 8010130359 8010130362 8010130363	8010150550 8010150537 8010150550 8010150537 8010150550	80/10/01 80/10/10 80/10/01 80/10/10 80/10/01	50-338 Q 27-37 50-338 Q 27-37 50-338 Q
8010150203 8010150215 8010150235 8010150271 8010150298	8010150182 8010150211 8010150230 8010150267 8010150274	80/09/18 80/09/15 80/08/21 80/10/03	50-412 50-354 50-341 50-271 50-312	8 0 P R		8010150547 8010150549 8010150574 8010150577 8010150581	8010150597 8010150537 8010150570 8010150537 8010150570	80/10/10 80/10/10 80/10/01 80/10/10 80/10/01	27-39 27-39 50-250 27-39 50-250 Q
8010150305 8010150313 8010150318 8010150323 8010150325	8010150300 8010150309 8010150316 8010150321 8010150322	80/10/07 80/10/01 80/10/08 80/10/08 80/10/10	50-271 50-254 50-324 50-346 50-29	R R R R		8010150584 8010150588 8010150609 8010150610 8010150614	B010150570 B010150570 B010150405 B010150407 B010150413	80/10/01 80/10/01 80/09/30 80/09/25 80/09/25	50-250 G 50-250 G CONTRACT 71-6346 71-5926
8010150330 8010150335 8010150341 8010150348 8010150357	8010150324 8010150332 8010150338 8010150343 8010150352	80/10/08 80/10/10 80/10/04 80/10/09 80/09/26	50-327 50-259 50-250 50-10 CONTRACT	R R P		8010150621 8010150622 8010150624 8010150626 8010150627	8010150591 8010150417 8010150411 8010150420 8010150411	80/10/10 80/09/26 80/10/04 80/09/12 80/10/06	50-209 O CONTRACT FOIA 70-1257 FOIA
8010150361 8010150362 8010150363 8010150367 8010150373	8010150359 8010150359 8010150367 8010150367	80/09/29 80/09/29 80/09/29 80/10/10 80/10/07	50-325 50-325 50-325 50-213 50-407	P P R R		8010150628 8010150630 8010150634 8010150645 8010150649	B010150620 B010150611 B010150611 B010150643 B010150600	80/09/12 80/10/06 80/10/06 80/09/19 80/09/29	70-1257 FDIA FDIA 50-317 G CONTRACT
8010150377 8010150384 8010150387 8010150397 8010150398	8010150375 8010150379 8010150386 8010150394 8010150393	80/10/10 80/10/04 80/10/07 80/10/08 80/10/08	50-277 50-266 50-324 50-266 50-289	R B R B		8010150665 8010150666 801015069 8010150671 8010150672	EAAO#1010B 1640E1010B 1640E1010B 1640E1010B 1640E1010B	80/10/02 80/09/29 80/09/29 80/09/29 80/09/29	50-237 P 50-324 Q 50-324 Q 50-324 Q 50-324 Q
8010150399 8010150402 8010150405 8010150406 8010150408	8010150392 8010150400 8010150403 8010150404 8010150392	80/10/09 80/10/10 80/10/10 80/10/08 80/10/09	50-387 50-307 50-155 50-220 50-387	M R P R		8010160002 8010160007 8010160012 8010160014 8010160027	8010160001 8010160006 8010160008 8010160013 8010160024	80/09/09 80/09/24 80/09/24 80/10/10 80/08/25	COMMISSION State Prog 70-27 50-289 T 50-482 G
8010150411 8010150417 8010150425 8010150431 8010150433	8010150407 8010150372 8010150423 8010150421 8010150426	80/10/09 80/10/09 80/10/07 80/10/09 80/10/07	50-263 50-387 50-261 50-331 50-312	R M P 8 P		8010160040 8010160045 8010160047 8010160061 8010160062	8010160036 8010160036 8010160041 8010160057 8010160052	90/10/14 80/10/14 80/09/24 80/06/13 80/10/03	50-10 G 50-10 G 50-321 G 50-324 G FDIA
8010150436 8010150448 8010150449 8010150450 8010150452	8010150427 8010150437 8010150438 8010150439 8010150444	80/10/03 80/10/07 80/10/06 80/10/08 80/10/09	50-295 50-271 50-344 50-331 50-10	P 8 8 8 P		8010140137 8010140141 8010140144 8010140145 8010140149	8010160133 8010160091 8010160102 8010160133 8010160105	80/08/21 80/09/29 80/09/26 80/08/21 80/09/29	50-373 @ CONTRACT CONTRACT 50-373 @ CONTRACT
8010150453 8010150454 8010150459 8010150462 8010150466	8010150443 8010150440 8010150442 8010150445 8010150456	80/10/07 80/10/07 80/10/09 80/10/10 80/10/08	40-8778 50-204 50-255 50-261 50-337	R R R		8010160152 8010160156 8010160159 8010160161 8010160162	8010160109 8010160112 8010160116 9010160122	80/09/29 80/09/29 80/09/29 80/08/19 80/09/29	CONTRACT CONTRACT CONTRACT 50-358 0 CONTRACT
8010150467 8010150468 8010150471 8010150479 8010150480	8010130457 8010150461 8010150460 8010150470 8010150472	80/10/09 80/10/07 80/10/08 80/10/07 80/09/23	50-331 50-271 50-292 50-219 TOPREP	8 b 8		8010160164 8010160166 8010160167 8010160170 8010160173	8010160155 8010160148 8010160125 8010160127 8010160132	80/09/30 80/10/09 80/09/29 80/09/29 80/09/29	CONTRACT 50-556 Q CONTRACT CONTRACT CONTRACT
8010150482 8010150483 8010150486 8010150491 8010150492	8010150460 8010150475 8010150481 8010150460 8010150484	80/10/08 80/10/08 80/10/09 80/10/09 80/10/08	50-292 50-331 50-290 50-282 50-289	8 8 8 8	•	8010160176 8010160177 8010160187 8010160196 8010160199	8010160135 8010160171 8010160182 8010160171 8010160172	80/09/29 80/09/30 80/08/26 80/09/29 80/09/23	CONTRACT 50-409 Q 50-305 Q CONTRACT 50-275 Q
8010150498 8010150499 8010150501 8010150502 8010150507	8010150493 8010150490 8010150494 8010150497 8010150503	80/10/08 80/10/09 80/10/07 80/10/10 80/10/10	50-247 50-331 50-237 50-282 50-255	8 8 8 R 8		8010160208 8010160217 8010160224 8010160227 8010160228	8010160203 8010160213 8010160217 8010160225 8010160233	80/07/30 80/07/05 80/07/26 80/07/23 80/07/30	CONTRACT XPORTLIC CONTRACT XPORTLIC CONTRACT
8010150508 8010150511 8010150515 8010150517 8010150518	8010150487 8010150500 8010150504 8010150505 8010150500	80/10/09 80/08/12 80/10/07 80/10/09 80/08/12	50-247 50-320 50-237 50-267 50-320	R G B S		8010160249 8010160250 8010160292 8010160297 8010160301	8010160246 8010160244 8010160288 8010160288	80/09/19 80/09/12 80/09/25 80/09/25	XPORTLIC 50-483 G GA999 GA999 GA999
8010150521 8010150525 8010150526 8010150527 8010150531	8010150510 8010150513 9010150520 8010150504 8010150523	80/10/07 80/10/09 80/10/07 80/10/07 80/10/07	50-324 50-260 50-324 50-325 50-325	8 8 8 8		8010160312 8010160322 8010160332 8010160334 8010160336	8010160288 8010160319 8010160324 8010160327 8010160330	80/09/25 80/09/30 80/09/10 80/09/30 80/09/10	GA999 CONTRACT 50-329 G CONTRACT 50-374 G
8010150540 8010150542 8010150544 8010150547 8010150551	8010150536 8010150537 8010150537 8010150537 8010150537	80/10/10 80/10/10 80/07/30 80/10/10 80/10/10	30~366 27~39 50~302 27~39 27~39	P	•	8010160342 8010160346 8010160347 8010160351 8010160352	8010160337 8010160337 8010160340 8010160340 8010160345	80/07/29 80/09/10 80/10/10 80/10/10 80/09/22	CONTRACT 50-254 G 50-263 P 50-263 P 50-254 B
		1							

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGOR	1	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8010160358 8010160365 8010160371 8010160375 8010160378	8010140345 8010140345 8010140345 8010160345 8010160345	80/09/22 80/09/22 80/09/22 80/09/22 80/08/29	50-254 50-254 50-254 50-254 50-201	8 8 8 8 8	8010170208 8010170232 8010170245 8010170278 8010170291	8010170199 8010170225 8010170238 8010170271 8010170288	80/09/30 80/09/30 80/10/09 80/08/25 80/09/08	50-546 50-289 50-313 50-321 XPORTLIC	В Р 8 Q
8010160416 8010160421 8010160427 8010160458 8010160461	8005220571 8010160415 8010160424 8010160456 8010160460	80/05/19 80/10/02 80/08/14 80/10/14 80/07/02	TOPREP 50-333 70-1151 50-338 50-29	0 R S	8010170275 8010170311 8010170315 8010170317 8010170318	8010170293 8010170309 8010170314 8010170316 8010170313	80/09/09 80/09/29 80/09/30 80/09/26 80/09/26	XPORTLIC CONTRACT CONTRACT CONTRACT 50-295	ū
8010160465 8010160468 8010160470 8010160475 8010160482	8010140463 8010160466 8010160469 8010160472 8010160479	80/10/14 80/10/01 80/10/07 80/10/09 80/10/09	50-318 50-293 50-133 50-366 50-321	5 R R 8 5	8010170323 8010170333 8010170347 8010170349 8010170352	8010170320 8010170319 8010170345 8010170345 8010170345	80/09/30 80/08/08 80/09/11 80/09/11	CONTRACT 50-245 50-320 50-320 50-320	O R R R
8010140494 8010160500 8010160511 8010160518 8010160520	8010160489 8010160489 8010160509 8010160515 8010160515	80/10/10 80/10/10 80/10/10 80/10/15 80/10/15	50-333 50-333 50-259 50-220 90-220	P R P P	B010170353 B010170355 B010170357 B010170363 B010170371	8010170345 8010170345 8010170345 8010170361 8010170368	80/09/11 80/09/11 80/09/11 80/09/08 80/09/24	50-320 50-320 50-320 50-397 CONTRACT	R R R Q
8010160526 8010160527 8010160528 8010160541 8010160543	8010160319 8010160524 8010160525 8010160535 8010160535	80/10/13 80/10/10 80/10/10 80/10/01	TOPREP 50-322 50-341 50-247 50-247	G F P	8010170380 8010170388 8010170393 8010170400 8010170422	8010170377 8010170379 8010170383 8010170373 8010170412	80/09/24 80/09/22 80/09/29 80/09/26 80/03/28	CONTRACT CONTRACT CONTRACT CONTRACT 50-321	R
8010160549 8010160555 8010160558 8010160562 8010160564	8010160545 8010160545 8010160553 8010160559 8010160560	80/10/14 80/10/14 80/10/13 80/10/13	50-285 50-285 50-395 50-255 50-338	p F S R	8010170428 8010170431 8010170452 8010170464 8010170466	8010170419 8010170412 8010170447 8010170454 8010170438	80/09/03 80/03/28 80/09/29 80/09/26 80/09/02	50-528 50-321 CONTRACT 50-445 50-206	G R G
8010160569 8010160573 8010160574 8010160577 8010160584	8010160565 8010160567 8010160571 8010160571 8010160580	80/10/06 80/10/10 80/10/15 80/10/15	50-498 50-318 50-29 50-29 50-339	G B P P	8010170477 8010170516 8010170518 8010170531 8010170538	8010170469 8010170481 8010170481 8010170445 8010170993	80/09/30 80/10/03 80/10/03 80/10/08 80/10/03	50-458 50-289 50-289 50-312 50-255	0 P P Q
8010160586 8010160590 8010160594 8010160603 8010160617	8010160581 8010160580 8010160580 8010160601 8010160608	80/10/10 80/10/10 80/10/10 80/10/07 80/07/19	50~271 50~339 50~339 50~255 50~348	G P P P	8010170544 8010170546 8010170552 8010170555 8010170586	8010170540 8010170543 8010170549 8010170551 8010170559	80/10/14 80/10/03 80/09/05 80/08/13 80/09/30	50-269 50-331 CONTRACT CONTRACT	g G
8010160630 8010160637 8010160645 8010160653 8010160657	8010160624 8010160634 8010160640 8010160641 8010160652	80/09/19 80/09/19 80/10/07 80/09/24 80/09/26	50-282 50-334 Toprep 40-6659 Gayyy	G G	8010170572 8010170580 8010170594 8010170612 8010170624	8010170565 8010170574 8010170590 8010170605 8010170617	80/09/30 80/09/30 80/09/29 80/09/29 80/09/30	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
8010160660 8010160663 8010160666 8010160676 8010160697	8010140457 8010140452 8010140452 8010140452 8010140490	80/10/03 80/09/26 80/09/24 80/09/26	50-293 GA999 GA999 GA999 50-294	F G	8010170662 8010170693 8010200029 8010200034 8010200036	8010170644 8010170687 8010200024 8010200021 8010200024	80/07/10 80/10/02 80/10/01 80/07/10 80/10/01	50-528 50-219 50-147 50-361 50-147	М 6 6
8010160724 8010160751 8010160757 8010160762 8010160777	8010140719 8010160745 8010160745 8010160754 8010160774	80/09/26 80/10/01 80/10/13 80/10/10	70-27 50-346 50-346 50-516 27-39	r p o	6010200080 6010200102 6010200108 8010200113 6010200117	8010200076 8010200079 8010200079 8010200079 8010200099	80/09/30 80/09/29 80/09/29 80/09/29	CONTRACT 50-191 50-151 50-151 90-151	0 0 0
8010170013 8010170017 8010170021 8010170024 8010170026	B010170010 B010170010 B010170010 B010170015 B010170010	80/09/30 80/09/30 80/09/30 80/09/29 80/09/30	50-250 50-250 50-250 ACRE 50-250	G G G	8010200124 8010200200 8010200205 8010200207 8010200216	8010200199 8010200199 8010200199 8010200199	80/07/29 80/07/09 80/10/14 80/10/14	50-151 ACRB 50-289 50-289 50-289	Q T T T
8010170031 8010170032 8010170035 8010170036 8010170037	8010170027 8010170028 8010170027 8010170030 8010170027	80/07/30 80/07/25 80/07/30 80/10/02 80/07/30	90-327 CONTRACT 50-327 50-245 50-327	G G O G	8010200220 8010200222 8010200223 8010200230 8010200234	8010200212 8010200179 8010200179 8010200228	80/09/19 80/10/14 80/09/22 80/10/14 80/09/29	40-1341 50-289 CONTRACT 50-289 CONTRACT	T
8010170041 8010170050 8010170052 8010170061 8010170072	8010170027 8010170045 8010170046 8010170055 8010170067	80/09/30 80/09/05 80/09/02 80/09/30 80/09/30	50-327 50-312 50-327 50-493 50-461	Q Q Q Q	8010200235 8010200249 8010200250 8010200252 8010200261	8010200227 8010200239 8010200242 8010200239 8010200257	80/09/54 80/10/05 80/10/05 80/10/05	50-298 50-277 CONTRACT 50-277 50-320	0 0 H
8010170079 8010170093 8010170110 8010170122 8010170123	8010170049 8010170086 8010170049 8010170120 8010170107	80/10/02 80/10/02 80/10/02 80/10/02	50-112 CONTRACT 50-112 50-397 50-327	P K G	8010200274 8010200277 8010200263 8010200291 8010200294	8010200270 8010200271 8010200280 8010200288 8010200289	80/10/05 80/05/59 80/10/05 80/10/08	40-2061 50-327 50-220 CONTRACT 50-237	, O
8010170131 8010170147 8010170158 8010170163 8010170180	B010170125 B010170140 B010170140 B010170140 B010170173	80/09/29 80/09/E7 80/09/E7 80/09/E7 80/09/29	50-461 NUREG NUREG NUREG 50-483	G B	8010200297 8010200297 8010200302 8010200308 8010200313	8010200287 8010200272 8010200287 8010200289 8010200305	80/10/02 80/10/02 80/10/02 80/09/29	50-297 CONTRACT 50-237 50-237 50-358	906

ACCERSION	I NUMBER				ACCERBION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	GUAJECT CATEGOR		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	
8010200317 8010200326 8010200327 8010200335 8010200346	8010200307 8010200316 8010200324 8010200332 8010200343	80/09/29 80/09/30 80/09/30 80/09/29 80/10/08	CONTRACT CONTRACT CONTRACT 50-327 50-445		8010200383 8010200385 8010200592 8010200594 8010200597	8010200576 8010200558 8010200591 8010200587 8010200588	80/10/13 80/10/10 80/10/10 80/10/10 80/10/09	50-334 8 50-349 A 50-272 8 50-333 8 50-324 8	
801020034/ 8010200349 8010200351 8010200352 8010200361	8010200343 8010200345 8010200345 8010200349 8010200359	80/10/08 80/09/15 80/09/15 80/09/03 80/09/12	50-445 50-272 50-272 70-143 70-1100	K P P	8010200400 8010200404 8010200420 8010200423 8010200431	8010200595 8010200579 8010200614 8010200613 8010200627	80/10/02 80/10/02 80/07/30 80/07/30 80/07/30	TARATIOD TARATIOD 27-271 0 27-10 0 EP2-00	
8010200364 8010200366 8010200368 8010260372 8010200373	8010200360 8010200360 8010200360 8010200360 8010200370	80/09/15 80/09/30 80/09/15 80/09/15 80/09/30	50-219 CONTRACT 50-219 50-219 CONTRACT	P ≱	8010200642 8010200653 8010200660 6010200666 8010200668	8010200634 8010200646 8010200694 8010200663 8010200667	80/09/30 80/09/25 80/09/30 80/09/30 80/09/02	CONTRACT 27-39 CONTRACT CONTRACT 50-358 G	
8010200374 8010200378 8010200381 8010200384 8010200390	8010200367 8010200376 8010200382 8010200386	80/09/24 80/10/10 80/10/06 80/10/10 80/09/15	PR 50-272 PR 50-311 40-341	R	8010200670 8010200673 8010200674 8010200675 8010200678	8010200667 8010160036 8010200672 8010160036 8010200676	80/09/02 80/10/14 80/09/02 80/10/14 80/09/19	50-358 Q 50-10 Q 50-454 Q 50-10 Q 50-546 Q	
8010200392 8010200396 8010200402 8010200404 8010200407	8010200389 8010200389 8010200400 8010200399 8010200405	80/10/15 80/10/15 80/10/10 80/10/14 80/10/14	50-280 50-280 50-285 50-271 50-302	R R R R R	8010200465 8010200489 8010200491 8010200700 8010200701	8010200683 8010200688 8010200688 8010200697 8010200698	80/09/17 80/09/08 80/09/08 80/09/15 80/09/11	50-331 Q 50-546 Q 50-546 Q 50-443 B CONTRACT	
8010200410 8010200415 8010200417 8010200422 8010200426	8010200407 8010200412 8010200408 8010200417 8010200424	80/10/14 80/10/14 80/10/14 80/10/09 80/10/09	50-315 50-315 50-259 50-320 50-320	R ft 8 8 8	8010200707 8010210004 8010210027 8010210046 8010210050	8010200703 8010210002 8010210025 8010210040 8010210040	80/07/15 80/07/23 80/07/30 80/10/07 80/10/07	50-443 8 40-8743 71-5971 50-269 P	
8010200428 8010200431 8010200434 8010200435 8010200439	8010200427 8010200429 8010200432 8010200433 8010200436	80/10/13 80/10/14 80/10/14 80/10/02 80/10/07	TOPREP 50-293 50-318 NUREQ 50-346	8 6 8	8010210054 8010210064 8010210077 8010210070 8010210073	8010210040 8010210040 8010210072 8010210087 8010210087	80/10/07 80/10/01 80/09/30 80/10/01 80/10/01	50-267 P CONTRACT 50-327 8 50-346 P 50-346 P	
8010200447 8010200448 8010200459 8010200461 8010200464	8010200445 8010200444 8010200451 8010200458 8010200451	80/10/03 80/10/07 80/10/14 80/10/03 80/10/14	50-347 50-346 50-277 50-277 50-277	A 8 P P P	8010210097 8010210109 8010210108 9010210117 8010210132	8010210087 8010210098 8010210095 8010210095 8010210125	80/10/01 80/07/30 80/07/10 80/07/10 80/07/27	50-346 P CONTRACT HISC HISC 50-334 P	
8010200469 8010200476 8010200477 8010200482 8010200483	8010200464 8010200471 8010200473 8010200472 8010200472	80/10/14 80/10/17 80/10/14 80/10/09 80/10/09	50-271 50-261 50-302 50-213 50-213	8 P 8 P P	8010210134 8010210138 8010210141 8010210169 8010210170	8010210125 8010210131 8010210125 8010210164 8010210165	80/09/29 80/09/15 80/09/29 80/07/29 80/10/02	50-334 P GUNTRACT 50-334 P 70-162 50-259 0	
8010200485 8010200488 8010200489 8010200492 8010200494	8010200479 8010200472 8010200480 8010200472 8010200472	80/10/14 80/10/09 80/10/14 80/10/09 80/10/09	50-302 50-213 50-305 50-213 50-213	8 P P P	8010210176 8010210179 8010210189 8010210195 8010210207	8010210145 8010210145 8010210175 8010210175 8010210201	80/10/02 80/10/02 80/10/10 80/10/10 80/10/01	50-259 0 50-259 0 FOIA FOIA 50-321 P)
8010200497 8010200499 8010200502 8010200505 8010200507	8010200472 8010200491 8010200472 8010200491 8010200472	80/10/07 80/10/16 80/10/07 80/10/16 80/10/07	50-213 50-280 50-213 50-280 50-213	P 8 8 8	8010210212 8010210243 8010210247 8010210248 8010210231	8010210201 8010210239 8010210240 8010210239 8010210240	80/10/01 80/09/18 80/09/17 80/09/18 80/09/17	50-321 P 71-9016 70-135 71-9016 70-135	
8010200509 8010200513 8010200523 8010200524 8010200531	8010200472 8010200491 8010200519 8010200491 8010200517	80/10/09 80/10/14 80/10/17 80/10/16 80/10/10	50-213 50-280 50-3 50-280 27-39	P 용 내 명	8010210253 8010210256 8010210259 8010210264 8010210280	8010210239 8010210240 8010210239 8010210240 8010210276	80/09/18 80/09/17 80/09/18 80/09/17 80/08/15	71-9016 70-135 71-9016 70-135 50-278 G	à
8010200534 8010200535 8010200537 8010200539 8010200545	9010200529 8010200528 8010200517 9010200532 8010200517	80/10/16 80/10/08 80/10/10 80/07/16 80/10/10	50-259 50-220 27-39 71-371 27-39	P 8	8010210281 8010210302 8010210322 8010210334 8010210337	8010210278 8010210278 8010210317 8010210332 8010210331	80/10/08 80/08/20 80/08/21 80/10/01 80/10/15	50-364 A 50-286 Q 50-322 Q TOPREP 50-206 P	3
8010200547 8010200548 8010200549 8010200550 8010200557	8010200532 8010200540 8010200544 8010200517 8010200544	80/09/16 80/10/15 80/10/15 80/10/10 80/10/15	71-371 50-306 50-498 27-39 50-498	8 0 0	8010210343 8010210383 8010210384 8010210371 8010210377	8010210331 8010210379 8010210378 8010210387 8010210396	80/10/15 80/10/07 80/09/15 80/10/15 80/10/09	50-206 P 50-397 G 40-8584 50-289 T 40-4492	;
8010200360 8010200364 8010200363 8010200370 8010200371	8010200517 8010200554 8010200558 8010200558 8010200554	80/10/10 80/10/13 60/10/10 80/10/10 80/10/15	27-39 50-155 50-349 50-349 50-155	8 4 4	8010210406 8010210407 8010210408 8010210414 8010210415	8010210402 8010210403 8010210404 8010210410 8010210412	80/10/15 80/10/14 80/10/15 80/10/10 80/10/10	50-348 R 50-77 J 50-331 R 50-366 R 50-286 R) ?
8010200573 8010200574 8010200577 8010200580 8010200581	8010200568 8010200567 8010200558 8010200575	80/10/10 80/10/03 80/10/10 80/10/10 80/10/15	50-287 PR 50-369 50-369 50-261	T	8010210416 8010210421 8010210423 8010210425 8010210428	8010210413 8010210418 8010210420 8010210419 8010210424	80/10/16 80/10/10 80/10/15 80/10/15 80/10/15	50-335 F 50-321 R 50-313 R 50-219 R 50-368 R	2

Company	ACCE88 I DN	NUMBER				ACCESSIO	N NUMBER			
						ENCLOSURE	DOCUMENT		CATEOURY	
Since S	8010210430 8010210431 8010210435 8010210437	8010210426 8010210427 8010210432 8010210434	80/10/14 80/10/15 80/10/14 80/10/15	50-287 50-334 50-247	R R R	8010210735 8010210738 8010210746	8010210595 8010210725 8010210595 8010210595	80/10/10 80/09/15 80/09/15	GA999 50-277 GA999 GA999	8
Section Sect	8010210444 8010210446 8010210449	8010210438 8010210438 8010210438	80/10/02 80/10/02 80/10/02	50-206 50-206 50-206	q	8010210752 8010210757 8010210760	8010210595 8010210595 8010210753	80/09/15 80/09/15 80/10/08	0A999 0A999 50-254	
SOURCE S	8010210459 8010210463 8010210464	8010210451 8010210451 8010210460	80/09/08 80/09/08 80/10/14	GA999 GA999 50-295		8010210781 8010220032 8010220038	8010210778 8010220030 8010220034	80/10/03 80/09/30 80/09/29	50-366 50-320 70-1151	H
SOLICION SOLICION	8010210475 8010210476 8010210477	8010210472 8010210473 8010210472	80/10/15 80/10/09 80/10/15	50-272 50-322 50-272	P K P	8010220081 8010220084 8010220090	8010220075 8010220076 8010220075	80/10/01 80/08/21 80/10/01	50-320 50-333 50-320 70-2609	Р 0 Р
	8010210499 8010210501 8010210505	8010210496 8010210498 8010210502	80/10/15 80/10/15 80/10/14	50-192 50-324 50-305	9 9	8010220125 8010220141 8010220148	8010220114 8010220135 8010220135	80/09/16 80/08/14 80/08/14	40-2384 50-29 50-29	G
Biblio 10329	8010210517 8010210518 8010210524	8010210514 8010210513 8010210520	80/10/10 80/10/03 80/10/08	50-327 50-275 50-237	8 9 8	8010220176 8010220207 8010220220	8010220169 8010220187 8010220212	80/07/04 80/07/16 80/07/14	RE000 50-309 70-25	
Biologico Biol	8010210539 8010210541 8010210548	8010210534 8010210535 8010210545	80/10/16 80/10/10 80/10/15	50-270 50-304 50-338	8 P	8010220284 8010220286 8010220289	8010220278 8010220278 8010220278	80/10/03 80/10/03 80/10/03	50-458 50-458 50-458	A A
BOIO210615 BOIO210693 BOV07/10 Buay Prop BOIO220391 BOIO220391 BOV020393 BOV07/10 South Prop BOIO220393 BOV020393 BOV08/27 A0-3453 BOV08/27 A0-3453 BOV08/27 BOV08/2	8010210579 8010210598 8010210602	8010210574 8010210574 8010210575	80/10/15 80/09/12 80/09/15	50-155 50-409 QA999	P	8010220309 8010220320 8010220356	8010220304 8010220316 8010220086	80/09/17 80/10/16 80/09/30	50-352 50-445 50-289	H
S010210649	8010210638 8010210639 8010210641	8010210633 8010210633 8010210635	80/10/01 80/10/01 80/10/15	State P 50-298 50-327	8	8010220391 8010220398 8010220399	8010220383 8010220373 8010220375	80/10/16 80/08/27 80/10/17	50-596 40-3453 50-296	o P
SOIO210464 SOIO210458 SO/10/02 TOPREP SOIO220478 SOIO220479 SO/10/12 SO-338 SOIO210462 SOIO210458 SO/10/14 SO-326 SOIO220462 SOIO220462 SOIO220462 SOIO220463 SOIO220463 SOIO220463 SOIO220463 SOIO220463 SOIO220464 SOIO220464 SOIO220464 SOIO220464 SOIO220464 SOIO220479 SOIO220464 SOIO220479 SOIO2204	6010210649 6010210651 8010210656	8010210644 8010210644 8010210632	B0/10/01 B0/10/10 B0/10/14	50~298 50~295 50~267	8 8	8010220442 8010220455 8010220470	8010220439 8010220453 8010220466	80/09/12 80/09/05 80/10/16	50-237 50-327 50-339	F R B
Sci Sci	8010210662 8010210663 8010210645	8010210628 8010210658 8010210657	80/10/02 80/10/14 80/10/17	TOPREP 50-260 50-327	8	8010220478 8010220481 8010220482	8010220477 8010220480 8010220479	80/10/14 80/09/25 80/10/15	50-338 50-155 50-339	9 9
Sol Sol	8010210677 8010210679 8010210680	8010210670 8010210669 8010210674	80/10/15 80/10/14 80/10/10	50-333 50-327 50-324	8	8010220496 8010220506 8010220509	8010220493 8010220500 8010220505	80/10/14 80/10/16 80/10/16	50-366 50-321 50-259	9 8 P
B010210678 B010210678 B0/10/07 B0/10/15 B0/10	8010210489 8010210489 8010210489	8010210673 8010210683 8010210682	80/10/03 80/10/10 80/10/17	50-204 50-295 50-296	8	9010220558 9010220540 9010220545	8010220550 8010220550 8010220550	80/10/06 80/10/06 80/10/05	50-295 50-295 50-295	P P
B010210705 B010210492 B0/10/17 50-304 B B010220551 B0/10/20550 B0/10/04 S0-295 B010210707 B010210700 B0/10/14 B0-344 B B010220555 B0/10/04 S0-295 B010220555 B0/10/04 S0-295 B010210710 B0/10/10 B0/	8010210695 8010210697 8010210698 8010210699	8010210478 8010210470 8010210471 8010210473	80/10/09 80/10/15 80/10/20 80/10/14	50-327 50-257 50-327	8	8010220574 8010220575 8010220577	8010220550 8010220550 8010220550	80/10/06 80/10/06 80/10/06	50-295 50-295 50-295	P P
8010210719 8010210711 80/10/01 50-247 6 8010220592 8010220589 80/08/01 71-9001 8010210712 80/09/30 50-293 8 8010220599 8010220550 80/10/06 50-295 9 8010220594 8010220550 80/10/06 50-295 9 8010210724 8010210715 80/10/10 50-293 8 8010220599 80/020550 80/10/06 50-295 9 8010210726 8010210718 80/10/11 50-249 8 8010210726 8010220550 80/10/06 50-295 9 8010210718 80/10/11 50-249 8 8010210726 8010220550 80/10/06 50-295 9 8010210718 80/10/11 50-249 8 8010210718 80/10/11 50-249 8 8010210718 80/10/10/10 50-295 9 8010220580 80/10/06 50-295 9 8010210718 80/10/11 50-249 8 8010210718 80/10/10/10 50-295 9 8010220580 80/10/06 50-295 9 8010220580 80/10/06 50-295 9 8010210718 80/10/10/10/10/10/10/10/10/10/10/10/10/10	8010210705 8010210707 8010210710 8010210714	8010210692 8010210700 8010210702 8010210701	80/10/17 80/10/14 80/10/09 80/10/15	50-344 50-260 50-327	8 8	801022058 801022058 801022038	8010220550 8010220550 8010220550	80/10/04 80/10/04 80/10/04	50-295 50-295 50-295	P P
	8010210722 8010210724 8010210726	8010210712 8010210715 8010210718	80/09/30 80/10/10 80/10/15	50-293 50-293 50-348	9 8	8010220594 8010220597 8010220604	8010220550 8010220550 8010220550	80/10/06 80/10/06 80/10/06	50-295 50-295 50-295	P

ACCESSION NUMBER			ACCESSION NU		
PRINCIPAL ENCLOSURE DOCUMENT	ISSUED	SUBJECT CATEGORY	PR	INCIPAL DATE OCUMENT 188UED	SUBJECT CATEGORY
8010220611 801022055 8010220412 601022055 8010220415 601022055 8010220417 601022055 8010220417 801022055	0 80/10/06 5 0 90/10/06 5 0 80/10/06 5 0 80/10/06 5	50-295 P 50-295 P 50-295 P 50-295 P 60-295 P	8010230629 80 8010230645 80 8010230645 80 8010230664 80	10230615 80/10/07 10230639 80/10/06 10230643 80/08/04 10230661 80/08/13 10230665 80/07/05	50-275 A 50-320 H 70-2933 50-317 Q 50-146 Q
8010220621 801022055 8010220622 801022055 8010220625 801022055 8010220630 801022055	0 80/10/06 5 0 80/10/06 5 0 80/10/06 5	80-295 P 50-295 P 50-295 P 50-295 P 50-295 P	6010230677 80: 6010230683 80: 6010230704 80:	10230665 80/09/05 10230674 80/09/15 10230680 80/10/10 10230702 80/10/10 10230703 80/09/08	50-146 Q 50-329 Q 50-546 Q 50-483 Q 50-298 F
8010220536 801022055 8010220537 801022055 8010220641 801022053 8010220644 801022063 8010220660 801022065	4 B0/09/10 4 0 B0/10/04 5 4 B0/09/10 4	50-295 P 40-4492 50-295 P 40-4492 50-155 S	8010230709 80: 8010230711 80: 8010230712 80:	10230704 80/09/05 10230703 80/09/08 10230710 80/09/26 10230708 80/10/06 10230710 80/09/26	50-412 0 50-298 F 50-352 0 50-320 H 50-352 0
8010220665 801022065 8010220668 801022066 8010220471 801022066 8010220473 801022066 8010220676 801022066	2 BO/09/22 5 2 BO/09/22 5 2 BO/09/22 5	60-333 0 60-333 0 60-333 0 60-333 8	8010230717 80 8010230718 80 8010230719 80	10230714 80/09/30 10230714 80/09/30 10230716 80/02/20 10230716 80/02/20 10230721 80/10/06	50-338 H 50-338 H 50-54 Q 50-54 Q 50-289 H
8010220694 801022068 8010220695 801022069 8010220696 801022069 8010220701 801022069 8010220703 801022069	7 80/10/07 7 2 80/09/24 C 9 80/09/19 5	1-9044 1-5998 ONTRACT 0-213 0	8010240007 801 8010240009 801 8010240010 801	10240003 80/10/09 10240003 80/10/09 10240003 80/10/09 10240003 80/10/09 10240003 80/10/09	50-321 Q 50-321 Q 50-321 Q 50-321 Q 50-321 Q
8010220704 801022067 8010220707 801022067 8010230018 801023001 8010230020 801023001 8010230043 801023003	9 80/09/19 5 6 80/09/10 5 6 80/09/10 5	0-213 Q 0-213 Q 0-5 P 0-5 P 0-387 Q	8010240017 801 8010240020 801 8010240021 801	10240014 80/08/27 10240018 80/10/14 10240018 80/10/14 10240018 80/10/14 10240018 80/10/14	GA999 GA999 GA999 GA999 GA999
8010230056 801023004 8010230068 801023006 8010230077 801023006 8010230084 801023007 8010230099 801023009	0 80/10/01 X 6 80/09/14 5 9 80/09/18 5	0-346 G PORTLIC 0-275 G 0-397 G 0-371	8010240026 801 8010240028 801 8010240031 801	10240017 80/10/08 10240024 80/09/03 10240024 80/09/03 10240029 80/09/18 10240033 80/10/08	50-327 0 50-313 0 50-255 0 50-256 0
8010230100 801023009 8010230107 801023010 8010230115 801023011 8010230114 801023011 8010230124 801023012	3 80/09/05 50 80/08/27 50 80/09/25 50	0-354 Q 0-375 Q 0-244 Q 0-344 Q 0-33	8010240038 801 8010240041 801 8010240042 801	0240034 80/09/29 10240037 80/09/18 10240040 80/10/07 10240040 80/10/07 10240052 80/10/03	71-102 50-263 Q 50-364 Q 50-364 Q 50-244 Q
8010230125 801023012 8010230137 801023013: 8010230143 801023014 8010230148 801023014 8010230157 801023015	80/10/03 70 80/07/05 50 80/08/25 70	0-338 0 0-1113 0-395 0 0-820 0-336 0	8010240062 801 8010240064 801 8010240081 801	10240057 80/10/21 10240058 80/10/03 10240058 80/10/03 10240073 80/10/06 10240076 80/10/16	50-287 T 50-244 Q 50-244 Q 50-257 P 50-596 Q
8010230180 801023017: 8010230203 801023019: 8010230262 801023025: 8010230276 8010230266 8010230283 8010230266	80/08/22 7: 80/09/04 50 80/10/02 50	0-344 Q 1-6294 0-566 Q 0-272 Q 0-272 Q	8010240091 801 8010240098 801 8010240100 801	0240073 80/10/06 10240073 80/10/06 10240094 80/10/06 10240094 80/10/06 10240094 80/10/06	50-259 P 50-259 P 50-336 P 50-336 P 50-336 P
8010230287 8010230246 8010230274 8010230236 8010230309 8010230303 8010230312 8010230303 8010230315 8010230303	9 80/10/02 50 9 80/10/06 50 9 80/10/06 50	0-272 Q 0-272 Q 0-344 P 0-344 P 0-344 P	\$010240111 801 8010240114 801 8010240120 801	0240095 80/08/29 10240107 80/10/01 10240108 80/08/29 10240107 80/10/01 10240119 80/09/04	70-1143 50-413 @ 70-135 50-413 @ 50-322 @
8010230330 8010230328 8010230322 8010230335 8010230372 8010230346 8010230382 8010230373	9 80/09/16 TO 9 80/10/17 50 9 80/10/17 50	DNTRACT DPREP 0-366 P 0-366 P 0-244 R	8010240134 801 8010240136 801 8010240146 801	0240127 80/09/02 10240115 80/10/06 10240129 80/09/05 10240115 80/10/06 10240142 80/09/03	50-247 G 50-349 G 50-213 G 50-348 G 50-247 G
8010230384 8010230383 8010230389 8010230383 8010230390 8010230394 8010230396 8010230394 8010230399 80102303993	B0/09/26 40 B0/10/16 50 B0/10/16 50	0-8463 0-8463 0-336 8 0-287 0 0-155 8	8010240154 801 8010240160 801 8010240166 801	10240144 B0/08/28 10240115 B0/10/06 10240156 B0/09/30 10240156 B0/09/30 10240161 B0/09/02	50-317 G 50-348 G 50-413 G 50-413 G 50-213 G
8010230410 8010230407 8010230412 8010230408 8010230420 8010230414 8010230428 8010230422 8010230433 8010230431	90/10/10 50 90/10/17 50 90/10/16 50	0-271 8 0-369 A 0-330 8 0-243 8 0-320 H	8010240174 801 8010240176 801 8010240185 801	0240156 80/09/30 0240115 80/10/06 0240161 80/09/02 0240178 80/10/06 0240178 80/10/06	50-413 G 50-348 G 50-213 G 70-143 70-143
8010230438 8010230444 8010230447 8010230447 8010230457 8010230453 8010230483	80/09/30 C0 80/10/13 50 80/10/06 50	0-317 R DNTRACT 0-155 0 0-320 H 0-259 Q	8010240202 901 8010240205 901 8010240210 901	0240190 80/09/29 0240194 80/09/19 0240196 80/09/19 0240203 80/10/14 0240204 80/10/21	PR 50-245 G 50-245 G 50-237 P 50-329 K
8010230491 8010230418 8010230528 8010230522 8010230539 8010230532 8010230575 80102305428 8010230628 8010230623	80/09/29 50 80/09/02 50 80/09/03 CD	0-321 P 0-410 G 0-311 G NTRACT 0-277 G	8010240221 901 8010240225 801 8010240228 801	0240196 80/09/19 0240204 80/10/21 0240220 80/10/17 0240219 80/09/04 0240204 80/10/21	50-245 Q 50-327 K 50-331 P 50-324 Q 50-329 K

ACCE9810A				ACCESSION HUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE DBUBBI	SUBJECT CATEGORY	ENCLOSURE DOCUMENT ISSUED	SUBJECT CATEODRY
8010240240 8010240241 8010240248 8010240247 8010240250	8010240237 8010240235 8010240242 8010240246 8010240247	80/10/20 80/09/04 80/09/12 80/09/05 80/10/16	50-293 R 50-328 Q 50-423 Q 50-395 Q 50-213 P	8010270014 8010270013 80/10/10 5 8010270014 8010270013 80/10/10 5 8010270017 8010270013 80/10/10 5 8010270022 8010270021 80/09/05 5	0-311 P 0-311 P 0-311 P 0-482 Q 0-382 Q
8010240262 8010240266 8010240271 8010240272 8010240278	8010240252 8010240252 8010240265 8010240265 8010240252	80/10/07 80/10/07 80/10/07 80/10/06 80/10/07	50-271 Q 50-271 Q 50-271 Q 50-305 Q 50-271 Q	8010270030 8010270027 80/09/05 9 8010270045 8010270042 80/10/10 5 8010270051 8010270037 80/10/15 F	0-392 Q 0-392 Q 0-320 H 014 0-289 H
8010240279 8010240283 8010240284 8010240290 8010240292	8010240274 8010240274 8010240277 8010240281 8010240282	80/10/01 80/10/01 80/09/08 80/09/09 80/01/08	50-133 P 50-133 P 70-820 50-277 Q 50-338 P	8010270060 8010270055 80/09/10 5 8010270063 8010270057 80/10/10 8010270064 8010270037 80/10/15 5	014 0-518 0 0-287 H 0-568 A 0-261 0
8010240276 8010240302 8010240307 8010240311 8010240315	8010240289 8010240282 8010240303 8010240305 8010240303	80/09/12 80/10/03 80/09/25 80/09/25 80/09/25	50-29 Q 50-338 P 50-289 Q 50-275 H 50-289 Q	#B10270073 #B010270067 #B0/10/10 # #B010270075 #B010270072 #B0/10/10 # #B010270078 #B010270074 #B0/09/17 #	01A 10-320 H 1-5450 ASTE HOT 10-320 H
8010240322 8010240330 8010240337 8010240338 8010240339	8010240303 8010240325 8010240331 8010240332 8010240335	80/09/25 80/09/15 80/08/29 80/09/23 80/09/30	50-289 0 50-329 0 50-320 0 50-219 0 50-413 0	8010270083 6010270079 90/09/29 5 8010270087 8010270037 80/10/15 F 8010270092 8010270089 80/10/10 5	01A 10-320 H 101A 10-320 H 10-477 A
8010240343 8010240344 8010240346 8010240347 8010240351	8010240332 8010240331 8010240335 8010240332 8010240332	80/09/23 80/08/29 80/09/30 80/09/23 80/09/23	50-219 Q 50-320 Q 50-413 Q 50-219 Q 50-219 Q	8010270104 8010270100 80/09/23 5 8010270106 8010270037 80/10/12 8010270107 8010270099 80/09/12 5	60-568 A 60-412 S 60-568 A 60-259 G 60-568 A
8010240397 8010240415 8010240418 8010240426 8010240437	8010240397 8010240412 8010240410 8010240421 8010240432	80/10/20 80/10/20 80/10/20 80/10/17 80/10/17	50-270 P 50-269 P 50-273 8 50-317 8 50-334 P	8010270122 8010270118 80/10/14 7 8010270126 8010270037 80/10/15 5 8010270131 8010270128 80/10/14 7	10-558 A 11-9022 10-568 A 11-9049 10-275 Q
8010240441 8010240445 8010240454 8010240461 8010240472	8010240433 8010240442 8010240447 8010240443	80/10/17 80/10/20 80/10/07 80/10/07 80/10/10	50-334 B 50-375 F 50-334 B 50-334 B	8010270149 8010270100 80/10/15 8 8010270149 8010270140 80/10/15 8010270151 8010270037 80/10/15 5	71-9019 50-568 A 27-10 50-286 P 60-358 Q
8010240479 8010240479 8010240480 8010240485 8010240500	8010240468 8010240475 8010240477 8010240477 8010240494	80/10/17 80/10/20 80/10/17 80/10/17 80/10/03	50-334 8 50-270 8 50-219 R 50-219 R 50-289 P	8010270160 8010270140 80/10/21 F 8010270161 8010270146 80/09/10 8010270163 8010270037 80/10/15 3	27-10 TOTA 50-358 Q 50-477 A TOTA
8010240508 8010240512 8010240515 8010240527 8010240532	8010240494 8010240494 8010240505 8010240519 8010240528	80/10/03 80/10/03 80/10/07 80/10/08 80/10/09	50-289 P 50-289 P XPORTLIC 50-335 F 50-173 J	8010270180 8010270037 80/10/15 5 8010270183 8010270181 80/10/06 8010270184 8010270181 80/10/06 5	10-477 A 10-477 A 10-369 Q 10-369 G
8010240533 8010240537 8010240537 8010240542 8010240551	8010240519 8010240519 8010240519 8010240541 8010240546	80/10/08 80/01/08 80/01/08 01/01/08 90/01/08	50-335 F 50-335 F 50-335 F 50-368 K 50-373 B	9010270220 8010270195 80/09/26 0 8010270208 8010270197 80/09/24 5 8010270212 8010270207 80/09/19 5	50-395 G CONTRACT 50-482 B 50-313 G LOCER
8010240553 8010240558 8010240562 8010240565 8010240567	8010240545 8010240545 8010240552 8010240557 8010240560	80/09/12 80/09/12 80/10/21 80/08/25 80/10/09	70-25 70-25 50-267 Q 50-286 Q CONTRACT	9010270287 8010270283 80/09/19 5 8010270289 8010270285 80/09/30 7 8010270295 8010270285 80/09/30 7	RPDRTLIC 50-312 0 70-143 70-143 50-346 0
8010240569 8010240574 8010240575 8010240581 8010240584	8010240566 8010240568 8010240566 8010240579 8010240573	80/09/17 80/08/24 80/09/17 80/07/11 80/08/29	50-327 P 50-272 G 50-327 P 50-460 G QAY79	8010270317 B010270313 B0/09/19 5 8010270322 B010270320 B0/10/10 8010270328 B010270323 B0/10/15 F	50-277 0 50-321 0 50-277 F 3E00D 50-269 0
8010240587 8010240590 8010240595 8010240599 8010240605	8010240579 8010240582 8010240582 8010240582 8010240582	80/07/11 80/10/06 80/10/06 80/10/06 80/10/06	50-440 Q 50-320 P 50-320 P 50-320 P 50-320 P	8010270343 8010270337 80/09/19 9 8010270393 8010270349 80/10/21 9 8010270373 8010270371 80/09/26	50-341 Q 50-302 Q 50-327 8 70-754 50-272 8
8010240609 8010240614 8010240616 8010240620 8010240623	8010240592 8010240609 8010240582 8010240582 8010240582	80/10/04 80/10/14 80/10/06 80/10/06 80/10/06	50-320 P CONTRACT 50-320 P 50-320 P 50-320 P	8010270381 8010270380 80/07/26 9 8010270383 8010270382 80/10/22 9 8010270389 8010270384 80/10/15	50-206 8 50-237 8 50-261 8 50-483 0 50-346 8
8010240653 8010240663 8010270005 8010270008 8010270011	8010240449 8010240461 8010270004 8010270006 8010270009	80/09/11 80/09/11 80/10/14 80/10/07 80/08/29	50-261 0 50-348 0 CONTRACT CONTRACT GATTT	8010270394 8010270392 80/10/15 8010270396 8010270395 80/10/09 8010270397 8010270395 80/10/09	50-155 0 50-150 0 50-327 0 50-327 0 50-327 0

ACCESSION					ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	₹Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
B010270402 B010270427 B010270491 B010270519 B010270529	8010270400 8010270419 8010270483 8010270516 8010270524	80/10/22 80/10/10 80/10/21 80/10/10 80/10/08	50-400 50-413 50-260 M18C 50-320	R O S	8010280325 8010280345 8010280377 8010280380 8010280388	8010280383 8010280362 8010280375 8010280327 8010280384	80/10/22 80/09/11 80/10/21 80/10/21 90/10/22	TOPREP TOPREP 50-366 50-278 50-270	8 P S
8010270504 8010270542 8010270547 8010270551 8010270556	8010270532 8010270539 8010270535 8010270535 8010270554	80/10/15 80/10/07 80/10/09 80/10/09 80/10/14	50-10 50-250 50-298 50-298 GATT9	U H G	B010280389 8010280375 8010280406 8010280412 8010280414	8010280385 8010280393 8010280402 8010280408 8010280407	80/09/12 80/10/14 80/10/24 80/10/20 80/10/22	50-321 50-247 50-325 50-54 50-293	V R S P S
8010270557 8010270559 8010270561 8010270563 8010270564	8010270548 8010270554 8010270554 8010270554 8010270548	80/10/03 80/10/14 80/10/14 80/10/14 80/10/03	COMMISS: QA799 QA799 QA799 COMMISS:		8010280415 8010280429 8010280429 8010280435 8010280443	8010280409 8010280421 8010280419 8010280433 8010280438	80/10/15 80/10/21 80/10/22 80/10/23 80/09/02	50-338 50-366 50-333 50-320 50-334	P 8 R V
8010270566 8010270570 8010270572 8010270573 8010270574	8010270548 8010270548 8010270568 8010270568 8010270571	80/10/20 80/10/03 80/10/03 80/10/03	COMMISS: COMMISS: GA999 GA999 50-313		8010280447 8010283452 8010280447 8010280471 8010280474	8010280440 8010280449 8010280460 8010280460 8010280470	80/10/23 80/10/21 80/10/24 80/10/24 80/10/21	50-382 50-344 50-133 50-133 50-366	C F 8 5 8
8010270575 8010270576 8010270577 8010280002 8010280003	8010270568 8010270568 8010270571 8010280001 8010280001	80/10/03 80/10/03 80/10/20 80/10/03 80/10/03	0A999 GA979 50-313 50-293 50-293	G P P	8010280479 8010280494 8010280490 8010280503 8010280508	8010280474 8010280490 8010280462 8010280467 8010280465	80/10/24 80/10/22 80/10/22 80/10/17 80/10/22	50-267 50-273 50-348 50-293 50-327	8 8 8 8 8
8010280018 8010280019 8010280026 8010280033 8010280035	8010280014 8010280016 8010280022 8010280030 8010280027	80/09/30 80/09/26 80/10/09 80/10/20	50-266 50-206 50-275 50-289 50-275	P Q H Q	8010280511 8010280512 8010280514 8010280519 8010280523	8010280468 8010280506 8010280448 8010280450 8010280455	80/10/23 80/10/24 80/10/14 80/10/22 80/10/24	50-257 50-281 50-237 50-334 50-213	8 8 8
8010283041 8010280054 8010288057 8010289058 8010280060	8010280039 8010280050 8010280050 6010280053 8010280050	80/09/26 80/10/16 80/10/16 80/10/15 80/10/16	50-397 50-370 50-370 50-440 50-370	0 0 0 0	8010280528 8010280532 8010280533 8010280534 8010280541	8010280458 8010280524 8010280526 8010280444 8010280537	80/10/24 80/10/22 80/10/20 80/10/24 80/10/22	50-213 70-33 50-243 50-313 50-336	S S S
8010280064 8010280070 8010280077 8010280092 8010280105	8010280050 8010280063 8010280073 8010280085 8010280097	60/10/16 60/10/09 60/10/16 60/10/01 80/10/07	50-370 50-352 50-289 CDMMISSI 50-250	9 H H NOI H	8010280942 8010280943 8010280948 8010280951 8010280952	8010280538 8010280446 8010280446 8010280516 8010280546	80/10/23 80/10/24 80/10/24 80/10/24 80/10/16	50-325 50-305 50-305 50-267 50-313	88888
8010280111 8010280114 8010280115 8010280121 8010280123	8010280107 8010280107 8010280110 8010280110 8010280118	80/07/25 80/07/25 80/09/09 80/09/09 80/10/01	40-8710 40-8710 50-267 50-267 50-275	a a U	8010280954 8010280554 8010280545 8010280545 8010280545	8010280446 8010280547 8010280518 8010280558 8010280563	80/10/24 80/10/23 80/10/23 80/10/23 80/10/23	50-305 50-339 50-327 50-280 50-259	6 5 5 5
8010280126 8010280127 8010280133 8010280147 8010280151	8010280119 8010280119 8010280119 8010280138 8010280138	80/10/14 80/10/14 80/10/14 80/10/15 80/10/15	FOIA FOIA FOIA FOIA		8010280572 8010280574 8010280579 8010280594 8010280591	8010280522 8010280570 8010280574 8010280527 8010280583	80/10/23 80/10/22 80/10/24 80/10/24 80/10/23	50-313 50-324 50-293 50-267 50-313	8 8 8 8
8010280197 8010280163 8010280166 8010280172 8010280178	8010280138 8010280135 8010280138 8010280138 8010280138	80/10/15 E2/80/08 E1/01/08 E1/01/08	F01A 50-237 F01A F01A F01A	Q	8010280605 8010280604 8010280647 8010280648 8010280660	8010280598 8010280604 8010280642 8010280644 8010280654	80/10/24 80/10/24 80/10/10 80/10/21 80/10/10	50-409 50-255 50-289 50-313 50-320	0 K H F P
8010280183 8010280189 8010280194 8010280197 8010280202	8010280138 8010280138 8010280138 8010280138 8010280138	80/10/15 80/10/15 80/10/15 80/10/15 80/10/15	FOIA FOIA FOIA FOIA		8010280474 8010280479 8010280481 8010280482 8010280485	8010140133 8010280675 8010280673 8010280676 8010280675	80/09/30 80/10/17 80/10/14 80/10/14 80/10/17	50-10 50-10 50-321 TOPREP 50-10	0 Р В
8010280205 8010280208 8010280207 8010280218 8010280224	8010280138 8010280204 8010280138 8010280138 8010280138	80/10/15 80/10/23 80/10/15 80/10/15 80/10/15	FOIA TOPREP FOIA FOIA FOIA		8010280688 8010280699 8010280701 8010280702 8010280704	8010280675 8010280686 8010280675 8010280677 8010280675	80/10/17 80/10/10 80/09/24 80/10/15 80/09/24	50-10 50-250 50-106 XPORTL10 50-106	P G C G
8010280232 8010280240 8010280257 8010280260 8010280274	8010280138 8010280138 8010280254 8010280254 8010280267	80/10/15 80/10/15 60/10/20 80/10/20 80/09/19	FOIA FOIA 50-373 50-373 50-261	К К 0	8010280710 8010280725 8010280725 8010280728 8010280730	8010280531 8010280722 8010280723 8010280722 8010280722	80/10/24 80/10/03 80/10/03 80/10/03	50-302 GA999 50-219 GA999 GA999	8 P
8010280282 8010280284 8010280268 8010280287 8010280293	8010280279 8010280280 8010280280 8010280280 8010280287	80/09/11 80/10/07 80/10/07 80/10/07 80/10/22	50-382 50-289 50-289 50-289 50-295	Q U U U P	8010280731 8010280734 8010280735 8010280736 8010280737	8010280723 8010280723 8010280722 8010280723 8010280723	80/10/23 80/10/23 80/10/03 80/10/23 80/10/23	50-219 50-219 9A979 50-219 50-219	P P P
8010280294 8010280298 8010280302 8010280303 8010280304	8010280280 8010280280 8010280297 8010280280 8010280280	80/10/07 80/10/07 80/10/22 80/10/07 80/10/07	50-287 50-287 50-250 50-287 50-287	U 9 U U	8010280/40 8010280742 8010280745 8010280748 8010280750	8010280723 8010280723 8010280723	80/10/23 80/10/23 80/10/23 80/10/23 80/10/23	50-219 50-219 50-219 50-219 50-219	P P P P

ACCESSION				ACCESSION NUMBER			
ENCLOBURE	PRINCIPAL	DATE 189UED	SUBJECT CATEGORY		DATE SSUED	SUBJECT	
8010270071	8010270086	80/10/16	CONTRACT	**************************************		COMITOR	_
8010270073 8010270077	8010290087 8010290094	60/10/09 60/10/16	CONTRACT	B010300154 B010300146 B0.	/09/19		G
B010290104 B010290105	8010290096 8010290101	80/10/10 80/07/29	State Prog QA999			WASTE MOT 50-335	a
8010290108 8010290110	8010290101 8010290102	80/07/29 80/09/15	QA999			70-364	
8010290111 8010290116	8010270102 8010270076	80/10/10 80/10/14	50-544 Q State Prog GA999	8010300241 8010300224 80	/09/19		9
8010290117	8010290096	80/10/10	State Prog				G G
8010270118 8010270121	8010290115 8010290112	80/09/03 80/10/14	50-358 Q 98999			50-272 KPORTLIC	a
8010290122 8010290124	8010270112 8010270115	80/10/14 80/09/03	QA797 50-358 Q	8010300287 8010300279 80	/10/08	50-320	0 0
8010290125	8010290120	80/10/22	50-10 Q			XPORTL1C	
8010270126 8010270127	8010270112 8010270076	80/10/14 80/10/10	GA777 State Prog	8010300337 8010300279 E0	/10/08	50-320	Q Q
8010290133 8010290136	8010290128 8010290131	80/09/12 80/09/26	50-546 Q 50-123 Q	8010300358 8010300351 80	710/06		P
B010270144 B010270151	8010290140 8010290148	80/09/25	50-292 Q 50-461 Q				P P
8010290155 8010290162	9010270146 9010290153 9010290146	80/10/21 80/10/21	50-461 Q 50-155 Q 50-155 H	8010300367 8010300351 60	/10/06	50-344	P G
8010270144 8010270175	8010280558 8010290161	80/10/23 80/10/13	\$0-280 B	8010300377 8010300372 80	/10/16	50-213	P Q
8010270187	8010290186	80/09/29	50-309 Q				a a
8010290191 8010290192	8010270184 8010270181	80/10/02	XPORTLIC 50-373 Q	8010300423 8010300380 80	/10/16	50-369	9 0
80102901 <i>96</i> 8010290202	8010290184 8010290198	80/09/29 80/10/03	50-309 Q 50-395 Q				P P
8010290203	8010290186	80/09/29	50-309 0				Q H
8010270204 8010270207	8010270198	80/10/03 80/09/29	50-375 G 50-307 G	B010300435 8010300432 80	710/03	50-458	Q Q
8010270220 8010270224	8010290216 8010290216	80/10/58	50-255 Q 50-255 Q				Š
8010270251 8010270258	8010270246 8010270241	80/10/20	50-483 B 50-255 Q			50-315	Ğ S
8010290262 8010290275	8010290257 8010290271	80/07/26	50-483 Q 50-335 H	8010300463 801030045B 80	/10/21	50-220	8
8010270281	8010270280	80/10/01	COMMISSION				Α .
8010290284 8010290287	8010290280 8010290285	80/10/01 80/10/24	COMMISSION 50-155 P	8010300490 8010300485 80	/10/14	SO-344 NUREG LOCFR	A
8010270288 8010270270	8010290280 8010290285	80/10/01	COMMISSION 50-155 P	8010300508 8010300492 80)/10/14)/10/16)/10/09		a
8010290292	8010270285	80/10/24	50-155 P		/10/14	10CFR	
8010290295 8010290317	8010270280 8010270165	B0/10/01 B0/10/07	COMMISSION 50-276 P	8010300519 8010300518 B0	/10/14	100FR -50-244	Q
8010290323 8010290329	8010270320	80/10/20	50-272 P 50-387 I 50-237 P	8010300528 8010300525 80		100FR 50-155	0
8010290335 8010290339	8010290333 8010290337	80/10/21	50-313 P	8010300538 8010300527 80	0/09/19		0
8010290357 8010290358	8010270356 8010270356	80/10/15 80/10/15	50-320 P 50-320 P	8010300548 8010300542 80	0/10/16 0/09/19	50-29	0
B010270357	8010270354 8010270356	80/10/15	50-320 P 50-320 P		0/10/14 0/09/03	COM:(18810	G
8010290361	8010290356	80/10/15	50~320 P		0/10/27 0/10/24	50-320 50-508	T Q
8010290364 8010290376	8010270363 8010270374	80/10/53	50-317 F 50-265 8	B010310014 B010310007 B0	0/10/24	50-508 50-508	Q Q
8010290382 8010290397	8010290378 8010290392	80\10\17 80\10\55	50-514 <i>Q</i> 50-324 Q	801031001B 8010310007 80	0/10/24	50-508	Q
8010290399	8010290392	80/10/16	50-324 G 50-264 G	8010310029 8010310022 80	0/10/17 0/10/17	50-413 50-413	9
8010290403 8010290407	9010290395 9010290392 9010290406	80/09/24 80/10/16 80/09/19	50-324 Q 70-27	8010310034 8010310022 80	0/10/17	50-413 50-413	G G
8010290410 8010290412	8010290409	80/09/30	50-338 G	0010010000 401101	0/10/17	50-413 50-413	a a
8010290414 8010290416	8010270413 8010270407	80/10/21 80/09/30	50-456 G 50-338 G	8010310044 8010310035 80	0/10/17 0/10/17 0/10/17	50-413 50-413	G G
8010290418 8010300017	8010290417 8010300015	80/10/17 80/10/14	50-373 A 50-312 G	8010310050 B010310049 B0	0/10/24 D/08/15	50-397 40-8084	ĕ
8010300019	8010300015	80/10/14	50-312 0	8010310049 8010310055 80	0/09/19	70-1151	
8010300021	8010300015	80/10/14 80/10/14	50-312 0 50-312 0 50-312 0	8010310070 8010310064 80 8010310075 8010310064 80	0/10/21 0/10/21	50-424 50-424	0
8010300024 8010300036	8010300015 8010300033	80/10/14	50-445 H 50-367 Q	8010310082 8010310074 80	0/09/22 0/10/23	50-27 71-18	Ģ.
8010300048	9010300043	80/10/27	90-367 0		0/10/09	50-324 50-334	Q P
8010300049 8010300075 8010300088	8010300061 8010300061 8010300061	80/10/24 80/10/24	50-367 0 50-367 0	BO 1031013B 8010310129 B	0/10/15 0/10/15 0/10/15	50-334 50-334	P
8010300090 80103000119	80103000B2	80/10/27 80/10/06	40-1142 27-39		0/10/23	50-151	P
uu							

ACCESSIO						N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR	!Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	EUBJEC CATEGO	RY
8010310151	8010310142	80/10/23	50-151	Р	8010310332	8010310326	80/10/24	50-245	p
8010310155	8010310150	80/10/21	71-371		8010310340	8010310313	80/10/21	70-1151	
8010310169	8010310125	80/10/07	50-324	Q.	8010310341	8010310329	80/10/20	50-400	œ
8010310175	8010310125	80/10/09	50-324	G	8010310346	8010310343	80/10/22	50-304	ē
8010310179	B010310125	80/10/09	50-324	œ	B010310347	8010310347	80/10/24	50-295	P
8010310187	8010310182	80/10/21	50-302	Qr.	8010310359	8010310330	80/10/24	50-317	8
8010310192	8010310182	80/10/21	50-302	Q.	8010310371	8010310355	80/10/24	50-282	Ë
8010310196	8010310182	BO/10/21	50-302	Or C	8010310307	8010310385	80/09/30	50~206	Ġ
8010310199	8010310182	80/10/21	50-302	a	8010310397	8010310393	80/10/27	50-400	A
8010310206	8010310203	80/10/01	50-155	P	8010310378	8010310395	80/10/20	50-250	8
8010310210	8010310203	80/10/01	50-155	P	8010310399	E010310396	80/10/28	NUREO	
8010310212	8010310198	80/10/24	FOIA		8010310409	8010310405	80/10/24	50-269	Þ
8010310220	8010310217	80/09/30	50-241	₽	8010310410	8010310406	80/10/23	50-366	B
8010310224	8010310217	80/09/30	50-261	Р	B010310417	8010310411	80/10/28	50-280	P
8010310226	8010310198	80/10/24	FOIA		8010310421	8010310414	80/10/27	50-219	8
8010310228	8010310217	60/09/30	50-241	P	8010310423	6010310419	80/10/15	50-320	Р
8010310235	8010310198	80/10/24	FOIA		8010310433	8010310428	80/10/22	50-250	8
B01031024B	8010310198	80/10/24	FOIA		8010310439	8010310426	80/10/27	50-320	š
8010310250	B010310246	80/10/17	71-5088		8010310441	8010310435	80/10/22	50-250	8
B010310252	8010310198	80/10/24	FOIA		8010310454	801031044B	80/10/24	50-220	6
0010310264	8010310198	BO/10/24	FOIA		8010310465	8010310459	80/10/07	PRM	
8010310267	8010310260	80/10/22	50-237	Q.	8010310466	8010310460	80/10/21	50~346	8
8010310274	8010310198	80/10/24	FOIA		8010310470	8010310459	80/10/07	PRM	~
8010310278	8010310272	80/10/01	50-361	a	8010310478	8010310471	80/10/27	50-271	8
8010310285	8010310198	80/10/24	FOIA		8010310480	8010310477	80/10/22	50-289	T
8010310269	8010310198	80/10/24	FOIA		8010310484	8010310458	80/10/30	50-219	0
8010310294	8010310286	80/10/20	50-313	P	8010310497	8010310494	80/10/20	50-329	Ä
B010310304	8010310298	80/09/19	50-206	0	8010310500	0010310494	80/10/20	50-329	Ä
B010310305	B010310301	80/10/21	30-272	F	B010310536	8010310535	80/09/24	50-458	a
8010310314	8010310307	80/09/12	50-397	Q	8010310538	8010310534	80/09/30	CONTRACT	u
8010310315	8010310310	80/10/24	50-318	s	B010310547	8010310543	80/10/03	50-123	o.
8010310318	8010310198	80/10/24	FOIA		8010310577	8010310572	80/10/14	CONTRACT	
8010310319	8010310313	80/10/21	70-1151		8010310585	8010310580	80/10/20	50-116	Q
8010310322	B010310313	80/10/21	70-1151		8010310387	8010310581	80/09/29	CONTRACT	u
8010310323	8010310317	80/09/24	50-321	G	8010310597	8010310594	80/10/04	CONTRACT	
					8010310692	8010310596	80/10/24	XPORTLIC	

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- Preliminary Safety Analysis Report (PSA Summary Report or Safety Analysis Rep
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES-or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence,
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or eyents. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel youchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry, the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria;
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

			And the state of t
•			
		•	
			e e e e e e e e e e e e e e e e e e e

•			

R C FORM 335 U.S. NUCLEAR REGULATORY COMM	MISSION	1. REPORT NUMBER (Assigned by DDC)		
BIBLIOGRAPHIC DATA SH	NUREG-0540 Vol 2, No 10			
FITLE AND SUBTITLE (Add Volume No , if appropriate)		2. (Leave blank)		
Title List of Documents Made Public October 1 - 31, 1980	3 RECIPIENT'S ACCESSION NO			
7. AUTHOR(S)		5. DATE REPORT COMPLETED		
	November YEAR 1980			
PERFORMING ORGANIZATION NAME AND MAILING AD	DRESS (Include Zip Cade)	DATE REPORT ISSUED		
Division of Technical Information and	MONTH YEAR 1981			
U.S. Nuclear Regulatory Commission Washington, D.C. 20555		6. (Leave blank)		
		8. (Leave blank)		
2. SPONSORING ORGANIZATION NAME AND MAILING A	10. PROJECT/TASK/WORK UNIT NO			
Division of Technical Information and Document C U.S. Nuclear Regulatory Commission Washington, D.C. 20555		11. CONTRACT NO		
TO SHAPE OF DEPORT	PERIOD CO	VERED (inclusive dates)		
13. TYPE OF REPORT Monthly				
		14 (Leave blank)		
15. SUPPLEMENTARY NOTES		14 (Feare Menu)		
This document is a monthly pu information received and gene	rated by the US NRC.	INIS INTORMATION		
This document is a monthly purinformation received and generated includes (1) docketed material plants and other uses of radismaterial received and generated regulatory agency. The docker merly issued through the U.S. Center under the title Power document replaces PRDI, which contains the following indexed Index, and Report Number Indexed	rated by the US NRC. I associated with ci oactive materials ared by NRC pertinent eted information included information included information included included information included information included in the control of the control	vilian nuclear power nd (2) nondocketed to its role as a udes information for- gy's Technical Information mation (PRDI). This prepared. This document		
information received and gene includes (1) docketed materia plants and other uses of radi material received and generat regulatory agency. The docke merly issued through the U.S. Center under the title <i>Power</i> document replaces PRDI, which contains the following indexe	rated by the US NRC. I associated with ci oactive materials ared by NRC pertinent eted information included information included information included included information included information included in the control of the control	vilian nuclear power nd (2) nondocketed to its role as a ludes information for- gy's Technical Information mation (PRDI). This prepared. This document		
information received and gene includes (1) docketed materia plants and other uses of radi material received and generat regulatory agency. The docke merly issued through the U.S. Center under the title <i>Power</i> document replaces PRDI, which contains the following indexe	rated by the US NRC. I associated with ci oactive materials ared by NRC pertinent eted information included information included information included included information included information included in the control of the control	Inis information (vilian nuclear power and (2) nondocketed to its role as a ludes information for- ay's Technical Information (PRDI). This prepared. This document Index, Corporate Source		
information received and gene includes (1) docketed materia plants and other uses of radi material received and generat regulatory agency. The docke merly issued through the U.S. Center under the title <i>Power</i> document replaces PRDI, which contains the following indexe Index, and Report Number Inde	rated by the US NRC. I associated with cioactive materials arged by NRC pertinent eted information included includ	Inis information (vilian nuclear power and (2) nondocketed to its role as a (udes information for- ay's Technical Information (PRDI). This (orepared. This document (Index, Corporate Source) (Index)		
information received and gene includes (1) docketed materia plants and other uses of radi material received and generat regulatory agency. The docke merly issued through the U.S. Center under the title Power document replaces PRDI, which contains the following indexe Index, and Report Number Index.	rated by the US NRC. I associated with cioactive materials ared by NRC pertinent ed by NRC pertinent of Energy Reactor Docket Information included information includes: Personal Author ex.	ivilian nuclear power and (2) nondocketed to its role as a ludes information for y's Technical Information (PRDI). This prepared. This document Index, Corporate Source		